

## MEETING LOG DIRECTORATE FOR ENGINEERING SCIENCES

**SUBJECT:** Meeting of the ANSI Z21.47 ANSI Z21/CGA Joint Central Furnace Subcommittee

**PLACE:** Clarion Hotel Cleveland Airport-West, Middleburg Heights, Ohio

**MEETING DATE:** September 14, 2000

**LOG ENTRY SOURCE:** Ronald A. Jordan

**ENTRY DATE:** September 19, 2000

### COMMISSION ATTENDEES:

Ronald A. Jordan, ESEE  
David Tucholski, LSME

### NON-COMMISSION ATTENDEES:

See attached member attendee list

### MEETING SUMMARY:

Staff attended the meeting of the Z21/CGA Joint Central Furnace Subcommittee to discuss the results of furnace emissions testing and to recommend changes to the furnace standard to address the risk of CO exposure when a furnace vent pipe is either disconnected, completely blocked or partially blocked. Following is a summary of that discussion.

- The test report, modeling report, and risk assessment for Furnace #1 were generally well received.
- The subcommittee requested that the Gas Appliance Manufacturers Association (GAMA) Furnace Engineering Committee and its Technical Working Group (TWG) review the test report and related reports for Furnaces #2-#5 and report back to the subcommittee with a recommendation. The two groups were going to meet during different time frames, but staff requested that they meet during the same week (i.e. the GAMA Furnace Engineering Committee would meet the day before the TWG) to avoid unnecessary delays in the standards development process. Staff also requested that these meetings be held before the spring time frame (e.g. May through June) in which the TWG normally meets. The subcommittee agreed to staff's request and stated that the meetings would be scheduled prior to the end of calendar year 2000 (e.g. in November or December 2000). Staff told the subcommittee that the remaining test and analysis reports for furnaces #2-#5 would be sent to the CSA staff for distribution within approximately one month (i.e. mid- to late October, 2000).
- The subcommittee discussed options available to prevent CO poisonings. Some initial options discussed included recommending a requirement that CO detectors be installed in homes; GAMA sponsored CO poisoning awareness programs; and installing non-adjustable gas regulators on the furnace to prevent overfire conditions. Staff reiterated the CPSC position that while these

OFFICE OF THE SECRETARY  
DEPARTMENT OF INFORMATION

2000 OCT 16 A 9:45

CPSA 6 (b)(1) Cleared

No Mfrs/Prvt Bdrs or

Products Identified

Excepted by \_\_\_\_\_

Firms Notified, \_\_\_\_\_

Comments Processed. \_\_\_\_\_

activities would be helpful in addressing the issue, more needed to be done to prevent the furnaces from becoming CO generators and leaking CO into the home when the vent is disconnected or blocked.

- Some attendees questioned the size of the CPSC test chamber and also the size of the house used in staff's indoor air model (1076 sq. ft). They felt that a 100,000 Btu/hr furnace would be oversized for both the test chamber and house. Staff replied that the chamber was appropriate for test purposes and that the modeling report describes how changing the volume of the house or the air exchange rate will effect the CO concentration.
- Some attendees asked why staff overfired Furnace #1 by 23 percent. Staff explained that the current ANSI Z21.47 standard requires certain tests be conducted at 12 percent over the manufacturer's specified rate. Staff stated that attempts have been to determine the rationale for the standard requirement for a 12 percent overfire rate test, but CSA was not able to locate the rationale statement for this provision. Staff stated that it could only assume that the input rate to the furnace could drift by up to 12 percent over the lifetime of the furnace. Staff further stated that since the furnace, as installed, overfired by 10 percent and that all installers may not "clock" the gas flow rate, the furnace was tested at 12 percent over the "as installed" rate. This resulted in an overfire rate of 23 percent.
- Some attendees asked at what point during testing did staff make observations about the burner flame shape and color. Staff replied that the flames were not visually observed during an actual test, since doing so would require removal of the furnace cover and interrupt closed chamber testing. Staff further replied that burner flames were therefore observed during non-tests, with the closet and chamber doors open and with the furnace cover removed. Also that this would be similar to how a furnace installer would check the flames during an installation.
- The attendees expressed surprise that all but one test furnace overfired when tested at the "as received" input rate. Staff explained that this input rate was based on a higher heating value of 1040 Btu/ft<sup>3</sup>. Some attendees were also surprised by this heating value and stated that it was not typical for the entire US. However, a representative from BG&E stated that a heating value of 1040 Btu/ft<sup>3</sup> was consistent with what he saw for this service area.
- Several attendees asked how closely staff followed the procedures in the ANSI Z21.47 standard for the blocked vent tests. Staff described the similarities and differences between its and the ANSI test procedures. One difference cited was that staff blocked the vent downstream of the flue collar, while ANSI specifies blockage at the flue collar. Staff also allowed for the depletion of oxygen around the furnace, while ANSI specifies that the tests are to be conducted in an atmosphere containing normal oxygen. Staff stated that we believe our blockage test more closely reflect what can occur in actual use.

cc:

Office of the Secretary  
Colin Church  
ESEE Chronological File

ATTENDANCE RECORD

CENTRAL FURNACE SUBCOMMITTEE

THURSDAY, SEPTEMBER 14, 2000

GUESTS

NAME (Please Print)    MARK "X"    COMPANY/ORGANIZATION    PHONE NO.    FAX NO.    e-mail

	NAME (Please Print)	MARK "X"	COMPANY/ORGANIZATION	PHONE NO.	FAX NO.	e-mail
1	BOB STACK		CSA INTERNATIONAL	216/524-4990	216/642-3463	Robert.Stack@csa-international.org
2	Bill Roy		Excel Comfort Sys	803 284 5340	803 284 4449	Bill.Roy@Excel-Csi.com
3	Marc Delsonis		Carrier Electronics	919 358 3335	919 358 2255	marc.delsonis@carrier.us.com
4	Matt Wilber		Reliant Energy Mmegasco	612-321-4385	612-321-4397	Matthew_M_Wilber@reliantenergy.com
5	TS Kennedy		Avana	931-436-2184	931 438 2189	t.j.kennedy@Avana.com
6	Kyu Hwang		Nordyne	636-561-7486	636-561-7300	hwangkk@nordyne.com
7	Carl Radcliffe		UL	919-549-1678	919-549-6031	carl.c.radcliffe@ul.com
8	Jim Neerka		Test House Concracornit	330-273-5023	/ 0843	jimneerka@pk.net
9	Don Harrison		UK	440-943-0873	440-943-3345	Don.H.Harrison@usa.m.com
10	Jim Hickson		Lennor Ind. Inc.	972/497-7807	972/497-7879	Jim.Hickson@lennorind.com
11	Gene Edgare		Seckret Inc.	740-385-5666	740-385-2485	gene.edgare@zara.com
12	John Seine		Arwood	815-877-5700	815-637-6507	seine.j@duccard.com
13	DAVID BAETER		ENBRIDGE consumers	416-495-3938	416-495-5837	dave.baeter@enbridge.com
14	DAVID JAKOBS		RHEEM	561 648-4114	561-648-6131	rdj@rheem.com

NAME (Please Print) \_\_\_\_\_ GUESTS \_\_\_\_\_  
 MARK "X" \_\_\_\_\_ COMPANY/ORGANIZATION \_\_\_\_\_ PHONE NO. \_\_\_\_\_ FAX NO. \_\_\_\_\_ e-mail \_\_\_\_\_

- 15 JPH dverralc \_\_\_\_\_ UNION GAS 416 496 5211 416 496 5303 [JPHdverralc@unionsgas.com](mailto:JPHdverralc@unionsgas.com)
- 16 Bill URQUHART \_\_\_\_\_ UNION GAS 519 436-4600 ext 2863 [Billurquhart@unionsgas.com](mailto:Billurquhart@unionsgas.com)
- 17 Carl Suchowsky X Gas Consultants Inc 440 232 3200 440 232 1834 [carlsuch@earthlink.net](mailto:carlsuch@earthlink.net)
- 18 Carl TOURNE X \_\_\_\_\_ / \_\_\_\_\_ / \_\_\_\_\_
- 19 Tom Chase York 316-852-6564 316-852-6564 [tom.chase@nyork.com](mailto:tom.chase@nyork.com)
- 20 Don SWANNA BHTO CONSULTANTS 410 291 5130 410 291 4821 [ASWanna@bhtoc.com](mailto:ASWanna@bhtoc.com)
- 21 TED WILC (RMAN) American RMA RMAN 202-824-7733 202-824-7088 [Turcotte@americanrma.com](mailto:Turcotte@americanrma.com)
- 22 Robert Blackwell NPGA/Action Gas Inc 303-838-9880 303-838-2976 [RBlackwell@npga.com](mailto:RBlackwell@npga.com)
- 23 Jim Vershans TRANS 803-581-5223 3200 [Jim.Vershans@trans.com](mailto:Jim.Vershans@trans.com)
- 24 Ron Jordan CPSC (301) 544-0508 (301) 544-4533 [rjordan@cpsc.gov](mailto:rjordan@cpsc.gov)
- 25 DAVED TUCHOLSKI X CPSC 301-413-0057 [d\\_tucholski@cpsc.gov](mailto:d_tucholski@cpsc.gov)
- 26 Hall Virgil Carrier Corp. 317 240 5291 317 481 5707 [Hall.Virgil@carrier.com](mailto:Hall.Virgil@carrier.com)
- 27 Dave Delaguida Honeywell 763-954-5532 763-954-4440 [dave.delaguida@honeywell.com](mailto:dave.delaguida@honeywell.com)
- 28 Mike Eberlein ICP 931-270-9450 931-270-5435 [mike.eberlein@icpsa.com](mailto:mike.eberlein@icpsa.com)
- 29 David Johnston X Washington Gas 703 750-4210 703 750-4210 [djohnston@washingtongas.com](mailto:djohnston@washingtongas.com)

GUESTS

NAME (Please Print) \_\_\_\_\_ MARK "X" \_\_\_\_\_ COMPANY/ORGANIZATION \_\_\_\_\_ PHONE NO. \_\_\_\_\_ FAX NO. \_\_\_\_\_ e-mail \_\_\_\_\_

- 30 KEITH BAIR X Olsen Technology 5191607-0791 519-627-8176 klbr@dsd.com
- 31 SPENCER LEONARD RADCO 219 463 7232 219 463 8258 —
- 32 JOHN SPANKO X ARMSTRONG-AIRCOND 419.483.4840 419.483.3557 JOHN.SPANKO@AARJNK.COM
- 33 P. E. BEACH WHITE-RODAGERS 4408351300 4408351304 pbeach@coppi.com
- 34 GARY P. THIBAUULT X GMMA 709-525-7000 709-525-6790 gthibault@gmma.com
- 35 ROBERT CARLTON X ICP 931-270-4132 931-270-5435 robert.carlton@icp.com
- 36 JOHN WIGEMAN X CSA INT. 589-4490 216-642-3081 CSAINTERNATIONAL@CSAINTERNATIONAL.COM
- 37 GLENN KROKOR RESTAURANT 519 360-1857 ghusone@xcelco.com
- 38 \_\_\_\_\_
- 39 \_\_\_\_\_
- 40 \_\_\_\_\_
- 41 \_\_\_\_\_
- 42 \_\_\_\_\_
- 43 \_\_\_\_\_
- 44 \_\_\_\_\_