333 Pfingsten Road Northbrook, Illinois 60062–2096 (847) 272–8800 FAX No. (847) 272–8129

FAX No. (847) 272-8129 MCI Mail No. 254-3343 Telex No. 6502543343



UL 1989 (N) - April 28, 1999





		was saur
	Deadline for Receipt	t: July 28, 1999
TOPIC:	Recognition of the Second Edition of the Standard for Safety for Standby Batteries, UL 1989, as an Updated American National Standard	
STATEMENT:	This standard is proposed for Standard.	or recognition as an Updated American National
QUESTION:	Should this standard be reco	ognized as an American National Standard?
YES		
NO	In accordance with ANSI procedures, in order to receive consideration, objections must be accompanied by supporting written reasons and, where possible, proposals for a solution to the problem raised. A negative ballot not accompanied by supporting written reasons will be recorded as a negative without comment and will not be circulated. Supporting reasons should be provided on a separate sheet.  If you cannot vote affirmatively or negatively and want to be recorded as abstaining, please state and explain the reasons for your abstention on the reverse side.	
ABSTAIN		
Signature <u>So</u>	iglas Luc	RETURN TO:
(Please Type or Print Below)  Name Douglas Lee		MITCHELL GOLD (Ext. 42850) Standards Department Underwriters Laboratories Inc.
Organization Represented	1.5. Consumer Product Safety Commission	333 Pfingsten Road Northbrook, IL 60062-2096 Fax Number (847) 509-6217
Phone Number	Satety Commission 301 504-0508 X	(1313
Date	7/26/99	

## Reason for abstention:

The staff of the U.S. Consumer Product Safety Commission (CPSC) are non-voting participants of the voluntary standards process.

At this time, the CPSC staff does not have any comments. A search of our incident databases revealed only limited data. The search revealed 7 accident investigations and 11 additional reported incidents related to standby batteries from January 1994 to the present. The products involved include 9 Uninterruptible Power Supplies (UPSs), 2 generators, 3 sump pumps, and 4 alarm systems.

Of the 7 accident investigations 1 involved a fire, 1 involved arcing, 4 involved emitting smoke, and 1 involved emitting hydrogen sulfide and carbon monoxide gases during charging. Of the 11 reported incidents 2 involved fire, 1 involved arcing, 2 involved emitting smoke, and 6 involved venting gases or acid.