

CHINESE DRYWALL INCIDENT INVESTIGATIONS - NATIONAL INJURY INFORMATION CLEARINGHOUSE

1 090504CBB1655 H0930229A SOURCE: CONSUMER COMPLAINT TYPE : ONSITE STATUS : C
 DATE INCIDENT: 070301 DATE ENTERED : 090520 CITY/STATE : BOYNTON BEACH, FL LOCATION : HOME
 AGE/SEX : 035 / M DISP : TR/REL DIAGNOSIS : POISONING BODYPART : ALL PARTS BODY
 1ST PRODUCT : 1876 HOUSE REPAIR OR CONSTRUCTION MAT'L NEC
 2ND PRODUCT : 4062 ELECTRIC WIRE OR WIRING SYSTEMS (EXCL.
 NARRATIVE : THE COMPLAINANTS, A 35 YEAR OLD MALE AND 36 YEAR OLD FEMALE MOVED INTO THE NEW HOUSE IN MARCH 2007. THE HOUSE WAS BUILT WITH IMPORTED CHINESE DRYWALL IN APRIL 2005. THE TWO AIR CONDITIONING UNITS IN THE HOUSE HAVE HAD TO BE RECHARGED WITH REFRIGERANT AND HAVE EVAPORATOR COILS REPLACED AND/OR PATCHED. THEY HAVE EXPERIENCED HEALTH ISSUES SUCH AS SEVERE ALLERGIES, HEADACHES, AND RESPIRATORY INFECTIONS. THEY ARE CONCERNED WITH THE LONG TERM HEALTH EFFECTS AND POSSIBLE SAFETY ISSUES.

2 090504CBB1658 H0940083A SOURCE: CONSUMER COMPLAINT TYPE : ONSITE STATUS : C
 DATE INCIDENT: 090406 DATE ENTERED : 090603 CITY/STATE : CAPE CORAL, FL LOCATION : HOME
 AGE/SEX : 063 / F DISP : TR/REL DIAGNOSIS : POISONING BODYPART : ALL PARTS BODY
 1ST PRODUCT : 1876 HOUSE REPAIR OR CONSTRUCTION MAT'L NEC
 2ND PRODUCT : 4062 ELECTRIC WIRE OR WIRING SYSTEMS (EXCL.
 NARRATIVE : THE 63 YEAR OLD HOMEOWNER AND HER 41 YEAR OLD DAUGHTER HAVE EXPERIENCED HEADACHES, SKIN IRRITATION, RUNNY NOSES AND CONGESTION SINCE MOVING INTO A NEW HOUSE IN AUGUST 2006. THE ELECTRICAL WIRING HAVE CAUSED THE LIGHTS TO FLICKER ON AND OFF AND THE SMOKE ALARMS ACTIVATE FOR NO REASON. ALSO, THE HOT WATER HEATER'S COPPER PIPES HAVE TURNED BLACK AND THERE IS PITTING ON THE FAUCETS, LIGHT FIXTURES AND MIRRORS IN THE HOME. THE DRYWALL MANUFACTURER IS A U.S. BASED FIRM BUT THE CONSUMER BELIEVES THE DRYWALL WAS MADE IN CHINA.

3 090504CBB1661 H0940126A SOURCE: CONSUMER COMPLAINT TYPE : ONSITE STATUS : C
 DATE INCIDENT: 070315 DATE ENTERED : 090602 CITY/STATE : LEHIGH ACRES, FL LOCATION : HOME
 AGE/SEX : 065 / M DISP : TR/REL DIAGNOSIS : POISONING BODYPART : ALL PARTS BODY
 1ST PRODUCT : 1876 HOUSE REPAIR OR CONSTRUCTION MAT'L NEC
 2ND PRODUCT : 0381 AIR CONDITIONERS
 NARRATIVE : A 65 YEAR OLD MALE HAS EXPERIENCED SINUS PROBLEMS, HEADACHES, THROAT IRRITATION AND INSOMNIA SINCE MOVING INTO A HOUSE IN LEHIGH ACRES, FL THAT WAS BUILT IN 2006. ACCORDING TO THE CONSUMER, THE AIR CONDITIONER EVAPORATOR COILS HAVE TURNED BLACK AND WILL HAVE TO BE REPLACED. THE CONSUMER ALSO REPORTED THAT THE CIRCUIT BREAKERS TRIP FOR NO APPARENT REASON. THE CONSUMER BELIEVES THAT CHINESE DRYWALL WAS USED INSIDE THE HOME.

4 090504CBB1664 H0930251A SOURCE: CONSUMER COMPLAINT TYPE : ONSITE STATUS : C
 DATE INCIDENT: 061102 DATE ENTERED : 090526 CITY/STATE : BOYNTON BEACH, FL LOCATION : HOME
 AGE/SEX : 034 / M DISP : TR/REL DIAGNOSIS : POISONING BODYPART : ALL PARTS BODY
 1ST PRODUCT : 1876 HOUSE REPAIR OR CONSTRUCTION MAT'L NEC
 2ND PRODUCT : 0381 AIR CONDITIONERS
 NARRATIVE : THE 34 YEAR OLD COMPLAINANT, HIS WIFE, AND FOUR MONTH OLD DAUGHTER HAVE EXPERIENCED HEALTH ISSUES AS A RESULT OF THE IMPORTED DRYWALL FROM CHINA USED IN THE CONSTRUCTION OF THEIR HOME. HE HAS NOTICED A VERY STRONG ODOR THAT HE DESCRIBES AS A CHOKING AND SUFFOCATING SULFUR SMELL. THEY HAVE EXPERIENCED COUGHING, ITCHING, BURNING AND WATERY EYES, AND INCREASED ASTHMA SYMPTOMS. THE COMPLAINANT HAS HAD TO REPLACE APPLIANCES BECAUSE THEY STOP WORKING UNITS IN THE HOME. HE HAS HAD REPEATED ISSUES WITH THE AIR CONDITIONING UNITS IN THE HOME. HE IS CONCERNED ABOUT THE LONG TERM HEALTH AFFECTS OF THIS PROBLEM.

CPSA 600(D) CLEARED for PUBLIC
 NO AFRSPRYTBLERS OR
 PRODUCTS IDENTIFIED
 1/21/09

EXCEPTED BY: PETITION
 RULEMAKING ADMIN. PRCDG
 WITH PORTIONS REMOVED:

CHINESE DRYWALL
INCIDENT INVESTIGATIONS
U.S. CONSUMER PRODUCT SAFETY COMMISSION - NATIONAL INJURY INFORMATION CLEARINGHOUSE

5 090504CBB1676 H0930258A SOURCE: CONSUMER COMPLAINT TYPE : ONSITE STATUS : C
 DATE INCIDENT : 061200 DATE ENTERED : 090528 CITY/STATE : PARKLAND, FL LOCATION : HOME
 AGE/SEX : 057 / M DISP : TR/REL DIAGNOSIS : INTERNAL INJURY BODYPART : NOT STATED/UNK
 1ST PRODUCT : 1876 HOUSE REPAIR OR CONSTRUCTION MAT'L NEC
 NARRATIVE : THE CONSUMER AND HIS WIFE HAVE EXPERIENCE HEALTH ISSUES, AN AIR CONDITIONING EVAPORATOR COIL FAILURE, AND METAL CORROSION ISSUES THAT SINCE PURCHASING THEIR RESIDENCE IN 2006. THE CONSUMER BELIEVES THAT IMPORTED DRYWALL FROM CHINA WAS USED IN CONSTRUCTING HIS RESIDENCE, AND THAT THE DRYWALL IS EMITTING CHEMICALS INTO THE ATMOSPHERE OF THE RESIDENCE AND RESULTING IN SOME OR ALL OF THE AFOREMENTIONED ISSUES.

6 090504CBB3554 10940279A SOURCE: CONSUMER COMPLAINT TYPE : ONSITE STATUS : C
 DATE INCIDENT : 050200 DATE ENTERED : 090604 CITY/STATE : SAN JUAN CAPISTRA, CA LOCATION : HOME
 AGE/SEX : 049 / F DISP : UNK DIAGNOSIS : HEMORRHAGE BODYPART : FACE
 1ST PRODUCT : 1876 HOUSE REPAIR OR CONSTRUCTION MAT'L NEC
 NARRATIVE : AFTER A HOUSE FIRE, THE DAMAGED AREAS OF THE HOME WERE REPAIRED USING REPLACEMENT DRYWALL. SOMETIME AFTER THE REPAIRS, A 49 YEAR-OLD WOMAN LIVING IN THE HOME EXPERIENCED BLOODY SINUS CAVITIES EVERYDAY FOR APPROXIMATELY THREE MONTHS.

7 090504CBB3555 10940364A SOURCE: CONSUMER COMPLAINT TYPE : ONSITE STATUS : C
 DATE INCIDENT : 080915 DATE ENTERED : 090529 CITY/STATE : LAKE HAVASU CITY, AZ LOCATION : HOME
 AGE/SEX : 047 / F DISP : TR/REL DIAGNOSIS : OTHER BODYPART : HEAD
 1ST PRODUCT : 1876 HOUSE REPAIR OR CONSTRUCTION MAT'L NEC
 NARRATIVE : 0960 PAINTS, VARNISHES OR SHELLACS THAT DRYWALL WAS CAUSING HER AND HER SPOUSE TO SUFFER HEADACHES, TIREDNESS, BLOODY NOSES, AND OTHER SYMPTOMS. THESE SYMPTOMS BEGAN TWO TO THREE MONTHS AFTER RETURNING TO THEIR SELF-BUILT HOME. THE DRYWALL IN QUESTION WAS INSTALLED BY THE CONSUMER WHILE BUILDING TWO ROOM ADDITIONS TO THEIR HOME. THE SYMPTOMS WOULD GO AWAY AFTER LIVING OUTSIDE OF THE HOME FOR ABOUT ONE WEEK. THEY HAVE NOT SOUGHT ANY MEDICAL ATTENTION FOR THEIR SYMPTOMS.

8 090505CBB1680 H0940273A SOURCE: CONSUMER COMPLAINT TYPE : ONSITE STATUS : C
 DATE INCIDENT : 040101 DATE ENTERED : 090521 CITY/STATE : VERO BEACH, FL LOCATION : HOME
 AGE/SEX : 054 / F DISP : TR/REL DIAGNOSIS : POISONING BODYPART : ALL PARTS BODY
 1ST PRODUCT : 1876 HOUSE REPAIR OR CONSTRUCTION MAT'L NEC
 NARRATIVE : THE MALE AND FEMALE COMPLAINANTS, BOTH 54 YEARS OLD, MOVED INTO THE NEWLY BUILT HOUSE IN DECEMBER 2001. THE HOUSE WAS CONSTRUCTED USING IMPORTED DRYWALL FROM CHINA. IN 2004, THEY STARTED TO NOTICE HEALTH ISSUES SUCH AS HEADACHES, BURNING SENSATION IN THE THROAT, AND PROBLEMS WITH VISION. THEY ARE CONCERNED WITH THE LONG TERM HEALTH EFFECTS THEY FACE IN THE FUTURE.

9 090505CBB1685 H0940137A SOURCE: CONSUMER COMPLAINT TYPE : ONSITE STATUS : C
 DATE INCIDENT : 061000 DATE ENTERED : 090608 CITY/STATE : POMPANO BEACH, FL LOCATION : HOME
 AGE/SEX : 050 / F DISP : TR/REL DIAGNOSIS : POISONING BODYPART : ALL PARTS BODY
 1ST PRODUCT : 1876 HOUSE REPAIR OR CONSTRUCTION MAT'L NEC
 NARRATIVE : THE 50 YEAR-OLD FEMALE CONSUMER AND HER HUSBAND HAVE EXPERIENCED HEALTH ISSUES, AN AIR CONDITIONING EVAPORATOR COIL FAILURE, AND METAL CORROSION ISSUES SINCE PURCHASING THEIR TOWNHOME IN 2007. THE CONSUMER BELIEVES THAT IMPORTED DRYWALL FROM CHINA WAS USED IN CONSTRUCTING HER TOWNHOME, AND THAT THE DRYWALL IS EMITTING CHEMICALS INTO THE ATMOSPHERE OF THE RESIDENCE AND RESULTING IN SOME OR ALL OF THE AFOREMENTIONED ISSUES. NO IDENTIFYING INFORMATION WAS AVAILABLE FOR THE DRYWALL.

10 090505CBB1688 H09401414 SOURCE: CONSUMER COMPLAINT TYPE : ONSITE
 DATE INCIDENT : 080301 DATE ENTERED : 090521 CITY/STATE : SEBASTIAN, FL STATUS : C
 AGE/SEX : 044 / F DISP : TR/REL DIAGNOSIS : POISONING BODYPART : ALL PARTS BODY
 1ST PRODUCT : 1876 HOUSE REPAIR OR CONSTRUCTION MAT'L NEC
 2ND PRODUCT : 4062 ELECTRIC WIRE OR WIRING SYSTEMS (EXCL.
 NARRATIVE : THE 44 YEAR OLD FEMALE COMPLAINANT OCCUPIES THE HOME BUILT USING
 IMPORTED DRYWALL FROM CHINA WITH HER 34 YEAR OLD HUSBAND, 16 YEAR
 OLD SON, 4 YEAR OLD DAUGHTER. THEY HAVE EXPERIENCED ISSUES INCLUDING
 UPPER RESPIRATORY INFECTIONS, BRONCHITIS, CONGESTION, AND ALLERGIES
 SINCE MOVING INTO THE HOME. THEY HAVE ALSO NOTICED BLACKENING,
 PITTING, AND CORROSION ON METAL SURFACES AND COPPER PIPES. THE
 COMPLAINANT IS CONCERNED WITH THE LONG TERM HEALTH EFFECTS HER
 FAMILY WILL EXPERIENCE.

11 090506CBB2608 X0950039A SOURCE: GOVERNMENT REFERRAL TYPE : ONSITE
 DATE INCIDENT : 090500 DATE ENTERED : 090520 CITY/STATE : SNEAD, AL STATUS : C
 AGE/SEX : 031 / F DISP : TR/REL DIAGNOSIS : OTHER BODYPART : ALL PARTS BODY
 1ST PRODUCT : 1876 HOUSE REPAIR OR CONSTRUCTION MAT'L NEC
 NARRATIVE : A 31-YEAR OLD WOMAN, HER 28-YEAR OLD HUSBAND AND THEIR 15-MONTH OLD
 SON HAVE ALL BEEN EXPERIENCING HEALTH PROBLEMS SINCE LIVING IN THEIR
 NEW HOME. CONSTRUCTION BEGAN ON THE HOUSE IN AUGUST 2004 AND THE
 COMPLAINANT AND HER HUSBAND MOVED IN DECEMBER 2004. IN FEBRUARY 2005
 THEY BEGAN EXPERIENCING UPPER RESPIRATORY TRACT INFECTIONS, FOLLOWED
 BY STAPH INFECTIONS. THEIR SON HAD HIS FIRST UPPER RESPIRATORY TRACT
 INFECTION IN FEBRUARY 2008. THE COMPLAINANT HAS ALSO HAD PROBLEMS
 WITH THE ELECTRIC DRYER AND STOVE AND AIR CONDITIONER'S PROGRAM BOX.

CHINESE DRYWALL INCIDENT INVESTIGATIONS

1 090224CNE4204 10920537A SOURCE: 47 TYPE : ONSITE
DATE INCIDENT: 090224 DATE ENTERED : 090305 CITY/STATE : SEBRING, FL STATUS : C
AGE/SEX : 031 / F DISP : TR/REL DIAGNOSIS : POISONING BODYPART : ALL PARTS BODY
1ST PRODUCT : 1876 HOUSE REPAIR OR CONSTRUCTION MAT'L NEC
2ND PRODUCT : 4062 ELECTRIC WIRE OR WIRING SYSTEMS (EXCL.)
NARRATIVE : THE 31 YEAR OLD FEMALE HAD BEEN EXPERIENCING SINUS PROBLEMS SINCE SHE
MOVED INTO HER NEW HOME IN 2006. SHE DISCOVERED IT HAD SHEETROCK
WITH SULPHUR WHICH WAS PROBABLY AFFECTING HER SINUS. HER AIR
CONDITIONER COILS HAD BEEN REPLACED THREE TIMES, NUMEROUS ELECTRICAL
APPLIANCES HAD FAILED AND SHE WAS CONCERNED ABOUT HER LONG TERM
HEALTH EFFECTS AND POSSIBLE FIRE OR SHORTAGE TO HER ELECTRICAL
PRODUCTS.

2 090504CBB1656 10940055A SOURCE: 47 TYPE : ONSITE
DATE INCIDENT: 061201 DATE ENTERED : 090521 CITY/STATE : BOYNTON BEACH, FL STATUS : C
AGE/SEX : 042 / M DISP : TR/REL DIAGNOSIS : POISONING BODYPART : ALL PARTS BODY
1ST PRODUCT : 1876 HOUSE REPAIR OR CONSTRUCTION MAT'L NEC
2ND PRODUCT : 4062 ELECTRIC WIRE OR WIRING SYSTEMS (EXCL.)
NARRATIVE : THE 42 YEAR OLD MALE AND 46 YEAR OLD FEMALE COMPLAINANTS MOVED INTO
THE NEW HOME IN DECEMBER 2006. THE HOME WAS BUILT USING IMPORTED
CHINESE DRYWALL. THE COMPLAINANTS HAVE HAD TO REPLACE EVAPORATOR
COILS IN ONE OF THE AIR CONDITIONING UNITS. THEY ALSO HAVE NOTICE
PITTING, BLACKENING AND CORROSION ON COPPER PIPES AND METAL FIXTURES
THROUGHOUT THE HOME. THE MALE COMPLAINANT HAS HAD ISSUES WITH SINUS
INFECTIONS SINCE MOVING INTO THE HOME. THEY ARE CONCERNED WITH THE
LONG TERM HEALTH EFFECTS AND FINANCIAL BURDEN OF REPAIRING THEIR
HOME.

3 090504CBB1660 10940152A SOURCE: 47 TYPE : ONSITE
DATE INCIDENT: 090304 DATE ENTERED : 090603 CITY/STATE : FORT MYERS, FL STATUS : C
AGE/SEX : 019 / F DISP : TR/REL DIAGNOSIS : POISONING BODYPART : ALL PARTS BODY
1ST PRODUCT : 1876 HOUSE REPAIR OR CONSTRUCTION MAT'L NEC
2ND PRODUCT : 1876 HOUSE REPAIR OR CONSTRUCTION MAT'L NEC
NARRATIVE : THE 48 YEAR OLD CONSUMER AND HER 48 YEAR OLD HUSBAND PURCHASED A
HOUSE IN FORT MYERS, FL IN DECEMBER 2008. THE CONSUMER'S 19 YEAR OLD
SON, HIS 19 YEAR OLD GIRLFRIEND AND A 20 YEAR OLD MALE LIVE IN THE
HOUSE. THE CONSUMER STATED THAT HER SON AND HIS FRIENDS HAVE
EXPERIENCED SEVERE HEADACHES AND SORE THROATS SINCE MOVING INTO THE
HOUSE AND THE HOME'S COPPER WIRING AND METAL FIXTURES ARE CORRODING.
THE CONSUMER BELIEVES THAT CHINESE DRYWALL WAS USED IN THE HOUSE.

4 090504CBB1662 10940125A SOURCE: 47 TYPE : ONSITE
DATE INCIDENT: 090404 DATE ENTERED : 090528 CITY/STATE : JUPITER, FL STATUS : C
AGE/SEX : 038 / M DISP : TR/REL DIAGNOSIS : POISONING BODYPART : ALL PARTS BODY
1ST PRODUCT : 1876 HOUSE REPAIR OR CONSTRUCTION MAT'L NEC
2ND PRODUCT : 0381 AIR CONDITIONERS
NARRATIVE : THE FAMILY OF FOUR HAS BEEN SUFFERING FROM SINUS CONGESTION, NOSE
BLEEDS, PNEUMONIA, WATERY EYES, CHRONIC COUGH, ETC., WHICH THE
OWNERS BELIEVE WERE CAUSED BY CONTAMINATED CHINESE DRYWALL USED IN
THE CONSTRUCTION OF THEIR HOME. ONE OF THEIR DOGS HAS PERIODIC NOSE
BLEEDS. THE HOME HAS TWO AC UNITS AND THE INSIDE COILS HAVE BEEN
REPLACED FOUR TIMES. THE FAMILY HAS BEEN LIVING IN THEIR NEW HOME
SINCE MAY OF 2006 AND THE COPPER WATER SUPPLY LINES HAVE BLACKENED
ALONG WITH PITTING OF SOME OF THE BATHROOM FIXTURES. NO LABELLING
COULD BE LOCATED ON THE SHEETROCK.

CHINESE DRYWALL INCIDENT INVESTIGATIONS - NATIONAL INJURY INFORMATION CLEARINGHOUSE U.S. CONSUMER PRODUCT SAFETY COMMISSION

5 090504CBB81666 H0940332A SOURCE: CONSUMER COMPLAINT TYPE : ONSITE
 DATE INCIDENT: 061201 DATE ENTERED : 090526 CITY/STATE : LAKE CITY, FL STATUS : HOME
 AGE/SEX : 030 / F DISP : TR/REL DIAGNOSIS : POISONING BODYPART : ALL PARTS BODY
 1ST PRODUCT : 1876 HOUSE REPAIR OR CONSTRUCTION MAT'L NEC
 2ND PRODUCT : 4061 ELECTRICAL OUTLETS OR RECEPTACLES
 NARRATIVE : THE 30 YEAR OLD FEMALE COMPLAINANT, HER HUSBAND, AND FOUR CHILDREN HAVE ALL EXPERIENCED NUMEROUS HEALTH ISSUES INVOLVING SINUS AND RESPIRATORY AILMENTS, DUE TO IMPORTED DRYWALL FROM CHINA USED IN BUILDING THEIR HOME. THE COMPLAINANT HAS EXPERIENCED ISSUES WITH APPLIANCES AND OBSERVED BLACKENING, PITTING, AND CORROSION ON METAL FIXTURES IN THE HOUSE. ON A CONSISTENT BASIS FOR NO APPARENT REASON, FLICKERING LIGHTS, CIRCUIT BREAKERS TRIPPING FOR NO APPARENT REASON, ARCS OR SPARKS IN ELECTRICAL SYSTEM, AND SIZZLING OR BUZZING. SHE IS CONCERNED WITH THE HEALTH OF HER FAMILY DUE TO THIS PROBLEM.

6 090504CBB81667 10930625A SOURCE: : 47 TYPE : PHONE
 DATE INCIDENT: 041025 DATE ENTERED : 090527 CITY/STATE : GULF BREEZE, FL STATUS : HOME
 AGE/SEX : 046 / F DISP : 0 DIAGNOSIS : NOT STATED OR UNK BODYPART : 99
 1ST PRODUCT : 1876 HOUSE REPAIR OR CONSTRUCTION MAT'L NEC
 NARRATIVE : THE 46 YEAR OLD FEMALE COMPLAINANT'S HOME WAS FLOODED WITH FIVE FEET OF WATER FROM HURRICANE IVAN. THE HOME WAS SEVERELY DAMAGED AND HAD TO BE RENOVATED. DRYWALL WAS REPLACED THROUGHOUT THE HOME. THERE WERE NO INJURIES. BUT THE CONSUMER IS SUFFERING FROM HEADACHES AS A SIDE EFFECT FROM THE REPLACED DRYWALL. THE COMPLAINANT DID NOT KNOW THE EXACT AMOUNT OF THE PROPERTY DAMAGE, BUT IT WAS IN EXCESS OF OVER \$100,000 DOLLARS.

7 090504CBB81673 10930544A SOURCE: : 47 TYPE : ONSITE
 DATE INCIDENT: 060700 DATE ENTERED : 090601 CITY/STATE : MIAMI, FL STATUS : HOME
 AGE/SEX : 037 / M DISP : TR/REL DIAGNOSIS : POISONING BODYPART : ALL PARTS BODY
 1ST PRODUCT : 1876 HOUSE REPAIR OR CONSTRUCTION MAT'L NEC
 2ND PRODUCT : 0381 AIR CONDITIONERS
 NARRATIVE : A 37 YEAR OLD MALE, HIS WIFE (33) AND 3 CHILDREN (AGES 8, 10, & 16) MOVED INTO A NEW HOME IN JUNE 2006. IT WAS REPORTED THAT CHINESE DRYWALL IN THE HOME HAS CAUSED A NUMBER OF HEALTH ISSUES (SINUS PROBLEMS, HEADACHES, FATIGUE, RED EYES, NOSE BLEEDS, ITCHING, SLEEP APNEA). APPLIANCES HAVE CEASED TO FUNCTION. BLACKENING AND DISCOLORATION OF COPPER PIPES AND METAL FIXTURES THROUGHOUT THE HOME HAVE BEEN OBSERVED. CORROSION WITHIN THE AC UNIT IS EVIDENT. LONG TERM HEALTH RISKS AND FINANCIAL BURDEN OF REPAIRING THE HOME IS STILL OF CONCERN.

8 090504CBB81679 10930787A SOURCE: : 47 TYPE : ONSITE
 DATE INCIDENT: 061200 DATE ENTERED : 090611 CITY/STATE : PARKLAND, FL STATUS : HOME
 AGE/SEX : 004 / M DISP : TR/REL DIAGNOSIS : POISONING BODYPART : ALL PARTS BODY
 1ST PRODUCT : 1876 HOUSE REPAIR OR CONSTRUCTION MAT'L NEC
 NARRATIVE : THE CONSUMER, HIS WIFE AND THEIR TWO CHILDREN HAVE EXPERIENCE HEALTH ISSUES, AN AIR CONDITIONING EVAPORATOR COIL FAILURE, AND METAL CORROSION ISSUES SINCE PURCHASING THEIR RESIDENCE IN 2006. THE CONSUMER BELIEVES THAT IMPORTED DRYWALL FROM CHINA WAS USED IN CONSTRUCTING HIS RESIDENCE, AND THAT THE DRYWALL IS EMITTING CHEMICALS INTO THE ATMOSPHERE OF THE RESIDENCE AND RESULTING IN SOME OR ALL OF THE AFOREMENTIONED ISSUES.

CHINESE DRYWALL INCIDENT INVESTIGATIONS
U.S. CONSUMER PRODUCT SAFETY COMMISSION - NATIONAL INJURY INFORMATION CLEARINGHOUSE

9 090505CBB1683 10930741A SOURCE: 47 TYPE : ONSITE STATUS : C
 DATE INCIDENT: 090329 DATE ENTERED : 090617 CITY/STATE : SATSUMA, FL LOCATION : HOME
 AGE/SEX : 045 / M DISP : TR/REL DIAGNOSIS : POISONING BODYPART : ALL PARTS BODY
 1ST PRODUCT : 1876 HOUSE REPAIR OR CONSTRUCTION MAT'L NEC
 2ND PRODUCT : 0381 AIR CONDITIONERS
 NARRATIVE : THE FAMILY OF THREE NOTICED A SULPHUR SMELL IMMEDIATELY UPON MOVING INTO THEIR NEW HOME IN 2005. THE WIFE AND SON BEGAN HAVING RESPIRATORY AND SINUS PROBLEMS IMMEDIATELY AND THE HUSBAND TWO MONTHS LATER. THE HOME'S A/C COIL WAS REPLACED IN AUGUST OF 2006. THE FAMILY THOUGHT THE CAUSE OF THEIR HEALTH PROBLEMS WAS DUE TO CURING CARPET PAINT AND THE NEW ENVIRONMENT UNTIL THEY SAW A REPORT ON THE NEWS OF THEIR SAME HEALTH ISSUES.

10 090505CBB1687 10930789A SOURCE: 47 TYPE : ONSITE STATUS : C
 DATE INCIDENT: 061101 DATE ENTERED : 090519 CITY/STATE : PORT SAINT LUCIE, FL LOCATION : HOME
 AGE/SEX : 047 / F DISP : TR/REL DIAGNOSIS : POISONING BODYPART : ALL PARTS BODY
 1ST PRODUCT : 1876 HOUSE REPAIR OR CONSTRUCTION MAT'L NEC
 2ND PRODUCT : 0381 AIR CONDITIONERS
 NARRATIVE : THE 47 YEAR-OLD FEMALE AND MALE HOMEOWNERS ARE CONCERNED WITH THE LONG TERM HEALTH EFFECTS AND POSSIBLE SAFETY ISSUES INVOLVING THE IMPORTED DRYWALL USED TO BUILD THEIR HOME. THEY MOVED INTO THE NEW HOME IN NOVEMBER 2006. IN THE FIRST YEAR THEY HAVE NOTICED HEALTH ISSUES INVOLVING FREQUENT HEADACHES, NAUSEA, COUGHING, RASHES, AND BURNING AND WATERY EYES. IN THE FIRST 13 MONTHS THEY REPLACED THE AIR CONDITIONING EVAPORATOR COILS FOUR TIMES DUE TO FREON LEAKAGE AND CORROSION. IN NOVEMBER 2008, THEY HAD TO REPLACE THE ENTIRE AIR CONDITIONING SYSTEM DUE TO THE SAME PROBLEMS.

11 090521CBB1732 108C0627A SOURCE: 47 TYPE : ONSITE STATUS : C
 DATE INCIDENT: 081226 DATE ENTERED : 090615 CITY/STATE : BRADENTON, FL LOCATION : HOME
 AGE/SEX : 037 / M DISP : TR/REL DIAGNOSIS : POISONING BODYPART : ALL PARTS BODY
 1ST PRODUCT : 1876 HOUSE REPAIR OR CONSTRUCTION MAT'L NEC
 2ND PRODUCT : 0381 AIR CONDITIONERS
 NARRATIVE : THE 37 YEAR OLD FEMALE DIDN'T NOTICE ANY ODORS OF SULPHUR FOR THE FIRST YEAR SHE WAS IN HER NEW 2005 BUILT HOME, BUT FOR UNKNOWN REASONS THE ACIDIC SULPHUR SMELL STARTED SHORTLY AFTER PAINTING ACCENT WALLS IN HER HOME. SHE CUT HOLES IN HER DRYWALLS AND IDENTIFIED THE CHINESE MANUFACTURER AND IMPORTER. ALSO, THE AIR CONDITIONER QUIT WORKING AND APPEARED TO HAVE CORRODED COILS AND LEAKING FREON AND. SHE WAS UNABLE TO TOLERATE THE SMELL AND HEALTH AFFECTS AND MOVED OUT OF HER HOME IN NOVEMBER OF 2007. SHE ENDED UP WITH HEADACHES, A SINUS INFECTION/BRONCHITIS, IRRITATED ITCHY EYES, SCRATCHY THROAT AND COUGHING.

U.S. CONSUMER PRODUCT SAFETY COMMISSION - NATIONAL INJURY INFORMATION CLEARINGHOUSE
CHINESE DRYWALL INCIDENT INVESTIGATIONS

1 090504CBB1657 10940830A SOURCE: 47 TYPE : ONSITE STATUS : C
 DATE INCIDENT : 090414 DATE ENTERED : 090526 CITY/STATE : ESTERO, FL LOCATION : HOME
 AGE/SEX : 062 / F DISP : TR/REL DIAGNOSIS : OTHER BODYPART : EYEBALL
 1ST PRODUCT : 1876 HOUSE REPAIR OR CONSTRUCTION MAT'L NEC
 2ND PRODUCT : 0381 AIR CONDITIONERS
 NARRATIVE : THE 70 YEAR OLD MALE CONSUMER REPORTED THAT HE EXPERIENCED CONSTANT HEADACHES AND HIS 62 YEAR OLD WIFE SUFFERED EYE IRRITATION DURING A RECENT VISIT TO THEIR RETIREMENT HOME IN ESTERO, FL. IN ADDITION TO THEIR HEALTH PROBLEMS, THE CONSUMER STATED THAT THE AIR CONDITIONER'S COILS AND THE COPPER WIRING INSIDE A LIGHT SWITCH IN THE HOME'S FOYER HAVE BEEN CORRODED BY SULFURIC MIST FROM CHINESE DRYWALL USED TO MANUFACTURE THE HOME IN 2005.

2 090504CBB1659 10940441A SOURCE: 47 TYPE : ONSITE STATUS : C
 DATE INCIDENT : 090416 DATE ENTERED : 090528 CITY/STATE : FT. LAUDERDALE, FL LOCATION : HOME
 AGE/SEX : 031 / M DISP : TR/REL DIAGNOSIS : POISONING BODYPART : ALL PARTS BODY
 1ST PRODUCT : 1876 HOUSE REPAIR OR CONSTRUCTION MAT'L NEC
 2ND PRODUCT : 0381 AIR CONDITIONERS
 NARRATIVE : THE FAMILY OF THREE HAD CONTINUOUS RESPIRATORY PROBLEMS SINCE MOVING INTO THE HOME, WHICH IS BELIEVED WERE CAUSED BY CONTAMINATED CHINESE DRYWALL USED IN THE CONSTRUCTION OF THEIR HOME. THE HOME HAD BLACKENED COPPER WATER SUPPLY LINES AND THE AC COILS HAD BEEN REPLACED ONCE SINCE THE HOME WAS BUILT IN 2006.

3 090504CBB1663 10940533A SOURCE: 47 TYPE : ONSITE STATUS : C
 DATE INCIDENT : 060000 DATE ENTERED : 090603 CITY/STATE : CAPE CORAL, FL LOCATION : HOME
 AGE/SEX : 062 / F DISP : TR/REL DIAGNOSIS : POISONING BODYPART : ALL PARTS BODY
 1ST PRODUCT : 1876 HOUSE REPAIR OR CONSTRUCTION MAT'L NEC
 2ND PRODUCT : 0381 AIR CONDITIONERS
 NARRATIVE : A 64 YEAR OLD MALE AND HIS 62 YEAR OLD WIFE HAVE EXPERIENCED HEALTH PROBLEMS FROM THEIR DRYWALL SINCE MOVING INTO A NEW HOUSE IN CAPE CORAL, FL IN 2006. EVAPORATOR COILS IN THE AIR CONDITIONING UNITS AND PLUMBING FIXTURES IN THE BATHROOMS HAVE ALSO BEEN REPLACED DUE TO CORROSION. DRYWALL USED IN THE HOUSE WAS LABELED: "MADE IN CHINA."

4 090504CBB1665 10940378A SOURCE: 47 TYPE : ONSITE STATUS : C
 DATE INCIDENT : 090410 DATE ENTERED : 090601 CITY/STATE : FORT MYERS, FL LOCATION : HOME
 AGE/SEX : 044 / M DISP : TR/REL DIAGNOSIS : POISONING BODYPART : ALL PARTS BODY
 1ST PRODUCT : 1876 HOUSE REPAIR OR CONSTRUCTION MAT'L NEC
 2ND PRODUCT : 0381 AIR CONDITIONERS
 NARRATIVE : A 44 YEAR OLD MALE, HIS 49 YEAR OLD WIFE AND THEIR 12 YEAR OLD SON HAVE EXPERIENCED SHORTNESS OF BREATH, NOSE BLEEDS, MIGRAINE HEADACHES AND SINUS PROBLEMS AFTER MOVING INTO A NEW HOME IN AUGUST 2008. THE HOUSE WAS BUILT IN 2006 BUT THE CONSUMERS WERE THE FIRST OCCUPANTS. SINCE MOVING INTO THE HOUSE THE AIR CONDITIONERS' EVAPORATOR COILS HAVE BEEN REPLACED, THE REFRIGERATOR COILS HAVE TURNED BLACK AND THE ELECTRICAL WIRING HAS CORRODED. THE CONSUMERS BELIEVE CHINESE DRYWALL WAS USED TO BUILD THE HOUSE AND WAS THE CAUSE OF THE FAMILY'S HEALTH PROBLEMS.

CHINESE DRYWALL INCIDENT INVESTIGATIONS
 U.S. CONSUMER PRODUCT SAFETY COMMISSION - NATIONAL INJURY INFORMATION CLEARINGHOUSE

5 090504CBB81672 10940291A SOURCE: 47 TYPE : ONSITE
 DATE INCIDENT : 090412 DATE ENTERED : 090603 CITY/STATE : HOMESTEAD, FL STATUS : C
 AGE/SEX : 031 / M DISP : TR/REL DIAGNOSIS : POISONING BODYPART : ALL PARTS BODY
 1ST PRODUCT : 1876 HOUSE REPAIR OR CONSTRUCTION MAT'L NEC
 2ND PRODUCT : 0381 AIR CONDITIONERS
 NARRATIVE : THE FAMILY OF 4 HAD BEEN EXPERIENCING HEALTH EFFECTS THEY BELIEVE ARE CAUSED BY CHINESE DRYWALL INCLUDING MAINLY RESPIRATORY AND SKIN ITCHING PROBLEMS. THE HAD EXPERIENCED SOME ELECTRICAL PROBLEMS, APPLIANCE FAILURE AND LIGHT FIXTURE PROBLEMS. THEIR A/C HAD NOT BEEN REPLACED BUT SHOWED A GREAT DEAL OF RUST/CORROSION WHEN EXAMINED.

6 090505CBB81684 10940496A SOURCE: 47 TYPE : ONSITE
 DATE INCIDENT : 090418 DATE ENTERED : 090603 CITY/STATE : RIVERVIEW, FL STATUS : C
 AGE/SEX : 050 / F DISP : TR/REL DIAGNOSIS : POISONING BODYPART : ALL PARTS BODY
 1ST PRODUCT : 1876 HOUSE REPAIR OR CONSTRUCTION MAT'L NEC
 2ND PRODUCT : 4062 ELECTRIC WIRE OR WIRING SYSTEMS (EXCL.
 NARRATIVE : A FAMILY OF FIVE EXPERIENCED SERIOUS HEALTH EFFECTS AND ELECTRICAL PROBLEMS TO THEIR HOME FROM CHINESE DRYWALL. ELECTRICAL WIRING HAD TURNED BLACK, APPLIANCES HAD FAILED AND BREAKERS WOULD TRIP. THE BUILDER AGREED TO MOVE THE FAMILY OUT OF THE HOME AND REPLACE DRYWALL, WIRING AND APPLIANCES.

7 090505CBB81686 10940472A SOURCE: 47 TYPE : ONSITE
 DATE INCIDENT : 051201 DATE ENTERED : 090526 CITY/STATE : PORT SAINT LUCIE, FL STATUS : C
 AGE/SEX : 050 / F DISP : TR/REL DIAGNOSIS : POISONING BODYPART : ALL PARTS BODY
 1ST PRODUCT : 1876 HOUSE REPAIR OR CONSTRUCTION MAT'L NEC
 2ND PRODUCT : 4061 ELECTRICAL OUTLETS OR RECEPTACLES
 NARRATIVE : THE 50 YEAR OLD FEMALE COMPLAINANT, HER HUSBAND, DAUGHTER, AND TWO GRANDCHILDREN HAVE EXPERIENCED MULTIPLE HEALTH ISSUES DUE TO IMPORTED DRYWALL FROM CHINA USED TO REPAIR SEVERAL APPLIANCES SUCH AS THE AIR CONDITIONING UNIT, STOVE, REFRIGERATOR, AND TOASTER OVEN THEIR HOME. THEY HAVE ALSO HAD TO REPLACE SEVERAL APPLIANCES SUCH AS THE AIR CONDITIONING UNIT, STOVE, REFRIGERATOR, AND TOASTER OVEN BECAUSE THEY HAVE ALL STOPPED WORKING UNEXPECTEDLY. THE CIRCUIT BREAKER FOR THE WATER HEATER TRIPS FOR NO APPARENT REASON. THE COMPLAINANT IS CONCERNED ABOUT THE LONG TERM HEALTH EFFECTS HER FAMILY WILL ENDURE.

8 090505CBB81690 10940417A SOURCE: 47 TYPE : ONSITE
 DATE INCIDENT : 061200 DATE ENTERED : 090601 CITY/STATE : PARKLAND, FL STATUS : C
 AGE/SEX : 034 / M DISP : TR/REL DIAGNOSIS : OTHER BODYPART : 25-50% OF BODY
 1ST PRODUCT : 1876 HOUSE REPAIR OR CONSTRUCTION MAT'L NEC
 NARRATIVE : THE CONSUMER AND HIS FAMILY HAVE EXPERIENCE HEALTH ISSUES, APPLIANCE FAILURES AND METAL CORROSION ISSUES SINCE PURCHASING THEIR RESIDENCE IN 2008. THE CONSUMER BELIEVES THAT IMPORTED DRYWALL FROM CHINA WAS USED IN CONSTRUCTING HIS RESIDENCE, AND THAT THE DRYWALL IS EMITTING CHEMICALS INTO THE ATMOSPHERE OF THE RESIDENCE AND RESULTING IN SOME OR ALL OF THE AFOREMENTIONED ISSUES.

U.S. CONSUMER PRODUCT SAFETY INFORMATION CLEARINGHOUSE
INCIDENT INVESTIGATIONS
CHINESE DRYWALL
INCIDENT - NATIONAL INJURY INFORMATION CLEARINGHOUSE

1 090427CWE8203 H0940206A SOURCE: CONSUMER COMPLAINT TYPE : ONSITE
 DATE INCIDENT: 080410 DATE ENTERED : 090605 CITY/STATE : CHALMETTE, LA STATUS : HOME
 AGE/SEX : 050 / F DISP : 0 DIAGNOSIS : NOT STATED OR UNK BODYPART : 99
 1ST PRODUCT : 1876 HOUSE REPAIR OR CONSTRUCTION MAT'L NEC
 2ND PRODUCT : 4061 ELECTRICAL OUTLETS OR RECEPTACLES
 NARRATIVE : A 50-YEAR-OLD MALE REPORTED THE DRYWALL IN HIS HOME, WHICH WAS IMPORTED FROM CHINA, IS MAKING HIS FAMILY ILL. THEY ARE SUFFERING FROM HEADACHES, BLOODY NOSES, AND SINUSITIS. THE MALE ALSO REPORTED CORROSION AND PITTING ON FIXTURES, AND BLACKENING OF COPPER PIPES AND WIRING IN THE RESIDENCE. THE EVAPORATOR COILS IN HIS A/C SYSTEM HAVE BEEN REPLACED DUE TO CORROSION.

2 090427CWE8304 H0940101A SOURCE: CONSUMER COMPLAINT TYPE : ONSITE
 DATE INCIDENT: 060809 DATE ENTERED : 090521 CITY/STATE : MANDEVILLE, LA STATUS : HOME
 AGE/SEX : 028 / M DISP : TR/REL DIAGNOSIS : OTHER BODYPART : ALL PARTS BODY
 1ST PRODUCT : 1876 HOUSE REPAIR OR CONSTRUCTION MAT'L NEC
 2ND PRODUCT : 4062 ELECTRIC WIRE OR WIRING SYSTEMS (EXCL.
 NARRATIVE : THE VICTIMS ARE A FAMILY CONSISTING OF TWO 28-YEAR-OLD ADULTS, TWO CHILDREN AGES 3-YEARS-OLD AND 19-MONTHS-OLD. THEY ALL HAVE BEEN EXPERIENCING CHRONIC UPPER RESPIRATORY INFECTIONS, SINUS INFECTIONS, RUNNY NOSES, AND HEADACHES SINCE MOVING INTO THEIR NEWLY CONSTRUCTED HOME IN 2006. THE HOME HAS DRYWALL IMPORTED FROM CHINA INSTALLED IN IT. THE HOME'S AIR-CONDITIONING UNIT HAS BEEN REPAIRED TWICE AND THEN RECENTLY REPLACED ALTOGETHER. PITTING AND CORROSION IS EVIDENT ON COPPER PIPES, WIRES, AND VARIOUS FIXTURES IN THE RESIDENCE. THE VICTIMS FELL THAT THE GASES EMANATING FROM THE DRYWALL IS CAUSING THEIR ILLNESSES.

3 090506C8B3567 H0940202A SOURCE: CONSUMER COMPLAINT TYPE : ONSITE
 DATE INCIDENT: 081118 DATE ENTERED : 090608 CITY/STATE : LAKE CHARLES, LA STATUS : HOME
 AGE/SEX : 041 / F DISP : TR/REL DIAGNOSIS : OTHER BODYPART : EYEBALL
 1ST PRODUCT : 1876 HOUSE REPAIR OR CONSTRUCTION MAT'L NEC
 2ND PRODUCT : A 41-YEAR-OLD FEMALE REPORTED THE DRYWALL IS MAKING HER ILL AND IS PRODUCING A BLACK RESIDUE. SHE WAS DX WITH AN EYE INFECTION. IT WAS DETERMINED DURING THIS INVESTIGATION THAT THE DRYWALL WAS MANUFACTURED IN THE UNITED STATES. CORROSION, PITTING, OR BLACKENING OF COPPER PIPES OR FIXTURES WAS NOT EVIDENT IN THIS RESIDENCE. IT HAS NOT BEEN DETERMINED WHAT IS PRODUCING THE BLACK RESIDUE IN THE FEMALE'S HOME.

4 090507C8B3568 10940826A SOURCE: SOURCE: 47 TYPE : ONSITE
 DATE INCIDENT: 070000 DATE ENTERED : 090611 CITY/STATE : NEW ORLEANS, LA STATUS : C
 AGE/SEX : 054 / F DISP : TR/REL DIAGNOSIS : OTHER BODYPART : HEAD
 1ST PRODUCT : 1884 CEILINGS AND WALLS (PART OF COMPLETED
 2ND PRODUCT : 0374 PIPES (EXCLUDING SMOKING PIPES)
 NARRATIVE : A 54-YEAR-OLD FEMALE COMPLAINT, WHOSE HOUSE WAS REBUILT IN 2007, HAS BEEN SUFFERING FROM WATERY EYES AND SINUS SYMPTOMS SINCE SHE BEGAN DRYWALL WAS INSTALLED. THE COMPLAINANT ALSO REPORTS BLACKENING AND CORROSION ON NEW COPPER PIPES IN HER HOME. SHE DID NOT MEDICAL TREATMENT FOR SINUS PROBLEMS RELATED TO THIS. SHE DID NOT SIGN AN AUTHORIZATION FOR RELEASE OF NAME FORM DURING THE ON-SITE VISIT. NOR DID SHE RETURN THE SIGNED FORM TO THE INVESTIGATOR LATER. THAT IS WHY NO IS INDICATED FOR PERMISSION FOR RELEASE OF NAME ON THE 182.

5 090507CBB83569 10940079A SOURCE: 090608 47 TYPE : ONSITE
 DATE INCIDENT: 060700 DATE ENTERED : 090608 CITY/STATE : MERAUX, MS
 AGE/SEX : 029 / F DISP : TR/REL DIAGNOSIS : OTHER
 1ST PRODUCT : 1884 CEILINGS AND WALLS (PART OF COMPLETED STATUS : C
 2ND PRODUCT : 4062 ELECTRIC WIRE OR WIRING SYSTEMS (EXCL. LOCATION : HOME
 NARRATIVE : A 29-YEAR-OLD FEMALE, A 29-YEAR-OLD MALE, AN 11-YEAR-OLD MALE, AND A : 25-50% OF BODY
 6-YEAR-OLD MALE REPORTED SUFFERING HEADACHES, NOSEBLEEDS, AND
 RESPIRATORY PROBLEMS AFTER MOVING INTO A HOUSE THAT HAD BEEN
 REMODELED WITH IMPORTED DRYWALL. THEY ALSO REPORTED BLACKENING OF
 COPPER PIPES, FIXTURES, AND ELECTRICAL WIRING. IN ADDITION, SEVERAL
 APPLIANCES HAVE FAILED. THEY HAVE NOT NOTICED FLICKERING, SPARKING,
 BUZZING, OR SIZZLING OF LIGHTS. THE VICTIMS HAVE SOUGHT MEDICAL
 ATTENTION FOR THEIR INJURIES.

6 090508CBB83570 10940292A SOURCE: 090617 47 TYPE : ONSITE
 DATE INCIDENT: 090408 DATE ENTERED : 090617 CITY/STATE : MERAUX, LA
 AGE/SEX : 216 / F DISP : TR/REL DIAGNOSIS : OTHER
 1ST PRODUCT : 1884 CEILINGS AND WALLS (PART OF COMPLETED STATUS : C
 2ND PRODUCT : 4062 ELECTRIC WIRE OR WIRING SYSTEMS (EXCL. LOCATION : HOME
 NARRATIVE : A SIXTEEN-MONTH-OLD FEMALE VICTIM HAD BEEN EXPERIENCING RESPIRATORY : 25-50% OF BODY
 PROBLEMS WHILE LIVING IN A HOUSE WITH IMPORTED DRYWALL, WHICH WAS
 INSTALLED IN 2007. HER SYMPTOMS IMPROVED DRAMATICALLY AFTER MOVING
 INTO ANOTHER RESIDENCE. HER PARENTS ALSO REPORT CORROSION ON
 ELECTRICAL WIRING, BLACKENING OF COPPER PIPES, AND CORROSION ON METAL
 OBJECTS THROUGHOUT THE HOUSE.

7 090508CBB83573 10930686A SOURCE: 090609 47 TYPE : ONSITE
 DATE INCIDENT: 070900 DATE ENTERED : 090609 CITY/STATE : VAGGAMAN, LA
 AGE/SEX : 045 / F DISP : 0 DIAGNOSIS : NOT STATED OR UNK BODYPART :
 1ST PRODUCT : 1876 HOUSE REPAIR OR CONSTRUCTION MAT'L NEC STATUS : C
 2ND PRODUCT : 4062 ELECTRIC WIRE OR WIRING SYSTEMS (EXCL. LOCATION : HOME
 NARRATIVE : A 45-YEAR-OLD FEMALE REPORTED THAT THE IMPORTED DRYWALL USED TO : 99
 CONSTRUCT HER HOME IS MAKING HER FAMILY ILL. SHE REPORTED HER
 FAMILY MEMBERS HAVE EXPERIENCED SYMPTOMS SUCH AS SORE THROAT,
 MIGRAINES, RAPID HEART BEAT, NAUSEA, AND HIVES. SHE ALSO REPORTED
 CORROSION, PITTING, AND BLACKENING OF FAUCETS, FIXTURES, AND COPPER
 PIPES IN HER HOME. THE EVAPORATOR COILS ON HER HOME'S
 AIR-CONDITIONING UNIT HAVE BEEN REPLACED TWICE. SHE IS CONCERNED
 ABOUT THE LONG TERM HEALTH EFFECTS AND FINANCIAL BURDEN THE DRYWALL
 HAS ON HER FAMILY.

8 090520CBB82629 H0930215A SOURCE: CONSUMER COMPLAINT
 DATE INCIDENT: 081010 DATE ENTERED : 090622 TYPE : PHONE
 AGE/SEX : 000 / M DISP : TR/REL CITY/STATE : GULFPORT, MS
 1ST PRODUCT : 1884 CEILINGS AND WALLS (PART OF COMPLETED STATUS : C
 2ND PRODUCT : 0463 CANDLESTICKS AND OTHER CANDLE LOCATION : HOME
 NARRATIVE : AN ADULT MALE NOTICED BLACK RESIDUE ON THE VENTS OF THE AIR : 25-50% OF BODY
 CONDITIONING SYSTEM IN HIS HOME, WHICH HE THINKS MIGHT BE CAUSED BY
 THE DRYWALL IN HIS HOUSE. HE HAS ALSO EXPERIENCED PROBLEMS WITH
 COUGHING A LOT SINCE HE MOVED INTO THE HOUSE IN 2007. NO
 AUTHORIZATION FOR RELEASE OF NAME FORM WAS OBTAINED BECAUSE THE
 COMPLAINANT CANCELED THE ON-SITE VISIT AND DID NOT WISH TO
 RESCHEDULE.

CHINESE DRYWALL
INCIDENT INVESTIGATIONS
U.S. CONSUMER PRODUCT SAFETY COMMISSION - NATIONAL INJURY INFORMATION CLEARINGHOUSE

9 090520CBB82630 H0950075A SOURCE: CONSUMER COMPLAINT TYPE : ONSITE
 DATE INCIDENT: 080500 DATE ENTERED : 090623 CITY/STATE : PERKINSTON, MS STATUS : C
 AGE/SEX : 045 / M DISP : TR/REL DIAGNOSIS : OTHER BODYPART : 25-50% OF BODY
 1ST PRODUCT : 1884 CEILINGS AND WALLS (PART OF COMPLETED
 2ND PRODUCT : 0381 AIR CONDITIONERS
 NARRATIVE : A 45-YEAR-OLD MAN AND HIS WIFE BEGAN EXPERIENCING RESPIRATORY
 PROBLEMS AFTER MOVING INTO THEIR NEWLY CONSTRUCTED HOME IN AUGUST
 2006. THE HOME CONTAINS DRYWALL IMPORTED FROM CHINA. THE COUPLE HAS
 ALSO EXPERIENCED PROBLEMS WITH VARIOUS APPLIANCES SINCE MOVING INTO
 THE HOME. THEY REPORT NOTICING A "ROTTEN EGG" OR "LIT MATCHES" ODOR
 IN THE HOME AS WELL.

10 090520CBB82638 10950711A SOURCE: DATE ENTERED : 090604 TYPE : ONSITE
 DATE INCIDENT: 050000 DATE ENTERED : 090604 CITY/STATE : MACON, GA STATUS : C
 AGE/SEX : 041 / M DISP : TR/REL DIAGNOSIS : OTHER BODYPART : ALL PARTS BODY
 1ST PRODUCT : 1876 HOUSE REPAIR OR CONSTRUCTION MAT'L NEC
 2ND PRODUCT : 1876 HOUSE REPAIR OR CONSTRUCTION MAT'L NEC
 NARRATIVE : A 37 YEAR OLD FEMALE REPORTED THAT HER FAMILY HAS EXPERIENCED HEALTH
 PROBLEMS AND THAT ELECTRICAL PRODUCTS IN HER HOME HAVE
 MALFUNCTIONED. THE COMPLAINANT'S HOUSE WAS RENOVATED IN 2004/2005
 AND SHE BELIEVES DRYWALL THAT WAS INSTALLED DURING THE RENOVATION
 MAY BE THE CAUSE OF THE PROBLEMS. THE FAMILY MOVED OUT OF THE HOUSE
 IN 2008 BECAUSE OF HEALTH CONCERNS.

11 090521CBB81733 10950250A SOURCE: DATE ENTERED : 090623 TYPE : ONSITE
 DATE INCIDENT: 090506 DATE ENTERED : 090623 CITY/STATE : HOLLY SPRINGS, NC STATUS : C
 AGE/SEX : 036 / F DISP : TR/REL DIAGNOSIS : POISONING BODYPART : ALL PARTS BODY
 1ST PRODUCT : 1876 HOUSE REPAIR OR CONSTRUCTION MAT'L NEC
 NARRATIVE : A 38 YEAR OLD MALE AND HIS 36 YEAR OLD WIFE STATE THAT THEY HAVE
 SUFFERED NUMEROUS HEALTH EFFECTS (SUCH AS ALLERGIES, BURNING EYES,
 SORE THROATS AND FATIGUE) AFTER MOVING INTO THEIR HOUSE. THEY
 ATTRIBUTE THESE SYMPTOMS TO CHINESE DRYWALL IN THEIR HOUSE. NUMEROUS
 ELECTRICAL PROBLEMS (FLICKERING LIGHTS, FREQUENT TRIPPING OF CIRCUIT
 BREAKERS AND PROBLEMS WITH SMOKE ALARMS GIVING OFF FALSE ALARMS)
 WERE EXPERIENCED AND THERE IS EVIDENCE OF CORROSION ON COPPER PIPES,
 JEWELRY, CHROME AND WIRING. THERE IS ALSO A VERY NOTICEABLE PUNGENT
 ODOR IN THE HOUSE.

12 090529CBB81741 10950507A SOURCE: DATE ENTERED : 090617 TYPE : ONSITE
 DATE INCIDENT: 090514 DATE ENTERED : 090617 CITY/STATE : CLERMONT, FL STATUS : C
 AGE/SEX : 043 / M DISP : TR/REL DIAGNOSIS : POISONING BODYPART : ALL PARTS BODY
 1ST PRODUCT : 1876 HOUSE REPAIR OR CONSTRUCTION MAT'L NEC
 2ND PRODUCT : 0381 AIR CONDITIONERS
 NARRATIVE : THE FAMILY MOVED INTO THEIR HOME IN OCTOBER 2006 AND HAD TO MOVE OUT
 IN APRIL 2009 DUE TO THE ILL HEALTH AFFECTS FROM THE TAINTED
 DRYWALL. THE OWNER OF THE HOME CUT HOLES IN HIS WALLS TO DISCOVER
 THAT THE DRYWALL WAS IMPORTED FROM CANADA BY AN AMERICAN COMPANY AND
 WAS A MEDIUM GRAY COLOR. THE HOMES TWO AIR CONDITIONERS COILS HAD
 BOTH BEEN REPLACED TWICE. CHROME FIXTURES WERE PITTED AND
 ELECTRICAL WIRING WAS TURNING BLACK.

CHINESE DRYWALL
INCIDENT INVESTIGATIONS
U.S. CONSUMER PRODUCT SAFETY COMMISSION - NATIONAL INJURY INFORMATION CLEARINGHOUSE

1
 090505CBB1681 H0940208A SOURCE: CONSUMER COMPLAINT TYPE : ONSITE STATUS : C
 DATE INCIDENT : 090325 DATE ENTERED : 090526 CITY/STATE : VIRGINIA BEACH, VA LOCATION : HOME
 AGE/SEX : 040 / F DISP : TR/REL DIAGNOSIS : POISONING BODYPART : ALL PARTS BODY
 1ST PRODUCT : 1876 HOUSE REPAIR OR CONSTRUCTION MAT'L NEC
 2ND PRODUCT : 4061 ELECTRICAL OUTLETS OR RECEPTACLES
 NARRATIVE : SIGNIFICANT SYMPTOMS OCCURRED FOR ALMOST THREE YEARS, SUCH AS RUNNY, BLOODY NOSES, SINUSITIS, CHEST CONGESTION, AND SEVERE COUGH, WHEN A FAMILY OF FIVE REALIZED THEY WERE LIVING IN A HOUSE THAT HAD BEEN CONSTRUCTED WITH BAD DRYWALL. NO HOSPITALIZATION WAS REQUIRED, OUT OF HOWEVER MULTIPLE DOCTOR'S VISITS ENSUED. THE FAMILY HAS MOVED, OUT OF THEIR HOME INTO A TRAILER IN THEIR DRIVEWAY. INSIDE THE HOME, METAL DECOR HAS CORRODED AND BECOME DISCOLORED AND THE BREAKERS TRIP SPONTANEOUSLY.

2
 090505CBB1689 H0940196A SOURCE: CONSUMER COMPLAINT TYPE : ONSITE STATUS : C
 DATE INCIDENT : 090410 DATE ENTERED : 090529 CITY/STATE : VIRGINIA BEACH, VA LOCATION : HOME
 AGE/SEX : 019 / M DISP : TR/REL DIAGNOSIS : OTHER BODYPART : FACE
 1ST PRODUCT : 1876 HOUSE REPAIR OR CONSTRUCTION MAT'L NEC
 2ND PRODUCT : 0381 AIR CONDITIONERS
 NARRATIVE : SEVERE HEADACHE AND SINUSITIS SYMPTOMS HAVE OCCURRED OVER THE PAST THREE YEARS FOR A FAMILY OF THREE AND THEIR DOG, WHICH ARE BELIEVED TO BE CAUSED BY CHEMICALS FOUND IN THE DRYWALL IN THEIR HOME. THE ELECTRICAL WIRES IN THEIR HOUSE HAVE BECOME BLACKENED AND THEIR AIR CONDITIONING COIL HAS RECENTLY HAD TO BE REPLACED. THERE ARE NO REPORTED ELECTRICAL PROBLEMS, AND THERE ARE NO ISSUES WITH THEIR BREAKERS SPONTANEOUSLY TRIPPING.