090504CBB1664		4	2. Investigator's ID		
			2391	EPIDEMIOLOGIC	
. Office Code	4. Date of Accid YR MO DA		5. Date Initiated YR MO DAY		INVESTIGATION REPORT
810	2006 11 02		2009 05 04		
. Synopsis of Acciden	it or Complaint		JPC		
imported drywall from describes as a choking eyes, and increased as	China used in the g and suffocating sthma symptoms, had repeated issu	construction sulfur smell. The compla	n of their home. He has They have experienced ainant has had to replac	noticed a ver I coughing, it e appliances	alth issues as a result of the y strong odor that he ching, burning and watery because they stop working a is concerned about the long
				PRODU	1) CLEARED for PUBLIC RS/PRVTIBLRSOR CIS IDENTIFIED 3/457
				EXCEP	TED BY: PETITION 02 PM
					ORTIONS REMOVED:
. Location (Home, Sch	nool, etc)		B. City		9. State
1 - HOME			BOYNTON BEACH		FL
IOA. First Product		10B. Trade	e/Brand Name		10C. Model Number
1876 - House Structur	es, Repair Or	UNKNOW	/N	· ·	UNKNOWN
			e/Brand Name	<u> </u>	11C. Model Number
11A. Second Product 381 - Air Conditioners 11D. Manufacturer Nar		11B. Trade UNKNOW			11C. Model Number UNKNOWN
381 - Air Conditioners 11D. Manufacturer Nar NONE					
381 - Air Conditioners 1D. Manufacturer Nar NONE 2. Age of Victim 34 6. Body Part(s)	ne and Address	UNKNOW	/N 14. Disposition	· · · · · · · · · · · · · · · · · · ·	UNKNOWN 15. injury Diagnosis
381 - Air Conditioners 1D. Manufacturer Nar NONE 2. Age of Victim 34	ne and Address 13. Sex 1 - Male	UNKNOW	/N 14. Disposition 1 - Injured, not H	· · · · · · · · · · · · · · · · · · ·	UNKNOWN 15. Injury Diagnosis 68 - Poisoning
381 - Air Conditioners 11D. Manufacturer Nar NONE 12. Age of Victim 34 16. Body Part(s) involved 85 - ALL OF BODY	ne and Address 13. Sex 1 - Male 17. Respond 1 - Victim/Ci	UNKNOW Jent omplainant 21. Case Sou	/N 14. Disposition 1 - Injured, not H 18. Type of Inves 1 - On-Site	tigation	UNKNOWN 15. Injury Diagnosis 68 - Poisoning 19. Time Spent (Operational / Travel)
<ul> <li>381 - Air Conditioners</li> <li>11D. Manufacturer Nar NONE</li> <li>12. Age of Victim</li> <li>134</li> <li>16. Body Part(s) Involved</li> <li>16. ALL OF BODY</li> <li>20. Attachment(s)</li> <li>9 - Multiple Attachmer</li> </ul>	ne and Address          13. Sex         1 - Male         17. Respond         1 - Victim/C         nts	UNKNOW dent omplainant 21. Case Sor 07 - Consum	/N 14. Disposition 1 - Injured, not H 18. Type of Inves 1 - On-Site urce ner Complaint	tigation	UNKNOWN 15. Injury Diagnosis 68 - Poisoning 19. Time Spent (Operational / Travel) 11 / 0.5
381 - Air Conditioners 11D. Manufacturer Nar NONE 12. Age of Victim 34 16. Body Part(s) Involved 85 - ALL OF BODY 20. Attachment(s) 9 - Multiple Attachmer	ne and Address          13. Sex         1 - Male         17. Respond         1 - Victim/C         nts	UNKNOW Jent omplainant 21. Case Sor 07 - Consun NEISS Cas	/N 14. Disposition 1 - Injured, not H 18. Type of Inves 1 - On-Site urce ner Complaint	tigation	UNKNOWN 15. Injury Diagnosis 68 - Poisoning 19. Time Spent (Operational / Travel) 11 / 0.5
<ul> <li>381 - Air Conditioners</li> <li>11D. Manufacturer Nar NONE</li> <li>12. Age of Victim</li> <li>13. Body Part(s) Involved</li> <li>85 - ALL OF BODY</li> <li>20. Attachment(s)</li> <li>9 - Multiple Attachmer</li> <li>23. Permission to Disc</li> </ul>	ne and Address          13. Sex         1 - Male         17. Respond         1 - Victim/C         nts         Hose Name (Non	UNKNOW dent omplainant 21. Case Sor 07 - Consum NEISS Cas No	/N 14. Disposition 1 - Injured, not H 18. Type of Inves 1 - On-Site urce ner Complaint es Only)	igation 22. S	UNKNOWN 15. Injury Diagnosis 68 - Poisoning 19. Time Spent (Operational / Travel) 11 / 0.5 ample Collection Number Yes for Manuf. Only Al Office Director

- --

Ņ. . .

CPSC FORM 182 (12/96) Approved for use through 01/31/2010 OMB NO. 30410029

This investigation was initiated through the receipt of Consumer Product Incident Report submitted by a 34 year old male complainant, involving imported drywall material used to build his home. Information for this report was gathered during an on-site interview with the complainant in the home.

The complainant, his 32 year old wife, and four month old daughter have been living in the affected house since November 2006. The house was built in November 2006; it is two-story, with 3,900 square feet and five carpeted bedrooms. The house was constructed using metal studs and does not operate any appliances using gas or natural gas service. All appliances are electric. The complainant reported that he has not made any changes to the house since moving in. Drywall in the garage ceiling was replaced in May 2007 by the builder due to a leak, but the complainant considered this unrelated to the drywall issues he is experiencing.

After moving in, the complainant noticed that he frequently had to replace appliances because they would stop working unexpectedly. He has noticed a very strong odor that he describes as a choking and suffocating sulfur smell. He has been aware of this odor since moving in, but he attributed the smell to a "new house smell," subsequently dismissing it. He has noticed that the odor is stronger in the summer months and is very noticeable when walking into the house. The odor never goes away and is strong on the second floor of the house. There has not been any change in the house such as new flooring that could determine if the odor has increased or decreased.

Within the first year of living in the house, the complainant experienced several appliances malfunctioning and having to be replaced. He has had the circuit boards on a television and laptop stop working. He has had the security company replace the alarm panel twice because it stopped working. The company technician could not explain why he was experiencing problems. The electrical panel in the refrigerator was replaced in the first 10 months of living in the home. Also in the first 10 months, he has had to replace the top portion of the oven that shows the temperature and other controls, twice. Each time because the top portion of the oven would overheat and cause the wood cabinet above it to start cracking. The erratic behavior of the oven caused concern to the complainant and his wife and they stopped using the oven. The air conditioning units on the first and second floor have been recharged with refrigerant on November 11, 2007, August 29, 2008, and the last time on March 14, 2009. Service invoices were provided and included as Exhibit 2. Each time at least three pounds of refrigerant was added and leaks in the evaporator coils were patched. The evaporator coils were never replaced during these service visits. The technician could not give an explanation for the problems the complainant was experiencing with the air conditioning units. An electrical receptacle in a guest bedroom started to arc and smoke and the builders had a service technician visit the home and replace the receptacle. On a consistent basis the complainant experienced the following issues: circuit breakers tripping for no apparent reason and an unusual odor in the vicinity of a receptacle. He is not experiencing issues with flickering lights, sizzling and buzzing, and light switches or outlets that are warm or hot to the touch. The complainant has noticed blackening, corrosion and pitting on metal surfaces throughout the house. Within 10 months of living in the house the complainant

. .

.

informed the builder that there was blackening and pitting on metal fixtures such as the drains in the showers and sinks, shower heads, faucets, lighting fixtures, bathtub fixtures, and metal fixtures on shower doors. The builder replaced all of the metal fixtures and the blackening and pitting began to appear again. The issues with the smoking receptacle and the oven panel caused concern to the complainant of a possible fire hazard. He has also noticed corrosion on his wife's jewelry, mirrors, and metal knobs on a table. Photographs of the affected metal surfaces and fixtures are included as Exhibit 3.

The complainant and his wife lived in the house for six months when they started to notice health issues arising. The complainant began developing an acute cough that lasted at least a month. He was prescribed antibiotics by his physician. In the summer months when the house is hotter, he has trouble breathing. He has also experienced itching, burning, and watery eves, but does not take any medications for that symptom. The complainant's wife has pre-existing asthma, but has had to use her inhaler on a more frequent basis. During the summer her use of the inhaler increases even more, as she begins to experience "flare-ups" in her asthma symptoms. The complainants four month old daughter has experienced coughing, watery and red eyes at all times, and blood in her stool. She has been seen by a pediatrician for her symptoms. The pediatrician has advised the complainant and his wife to remove her from the home. His wife and daughter moved out of the house on May 3, 2009 as advised by the pediatrician. The complainant is still living in the house. He has noticed that the symptoms lessen when the family is not in the home. His symptom of itching and burning eyes occurs while he is in the house. His wife returned to the home on May 11, 2009 and after being away for eight days, the smell of the house was too strong for her to withstand. His wife and daughter have seen an improvement in their health as a result of leaving the house. The complainant does not own any pets. Documentation of the pediatrician's advice to remove the complainant's daughter from the house is included as Exhibit 4.

The complainant has contacted the builder to report issues he is experiencing with corrosion, unusual odors, and health problems. The builder came into the home for an inspection. The complainant did not provide this investigator with any documentation and/or report of the builder's inspection. The complainant has also had his insurance company visit the home for a survey. Most recently he has had the Rinker school of construction from the University of Florida visit the home and collected a piece of drywall from a closet on the first floor. The complainant has contact several entities. He has contacted the office of Congressman Robert Wexler and on April 7, 2009 the Congressman visited the complainant's house. He has contacted the office of Senator Bill Nelson, Florida Department of Health, Environmental Protection Agency, White House, Governor Charlie Crist, State House Representative Kevin Rader, State House Representative Joseph Abruzz, and Congressman Ron Klein. His community has organized a committee of homeowners that meets to discuss drywall issues. He is on the board of this committee. He contacted the offices of Senator Ted Deutch and Commissioner Burt Aaronson, and both attended a community meeting in April 2009. His plans for dealing with this problem are to await a recall of the drywall product by the U.S. CPSC. The complainant added and requested to be quoted, "I am looking to the CPSC for an immediate recall of drywall without any conditions, based on one fact, there

٩,

is highly corrosive activity occurring in these homes. It may take years to determine health effects, but must be immediately recalled based on the corrosion in homes. Secondly, there is real evidence of immediate fire danger through the breakdown of copper wiring. There is real evidence of corrosion in water pipes that could cause flood and/or mold. Recall immediately." He would like to provide drywall samples in the event that the Commission would like to revisit his home.

### **Product Description**

The product involved is imported drywall from China. During the on-site interview, this investigator did not locate any visible labeling of the drywall in the home. Access to the attic for identification was not available.

### Exhibits

Exhibit 1	Contact Information
Exhibit 2	Air Conditioning Service Invoices (4)
Exhibit 3	Photographs (18)
Exhibit 4	Medical Documentation
Exhibit 5	Authorization for Release of Name

# **Contact Information**

а. <u>с</u>. – т

Frank and Romy LaLama, Complainants 9924 Cobblestone Creek Dr. Boynton Beach, FL 33472 Tel. 561-364-8503 May 5, 2009

# **Complainant Contacted Builder**

Northstar Homes of Florida 14901 Military Trail Delray Beach, FL 33484 Tel. 561-638-6270

Total Materials Service Materials	665 N.W. E	NTERPRISE 1954) 42 201 780-511	PHONE #	LUCIE, FL 34 55-3688 • (77) 84503 - www 5 • ER 001787 JOB # JOB #	1986 = LICS. 2) 398-6668 Asarisone a Asarisone a Asari	. CAC 0514 }	473 ### 222.20 No.2, 40			10 J. 17 19	nce entary Complet EXP	APPR.NO. Compressor Suct Press Head Press Volts Amps Cond Coil
Total Materials Service Materials			CITY Model No.44 Model No.44 Description of Photo	21 - Dain Piller () Co (V) ;	7 <u>777</u>	ZIP Serial Serief/	8223 No.7 No.7 No.7 No.7 No.7 No.7 No.7 No.7	42			EXP p Inc 4 7 4 7 4 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7	APPR. NO. Compressor Suct Press Head Press Volis Amps Cond Coil Entr Air Temp Leav Air Temp Refrigerant Adequate Charg Check for Leaks
Total Materials Service Materials			Model No. Model No. Description of Charles	C / U / C / U / C / Work Perf C ////C	9 40 - X 11 - 1	Serief	No.2		ARD 2 1 1/2 2 4 1/2 1 1 1/2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		p Inc 47 47 47 47 47 47 47 47 47 47	Compressor Suct Press Head Press Volts Amps Cond Coil Entr Air Temp Leav Air Temp Refrigerant Adequate Charg Check for Leaks
Total Materials Service Materials			Model No. Description of Charles	COSCO COSCO Of Work Perf	9 40 - X 11 - 1	Seniet	<b>1</b> <b>1</b> <b>1</b> <b>1</b> <b>1</b> <b>1</b> <b>1</b> <b>1</b> <b>1</b> <b>1</b>					Suct Press     Head Press     Volts Amps     Cond Coil     Entr Air Temp     Leav Air Temp     Refrigerant     Adequate Charg     Check for Leaks
Total Materials Service Materials			Model No. Description of Charles	CU (U) of Work Perf	9 40 - X 11 - 1	1.						Suct Press     Head Press     Volts Amps     Cond Coil     Entr Air Temp     Leav Air Temp     Refrigerant     Adequate Charg     Check for Leaks
Total Materials Service Materials			1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	of Work Perf	9 40 - X 11 - 1							Suct Press     Head Press     Volts Amps     Cond Coil     Entr Air Temp     Leav Air Temp     Refrigerant     Adequate Charg     Check for Leaks
Total Materials Service Materials			1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		9 40 - X 11 - 1							Volts Amps Cond Coil Entr Air Temp Leav Air Temp Retrigerant Adequate Charg Check for Leaks
Total Materials Service Materials												Cond Coil     Entr Air Temp     Leav Air Temp     Retrigerant     Adequate Charg     Check for Leaks
Total Materials Service Materials												Entr Air Temp     Leav Air Temp     Retrigerant     Adequate Charg     Check for Leaks
Total Materials Service Materials												Leav Air Temp Retrigerant Adequate Charg Check for Leaks
Total Materials Service Materials		5.00										Refrigerant Adequate Charg Check for Leaks
Total Materials Service Materials		5.00										Adequate Charg Check for Leaks
Service Materials		5.00										Check for Leaks
Service Materials		5.00				7 		· · ·			15	
Service Materials	(2) (中) (1) (在) (1) (4) (4) (5) (4) (5) (4) (5) (4) (5) (4) (5) (4) (5) (4) (5) (4) (5) (4) (5) (5) (5) (5) (5) (5) (5) (5) (5) (5	5.00				1 . Xi			1	1. The second	1 1 2	Cond Motor
Service Materials	1920 - 1920 7420 <b>\$</b> 743	5.00		17Å			14 - 1 				1	
21 - M - 11 - 1	42 <b>\$</b> 83	3.WJ	J Tankala a			*** **	: y -	- <u>2</u> -	Est Dila			Volts Amps
Total Labor		14 - 44	Technician F	tecomment	<b>S</b> 200 of 	····		44 100	Est Pric	8	-17	the second s
Inter Family								ن بين ا	en en en Referencia			Entr Air Temp
Flat Rate Pricing			<b>-</b>	1					·			Leav Air Temp
Discount							· · · ·	÷.	· · · · · ·			Volts Amps
												Pulleys (Adj belt
Tax		yî si. Na w		;- ·		<del></del>						Clean Drain Pan
Total	1 99	(		····		· · ·			e in	iya kw n		Clean Drain
											- <u>-</u>	
you. Please be sure to care	etully exam-				e shown but sh	al not be lieb	le lot taiture io	o discover co	nditions nacess		0	
es your premises. Please le	t him know	lating repair	rs or replacements, n	or shall any inape	ection be cons	tructed as an	approval or	guarantee of	the equipment	t Cra	1 3 2	
RM WORK gree to pay in full this invok Completion? I further ag of the signing of the "Adars the guarantee embodied ha	ce upon sign- ree that any owiedgement andit expires,	days unless required in 1 ed to norma equipment, sons are no hours: 8AM	a otherwise stated on t the future by failure of al wear and tear, part will be charged to the st authorized to make a KSPM Mon-Fril. 8AM-	this Invoice. This w parts not under or a damaged by une i customer. Sansoi my such wanantie 3PM Sat. UNDE	venantly does n terwanantly or authorized pers ne makes no o is for Sansone. ER NO CIRCI	not cover any o by conditions sonnel, acts of other warrantie Warranty work UMSTANCES	other parts in not under our of God, or impl as expressed of k shall be perfo	i your unit(s), r control such xoper operati or limited any formed during	Any new repair as but not limit on or use of th d its service per regular workin	Acknov Limited By Exclus	Warranty	nt of Work Performer and Mold and Milde
									· · · · ·	Signat	ure 🥼	
to pay this contract in full	then the pur-	It is unders result of mo property da	stood and agreed that old, sligae, or fungus, l amage, and clean up	Sansone Corpon It is understood this expenses cause	ut Sansone will to directly or in	l not be respo ndirectly in w	onsible for dan thole for any i	mages relaté reason as a	to bothy injur result of mol	s Date_	*2	
	s your premises. Please is a not clearly understood. IM WORK gree to pay in full this invol Completion. <sup>2</sup> I further ag of the signing of the "Actin he guarantee embodied his crue at 1.5% per month up further agrees that if any a bor pay this contract in full easonable altomety's lees.	IM WORK gree to pay in full this involce upon sign- consistent. I further agree that any of the signifies embodied herein expires, crue at 1.5% per month upon the entire hurther agree that if any action of law is to pay this contract in full then the pur- easonable altorney's tees, court costs, it law.	cou. Presse be sure to catefully exam- s your premises. Please let him know s not cleanly understood. MWORK grae to pay in full this invoice upon sign- completion. <sup>2</sup> I further agree that any of the signing of the "Acknowledgement the guarantee embodied herefit expires, crue at 1.5% per month upon the entire further agree that if any action of law is to pay this contract in full then the pur- saconable attorney's tees, court costs. It is unders the aw.	cou. Presse be sure to catefully examples your premises. Please let him know a not clearly understood.     Sansone warrants all parts and n days unless otherwise stated on required in the houre by failure of ed to normal weer and tear, part equipment, will be charged to the signing of the "Admowledgement of the signing of the "Admowledgement of the signing of the "Admowledgement is to pay this contract in hull then the purses on the attorney's tees, court costs, it is understood and agreed that is understo	s your premises. Please let him know s not clearly understood. WWORK gree to pay in full this invokes upon sign- Completion." I further agree that any of the signing of the "Acknowledgement is guarantee embodied herefit expires, crue at 1.5% per month upon the entire further agree that if any action of law is to pay this contract in full thein the pur- passonable altorney's kees, court costs, it law.	Completion." I further agree that any color of the same that if any action of the same that that than the pureoff that	Completion: I further agree that any four state of the signing of the "Admonifedgement is the storage that if any action of the surface. This watch of the signing of the "Admonifedgement is to pay this contract in full then the pursesonable altorney's tees, court costs, if iaw.     Song the sonable altorney's tees, court costs, if iaw.     Sonable altorney's tees, court costs, if iaw.     Sonable altorney's tees, court costs, if iaw.     Sonable altorney's tees, court costs, if iaw.	cour Presse be sure to catefully examples       Sansone will use normal care performing the service shown but shall not be liable for failure it failing repairs or replacements, nor shall any inspection be constructed as an approval or sansone warrants all parts and materials fisted above and the labor performed as shown on days unless otherwise stated on this invoice. This warranty does not cover any other parts in required in the faure by failure of parts not under our warranty or by conditions not under our ed to normal wear and tear, parts damaged by unsufficiated personnel, acts of God, or impletion." I further agree that any of the signing of the "Admoniadgement is guarantee embodied herein expressed to make any other parts, will be charged to the customer. Sansone makes no other warranties expressed ons at not authorized to make any sub-thereades to Sansone. Warranties expressed ons at not authorized to make any sub-thereades to Sansone. Warranties expressed to make any sub-thereades to Sansone. Warranties expressed ons at not authorized to make any sub-thereades to Sansone. Warranties expressed ons at not authorized to make any sub-thereades to Sansone. Warranties expressed ons at not authorized to make any sub-thereades to Sansone. Warranties expressed to the signing of the "admoniadgement any embodied hereith express." SPECIAL, SUBSEQUENT OR CONSEQUENTIAL DAMAGES.	Sincore will use normal care performing the service shown but shall not be liable for failure to discover co syour premises. Please let him know a not clearly understood. WWOPK gree to pay in full this invokes upon sign- completion. <sup>2</sup> I further agree that any of the signing of the "Admowledgement is guarantee embodied herein expires, crue at 1.5% per month upon the entire further agree that if any action of law is to pay this contract in hull then the pur- secontable altorrey's tees, court costs, it is understood and agreed that Sansone Corporation will be held harmless for saleged or actual damy to understood and agreed that Sansone Corporation will be held harmless for saleged or actual damy to understood and agreed that Sansone Corporation will be held harmless for saleged or actual damy to understood and agreed that Sansone Corporation will be held harmless for damages related property damage, and clean up expenses caused directly or indirectly in whole for any reason as a including lungus and mildew regardless of the cost, event material, product or workmanship that may	Sour previous prev	LINITED WARRANTY Support prenises. Please is thin know stort clearly understood.  LINITED WARRANTY Support prenises. Please is thin know stort clearly understood.  LINITED WARRANTY Support prenises. Please is thin know stort clearly understood.  LINITED WARRANTY Support or replacements, not shall any inspection be constructed as an approval or guaranties of the explorent. Support prenises. Please is thin know stort clearly understood.  LINITED WARRANTY Support or replacements, not shall any inspection be constructed as an approval or guaranties of the explorent. Support of the support of the target of the target of the customer.  MWORK order in that this invoice upon sign- conclusion? I further agree that any of the signing of the "Acknowledgement is guarantee embodied herein express, crue at 1.5% per month upon the entire inuther agree that if any action of taw is to pay this contact in full thein the pur- passonable altorney's tees, court costs, it is understood and agreed that Sansone Corporation will be held harmless for alteged or actual damagesidalings as a result of moid, sigae, or fungus, it is understood that Sansone will not be responsible for damages related to body injury; property demage, and clear up expenses caused directly or indirectly in whole for any reason as a sense as a sense.  Control of the signal, and clear up expenses caused directly or indirectly in whole for any reason as a sense as a sense of milder the pre- property demage, and clear up expenses caused directly or indirectly in whole for any reason as a result of moid, including lungus and mildew regardless of the cost, event material, product or workmanship that may have contributed	LIMITED WARRANTY Sensorie will use normal care performing the service shown but shall not be liable for tables to fallow to discover conditions necessi- taing regulars or replacements, not shall any inspection be constructed as an approval or guarantee of the equipment. Sansorie wait use normal care performing the service shown but shall not be liable for fallows to discover conditions necessi- taing regulars or replacements, not shall any inspection be constructed as an approval or guarantee of the equipment. Sansorie wait uses otherwise stated on the linkice. This warranty does not cover any other parts in your utilis). Any new repairs required in the future by fallow of parts not under our control such as but not limit of the signing of the "Admonfedgement in the guarantee encoded herefit expires, crule at 1.5% per month upon the entire hurther agree that if any action of law is to pay this contact in full thein the pur- passonable altorney's tees, court costs, it is w.

	Deliver Cool"	665 N.V	)olsby blyr V. Enterpris (95414)	CE AND MAINTENANO D. DEERFIELD BEACH I E DRIVE, PORT ST LUCIE 28-8919 • (561) 455-368 88 • Fax (954) 428-6503 CFC 1426106 • ER C	L 33442 + LICS. FL 34986 + LICS. 8 + (772) 398-6668 • www.sansone-ac	CAC 045862 CAC 051473		⊡ Warn ⊡ Call ⊡ Main		☐ COD ☐ Bill to @ Ext Warranty ☐ Construction ☐ Lost Time
USTOMER NAME				PHONE #	JOB #	DISPATCH#	TIMEIN 9:38	TIME OUT	COMPLET	E INCOMPLET
DORESS DORESS	En	er.		CITY		ZP 23407	CREDIT CARD		EXP.	APPR NO.
Martin Carlos	and a second second Second second second Second second		R	Model No.7443	NCOMBOIO	Serial No. / //	5A223/6		Comp   Inc	
ERVICE COMPLAINT		COST		Model No.	<mark>जिन्दा उन्हें के</mark> क्रावेद के के	Serial No.			Comp Inc	Compressor
ANIO & MAICHINLO				Proprietor at 18/2	Dorfamadi		가 한 것은 것은 것은 2013년 3월 2일 2013년 3월 2일 같은			Suct Press
Minwashi			<u>.00 · · · · · · · · · · · · · · · · · · </u>	Description of Wor	renomed.					Head Press
Jork 1031	動量 新闻 着 4. 共同 查 第二章 <u>新</u> 经上述 百	144	20.	2 =0 flora	AREN	Macconic	1 SUEn-	Ø.,		Volts Amps
		l, K., g. /- Mi	1 4 9 9 9 19 19 19	POUT ON, 1	LEON :	<u>290</u>	Arton)	mer		Cond Coil
A State of the second s				1811K -05	t, Frith	d cal	$\frac{5}{10}$	<u>.</u>	한 위험(군) 신입 전값) 일시 요구	Entr Air Temp
And o				evication/C		ALL BO	18 6 1212	rs 		Leav Air Temp
金属 (加化)				1277 anrek 2 2013	ING NA	rot_ 76'	<u>क दर्ग देग है ।</u> होहिन्दी के ब			Adequate Charg
n an de sei de sei Recepción de sei Recepción de sei de sei	n de Arriente de Constantes 20 Anno 1988, en de Constantes 20 Anno 1988, en de Constantes de Constantes				n an					Check for Leaks
		an Arrian An Carlon An An Anna	na Serie La Serie		an sa lan sa					Cond Mator
	Total Materials									Volts Amps
の第三部第三部第三部 人物的学校者	Misc. Service Materials	\$	5.00	Technician Recomm		11日日 2月1日日日 1日日日日	Est l	2-2-2		Evap Sect
	Total Labor	ू भूस		Cipoviala	r terL	Replacen				Entr Air Temp
		n tean ann an tean ann Ann an tean ann			<u> </u>	The first of the second	$\rightarrow M \sim z$			Leav Air Temp
CHIR >	Flat Rate Pricing	161 - 163 187 - 187		UVALLE	P10-0-1	101: (Care				Volts Amps
Cerrier	Discount			1.200V 77	dlo 1 6 - 11 - 1					Pulleys (Adj belt)
Turn to the Experts.	Tax					(* 328° N				Lubricate Clean Drain Pans
	Total	12	58.00							Clean Drain Park
A CARLEN			n an		a tala ana ana ana ana ana ana ana ana ana					Check Filter
PLEASE READ	turily to save you Please be sure to caref	iy exem-	Sansone will	WARRANTY Luse normal care performing the	service shown but shall	not be liable for failure to d	iscover conditions neo	*		Thermostal
	nyice man leaves your premises. Please let nyice man leaves your premises. Please let co if anything is not dearly understood.	vinn Krichw	tating repain Sansone wa	s or replacements, not shall en ments all parts and materials list	inspection be construined above and the labor	cted as an approvel or gu benomed as shown on thi	ariantee of the equips s invoice for a period	nent. XXX		Heating.
	and the second		cays unless required in t	otherwise stated on this invoice. he tuture by feilure of certs not u	This warranty does not rader our warranty or by	cover any other parts in yo conditions not under our o	ur unit(s). Any new re xmrol such as but not	Ackn		ot Work Performed
AUTHORIZATION TO	PERFORMWORK	uner ann	antipment.	L'vear and tase, parts damaged will be changed to the contomer.	Sanaces makes no othe	r warranties expressed or	insted and its service	per-		in Make and Milder
	be cone and agree to pay in full this invoka of Satisfactory Completion," I further agree		H HENRY SAM	Capitorized to make any such wa SPM Mon-Fil BAM-3PM Sal.	UNDER NO CIRCUM	nanty work shell be perior STANCES SHALL SAN	ned Guring regular wo Sone be liable		Isica: M	PPALLE
ARROADE DUS ENTINOED JUCEY	S ICOPPER CARE AND SPEED OF THE CARE	in extres.	SPECIAL.	SUBSEQUENT OR CONSECU	AENTIAL DAMAGES.				Jan J	26 Citty
then from the 30th cay ionier	and the real linear streets the I are ad	n of law is .	unin i	AND MILDEW		n inder der Frischer Amerikanska singer National Amerikanska		Sign	ature <u>V</u>	AT JANA
ORCESSARY BECAUSE OF IMAGE OF	the purchaser to pay the contract of the side site of the side of	DUCKING Proc. of	t's underst	bod and agreed that Sansone (	orpozilon wil be held	hermines for alleged or ac	tuai damages/clams	ai a Date		7-175-8-2- 7-176-2-4-
ndor collection thes pursuant	torsuch action of law.		nicocenty da	ld, algae, or lungus. It in underst mage, and clean up expenses	caused directly or india	actly in whole for any rea	son as a result of a	kury xold,	1 × 14	A CAL
物理学生学				ngus and milder regardless of t y or in any sequence to the injur			insi may have contrib	uted    Tech	nician_/	在電腦網2個

#### 090504CBB1664 Exhibit 2 Page 3 of 4



BLANTON HEATING & MR CONDITIONING, INC. 2515 Harding Street HOLLYWOOD, FLORIDA 33020

Phone (964) 521-7235

# HVAC SERVICE ORDER INVOICE

21963

811.70 THIS WORK IS TO BE C C.O.D. CHARGE L. NO CHARGE MAKE CAKE VODE NODE SEINAL NUMBCH SEFIAL NURGED abblesteve and DN. 1-01 ENVIRONMENTAL CHECK LIST WORK PERFORMED WORK PERFORMEN TYPE DISPOSITION CORDISATE DRAMS GTV CONDENSING UNIT ollaned Man Dhain RECOVERSO LEVELED CALL NE\* ORE . A.M. . RM. AERAUSED Webs and a ALCYCED CLEANSD COL ALL ROLL \* FOR T FADRO PAL CRAD CHECKED L. Abathawen HEFAIRSD LEAR IN C HERVINED NEC DRAIN ी अल्गामारक RUFF 100 REFANICO LEAK EN COPÉE Ð FURN, QR FAN COI ate/hoisia: 458155TLED ASPLACED ROLT v Pr TOTAL S CHANGED ON CLECKED ROTOR រ រាល សារសេស្ត HORDER LITER DE LI HORDER HORDER JANDRAISEANNA KOL 948 - 34C Amada N OF WORK FERFORMED 463061EG PUILLEY REPLACED REFRIGERANT R-LBS ADJUSTED BELT CLEANCE CLEANCE CLEANCE DL folfilacife Ni Arengo VIAC 1 STAR THE REPORT EPL STAR DHED EEARMS: REPLACES RU ri - Ansir Reat exch PEPLACED HEAT EXCH LEANED DR NGE CONTACTO REPA(RED CLEWED OF ADJ PLOT WARING SCHLALAL MARINGOU NEPLACES FOSE ASPLACED COMPRESSOR NEPARED WALVE REPLACEL EVAPORATOR COL REPLACE C CXF, VALVE OLE ANELS SOMMERS ADJUSTED EXTENDE 90C REFEACED CAP TL BE TERA RED FUTERS CLEARED CAR TUBE 20105160 HERMRED COAL GESP THE COMPANY FILTERS PERMIEO DOPREH CONTR REPURCED BF: IS RECOMMENDATIONS CLEANED COL ათხეი , EVELED GOL TOTAL MATERIALS ELECT HTR CLG 10WER ASCUM 0.051.460.44 SATE aem agegrun. 12 245550 NEPLAGED SELA DEPARED WIT PUwP(8) 14667-4020-0020 6-42.582° ner anner 1 Sert ADLD FILTERS GLEAN D に可能を見た 550 れき感 だければ起かりの地域を知道 LIMITED WARRANTY: All materials, parts TOTAL LABOR and equipment are warranted by the TOTAL PLANTED TERMS manufacturors' or suppliers' written watranty only. All labor performed by the above named IOIAL MATERIALS company is warranted for 30 days or as otherwise indicated in writing. The above named TOTAL company makes no other warranties, express LAJOR or implied, and its agents or technicians are Consideration of the second president and above which has been called upper an entropy of a second standard and a second president of the second president of the second president of the second president of the second president and a second president not authorized to make any such warranties on behalf of above named company. TRAVEL CHARGE REGULAR WARRANTY SERVICE CONTRACT TAX (j.N.s. 1. r 11/2/01 ( 1 1 1 1 ~~

090504CBB1664	Exh	ibit 2	Page	4	of 4

A "le	Deliver Cool"		SERVICE	IDITIONING - APPLIANCES - PLUMBING E AND MAINTENANCE AGREEMENTS D. DEERFIELD BEACH, FL 33442 • LICS. CAC 045862
	ne	665 N.W. I	NTERPRISE (954) 421	E DRIVE, PORT ST, LUCIE, FL 34986 • LICS. CAC 051473         28.8919 • (561) 655-3688 • (772) 398-6668         88 • Fax (954) 428-6503 • www.sansone-ac.com         CFC 1426106 • ER 001787
IER NAME		CUST #		PHONE # JOB # DISPATCH # TIME IN TIME OUT COMPLETE INCOMPLETE
		APT #	2 644	219 CREDIT CARD CREDIT CARD
s (4 - 7/1	in the Asia in			
CE COMPLAINT			n ser inst	Model No. 4 N. Comp Inc Serial No. 3057 72411 Gomp Inc
& MATERIALS		COST		Model No. Compressor
* 7 7	<u>.</u>	3.401 ( 	н н (4. 1977 (*)	Surt Proce
Allan Tenk	<u>Chin</u>			Description of Work Performed:
	2 Berlin	an a	- · · · · · · · · · · · · · · · · · · ·	Flore consi los chested coste parts haid Votes Amos
	<u>na de la p</u> roposition de la composition de la	1	- -	Changest in the left by Surface Value Cond Coll
			· " .	Harster Bawit Sizian Charlest with Michan State Entrain Temp
14 () (32 (27) 			·	Leav Air Temp
	· · · · · · · · · · · · · · · · · · ·			Refrigerant
No yo yo yo ya Na iyo yo yo ya			. t ša . 75	Adequate Charg
				Check for Leaks
				- Cond Motor
	Total Materials		i na aja	Volts Amps
	Misc. Service Materials	\$ 1.	5.00	Technician Recommends Est Price Evap Sect
	Total Labor	2 - 1		The second se
HICTORY ALTRICKIZED	Flat Rate Pricing	,	<u>) A -</u> M N A	- Leav Air Temp
DEALER				Volts Amps
Carrier	Discount			Pulleys (Adj belt
n to the Experts	Tex.		e o Sa	
n in naithe Anns an Annaithe Anns an Annaithe	Total			Clean Drain Pan
		<u></u>		le se
ASE READ				D WABRANTY
statement before our a	riumity to serve you. Please be sure to care endce man leaves your premises. Please lei	t him know	tating repair	All use normal care performing the service shown but shall not be liable for laiture to discover conditions necessi- lins or replacements, nor shall any inspection be constructed as an approval or guarantee of the equipment.
elely of note on this inv	cios il anything is not clearly understood.		days unless	Heating is and materials fixed above and the labor performed as shown on this involte for a period of 30 is otherwise stated on this involte. This warranty does not over any other parts in your unit(s). Any new repeirs
w order the above work i the "Acknowledgemeni vis due and unpaid 30 de Islactory Completion" the tom the 30th day forward	O PERFORM WORK to be done and agree to pay in hull this involu- of Satisfactory Completion. I further agr yos from the date of the signing of the "Actors a date in which the guarantee embodied he interest shall accrue at 15% per month up	ree that any owledgement trein expirus, kon the entire	required in 1 ed to normal equipment, sons are no hours: 8AM	I the future by tailure of parts not under our warranty or by conditions not under our control such as but not initi- nal wear and tear, parts damaged by unauthorized personnes, acts of God, or improper operation or use of the will be charged to the customer. Sansone makes no other warranties expressed or limited and its service per- lot authorized to make any such warranties for Sansone. Warranty work shall be performed during regular working M-SPM Mon-Fit. SAM-3PM Sat. UNDER NO CIRCUMSTANCES SHALL SANSONE BE LIABLE FOR , SUBSEQUENT OR CONSEQUENTIAL DAMAGES.
i balance until all amoun sary because ci tailune	is are fully paid. I lurther agree that if any ac of the purchaser to pay this contract in full rests due plus reasonable attorney's less,	tion of law is then the pur-	it is unders result of m	AND MILDEW AND MILDEW rstood and agreed that Sansone Corporation will be held harmless for allegied or actual damages/cleims as a nold, algae, or fungus. It is understood that Sansone will not be responsible for damages related to bodily injury, damage, and idean up expenses caused directly or indirectly in whole for any reason as a result of mold,

## 090504CBB1664 Exhibit 3 Page 1 of 9



Photo 1 shows the section of drywall sampled by the Rinker School of Construction.




Photo 2 shows the second floor air conditioning unit

#### 090504CBB1664 Exhibit 3 Page 2 of 9



Photo 3 shows blackening on of a copper pipe connected to the second floor air conditioning unit.




Photo 4 show pitting on the metal shower head in the master bathroom.

# 090504CBB1664 Exhibit 3 Page 3 of 9




Photo 5 shows pitting of metal fixture on the shower door in the master bathroom.




Photo 6 shows pitting on the mirrored light fixture in the master bathroom.



Photo 7 shows pitting on the metal faucet in the guest bathroom.



Photo 8 shows blackening beginning on the edge of the mirror in the guest bathroom




Photo 9 shows pitting underneath the faucet in the laundry room.



Photo 10 shows a blackened ground wire in an electrical receptacle that has been replaced due to smoking in the past.

090504CBB1664 Exhibit 3 Page 6 of 9






Photo 12 shows a blacked copper pipe located behind the refrigerator.

# 090504CBB1664 Exhibit 3 Page 7 of 9




Photo 13 shows an additional copper pipe located behind the refrigerator.




Photo 14 shows the air conditioning unit on the first floor.




Photo 15 shows a closer view of the evaporator coils in the a/c unit.



Photo 16 shows another view of the corroded evaporator coils.

## 090504CBB1664 Exhibit 3 Page 9 of 9



Photo 17 shows another view of the corroded evaporator coils and wiring.



Photo 18 shows more corroded coils and rust on the evaporator coils.

# SHORE PEDIATRICS

April 27, 2009

Re: Sydni Quittner DOB 12/23/08

To Whom It May Concern:

Sydni Quittner is currently under my care. I have evaluated this infant on several visits for respiratory symptoms including cough, runny nose, and cyc-rubbing. Her parents have reported that their house contains Chinese drywall. As the health effects of this sulfur- containing compound are not fully known, and there is a known association between exposure to Chinese drywall and respiratory symptoms, it is my recommendation to Sydni's parents that she not reside in their home until this potentially toxic substance has been removed from the home environment.

Sincerely, Raine S

Rachel S. Shore, MD, FAAP

www.shorepediatrics.com

# U.S. Consumer Product Safety Commission

# AUTHORIZATION FOR RELEASE OF NAME

Thank you for assisting us in collecting information on a potential product safety problem. The Consumer Product Safety Commission depends on concerned people to share product safety information with us. We maintain a record of this information, and use it to assist us in identifying and resolving product safety concerns.

We routinely forward this information to manufacturers and private labelers to inform them of the involvement of their product in an accident situation. We also give the information to others requesting information about specific products. Manufacturers need the individual's name so that they can obtain additional information on the product or accident situation.

Would you please indicate on the bottom of this page whether you will allow us to disclose your name? If you request that your name remain confidential, we will of course, honor that request. After you have indicated your preference, please sign your name and date the document on the lines provided.

I request that you do not release my name. My identity is to remain confidential.

You may release my name to the manufacturer but I request that you do not release it to the general public.

You may release my name to the manufacturer and to the public.

(Signature) (Signature) (Date)

r	CONSUME	R PRODUC	T INCIDENT	REPORT	Region: EASTERN
1.NAME OF RESPONDEN Lee Quittner	IT		HONE NO. (H 1-699-7913	OME) (WORK) unknown	
3.STREET ADDRESS		4.0			ST ZIPCODE
9830 Cobblestone Creek D	r.		oynton Beach		L 33472
4a.EMAIL ADDRESS			INCIDENT CI		ST ZIPCODE -L 33472
5.DESCRIBE INCIDENT The A/C has been times and it is - cont -	affected	3 times	, it has	also been sei	rviced 3 are
OF AGE/S INCIDENT(S) AND D	JURY OR NEAD EX 34 Y/M ESCRIBE INJU respiratory issues, v	JRY		8.IF VICTIM DI RESPONDENT, self RELATIONSH self	PROVIDE NAME
9.DESCRIPTION OF PE Chinese drywall	RODUCT			10.BRAND NAME Knauf Tijan	
11.MFR/DISTRIBUTOR unknown Blake unknown unknown unknown unknown	I	& PHONE SSUE 2' 30/2009	7 unknowr 13.DEALE	R'S NAME, ADDRE	
14.WAS THE PRODUCT OR MODIFIED? YES	-	PAIRED	15.PRODUCT DATE PU	PURCHASED NEW RCHASED 10/15/200	06 <b>AGE</b> 2 Y
IF YES, BEFORE O INCIDENT? AFTER DESCRIBE: See narrative for various p			IF SO, 1	DDUCT HAVE WARN NOTE: ning to the problem.	ING LABELS?
MANUFACTURER? NO YES			PRODUCT STI ITS DISPOS	19.MAY WE USE YOUR NAME WITH THIS REPORT? YES	
	FO	R ADMINI	STRATION US	3E	
20.DATE RECEIVED 2 03/27/2009	1.RECEIVED E mlj/HL	BY (NAME	& OFFICE)	22.DOCUMENT NO H0930251A	).
23.FOLLOW-UP ACTION	1			24.PRODUCT COI 1876	DE(S)
25.DISTRIBUTION			DRSER'S NAM 0/27/2009	E & TITLE	

۰.

H0930251A

#### Narrative Continued

#### completely blackened.

- All of the electrical wires in the home are corroded. The alarm system panel has been replaced twice. The consumer's 36" television has stopped working. All of the hardware (shower heads, lighting fixtures) have been replaced during the warranty period by the builder, but they are turning black in color and becoming pitted again.
- The consumer believes that he has a severe, urgent, immediate electrical issue within the home. The consumer is in a community where most if not all of the homes were built around the same time. Therefore, the problem would definitely be widespread throughout this community. The consumer understands that federal and state government agencies are looking into this matter, but he believes that the CPSC should coordinate with FEMA and address this matter immediately. Based on problems that have been identified with this drywall, people can not live in these homes without being negatively affected by this problem. The consumer said based on his research, there has been enough drywall imported into the U.S., to where it could affect 60,000+ homes.
- This problem needs to be brought to the national public's attention, because there may be an unidentified amount of people who have experienced similar problems as the ones caused by this drywall, but who may not have had any idea what was causing their problems.
- The consumer can not emphasize strongly enough how severe this problem is. His 3 month old daughter has a constant runny nose and irritated/watery eyes. The consumer has experienced severe respiratory issues along with a whooping cough. He is extremely concerned about the types of health symptoms his wife experienced during her pregnancy and what his entire family may develop down the line as a result of the exposure to this drywall.

The consumer has also volunteered his home for inspection/investigation if the CPSC decides to look at it.

Vict #	Sex	Age		Name			Relationship
2	F	3 M	not given			daughter	
Vict #	-			Victim	Injury	Description	
2	con	stant runny nos	e and irritated/w	vatery eyes			
Distrik	utor	Phone #:	unknown				
CPSC Sc	nurce	e: CPSC					

•

1. Task Number	· · · · · · · · · · · · · · · · · · ·	-	2. Investigator's ID			
090504CBB1663			8919		EPIDEMIOLOGIC	
3. Office Code	4. Date of Accid		5. Date Initiated		INVESTIGATION	
840	YR MO DA 2006 01 01		YR MO DAY		REPORT	
810			2009 05 05			
8. Synopsis of Accide	•		UPC			
new house in Cape C	oral, FL in 2006. E	Evaporator	coils in the air condition	ing units and house was la	eir drywall since moving into a d plumbing fixtures in the abeled: "MADE IN CHINA."	
				PRODUC 	CD CLEARED for PUBLIC RS/PRVTLBLRS OR CTS IDENTIFIED ED BY: PETITION KING ADMIN, PRCDG RTIONS REMOVED US MA	
7. Location (Home, Sc	hool, etc)		8. City		9. State	
1 - HOME			CAPE CORAL	•	FL	
10A. First Product		10B. Tra	de/Brand Name		10C. Model Number	
1876 - House Structu	res, Repair Or	CHINES	E DRYWALL	• •	UNKNOWN	
11A. Second Product		11B. Trac Not Respon	de/Brand Name nsive		11C. Model Number	
381 - Air Conditioners		-				
11D. Manufacturar Ma Not Responsiv	<u>e</u>	·				
12. Age of Victim 62	-		14. Disposition 1 - Injured, not Hosp.		15. Injury Diagnosis 68 - Poisoning	
16. Body Part(s) Involved 85 - ALL OF BODY	17. Respondent           Y         1 - Victim/Complainant		18. Type of Invest       1 - On-Site	stigation	19. Time Spent (Operational / Travel) 12 / 2	
20. Attachment(s) 9 - Multiple Attachme	20. Attachment(s)     21. Case S       9 - Multiple Attachments     07 - Const			22. 5	Sample Collection Number	
23. Permission to Disc	close Name (Non	NEISS Ca	ises Only)	•		
⊖ Yes	No No		🔿 Verbai	0	Yes for Manuf. Only	
24. Review Date 06/02/2009	25. Reviewed B 9057	У		26. Region Dennis R	nal Office Director Blasius	
<b>27. Distribution</b> Blasius, Dennis; Rose	e, Blake; Woodard	, Dean		28. Source 10940533	e Document Number A	

CPSC FORM 182 (12/96) Approved for Use Thru 1/31/2010 OMB No. 3041-0029

All of the information contained in this report was obtained during an on-site interview with the consumer and his wife on 5/15/2009. The consumer reported this incident to CPSC via the Internet on 4/21/2009.

-1-

The 64 year old consumer and his 62 year old wife had a new house built in Cape Coral, FL in 2006. The house was built on top of the foundation of an older home they had lived in for many years. The consumers moved into the new house in December 2006. The new, two story, Mediterranean style house measures 5,000 square feet has 4 bedrooms, 3 baths and a 3 car garage. The bedrooms are carpeted. There is natural gas service to the stove and fireplaces and electric service to the other appliances in the house. Woods studs were used in the house. The consumers have not noticed an odor in the house. The consumers do not have any pets.

The 64 year old male consumer stated that he was diagnosed with Chronic Obstructive Pulmonary Disease (COPD) before he moved into the new house. He stated that some days he has more difficulty breathing than other days. He does not know if his condition has been aggravated by the drywall in his house. The consumer's wife stated that in the last six months she has developed sinus problems and post nasal drip. She said that she sometimes wakes up in the morning with a headache and that she occasionally has insomnia. The consumer has not sought medical attention for her symptoms.

The consumer stated that he purchased a brand new dryer when they moved into the house. He said the dryer isn't drying properly now and the washing machine makes loud noised when it runs. The consumer also said the microwave's digital "brain" has been replaced three times since they moved into the house. He said it was first replaced six months after they moved into the home, replaced again 8 months later and was last replaced a year ago. A technician who repaired the microwave told the consumer that the firm had not really seen any previous problems with the consumer's microwave model.

The consumer said they have had problems with the home's three air conditioning units since the day they moved into the house. He said technicians came to the house several times to the recharge the Freon after they moved in, but that never solved the problem. On 3/16/2009, an A/C technician found that the upstairs air conditioner unit was out of Freon and that the air compressor needed to be replaced. On 3/30/2009, A/C technicians opened all three air conditioning units in the consumer's house and performed a leak search. The consumer said that the evaporator coils in all three units were black. The evaporator coils were replaced on 4/14/2009. (Refer to copies of A/C invoices in Exhibit 21).

The consumer's wife stated that the light bulbs burn out in the upstairs bedrooms, the circuit breaker in the master bedroom upstairs trips, and the phone line went out in the office for the master bedroom. The consumer added that the light switches by the entry feel hot if they have been on for a while, and the smoke alarm at the top of the stairs activated last year for no reason.

-2-

The consumer stated a year into the home they noticed that the drain on the master bathroom sinks started pitting. The consumer got in touch with the builder and complained that the fixtures had started pitting. The builder agreed that the fixtures were faulty and replaced the faucets, shower bodies, knob Not Responsive ub filter, shower stops and handles in the master bathroom. The consumer stated that the new fixtures are showing signs of pitting again (refer to photos in exhibits 14-20). The consumer's wife stated that her silver jewelry has also turned black.

The consumer stated that 800 sheets of drywall were delivered to the house on 9/1/2009. The consumer said he walked by the drywall and noticed that it was labeled, "MADE IN CHINA." The consumer became upset that he couldn't even get American-made drywall in his house. (Refer to photos of the drywall being delivered to the house on 9/1/2009 in exhibits 1-13).

The consumer said he first realized there might be a problem with the drywall in his house on 3/16/2009 when the air conditioner technician visited his house and told him that the A/C was completely out of Freon. The consumer contacted his insurance company about the drywall. The consumer insurance company told him that it was an outside pollution problem that it is not covered by their homeowner's policy.

The consumer contacted the home builder on 3/16/2009. The homebuilder came to the consumer's house, examined the electrical wiring, and found that the copper wiring was turning black inside the light switches and the outlets. The builder told the consumer that they may have to rewire the entire house. The consumer said it would cost \$1,000,000 to replace the CAD 5 wiring throughout the home.

The consumer spoke to Senator Nelson when he visited Coral Lakes, FL in April 2009 to address the Chinese Drywall situation. He has also been in contact with Christopher Day, Legislative Counsel in the Senator Nelson's office.

The consumer said he has been approached by quite a few attorneys but he has refrained from joining a class action lawsuit. He said his short term plan is to gather all the information necessary to make government agencies realize the severity of the problem. The consumer said that long term he wants the house to be repaired.

During my 5/15/09 on-site, I observed and photographed the following: Pitting on the sink in the first floor guest bedroom (exhibits 14 & 15). Pitting on the shower drain the master bedroom bath (exhibit 16). Corrosion on gold fixtures inside the Responsive exhibits 17 & 18). Pitting on the shower handle in the master bedroom bath (exhibit 16). There was no blackened copper pipe outside of second floor air handler (exhibit 20). There was no exposed drywall available for examination at the time of the IDI.

-3-

#### **PRODUCT IDENTIFICATION:**

There was no exposed drywall to examine in the consumer's house at the time of the IDI. The consumer stated that the drywall delivered was labeled Made in China. Refer to photos taken by the consumer of drywall in Exhibit 1-12.

House Structures: Brand: Manufacturer:	(Product Code 1876) Unknown Unknown
Drywall Supplier:	Stock Building Supply 3601 Work Dr. Fort Myers, FL 33916 (239) 337-5001
Builder:	Alvian Homes 3100 Del Prado Blvd. Suite 308 Cape Coral, FL 33904 (239) 541-0211

# EXHIBITS:

Exhibits 1-20 Photographs.

Exhibit 21 Copy of Air Conditioner Service Invoices.

Exhibit 22 Authorization for Release of Name Form.

Exhibit 23 Respondent List.

Exhibit 24 Consumer Contact List.





Exhibit 1 – Photograph of drywall being delivered to the consumer's home on 9/1/2006.




Exhibit 2 – Photograph of drywall being delivered to the consumer's home on 9/1/2006.




Exhibit 3 – Photo of drywall being carted into consumer's home.




Exhibit 4 – Photo of drywall sheets inside consumer's home.





Exhibits 5 & 6 - Additional views of drywall sheets inside consumer's home.








Exhibit 7 – Photograph of workers installing drywall inside consumer's home




Exhibit 8 – Additional view of drywall in the consumer's house.





Exhibits 10 & 11 - Photograph of workers installing drywall in the consumer's house on <math>9/7/2006.





Exhibit 12 – Photograph of drywall being installed on 9/7/2009.



Exhibit 13 – Finished view of the outside of the consumer's home.

-9-

-10-




Exhibit 14 – Photograph of pitting on sink in the first floor guest bedroom.




Exhibit 15 – Close up of pitting on bathroom sink in first floor guest bedroom.



Exhibit 16 – Photograph of pitting on shower drain the master bedroom bath.








Exhibit 18 – Photo of corrosion on gold fixtures inside the Jacuzzi.




Exhibit 19 - Photo of pitting on shower handle in master bedroom bath.






Exhibit 20 - Photo of blackened copper pipe outside of second floor air handler.

Purified Air Condition 18000 Leetana N. Ft. Myers, FL 3 Office (239) 573-1 Fax (239) 543-1 Lic. #CAC0538						Rd. Air Conditioning 3917 2086 297					
NAME	(b)(3):CPSA Section 25(c)	1				PHONE					
						BILLING ADDRESS APT./UNIT					
STRE					INIT	BILLING ADDRESS					
CITY			11		P	CITY		STATE	ZIP		
ALTER		\ <u>.</u>	<u> </u>	ONE NUMB	ER	AUTHORIZED BY PHONE NUMBER					
	A	SYSTEM INFORM				OUTDOOR			<b>D</b>		
TECH	NAME L'ASCY	MANUFACTURER	ALC:N	Not R	esponsiv	e					
ТІМЕ	ARRIVED	MODEL NUMBER							- 		
TIME	DEPARTED	SERIAL NUMBER									
NO	RMAL WARRANTY (1st YEAR)	CONDITION (1 = B	ËST)	0	2	3 4 5		$\binom{1}{2}$ 2 3	4 5		
PROE	LEM REPORTED					PROBLEM DIAGNOSED		<b>b</b> d'	<u> 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000</u>		
								da u -			
QTY	PARTS AND MATERIA	L USED	UNIT PRICE	AMOUNT		DESCRIPTION OF WORK PERFORMED					
		(			Una	in according customer explained system					
	and all the states of the stat				1 jay	is not along Found System almost flat.					
	A sector of the				Dech	nuged system. Started system up. 2 stage					
					545	han compressor " I works, " I a has					
	N/					5 42 (umpri)	50- 11	placed Also re	se la		
					5000	Sim ligh grant of elu & Alth roll, M					
						lease is found	in in f	f .	4 hr iso.		
					1054	on system licelystants \$ \$9, Iso lost					
						diara A .		<u>م ال الم الم الم الم الم الم الم الم الم</u>	A 1 tale		
					1				740		
		e san de constante de la constante con	· · · · · · · · · · · · · · · · · · ·		12	Itshur comp	11. 1		140,		
	<u> </u>				1	stance philo and that system had had justice					
	MPRESSOR	CHECK &	LUBE BE	ARINGS & I	MOTOR	SERVICE CH		\$70			
🗆 SU	CTION PSI		TOR COIL	-				\$P10			
Image:						PARTS	لا بر ای میسید بقو				
□ ELECTRICAL CONNECTIONS     □ REFRIGERANTS       □ CONTACTS TIGHT & CLEAN     □ LEAKS     □ CHARGE					TOTAL CH		\$740				
CONDENSER COIL CLEAN COIL A CHECK FIN COND. CLEANED C											
D FAN & MOTOR D CONDENSATE AREAS					I HEREBY AUTHORIZE THIS WORK TO BE CHARGED TO MY CREDIT CARD.						
ID VOLTS AMPS       ID INSPECT & CLEAN DRAIN PANS         ID ELECTRICAL CONNECTIONS       ID INSPECT & CLEAN DRAIN					SIGN						
CONTACTS TIGHT & CLEAN     ELECTRICAL COMPONENTS     FAN PULLEYS (ADJUST BELT)     ELECTRICAL COMPONENTS					AMOUNT CHARGED						
PLEASE PAY FROM THIS INVOICE. NO OTHER					VISA OR MASTE	RCARD MI	UST HAVE FOUR SETS C	FNUMBERS			
STATEMENT WILL BE ISSUED								EXP.			
CUSTO	CUSTOMER V								DATE		
SIGNATURE					C.S.V. (three digit number on bi	ack of card)	Billing Zip Code				

090504CBB1663 Exhibit 21 Page 1 of 2

p.2



Purified Air Conditioning, Inc. 18000 Leetana Rd. North Ft. Myers, FL 33917

Date	Invoice #				
3/30/2009	1302				

# Bill To ALLVIAN HOMES (b)(3):CPSA Section 25(c) Cape Coral, FL

Project Terms Via Rep Ship Due on receipt RS 4/14/2009 FAX Q .. Item Code Price E... Amount Description SERVICE PER... PERFORMED LEAK SEARCH ON SYSTEM WE REPLACED COMPRESSOR ON. FOUND MULTIPLE LEAKS IN EVAPORATOR COIL, SYSTEM LOW ON **REFRIGERANT. RALPH EXPLAINED THAT THE OTHER (2) SYSTEMS NOT** WORKING PROPERLY. CHECKED REFRIGERANT LEVELS ON OTHER SYSTEMS, BOTH ARE LOW. PERFORMED ELECTRONIC LEAK SEARCH ON EACH SYSTEM, BOTH SYSTEMS EVAPORATOR COILS LEAKING. ALL (3) COILS NEED TO BE REPLACED. COILS ARE COVERED UNDER MANUFACTURER WARRANTY, LABOR AND MATERIALS ARE NOT COVERED. ADDED (14) LBS OF REFRIGERANT TO SYSTEMS TO BRING TO PROPER LEVELS FOR TEMPORARY COOLING. 1 SERVICE DIA... 85.00 85.(0) 7 REFRIGERANT FIRST FLOOR SYSTEM 25.00 175.00 4 REFRIGERANT MAIN SYSTEM 25.00 100.00 **3 REFRIGERANT** MASTER BEDROOM SYSTEM 75.00 25.00 **3 LEAK SEARCH** 79.00 237.00 I PARTS FOUND MOTOR AND MOTOR MODULAR BAD. PICKED UP PARTS UNDER (0.00)0.00 WARRANTY FROM TRANE, RETURNED AND INSTALLED PARTS, NO CHARGE FOR LABOR. Total \$672,00 Phone # Fax # E-mail 239-573-2086 239-543-1297 purifiedairconditioning@netzero.com

p.3 090504CBB1663 Exhibit 21 Page 2 of 2



Purified Air Conditioning, Inc. \* 18000 Leetana Rd. North Ft. Myers, FL 33917

Date	Invoice #
4/14/2009	1303

Invoice

Bill To		
(b)(3):CPSA Section 25(c	)	
Cape Coral, FL		

			Terms	Rep	Ship	Via	Project	10.0 At 10.000
			Due on receipt	RS	4/14/2009	FAX		
Q	Item Code			Descriptio	<u> </u>	· ·	Price E	Amount
3	EVAPORATOR	COATING	······································		<u></u>		535.00	t.605.00
1 1 1	EVAPORATOR EVAPORATOR EVAPORATOR	3-TON VERTIC	ONTAL, LABOR, M Cal. LABOR, MAT Cal. LABOR, MAT	ERIALS,	REFRIGERANT	7	600.00 475.00 475.00	600.0( 475.0( 475.0(
-								
		L				Total	<b>   </b>	\$3,155.00
	Phone #	Fax#	E	mail		I		
239-573-2086		239-543-1297	purifiedairconditi	oning@netz	ero eom			

# U.S. Consumer Product Safety Commission

# AUTHORIZATION FOR RELEASE OF NAME

Thank you for assisting us in collecting information on a potential product safety problem. The Consumer Product Safety Commission depends on concerned people to share product safety information with us. We maintain a record of this information, and use it to assist us in identifying and resolving product safety concerns.

We routinely forward this information to manufacturers and private labelers to inform them of the involvement of their product in an accident situation. We also give the information to others requesting information about specific products. Manufacturers need the individual's name so that they can obtain additional information on the product or accident situation.

Would you please indicate on the bottom of this page whether you will allow us to disclose your name? If you request that your name remain confidential, we will of course, honor that request. After you have indicated your preference, please sign your name and date the document on the lines provided.



I request that you do not release my name. My identity is to remain confidential.



CP


You may release my name to the manufacturer but I request that you do not release it to the general public.

(b)(3) CPSA Section 25(c) to the manufacturer and to the public.



# **IDI # 090504CBB1663** Exhibit 23

### RESPONDENT LIST:



The consumers were initially contacted on 5/5/2009.



# **IDI # 090504CBB1663** Exhibit 24

## **CONSUMER CONTACT LIST:**

(b)(3):CPSA Section 25(c) consumer, Cape Coral, FL reported problems associated with Chinese drywall to:

- Bill Bernecker, General Adjuster AIU Holdings P.O. Box 157273 Cape Coral, FL 33915 (973) 727-8536
- Rob Rimany, President Alvian Homes
   3100 Del Prado Blvd.
   Suite 308
   Cape Coral, FL 33904
   (239) 541-0211
- Christopher Day, Legislative Counsel Senator Bill Nelson (FL) (202) 224-5274 (202) 228-2183 Christopher\_Day@BillNelson.Senate.gov

1. Task Number				2. Investigator's ID				EPIDEMIOLOGIC	
090727CBB1886	9102								
3. Office Code	5. Date Initiated YR MO DAY				INVESTIGATION REPORT				
810	YR MO D. 2007 08 1		2009					NEI ON	•
6. Synopsis of Accide	nt or Complaint			22332	2-02184-3				
The 54 year old male new air conditioner co problems due to the c their home. Only the	and 64 year old f bils in August 200 Irywall in their hor	7. They had ne. The ho	e owners 1 previou me had r	move s upp	ed into the er respira	ir hom tory pre	oblem	s and were uncertain	of health
					MFR	/PRVLI	BR NO	TIFIED /	
					сом 0	MENTS	:\ LED;_	ATTACHED	
					<u>_</u> E	xcisio	NS/FO	IA EXS. 4, 250	
						·		DTIFYRE-NOTIFY	
						-		wo //	2 <i>CID</i>
7. Location (Home, Sc	hool, etc)		8. City					9. State	
1 - HOME			SUN C	ITY C	ENTER			FL	
10A. First Product		10B. Trac	le/Brand	Nam	e			10C. Model Number	
1876 - House Structu	res, Repair Or	NATION,	IAL GYPSUM					GRIDMARX	
Charlotte, N	C 28211								
11A. Second Product 11B. Trac 0 NONE			de/Brand Name			11C. Model N NONE	umber		
11D. Manufacturer Nar NONE	me and Address								
12. Age of Victim         13. Sex           54         1 - Male			<b>14. Disposition</b> 0 - No injury				<b>15. Injury Diagnosis</b> 70 - No Injury		
16. Body Part(s) 17. Respondent			18. Type of Investigation					19. Time Spent	
Involved 99 - NO INJURY 1 - Victim/Complainan			1 - On-Site				(Operational / Travel) 20 / 4		
20. Attachment(s)21. Case S9 - Multiple Attachments07 - Const			ource 22.3 Imer Complaint			Sample Collection Number			
23. Permission to Disc	lose Name (Non	NEISS Ca	ses Only	')		_	<b></b>		
🔿 Yes 🔷 No				🔿 Verbal 🛛 🌒			•	Yes for Manuf. Only	
24. Review Date         25. Reviewed By           08/11/2009         9001			<b>26. Region</b> Dennis R.			al Office Director Blasius			
<b>27. Distribution</b> Blasius, Dennis; Matheson, Joanna; Rose, Blake; Andrew				anna, Rohit; Trotta, 10960598A					

CPSC FORM 182 (12/96) Approved for Use Thru 1/31/2010 OMB No. 3041-0029

This investigation was initiated by a complaint received by the U.S. Consumer Product Safety Commission.

The information contained in this investigation was supplied by the following sources:

1. An onsite interview with the male owner of the home on 7-28-2009.

Family Members:


Husband – 54 year old male Wife – 64 year old female

This incident involves health issues and copper and metal corrosion at the non seasonal home of the victims over an extended period of time as will be detailed later in this report which the owners believe were caused by contaminated Chinese drywall used in the construction of their home.

An engineering firm was hired by the CPSC to collect and conduct air and drywall sampling and examination at the home and the results will be provided to the consumer once completed.

The home was 2 bedrooms plus den, 2 bathrooms new construction, 1820 square foot home in Sun City Center, FL. The owner contacted the CPSC on 6-17-2009. The incident date is being listed as when the Air Conditioner coils were replaced on an unspecified date in August of 2007.

The home was built in 2006 and the homeowners purchased and occupied the home in August of 2006. The home is a single story ranch style home with tile in the main living areas and carpeting in the bedrooms. The home was a cinder block and stucco construction home with wood studs. The home was mainly electric with natural gas to the clothes dryer, central heater and water heater.



The homeowners had no invoices they could locate to document the drywall supplier or installer however a firm they believe installed the drywall is included at the end of this report. The home owners conducted no changes or replacements to the drywall, paint etc. They had no pets.

The homeowners lived in the home on a full time basis until August 2007. They commute to the Washington DC area as consultants and since that time are gone three out of four weeks each month.

Both the homeowners had sensitive sinus conditions before they moved into the home and could not tell any difference in their health condition since living in the home. However they noticed a distinctive pungent solvent like odor upon moving into the home and notice the odor each time they returned to the home, but became accustomed to the odor very quickly. This investigator noticed a sulphur smell immediately upon entering the home and noticed eye irritation after being in the home 3 hours.

They did not notice any stronger odors anywhere in the home and did not notice that the odor was stronger at any particular time.

The homeowners had not noticed any particular problems with the appliances or electronics of the home until their Air Conditioner coils failed and had to be replaced under warranty in August of 2007. The AC coils were inspected during this onsite investigation and showed considerable rusting/corrosion.




Photograph of recent corrosion to the evaporator coils at the home.

The only other item which had failed in the home was the television cable box which had been replaced twice for unknown reasons.

The homeowners saw a television news article in January of 2009 about homes having Chinese Drywall and the accompanying problems. They immediately realized that their home was probably constructed out of Chinese Drywall and began to investigate their home for symptoms.

The home had moderate corrosion to the copper water supply lines underneath the sinks and considerable blackening of the ground copper electrical wiring at the electrical receptacle. The brass water cut offs had turned an odd brown bronze color.



Photograph of blackening of the ground and power wires to the dining room electrical receptacle.

A bathroom mirror was showing corrosion at the edges.



Photograph of the bathroom mirror corrosion.

The brand, name or manufacturer of the drywall in the walls could not be identified. However a piece of drywall the consumer cut out of the ceiling in the garage to install an attic access had been retained and appeared to be American made. The information on that firm and labeling is included in the exhibits; however the drywall in the ceiling is not necessarily the same as that in the walls. In fact the homeowner indicated that the drywall thickness in the ceiling is different that the drywall in the walls and probably a different manufacturer.

The consumers contacted the builder who inspected their home on 4-30-2009. They found blackened AC evaporator coils, blackened electrical copper wiring in the outlets, blackened refrigerator coils, moderate corrosion of the water supply lines and a definite sulfur odor in the home. According to the consumer, the builder refused to produce a report or document their inspection of the home. On 6-08-2009 an adjuster of the homeowner's insurance company inspected the home but had not produced a report for the consumer. On 6-09-2009 an engineer for the homeowner's attorney inspected the home but had not produced a report for the consumer.

The homeowner indicated he would send a copy of any reports they receive.

On 6-19-2009 an engineer was hired by the consumer's attorney, inspected the home but had not produced a report by the time of this inspection by the CPSC. A copy of the consumer's time line is included in the exhibits.

The consumer also indicated that he had attempted to use 35mm film for his camera but it could not be developed and had been affected/corroded by the odors in his home. The builder is now in Chapter 11 and information about the firm is included in the exhibits. The homeowner had not experienced any flickering lights or breakers flipping.

The homeowner had heard from the community the name of the drywall installer for the builder. He had no documentation. Two firms by the same name were located on the Internet and their addresses are included in the exhibits.

The consumer indicated he had also completed an online complaint with the Florida Department of Health and had been on ABC's Action News twice explaining problems with his home.

Photographs of the consumer's home are included in the exhibits. The homeowner indicated his permission to release his name only to the manufacturer of the drywall. A copy of the permission to examine the home is included in the exhibits. The exit final release form was not signed.

#### **Product Information:**

Product: Wall Drywall, Possible Chinese Drywall Manufacturer: Unknown

Product: Ceiling drywall National Gypsum Company Headquarters 2001 Rexford Road Charlotte, North Carolina 28211 Phone: 704-365-7300 Fax: 800-329-6421 ng@nationalgypsum.com Barcode: 0-22332-02184-3 GridMarX

#### Builder:

WCI Communities, Inc. 24301 Walden Center Drive Bonita Springs, FL 34134 United States Of America Employees: 1,800 Investor Relations Phone: (239) 498-8269 (239) 498-8146 (239) 498-8200 www.wcicommunities.com

Management: David L. Fry Interim President and CEO Jonathan M. Pertchik Chief Restructuring Officer Russell Devendorf Senior Vice President and Chief Financial Officer Paul D. Appolonia Senior Vice President of Human Resources Vivien N. Hastings Senior Vice President and General Counsel

#### Drywall Subcontractor:

#### Hinkel Drywall

Further details could not be determined or ascertained. Two firms by the same name are listed in the exhibits.

#### Drywall Supplier: Unknown


### -----

#### Attachments:

Exhibit #1 Contacts Exhibit #2 Release of name form Exhibit #3 Photographs of the home (20) Exhibit #4 Consent form to inspect and sample the home Exhibit #5 Information on the builder Exhibit #6 Information on the ceiling drywall manufacturer Exhibit #7 Time line notes from the consumer Exhibit #8 Two possible drywall installer firms.

## **Contacts:**

х 1 с. Х



## **Consumer contacts:**

4-30-2009 6-8-2009	Tim with WCI unspecified adjuster from HomeWise Insurance					
6-9-2009	Michael Bass and engineer with HAS, hired by HomeWise					
6-19-2009	inspected home unspecified engineer hired by Krupnick Law Firm inspected home.					
Details, addresses and phone numbers for the contacts were not provided.						

# U.S. Consumer Product Safety Commission

# **AUTHORIZATION FOR RELEASE OF NAME**

Thank you for assisting us in collecting information on a potential product safety problem. The Consumer Product Safety Commission depends on concerned people to share product safety information with us. We maintain a record of this information, and use it to assist us in identifying and resolving product safety concerns.

We routinely forward this information to manufacturers and private labelers to inform them of the involvement of their product in an accident situation. We also give the information to others requesting information about specific products. Manufacturers need the individual's name so that they can obtain additional information on the product or accident situation.

Would you please indicate on the bottom of this page whether you will allow us to disclose your name? If you request that your name remain confidential, we will of course, honor that request. After you have indicated your preference, please sign your name and date the document on the lines provided.



I request that you do not release my name. My identity is to remain confidential.




You may release my name to the manufacturer but I request that you do not release it to the general public.

You may release my name to the manufacturer and to the public.

07/3-/2-09 (Date)


(Signature) T


CPSC Form 322





Photograph of the front of the home















IDI 090727CBB1886 Exh #3 Page 6 of 20




Photographs showing some darkening of the copper water supply line to another sink of the home.













Close up photograph of the Air Conditioner copper evaporator lines.




Labeling on the Air Conditioner.






The attic access of the home was added by the home owner and the drywall cutout was retained by the home owner. Labeling on the edges of the drywall retained by the home owner.





Additional labeling on the retained drywall cutout of the attic access.



Photograph of water mark labeling on the back of the drywall in the attic access of the garage.

"National Gypsum Company"





•

.

**RELEASE & WAIVER OF LIABILITY FORM** 

Ginned by All Residents 18 Years or Age or Older]

I, \_\_\_\_\_\_, do hereby give permission to the U.S. Consumer Product Safety Commission and any of its designated representatives, consultants, or other designees ("CPSC") to utilize my residence located at

for an indoor air-quality monitoring and testing study. This work is being undertaken as a part of an exploratory study to assess potential associations between constituents that may be present in indoor air and constituents that may be detected in drywall imported from China.

I understand that CPSC will be testing my residence for a variety of gases and/or other substances. Additionally, I understand that while CPSC will inform me of the chemical analysis results for my own residence, CPSC will not be providing further individualized analysis or recommendations concerning possible actions regarding health, safety and/or remediation which occupants could take in light of the information provided. However, CPSC will inform me if the chemical analysis results for my residence indicate the presence of gases or other substances above established risk levels.

I understand that this testing will take one full day of active testing and up to one to two week(s) of having passive sampling equipment in my home. I understand that after one to two week(s) of passive sampling, CPSC will contact me to arrange a time for CPSC to retrieve the passive sampling equipment. I represent that neither I nor members of my household will touch the passive sampling equipment while it is present in my home. CPSC requests that homeowners refrain from using cleaning supplies containing bleach, ammonia, and acetone. There may be other limited household activities which CPSC will request the homeowner to minimize, and CPSC will explain those activities in more detail when the testing begins.

I understand that CPSC intends to take small nail-size samples (less than 1/8 inch) from multiple inconspicuous locations throughout the home, such as behind switch plates and near baseboards. Additionally, CPSC may take drywall sample(s) of an approximate size of 6 inches by 6 inches and will cover the resulting hole(s) with a blank access panel.

I understand that neither 1 nor other members of my household, including minor children, will be compensated for our participation in this study nor will we receive any per diem allowance or other funds.

I understand that this study involves multiple residences and the final study and analysis will not be completed for a period of time, likely in the fall of 2009. I also understand that CPSC will likely not release information to the general public until the completion of the entire study. I further understand that this study may be widely disseminated to the public and that my own residence will not be identifiable by personally identifiable information such as address, name, etc. within the larger study.

I assume the risk of any and all injury or damage to my person or property that may arise, whether directly or indirectly, as a result of my participation in this study.

I hereby release and hold harmless CPSC, its officers, employees, consultants, representatives, and other designees and the United States Government from any liability for illness, injury, property loss or damage arising from participation in this study.

This agreement is made upon the express condition that for the period of time which CPSC or any of its equipment is in my residence for the purpose of conducting this testing, I shall be free from all liabilities and

Page | of 2

claims for damages and/or suits for or by reason of any illness, injury, or death to any CPSC officers, employees, consultants, representatives, and other designees of the CPSC or the United States Government, and that I shall be free from all liabilities and claims for damages and/or suits resulting to damage of CPSC property. CPSC hereby agrees to release and hold me harmless from any liability for illness, injury, death, and/or property lossor damage in connection with the testing as outlined above, however occurring.

<u>ly 18, 20</u>09 Signature

## [REMAINDER OF THIS PAGE LEFT INTENTIONALLY BLANK]

Page 2 of 2



# 1-800-WCI-400

NCI Communities	
ırs	
nization	
ns	
ienters	
	Search
Profile   Governance   Press Releases   Historical Annual Reports & Prox Detailed Quote   Email Alert   Request Info   Contact Us   Mi	
unities, Inc., named America's Best Builder in 2004 by the National of Home Builders and Builder Magazine, has been creating amenity- r-planned lifestyle communities since 1946. Florida-based WCI caters to tirement, and second-home buyers in Florida, New York, New Jersey, t, Maryland and Virginia. The Company offers traditional and tower home h prices from the high-\$100,000s to more than \$10 million and features y of recreational amenities in its communities. In addition to ng, WCI generates revenues from its Prudential Florida Realty Division, isinesses, and its recreational amenities, as well as through land sales entures.	User Preferences Mobile Office Online Briefcase Email Alert Request Info Feedback Center RSS Feed
	Investor Relations
	Phone: (239) 498-8269 Address: WCI Communities, Inc. (239) 498-8200 24301 Walden Center Drive Bonita Springs, FL 34134 United States Of America Employees: 1,800
	Management: David L. Fry
	Interim President and CEO Jonathan M. Pertchik
	Chief Restructuring Officer           Russell Devendorf
	Senior Vice President and Chief Financial Officer
	Paul D. Appolonia Senior Vice President of Human Resources
	Resources IDI 090727CBB1886 Exh #5 Page 1 of 9

<u>Vivien N. Hastings</u> Senior Vice President and General Counsel

.

rmation included herein and in other company reports, Securities and Exchange Commission filings, and presentations is forward-looking within the meaning of the Private Securities Litigation Reform , including, but not limited to, statements about the company's ability to operate its business while L1 proceedings, anticipated operating results, financial resources, ability to acquire land, ability to and properties, ability to deliver homes from backlog, and ability to secure materials and ors. Such forward-looking information involves important risks and uncertainties that could ' affect actual results and cause them to differ materially from expectations expressed herein and in

any reports, filings, statements and presentations. These risks and uncertainties include WCI's mpete as a going concern in real estate markets where we conduct business; WCI's ability to obtain val with respect to motions in the chapter 11 proceeding prosecuted by it from time to time; the CI to develop, prosecute, confirm and consummate one or more plans of reorganization with he chapter 11 cases; risks associated with third parties seeking and obtaining court approval to r shorten the exclusivity period for WCI to propose and confirm one or more plans of ion, for the appointment of a chapter 11 trustee or to convert the cases to chapter 7 cases; WCI's tain and maintain normal terms with vendors and service providers; WCI's ability to maintain at are critical to its operations; the potential adverse impact of the chapter 11 cases on WCI's results of operations; the ability of the WCI to fund and execute its business plan; the ability of WCI notivate and/or retain key executives and associates; WCI's ability to maintain or increase historical nd profit margins; WCI's ability to obtain necessary permits and approvals for the development of ie availability of capital to WCI and our ability to effect growth strategies successfully; availability of laterials and material increases in insurance, labor and material costs; increases in interest rates ility of mortgage financing; the ability of prospective residential buyers to obtain mortgage ie to tightening credit markets, appraisal problems or other factors; increases in construction and insurance and availability of insurance, the continuing negative buyer sentiment and erosion of onfidence; the negative impact of claims for contract rescission or increasing cancellation rates by rchasers; adverse legislation or regulations; adverse legal proceedings; the ability to retain changes in generally accepted accounting principles; natural disasters; adverse weather and changes in general economic, real estate and business conditions and other factors over which y has little or no control. If one or more of the assumptions underlying our forward-looking proves incorrect, then the company's actual results, performance or achievements could differ rom those expressed in, or implied by the forward-looking statements contained in this report. we caution you not to place undue reliance on our forward-looking statements. We undertake no o update or revise any forward-looking statements, whether as a result of new information, future therwise. This statement is provided as permitted by the Private Securities Litigation Reform Act of

Reorganization	I	Careers	Ι	<u>Investors</u>	Ι	Experience WCI	ì	Brokers	1	Title	ł	Mortgage	ł	Sitemap
----------------	---	---------	---	------------------	---	----------------	---	---------	---	-------	---	----------	---	---------

ommunities, Inc.

1-800-WCI

Ê

ed to providing unparalleled lifestyle experiences, WCI Communities is America's premier homebuilder of luxury homes and <u>Sky Homes®</u> compleivated <u>golf</u>, <u>fitness</u>, <u>spa</u>, <u>marina</u>, <u>beach</u>, <u>resort</u> and <u>club</u> amenities.

naster-planned communities, neighborhoods and highrise towers are located in superb destinations throughout Florida, Connecticut, New Jersey ( <u>rk</u>.


Copyright 1996-2009 © WCI Communities, Inc. All Rights Reserved.

Use of this website is subject to WCI Terms of Use. Privacy Policy. Contact us at 1-800-WCI-4005.

[ Privacy ]



> About WCI Communities



Il Address: *	
Name: *	
Name: *	

Contact: Sitrick And Company Sandra Stemberg Maya Pogoda 212-573-6100 310-788-2850

## COURT CLEARS WAY FOR WCI TO PROCEED TO CONFIRMATION OF ITS CHAPTER 11 PLAN

#### Deals Reached With Senior Lender Groups, Unsecured Creditors Committee and Drywall Claimants; Confirmation Set for August 26

**Bonita Springs, Florida - July 17, 2009 -** WCI Communities, Inc. announced today that the Delaware Bankruptcy Court presiding over its chapter 11 cases has approved the adequacy of its Disclosure Statement for its Plan of Reorganization. At the hearing, it was announced that agreements on terms of the Plan had been reached with the steering committees for the Company's senior secured term and revolving lenders, the WCI Official Committee of Unsecured Creditors and representatives of a group of homeowners claiming damages related to Chinese drywall.

The Court's approval paves the way for WCI to begin soliciting votes to accept its Plan of Reorganization, which already enjoys the support of the steering committees for the Company's secured term and revolving lenders and the Official Committee of Unsecured Creditors. It is anticipated that Plan materials and ballots will be mailed by July 24, 2009. The deadline for returning ballots is August 19, 2009, in accordance with instructions in the Bankruptcy Court's order and on the ballots. A hearing to confirm the Plan is scheduled for August 26, 2009.

"We are very pleased to have cleared this important hurdle in our path toward exiting from chapter 11," said David L. Fry, Interim President and Chief Executive Officer. "With the voting process about to begin, and with the firm support of our primary constituencies, WCI is squarely on track to emerge from chapter 11 as a deleveraged lifestyle community developer and land holding company with the flexibility to navigate its business during these unprecedented times and beyond."

Under the Plan, it is anticipated that the Company's senior secured lenders will receive new first lien debt in the aggregate amount of \$450 million, which includes a \$150 million payment-in-kind (PIK) component and an initial 95% equity stake in the reorganized company. The remaining 5% would be shared by the Company's unsecured creditors. The unsecured creditors' share would begin to increase when the new debt is

fully retired and would reach a maximum of 34% after the secured lenders have received payments that are equivalent to the amount currently owed to them (approximately \$740 million).

The Plan also includes an agreement reached with the lead attorneys representing the Chinese drywall claimants. The terms of the agreement as described in the Plan provide for the creation of a Chinese Drywall Trust and allow the Chinese drywall claimants to pursue causes of action related to the manufacture and installation of defective imported drywall in their homes.


"Today marks an important step in WCI's restructuring. The Company and its secured lenders and the Official Committee of Unsecured Creditors have been able to work together to maximize value under extremely challenging circumstances and to ensure that recoveries are allocated fairly among the Company's stakeholders," said Thomas Lauria of White & Case, WCI's counsel in the Chapter 11 case. "This consensual resolution is a tribute to all involved, given that we had no agreement with any of our creditors when we commenced these cases just 11 months ago, and in light of the unprecedented events that have transpired since."

#### About WCI Communities

WCI is a fully integrated homebuilding and real estate services company with more than 50 years experience in the design, construction and operation of leisure-oriented, amenity rich master-planned communities. It has operations in Florida, New York, New Jersey, Connecticut, Virginia and Maryland. The company directly employs approximately 1,170 people, as well as approximately 1,800 sales representatives as independent contractors.

#### Forward Looking Statement

Certain information included herein and in other company reports, Securities and Exchange Commission filings, statements and presentations is forward-looking within the meaning of the Private Securities Litigation Reform Act of 1995, including, but not limited to, statements about the company's ability to operate its business while in Chapter 11 proceedings, anticipated operating results, financial resources, ability to acquire land, ability to sell homes and properties, ability to deliver homes from backlog, and ability to secure materials and subcontractors. Such forwardlooking information involves important risks and uncertainties that could significantly affect actual results and cause them to differ materially from expectations expressed herein and in other company reports, filings, statements and presentations. These risks and uncertainties include WCI's ability to compete as a going concern in real estate markets where we conduct business; WCI's ability to obtain court approval with respect to motions in the chapter 11 proceeding prosecuted by it from time to time; the ability of WCI to develop, prosecute, confirm and consummate one or more plans of reorganization with respect to the chapter 11 cases; risks associated with third parties seeking and obtaining court approval to terminate or shorten the exclusivity period for WCI to propose and confirm one or more plans of reorganization, for the appointment of a chapter 11 trustee or to convert the cases to chapter 7 cases; WCI's ability to obtain and maintain principles; natural disasters; adverse weather conditions; and changes in general economic, real estate and business conditions and other factors over which the company has little or no control. If one or more of the assumptions underlying our forward-looking statements proves incorrect, then the company's actual results, performance or achievements could differ materially from those expressed in, or implied by the forwardlooking statements contained in this report. Therefore, we caution you not to place undue reliance on our forwardlooking statements. We undertake no obligation to update or revise any forward-looking statements, whether as a result of new information, future events or otherwise. This statement is provided as permitted by the Private Securities Litigation Reform Act of 1995. normal terms with vendors and service providers; WCI's ability to maintain contracts that are critical to its operations; the potential adverse impact of the chapter 11 cases on WCI's liquidity or results of operations; the ability of the WCI to fund and execute its business plan; the ability of WCI to attract, motivate and/or retain key executives and associates; WCI's ability to maintain or increase historical revenues and profit margins; WCI's ability to obtain necessary permits and approvals for the development of its lands; the availability of capital to WCI and our ability to effect growth strategies successfully; availability of labor and materials and material increases in insurance, labor and material costs; increases in interest rates and availability of mortgage financing; the ability of prospective residential buyers to obtain mortgage financing due to tightening credit markets, appraisal problems or other factors; increases in construction and homeowner insurance and availability of insurance, the continuing negative buyer sentiment and erosion of consumer confidence; the negative impact of daims for contract rescission including the impact of any Chinese drywall claims or lawsuits by contract purchasers; adverse legislation or regulations; adverse legal proceedings; the ability to retain employees; changes in generally accepted accounting



#### WCI Communities, Inc.

1-800-WCI-4005

Dedicated to providing unparalleled lifestyle experiences, WCI Communities is America's premier homebuilder of <u>luxury new homes</u> and <u>Sky Homes</u>® complemented by unrivaled <u>golf</u>, <u>fitness</u>, <u>spa</u>, <u>marina</u>, <u>beach</u>, <u>resort</u> and <u>club</u> amenities.

10 -

WCI's master-planned communities, neighborhoods and highrise towers are located in superb destinations throughout <u>Florida</u>, <u>Connecticut</u>, <u>New Jersey</u> and <u>New York</u>.



..

.

. .

. .


. .

• .•

Use of this website is subject to WCI Terms of Use. Privacy Policy. Contact us at 1-800-WCI-4005.



> About WCI Communities



Building and Design

Investors

Reorganization

Locations

Sales Centers

**Customer Service** 

**Resident Spotlight** 

II Address: \*

Designed to give guests a feel for the overall community, each WCI sales center offers a rich variety of displays and information on community amenities, home styles, location and more. A professionally trained and licensed staff of Community Representatives is on hand to answer any questions, give tours of the community and models, and guide guests through the homebuying process.

ENCORE ATLANTIC SHORES	FOUR CORNERS
Encore Atlantic Shores Sales Center 59 Encore Boulevard Eastport, NY 11941	Four Corners Sales Office 11 Mulberry Place East Fishkill, NY 12533
(631) 325-1616	(800) 92 <del>4-4</del> 005
Visit Community Website	Visit Community Website
Наммоск Вау	Lost Key Golf & Beach Club
Hammock Bay Sales & Information Center 950 Mainsail Dr. Naples, FL 34114	Lost Key Sales & Information Center 14000 Perdido Key Drive Perdido Key, FL 32507
(239) 389-7500	(850) 549-2120
(800) 525-8840 <u>Visit Community Website</u>	(866) 770-2989 Visit Community Website
Lost Key Marina & Yacht Club	OLD PALM GOLF CLUB
Lost Key Marina Sales & Information Center	Old Palm Golf Club
14000 Perdido Key Drive Perdido Key, FL 32507	11089 Old Palm Drive Palm Beach Gardens, FL 33418
(850) 549-2120	(561) 493-7220
(866) 770-2989 Visit Community Website	(866) 499-6742 <u>Visit Community Website</u>
One Singer Island	PARKLAND GOLF & COUNTRY CLUB
One Singer Island Sales Office	Parkland Golf & Country Club
3800 N. Ocean Drive	9425 Old Club Road
Singer Island, FL 33404	Parkland, FL 33076
(561) 340-1772 (800) 924-4005	(954) 757-7747 (866) 500-7422
<u>Visit Community Website</u>	Visit Community Website
Pelican Preserve	Rivington
Pelican Preserve	Rivington Sales and Information Center
10571 Veneto Drive Fort Myers, FL 33913	1 Reserve Road Danbury, CT 06817
(239) 985-1600	(203) 798-6000
(877) 881-5973 <u>Visit Community Website</u>	(800) 924-4005 <u>Visit Community Website</u>
	DI 090727CBB1886 Exh #5 Page 8 of 9

•.• • • • • •

F	Reorganization	l	Careers	1	Investors	i	Experience WCI	- I	Brokers	1	Prudential	T	Title	ł	Mortgage	I	Sitemap	
---	----------------	---	---------	---	-----------	---	----------------	-----	---------	---	------------	---	-------	---	----------	---	---------	--

#### WCI Communities, Inc.

.,

٠

• . •

1-800-WCI-4005

Dedicated to providing unparalleled lifestyle experiences, WCI Communities is America's premier homebuilder of <u>luxury new homes</u> and <u>Sky Homes®</u> complemented by unrivaled <u>golf</u>, <u>fitness</u>, <u>spa</u>, <u>marina</u>, <u>beach</u>, <u>resort</u> and <u>club</u> amenities.

WCI's master-planned communities, neighborhoods and highrise towers are located in superb destinations throughout <u>Horida</u>, <u>Connecticut</u>, <u>New Jersey</u> and <u>New York</u>.



Copyright 1996-2009 © WCI Communities, Inc. All Rights Reserved.

Use of this website is subject to WCI Terms of Use. Privacy Policy. Contact us at 1-800-WCI-4005.



11 0

----

#### Dunlap, Glenn

From: Sent: To: Subject:

Wednesday, July 29, 2009 5:07 PM Dunlap, Glenn OTHER INSPECTIONS ON OUR HOME

Glenn,

Below is a list of the dates that inspections have been conducted on our home regarding Chinese drywall.

#### April 30, 2009

Tim from WCI inspected our house for signs of copper corrosion. He would not provide us with a written report; he stated that he will forward his notes to Jennifer Polkow, and that we should contact Jennifer in a few days to discuss the next steps. Jason Peet was present during the inspection.

Tim inspected the AC condenser coils and found them to be blackened. He then inspected the wiring in light switches and/or electrical outlets in every room. In every case, the exposed copper wiring was black. He stated that he could smell the sulfur odor in the house. The copper pipes in the kitchen and bathrooms are showing some blackening. The edge of the medicine chest mirror in the master bathroom is blackened. The refrigerator coils are also blackened (photo taken).

#### June 8, 2009

An adjuster from HomeWise Insurance inspected our home. Jason Peet was present during the 45minute inspection. He took photos of corrosion evidence throughout the home (outlets, refrigerator coils, mirrors, etc).

#### June 9, 2009

Michael Bass, an engineer with HSA, was hired by HomeWise Insurance to inspect our home. Jason Peet was present during the inspection.

#### June 19, 2009

Engineer hired by the Krupnick law firm conducted inspection of home. Jason Peet was present during the inspection.

We have not yet received a report from either our law firm or our homeowners insurance. Once we receive these reports, I will email a copy to you.

Good luck on the rest of the testing. We look forward to seeing the results.

4:15:13 PM 8/10/2009

Licensee Details	
Licensee Information	
Name:	HINKLE DRYWALL INC (Primary Name)
	(DBA Name)
Main Address:	1460 BOOTH DRIVE
	VALRICO Florida 33594
County:	HILLSBOROUGH
License Mailing:	
LicenseLocation:	2404 BUCKHORN RUN DR VALRICO FL 33594
Country	
County:	HILLSBOROUGH
License Information	
License Type:	Construction Qualified Business
Rank:	Qualified Org
License Number:	QB0001962
Status:	Delinquent, Active
Licensure Date:	11/04/1996
Expires:	08/31/2007
Special Qualifications	Qualification Effective

# View Related License Information View License Complaint

..

~ • • • •

~ ·

-• • | Terms of Use | | Privacy Statement |

Home   About Us   myManta   FAQ   View Cart   A	Ay Profile	Login:	۵
	Monday, Aug. 10, 2009 <b>63,778,867</b> companies	Not Ads by Google Chinese Dry	•
COMPANIES: U.S., U.S. Public, Australia, Canada, U.	K., Worldwide		
RESOURCES: Video, Jobs, Reports, White Papers   J	IOIN US: Twitter, Facebook		
U.S. business name, category, location	Search BUSINESS CENTERS: S	imall Biz, Sales Expertis	se, HR, Travel, Career, Tech
U.S. » Lithia, FL » Building & Construction » Plas Drywall » Hinkle Drywall Llc	tering, Drywall, Acoustical, and insulatic	on Work »	Add Company to List Set Company Alert
Hinkle Drywall Llc			These Members Work Here
6122 Audubon Manor Bivd Lithia, FL 33547			Do you? SAY SO
Phone: (813) 643-8605			
Website: Information not found (?)			Related Links
Ads by Google			Other companies named Hinkle Drywall Llc
Find Drywall Contractors Read Reviews & G	et Quotes From Local Contractors.	Free Search!	Jobs in Lithia, FL Lithia, FL Videos
Mac Handyman Services Concrete Driveway	vs & Sidewalks Remodeling & Repa	ir Contractors.	
MasterColors, Inc. Affordable Quality Paintin	ng Painting-Textures-Drywall Repa	irs	Recent Visitors
The ads are not affiliated with Hinkle Drywa	all Lic		
<b>Business Categorles</b> Drywall in Lithia, FL Drywall/Insulating Contractor			
Hinkle Drywall Llc Business Infor Hinkle Drywall Llc is a private company cat records show it was established in 2007 and company has an annual revenue of \$310,00	egorized under Drywall and locate d incorporated in Florida. Current e	estimates show this	
Also Does Business As Information not found (?)	<u>Home Improvement</u> We Do It All. Drywall Repairs		
HQ, Branch or Single Location Single Location	Handyman Needs & Landsca www.ppmarkservices.com	aping.	
<b>Annual Sales</b> (Estimated) \$310,000	Remodeling Services Can Travel Anywhere. Call F Today!	or Free Quote	
Employees (Estimated)	www.HenrysHandyman.com		
5	<u>Bid On Construction</u> Get Unlimited Construction L 100% Risk Free- Bid Today! www.BidClerk.com		
		- <b>-</b>	

## N Y

~ . . .

....

.

.

.,

Ads by Google

SIC Code and Description 1742, Plastering, Drywall, Acoustical, and Insulation Work	Products, Services and Bra Information not found (?)	nds	Find Pre-Screened Drywall Pros. Install,
NAICS Code and Description 238310, Drywall and Insulation	State of Incorporation Florida		Fix, Remodel. Free Quotes! www.ServiceMagic.com
Contractors	<b>Years in Business</b> 2		<u>Mac Handyman</u> <u>Services</u> Concrete Driveways &
Company Contacts			Sidewalks Remodeling
Contact Name	Gender		& Repair Contractors. www.machandymanservices.net
Bruce T Minnick, Principal	_	Is this your company?	MasterColors, Inc.

Click on the <u>reports tab</u> at the top of the page to research company background, detailed company profile, credit and financial reports for Hinkle Drywall Llc.

Data above provided by D&B. © Dun and Bradstreet, Inc. All rights Reserved.

#### MasterColors, Inc. Affordable Quality Painting Painting-Textures-Drywall Repairs www.MasterColorsInc.com

Defective Drywall Lawsuit Drywall Smell Like Rotten Eggs? Can Cause Health Issues and More. defective-drywall-lawsuit.com

Companies by Location: Lithia, Florida

----

.,

Privacy Policy | Refund Policy | Contact Manta | Advertise | Featured Listings | Terms & Conditions | Site Map | Partners Copyright © 2009, Manta.com. All Rights Reserved.

~ ...

#### lssue: 38

#### 06/18/2009

## Doc No: 10960598A

06/17/2009 11:03:12

. . .

Name = Address City = S State =			
Zip = 33			
Email =			
Telepho			·
Name d			
Victim's			1
Victim's			

Incident Description = All evidence indicates that we have Chinese drywall throughout our home. There has been a persistent, pungent odor in the house since the day we moved in. The AC evaporator coils had to be replaced in August 2007; a recent inspection of the new AC coils indicates that they are corroded as well. Traces of copper and silver corrosion have been found in every room in our house.

Victim's age at time of incident = 52 Victim's sex = male Date of incident = 08/04/2006 Product involved = Chinese drywall Product brand name/manufacturer = Homebuilder is WCI Communities Manufacturer street address = WCI Headquarters is in Bonita Springs, FL Place where manufactured (City and State or Country) = Unknown Product model and serial number, manufacture date = Unknown Product damaged, repaired or modified = no If yes, before or after the incident = Description of damage, repair or modification = Date product purchased = August 2006 Product involved still available = yes Have you contacted the manufacturer = yes If not, do you plan to contact them = Name Release = Release name to the manufacturer and public

If you have any changes, additions, or comments you wish to make concerning your attached report, please make them in the space below.

I confirm that the information in the attached report (including any changes, additions, or comments I have made) is accurate to the best of my knowledge and belief.

	July 2/2009
Signature	Date

• • • • •

I request that you do not release my name.

You may release my name to the manufacturer but I request that you not release it to the general public.

You may release my name to the manufacturer and to the public.

.

.

1. Task Number 090804CBB1927		<b>_</b>	. Investigator's ID 9102		EPIDEMIOLOG
3. Office Code	4. Date of Accid YR MO DA		. Date Initiated YR MO DAY		INVESTIGATIC REPORT
810	2006 06 01		2009 08 04		
6. Synopeis of Accide	ent or Complaint	U	IPC		
noticed a "pungent a home each time they	crid odor" and thou return they would	ight it was sin begin to expe	nply new construction r	naterials. W ritated eyes	home. They immediate ithin hours of being in th and a scratchy throat. S
			l	MFR/PRVLBR	NOTIFIED /
			_	COMMENTS:	D:ATTACHED
				EXCISION	S/FOIA EXS. 3. (4. 250
					E-NOTIFY RE-MATIEV (b)(3):( Section
		·····			WE SI
7. Location (Home, S	chool, etc)				9. State
1 - HOME					FL
10A. First Product		10B. Trade	/Brand Name		10C. Model Numb
1876 - House Struct 10D. Manufacturer Na UNKNOWN	ame and Address	<u>}</u>			
10D. Manufacturer Na UNKNOWN	ame and Address	11B. Trade	/Brand Name		11C. Model Num
10D. Manufacturer Na UNKNOWN 11A. Second Product 0 11D. Manufacturer Na	ame and Address	11B. Trade NONE			
10D. Manufacturer Na UNKNOWN 11A. Second Product 0	ame and Address	11B. Trade NONE		 	11C. Model Numl
10D. Manufacturer Na UNKNOWN 11A. Second Product 0 11D. Manufacturer Na NONE	ame and Address	11B. Trade NONE	/Brand Name 14. Disposition 1 - Injured, not H	·	11C. Model Numl NONE 15. Injury Diagnosis 68 - Poisoning
10D. Manufacturer Na UNKNOWN 11A. Second Product 0 11D. Manufacturer Na NONE 12. Age of Victim 62	ame and Address	11B. Trade NONE	/Brand Name	·	11C. Model Numl NONE
10D. Manufacturer Na UNKNOWN 11A. Second Product 0 11D. Manufacturer Na NONE 12. Age of Victim 62 16. Body Part(s) Involved	ame and Address	dent 21. Case Sou	/Brand Name 14. Disposition 1 - Injured, not He 18. Type of invest 1 - On-Site	tigation	11C. Model Numl NONE 15. Injury Diagnosis 68 - Poisoning 19. Time Spent (Operational / Tra
<ul> <li>10D. Manufacturer Na UNKNOWN</li> <li>11A. Second Product 0</li> <li>11D. Manufacturer Na NONE</li> <li>12. Age of Victim 62</li> <li>16. Body Part(s) Involved 85 - ALL OF BODY</li> <li>20. Attachment(s) 9 - Multiple Attachment 23. Permission to Dia</li> </ul>	ame and Address	dent complainant 21. Case Sou 07 - Consum	14. Disposition 14. Disposition 1 - Injured, not He 18. Type of Inves 1 - On-Site Irce Ner Complaint as Only)	tigation 22. S	11C. Model Numl         NONE         15. Injury Diagnosis         68 - Poisoning         19. Time Spent (Operational / Tra 14 / 6         sample Collection Numl
10D. Manufacturer Ni UNKNOWN 11A. Second Product 0 11D. Manufacturer Ni NONE 12. Age of Victim 62 16. Body Part(s) Involved 85 - ALL OF BODY 20. Attachment(s) 9 - Multiple Attachme 23. Permission to Dia Ves	ame and Address	dent complainant 21. Case Sou 07 - Consum	14. Disposition 14. Disposition 1 - Injured, not He 18. Type of Inves 1 - On-Site Her Complaint	tigation 22. S	11C. Model Numl NONE 15. Injury Diagnosis 68 - Poisoning 19. Time Spent (Operational / Tra 14 / 6
<ul> <li>10D. Manufacturer Na UNKNOWN</li> <li>11A. Second Product 0</li> <li>11D. Manufacturer Na NONE</li> <li>12. Age of Victim 62</li> <li>16. Body Part(s) Involved 85 - ALL OF BODY</li> <li>20. Attachment(s) 9 - Multiple Attachment 23. Permission to Dia</li> </ul>	ame and Address	dent complainant 21. Case Sou 07 - Consum	14. Disposition 14. Disposition 1 - Injured, not He 18. Type of Inves 1 - On-Site Irce Ner Complaint as Only)	tigation 22. s	11C. Model Numl NONE 15. Injury Diagnosis 68 - Poisoning 19. Time Spent (Operational / Tra 14 / 6 isample Collection Numl /es for Manuf. Only al Office Director

CPSC FORM 182 (12/96) Approved for Use Thru 1/31/2010 OMB No. 3041-0029

1 **4** 7

•

This investigation was initiated by a complaint received by the U.S. Consumer Product Safety Commission.

The information contained in this investigation was supplied by the following sources:

1. An onsite interview with the male owner of the home on 8-07-2009.

Family Members:

Husband – 62 year old male Wife – 59 year old female

This incident involves health issues and copper and metal corrosion at the periodic home of the victims over an extended period of time as will be detailed later in this report which the owners believe were caused by contaminated Chinese drywall used in the construction of their home.

An engineering firm was hired by the CPSC to collect and conduct air and drywall sampling at the home and the results will be provided to the consumer once completed.

The home was 2 bedrooms, 2 bathrooms new construction, 1700 square foot townhome in North Venice, FL. The home is a one story cinder block construction with stucco exterior walls and metal framing studs. The owner contacted the CPSC on 5-26-2009. The Air Conditioner had not failed or leaked Freon so the incident date is considered the move in date as respiratory like allergy symptoms started at that time.



Photograph of the front of the home.

The family moved into the home in June of 2006 and the wife noticed that the builder had placed the wrong tile in the bathroom walls of the master bath and it was replaced one year after move in. There were no other renovations or alterations to the home.

The home was electric with natural gas to the stove, water heater, dryer and furnace. The home had tile in the common areas and carpeting in the bedrooms.

The family immediately upon move in noticed a "pungent, acrid odor." The family believed it was just new construction smell and thought it would eventually dissipate. The family lives in the Washington D.C. area and traveled to the Florida home every two to four months and stayed approximately one week on each visit. Both the owners were in excellent health but both began experiencing upper respiratory symptoms including runny nose, irritated eyes and a scratchy throat. The husband had one additional symptom of wheezy respiratory breathing. The symptoms would start after being in the home for a few hours and would alleviate after being away from the home for a few hours. No medical records were provided.

The family would turn the air conditioner up to 80 degrees and turn the humidity controller to 50% when they leave. He believed that because the A/C unit was in a higher position and no one lived in the home most of the time, it had probably not run as much as a normally occupied home. The home A/C was serviced every six months and he did not know if the unit had leaked any Freon and had to be recharged, however the A/C technician sprayed the copper coils with silver paint presumably to slow the corrosion. The home owner was not able to locate any of the service tickets.

In May of 2009 the family began hearing reports in the media regarding homes in Florida having Chinese Drywall and subsequent corrosion. He began examining all the affects in his home and noticed serious darkening/corrosion of copper water supply lines and many chrome water fixtures had pitting and corrosion.

The builder is listed at the bottom of this report and according to the consumer the firm is currently in bankruptcy. He had no information regarding the drywall contractor, installer or supplier. The builder conducted an inspection of the home for Chinese drywall on May 13, 2009. The employee conducting the inspection is listed at the end of this report. He opened 5-10 electrical outlets and examined the A/C coils, copper water supply lines and other evidence of corrosion. He stated that the home "showed evidence of tainted drywall." The firm refused to produce a written report on their examination.



Photograph of blackening of the ground, hot and neutral wires to an electrical receptacle.


The homeowner indicated he had purchased two small LCD televisions and one of them had died in 2007 on an unspecified date. They had also purchased an electric hand mixer that had never been used and failed to operate. The remote control for the family room had batteries which were leaking a white material. There was some blackening/corrosion of the A/C evaporator coils. Silver items in the home had tarnished. Copper water supply lines in the home had darkened or turned black. Chrome bathroom fixtures showed pitting and corrosion. Copper lines in the back of the refrigerator showed blackening.



Photograph of pitting and corrosion on a brass trivet.



Corrosion and pitting on a chrome water supply line.



Blackening on a copper water supply line.

The home owner did not believe he had any problems with flickering lights, sizzling or buzzing of electrical switches. However due to the blackening of the ground wires, hot and neutral wires he felt that there may be an unseen future electrical hazard in the home. No other appliances had failed.

The copper water supply lines in the garage and the copper electrical wiring in the breaker box did not show blackening. The home owner indicated his desire to keep his name confidential when releasing copies of this report.

#### **Product Information:**

Product: Possible Chinese Drywall Manufacturer: Unknown

#### Builder:

WCI Communities, Inc. 24301 Walden Center Drive Bonita Springs, FL 34134 United States Of America Employees: 1,800 Investor Relations Phone: (239) 498-8269 •

(239) 498-8146 (239) 498-8200 www.wcicommunities.com

Management: David L. Fry Interim President and CEO Jonathan M. Pertchik Chief Restructuring Officer Russell Devendorf Senior Vice President and Chief Financial Officer Paul D. Appolonia Senior Vice President of Human Resources Vivien N. Hastings Senior Vice President and General Counsel

#### Drywall Subcontractor: Unknown

Drywall Supplier: Unknown

## **Attachments:**

on to conduct sampling tests
of name form
ease and walk through form
phs of the home (22)

## Contacts:

8-07-2009

The consumer indicated he had contacted the following agencies about his home having Chinese Drywall. He had received no reports about his contact to them.

Florida Department of Health Florida Attorney General Sarasota County Health Department

#### **RELEASE & WAIVER OF LIABILITY FORM**

[To Be Signed by All Residents 18 Years or Age or Older]

I, Explored a set of an exploratory of the set of an exploratory of the set of an exploratory of the set of an exploratory study. This work is being undertaken as a part of an exploratory

study to assess potential associations between constituents that may be present in indoor air and constituents that may be detected in drywall imported from China.

I understand that CPSC will be testing my residence for a variety of gases and/or other substances. Additionally, I understand that while CPSC will inform me of the chemical analysis results for my own residence, CPSC will not be providing further individualized analysis or recommendations concerning possible actions regarding health, safety and/or remediation which occupants could take in light of the information provided. However, CPSC will inform me if the chemical analysis results for my residence indicate the presence of gases or other substances above established risk levels.

I understand that this testing will take one full day of active testing and up to one to two week(s) of having passive sampling equipment in my home. I understand that after one to two week(s) of passive sampling, CPSC will contact me to arrange a time for CPSC to retrieve the passive sampling equipment. I represent that neither I nor members of my household will touch the passive sampling equipment while it is present in my home. CPSC requests that homeowners refrain from using cleaning supplies containing bleach, ammonia, and acetone. There may be other limited household activities which CPSC will request the homeowner to minimize, and CPSC will explain those activities in more detail when the testing begins.

I understand that CPSC intends to take small nail-size samples (less than 1/8 inch) from multiple inconspicuous locations throughout the home, such as behind switch plates and near baseboards. Additionally, CPSC may take drywall sample(s) of an approximate size of 6 inches by 6 inches and will cover the resulting hole(s) with a blank access panel.

I understand that neither 1 nor other members of my household, including minor children, will be compensated for our participation in this study nor will we receive any per diem allowance or other funds.

I understand that this study involves multiple residences and the final study and analysis will not be completed for a period of time, likely in the fall of 2009. I also understand that CPSC will likely not release information to the general public until the completion of the entire study. I further understand that this study may be widely disseminated to the public and that my own residence will not be identifiable by personally identifiable information such as address, name, etc. within the larger study.

I assume the risk of any and all injury or damage to my person or property that may arise, whether directly or indirectly, as a result of my participation in this study.

I hereby release and hold harmless CPSC, its officers, employees, consultants, representatives, and other designees and the United States Government from any liability for illness, injury, property loss or damage arising from participation in this study.

This agreement is made upon the express condition that for the period of time which CPSC or any of its equipment is in my residence for the purpose of conducting this testing, I shall be free from all liabilities and

claims for damages and/or suits for or by reason of any illness, injury, or death to any CPSC officers, employees, consultants, representatives, and other designees of the CPSC or the United States Government, and that I shall be free from all liabilities and claims for damages and/or suits resulting to damage of CPSC property. CPSC hereby agrees to release and hold me harmless from any liability for illness, injury, death, and/or property performance in connection with the testing as outlined above, however occurring.

<u>20</u>09 nature

#### [REMAINDER OF THIS PAGE LEFT INTENTIONALLY BLANK]

Page 2 of 2

#### IDI 090804CBB1927 Exh #2 Page 2 of 2 07/18/2009 1:19PM (GMT-04:00)

# U.S. Consumer Product Safety Commission

# **AUTHORIZATION FOR RELEASE OF NAME**

Thank you for assisting us in collecting information on a potential product safety problem. The Consumer Product Safety Commission depends on concerned people to share product safety information with us. We maintain a record of this information, and use it to assist us in identifying and resolving product safety concerns.

We routinely forward this information to manufacturers and private labelers to inform them of the involvement of their product in an accident situation. We also give the information to others requesting information about specific products. Manufacturers need the individual's name so that they can obtain additional information on the product or accident situation.

Would you please indicate on the bottom of this page whether you will allow us to disclose your name? If you request that your name remain confidential, we will of course, honor that request. After you have indicated your preference, please sign your name and date the document on the lines provided.

I request that you do not release my name. My identity is to remain confidential.

You may release my name to the manufacturer but I request that you do not release it to the general public.

You may release my name to the manufacturer and to the public.

Aug 7, 2009 (Date)

CPSC Form 322

TO BE SIGNED UPON COMPLETION OF IN-HOME AIR-QUALITY MONITORING AND TESTING STUDY

#### FINAL RELEASE & WAIVER OF LIABILITY FORM

[To Be Signed by All Residents 18 Years or Age or Older]

I, \_\_\_\_\_\_\_, do hereby acknowledge that with my permission the U.S. Consumer Product Safety Commission and any of its designated representatives, consultants, or other designees ("CPSC") utilized my residence located at \_\_\_\_\_\_\_ for a preliminary pilot indoor air-quality monitoring and testing study on  $\frac{5}{0}$ , 2009.

On today's date, I have completed a walk-through inspection of my residence with

<u>Glenn Dunlap</u> a CPSC employee. I further acknowledge that except for any items listed and described below, no items are missing, damaged, or destroyed in my residence.

Notation of missing, damaged or destroyed items in residence (if applicable):

I acknowledge that CPSC offered reimbursement for the \_\_\_\_\_

but I have declined CPSC's offer. I acknowledge that I have not requested that the \_\_\_\_\_

be repaired or replaced by CPSC.

8/07/2009


Signature of Resident

Date

[REMAINDER OF THIS PAGE LEFT INTENTIONALLY BLANK]































.











IDI 090804CBB1927 Exh #5 Page 18 of 22



:




## Doc No: 10950977A

Issue: 35

05/28/2009

05/26/2009 21:02:49



Victim's City = N. Venice Victim's State = Florida Victim's Zip = 34275

Incident Description = On May 13, 2009, WCI Communities Construction Manager Todd Rudkin Inspected our second home at **Galaxy Manager Construction Manager** Todd Rudkin Inspected our second home at **Galaxy Manager Construction Manager**, for the presence of installed Imported (Chinese) drywall. While in the home, we have experienced irritated nasal passages and eyes; and noticed the presence of sulfur-like odors, premature corrosion of chrome plumbing fixtures, and had premature failure of electronic small appliances. Mr. Rudkin found corroded ground wires in 5-10 electrical outlets, corroded copper plumbing connections, corroded chrome plumbing fixtures, and corroded A/C coils. He said, "...we have all indications of the presence of Chinese drywall."

Victim's age at time of incident = 62 Victim's sex = male Date of incident = May 13, 2009 Product involved = Drywall Product brand name/manufacturer = Unknown Manufacturer street address = Unknown Place where manufactured (City and State or Country) = Presumed to be China (did not manufacturer's markings) Product model and serial number, manufacture date = Unknown Product damaged, repaired or modified = no If ves, before or after the Incident = Description of damage, repair or modification = N/A Date product purchased = June 2006 from WCI Communities Product involved still available = ves Have you contacted the manufacturer = no If not, do you plan to contact them = no Name Release = Release name to manufacturer only

ł.

ł.

1. Task Number			2. Investigator's ID			
090804CBB1930			9052		EPIDEMIOLOGIC	
3. Office Code	4. Date of Accid YR MO DA	AY	5. Date Initiated YR MO DAY		INVESTIGATION REPORT	
810	2009 06 15	5	2009 08 06			
6. Synopsis of Accid	-		UPC			
have corroded and t	urned black. Also, a	all of their g	s built in 2006 have foun round wires in the outlet ise. They suspect it was	s have turne	ils on their air conditioning unit d black. The 79-year-old male with Chinese drywall.	
			MFR/P	RVLBR NOTI		
				ent <b>s:y</b> es Rruled;		
			<u>.√</u> EXC	SISIONS/FOIA	EXS. 3.6:250	
			<u></u> D0	NOT RE-NOT	EXS. 3, 6, 25 WE WE	
7. Location (Home, School, etc)			8. City	9. State		
1 - HOME			SUN CITY CENTER		FL	
10A. First Product		10B. Tra	de/Brand Name		10C. Model Number	
1876 - House Struct	ures, Repair Or	UNKNO			UNKNOWN	
		<b>.</b>			11C. Model Number	
				de/Brand Name		
4061 - Electric Outle						
NONE	anio anu Ausioso					
12. Age of Victim 79	<b>13. Sex</b> 1 - Male		<b>14. Disposition</b> 1 - Injured, not Hosp.		15. Injury Diagnosis 71 - Other	
16. Body Part(s)	17. Respond	lent	18. Type of Inves	19. Time Spent		
Involved 85 - ALL OF BODY	1 - Victim/Co	(Operational Coperation (Operation)		(Operational / Travel) 15 / 3		
		21. Case So 07 - Consu	Source 2 umer Complaint		2. Sample Collection Number	
23. Permission to Dis	sclose Name (Non	NEISS Ca	ses Only)			
	No		◯ Verbal	Yes for Manuf. Only		
24. Review Date 08/20/2009	25. Reviewed B 9001		<b>26. Regional Office Director</b> Dennis R. Blasius			
<b>27. Distribution</b> Rose, Blake; Blasius, Dennis; Woodard, Dean; Trotta, Andrew; Matheson Joanna; Khanna, Rohit				<b>28. Source Document Number</b> 10960493A		

CPSC FORM 182 (12/96) Approved for Use Thru 1/31/2010 OMB No. 3041-0029

Information contained within this report was obtained from an on-site visit with the homeowner at his home. During this visit, engineers from EH & E were conducting air quality tests.

The homeowners consist of a 69-year-old female and a 79-year-old male. They have a schnauzer/poodle dog that is 5-years-old. No one else has lived with them in the home. The home was built in 2006 by WCI Builders of Bonita Springs, FL. The homeowners moved into the home in September 2006. They lived in this house for eight to ten months a year during the winter time and then live in a home in Indiana for two to four months during the summer time. They left this home in April 2009 and have lived in their home in Indiana since then.

The home is a one story family home. It has approximately 2,100 square feet of living space. There is a two-car attached garage and a screened in patio on the back of the home. The house has three bedrooms, two full bathrooms, a large kitchen area, a dining room, a family room and a laundry room. The house was built on a concrete slab and is constructed of concrete block and stucco. The homeowner believed the house has metal and wood studs. The house has tile throughout the house. Several of the rooms have area rugs. All of the appliances were new when the house was built in 2006.

This home is equipped with natural gas for the oven, water heater, clothes dryer, furnace and barbecue grill. All other appliances are electric. The homeowner stated that the builder painted all the walls before they moved into the home in September 2006. They have not made any other major changes to this home since they moved into the home in September 2006.

The homeowner stated that none of the drywall in this house has been replaced. He did not know the name of the drywall contractor or the drywall installer. The home was built by WCI Builders of Bonita Springs, FL.

The male homeowner has had some breathing problems since he has lived in this house. Also, his voice has changed because of the breathing problems. He has had an occasional nose bleed and has suffered from watery eyes while living in this house. Also, he has had trouble sleeping at night. When he stays in Indiana, he has noticed that his problems subside after being out of this house for a short time. When he comes back to this house, the problems reappear. He has not sought any type of medical treatment for these symptoms. The female homeowner has not had any medical issues as a result of living in this house.

The homeowner related that his dog has not shown any medical problems because of the Chinese drywall.

The homeowners detected a strange odor when they first moved into the house. They attributed it to a "new house smell" or "new paint smell". The male homeowner related

that he has continued to smell this odor every day. When the house has been closed up, the smell is stronger. He described the smell as a distinct odor that is like walking into a bar full of smokers and drinkers.

This home has one air conditioning unit. The homeowner stated that he has not had to replace the coils on the air conditioning unit and has not had to have it recharged. It has always worked fine without any problems. The coils in the air conditioning unit were examined. All of the coils have turned black and show corrosion.

The homeowner stated he has had problems with his big screen plasma television. He purchased a new Samsung plasma television in 2006. In February 2009, the television completely stopped working. A television repairman looked at it and could not determine what was wrong with it. He told the homeowner that it would be very costly to repair, so the homeowner purchased a new LCD television. He has not had any problems with the new LCD television since he purchased it in February 2009.

The homeowner checked the ground wires in some of his outlets in this house. He stated that the ground wires have turned black. Several of the outlets were examined during this visit and all of them showed signs of corrosion on the ground wires.

The homeowners first became aware of Chinese drywall in the latter part of 2008. Several of his neighbors have had problems with their air conditioning coils and have had to have them replaced two and three times. The neighbors also told him about problems they were having with the televisions that stopped working and breathing problems they were having since moving into their new homes. The neighbors told him about the problems with the Chinese drywall and then he learned more about it from the news in the newspaper and on television. His neighbors have gotten together and have shared information with each other. The homeowner and his neighbors have registered with an attorney to represent them. The attorney has visited the homeowner's house and did a visual inspection of the house.

The homeowner contacted the builder, WCI who sent out an employee to look at his house. The employee saw the black coils in the air conditioner and the black ground wires in the outlets. However, he was very non-committal. The homeowner has tried to get someone from WCI to help him but the company is just now emerging from a Chapter 11 Bankruptcy, so they are not willing to talk to him.

The homeowner has contacted his homeowner's insurance company about the problem with the Chinese drywall. The insurance company rejected his claim.

The homeowner was contacted by a company that has declared they can decontaminate the Chinese drywall in order to make it safe to be in his home. He had the owner of the company come to his house and give a presentation to him and some of his neighbors. The owner of the company stated that they can inject their product into the drywall that

will stop 100% of the off gassing. Their product will chemically alter the gases being emitted by the Chinese drywall and would form inert, safe compounds. The homeowner provided a copy of the owner's explanation of how the process would work (See Attachment 3).

The homeowner stated that he wants to be pro-active and is very interested in finding a solution to the Chinese drywall problem. He suggested that he would be willing to have the company that claims they can decontaminate the Chinese drywall treat his home. After they have treated his home, CPSC could bring back their engineering test team to test his house again to determine if this is a viable solution to the Chinese drywall problem. He would rather have the drywall treated then to have to move out while the drywall in his house is taken out and then replaced. He believes this would save homeowners a lot of time and money if this process was determined to be safe and effective by a third party, such as the CPSC.

The homeowners' short term plan for now is to try to find a solution to the Chinese drywall as quickly as possible. The homeowner stated that he purchased this house as his last house and does not want to sell it or move out. He plans to have this house as his primary residence and live in Indiana during the hot summer months.

During this investigation, the homeowner's neighbor came to the homeowner's home. The neighbor related that he had to replace the coils in his new air conditioner and the ground wires within his outlets have all turned black. He believes his home was also built with Chinese drywall. The neighbor and the homeowner had the same builder and both of their homes were built in 2006. The neighbor has purchased two carbon filtered air cleaners for \$3,000 each. He and his wife are in their 70's and are trying to alleviate or minimize the chemicals that are being emitted from the Chinese drywall because they cannot move out of their home. They are very much concerned about the physical effects the Chinese drywall may be having on their health. A photograph of the carbon air filter was taken and is attached as Attachment 1, Photo 6.

#### **PRODUCT IDENTIFICATION:**

The drywall in the homeowner's house is suspected Chinese drywall. The manufacturer could not be determined.


#### **ATTACHMENTS:**

Attachment 1 – Photos 1 – 6 Attachment 2 – Commitment Form Attachment 3 – Copy of Biohazard Abatement Solutions, Inc information sheet provided by the homeowner Attachment 4 – Information concerning the neighbor's carbon air filter system Attachment 5 – Final Release Form

Attachment 6 – Authorization for Release of Name Attachment 7 – Identification of Contacts


## **ATTACHMENT 1**

### **PHOTO 1 – View of homeowner's home**




## **090804CBB1930 ATTACHMENT 1**


## PHOTO 2 – View of air conditioning unit in garage



## 090804CBB1930 ATTACHMENT 1


# PHOTO 3 – Closer view of the coils in the air conditioning unit showing corrosion and have turned black





## PHOTO 4 – View of an outlet in the bedroom where the ground wire turned black


## **ATTACHMENT 1**



## PHOTO 5 – Another view of the outlet where the ground wire has turned black

## **090804CBB1930 ATTACHMENT 1**

PHOTO 6 – View of carbon air filter that the homeowner's neighbor has purchased to help alleviate the odor in his home that also is suspected of having Chinese drywall



[To Be Signed by All Residents 18 Years or Age or Older]

Commission and any of its designated representatives, consultants, or other designces ("CPSC") to utilize my

residence located at <u>set of an exploratory</u> for an indoor air-quality monitoring and testing study. This work is being undertaken as a part of an exploratory study to assess potential associations between constituents that may be present in indoor air and constituents that may be detected in drywall imported from China.

I understand that CPSC will be testing my residence for a variety of gases and/or other substances. Additionally, I understand that while CPSC will inform me of the chemical analysis results for my own residence, CPSC will not be providing further individualized analysis or recommendations concerning possible actions regarding bealth, safety and/or remediation which occupants could take in light of the information provided. However, CPSC will inform me if the chemical analysis results for my residence indicate the presence of gases or other substances above established risk levels.

I understand that this testing will take one full day of active testing and up to one to two week(s) of having passive sampling equipment in my home. I understand that after one to two week(s) of passive sampling, CPSC will contact me to arrange a time for CPSC to retrieve the passive sampling equipment. I represent that neither I nor members of my household will touch the passive sampling equipment while it is present in my home. CPSC requests that homeowners refrain from using cleaning supplies containing bleach, ammonia, and acetons. There may be other limited household activities which CPSC will request the homeowner to minimize, and CPSC will explain those activities in more detail when the testing begins.

I understand that CPSC intends to take small nail-size samples (less than 1/8 inch) from multiple inconspicuous locations throughout the home, such as behind switch plates and near baseboards. Additionally, CPSC may take drywall sample(s) of an approximate size of 6 inches by 6 inches and will cover the resulting hole(s) with a blank access panel.

[ understand that neither I nor other members of my household, including minor children, will be compensated for our participation in this study nor will we receive any per diem allowance or other funds.

I understand that this study involves multiple residences and the final study and analysis will not be completed for a period of time, likely in the fall of 2009. I also understand that CPSC will likely not release information to the general public until the completion of the entire study. I further understand that this study may be widely disseminated to the public and that my own residence will not be identifiable by personally identifiable information such as address, name, etc. within the larger study.

I assume the risk of any and all injury or damage to my person or property that may arise, whether directly or indirectly, as a result of my participation in this study.

I hereby release and hold harmless CPSC, its officers, employees, consultants, representatives, and other designces and the United States Government from any liability for illness, injury, property loss or damage arising from participation in this study.

This agreement is made upon the express condition that for the period of time which CPSC or any of its equipment is in my residence for the purpose of conducting this testing, I shall be free from all liabilities and

claims for damages and/or suits for or by reason of any illness, injury, or death to any CPSC officers, employees, consultants, representatives, and other designees of the CPSC or the United States Government, and that I shall be free from all liabilities and claims for damages and/or suits resulting to damage of CPSC property. CPSC hereby agrees to release and hold me harmless from any hability for illness, injury, death, and/or mean the state of the testing as outlined above, however occurring.

 Abidity constraint and allowed allowe 

Signature

07. 06. 2009

Date

07/09/2009 9:24AM (GMT-04:00)

## **Biohazard Abatement Solutions, Inc.**

090804CBB1930 ATTACHMENT 3 Page 1 of 5

## Decontamination of Chinese Drywall

#### Abstract

It has been reported that drywall imported into the US between 2004 and 2006 from certain areas in China, can release sulfur-containing odorous components. These compounds can corrode air conditioning coils and other copper-bearing materials, causing them to be replaced repeatedly. Chemical analysis suggests that the problem is possibly related to presence of iron disulfide (FeS2 pyrite) and strontium sulfide (SrS). These sulfides tend to decompose in the presence of humidity, releasing sulfur-containing gases. Hydrogen sulfide (H2S), carbonyl sulfide, sulfur dioxide (SO2), carbon disulfide (CS2), and mercaptants are the most common sulfur-containing gases suspected as the cause of the odor and the corrosion propensity.

Our product RemedialConG® was created to safely decontaminate equipment and personnel from both chemical and biological warfare agents. After treating a house that utilized Chinese Drywall with RemedialConG®, the levels of VOCs, Hydrogen Sulfide, Sulfur Dioxide and other compounds were below detection limits.

#### Background

Drywall is usually made of gypsum (hydrated calcium sulfate). Therefore, sulfur is one of the main components present in the sample. All drywall has sulfur in its elemental composition; therefore the odor is not explained by an analysis of the total sulfur content. The extent of the indoor air quality issues related to this is still unclear. The EPA is currently investigating the severity of the problem. However, it is well known that exposure to sulfur-containing gases can create irritation and breathing disorders.

#### **Hypothesis**

Applying RemedialConG® via a variety of application techniques would provide coverage of the Chinese Drywall. Once the formulation is absorbed into the drywall, a chemical reaction will occur, resulting in an immediate increase in VOCs, which will then fall back to acceptable levels after a period of 24 - 48 hrs, Also, the application of the RemedialConG® would increase the rate of off-gasing by the drywall. The surfactants in the formulation would allow for filling in capillary spaces that were once occupied. Our lab and field test results show that we are able stop 100 % of the off-gassing. Our formulation will chemically alter the products currently being given off by the Chinese Drywall and would form inert, safe compounds. Applying RemedialConG® will render the Chinese Drywall safe for occupants and also cease the conosion of copper and other metal components. However, RemedialConG® may not stop corrosion that occurs naturally with time or with moisture intrusion. A current school of thought is that the chemicals from the Chinese drywall are affecting other building materials, such as the studs that the drywall is in direct contact with. This is not a problem with our system as we treat the entire area including the studs and insulation

## 090804CBB1930 ATTACHMENT 3 Page 2 of 5

#### **BAS1** Overview

Biohazard Abatement Solutions, Inc. a Florida based company, continually strives to develop cost effective, practical solutions to contamination problems incorporating the newest, cutting edge technologies available for commercial use.

We provide comprehensive, environmentally-safe, non-toxic, decontamination of molds, mold spores and mold related mycotoxins, bacteria, viruses and many chemical contaminants including Formaldehyde and Sulfur compounds. Our decontamination processes incorporate patented revolutionary products, unique application techniques and monitoring and testing technologies unsurpassed in the industry.

Our decontamination processes do not require tenting or time-consuming labor and, in many instances, we can decontaminate sections of a facility without disruption of services in other sections.

#### Product Information - RemedialConG®

The original technology, was developed for the U.S. Department of Energy and National Security Administration for their Chemical and Biological National Security Program (CBNSP). The formulation's unique characteristics provide tactical advantages in the decontamination process that previously required the dedication of large numbers of resources, personnel and time.

The decontamination formulation is the first known to be effective on a broad spectrum of biological agents, bacteria, viruses, bacterial spores and chemical agents. The decontamination formulation is non-toxic and non-corrosive. The product is slightly basic with enhanced physical stability for the rapid mitigation and decontamination of chemicals and biological agents based on a surfactant system that solubilizes sparingly soluble agents and increases the reaction rate with nucleophilic reagents.

The catalytic reaction of the formulation increases the speed of the oxidative reactions that could otherwise take years to complete. The reaction requires a slightly basic pH and results in the formation of a highly reactive species three times more oxidative than chlorine without the corrosive effects. The formulation exhibits none of the problems of gaseous release from chlorine (chlorinated organics) or chemical residues associated with other chemical oxidants.

The formulation is miscible with water and is safe to apply on most fabrics, clothing, carpeting, walls, furniture and a variety of soft goods that would be permanently damaged by chlorine bleach.

There is no residual effect on the environment due to the decomposition of the primary oxidizers within the formulation into oxygen and water vapor.

The RemedialConG® formulation was specifically developed to cubance the base product's ability to proteinate drywall sheeting. The foaming characteristics enable the product to more effectively and efficiently be absorbed into the drywall by extending the time it is in contact with the surface area to be treated. In addition, specially designed and engineered equipment allows for total verifiable coverage of all materials to be decontaminated.



David Fago 813-967-3685 Fax: 813-926-5999 dfagoil@aol.com

## RAE Systems handheld VOC monitor - Model No. ppbRAE3000

ł

FLIR Infrared Camera - Model B-2

### 090804CBB1930 ATTACHMENT 3 Page 3 of 5

Delmhorst Moisture Meter - Model BD-10

## Sampling Results - VOC ppb

That	Living Naom	Living Room Behind Walls	Office	Office Behind Walls	Frigat Bestroaes	Front Bedroom Bahins Walls	Såæter Bedroom	Mastor Bedroom Behind Walls
11:30	0	4217	0	3250	400	3654	0	N/A
12:30	D	3139	٥	2948	215	2874	0	N/A
1:00	0	2960	0	2687	0	2489	0	N/A
1:30	0	1592	0	1763	0	1536	0	N/A
2:00	0	612	0	752	0	9 <b>87</b>	0	N/A

## **Conclusions**

The RemedialConG® was applied to the house where Chinese Drywall was present and resulted in the climination of hydrogen sulfide odors. In addition, applying RemedialConG® was effective in reducing and eliminating all detectable (TDL 1ppb) VOCs including Sulfur Dioxide and Hydrogen Sulfide from the Chinese Drywall.

## Subsequent Testing

Air monitoring equipment (Procheck+ 5000Ex) was utilized to determine the concentrations of VOCs. The PhoCheck+5000Ex was pre-calibrated at Ion Science by Bob Wheelhouse to measure ppb. The results in the sample home were after a 2 week period, during which the home HVAC system was turned off for a period of 4 days during a hot Florida summer with lots of rain. Even with this extreme measure to test the product, no VOC's were found. Lab results as well as results from other studies suggest the following findings are accurate. We have stopped all off gassing of the Chinese drywall as well as any other contaminated building materials in the wall system as well.

## Testing Equipment

Phocheck+5000Ex

### Sampling Results

Sampling Location	VOC	HS2	SO2	Other	Other	
Living Room	0	0	0	0		
Bedroom 1	0	0	0	0	••••• ••• ••• ••• ••• •••	090804CBB1930 ATTACHMENT 3 Page 4 of 5
Kitchen	0	0	0	0	9,4i	
A/C Closet	Ŭ.	0	0	0		
Bedroom 2	0	0	0	0	6 6 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
zem on in 1944 mm. Alice Vir Anderkagen (de Lingman Leijkeur infres i synt						
j Angel and a state of the strainer statement of the strainer statement of the strainer statement of the strainer	· · · · · · · · · · · · · · · · · · ·	•	n en ser a la m	•		,
the many strategy of the second s			the second second second	• 100 404 proc		

#### Conclusions

The RemedialConG® was applied to the house where Chinese Drywall was present and resulted in the elimination of hydrogen sulfide odors. In addition, applying RemedialConG® was effective in reducing and eliminating all detectable (TDL 1ppb) VOCs including Sulfur Dioxide and Hydrogen Sulfide from the Chinese Drywall.

Due to the use of well trained people and well designed chemical reactions and processes versus large amounts of man hours, we are able to offer safe, reliable, economical, and reproducible results in the fix for Chinese drywall. We are able to do this in about 1/8 of the time, and for about 1/3 of the cost of replacing the Chinese drywall.

### **Testing Methods**

BASI, and their affiliates have conducted numerous tests in the lab and in the field with the product to determine its effectiveness in eliminating the off gassing produced by the Chinese drywall.

Location - Single Family residence (unoccupied), Sun City, FL

090804CBB1930 ATTACHMENT 3 Page 5 of 5

Field test Dates : July  $14 - 17^{\circ}_{\rho}$  2009

Environmental Conditions – Conditioned Air (77 F)

Builder installed an exhaust system independent of HVAC system in a previous attempt to resolve off-gassing issues related to Chinese Drywall. The exhaust system was not effective in preventing off-gassing and corrosion. This is considered an anomaly as standard homes do not have an independent exhaust system.

In this field test, pre-decontamination air sampling was not conducted due to time constraints and lack of availability of the air monitoring equipment. However, physical evidence of corrosion on copper wiring was visibly evident as well as detection of hydrogen sulfide odor using olfactory sense. Upon entering the house, the team experienced symptoms of low concentration exposure to hydrogen sulfide including headaches, upper respiratory irritation and irritation of the eyes. The builder confirmed that Chinese Drywall was installed and was also confirmed by a visual inspection of the drywall that proved the drywall was manufactured in China (CK label).

None of the mill work, cabinets, appliances or baseboards were removed from the house or disturbed from their installed locations. The house was prepared via our carefully designed system. After treating the home with RemedialConG®, the concentration of VOCs increased as expected (see sampling results). The product then completed the natural process of breaking the sulfur dioxide bonds, releasing the harmful gasses, and then neutralizing the VOC's that are a product of this process.

## Initial Testing

After we completed our process, air monitoring equipment (PPB Rae 3000) was utilized to determine the concentrations of VOCs. The PPB Rae was pre-calibrated at Peterson Environmental (Calibration Data available upon request). The results in the living areas were zero parts per billion for VOCs in all the rooms upon initial and follow up readings. The only exception was the Second Bedroom, where the readings initially were 400 ppb for VOCs, However, the VOC concentrations dropped to Zero ppb after an hour. This room was treated last with the RemedialConG® Product.

In order to measure the concentration of Sulfur Dioxide and Hydrogen Sulfide. Gastee gas detector tubes and hand pump were utilized. No detectable levels were found.


## Testing Equipment

GASTEC gas detector tube system - Model No. 45S



RAP 204 H / RAP 204 CC / RAP 204 CC/ RAP 204 CCPC Series Space Saver<sup>TM</sup> Odor and Particulate Controller

ALEER AIR, 514-335-427/ Henne



813-353-7618


090804CBB1930 ATTACHMENT 4 Page 1 of 3


## SETUP AND OPERATING INSTRUCTIONS

*Note:* Your unit is shipped in two boxes. The first box contains the motor blower with controls, and the second box contains the lower body assembly with the filters.

866.667.0297 Email: info@electrocorp.net | Website: www.electrocorp.net

Electrocorp/Manuals/RAP204-CC/InstrRAP204\_061708.doc





090804CBB1930 ATTACHMENT 5 TO BE SIGNED UPON COMPLETION OF IN-HOME AIR-QUALITY MONITORING AND TESTING STUDY

## FINAL RELEASE & WAIVER OF LIABILITY FORM

+ Fo Be Signed by All Residents 18 Years or Age or Older]

On today's date, I have completed a walk-through inspection of my residence with SUSAN GABRIEL, a CPSC employee. I further acknowledge that except for any items listed and described below, no items are missing, damaged, or destroyed in my residence.

Notation of missing, damaged or destroyed items in residence (if applicable):

.

I acknowledge that CPSC offered reimbursement for the \_\_\_\_\_, but I have declined CPSC's offer. I acknowledge that I have not requested that the \_\_\_\_\_\_ be repaired or replaced by CPSC.

Signature of Resident

et 26 200 9

Date

[REMAINDER OF THIS PAGE LEFT INTENTIONALLY BLANK]

# U.S. Consumer Product O90804CBB1930 ATTACHMENT 6 Safety Commission

## **AUTHORIZATION FOR RELEASE OF NAME**

Thank you for assisting us in collecting information on a potential product safety problem. The Consumer Product Safety Commission depends on concerned people to share product safety information with us. We maintain a record of this information, and use it to assist us in identifying and resolving product safety concerns.

We routinely forward this information to manufacturers and private labelers to inform them of the involvement of their product in an accident situation. We also give the information to others requesting information about specific products. Manufacturers need the individual's name so that they can obtain additional information on the product or accident situation.

Would you please indicate on the bottom of this page whether you will allow us to disclose your name? If you request that your name remain confidential, we will of course, honor that request. After you have indicated your preference, please sign your name and date the document on the lines provided.

I request that you do not release my name. My identity is to remain confidential.



You may release my name to the manufacturer but I request that you do not release it to the general public.

V.	may paleone my name to the manu	facturer and to the public.
(Signature)	(Daio)	8.06 2009
CPSC Form 322		

#### **090804CBB1930 ATTACHMENT 7**

#### **IDENTIFICATION OF CONTACTS:**


1. homeowner, the second secon

#### **CONTACTS MADE BY THE HOMEOWNER:**

- 1. WCI Builder of Bonita Springs, FL.
- 2. Homeowners Insurance Company.
- 3. Attorney, name not released.
- 4. David Fago, owner, Biohazard Abatement Solutions, Inc, 306 15 Avenue NW, Ruskin, FL 33570 (813) 967-3685.

### Doc No: 10960493A

06/15/2009 17:39:04




Incident Description = My home, only 2 1/2 years old has been inspected and diagnosed with the China Wallboard problem. Already I have lost a \$ \$2000.00 TV and in time all appliances and AC will have to be replaced, as well as complete re-wiring. This will happen over again until this problem has been addressed and repaired. My healt his being affected in the threat and pulmonary trackt. I am stying in Indiana for the time being until i find a solution. My phone # here is the threat and pulmonary trackt. I am stying in Indiana for the time being until i find a solution. My phone # here is the threat and pulmonary trackt. I am stying in Indiana for the time being until further notice. My cell number is the threat and pulmonary trackt are 7 other homes with this problem, all new. Neighbors have access to my home if neccessary. Mail is being forwarded to Indiana.

Victim's age at time of incident = 79 Victim's sex = male Date of incident = February 2009 Product involved = China Wall Board Product brand name/manufacturer = unknown or Knauf Manufacturer street address = unknown Place where manufactured (City and State or Country) = China Product model and serial number, manufacture date = Product damaged, repaired or modified = yes If yes, before or after the incident = before Description of damage, repair or modification = Wallboard emitting sulphur gases Date product purchased = 2006 Product involved still available = yes Have you contacted the manufacturer = no If not, do you plan to contact them = yes Name Release = Release name to the manufacturer and public

If you have any changes, additions, or comments you wish to make concerning your attached report, please make them in the space below.

I confirm that the information in the attached report (including any changes, additions, or comments I have made) is accurate to the best of my knowledge and belief





I request that you do not release my name.

You may release my name to the manufacturer but I request that you not release it to the general public.

You may release my name to the manufacturer and to the public.

1. Task Number			2. Investigator's ID					
090817CBB1957			9102					PIDEMIOLOGIC
3. Office Code	4. Date of Accie YR MO D		5. Date YR		ted DAY		INVESTIGATION REPORT	
810	2009 05 08	3	2009	08	18			
6. Synopsis of Accide	nt or Complaint		UPC					
	ninese drywall. Th	e air condit	ioner and					n the home, from what ad minor discoloration.
					MFR/PI	RVLBR NOTI	FIED	/
					COMME OVEI	:NTS:YE: RRULED;		NO Che <b>d</b>
					EXC	ISIONS/FOIA	EXS.	:
						NOT RE-NOT		
								."]
7. Location (Home, So	:hool, etc)		8. City					9. State
1 - HOME		<del></del>	BOYT					FL
10A. First Product		10B. Tra		l Nam	e			10C. Model Number
1876 - House Structu			VVIN					UNKNOWN
11A. Second Product		11B. Tra	de/Brand	l Nam	10			11C. Model Number
0381-Air Conditioner		NONE				NONE		
11D. Manufacturer Na NONE	me and Address							
<b>12. Age of Victim</b> 45	<b>13. Sex</b> 2 - Female				<b>oosition</b> red, not H	losp.	<b>15</b> . 6	I <b>njury Diagnosis</b> 8 - Poisoning
16. Body Part(s) Involved 85 - ALL OF BODY	17. Respon 1 - Victim/C		nt 1 - On-Site 19. Time Spent 19. Time Spent (Operation 11/		(Operational / Travel)			
20. Attachment(s) 9 - Multiple Attachments21. Case S 07 - Const		ource 22. Sumer Complaint		Samp	le Collection Number			
23. Permission to Disc	close Name (Nor	NEISS Ca	ses Only	/)		I		
Yes	Nc	◯ No		) Ver	bal	Yes for Manuf. Only		or Manuf. Only
24. Review Date 09/22/2009	<b>25. Reviewed E</b> 9001	25. Reviewed By 9001			26. Regional Office Director Dennis R. Blasius			
<b>27. Distribution</b> Woodard, Dean; Blas Rohit; Matheson, Joa	sius, Dennis; Rose Inna	e, Blake; Tro	otta, And	rew; K	- íhanna,	28. Source H095004		ument Number

CPSC FORM 182 (12/96) Approved for Use Thru 1/31/2010 OMB No. 3041-0029

· ·

~

This investigation was initiated by a complaint received by the U.S. Consumer Product Safety Commission.

The information contained in this investigation was supplied by the following sources:

1. An onsite interview with the female owner of the home on 8-18-2009.

Family Members:

Husband – 53 year old male Wife – 45 year old female Daughter – 19 year old female Son – 16 year old male

This incident involves health issues and possible copper and metal corrosion at the non seasonal home of the victims over an extended period of time as will be detailed later in this report which the owners believe were caused by contaminated Chinese drywall used in the construction of their home.



An engineering firm was hired by the CPSC to collect and conduct air and drywall sampling and examination at the home and the results will be provided to the consumer once completed.

The home was 5 bedrooms, 3 bathrooms new construction, 3800 square foot two story home in Boynton Beach, FL. The owner contacted the CPSC on 5-08-

2009. The Air Conditioner coils had not leaked Freon or had to be replaced so the incident date is being listed as when the family contacted the CPSC on 5-08-2009.

The home was a cinder block construction with metal studs for interior framing with wood trusses and probably wood framing around doors and windows. The home was built in late 2006 and the family moved into the home in January of 2007. The home is a two story home with lanai. The home has received no renovations or changes since the family moved into the home. The downstairs has tile floors and the upstairs common area and bedrooms have carpeting.

The family had been in excellent health and was not experiencing any ill health affects until about 9 months after having lived in the home.

The husband began experiencing headaches, itchy eyes and nose, skin irritations and some coughing and sore throat. He was unable to sleep at nights for unspecified reasons and had not had any of those problems before moving into the home.

The wife was having frequent headaches at least four times per week and would have to take three Advil's to combat the symptoms. She was also experiencing allergy sneezing, sore throats, dry eyes and coughing and a lack of being able to sleep well at nights.

The 16 year old male was having frequent headaches and difficulty sleeping at nights for unspecified reasons. The 19 year old female was not experiencing any ill effects.

All of the family would notice a quick lessening of the affects of the symptoms within 30 minutes to one hour after leaving the home. Most of the symptoms would abate soon after being out of the home however most of the symptoms would start up again by the next morning.


The wife indicated that the loft area of the second floor and the storage area under the stairs on the first floor had the worst odors. She described the odors as a "frying onion stale cooking odor," and was first noticed about five months after moving into the home and was especially noticeable in the rooms indicated previously and in closets or stale air areas of the home.

This investigator was only able to detect a slight sulfur odor in the upstairs and downstairs closet areas of the home. The home used to have air fresheners throughout the home but the husband wanted to see how the odors smelled without them. All of the air fresheners were removed except those in the bathrooms.

The only appliances that appeared to be affected in the home were the downstairs and upstairs televisions which were new to the home but were starting to fail by having picture distortion especially upon startup.


No other appliance or electrical problems were known by the consumer to be having problems. The two air conditioner coils of the home were turning black according to the consumer when they were examined by the builder in April of 2009. The builder examined the home for the presence of Chinese Drywall however he was non committal regarding the results and had not produced a report regarding his results for the consumer.

The coils for one Air Conditioner was examined and showed only minor discoloration. Copper water supply lines showed minor discoloration. Copper lines in the refrigerator showed only minor discoloration.



Photograph of minor AC coil discoloration

Photographs of the home and some of the usual items which should have showed corrosion are included in the photographs however most of the items showed minimal discoloration.



Photograph of minor copper water supply line discoloration.



Photograph of minor copper water supply line discoloration.



Photograph of minor copper water supply line discoloration.

The consumer indicated her permission to release her name with copies of this report.

#### **Product Information:**

Product: Possible Chinese Drywall Manufacturer: Unknown

Builder: Northstar Homes 14901 Military Trail Delray Beach, FL 33484 Phone 561-638-6270 Fax 561-638-7458

Drywall Subcontractor: Unknown

Drywall Supplier: Unknown


## Attachments:


• . ·

Exhibit #1	Contacts
Exhibit #2	Photographs of the home (12)
Exhibit #3	Information on the builder

Contacts: Betty Benzino (Complainant) 8-18-2009 10077 Cobblestone Creek Dr. Boyton Beach, FL 33472 (561) 400-2196


•





IDI 090817CBB1957 Exh #2 Page 2 of 12











Photograph of the homes Air Conditioner


APPROVED ACCESSORIES         XFCEH**01NDS       KFCEH**01NDS       KFCEH**01NDS <th>PRODUCT NO. MODEL NO SERIAL NO. VOLTS MOTOR HP MOTOR FLA PHASE/HERTZ TEST STATIC REFRIGERANT 22</th> <th>FA1CNC84201 FA1CNC842 3286A90245 208/230 1/2 2.9 1/60 .20 IN. W.C. DESIGN PSIG</th> <th></th> <th>COD os</th>	PRODUCT NO. MODEL NO SERIAL NO. VOLTS MOTOR HP MOTOR FLA PHASE/HERTZ TEST STATIC REFRIGERANT 22	FA1CNC84201 FA1CNC842 3286A90245 208/230 1/2 2.9 1/60 .20 IN. W.C. DESIGN PSIG		COD os
Hum Field Installed Electric Heaters Apply Electrical Information         PLATE SUPPLIED WITH HEATER IN THIS BLOCK.	KFCEH**01N03 KFCEH**01C10	KFCEH**01H20 KFCEH**01C08 KFCEH**01F15	KFCEH**01N05 KFCEH**01N09 KFCEH**01C15	KFCEH***#TIN18 KFCEH**#1315
L1L2 HEATER AMPS       36.2/40.0       MIN. AMPACITY       48.9/53.6         MAX. OVERCUR. PROTECTION       50/60         DUAL SUPPLY CIRCUIT	I FUH FIELD INSTALLED	) ELECTRIC HEATERS . H HEATER IN THIS BLI	APPLY ELECTRICAL OCK.	UNIT INFORMATION
A T -AS INTEGRAL LIMIT CONTROL, MAX. OUTLET TEMP. 200F ACTOR THERMALLY PROTECTED. SEE INSTALLATION INSTRUCTIONS FOR SPECIFIC INSTALLATION REQUIREMENTS AND SEPONED ACCESSORY KIT INFORMATION. MAX VOLTAGE TO GROUND OF SUPPLY CIRCUIT NOT TO EXCEED 120 VOLTS IF HEATE AS CHOOT BREAKER CONTROL. SCHOOT BREAKER CONTROL. S	MAX. OVER LT 12 HEATER AMPS MAX. OVER L3 14 HEATER AMPS MAX. OVER	CUR. PROTECTION SC — DUAL SUPI N/A CUR. PROTECTION N N/A CUR. PROTECTION N	¥60 PLY CIRCUIT /A /A /A	ACITY N/A
HATING PLATE REPLACE IF NECESSARY. THIS UNIT IS EQUIPPED WITH METERING DEVICE: Model Number FA4CNC0420T0AAAA	A T HAS INTEGRAL LI MOTOR THERMALLY PR DEFINISTALIATION INS DEFINED ACCESSORY AAK VIRTAGE TO GRO AS CIRCUIT BREAKER DU FOR COOLING ONL PEPTYEC HEATERS MI LEAFANCE TO DOMBUS NICL WITH STOTES WI DEFINIC MITH HEATE DEFINIC CASING AN CAUTION	MIT CONTROL. MAX. ( OTECTED. TRUCTIONS FOR SPEC KIT INFORMATION. UND OF SUPPLY CIRC CONTROL. Y EXCEPT WHEN INST FGID BY CAC/BOP. INI STIBLE MATERIALS TO HEATERS. RS 20KW AND ABOVE IC 1" FOR FIRST 36" METERING DEVICE FO MATCH THAT SHOWN	DUTLET TEMP. 200F CIFIC INSTALLATION CUIT NOT TO EXCEED TALLED AS PART OF DIANAPOLIS, IN D BE 0" FOR CASING E. CLEARANCE TO CI OF PLENUM AND DI OF PLENUM AND DI A THIS COIL MUST ON OUTDOOR UNIT	REQUIREMENTS AND 120 VOLTS IF HEATE A LISTED HEAT PUMF G. PLENUM AND DUCT OMBUSTIBLE MATERIA
·····································	F	RATING PLATE REPLA	ACE IF NECESSARY.	<u> </u>


A/C Labeling


•













Home

Communities The Northstar Difference Build Your Own Floorplan Customer Care Press Room Immediate Delivery Homes



## THE NORTHSTAR DIFFERENCE

Since our inception over two decades ago. Northstar Homes has remained steadfastly committed to creating distinctive homes, unsurpassed lifestyles and customer care. David Ettinger and Scott Worley, the principals of Northstar Homes, recognize the importance of quality home building and, with that understanding, have successfully made Northstar Homes a leader in home building thousands of distinctive residences

At Northstar Homes, homebuilding isn't just a business. It's a craft. In the centuries-old tradition of building, Northstar Homes forges each new home from the ground up with meticulous attention to every detail. From concrete and mortar, stone, wood and steel, we create unique homes with the timeless beauty and exceptional quality only a true craftsman can build. And like a true craftsman, we are committed to building homes that will endure for generations to come.

We believe in creating a lifestyle for our homeowners as well. Understanding that homebuyers are looking for more than just a nice home, we are in the forefront of designing communities that offer spectacular lifestyles with amenities such as well-appointed clubhouses, tennis courts, swimming pools, playgrounds and fully equipped fitness centers.

At Northstar Homes, we pride ourselves on consistently offering homebuyers the very best in customer care and service. We believe that it is our responsibility to make our customer's homebuilding experience a pleasant one, from beginning to end. Our customer care representatives are dedicated to ensuring each customer's complete satisfaction throughout the homebuilding process.

From quality homebuilding to unsurpassed lifestyles to superior customer care, Northstar Homes is committed to building dreams and exceeding expectations - one customer at a time.

Northstar Homes | 14901 Military Trail | Delray Beach, FL 33484 Phone 561-638-6270 | Fax 561-638-7458 | Contact Us powered by iXL Studios, LLC





CONSUME	R PRODUC	T INCIDENT	REPORT	Region: EASTERN
1.NAME OF RESPONDENT Bat-El (Betty) Benzino		HONE NO. (H 1-400-2196	OME) (WORK) unknown	
3.STREET ADDRESS	4.0	ITY	S	T ZIPCODE
10077 Cobblestone Creek Dr.	Bo	ynton Beach	F	L 33472
4a.EMAIL ADDRESS		INCIDENT CI		
batelb@aol.com		oynton Beach	F	L 33472
5.DESCRIBE INCIDENT OR HAZARD, The consumer said she and 1 cold symptoms than usual - cont -	her fam	ily have	experience mo	re frequent This
6. DATE OF7.IF INJURY OR NEAR AGE/SEX 21 Y/FINCIDENT(S) 04/15/20097.IF INJURY OR NEAR AGE/SEX 21 Y/F04/15/200904/15/2009		OBTAIN	8.IF VICTIM DI RESPONDENT, 1 not given RELATIONSHI daughter	PROVIDE NAME
9.DESCRIPTION OF PRODUCT Chinese drywall			10.BRAND NAME unknown	
11.MFR/DISTRIBUTOR NAME, ADDR. unknown		unknow	, SERIAL #'s, D.	ATE OF MFR
unknown USSUE 32 UNATON UNKnown 05/08/2009 UNATON UNKnown			n ⊨Beach, FL	SS & PHONE
14.WAS THE PRODUCT DAMAGED, RE OR MODIFIED? YES IF YES, BEFORE OR AFTER THE	PAIRED	DATE PU		6 AGE 2 Y
INCIDENT? AFTER DESCRIBE: See narrative		IF SO,	ODUCT HAVE WARN NOTE: ining to the problem	ING LABELS?
17. HAVE YOU CONTACTED THE MANUFACTURER? YES IF NOT, DO YOU PLAN TO CONTACT THEM?	YES	NOT, ITS DISPOSITION NAME WI THIS		USE YOUR NAME WITH THIS REPORT?
FO	R ADMINI	STRATION U	SE	
20.DATE RECEIVED 21.RECEIVED E 05/07/2009 mlj/HL		22.DOCUMENT NO H0950047A	•	
23.FOLLOW-UP ACTION			<b>24.PRODUCT COD</b> 1876	E(S)
25.DISTRIBUTION			IE & TITLE	
CDSC FORM 175 (02/2004)	·			

•

Region: EASTERN

#### Narrative Continued started within 6 months of them moving into the home. They actually moved into the home in January 2007. The consumer has a daughter in college, who is allergic. When her daughter comes home, she experiences difficulty breathing. Therefore, her daughter does not come home as often as she could The A/C coils are blackened. The builder came over and opened the back of the refrigerator. The back portion had begun to change color, but it had not turned completely black as of yet. The consumer noted that they have lived in $\frac{1}{222}$ Florida climate $\frac{1}{222}m_0 \frac{1}{27}$ of their life, so it is not as if they change climates. They simply changed homes and the symptoms began to occur. Vict # Sex Relationship Age Name 4-F 19 Dright-5 2 53 Y Μ Haim husband 3 F 45 Y self self 4 F 21\$Y not given daughter 5 M 15 Y not given son Vict # Victim Injury Description la headlaches 2 unable to sleep at night, frequent cold symptoms 3 frequent headaches and frequent cold symptoms 4 headaches and frequent cold symptoms - Acture 5 headaches and frequent cold symptoms Distributor Phone #:

CPSC Source: WOM

We, must likely, have chines Dywall.

#### H0950047A

#### Narrative Continued

started within 6 months of them moving into the home. They actually moved into the home in January 2007.

The consumer has a daughter in college, who is allergic. When her daughter comes home, she experiences difficulty breathing. Therefore, her daughter does not come home as often as she could

The A/C coils are blackened. The builder came over and opened the back of the refrigerator. The back portion had begun to change color, but it had not turned completely black as of yet.

The consumer noted that they have lived in the Florida climate all of their life, so it is not as if they change climates. They simply changed homes and the symptoms began to occur.

Vict #	Sex	Age	Name	Relationship
2	M	53 Y	Haim	husband
3	F	45 Y	self	self
4	F	19 Y	not given	daughter
5	М	15 Y	not given	son

Vict #	Victim Injury Description				
2	unable to sleep at night, frequent cold symptoms				
3	frequent headaches and frequent cold symptoms				
4	headaches and frequent cold symptoms				
5	headaches and frequent cold symptoms				
Distrib	itor Phone #:				

CPSC Source: WOM

#### H0950047A

If you have any changes, additions, or comments you wish to make concerning your attached report, please make them in the space below.

We most likely have chance Drawale I would like to have my house inspectory.

I confirm that the information in the attached report (including any changes, additions, or comments I have made) is accurate to the best of my knowledge and belief.

Signature

I request that you do not release my name.

You may release my name to the manufacturer but I request that you not release it to the general public.

You may release my name to the manufacturer and to the public.

ł I. L 1 I 1 l 

T

1. Task Number			2. Investigator's ID			
090817CBB1958			2248		EPIDEMIOLOGIC	
3. Office Code	4. Date of Accid YR MO DA		5. Date Initiated YR MO DAY		INVESTIGATION REPORT	
810	2009 03 28		2009 08 17			
6. Synopsis of Accide	nt or Complaint	<u>.</u> ι	UPC			
drywall in the home ha	as caused several	health issu	l into a new home in Aug ues. Appliances have cea roughout the home have	sed to function.	reported that Chinese . Blackening and Corrosion within AC units is	
			MFR	PRVLBR NOTIFI	ED	
			сом	MENTS:YES /ERRULED;A	NO	
			<u></u> 5	KCISIONS/FOIA E	XS. 6,25 ~ Win	
			Z	O NOT RE-NOTIF	Y_RE-NOTIFY SLET	
7. Location (Home, Sc	hool, etc)		8. City		9. State	
1 - HOME			BOYNTON BEACH		FL	
10A. First Product		10B. Trac	de/Brand Name		10C. Model Number	
1876 - House Structu	res, Repair Or	UNKNO	WN		UNKNOWN	
11A. Second Product			de/Brand Name		11C. Model Number	
0	<u> </u>	NONE			NONE	
11D. Manufacturer Nat NONE	me and Address					
<b>12. Age of Victim</b> 39	<b>13. Sex</b> 2 - Female		<b>14. Disposition</b> 0 - No Injury	1	<b>5. Injury Diagnosis</b> 70 - No Injury	
16. Body Part(s) Involved 99 - NO INJURY		(Operation		9. Time Spent (Operational / Travel) 18 / 3		
20. Attachment(s)21. Case S9 - Multiple Attachments07 - Const		iource 22. Sar umer Complaint		nple Collection Number		
23. Permission to Disc	close Name (Non	NEISS Ca	ses Only)			
◯ Yes	No Overbal		🔵 Verbal	⊖_Yes	for Manuf. Only	
<b>24. Review Date</b> 08/30/2009	25. Reviewed By 9001			26. Regional Office Director Dennis R. Blasius		
<b>27. Distribution</b> Blasius, Dennis; Woo Joanna; Khanna, Rof		a, Andrew;	Rose, Blake; Matheson,	28. Source Do 10950409A	ocument Number	

CPSC FORM 182 (12/96) Approved for Use Thru 1/31/2010 OMB No. 3041-0029

.

#### 090817CBB1958

This in-depth-investigation was initiated as follow-up to a consumer complaint reporting that a consumer and her family moved into a home constructed with Chinese drywall. The family has had health problems and several appliances replaced. Air conditioning coils need replacement as well. It was further reported that the family smelled fire, probably coming from corroded wiring in the walls. The family is no longer residing in the home.

Information contained in this investigation was obtained from the consumer during an onsite visit to the home. During this visit, the consumer signed an authorization to release name form (see Exh. 2). The consumer also agreed to participate in a drywall air sampling study (see release forms attached, Exh. 3 and 4).

The home is a 4091 square foot 2-story single family home with 6 bedrooms and 3 bathrooms, made with metal studs and tiled throughout. It was purchased new in August of 2006. The home is occupied by the consumer, her husband, and two children. The family moved into the home in August of 2006. No modifications, alterations or additions were made to the home. The interior walls were painted prior to the move. No drywall has been replaced.

The consumer reported that from the moment she moved in, an unidentified odor was always present in the home. This odor was attributed to the smell of new construction or building materials. As a result the consumer continuously burned candles and purchased air fresheners in an attempt to mask the odor. The odor persists presently and is described by the consumer as the smell of burning metal.

The consumer also reported that on 3 separate occasions both she and her children smelled burning. No smoke or fire was ever observed.

The consumer also reported that as early as August of 2006, the whole family began to feel ill. The following is a list of physical symptoms felt by each member of the family:

#### Health Effects:

Adult, female (39) - headaches, sinus congestion, watery eyes, scratchy throat, insomnia. Adult, male (41) – headaches, sinus congestion, watery eyes, insomnia. Child, female (13) – headaches, watery eyes, nose bleeds, insomnia. Child, male (12) – headaches, watery eyes, nose bleeds, insomnia

The consumer confirmed that all symptoms mentioned above are felt at all times while inside the home. A chronological list of the children's doctor visits is shown in Exhibit 5. The consumer was concerned about her daughter's extreme headaches and sought the opinion of her pediatrician. It was also reported that no one in the family had ever suffered from insomnia until they moved into this home. The family pet was reported to have suffered from frequent urination all throughout the house and unexplained persistent barking. The consumer reports that several appliances have been damaged. The following is a list of damaged appliances and their current conditions:

#### <u>Appliances:</u>

<u>2 Air conditioners</u> – rotted coils and copper, no longer cooling, not yet replaced. <u>Microwave</u> – motherboard replaced by manufacturer in 2006, currently working. <u>Intercom</u> – fixed 3 times (still not working). <u>Stove</u> – replaced motherboard in 2008, currently working. <u>Samsung 51' Television</u> – replaced motherboard, March 2009, currently working. <u>08' Dell Computer</u> - replaced motherboard, March 2009. <u>3 Comcast cable boxes</u> - replaced

According to the consumer, there has been no fire or smoke in the home. Flickering lights were neither observed nor reported. The consumer is unaware if any of the outlets in the home are non-functional. Some smoke detectors have sounded at times, but for no apparent reasons, even after their batteries were replaced.

Shower heads were observed with discoloration. Corrosion and rust was observed within the air conditioning units (see Exh. 6, pgs.10-15). Evidence of tarnishing was observed on jewelry as well (see Exh. 6, pg. 16).

#### **Contact with Builder**

On March 28, 2009, after 1 and  $\frac{1}{2}$  years of unexplained headaches and broken appliances along with the continued unidentifiable odor, the consumer found out that her home may have been built with Chinese drywall. On April 3, 2009, the family moved out of the home.

The consumer has made numerous calls to the builder. To date, messages have not been returned. It is suspected that the builder may be avoiding contact with the homeowners affected by the Chinese drywall.

At this time the consumer is no longer living in the home and has rented another property in the area. The consumer is concerned over the uncertainty of the future and explained that the situation has caused an unexpected financial burden. The consumer continued to express concerns over current and long-term health effects. However, she is pleased to report that since they moved out, all symptoms are no longer being felt and even the dog's odd behavior has ceased.

This investigator conducted an internet search of the building company's website and results are included in Exhibit 7.

An internet search of the residence county property information was conducted and results are shown in Exhibit 8.

#### **Investigator Observations**

During this visit this investigator detected an odor which appeared to smell like burning metal. The odor was present inside and just outside the front and back doors as well. Shortly thereafter, this investigator experienced a headache and scratchy throat. This persisted throughout the interview and did not cease until about an hour after being out of the home.

#### **PRODUCT INFORMATION**

The product is suspected to be Chinese drywall. No product identification could be obtained.

#### **ATTACHMENTS**

•

<u>EXHIBIT 1</u>	Contact Sheet
<u>EXHIBIT 2</u>	Authorization to Release Name Form
<u>EXHIBIT 3</u>	Initial In-Home Release Form (for drywall air sampling)
<u>EXHIBIT 4</u>	Final Waiver & Liability Release Form
<u>EXHIBIT 5</u>	"Pediatric Associates" Children's Chronological Medical Appt's
EXHIBIT 6	Photographs
EXHIBIT 7	Builder's Website Information
<u>EXHIBIT 8</u>	Palm Beach County Property Information

## EXHIBIT 1 CONTACT SHEET

**RESPONDENTS** 

1) Consumer/Complainant



# U.S. Consumer Product Safety Commission

## **AUTHORIZATION FOR RELEASE OF NAME**

Thank you for assisting us in collecting information on a potential product safety problem. The Consumer Product Safety Commission depends on concerned people to share product safety information with us. We maintain a record of this information, and use it to assist us in identifying and resolving product safety concerns.

We routinely forward this information to manufacturers and private labelers to inform them of the involvement of their product in an accident situation. We also give the information to others requesting information about specific products. Manufacturers need the individual's name so that they can obtain additional information on the product or accident situation.

Would you please indicate on the bottom of this page whether you will allow us to disclose your name? If you request that your name remain confidential, we will of course, honor that request. After you have indicated your preference, please sign your name and date the document on the lines provided.

## $\square$

I request that you do not release my name. My identity is to remain confidential.



You may release my name to the manufacturer but I request that you do not release it to the general public.




You may release my name to the manufacturer and to the public.


an a	8/19/09	
(Signature)	(Date)	




090817CBB1958

Exh. 6 Page 1 of 16



































#### Welcome to Northstar Homes : NorthStar Communities

090817CBB1958

Exh. 7 Page 1 of 3



Home Communities The Northstar Difference Build Your Own Floorplan Customer Care Press Room Immediate Delivery Homes





### COMMUNITIES

#### AVAILABLE COMMUNITIES



Conveniently located in Delray Beach, Gramercy Square is just minutes from the vibrant, trendy downtown area known for its unique shops, eclectic restaurants, cultural attractions, live entertainment and more.



Cobblestone Creek is located on the Northeast corner of Boynton Beach Boulevard and Lyons Road in Boynton Beach. We are conveniently situated one mile west of Florida's Turnpike and one mile east of 441. Just minutes from the area's shopping, dining, recreation and more!

#### PREVIOUS COMMUNITIES




Priced from the mid \$500s to mid \$600s, these quaint two and three-story townhomes. will create a charming setting reminiscent of a secluded Italian village. Inside this new upscale community exists just 37 luxury townhomes that redefine style. Spacious 10-foot ceilings envelope sophisticated living at its finest. Gourmet kitchens are adorned with granite-countertops, stainless steel fixtures and appliances, and 42" European-style wood cabinets. Exquisite courtyards, gardens and a heated swimming pool can be viewed from towering balconies on all floorplans. At Tuscany Village, your home is your oasis!



An incomparable combination of fine living and recreation is what residents of Avalon Estates take pleasure in, Nestled within the core of this active adult community is an 18,000 square foot Grand Clubhouse that is surrounded by paralleled recreational facilities including Bocce Ball courts, Har-Tru tennis courts and a resort-style heated pool. Architecturally designed homes line the winding streets within this gorgeous community. Here, residents have everything they want in a home, and everything they need in a community.

This charming neighborhood offers the best in active adult living. Here, residents are pampered with customized homes, community activities, and spectacular activities.

#### DOWNLOAD OUR Builder Map



090817CBB1958

Exh. 7 Page 2 of 3



residents. This distinguished neighborhood is made up of beautifully designed homes, lushly landscaped streetscapes and winding walkways...but, we like to think that what sets it apart from other communities is the satisfied homeowners who take pride in their home and their community.



The Cascades has everything Active-Adult homeowners need, all within its beautifully manicured entrance and private gates. Single-family and estate homes surround a 30,000 square foot Grand Clubhouse that houses a wide variety of recreational activities to suit all types of interests. Twenty-seven holes of a non-equity, championship golf course wind through the 100 acres of lush grounds and shimmering lakes of this spectacular community. Residents can shop at the community's own Market Place, where food and sundry items are available for purchase. At the Cascades, homeowners experience a whole new world of active adult living.



This spectacular enclave of single-family homes offers its residents a recreation-filled lifestyle with amenities such as a swimming pool with poolside gazebo, BBQ area, tennis courts, volleyball court, and a tot-lot for the children. An exquisitely designed gated entrance welcomes residents into a community of charming homes and beautifully manicured landscaping while its prime location within Boca Raton is just minutes from premier shopping, dining, golf, and miles of beautiful beaches. This wonderful combination of impressive amenities, stunning homes, gorgeous grounds, and central location, makes Meadow Lakes the ideal community for family living.

Northstar Homes took its fourth community in the Lakeridge series to a new level by building a stunning front entrance to the community. This impressive entryway into Lakewood Falls features cascading waterfalls. sweeping trees and lush, flowering bushes. This impressive community entrance was meant to make a statement the moment the residents arrive. Inside Lakeridge Falls exists beautiful estate-sized homes that could be customized. This freedom of choice and customization has become a staple of Northstar Homes. Another staple of Northstar Homes are the amenities...and Lakeridge Falls boasts amazing recreational facilities to suit all types of interests.

Taking the success of Lakeridge Estates one step further, Northstar Homes envisioned a new concept for its third community in Westchester Golf and Country Club -Lakeridge Greens. Here, active adults would get more out of their neighborhood than just a home... they would get . choices. Lakeridge Greens offered the choice of smaller, single-family homes or larger, estate sized homes. In addition, a 10,000 square foot clubhouse was the centerpiece. The clubhouse included a wide variety of recreational facilities that gave residents the opportunity to explore their many hobbies and interests. With Lakeridge Greens, Northstar gave a new meaning to the phrase "active" adult community.



Following the completion of its prior community, Lakeridge, Northstar Homes had grander visions for their next community, Lakeridge Estates. This new community offered large homes placed within a more intimate setting. Now an established community located within Westchester Golf and Country Club, Lakeridge Estates boasts estate-sized homes with golf course views tucked away in a charming



Wears

AKERIDGE

090817CBB1958

•

Page 3 of 3

Lakenidge

Northstar Homes' reputation as an established builder and solid leader in developing active adult communities in the Boynton Beach area began with Lakeridge. It was this community that inspired Northstar's vision to create a series of communities that would eventually build off one another. As Northstar's vision grew...so did their communities.

.

Northstar Homes | 14901 Military Trail | Delray Beach, FL 33484 Phone 561-638-6270 | Fax 561-638-7458 | Contact Us powered by iXL Studios, LLC

#### Palm Beach County Property Appraiser Property Search System

090817CBB1958

Exh. 8 Page 1 of 1

Gary R. Nike Property	Apprais	Property A SCI (c	ppraiser's Pu The contract	ublic Access System		
Property Information	on ———-					
Location Addres		and a second		View Map		
Municipalit	y: UNINCORPO	Calculate Portability				
Parcel Control Numbe	r: 00-42-45-20-05-002-0630 Proposed					
Subdivisio	n: COUNTRYSI	COUNTRYSIDE MEADOWS				
Official Records Boo		age: <b>756</b>		e: Aug-2006 Help		
Legal Descriptio	n: COUNTRYSI	DE MEADOWS	S LT 63 BLK 2	2		
Cowner Information						
Nam	ie:			All Owners		
Mailing Addres	55: <b>Children</b>					
Sales Information -						
Sales Date Book/Pag	-	Sale Type	Own	ler		
Aug-2006 20737/07	56 <b>\$577,908</b>	WARRANTY	DEED			
Арг-2005 18518/133	11 <b>\$0</b>	DEED OF TR	UST NOR	THSTAR HOLDINGS AT B & A LLC		
Exemptions ————						
Regular	Homestead: \$	\$25,000	Yea	r of Exemption: 2009		
Additional	Homestead: \$	\$25,000				
	Total:	50,000				
Appraisals ———						
Tax Year:	2009 P	2008	2007	<b>Property Information</b>		
Improvement Value:	\$403,490	\$537,425	\$469,456	Number of Units: 1		
Land Value:	\$0	\$0	\$0	*Total Square Feet: 4051		
Total Market Value:	\$403,490	\$537,425	\$469,456	Acres: 0.1678		
Use Code: 0	)130 Des	scription: RES	<b>SIDENTIAL</b>	* May indicate living area in residential properties.		
	values are as	of January 1	<sup>st</sup> each year	P = Preliminary Values		
Assessed and Taxa	ble Values —					
Tax Year:	2009 P	2008	2007			
Assessed Value:	\$403,490	\$483,540	\$469,456	Structure Detail		
Exemption Amount:	\$50,000	\$50,000	\$25,000			
Taxable Value:	\$353,490	\$433,540	<u>\$444,456</u>			
r Taxes ———						
Tax Year:	2009 P	2008	2007	<b>T    - - - - - -</b>		
Ad Valorem:	\$6,933	\$7,537	\$7,463	Tax Calculator		
Non Ad Valorem:	\$356	\$330	\$285	Details		
Total Tax:	\$7,289	\$7,867	\$7,748			
		Tax Collector	r WebSite			
NOTE: Lower the top and b	ottom margins t	o 0.25 on File-	>Page Setup r	nenu option in the browser to print the		

NOTE: Lower the top and bottom margins to 0.25 on File->Page Setup menu option in the browser to print the detail on one page.

#### Doc No: 10950409A

lssue: 33

05/11/2009 <u>17·16·17</u>

Name :	
Addres	
City = E	
State =	
Zip = 3	
Email =	
Teleph	
Name	
Victim's	

Incident Description = We have a home constructed with Chinese Drywall. My family has had health affects and concerns, my appliances have all needed to be replaced, my air conditioner coils have been ordered (to be replaced), and I have smelt "firre" in my home that is probably coming form the corroded wiring in the walls. We are currently not living in our home as we have found a safe, temporary housing.

Victim's age at time of incident = Victim's sex = Date of incident = 3-27-2009 Product involved = poisonous chinese drywall Product brand name/manufacturer = Knauf Manufacturer street address = China Place where manufactured (City and State or Country) = Tienian, China Product model and serial number, manufacture date = Product damaged, repaired or modified = no If yes, before or after the incident = Description of damage, repair or modification = Date product purchased = closed on th home 8/2006 Product involved still available = yes Have you contacted the manufacturer = no If not, do you plan to contact them = no Name Release = Release name to the manufacturer and public

1. Task Number			2. Investigator's ID				
090817CBB1959			2248		EPIDEMIOLOGIC		
3. Office Code	4. Date of Accid		5. Date Initiated		INVESTIGATION REPORT		
810	YR MO D 2006 10 0		YR MO DAY 2009 08 21		REPORT		
6. Synopsis of Accide	nt or Complaint		UPC	<u> </u>			
several health issues. pipes and metal fixtur	Appliances have es throughout the	been effect	ted and ceased to function	on. Blackeni ion within A0	drywall in the home has caused ng and discoloration of copper C units is evident. The builder		
			MFR/	PRVLBR NOT	TIFIED		
			COMN OV	COMMENTS:YESNO OVERRULED;ATTACHED			
			EX	CISIONS/FOI	A EXS. 3, 6, 250		
				) NOT RE-NO	DTIFY RE-NOTIFY RE-NOTIFY RE-NOTIFY		
7. Location (Home, Sc	hool, etc)		8. City		9. State		
1 - HOME			BOYNTON BEACH		FL		
10A. First Product		10B. Tra	de/Brand Name		10C. Model Number-		
1876 - House Structu	res, Repair Or		WN		ÜNKNOWN		
11A. Second Product			de/Brand Name	11C. Model Number NONE			
1 1D. Manufacturer Nat NONE							
<b>12. Age of Victim</b> 53	<b>m 13. Sex</b> 2 - Female		<b>14. Disposition</b> 1 - Injured, not Hosp.		<b>15. Injury Diagnosis</b> 68 - Poisoning		
16. Body Part(s) Involved 85 - ALL OF BODY	17. Respondent 1 - Victim/Complainant		<b>18. Type of Investigation</b> 1 - On-Site		19. Time Spent (Operational / Travel) 18 / 3		
20. Attachment(s)     21. Case So       9 - Multiple Attachments     07 - Consultation		purce 22 Imer Complaint		Sample Collection Number			
23. Permission to Disc	lose Name (Non	NEISS Ca	ses Only)				
O Yes	<u> </u>		Verbal •		Yes for Manuf. Only		
<b>24. Review Date</b> 08/31/2009	<b>25. Reviewed By</b> 9001		<b>26. Regiona</b> Dennis R. B		n <b>al Office Director</b> . Blasius		
<b>27. Distribution</b> Rose, Blake; Blasius, Andrew; Khanna, Roł		n, Joanna;	Woodard, Dean; Trotta,	<b>28. Source Document Number</b> 10950282A			

CIPSC FORM 182 (12/96) Approved for Use Thru 1/31/2010 OMB No. 3041-0029

•

This investigation was initiated by a complaint received by the U.S. Consumer Product Safety Commission.

The information contained in this investigation was supplied by the following sources:

1. An onsite interview with the male owner of the home on 8-07-2009.

Family Members:

Husband -62 year old male Wife -59 year old female

This incident involves health issues and copper and metal corrosion at the periodic home of the victims over an extended period of time as will be detailed later in this report which the owners believe were caused by contaminated Chinese drywall used in the construction of their home.

An engineering firm was hired by the CPSC to collect and conduct air and drywall sampling at the home and the results will be provided to the consumer once completed.

The home was 2 bedrooms, 2 bathrooms new construction, 1700 square foot townhome in North Venice, FL. The home is a one story cinder block construction with stucco exterior walls and metal framing studs. The owner contacted the CPSC on 5-26-2009. The Air Conditioner had not failed or leaked Freon so the incident date is considered the move in date as respiratory like allergy symptoms started at that time.



Photograph of the front of the home.

The family moved into the home in June of 2006 and the wife noticed that the builder had placed the wrong tile in the bathroom walls of the master bath and it was replaced one year after move in. There were no other renovations or alterations to the home.


The home was electric with natural gas to the stove, water heater, dryer and furnace. The home had tile in the common areas and carpeting in the bedrooms.

The family immediately upon move in noticed a "pungent, acrid odor." The family believed it was just new construction smell and thought it would eventually dissipate. The family lives in the Washington D.C. area and traveled to the Florida home every two to four months and stayed approximately one week on each visit. Both the owners were in excellent health but both began experiencing upper respiratory symptoms including runny nose, irritated eyes and a scratchy throat. The husband had one additional symptom of wheezy respiratory breathing. The symptoms would start after being in the home for a few hours and would alleviate after being away from the home for a few hours. No medical records were provided.

The family would turn the air conditioner up to 80 degrees and turn the humidity controller to 50% when they leave. He believed that because the A/C unit was in a higher position and no one lived in the home most of the time, it had probably not run as much as a normally occupied home. The home A/C was serviced every six months and he did not know if the unit had leaked any Freon and had to be recharged, however the A/C technician sprayed the copper coils with silver paint presumably to slow the corrosion. The home owner was not able to locate any of the service tickets.


In May of 2009 the family began hearing reports in the media regarding homes in Florida having Chinese Drywall and subsequent corrosion. He began examining all the affects in his home and noticed serious darkening/corrosion of copper water supply lines and many chrome water fixtures had pitting and corrosion.

The builder is listed at the bottom of this report and according to the consumer the firm is currently in bankruptcy. He had no information regarding the drywall contractor, installer or supplier. The builder conducted an inspection of the home for Chinese drywall on May 13, 2009. The employee conducting the inspection is listed at the end of this report. He opened 5-10 electrical outlets and examined the A/C coils, copper water supply lines and other evidence of corrosion. He stated that the home "showed evidence of tainted drywall." The firm refused to produce a written report on their examination.



Photograph of blackening of the ground, hot and neutral wires to an electrical receptacle.


The homeowner indicated he had purchased two small LCD televisions and one of them had died in 2007 on an unspecified date. They had also purchased an electric hand mixer that had never been used and failed to operate. The remote control for the family room had batteries which were leaking a white material. There was some blackening/corrosion of the A/C evaporator coils. Silver items in the home had tarnished. Copper water supply lines in the home had darkened or turned black. Chrome bathroom fixtures showed pitting and corrosion. Copper lines in the back of the refrigerator showed blackening.



Photograph of pitting and corrosion on a brass trivet.



Corrosion and pitting on a chrome water supply line.



Blackening on a copper water supply line.

The home owner did not believe he had any problems with flickering lights, sizzling or buzzing of electrical switches. However due to the blackening of the ground wires, hot and neutral wires he felt that there may be an unseen future electrical hazard in the home. No other appliances had failed.

The copper water supply lines in the garage and the copper electrical wiring in the breaker box did not show blackening. The home owner indicated his desire to keep his name confidential when releasing copies of this report.

#### **Product Information:**

#### Product: Possible Chinese Drywall Manufacturer: Unknown

#### Builder:

WCI Communities, Inc. 24301 Walden Center Drive Bonita Springs, FL 34134 United States Of America Employees: 1,800 Investor Relations Phone: (239) 498-8269 (239) 498-8146 (239) 498-8200 www.wcicommunities.com

Management: David L. Fry Interim President and CEO Jonathan M. Pertchik Chief Restructuring Officer Russell Devendorf Senior Vice President and Chief Financial Officer Paul D. Appolonia Senior Vice President of Human Resources Vivien N. Hastings Senior Vice President and General Counsel

Drywall Subcontractor: Unknown

Drywall Supplier: Unknown

#### Attachments:

Exhibit #1	Contacts
Exhibit #2	Permission to conduct sampling tests
Exhibit #3	Release of name form
Exhibit #4	Final release and walk through form
Exhibit #5	Photographs of the home (22)

#### Contacts:

# 8-07-2009



The consumer indicated he had contacted the following agencies about his home having Chinese Drywall. He had received no reports about his contact to them.

Florida Department of Health Florida Attorney General Sarasota County Health Department

#### **RELEASE & WAIVER OF LIABILITY FORM**

I, \_\_\_\_\_\_\_, do hereby give permission to the U.S. Consumer Product Safety Commission and any of its designated representatives, consultants, or other designees ("CPSC") to utilize my residence located at \_\_\_\_\_\_\_\_\_ for an indoor air-quality monitoring and testing study. This work is being undertaken as a part of an exploratory study to assess potential associations between constituents that may be present in indoor air and constituents that may be detected in drywall imported from China.

I understand that CPSC will be testing my residence for a variety of gases and/or other substances. Additionally, I understand that while CPSC will inform me of the chemical analysis results for my own residence, CPSC will not be providing further individualized analysis or recommendations concerning possible actions regarding health, safety and/or remediation which occupants could take in light of the information provided. However, CPSC will inform me if the chemical analysis results for my residence indicate the presence of gases or other substances above established risk levels.

I understand that this testing will take one full day of active testing and up to one to two week(s) of having passive sampling equipment in my home. I understand that after one to two week(s) of passive sampling, CPSC will contact me to arrange a time for CPSC to retrieve the passive sampling equipment. I represent that neither I nor members of my household will touch the passive sampling equipment while it is present in my home. CPSC requests that homeowners refrain from using cleaning supplies containing bleach, ammonia, and acetone. There may be other limited household activities which CPSC will request the homeowner to minimize, and CPSC will explain those activities in more detail when the testing begins.

I understand that CPSC intends to take small nail-size samples (less than 1/8 inch) from multiple inconspicuous locations throughout the home, such as behind switch plates and near baseboards. Additionally, CPSC may take drywall sample(s) of an approximate size of 6 inches by 6 inches and will cover the resulting hole(s) with a blank access panel.

I understand that neither 1 nor other members of my household, including minor children, will be compensated for our participation in this study nor will we receive any per diem allowance or other funds.

I understand that this study involves multiple residences and the final study and analysis will not be completed for a period of time, likely in the fall of 2009. I also understand that CPSC will likely not release information to the general public until the completion of the entire study. I further understand that this study may be widely disseminated to the public and that my own residence will not be identifiable by personally identifiable information such as address, name, etc. within the larger study.

I assume the risk of any and all injury or damage to my person or property that may arise, whether directly or indirectly, as a result of my participation in this study.

I hereby release and hold harmless CPSC, its officers, employees, consultants, representatives, and other designees and the United States Government from any liability for illness, injury, property loss or damage arising from participation in this study.

This agreement is made upon the express condition that for the period of time which CPSC or any of its equipment is in my residence for the purpose of conducting this testing, I shall be free from all liabilities and

Page 1 of 2

claims for damages and/or suits for or by reason of any illness, injury, or death to any CPSC officers, employees, consultants, representatives, and other designees of the CPSC or the United States Government, and that I shall be free from all liabilities and claims for damages and/or suits resulting to damage of CPSC property. CPSC hereby agrees to release and hold me harmless from any liability for illness, injury, death, and/or property lessor damage in connection with the testing as outlined above, however occurring.

18, 2009 V Signature

#### [REMAINDER OF THIS PAGE LEFT INTENTIONALLY BLANK]

Page 2 of 2

# U.S. Consumer Product Safety Commission

# AUTHORIZATION FOR RELEASE OF NAME

Thank you for assisting us in collecting information on a potential product safety problem. The Consumer Product Safety Commission depends on concerned people to share product safety information with us. We maintain a record of this information, and use it to assist us in identifying and resolving product safety concerns.

We routinely forward this information to manufacturers and private labelers to inform them of the involvement of their product in an accident situation. We also give the information to others requesting information about specific products. Manufacturers need the individual's name so that they can obtain additional information on the product or accident situation.

Would you please indicate on the bottom of this page whether you will allow us to disclose your name? If you request that your name remain confidential, we will of course, honor that request. After you have indicated your preference, please sign your name and date the document on the lines provided.



I request that you do not release my name. My identity is to remain confidential.



You may release my name to the manufacturer but I request that you do not release it to the general public.

You may release my name to the manufacturer and to the public.

Aug 7, 2009 (Date)

CPSC Form 322

TO BE SIGNED UPON COMPLETION OF IN-HOME AIR-QUALITY MONITORING AND TESTING STUDY

## FINAL RELEASE & WAIVER OF LIABILITY FORM

[To Be Signed by All Residents 18 Years or Age or Older]

I, \_\_\_\_\_\_, do hereby acknowledge that with my permission the U.S. Consumer Product Safety Commission and any of its designated representatives, consultants, or other designees ("CPSC") utilized my residence located at \_\_\_\_\_\_ for a preliminary pilot indoor air-quality monitoring and testing study on  $\frac{\mathcal{E}}{\mathcal{O}_{T}}$ , 2009.

On today's date, I have completed a walk-through inspection of my residence with

<u>Glenn Dunlap</u>, a CPSC employee. I further acknowledge that except for any items listed and described below, no items are missing, damaged, or destroyed in my residence.

Notation of missing, damaged or destroyed items in residence (if applicable):

SAR\_\_\_\_\_


I acknowledge that CPSC offered reimbursement for the \_\_\_\_\_


but I have declined CPSC's offer. I acknowledge that I have not requested that the


be repaired or replaced by CPSC. 8/07/2009 Signature of Resident Date [REMAINDER OF THIS PAGE LEFT INTENTIONALLY BLANK]


















































.










Issue: 35

# Doc No: 10950977A

05/26/2009 21:02:49



the presence of Chinese drywall."

Incident Description = On May 13, 2009, WCI Communities Construction Manager Todd Rudkin inspected our second home at **Example 10 and the second home at Example 10 and the second home at Example 10 and 10** 

Victim's age at time of incident = 62 Victim's sex = male Date of incident = May 13, 2009 Product involved = Drywall Product brand name/manufacturer = Unknown Manufacturer street address = Unknown Place where manufactured (City and State or Country) = Presumed to be China (did not manufacturer's markings) Product model and serial number, manufacture date = Unknown Product damaged, repaired or modified = no If yes, before or after the incident = Description of damage, repair or modification = N/A Date product purchased = June 2006 from WCI Communities Product involved still available = yes Have you contacted the manufacturer = no If not, do you plan to contact them = no Name Release = Release name to manufacturer only

1. Task Number			2. Investigator's ID				EPIDEMIOLOGIC		
090825CBB1980			2248						
3. Office Code	4. Date of Acci		5. Date				INVESTIGATION		
	YR MO D			MO				REPORT	
810	2006 04 0	1		09	01				
6. Synopsis of Accide	-		UPC						
	ith Chinese manu	ufactured dr	ywall, the	consu	imer repo			ns in the attic. Despite vith appliances, corrosion	
	MFR/PRVLBR NOTIFIED								
COMMENTS:YESNO OVERRULED;ATTACHED									
						IONS/FOIA E	xs. <u>4</u>	1250	
						OT RE-NOTIF		RE-NOTIFY	
								5/00/10 5/00/10	
7. Location (Home, Sc	hool, etc)		8. City					9. State	
1 - HOME			DELRA	Y BEA	АСН			FL	
10A. First Product		10B. Tra	de/Brand	Name	)			10C. Model Number	
1876 - House Structu	res, Repair Or		WN					UNKNOWN	
11A. Second Product		11B. Tra	de/Brand	de/Brand Name				11C. Model Number	
0		NONE			•			NONE	
11D. Manufacturer Na NONE	me and Address	i 							
12. Age of Victim 74	<b>13. Sex</b> 1 - Male		<b>14. Disposition</b> 0 - No Injury				<b>15. Injury Diagnosis</b> 70 - No Injury		
16. Body Part(s) Involved 99 - NO INJURY	17. Respon 1 - Victim/C	dent Complainant		. <b>Type</b> - On-S	<b>of Inves</b> Site	tigation	19. Time Spent (Operational / Travel) 12 / 3		
<b>20. Attachment(s)</b> 9 - Multiple Attachme		21. Case S 07 - Consi		nplaint		22. \$	Samp	le Collection Number	
23. Permission to Disc	close Name (Nor		ises Only	r) )Verb		$\bigcirc$	/	Maruf Orbi	
24. Review Date 09/10/2009	25. Reviewed I 9001			) vert			al Of	or Manuf. Only fice Director us	
<b>27. Distribution</b> Blasius, Dennis; Woo Rose, Blake; Trotta, /	odard, Dean; Khai	nna, Rohit;	Mathesor	, Joan	na;		Doc	ument Number	

CPSC FORM 182 (12/96) Approved for Use Thru 1/31/2010 OMB No. 3041-0029

#### 090825CBB1980

\*: •

This in-depth-investigation was initiated as follow-up to a consumer complaint which reported that the consumer and his wife purchased a home containing Chinese drywall. The consumer's wife reportedly has cancer. The couple has never lived in the home.

Information contained in this investigation was obtained from the consumer during an onsite visit to the home. During this visit, the consumer signed the authorization to release name form (see Exh. 2).

The home is a 2297 square foot one-story single family home with 3 bedrooms and  $2\frac{1}{2}$  bathrooms. The home is made with metal studs and is tiled throughout (except for the bedrooms). The home was completed in April of 2007. The home has never been occupied.

The consumer reported that he learned of the problems with Chinese drywall in the news prior to moving into the home and decided to inspect the attic area located the in the hallway between the master bedroom and bath. The drywall adjacent to the air conditioner is described as having been manufactured in China (see Exh. 6, pg. 9). It should be noted that the home contains 2 air conditioning units both of which are located in the attic.

There have been no modifications, additions or drywall replacements made in this home. The consumer reports no problems with any appliances. He states that at this time there is no evidence of blackening or rotting of air conditioning coils. No fire or smoke has ever been observed in the home. The smoke alarms are in working condition. No flickering lights have been observed. The air conditioning is functioning properly. No repairs of any kind have been made in the home.

This investigator photographed drywall located in the hallway attic between the master bedroom and bath. The word "China" is seen written on part of the drywall (see Exh. 6, pg. 9). Also photographed were several sink fixtures throughout the home (see Exh. 6, pgs. 7-19). No evidence of corrosion or pitting was observed. The air conditioning units were observed free of corrosion at this time as was the water heater located in the garage (see Exh. 6, pg. 13).

The consumer also reports that there is no detectable odor in his home and that neither he nor his wife has felt any health-related symptoms when visiting the home on occasion. Although they do not reside in the home, at this time, no obvious health effects have been noted.

This investigator did not notice any unidentifiable or uncomfortable odor while in the home. No health-related symptoms were felt during the visit.

#### Effects on Appliances and Health

<u>\*No applicances have been effected and no health-related symptoms have been noted</u> by the consumer in this home. The consumer provided a list of notes regarding his concerns regarding the drywall. This list is included as Exhibit 4.

#### **Contact with Builder**

The consumer has not made contact with the builder. He also reports that the builder has made no attempt to contact him or examine his home.

The consumer's goal is to confirm whether or not the drywall in his home, although, apparently manufactured in China, is safe and unaffected. He is unsure, at this time, if he will ever move into the home given his concern.

This investigator obtained property information on the home and it is included as Exhibit 7.

This investigator conducted an internet search of the builder and located an article regarding the development where the consumer's home is located in (see Exh. 5, pg. 1). Also located was information on the development and its amenities (see Exh. 5, pg. 2).

### **PRODUCT INFORMATION**

<u>The product is suspected to be Chinese drywall. Product identification cannot be</u> <u>confirmed on all drywall in the home.</u>

• <u>Product Identification available from drywall sheet photographed in Exhibit</u> <u>4 states in part, "Beijing New Building Materials \*\*\* China 1A ASTMC-</u> 1396-04\*\*\*"

Builder information: www.tivoliisles.com

Home Devco at Tivoli Isles 6900 W. Boynton Beach Blvd. Boynton Beach, Fl 33437 Telephone: (561)737-2520

#### **ATTACHMENTS**

- EXHIBIT 1 Contact Sheet
- EXHIBIT 2 Authorization to Release Name Form
- EXHIBIT 3 Consumer's Written Notes

Page 3 of 3

#### 090825CBB1980

с с т

<u>EXHIBIT 4</u>	Consumer's photograph of Drywall in Garage Attic
<u>EXHIBIT 5</u>	News Article/Builder Information
EXHIBIT 6	Investigator Photographs
EXHIBIT 7	Property Information

# EXHIBIT 1 CONTACT SHEET

## **RESPONDENTS**

 <u>Consumer/Complainant</u> <u>James Walsh</u> Address: 14781 Quay Lane Delray Beach, Fl 33446 Telephone: (954)815-4442

\*interviewed during on-site visit to the home 9/4/09

James P. Walsh 5728 NW 127 Terrace Coral Springs, FL. 33076 (954) 815-4442

September 4, 2009

U.S. Consumer Product Safety Commission Product Safety Investigator Attn: Ms Renee Morelli-Linen

Subject: On site visit Friday September 4, 2009 Home constructed using China Drywall Tivoli Isles (development) 14781 Quay Lane Delray Beach FL. 33446-9640

The new home we purchased was constructed with drywall manufactured in China.

We had planned to relocate from our current home a two-story Townhouse.

We selected the home for the one level feature not requiring climbing a stair.

The home remains vacant since the discovery of the China manufactured drywall, (BEBING NEW BUILDING MATERIALS PUBLIC COMPANY CHINA) (Copy of photo attached)

The home has been maintained with the Air Condition system activated.

A report dated March 17, 2009 prepared by Unified Engineering Inc to the Florida Depart of Health summarizes their findings regarding China manufactured drywall. (copy attached).

The report concluded China manufactured drywall contains strontium sulfide at trace levels.

The drywall gives off Hydrogen Sulfide and Sulfuric acid gas.

Florida environment that is not air conditioned and exposed to moisture contributes to the release of compounds. (note: home A/C activated)

The report states all Chinese drywall have over 5% organic material.

My wife has lung cancer and is being treated at University of Miami Sylvester Cancer Center. Because of a potential possible health risk we are unable to relocate.

The safety of the China manufactured drywall should be evaluated.

I will provide the drywall if the Commission is interested in conducting a test.

Information concerning Strontium Sulfide:

STRONTIUM SULFIDE reacts vigorously with acids to release hydrogen sulfide gas. May react exothermically with oxidizing agents including inorganic oxoacids, organic peroxides and epoxides, and inorganic peroxides to generate toxic gases.

Health Hazard: Irritant to skin and tissue.

INHALATION: Immediately leave the contaminated area; take deep breaths of fresh air. Call a physician.

Air & Water Reactions: Releases H2S in moist air.

James Maler

# U.S. Consumer Product Safety Commission

# **AUTHORIZATION FOR RELEASE OF NAME**

Thank you for assisting us in collecting information on a potential product safety problem. The Consumer Product Safety Commission depends on concerned people to share product safety information with us. We maintain a record of this information, and use it to assist us in identifying and resolving product safety concerns.

We routinely forward this information to manufacturers and private labelers to inform them of the involvement of their product in an accident situation. We also give the information to others requesting information about specific products. Manufacturers need the individual's name so that they can obtain additional information on the product or accident situation.

Would you please indicate on the bottom of this page whether you will allow us to disclose your name? If you request that your name remain confidential, we will of course, honor that request. After you have indicated your preference, please sign your name and date the document on the lines provided.

1	 	

I request that you do not release my name. My identity is to remain confidential.




You may release my name to the manufacturer but I request that you do not release it to the general public.



You may release my name to the manufacturer and to the public.

Mahr

SC Form 12.3



#### Home Devco's Tivoli Isles faces foreclosure - South Florida Business Journal:

090825CBB1980

Exh. 5 Page 1 of 2



9/10/2009

Tivoli Isles in Delray Beach, Florida

090825CBB1980

Exh. 5 Page 2 of 2

Home | For Sale | Amenities | Area Info

Tivoli Isles



Delray Beach, Florida 33446

*Tivoli Isles - Sophisticated Active Adult Living in Delray Beach* 

Tivoli Isles in Delray Beach is HomeDevco's newest active adult community. This community will feature 315 architecturally inspired estate and single-family homes designed with a timeless and sophisticated European charm. The homes designs will range in size from 1,760 to 3,091 air-conditioned square feet, with 11 spacious singlestory floor plans offering 3 to 4 bedrooms and 2-car garages.

Tivoli Isles will have everything you expect in a fine country club community, except for the equity fees! The community's social centerpiece will be the 22,000 square foot Tivoli Isles Club that will cater to residents and their guests with its heated grand resort-sized pool and spa area with cabanas, separate kiddie pool for the visting grandchildren, outdoor stage area, a grand ballroom with stage for theatric events and shows, gathering rooms, catering kitchen, arts and crafts room with kiln, card rooms, movie theater and billiards room with a sports bar. The full-time on-site lifestyle coordinator will ensure there are plenty of scheduled shows, trips and social functions to keep everyone's social calendar filled to the brim.

In addition, the community will feature a separate state-ofthe-art Fitness and Tennis Center with weight machines, treadmills, recumbent bicycles, freeweights as well as an aerobics studios, a sauna, men's and women's locker rooms, and a fully stocked tennis pro shop and 6 lighted Har-Tru tennis courts.


*Come see for yourself the unprecedented luxurious and sophisticated lifestyle Tivoli Isles has to offer. The community is conveniently located on the west side of 441 (SR-7) just north of Atlantic Avenue.* 

TivolilslesDelrayBeach com and Brenda Brooks are not affiliated with the community Tivoli Isles located in Delray Beach, Florida All information provided through this site is deemed reliable but is not guaranteed and should be independently verified. Please note that prices are subject to change without

notice. Copyright 2006-2007









ς.


CAUTION - INSTALLER BEFORE OPERATING UNIT) HADDING DAY COM THE OWNER es ti ACTION OF THE ACTION OF THE STREET ATTENTION - INSTALLEUR ANTENTION - INSTALLEUR ATTENTION - INSTALLEUR AVANT D'OPERER L'APPAHELLI MARCANDER D'APPAHELLI MARCANDER D'APPAH ATENCIÓN - INSTALADOR ATENCIÓN - INSTALADOR (ANTES DE FUNCIONAR LA UNIDAD) MINICO UE FUNUIUNAR LA UNIUAU) MARINE OL TORIA UNIONETORIS ELEMENTO LA UNIUAU) MARINE OL TORIA UNIONETORIS ELEMENTO LA UNIU MARINE OLIVITATIONA ALTORIA ELEMENTATIONALI MARINE OLIVITATIONA ALTORIA ELEMENTATIONALI MARINE OLIVITATIONALI ALTORIA ELEMENTATIONALI MARINE OLIVITATIONALI ALTORIA ELEMENTATIONALI MARINE OLIVITATIONALI ALTORIA ELEMENTATIONALI MARINE CONCELLA UNIO FILIPACIO ELEMENTATIONALI ALTORIA MARINE ELEMENTATIONALI ALTORIA ELEMENTATIONALI MARINE ELEMENTATIONALI ALTORIA ELEMENTATIONALI ALTORIA ALTORIA MARINE ELEMENTATIONALI ALTORIA ALTORIA ALTORIA ALTORIA MARINE ELEMENTATIONALI ALTORIA MARINE ELEMENTATIONALI ALTORIA MARINE ALTORIA A N Anna and














# 090825CBB1980


Exh. 6 Page 10 of 19


· 新开,并不是一个。				1	
			no survey for		
			1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		
		1	5 M 5 7		
	1893 et 1				
			1 10 ×10	and the second sec	
				*	
				<i>e</i> **	
			6 F <sup>0</sup> H.	et he	
			90 🕎 95-		
and the second			A.A. Hatter	1	
				2	
24		10 M 10 M	An I'VE TANKA THE WE ARE		
SALES OF THE ASS			×	all a start and a start	























# Palm Beach County Property Appraiser Property Search System

Exh 7 Page 1 of 1

ASSA DIA ANA ANA ANA		Property A	ppiaiser's Pu	blic Access Sy	51611
Propenty				t, <b>r.</b> es a su f. November 1	
Property Information	on ———				
Location Addres		Y LN			View Map
Municipalit	Calculate Portability				
Parcel Control Numbe	Proposed Tax Notice				
Subdivisio	n: TIVOLI ISL	ES PUD			
Official Records Boo		age: 1471		e: Apr-2007	<u>Reverse Side</u> <u>Help</u>
Legal Descriptio	n: TIVOLI ISL	ES PUD LT 67			
Owner Information					
Nam	e: WALSH JAN	MES PATRICK	8		All Owners
Mailing Addres	ss: 14781 QUA	Y LN			
	DELRAY BE	ACH FL 33440	6 9640		
Sales Information -					
Sales Date Book/Pag		Sale Type	Owne	ar .	
Apr-2007 21690/147	-				
Exemptions	-			H JAMES PATR	
Exemption Information	n Unavailable.	- <u></u>			
•	n Unavailable.	- <u></u>			
Exemption Information	n Unavailable. 2009 P	- <u></u>	2007	- Property I	nformation 7
Exemption Information Appraisals Tax Year: Improvement Value:		· · · · · · · · · · · · · · · · · · ·		Property I Number of	nformation
Exemption Information Appraisals Tax Year: Improvement Value: Land Value:	<u>2009 P</u> \$290,000 \$0	<u>2008</u> \$376,500 \$0	<u>2007</u> \$123,000 \$0	- Property I	nformation Units: 1 e Feet: 2297
Exemption Information Appraisals Tax Year: Improvement Value:	<u>2009 P</u> \$290,000	<u>2008</u> \$376,500	<u>2007</u> \$123,000	- Property I Number of *Total Squar	Information Units: 1 e Feet: 2297 Acres: 0.1438
Exemption Information Appraisals Tax Year: Improvement Value: Land Value:	2009 P \$290,000 \$0 \$290,000	<u>2008</u> \$376,500 \$0	2007 \$123,000 \$0 \$123,000	Property I Number of *Total Squar * May indica	nformation Units: 1 e Feet: 2297
Exemption Information Appraisals Tax Year: Improvement Value: Land Value: Total Market Value: Use Code: 0	2009 P \$290,000 \$0 \$290,000	<u>2008</u> \$376,500 \$0 \$376,500 scription: RES	2007 \$123,000 \$0 \$123,000 SIDENTIAL	Property I Number of *Total Squar * May indica residentia	nformation Units: 1 e Feet: 2297 Acres: 0.1438 te living area in
Exemption Information Appraisals Tax Year: Improvement Value: Land Value: Total Market Value: <u>Use Code</u> : C All v	2009 P \$290,000 \$0 \$290,000 0130 Des values are as o	<u>2008</u> \$376,500 \$0 \$376,500 scription: RES	2007 \$123,000 \$0 \$123,000 SIDENTIAL	Property I Number of *Total Squar * May indica residentia	nformation Units: 1 e Feet: 2297 Acres: 0.1438 te living area in al properties.
Exemption Information Appraisals Tax Year: Improvement Value: Land Value: Total Market Value: <u>Use Code</u> : C All v Assessed and Taxa	2009 P \$290,000 \$0 \$290,000 0130 Des values are as o ble Values —	2008 \$376,500 \$0 \$376,500 scription: RES of January 1	2007 \$123,000 \$0 \$123,000 SIDENTIAL <sup>st</sup> each year	Property I Number of *Total Squar * May indica residentia	nformation Units: 1 e Feet: 2297 Acres: 0.1438 te living area in al properties.
Exemption Information Appraisals Tax Year: Improvement Value: Land Value: Total Market Value: <u>Use Code</u> : C All v Assessed and Taxa Tax Year:	2009 P \$290,000 \$0 \$290,000 0130 Des values are as o ble Values - <u>2009 P</u>	2008 \$376,500 \$0 \$376,500 scription: RES of January 1 2008	2007 \$123,000 \$0 \$123,000 SIDENTIAL st each year 2007	Property I Number of *Total Squar * May indica residentia	nformation Units: 1 e Feet: 2297 Acres: 0.1438 te living area in al properties.
Exemption Information Appraisals Tax Year: Improvement Value: Land Value: Total Market Value: <u>Use Code</u> : C All v Assessed and Taxa	2009 P \$290,000 \$0 \$290,000 0130 Des values are as o ble Values — <u>2009 P</u> \$290,000	2008 \$376,500 \$376,500 scription: RES of January 1 2008 \$376,500	2007 \$123,000 \$0 \$123,000 SIDENTIAL st each year <u>2007</u> \$123,000	Property I Number of *Total Squar * May indica residentia	nformation Units: 1 e Feet: 2297 Acres: 0.1438 te living area in al properties.
Exemption Information Appraisals Tax Year: Improvement Value: Land Value: Total Market Value: <u>Use Code</u> : C All v Assessed and Taxa Tax Year: Assessed Value:	2009 P \$290,000 \$0 \$290,000 0130 Des values are as o ble Values - <u>2009 P</u>	2008 \$376,500 \$0 \$376,500 scription: RES of January 1 2008	2007 \$123,000 \$0 \$123,000 SIDENTIAL st each year 2007	Property I Number of *Total Squar * May indica residentia	nformation Units: 1 e Feet: 2297 Acres: 0.1438 te living area in al properties.
Exemption Information Appraisals Tax Year: Improvement Value: Land Value: Total Market Value: Use Code: All v Assessed and Taxa Tax Year: Assessed Value: Exemption Amount: Taxable Value:	2009 P \$290,000 \$0 \$290,000 0130 Des values are as o ble Values 2009 P \$290,000 \$0	2008 \$376,500 \$376,500 scription: RES of January 1 2008 \$376,500 \$0	2007 \$123,000 \$0 \$123,000 SIDENTIAL st each year 2007 \$123,000 \$0	Property I Number of *Total Squar * May indica residentia	nformation Units: 1 e Feet: 2297 Acres: 0.1438 te living area in al properties.
Exemption Information Appraisals Tax Year: Improvement Value: Land Value: Total Market Value: <u>Use Code</u> : 0 All v Assessed and Taxa Tax Year: Assessed Value: Exemption Amount: Taxable Value:	2009 P \$290,000 \$0 \$290,000 0130 Des values are as ble Values 2009 P \$290,000 \$0 \$290,000	2008 \$376,500 \$376,500 scription: RES of January 1 2008 \$376,500 \$0 \$376,500	2007 \$123,000 \$0 \$123,000 SIDENTIAL st each year 2007 \$123,000 \$0 \$123,000	Property I Number of *Total Squar * May indica residentia	nformation Units: 1 e Feet: 2297 Acres: 0.1438 te living area in al properties. iminary Values
Exemption Information Appraisals Tax Year: Improvement Value: Land Value: Total Market Value: <u>Use Code</u> : C <u>All v</u> Assessed and Taxa Tax Year: Exemption Amount: Taxable Value: Taxes Tax Year:	2009 P \$290,000 \$0 \$290,000 0130 Des values are as of ble Values 2009 P \$290,000 \$0 \$290,000 \$0 \$290,000	2008 \$376,500 \$0 \$376,500 scription: RES of January 1 2008 \$376,500 \$0 \$376,500 \$0 \$376,500	2007 \$123,000 \$0 \$123,000 5IDENTIAL st each year 2007 \$123,000 \$0 \$123,000	Property I Number of *Total Squar * May indica residentia	nformation Units: 1 e Feet: 2297 Acres: 0.1438 te living area in al properties.
Exemption Information Appraisals Tax Year: Improvement Value: Land Value: Total Market Value: <u>Use Code</u> : All v Assessed and Taxa Tax Year: Assessed Value: Exemption Amount: Taxable Value:	2009 P \$290,000 \$0 \$290,000 0130 Des values are as o ble Values <u>2009 P</u> \$290,000 \$0 \$290,000 \$0 \$290,000	2008 \$376,500 \$376,500 scription: RES of January 1 2008 \$376,500 \$376,500 \$376,500 \$376,500	2007 \$123,000 \$0 \$123,000 5IDENTIAL st each year 2007 \$123,000 \$0 \$123,000 \$0 \$123,000	Property I Number of *Total Squar * May indica residentia	nformation Units: 1 e Feet: 2297 Acres: 0.1438 te living area in al properties. iminary Values Structure Detail.
Exemption Information Appraisals Tax Year: Improvement Value: Land Value: Total Market Value: Use Code: All v Assessed and Taxa Tax Year: Assessed Value: Exemption Amount: Taxable Value: Taxes Tax Year: Ad Valorem:	2009 P \$290,000 \$0 \$290,000 0130 Des values are as of ble Values 2009 P \$290,000 \$0 \$290,000 \$0 \$290,000	2008 \$376,500 \$0 \$376,500 scription: RES of January 1 2008 \$376,500 \$0 \$376,500 \$0 \$376,500	2007 \$123,000 \$0 \$123,000 5IDENTIAL st each year 2007 \$123,000 \$0 \$123,000	Property I Number of *Total Squar * May indica residentia	Information Units: 1 e Feet: 2297 Acres: 0.1438 te living area in al properties. Iminary Values

detail on one page.

Page 1 of 1

08/11/2009 16:33:48

Name = James P and Barbara A Walsh Address = 5728 NW 127th Terrace City = Coral Springs State = Florida Zip = 33076 Email = jpw1933@aol.com Telephone = 954-815-4442 Name of Victim = James P and Barbara A Walsh Victim's Address = 14781 Quay Lane Victim's City = Delray Beach Victim's City = Delray Beach Victim's State = Florida Victim's Zip = 33446 Victim's Telephone = 954-815-4442

Incident Description = Chinese drywall in home Beijing New Building Materials Public Company (BNBM). Wife has cancer never lived in the house.

Victim's age at time of incident = Victim's sex = male Date of incident = 10/2006 Product involved = Chinese Drywall Product brand name/manufacturer = Chinese Drywall / Beijing New Building Materials Manufacturer street address = Place where manufactured (City and State or Country) = China Product model and serial number, manufacture date = Product damaged, repaired or modified = no If yes, before or after the incident = Description of damage, repair or modification = Date product purchased = 10/2006 Product involved still available = yes Have you contacted the manufacturer = no If not, do you plan to contact them = yes Name Release = Do not release name

If you have any changes, additions, or comments you wish to make concerning your attached report, please make them in the space below.

CHINESE MANUFACTUREd DRYWALL Exposed TO MOISTURE RELEASE VOLATILE SULFUR Compounds. FLORIDA Depantment of HEALTH IS Reviewing Reports of Concerns Related to Coting Manufactured Drywall.

I confirm that the information in the attached report (including any changes, additions, or comments I have made) is accurate to the best of my knowledge and belief.

James P walk 8/10/2009



I request that you do not release my name.

You may release my name to the manufacturer but I request that you not release it to the general public.

You may release my name to the manufacturer and to the public.

1. Task Number			2. Investigator's ID		EPIDEMIOLOGIC	
090520CBB2638			2147			
3. Office Code	4. Date of Accid YR MO DA		5. Date Initiated YR MO DAY		INVESTIGATION REPORT	
810	2005 01 01		2009 05 22			
6. Synopsis of Accide	nt or Complaint		UPC 081099000355	I		
have malfunctioned.	The complainantA	Es house w	as renovated in 2004/20	005 and she t	electrical products in her home believes drywall that was at of the house in 2008 because	
			COMMEN OVERF EXCIS	ILBR NOTIFIE ITS:YES RULED;AT SIONS/FOIA EX DT RE-NOTIFY	NO TACHED	
7 Location (Home Sc	hool etc)		8. City		9. State	
1 - HOME	7. Location (Home, School, etc)		MACON		GA	
10A. First Product		10B. Tra	de/Brand Name		10C. Model Number	
1876 - House Structu	res, Repair Or		IEETROCK		UNKNOWN	
Chicago, IL	606064678					
11A. Seco (b)(3):CPS,	A Section 6(b)	AAD Tee	de/Deend Neuro		11C. Model Number	
1876 - H 11D. Man					UNKNOWN	
12. Age of Victim 41	<b>13. Sex</b> 1 - Male		<b>14. Disposition</b> 1 - Injured, not Hosp.		15. Injury Diagnosis 71 - Other	
16. Body Part(s) Involved 85 - ALL OF BODY	17. Respond 1 - Victim/C		18. Type of Invest	stigation	<b>19. Time Spent</b> (Operational / Travel) 19 / 4	
<b>20. Attachment(s)</b> 9 - Multiple Attachme		21. Case S 07 - Consu	ource umer Complaint	22. 5	Sample Collection Number	
23. Permission to Dise	close Name (Non	NEISS Ca	ises Only)	•		
Yes		•	🔵 Verbal	$\bigcirc$ `	fes for Manuf. Only	
24. Review Date 06/03/2009	<b>25. Reviewed E</b> 9085	Зу		26. Region Dennis R.	nal Office Director Blasius	
27. Distribution Rose, Blake; Woodar	d, Dean; Blasius,	Dennis		28. Source 10950711,	e Document Number A	

CPSC FORM 182 (12/96) Approved for Use Thru 1/31/2010 OMB No. 3041-0029

This investigation was initiated as a result of an internet complaint filed with the Consumer Product Safety Commission (CPSC) on May 19, 2009. The complainant, a 37 year old female, reported that her family has experienced health problems and that electrical products in her house have malfunctioned. The complainant's home was renovated in 2004/2005 and she believes drywall that was installed during the renovation may be the cause of the problems. The family moved out of the house in 2008 because of health concerns. The complainant was interviewed outside of the incident home on May 27, 2009.

#### House Construction

The incident brick house is a one-story single family residence that was built in 1959. The ranch style home sits on a partial daylight basement and has approximately 1,700 square feet of heated living space.

The house is equipped with a natural gas hot water heater and a natural gas central heating system. All other appliances are electric.

The complainant and her family moved into the house in 1996. On April 22, 2004, a fire damaged the home. The fire started when a can of spray paint fell in a carport utility room and was punctured. The nearby natural gas water heater ignited the paint fumes. The complainant believed that the house was a total loss due to fire, smoke, and fire suppression damage. However, her homeowner's insurance company determined that the house was repairable and did not provide enough funds to totally rebuild the house.

The complainant, acting as her own general contractor, renovated the interior of the house (including the basement). The interior wood studs were replaced. The wood studs around the exterior of the house were sealed with primer and remained in place. New drywall was installed in the walls and ceilings throughout most of the house. The complainant estimated that 12 square feet of the original drywall was not removed in the kitchen/laundry room area.

The complainant purchased the new drywall from a home improvement retailer in a nearby town (a closer store of the same retailer was out of stock). On December 19, 2004, she purchased 150 pieces of ½" x 4' x 12' drywall. On January 3, 2005, she purchased 22 pieces of ½" x 4' x 8' water resistant drywall (see purchase receipts found as Exhibits C and D). The complainant believes a small quantity of additional drywall was later purchased from the same retailer but she could not provide a receipt. A sub-contractor installed the drywall. The water resistant drywall was installed along the bottom four feet of the walls in the basement.

The electrical system throughout the house was replaced as well as much of the plumbing. New appliances, wall receptacles, light fixtures, cabinets, etc. were

also installed. New carpet was placed in most of the house (except the kitchen, bathrooms, hallway, and part of the basement) and the walls were painted.

The exterior bricks of the house were discolored in the fire and the complainant was unable to clean them. Consequently, the bricks were sealed with a primer and covered with vinyl siding.

The complainant estimated that one third of the roof was replaced. The wood in the rest of the roof was blackened in the fire but not replaced. The wood was sealed with a primer.

The renovation was completed in May of 2005 and the family moved back into the house at the end of the month. The home was occupied by the complainant (a 37 year old female), her husband (41 years old), three children (a 9 year old male, 11 and 13 year old females), and the complainant's mother (70 years old). The ages in parentheses are the ages of the individuals as of the on-site interview. There were no pets present in the house.

The complainant estimated that later in 2005 is when she first noticed an odor in the house. She described it as an old, musty, sulfuric, vinegar smell. At first the odor was worse during the summer months, but more recently (in 2007 and 2008) became more persistent year round. The odor was present throughout the house and was noticeable at all times, not just when the house had been shut up. A heating/air conditioning technician visited the house in 2005 and determined that the odor was not coming from the central heating/air conditioning system (see Exhibit E).

# Health Effects

After moving back into the renovated house, family members began to experience various health problems that they had not suffered from previously. The complainant believes that many of the adverse health issues began in 2006 and worsened over time. She reported the following list of health problems (approximate dates of on-set or diagnosis, if known, are in parenthesis and ages are as of May 2009):

9 year old male: stomach ache, headache, nausea, acid reflux (August 2007), diagnosed with Ketoacidosis (hospitalized with type one diabetes and is currently insulin dependent, October 2007), uncontrollable blood sugar levels

11 year old female: stomach aches, headaches, tiredness, skin rashes, and little energy, bloody nose during sleep (once)

13 year old female: skin rashes, headaches, tiredness, stomach aches, constipation

37 year old female: tiredness, heaviness/pressure in chest (2006), sinus infection (2007), numbness in upper and lower extremities, limbs would go to sleep during the night (2008), heavy or hard sleeping, gas, bloating, lower back pain in kidney area, respiratory discomfort (asthma-like), constipation

41 year old male: tiredness, headaches, uncontrolled muscle drawing in hands and cramps in legs/hands (2008), finger numbness/tingling (2008), chest discomfort, constipation, irritated itchy eyes

The complainant's mother suffered from rheumatoid arthritis and diabetes prior to 2005. Her health deteriorated after moving into the house (including respiratory problems, uncontrollable blood sugar levels, and losing approximately 25 pounds). She moved into an assisted living facility around November of 2006 and her health somewhat improved over time. She later moved to a retirement community.

The complainant reported several instances when visitors to the house suffered unexplained symptoms including:

The complainant's 39 year old brother told her that he suffered from burning eyes and sinus problems during weekend visits to the house (dates unknown). He did not have these problems while away from the house. He stayed in the basement during his visits. The complainant placed a humidifier in the basement in an attempt to mitigate the problem but she does not know if it helped.

On one occasion the complainant's mother-in-law began to feel poorly and needed to go outside for fresh air (date unknown).

In late 2007 or in 2008 an aunt of the complainant's husband had a rapid heartbeat, clammy skin, and almost fainted at the house.

The complainant began to home school her son in September of 2007 because of the health problems associated with his soon to be diagnosed diabetes. The two female children started home school in October of 2008 because of their severe allergies. The complainant's youngest daughter developed allergies after the renovation but her son and older daughter had allergies beforehand. The complainant believes that school food played a role in the children's allergies. She reported that their skin related problems (including eczema) improved after starting home school but that other complaints (headaches, ill feelings, etc.) increased. She believes that the additional time spent in the house by the children for home school was detrimental to their health.

The complainant visited her physician in 2006 for "heaviness" or pressure in her chest in addition to heart palpitations. She did not receive a diagnosis or

treatment. She tried using dietary supplements and natural remedies but believes that being out of the house more (she started going to school) helped her feel better. She continued to have these symptoms off and on until she moved out of the house. She suffered from a severe sinus infection in 2007 that required her to receive a shot.

In 2008, the complainant visited her physician for numbness problems. She would regularly (approximately three times per week) wake up in the night with one or more of her extremities asleep. On one occasion her leg and pelvis were both asleep. She did not receive a diagnosis or treatment. Her physician recommended a nerve study but she did not have one completed.

Since moving out of the house, the complainant has only experienced similar numbness on two occasions. They both occurred on nights when her husband had been at the house during the day. She believes these episodes were caused by residual odor from the house in her husband's clothes. She now makes him promptly wash his clothes when he has been at the house.

The complainant's medical records were requested but have not been received.

The family members physical symptoms lessened when they were away from the house and returned once they were home again. It was not until 2008 that the complainant became aware that she and her family members felt better when they were away from the house. She could not estimate how quickly symptoms subsided and returned in association with being in or out of the house on a daily basis.

The complainant and her three children moved out of the house and into an apartment in early November of 2008. Her husband did not move out until mid to late December of 2008. He did not feel that there was a problem with the house and continued to primarily live there. However, after the medical issue discussed in the next paragraph, he reconsidered at eventually decided he should join his family in the apartment.

On November 24, 2008, (after the rest of the family had moved out), the complainant's husband was taken to the emergency room after spending three or four days in the house. The complainant went over to the house and found that her husband was suffering from tightness in his chest, leg and hand cramps, and numbness/tingling in the tips of his fingers. His finger numbness/tingling had been present for several months but had recently intensified. That day her husband's fingers had also begun to draw away from each other (separate) involuntarily. He was transported by emergency response personnel to a nearby hospital. The hospital ran numerous tests but no cause was identified (although he was diagnosed with microscopic hematuria, see Exhibit H). He has been in and out of the house on many occasions since moving out in December of 2008 without incident. However on Saturday, May 30, 2009, he went back to the

house to move some things. By late Sunday/early Monday he experienced numbness/tingling in his fingertips again.

The complainant was in and out of the house over the next several months after she moved. She estimated that her symptoms generally lessened 24 to 36 hours after being out of the house and reappeared four hours after returning to it. The complainant considered herself to be the most sensitive member of the family to the conditions in the home.

On May 24, 2009, the complainant went into the house wearing a dust particle respirator. She was in the house for about 15 minutes. Within half an hour she became "gassy". Three to four hours later she felt bloated, nauseous, light-headed, clammy, and experienced a rapid heartbeat. She went to sleep and felt better the next day. The complainant decided that she will no longer go into the house.

#### Electrical and Corrosion Complaints

In addition to health issues, the complainant also reported problems with items in the house that began around the year 2006. She reported flickering lights (mostly on the main floor), circuit breakers tripping for no apparent reason, buzzing noises at light switches that have dimmers, short-lived light bulbs, and plugs that were warm to the touch (the wall receptacles and the light switches themselves were not unusually warm). She did not report any unusual odors (other than the odor that permeated the entire house) in the vicinity of any wall receptacles, switches, or light fixtures.

The complainant installed several compact fluorescent lights in an effort to extend the life span of light bulbs in the house. However, these lights appeared to smoke once installed and were removed for fear of starting a fire.

The recessed lights in the kitchen would regularly go out after being on for about 15 minutes. The complainant would turn the light switch off for a couple of minutes before turning the lights back on.

The smoke alarms in the home are hard-wired with a battery back-up. The complainant feels that the batteries are short-lived but did not report any other problems with the smoke alarms.

In 2007 the motion floodlights around the exterior of the home began to malfunction. The floodlights are hardwired into the electrical system and the motion sensors are battery powered. The lights would come on for no apparent reason, they would blink on and off, and sometimes they would not turn off when they should (after a set amount of time). The motion sensors also had problems with short-lived batteries.

In 2008 the ground fault circuit interrupter (GFCI) wall receptacles (both interior and exterior) around the house began to trip for unknown reasons.

Several problems were reported with the home's central heating/air conditioning unit. The unit was installed during the renovation and it is located entirely outside of the house (referred to as a single outdoor package). The complainant specifically denied having any part of the unit inside of the house and this investigator did not observe any indoor heating/air equipment during a walkthrough of the house.

In January of 2006 the digital thermostat and the heat relay were replaced. The technician recommended increasing the size of the transformer in the unit because it was not sending the proper voltage to the thermostat. The complainant did not replace the transformer. In December of 2008 the unit's pilot light igniter was replaced after the complainant smelled gas.

The air conditioner has never been recharged with refrigerant. However, the complainant reported that she was told by a service technician that there were holes in the evaporator coils of the air conditioning unit (which is located outside of the house).

The complainant never received an explanation concerning the cause of any of the heating/air conditioning unit's problems. Three service orders regarding the heating/air system are attached as Exhibit I.

The complainant's electric cook top, installed in November of 2004, malfunctioned in 2007 or 2008. The complainant had previously noticed that when the right rear burner was turned to "low" it would actually heat to "high". The control knob for that burner was removed from the cook top. On an unknown date in 2007 or 2008, the complainant's husband decided to use the right rear burner again so he put the control knob back on. The area around the knob began sparking when he turned the burner on. He was not injured and the complainant thinks the circuit breaker may have tripped. The entire cook top was replaced under warranty with a similar unit.

The complainant reported only one instance of a product blackening in the home. The frame around a mirror that she removed from the living room of the house in late 2008 or in 2009 appeared to her to be unusually tarnished. She used a cleaner and rag to remove the tarnish and the rag quickly turned black.

The complainant advised this investigator that an identical mirror and frame were still in the incident house in one of the children's bedrooms. Per the complainant's suggestion, I removed the mirror from the wall and brought it outside for examination (the complainant would not enter the house). The complainant said it appeared to look tarnished like the other frame. She unsuccessfully attempted to wipe what she thought was tarnish from the frame with a dry cloth. The frame on the mirror appeared to be made of wood. The wood appeared to have been painted a metallic gold/silver color with additional black accents painted on. When I informed the complainant that the frame was probably made of wood, she agreed and determined that the cleaner she used on the other mirror was likely removing the paint and causing the rag to turn black.

She did not report any signs of corrosion or pitting on pipes, faucets, light fixtures, jewelry, etc.

Some of the furniture in the house had been relocated to the complainant's apartment when she moved. She had the upholstered furniture professionally cleaned to remove the offensive odor of the house. She threw away one of her daughter's mattresses because of the odor. The complainant brought some of the children's furniture to the apartment and cleaned it herself but it still made the children feel ill for a short period. She is concerned that bringing more items from the house to the apartment will cause additional adverse health reactions.

#### Examination of the House

During the on-site visit, the complainant unlocked a door and allowed me to examine the interior of the house. She would not go inside because of health concerns. The house was still full of personal effects and furniture.

The hot water heater and the circuit breaker panel were locked in a carport utility room. The complainant did not have the key. She contacted her husband in an effort to obtain the key. He stated that he was going to come to the house but had not arrived after one hour. Therefore, the water heater and the circuit breaker panel were not examined.

I examined the exposed wires behind several wall receptacles and light switches in the living room, kitchen, and basement. The wires were not corroded. Examination of the wires was limited because electricity could not be turned off to the switches and receptacles (the circuit panel was not accessible).

The copper on a coaxial cable and from speaker wires coming out of the wall in the living room were not corroded. None of the metal light switch plates located throughout the house appeared corroded, blackened, or pitted. Fixtures in the kitchen were examined and none showed evidence of pitting, blackening, or corrosion.

One toilet water supply valve located in a bathroom near the kitchen and living room appeared corroded. No other metal objects in the bathroom showed evidence of pitting, blackening, or corroding. Similar toilet water supply valves in other bathrooms had little to no corrosion and did not show evidence of pitting or blackening. No other bathroom fixtures that were examined appeared corroded, blackened, or pitted.

An outlet wiring tester was placed in several wall receptacles in the house. They appeared to be wired properly. The test button of a GFCI wall receptacle in the kitchen appeared to function properly.

The drywall in a basement bathroom was examined for markings. The back of the drywall (floor to ceiling) on one small wall was accessible from an unfinished part of the basement. No markings of any kind were visible on the exposed drywall (see Exhibit B photos 2 and 3). The unfinished basement area was damp and had a hole in the ground with standing water in it (a sump pump may have been in the water).

I entered the house's low height attic and found that it had been largely covered with plywood and used for storage. Blown insulation around the edge of the plywood flooring was moved aside in several locations but no markings of any kind were visible on the back of the ceiling drywall.

I did not note any unusual odors in the house. However, I was suffering from allergies at the time of the examination and my sense of smell was impaired.

#### <u>Other</u>

The complainant reported that mold or mildew was discovered on some baseboards in the basement in 2008. A section of baseboard, estimated by the complainant to be six feet in length, was removed and mold or mildew was discovered growing on the moisture resistant drywall. The complainant estimated that a one foot by two foot section of drywall was removed and the accessible area between the exterior and interior walls was sealed. She could not recall how the area was sealed (foam sealant, a plastic barrier, etc.).

No outside experts or professionals (other than heating/air conditioning technicians) have visited the house to investigate the cause of the various health and electrical problems. The complainant believes that the source of the problems in her home may be the drywall. She has not contacted the drywall retailer or manufacturers.

The complainant contacted several government agencies for assistance including her county health department, the Environmental Protection Agency, and the Occupational Safety and Health Administration. These entities advised her that she needed to arrange for professional help on her own. She was not able to provide any names, dates, or specific information about these contacts. She contacted CPSC after discovering reports of similar problems blamed on imported drywall in Florida. In early to mid-May of 2009, the complainant spoke with a representative of her homeowner's insurance company and explained the situation. The representative did not offer any solutions and mentioned that they were not her insurance carrier at the time the drywall was installed.

The complainant's next door neighbor moved out due to health problems several months ago. The neighbor's home was renovated around the same time as the complainant's home. The complainant was not sure if the neighbor's health problems and home renovation are related. She is not aware of any community action in regards to drywall issues.

The complainant is not sure of her short or long term plans with the house. The family is trying to cope with the financial burden of paying their mortgage and apartment rent as well as two sets of utilities. She is afraid to bring any more of her personal belongings from the house to her apartment because the odor makes her ill.

She agreed to provide a sample of the home's drywall to CPSC if requested in the future.

On May 27, 2009, a visit was made to a location of the retailer where the drywall was purchased (note that this is the same retail chain but not the same location where the complainant bought her drywall). Consumer Product Safety Commission credentials and a Notice of Inspection were presented to the manager on duty. In addition to the manger on duty, an assistant manager, the store manager, and a district operations manager were asked about any similar complaints regarding drywall. They were not aware of any similar consumer complaints. One of the product SKUs found on the complainant's purchase receipts (150 pieces of ½" x 4' x 12' drywall) was located in the store and the manufacturer information was recorded. The managers checked the SKU for the water resistant drywall in their computer system. It returned as "item not found" at the store as well as at the store where the incident drywall was purchased. The managers believe this means that the SKU is not likely sold in the region.

# PRODUCT DESCRIPTION / LABELING

#### Drywall (A)

The product is  $\frac{1}{2}$ " x 4' x 12' drywall. The purchase receipt lists the product SKU  $\frac{1}{2}$ (b)(3):CPSA The SKU was located at the retailer and was found to be  $\frac{(b)(3):CPSA}{(b)(3):CPSA}$ .

The product found at the retailer was labeled in part:

(b)(3):CPSA Section 6(b)

(t	)(3):CPSA Section 6(b)	· ·	 	 	
Ma					ļ

150 pieces of drywall were purchased on December 19, 2004, for \$10.12 each from:

Home Depot 2620 Watson Blvd. Warner Robins, GA 31093 (478) 923-4594

SKU 258-377 was found for sale at the following retailer on May 27, 2009:

Home Depot 4635 Presidential Parkway Macon, GA 31206 (478) 477-0266

#### Drywall (B)

The product is  $\frac{1}{2}$ " x 4' x 8' water resistant drywall. No markings were located on the drywall in the incident house. The big found on the purchase receipt was not located in the retailer's computer system. However, the complainant reported that the product was manufactured by (b)(3):CPSA Section 6(b)

22 pieces of drywall were purchased on January 3, 2005, for \$10.29 each from:

Home Depot 2620 Watson Blvd. Warner Robins, GA 31093 (478) 923-4594

Manufacturer:

(b)(3):CPSA Section 6(b)

(b)(3):CPSA Section 6(b)

Cook Top

The incident product is a **Jenn-air** brand cook top, model JEC8536ADF. The electric, smooth surface unit was installed new on November 11, 2004. No further identifying information was provided.

Manufacturer:

Jenn-Air Brand Home Appliances Customer eXperience Center 553 Benson Road Benton Harbor, MI 49022-2692 (800) Jenn-Air www.jennair.com

Heating / Air Conditioning Unit

The incident product is a **Ruud** brand central heating/air conditioning unit. The single outdoor package system was installed during the renovation. The entire unit is located outside of the house. No further identifying information was provided.

Manufacturer:

Ruud 5600 Old Greenwood Road Post Office Box 17010 (72917-7010) Fort Smith, Arkansas 72903 (479) 646-4311 www.ruudac.com

# **ATTACHMENTS**

- Exhibit A List of Respondents
- Exhibit B Photographs (12)
- Exhibit C Purchase Receipt (December 19, 2004)
- Exhibit D Purchase Receipt (January 3, 2005)
- Exhibit E Statement from AC Technician Concerning Odor
- Exhibit F Medical Records 9 Year Old Male (Reflux)
- Exhibit G Medical Records 9 Year Old Male (Diabetes)
- Exhibit H Medical Records 41 Year Old Male
- Exhibit I Heating/Air Service Orders
- Exhibit J Cook top Warranty
- Exhibit K Notice of Inspection
- Exhibit L Release of Name
- Exhibit M Missing Document Form

# LIST OF RESPONDENTS

#### COMPLAINANT

 Adrianna Gantt 1720 Winston Drive Macon, GA 31206 (478) 254-2969 dgantts@cox.net

May 22, 2009

Currently living at:

312 Juniper Lane Macon, GA 31220

# HOSPITAL

 Unknown Representative Medical Records - Release of Information 777 Hemlock St Macon, GA 31201-6884 (478) 633-1067

May 22, 2009

# RETAILER

- Art Wright, Manager on Duty
- Gina Defranco, Assistant Manager
- Calvin Martin, Store Manager
- Mike George, District Operations Manager Home Depot
   4635 Presidential Parkway Macon, GA 31206 (478) 477-0266

May 27, 2009

# PHYSICIAN'S OFFICE

 Maggie (last name unknown) Macon Family Health Center 1051 Pio Nono Avenue Macon, GA 31204 (478) 755-8400 (478) 755-10730 fax

May 27, 2009

HEATING / AIR (contacted by the complainant)

 Adam Guesin, Service manager Air Temperature Control, Inc. 7067 Cochran Field Road Macon, GA 31216 (478) 784-1109

Unknown date in 2005

INSURANCE (contacted by the complainant)

 Mary (last name unknown) Allstate
 4917 Suite-B Mercer University Drive Macon, GA 31210 (478) 474-8785

Early to Mid-May 2009

# Photo 1: View of the incident house.



Photo 2: View of the back of drywall installed in the basement bathroom. No markings of any kind were visible on the drywall.



Photo 3: View of the back of additional drywall installed in the basement bathroom. No markings of any kind were visible on the drywall.



Page 4 of 12

Photo 4: View of the attic space. Insulation around the edge of the plywood flooring was moved aside in several locations but no markings of any kind were visible on the drywall. Note that the wood that forms the roof has been sealed with primer (from the 2004 fire).




Photo 5: View of the attic space. Insulation around the edge of the plywood flooring was moved aside in several locations but no markings of any kind were visible on the drywall. Note that the wood that forms the roof has been sealed with primer (from the 2004 fire).



Photo 6: View of a corroded toilet water supply valve located in a bathroom near the kitchen and living room. No other metal objects in the bathroom showed evidence of pitting, blackening, or corrosion.



Photo 7: View of a mostly uncorroded toilet water supply valve located in a bathroom off of the hallway.





Photo 8: View of exposed copper wires in a living room wall receptacle. The wires did not appear blackened or corroded (the receptacle and wires are speckled with paint).

# Photo 9: View of the replacement cooktop.



Page 10 of 12






# Photo 11: View of the central heating/air conditioning unit (single outdoor package).



Photo 12: View of the 2004 fire damage (scanned photo provided by the complainant). The photo depicts the side of the house and shows the carport/utility room area.





VALIDATION AREA

Exhibit C

090520CBB2638

Store 0163 WARNER ROBINS 2620 WATSON BLVD

WARNER ROBINS, GA 31093

UNE DESVICED OUDIDINER INVUICE

Phone: (478) 923-4594 Salesperson: YML766 Raviewer:

Page 1 of 2

# This is only a $^{\dagger}$ QUOTE for the merchandise and services printed below. This becomes an Agreement upon payment and an endorsement by a Home Depot register validation.

GAN	TT		ADRIANA				(478) 471-868
Aridrés	1720 WINSTON DR.				Worl Phon-	(478) 319-3535	
	·	•• •••••••••••••••••••••••••••••••••••	an tanugan munguna dan kanga tang		Company Name	غ الم	۵. کاللا در این کال
it iy	MACON				, ob Cescoption	REMODEL	99949 I & TITAL DI HANNE DI HAN
Sinte	GA	Ζŗ	31206	County	BIBB		ale 2014 Malalanda - ang

<sup>†</sup>OUOTE is valid for this date: 12/19/2004

			У 4	MERCHANDISE AND SERVICE SUMMARY We	reserve the chandise so	right dd to (	to limit the qua customers.	ntities of
HUIM		DELIVEF	ί¥ #	REF #V08			11/3	
STOCK M	ERCHANDISE	ID BE DELIVERE	D:			Ň	J. J.	
ref #	SKU	ΩΤΥ	UM			, TAX	PRICE EACH	EXTENSION
R01	(b)(3):CP	150.00	ĘA	1/2"X4X12 DRYWALL /WE DO NOT CARRY INSIDE		Ŷ	\$10.12	\$1,518.00
R02	430-684	7.00	ĘĄ	500FT ROLL JOINT TAPE	1	Y	\$2.88	\$20.16
R03	423-629	12.00	Ę٨	1 14X8FT GALV CORNERBEAD EA		Y	\$1.39	\$16.68
R04	370-714	1.00	BX	1-3/8 PC DRYWALL NAIL 30LB BUCKET		Y	\$34.54	\$34.54
R05	258-725	25.00	EA			Ŷ	\$9.99	\$249.75
					I	MERCH	ANDISE TOTAL:	\$1,839.13
DELIVERY	INFORMATIO	N: A t at		SCHEDULED DELIVERY DATE: 12/2 H2004				
V08	515-663	1.00	ξA	CURBSIDE DELIVERY SERVICE		Y	\$55.00	\$55.00
					DELIVER	Y SERI	ICE SUBTOTAL:	\$55.00
							nt≇ t « A = sinds » var senare anvanserer var versie	·····
					+ # #	CONT	NUED ON NEXT I	PAGE ***
			1					
			۲.					
		r v						



1


090520CBB2638

	Page 2 of 2	Page 2 of 5 No	. 0 🐨3-5926
HOME DEPOT DELIVERY #1 REF #V08			
HOME DEPOT WILL DELIVER MOSE TO: GANTT, ADRIANA			1990-1990-1990-1990-1990-1990-1990-1990
ADDRESS: 1720 WINSTON DR.	CITY: MACON	an - randon ( )	
STATE: GA ZIP: 31206 COUNTY: BIBB	SALES TAX RATE: 6.00	00	nan e alter ol angegen and antisanner." Angenanner - der -
PHONE: (478) 471-8684 ALTERNATE PHONE: (478) 319-35	535		annonananananananananananananananananan
		MDSE & DELIVE	RY TOTALS: \$1,894.13
DRIVER SPECIAL INSTRUCTIONS: 175 N GET OFF EISENHOWER EXIT MAKE LEFT OFF EXIT G FIRST LEFT ON KENT SECOND RIGHT ON WINSTON FOURT		EXIT MAKE LEFT AT LIGHT MAKE	
		END OF HOME DEF	POT DELIVERY - REF #V08
TOTAL CHARGES OF ALL MERCHANDISE & SE	RVICES	OR	DERTUTAL \$1,894.13
			SALES TAX \$113.65
			TOTAL \$2,007.78
		BA	LANCE DUE \$2,007.78

END OF ORDER No. 0163-59264

Curbside Deliveries. If You are purchasing merchandise for CURBSIDE DELIVERY only, i.e., Your purchase DOES NOT provide for delivery beyond curbside or for installation/hook-up, YOU ASSUME THE RISK OF, AND THE FULL LIABILITY FOR, ANY RESULTING PERSONAL INJURY, DAMAGE TO PROPERTY, OR DAMAGE TO MERCHANDISF IF YOU REQUEST THAT THE DELIVERY AGENT DELIVER BEYOND CURBSIDE OR PROVIDE INSTALLATION/HOOK-UP.

Roads. The delivery address(es) indicated above must be completely accessible by vehicle over roads rated to handle nine (9) ton loads or heavier. Otherwise. You will be responsible for seeking a waiver, at Your expense, from the appropriate authority. If You are unable to obtain a waiver, delivery will not be available to Your delivery address(es).





SPECIAL SERVICES CUSTOMER INVOICE Store 0135 MACON

2525 PIO NONO AVENUE MACON, GA 31206

Phone: (478) 781-2151 Salesperson: ELE042 Reviewer:

Page 1 of	4	No.	0	135-1		38	5	3	8
-----------	---	-----	---	-------	--	----	---	---	---

VALIDATION AREA

11

 $v_{11}^3$ 

This is only a <sup>1</sup>QUOTE for the merchandise and services printed below. This becomes an Agreement upon payment and an endorsement by a Home Depot register validation.

						home Proce
ITT		ADRIANA				(478) 471-8684
* 1720 WINSTON DR		τ		Work Plice	(478) 319-3535	
				С этраку Name	**************************************	
MACON			•	cob Description	DRYWALL ACC.	and a second
GA	Zş	31206	Семку	BIBB		
	MACON	MACON	MACON	MACON	C impany Name Cob Description Cob Description	Company Name Condescription DRYWALL ACC.

# <sup>1</sup>QUOTE is valid for this date: 01/03/2005

	ICTOME		44	MERCHANDISE AND SERVICE SUMMARY	e reserve the right erchandise sold to	to limit the qu customers.	antities of	
	191 UME	r pickup		REF #W04 SKU #515-664 Customer Pickup / Will Call	Vitop grannes and a second second	AN	<u>.</u>	
STOCK N	ERCHANDISE '	TO BE PICKED U	P:		as V	tt it.		
REF #	SKU	QTY	UM	DESCRIPTION	AT TA	PRICE EACH	EXTENSION	
R01	(b)(3):CP	22.00	EA	1/2IN 4X8 WATER RESISTANT DRYWALL /	VIEW Y	\$10.29	\$226.38	
R02	632-716	12.00	EA	EZ SAND45-LITE ST CMPND 18LB-JLQ120 /	Y	\$8.19	\$98.28	
R03	423-629	20.00	EA	1 1/4X8FT GALV CORNERBEAD-EA	Y	\$1.39	\$27.80	
SCHEDUL	ED PICKUP DA	TE: 01/30/2005		ATT DE	MERCI	ANDISE TOTAL:	\$352.46	
<del>,</del>					END OF CUS	TOMER PICKUP	- REF #W04	
TOT	AL CHAR	GES OF /	ALL	MERCHANDISE & SERVICES				
	· · · ·					ORDER TOTAL	\$352.46	
	SALES TAX \$21.15							
						TOTAL	\$373.61	
<b>18</b> c. <b>78</b> 0,000 darger		••••••••••••••••••••••••••••••••••••••		END OF ORDER No. 0135-138538		BALANCE DUE	\$373.61	
		, and the second se		CHU OF ONDER NO. 0135-138538				
	LL MERCHAND	HSE PICK-UP	re for 7	FOR WILL CALL MERCHANDISE PICK-UP PROCEED TO WILL CALL OR SERVICE DESK ADEA				
		o. 0135		(Pro Customers, Proceed To The Pro Desk)		(0801)		

HAGE 05

090520CBB2638 Exhibit E

At some point in 2005 I made a site visit at 1720 Winston Dr. concerning an ador. To the best of my knowledge I determined it was not coming from the central heat/air system. The odor was in the area around the return going downstairs to basement. alan A I Adam S. Guerin Service Manager Air Temperature Control

Page 1 of 1

(478)784-1109

# The Medical Center of Central Georgia

777 Hemlock Street | Macon, GA 31201 | www.mccg.org Part of Central Georgia Health System

5925 Zebulon Rd., Macon, GA 31210 \* (478) 757-7865

G7280

I have received and understand the instructions in this handout.

Patient/Guardian's Signature Patient's Name: STERLING A GANTT

Caregiver's Signature Caregiver's Name: M (b)(3):CPSA Section 25(c)

Special Instructions: 1. TAKE PRESCRIPTIONS AS DIRECTED 2. INCREASE WATER/FLUID INTAKE 3. AVOID SPICY, HOT AND GREASY FOODS 4. FOLLOWUP WITH DR. BARROSO 5. RETURN TO MED CENTER NORTHWEST AS NEEDED AND/OR CALL US IF ANY QUESTIONS/CONCERNS AT 757-7865

#### Gastroesophageal Reflux in Children

#### WHAT YOU SHOULD KNOW:

- Gastroesophageal (gas-tro-e-sof-uh-g-ull) reflux is also called "GER." It is when the food or stomach acid in the stomach comes back up the esophagus (e-sof-uh-gus). The esophagus is the tube that takes food from the mouth to the stomach. GER is most common in infants (less than 1 year old), but can occur at any age. GER is usually gone by the time a child is 12 to 18 months old. A muscle on the bottom of the esophagus that does not work properly is the cause of GER. If this muscle does not work properly the food or stomach acid can come back up the esophagus.
- Some of the most common problems seen with GER are spitting up, vomiting, crying, coughing, gagging, and heartburn. Your child's caregiver may want to change your child's feeding habits to help the GER. Special medicine may also be needed to help with GER. Proper positioning after feeding may help prevent GER. Ask your child's caregiver

about the best position for your child. Surgery is usually only needed when GER is very serious.

#### AFTER YOU LEAVE:

090520CBB2638 Exhibit F

CareNotes<sup>™</sup> System

#### Your child's medicines are: ZANTAC, TAKE AS DIRECTED .

- Keep a written list of what medicines your child takes and when and why your child takes them. Bring the list of your child's medicines or the pill bottles when you visit your child's caregivers. Ask your child's caregiver for more information about the medicines. Do not give any medicines to your child without first asking your child's caregiver. This includes prescriptions, over-the-counter drugs, vitamins, herbs, or food supplements.
- Always give your child's medicine as directed by caregivers. Call your child's caregiver if you think your child's medicines are not helping. Or if you feel your child is having side effects. Do not quit giving the medicines to your child until you discuss it with your child's caregiver. If your child is taking antibiotics (an-ti-bi-ah-tiks), give them until they are all gone. Even if your child seems to feel better.
- Never give aspirin to your child without first asking your child's caregiver. Giving aspirin to your child when he is ill may cause a very serious illness called Reye's syndrome. Read medicine labels to see if your child's medicine has aspirin.

#### Diet:

- Proper positioning after feeding may help prevent GER. The position your child needs to be in after eating may depend on the age of your child. It may also depend on how bad your child's symptoms are. Some caregivers may suggest placing infants on their back after eating. This is especially true if an infant sleeps after eating. Ask a caregiver about the best position for your infant or child.
- Feed your child more frequently with smaller amounts of food. Adding 1 teaspoon or tablespoon of rice cereal for every 1 ounce of formula can thicken your child's formula. This may help your child keep the formula in the stomach. Talk to your child's caregiver before thickening your child's formula. Hold your child in an upright position during feedings. Burp your child frequently during and after each feeding. Try to feed your child 2 hours before bedtime.
- Do not place your child in a child safety seat (car seat) after feeding your child. Try to avoid putting pressure on your child's tummy after feeding, such as tight diapers.
- Children old enough to eat solid foods, should avoid the following foods or drinks to prevent GER:
  - Chocolate
  - Drinks with caffeine
  - Foods high In acid such as citrus fruits or tomatoes
  - Fried or fatty foods

• Spicy foods

#### CALL DR. BAROSSO IF:

- Your child continues to spit up.
- Your child is irritable or fussy during or after feedings.
- Your child is not eating.
- Your child is not gaining weight normally.
- Your child has a temperature over 101 F ( \_\_\_\_\_ C).
- Your child vomits (throws up) forcefully.
- You have any questions about your child's care, condition, or medicine.

#### SEEK CARE IMMEDIATELY IF:

- The spitting up causes your child to cough or choke.
- Your child spits up blood.
- Your child has trouble breathing.
- 🖀 © 1974-2007 Thomson MICROMEDEX. All rights reserved.

#### GASTROESOPHAGEAL REFLUX IN CHILDREN - Discharge Care, English Printed on Wednesday, August 15, 2007 9:16:03 AM

IPAPCRTANT MOTICE: The examination and treatment you have received is provided on an opisodic basis and is not intended to be a submiture for on an effort to provide complete medical care. It is your responsibility to follow the instructions provided. It is abacour responsibility to follow up with your regular health care provider and/or the health care provided to whom you have been referred. If your condition seems to be worsening on if any new problems occur before your follow up appointment, please refurnimmediately to the Emuryency Center/Urgent Care Center.

Events and other tests done in our Center initially are reviewed by the physician on outy and/or any other non-physician provider who may be involved in patient card. A final official reading will be performed by the appropriate specialist (Radiologist, Pathelogist, ecc.). If the radiologists' or other specialist's reading varies significantly from the initial provider's interpretation, you may be contented and given further instructions, including a possible need fur-further tests or a return visit to the Emergency content-depend care Center.

2.03D DAVDRTAUTE: El examen y tratminato que usted ha recipido son suministrados en forma episódica; la intención nu es de subutur o proveer vullados médicos completos. Su responsionidad es de senur las instrucciones suministradas. También es responsabilidad solvinde contribue el segundiento con su proveedor de sulud y/o con cualquier otro proveador de salud al cual rue el instello, Vuelva de molectato a la sala de energiencia (Emergency/Orgent Care Center) su su condición se empeora o si aparecen cuando aconce misera antes de su próxima cita.

Les radingenties y ount exements reclidos a capo en nuestro tientro son revisidos por ol médico de turno y/o por cualquer otre provente oconceo a los cuidados cel naciente. Un especialista opropiado (radiologo, patólogo) leota los resultados finales del exerción esturenos en contacto con usted si los resultados unales de los radiologos o otros especialistas varian considerablemente en esturenos en contacto con usted si los resultados unales de los radiologos o otros especialistas varian considerablemente en esturenos en contacto con usted si los resultados unales de los radiologos o otros especialistas varian considerablemente en esturendo indexe de provuedos) le naremos informacion unicional, incluvendo la necesidad de nacerso más examenos si ocono o de concerción de secunimento en los salla de emor provina (Emerica d'Onterchurgens Caro Centert)



Exhibit G

#### 

7/10 Pine Street, Soite 360 • Macon, Georgia 31201 • Phone: 478-663-8391 • 5452 478-633-6395

#### FOLLOW-UP CONSULTATION

NANE: Sterling Gantt

005: 08/23/99

OAT 3 OF VISIT: 12/06/07

CHILF COMPLAINT: Diabetes mailitus.

#### PREBENT ILLNESS:

Storling is an 8 year 3 month oic African-American male who was admitted to the Children's Hospital on 10/15/07 with what was thought to be insulin dependent diabetes melli us. At the time of admission he find a blood sugar of 553 a bicarbonate of 21 but only low grade ketones in his unine. He responded very promptly to fluids and insulin. He did have an elevated blood sugar and his Hgb A1C was 12 percent on admission and he was thought to be an early type-1 diabetic. He was sent home on 70/30 NovoLog, 16 units in the moming, 12 units at night. He quickly tapered off on this because of sugars now becoming low. By 10/34/07 he had tapered completely off of insulin. He has remained off all insulin since that time. The family continues to check blood sugars several times a day and they are generally in the 90-120 range. He has no particular new problems and has prefy much resumed his norm all activity. When seen today, he has no new complaints.

#### EXA:#:

Height: 133,8 cm. Weight: 28 tg. Blood pressure: 112/74. Pulse rate: 80. General appearance is that of an adequately sourished young man who does not appear acutely or chronically ill. HEENT, unremarkable. The cranial nerves are intact. PERRLA. He does have areas of depigmentation of the soleration his eyes, which he has had since birth. The tympanic membranes are clear. The pharyox is clear. The neck is supple with no thyromegaly. The ches is clear to auscultation. The hear has a regular rate with no mumur. The abdomen is soft with no organomegaly. Genitalia was not examined. The extremities were otherwise normal. He has normal muscle tonal. He has normal gait and normal mentation. His general neurologic exam is normal and appropriate for age. Hgb A1C: 8.8%, down from his initial level of 12% on admission to the Children's Eospital.

#### ASSESSMENT:

Diabetes mellitus. It is unclear whether this is a true type. He may be a MODY which can present along this type of line. The sugars were high enough and sustained enough with an elevated Hgb A1C, I would not think, his was simply a transient stress hyperglycemia. Finally, he does not have the classic phototype for his age to be associated with a type-2 diabetes. Therefore, MODY, or a simply prolonged honeymoon phase of type-1 would be the most likely eticlogy to explain his course.

#### -

asymptomatic, I would not restart insulin. I told the family I would continue to check sugars about twice a day. As long as they remain in a normal range we will not initiate further therapy. If they begin to elevate, they are to tail the and we will reinstitute insulin therapy appropriately. Page 2 of 3

 $\searrow$ 

Page Two Sterling Gantt

There are genetic probes for MODY. Unfortunately, however, they are so expensive that we are traving problems getting them paid for by the third party payers all this time, but I think these will become available in the not too distant jutare and will be something to check on if he continues with his current course. I discussed this with his family. I will see him back in three months with instructions to call me sooner if the sugars start elevating.

(b)(3):CPSA Section 25(c)

.

~~ '

# PEDRARK ENDOCRYCENTER Page 3 of 3 Con

#### Tradit Garage Att

and a survey of the Marian Approximation (Marian Provide States)

A set of the set o

and the providence of the strength optimized

and the second second

a service a service and the data service and the s

Male

ED08

090520CBB2638 Exhibit H

# THE MEDICAL CENTER OF CENTRAL GEORGIA

DEPARTMENT OF PATHOLOGY AND LABORATORY MEDICINE

777 HEMLOCK STREET,	MACON.	GA 31201
---------------------	--------	----------

Page 1 of 15

#### O. EUGENE BATTLES, M.D. - MEDICAL DIRECTOR

Name: GANTT, CHARLES LAMAR

Med. Rec. #: 098015571

Acct. #: 0980155718329

Age: 41 years Loc: EDFT Dr.: (b)(3):CPSA Section 25(c) Sex: Room:

Printed: 5/28/2009 4:04:35 PM

		COMPLET	E BLOOD COUN	T AND I	DIFFERENTIAL
Day Date Time	0 11/24/2008 18:29:00				
Procedure WBC RBC HGB HCT MCV MCH MCHC RDW PLT MPV Auto NRBC Diff? Auto PMN Auto Lymph Auto Lymph Auto Mono Auto Eos	4.39 4.93 14,9 44.1 89.5 30.3 33.8 13.1 190 8.3 0 Auto Diff 46 39 14 H 1	Ref Range [3.07-11.77] [4.28-5.48] [12.9-16.9] [38.7-49.1] [81.1-98.4] [27.2-34.0] [32.2-35.9] [10.4-13.9] [129-355] [7.4-11.4] [40-80] [15-40] [0-10] [0-7]	Units K/mm3 m/mm3 gm% % fL UUG % % K/mm3 fL % %		
Auto Baso	0	[0-2]	% URINAL	<u></u>	
	Day Date Time	0 t 1/24/2008 20:30:00			
Procedu UA Color UA Character UA SpGr UA pH UA Protein UA Gluc UA Ketones UA Bilirubin UA Blood	lre	YELLOW CLEAR 1.009 7.5 NEGATIVE NEGATIVE NEGATIVE NEGATIVE SMALL	Ref Range [1.00]-1.035] [5.0-8.0]	Units mg/dL mg/dL mg/dL	
					NAME:GANTT, CHARLES LAMAR         ROOM:ED08           MED_REC: 098015571         ACCT #:0980155718329           DF(b)(3):CPSA Section 25(c)

**I LAB RESULTS** 

Page 1 of 4

090520CBB2638 Exhibit H

Page 2 of 15

# THE MEDICAL CENTER OF CENTRAL GEORGIA

DEPARTMENT OF PATHOLOGY AND LABORATORY MEDICINE

## 777 HEMLOCK STREET, MACON, GA 31201

O. EUGENE BATTLES, M.D. - MEDICAL DIRECTOR

1

÷

Name: GANTT, CHARLES LAMAR Med. Rec. #: 098015571 Acct. #: 0980155718329	Age: 41 years Loc.: EDFT Dr.: (b)(3):CPSA Section 25(c)	Sex: Male Room: ED08
	Printed: 5/28/2009 4:0	)4:3 <u>5 PM</u>

		URINAL	/SIS	
Day Date	0 11/24/2008			:
Time	20:30:00			i
Procedure		Ref Range	Units	•
UA Urob	0.2	[0.0-1.0]		•
UA Nitrite	NEGATIVE			
UA Leukocyte Esterase 1	NEGATIVE			
UA WBC	0	[0-4]	/hpf	
UA RBC	1	[0-4]	/hpf	•
UA Squamous Epi Cells	0	[0-3]	/hpf	:
UA Bacteria	NEG		,	
Hyaline Cast	0	[0-7]	/lpf	
Microscopic?	Urinalysis with Micro		,	
				•

11/24/2008 20:30:00 UA Leukocyte Esterase:

Cephalexin, Gentamicin and high levels of Albumin (>500 mg/dl) may interfere with Leukocyte Esterase reaction.

#### **GENERAL CHEMISTRY PANEL**

	Day Date	0 11/24/2008		
	Time	18:29:00		
Procedure			Ref Range	Units
NA		143	[135-145]	mEq/L
к		3.5	[3.5-5.0]	mEq/L
Chloride		103	[99-109]	mEq/L
CO2		32	[22-32]	mmol/L
AGAP		8	[3-[1]	mEq/L
Glucose Level I		113 H	[70-99]	mg/dL
BUN		14	[5-22]	mg/dL
Creatinine		1.2	[0.5-1.4]	mg/dL
Bun/Creat Ratio		31.7	[8.0-20.0]	Ratio
GFR if African American		>60		
GFR if Non-African Americ	an I	>60		

NAME GANTT, CHARLES LAMAR	ROOM: ED08
MED. REC.:098015571	
ACCT #:0980155718329	
DR (b)(3):CPSA Section 25(c)	

#### I LAB RESULT

#### Page 2 of 4

05/18/2009 04:23 090520CBB2638 Exhibit H	14784718684	Page	GANTT 3 of 15		PAGE
	MEDICAL			CENTRAL	GEORGIA
DI					
			•	ACON, GA 31201 MEDICAL DIREC	
Name: GANTT, CHA Med. Rec. #; 098015 Acct. #: 0980155718			Age: Loc.: Dr.:	<b>41 years</b> (b)(3):CPSA Section 25(c)	Sex: Male Room: ED08
				1	J09 4:04:35 PM
Calcium	9.4	[8.5-10.2]	mg/dL		
	GI		IEMIST		
<u></u>	Day 0				
	Date 11/24/2008 Time 18:29:00				
Procedure MG		Ref Range	Units ma/dt		
СРК	2.2 134	[1.7-2.5] [39-195]	mg/dL Units/L		
11/24/2008 18:29:00 Glud Normals are for fasting sp The critical limit for outpa	ecimens.	mg/dl.			
11/24/2008 18:29:00 GFR GFR Normal Ranges (Afr			can):		
AGE	Average GFR Resu	lt ml/min/1.73m	2		
18 - 29 yrs 30 - 39 yrs	116				
40 - 49 yrs	107 99				
50 - 59 yrs 60 - 69 yrs	93 85				
70 - 150 yrs GFR is not calculated for	75 ages less than 18 years				
		CARDIA		(EDC	
	· · · ·	CARDIA			
Day 0 Date 11/24/200 Time 18:29:00					
Procedure Troponin 11 0.02	•	Units g/mL			
СКМВ 2.0 СРК 134	[0.6-6.3] r	ig/mL Inits/L			
RINX I I.5		Index			

NAME:GANTT, CHARLES LAMAR	ROOM: ED08
MED. REC.:098015571	
ACCT #:0980155718329	
DR. (b)(3):CPSA Section 25(c)	
Pao	e 3 of 4

I LAB RESULT

090520CBB2638 Exhibit H

Page 4 of 15

# THE MEDICAL CENTER OF CENTRAL GEORGIA

DEPARTMENT OF PATHOLOGY AND LABORATORY MEDICINE

# 777 HEMLOCK STREET, MACON, GA 31201

#### O. EUGENE BATTLES, M.D. - MEDICAL DIRECTOR Age:

Dr.:

Name: GANTT, CHARLES LAMAR Med. Rec. #: 098015571 Acct. #: 0980155718329

41 years EDFT (b)(3):CPSA Section 25(c) Loc.:

Sex: Room:

Male ED08

Printed: 5/28/2009 4:04:35 PM

#### CARDIAC MARKERS 11/24/2008 18:29:00 Troponin I: Troponin I interpretative ranges: (ng/ml) 99th % for normal population: 0.0 - 0.05 Myocardial injury: > = 0.10Optimal ami cutoff: >/= 0.50 11/24/2008 18:29:00 RINX: CK-MB RELATIVE NG/ML INDEX (0-5.0)(0-2.1)Interpretation Normal Normal Normal NormaL Nonspecific vs Normal Increased Increased Normal or Not Calculated Indeterminate Myocardial vs Skeletal Origin Increased Increased Probable Myocardial Origin

Note: Relative Index is not calculated if Total CPK is <80 U/L.

NAME GANTT, CHARLES LAMAR	ROOM: ED08
MED. REC.:098015571	
ACC (b)(3):CPSA Section 25(c)	
DR.: (5)(0):01 07 000101 20(0)	
	·····

I LAB RESULT

#### Page 4 of 4

GANTT, CHARLES LAMAR - 098015571

!

090520CBB2638 Exhibit H

Page 5 of 15

# Emergency Center Dictation \* Final Report \* Medical Center of Central Georgia

Result Type:Emergency Center DictationResult Date:November 24, 2008 6:08 PMResult Status:Auth (Verified)Result Title:FCPerformed By:(b)(3):CPSA Section 25(c)Encounter info:0980155718329, MCCG, Emergency Room, 11/24/2008 - 11/24/2008

#### \* Final Report \*

EĈ

EMERGENCY CENTER DICTATION

Document Number: 2122693 Encounter Number: 980155718329

CHIEF COMPLAINT:

HISTORY OF PRESENT ILLNESS: The patient is a 40-year-old male who started having some cramping in his hand and then started with cramping in his legs, later felt some cramping in his chest, sharp in nature, and it resolved, still having some cramps in the right leg. The patient is going to nursing school.

FAMILY HISTORY: Per the patient there is coronary artery disease in his father.

SOCIAL HISTORY: Does not smoke or drink. No drugs.

REVIEW OF SYSTEMS: CONSTITUTIONAL: No fever or chills. HEENT: No sore throat, no earache. CARDIOVASCULAR SYSTEM: Sharp pain in the chest. RESPIRATORY SYSTEM: No shortness of breath. GASTROINTESTINAL SYSTEM: No abdominal pain. NEUROLOGIC: No headache, no syncope. PSYCHIATRIC HISTORY: None. DERMATOLOGIC: No rash. MUSCULOSKELETAL: Cramping in all extremities.

ALLERGIES: NONE,

MEDICATIONS: None.

PHYSICAL EXAMINATION: General appearance: The patient appears to be anxious, with reassurance started calming down. Vital Signs: Temperature 96.8, pulse 79, respirations 16, blood pressure 115/21, pulse oximetry 100% on room air normal saturation. Page 6 of 15

#### Exhibit H Operative Report

GANTT, CHARLES LAMAR - 098015571

\* Final Report \*

Medical Center of Central Georgia

and 70-degree lens with completely cystoscopy. No mass, lesions or filling defects. There are a couple of air bubbles noted on retrogrades but no masses or significant stones.

#### **OPERATIVE NOTE**

The patient was taken back to the operative suite, placed in the supine position. Once anesthesia was initiated, the patient was adequately sedated. He was then placed in lithotomy position, making sure to pad all pressure points.

He was prepped and draped in standard surgical fashion.

We entered the ureteral meatus with a 2I-French rigid cystoscope. A penile urethra and prostatic urethra appeared without abnormalities. Slightly high bladder neck but minimal prostatic hypertrophy. Entered the bladder, visualized both ureteral orifices with clear efflux and did a complete cystoscopy with both 30-degree and 70-degree lenses, appreciating normal mucosa without any mass, lesions or stones.

We then performed retrograde pyelogram with a cone-tip catheter. Retrograde on the left side showed normal delicate ureter and collecting system. No mass, lesion or stone. A few small air bubbles were noted on retrograde.

Then, we performed a retrograde on the right side again with the cone-tip catheter injected with contrast. The distal was \_\_\_\_\_ no mass, filling, no hydronephrosis or hydroureter. The kidney itself showed a delicate system with normal calices and normal collecting system. No abnormalities.

The patient's bladder was drained. We then placed the Uro-jet pre-urethra and the patient tolerated it well.

(b)(3):CPSA Section 25(c)

Printed by: Atkinson , Letrice Printed on: 5/28/2009 3:55 PM Page 2 of 3 (Continued)

Exhibit H **Operative Report** 

090520CBB2638

Page 7 of 15 GANTT, CHARLES LAMAR - 098015571

\* Final Report \*

Medical Center of Central Georgia

#### **Completed Action List:**

\* Perform by(b) D , Frank on September 25, 2008 12:06 PM

\* Transcribe (3):CPS\_INKNOWN, PERSONNEL on September 25, 2008 9:29 PM

Printed by: Atkinson , Letrice Printed on: 5/28/2009 3:55 PM

Page 3 of 3 (End of Report)

090520CBB2638 Exhibit H Surgery Retrograde Pyelogram

#### Page 8 of 15 GANTT, CHARLES LAMAR - 098015571

\* Final Report \*

Medical Center of Central Georgia

Surgery Retrograde Pyelogram Result Type: **Result Date:** September 25, 2008 12:05 PM Result Status: Auth (Verified) Result Title: Surgerv Retrograde Pyelogram Performed By: (b)(3):CPSA n September 25, 2008 1:53 PM Section 25(c) Jn September 25, 2008 2:29 PM Verified By: 0980155718254, MCCG, Outpatient Surgery, 9/25/2008 - 9/25/2008 Encounter info:

#### \* Final Report \*

Reason For Exam

hematuria

#### Surgery Retrograde Pyelogram

History: Hematuria.

#### Retrograde pyelogram, 9/25/2008.

The preliminary film reveals no definite renal calcification. The film #1 reveals retrograde injection of contrast into the left collecting system with a few filling defects seen in the proximal left ureter which may represent air bubbles. The film labeled #3 reveals retrograde injection of contrast into the right collecting system with no definite filling defects seen. There was a filling defect seen in the right renal pelvis on film #4 which is probably an air bubble. The study is felt to be essentially negative.

(b)(3):CPSA Section 25 Signed By<sup>(C)</sup>

Transcribed By: Campbell, Reiko

#### **Completed Action List:**

- \* Order by Casey MD , Frank on September 25, 2008 11:42 AM
- \* Perform by Jimerson, Julia E on September 25, 2008 12:05 PM
- \* VERIFY by Hall MD, Lee H on September 25, 2008 2:29 PM

Printed by: Atkinson , Letrice Printed on: 5/28/2009 3:55 PM Page 1 of 1 (End of Report) 090520CBB2638 Exhibit H

# Page 9 of 15

THE MEDICAL CENTER OF CENTRAL GEORGIA DEPARTMENT OF PATHOLOGY AND LABORATORY MEDICINE

		-
777 HEML	OCK STREET, MACON, GA 31201	

#### O. EUGENE BATTLES, M.D. - MEDICAL DIRECTOR

Name: GANTT, CHARLES LAMAR

Med. Rec. #: 098015571

Acct. #: 0980155718254

Age: 41 years Loc: (b)(3):CPSA Section 25 Dr.:

(c)

Male Sex:

Room:

Printed: 5/28/2009 4:04:52 PM

#### COMPLETE BLOOD COUNT AND DIFFERENTIAL

Day	-1
Date	09/23/2008
Time	10:45:00

Procedure		Ref Range	Units
WBC	3.57	[3.07-11.77]	K/mm3
RBC	4.71	[4.28-5.48]	m/mm3
HGB	14.2	[12.9-16.9]	gm%
HCT	42.2	[38.7-49.1]	%
MCV	89.6	[81.1-98.4]	fL
MCH	3 <b>0</b> .1	[27.2-34.0]	UUG
MCHC	33.6	[32.2-35.9]	%
RDW	13.0	[10.4-13.9]	%
PLT	174	[129-355]	K/mm3
MPV	8.5	[7.4-11.4]	fL
Auto NRBC	0		%
Diff?	Auto Diff		
Auto PMN	53	[40-80]	%
Auto Lymph	33	[15-40]	%
Auto Mono	11 H	[0-10]	%
Auto Eos	3	[0-7]	%
Auto Baso	0	[0-2]	%

09/23/2008 10:45:00 CBC w/ Auto Diff: Special Instructions: PreOp, DOS

#### GENERAL CHEMISTRY PANEL Day - I 9/23/2008 Date Time 10:45:00 Procedure Ref Range Units NA 142 [135-145] mEq/L ĸ 4.1 [3.5-5.0] mEq/L Chloride 105 [99-109] mEq/L NAME: GANTT, CHARLES LAMAR ROOM: MED REC: 098015571 ACCT # 0980155718254 (b)(3):CPSA Section 25(c)

#### **ILAB RESULTS**

Page 1 of 3

#### Page 10 of 15 THE MEDICAL CENTER OF CENTRAL GEORGIA

DEPARTMENT OF PATHOLOGY AND LABORATORY MEDICINE

777 HEMLOCK STREET, N	MACON. GA 31201
-----------------------	-----------------

#### O. EUGENE BATTLES, M.D. - MEDICAL DIRECTOR

GANTT, CHARLES LAMAR Name: Med. Rec. #: 098015571

Age: 41 years Loc.: (b)(3):CPSA Section Dr.: 25(c)

Sex: Male Room:

Acct. #: 0980155718254

090520CBB2638 Exhibit H

Printed: 0/28/2009 4:04:52 PM

#### **GENERAL CHEMISTRY PANEL**

Day	-1
Date	9/23/2008
Time	10:45:00

Procedure		Ref Range	Units
CO2	31	[22-32]	mmol/L
AGAP	6	[3-11]	mEq/L
Glucose Level I	89	[70-99]	mg/dL
BUN	14	[5-22]	mg/dL
Creatinine	1.1	[0.5-1.4]	mg/dL
Bun/Creat Ratio	12.7	[8.0-20.0]	Ratio
GFR if African American	>60		
GFR if Non-African American I	>60		
Total Protein - Serum	7.0	[6.2 <b>-8</b> .0]	g/dL
Albumin - Serum	4.0	[3.5-5.0]	g/dL
A/G Ratio	1.3	[1.2-3.1]	Ratio
Calcium	9.2	<b>[8</b> .5-10.2]	mg/dL
Corr Calcium I	9.20	[8.50-10.20]	mg/dL
Total Bilirubin	0.8	[0.2-1.3]	mg/dL
Alk Phos	58	[30-11 <b>2</b> ]	Units/L
AST/GOT	30	[15-38]	Units/L
ALT/GPT	22	[5-37]	Units/L

09/23/2008 10:45:00 Glucose Level:

Normals are for fasting specimens.

The critical limit for outpatient specimens is <40 mg/dl.

09/23/2008 10:45:00 GFR if Non-African American: GFR Normal Ranges (African American and NonAfrican American):

AGE Av	rage GFR Result ml/min/1.73m2
--------	-------------------------------

18 - 29 yrs	116
30 • 39 yrs	107
40 - 49 yrs	99
50 - 59 yrs	<b>9</b> 3
60 - 69 yrs	85
70 - 150 yrs	75

GFR is not calculated for ages less than 18 years.

NAME: GANTT, CHARLE	5 LAMAR	ROOM:	
MED. REC.:098015571			
ACCT + 0090155718254 DR (b)(3):CPSA			
Section 25(c)			<u> </u>

I LAB RESULT

090520CBB2638

Page 11 of 15

#### Exhibit H THE MEDICAL CENTER OF CENTRAL GEORGIA DEPARTMENT OF PATHOLOGY AND LABORATORY MEDICINE

777 HEMLOCK STREET, MACON, GA 31201

### O. EUGENE BATTLES, M.D. - MEDICAL DIRECTOR

Dr.:

Name: GANTT, CHARLES LAMAR Med. Rec. #: 098015571 Acct. #: 0980155718254

Age: 41 years (b)(3):CPSA Section 25(c) Loc.:

Sex: Male

Room:

1:04:52 PM

#### **GENERAL CHEMISTRY PANEL**

09/23/2008 10:45:00 Corr Calcium:

Corrected Calcium is Total Calcium adjusted for the deviation of Albumin from Normal, using the formula:

Corrected Calcium = Total Calcium + 0.8 (4.0 - Albumin).

09/23/2008 10:45:00 Chem 14: Special Instructions: (G) PreOp, DOS

NAME: GANTT, CHARLES LAMAP	ROOM;
MED. REC.:098015571	
A(b)(3):CPSA	
Section 25(c)	

I LAB RESULT

Page 3 of 3

05/18/2009 04:23 14784718684

090520CBB2638

Exhibit H

GANTT

Page 12 of 15

Emergency Center Dictation

GANTT, CHARLES LAMAR - 098015571

\* Final Report \*

Medical Center of Central Georgia

HEENT: Pupils are round and reactive to light. Nostrils, pharynx and TMs normal. NECK: Supple. Trachea in the midline. No jugular venous distention. CHEST: Chest wall nontender. CARDIOVASCULAR SYSTEM: Regular heart sounds. No murmur. No gallop. RESPIRATORY SYSTEM: Clear. No rales, no rhonchi. No wheezing. ABDOMEN: Soft, nontender. No guarding. No rebound tenderness. EXTREMITIES: No edema, No phiebitis. Distal pulses felt well. NEUROLOGIC: Cranial nerves intact. Sensory and motor normal. Reflexes hyperreflexic plantar withdrawal. PSYCHIATRIC: Is oriented to place, person and time. No suicidal or homicidal thoughts.

INTERPRETATIONS:

LABORATORY DATA: CPK 134, CK-MB is 2.0, troponin 0.02, WBC 4300, hemoglobin 14, hematocrit 41. Urine sodium 143, potassium 3.5, glucose 113, BUN 40, creatinine 1.2, magnesium 2.2, calcium 9.4.

ED COURSE/PROCEDURES: The patient is being observed in the emergency room, administered IV fluids. The patient is being observed in the emergency room, resting comfortable. The patient is asymptomatic.

DISPOSITION: Pending.

(b)(3):CPSA Section 25(c)

Report Dictate Dictator Status

(b)(3):CPSA Section 25(c)

**Completed Action List:** 

Printed by: Atkinson , Letrice Printed on: 5/28/2009 3:54 PM Page 2 of 3 (Continued)

05/18/2009 04:23 14784718684 090520CBB2638

Emergency Center Dictation

GANTT, CHARLES LAMAR - 098015571

\* Final Report \*

Exhibit H

Medical Center of Central Georgia

\* Perform t (b)(3):CPSA Section 25(c) ember 24, 2008 8:54 PM

\* Transcribe by MW -UNKNOWN, PERSONNEL on November 25, 2008 3:07 PM

Printed by: Atkinson , Letrice Printed on: 5/28/2009 3:54 PM Page 3 of 3 (End of Report)

Exhibit H Port Chest Routine

090520CBB2638

Page 14 of 15 GANTT, CHARLES LAMAR - 098015571

\* Final Report \*

Medical Center of Central Georgia

Result Type: **Result Date: Result Status:** Result Title: Performed By: Verified By: Encounter info:

Port Chest Routine November 24, 2008 9:02 PM Auth (Verified) Chest Routine Port (b)(3):CPSA Section 25(c) November 25, 2008 8:44 AM November 25, 2008 1:25 PM оэротроттозда, мосса, Entergency Room, 11/24/2008 - 11/24/2008

# \* Final Report \*

#### Reason For Exam Chest Pain

#### Port Chest Portable chest

History: Chest pain

One view reveals the heart, great vessels, pulmonary vasculature and mediastinum are normal. The lungs are clear. There are no significant osseous abnormalities.

IMPRESSION: Normal chest.

(b)(3):CPSA Section 25(c) Signed

Transcribed By: Reeves, Gloria

- Completed Action List: \* Order by (<sup>(b)(3)</sup>:CPSA Section 25(c)
- \* Perform b

\* VERIFY b

ovember 24, 2008 8:48 PM 8 9:02 PM nber 25, 2008 1:25 PM

Printed by: Atkinson , Letrice Printed on: 5/28/2009 3:54 PM

Page 1 of 1 (End of Report)

Page 15 of 15

#### Exhibit H Operative Report

090520CBB2638

GANTT, CHARLES LAMAR - 098015571

\* Final Report \*

Medical Center of Central Georgia

Result Type:Operative ReportResult Date:September 25, 2008 8:33 AMResult Status:Auth (Verified)Result Title:OPPerformed By:(b)(3):CPSAEncounter info:Op(3):CPSA, MCCG, Outpatient Surgery, 9/25/2008 - 9/25/2008

## \* Final Report \*

OP Document Number: 2089364 Encounter Number: 980155718254

PROCEDURE DATE: 09/25/2008

PREOPERATIVE DIAGNOSIS Microscopic hematuria,

POSTOPERATIVE DIAGNOSIS Microscopic hematuria.

PROCEDURE Cystoscopy and retrograde pyelograms.

SURGEON Dr. Frank Casey.

ANESTHESIA GET.

INTRAVENOUS FLUIDS Per Anesthesia.

ESTIMATED BLOOD LOSS None.

COMPLICATIONS None.

SPECIMENS None.

FINDINGS

Normal \_\_\_\_\_ pyelograms bilaterally, normal cystoscopy with both 30-degree

Printed by: Atkinson , Letrice Printed on: 5/28/2009 3:55 PM Page 1 of 3 (Continued)

090520CBB2638 Exhibit I 777847524

Page 1 of 3

			a.		RVICE		(INIVALO
					FRUCEU	IRUEN	INVOICE
		teris por l'instal Production de la company accordent de <b>l'accord</b>					
		and the second secon			in the second		
		44. J					
		e le ra			THIS WORK IS TO BE	the Strate Constraints	CALL AND
J	BILL TO					CHARGE	
	Il't's Gent				MAKE 0	MAKE	
	1770 41. 1	n			MOJEL		
	110 Winsten	<u>Ul</u> .			Land		
	Macan I.A.	27106			Serial humber	SCRIAL N	
NAME		and the second second		and the second	Restricted and second	ap an an a state of the second	
					TAL CHECK LIST	WORK	PERFORMED
STPEET			1-41-65	VTO DEMRURRER OTV	TYPEDISPOSITION	CONDENSING UN	T CONDIGATE DRAINS
GITY	her en skrie de mekken komme ombereken. Hen er en skrifter de men mensemmen andere en societ e societ		CHARES	T RECOVERED		LEVELED	I DEDARES
PHONE	CA.1.1	REFORE	E + 58	TO RECYCLED	a na di sama na sanga na ganaran na santan te sering d	CLEANED CON	I MAIN DEAR
	***************************************			T D RECLAMED		JIAROL	SLEANES PAN SEAL REPAILOS PAN ORIAN
TECHN	LAN AUTHO	F1760 6V		DISPOSAL		HERARS	FURN OR FAN EG L
WCRK T	O BE PERFORMED	n tanahy dalaya int spiller a gen white or on you	<u> </u>		TOTAL S	i hef	HERMALED BELT
	ALTINALS & DECURCES			I C O'SMANTLEL		10128	· + ;+US7E12 948_1
QTY.	MATERIALS & SERVICES	UNIT PRICE	AMOUNT	DESCRIPTION OF	WORK PERFORMED	HANGES HERE	HEALAGED PLLLEY
	PEFRIGERANT A. L89			In al der	Thursday	ABELACEO ABE.	CLEANED
	an a			entrin Martin Halland H	/ www.	ACAURTED BEJT	AEPLACED
· · · · · · · · ·				- made to the fact	Konner Lake &	SONTATION	BEARWING ON BE WINDS
		8		· + / cenes las	E lait	AE A	LOKEDBEARINGS
				wes and	man and for	AEVLACED AVA	CIEANED VENTEX'N
<b>.</b>	nya manya mini magangané nya kangané na mini kang ang mgangané katalah kangahamanan pang dinakaké dé kanaly	••••			<u>na na selektetetetetetetetetetetetetetetetetete</u>	KOL CONTROTOR	PEPLACED
	analar barang mega melantak talah dalam kan den den menanggan tak sebatah katalah menan			The west	- Wald sign	- REFAIRBO	CLEANED CA
			·	under the	Lower	REPLACED FUSE	THERMOCCUPLE
				Collect in	11 011 160	COMPRESS I	REAMAEL VALVE MEMACED
	and a second	T		1 J. 1	t a strand a so	EVAPOHATOR COL	- VALVE
	an ann an an an ann an ann an an ann an	• • • • • • • • • • • • • • • • • • •	• · · · · • • • • • • • • • • • • • • •	hard in the	be purtage	ADJUSTED	D.C.
	الله الله الله الله الله الله الله الله			un tord	w. isd	ASPLACED GAP TURE	REMINST
	FATERS K A			Heat an	Licar.	CLEANED CAP YOR	ALULIU (EC.
	OLTEAS X X				a constant.	REPAIRED	THEMMOS AT
<i>i</i>	66.35		·	appending_	peter Ely-		AERACES
i			······		a bina a bina kang mga mga mga mga mga mga mga mga mga mg	CLEANED CON	CJUSTEC
	مىرىيا سىكىلىكى <mark>بولىرانىكار سىز 10 يىلىنىڭ بىرىنىڭ بىرىنىڭ م</mark> ىرىنىڭ قارىلىلىنىڭ 10 يارىنىڭ 10 يىرىنىڭ 10 يوپ بىر	MATERIALS				ELECT. FIR	CL3 TOWER
HRS.	LABOR	RATE	AMOUNT	RECOMME	NOATIONS	ARPLACED LINE	CLEANED !
	an a		1			REPUBLIES HUM	
	۲۰۰۰ ۲۰۰۰ ۲۰۰۰ ۲۰۰۰ ۲۰۰۰ ۲۰۰۰ ۲۰۰۰ ۲۰۰	~				STRUCED WIPE	FUMP(S)
	an ann a bhair a san an Star ann an Star an Star an Star an Star an Star ann an Star an Star an Star an Star an					ASHARED CONT	, OPEASEL
	وروا المحلف المحلف المحلوم والمحلوم المحلول والمحلول والمحلول والمحلول والمحلول والمحلول والمحلول والمحلول والم			······································		FL16R5 [][	AEAKARE Ante (C Refused)
	TO	TAL LABOR		LIMITED WARRANTY		an 1999 ( 1996 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 19 1	,
TERM	S		د. با الأكسينيونيوني با ا ا	and equipment are manufacturers' or sup-	warrented by the olieis' written warranty		SUMMARY
	ck 1369	- 6		only. As labor performe	to by the acove hamed		
		13-05		Dipervise indicated in	writing The above	MATEGIALS TOTAL	arian in cristian commerce
i 44 :	rear be as a refer. the awar a chime	· · · · · · · · · · · · · · · · · · ·		named company make express or implied,	and is agents of	LABOR	,
aligika - 1930 1947 - 1949 1948 - 1957 - 1949 1949 - 1957 - 1949	a and the state of the second control of the second state of the	ακαι ταμβλαρβοτικό υξηξι Μι τι προσφαία Γιακα Και μιαρατικά Πιτη ζαμπ	end i synar (ns. Heri i Heri Heri Øgs sen Heri i skal	techniciana are not au	ithonized to make any shalf of above named	: دېمو د دېږې د روه وروي و او وو وو وو.	· · · · · · · · · · · · · · · · · · ·
1.0 1 10	n anall sur an shu muarran in talay.			company		TRAVEL CHARGE	
	an Marin		1	C. REGULAR		ΤΑλ	n internetienen mitten gipt is sit Bernhetet fan an ein hereinen
*	Minana VET			SERVICE UNITIACT	i. Vari		
UNETONII NINNETONII	un gerup yang menungka peringkan di kana dari kana La dari kana	3 IAC	) 	ារកខ្លា	k You	TOTAL	75 60

Ũ÷.	02712385 86128 478 090520CBB2638 Exhibit I	7847324		Pa	ge 2 of 3	(BOFIN:		Pa(	9 <b>E</b> 00
				7	an a		14.4 A.N		
					SE	RVICE O	RDE	ER//	NVOI
-		and a second					ana an	NHUMER	Constant States and Sta
8. j.,					$F_{1},F_{2},H_{2}$		5 1 1 1		a second
		- San Start					Sector Sec		W Providence
50. V.			13 A			an dan dari dari dari dari dari dari dari dari		<b>WAR</b>	
1944 (1957) 1944 - 1944 1947 - 1944				13 A.		THIS WOPK IS TO BE		111	
	BILL TO	- n				□ <b>c.c</b> .p. □	CHARGE		C NO CHARGE
- 19 jan	Maldiana G	ognitt		• • • • • • • • • • • • • • • • •		Surp.	M	ANE	
1	1990 (720 L	l'aston	12			NODEL		OUEL	
1935) 	1.					HUT RE	dd d Al	EHLAL NUM	BER
	Macon 6A.					······································			·····
NAVE	AN ART I THE AND AN AND AN AREA AND AND AND AND AREA AND AND A	and the second		ii au	ENVIRONMENT				RFORMED
STREET	The second se		A E		WORK PERFORMEL OT 1	TYPE/DISPOSITICK	OCNDEN		CONDISATE DR
	SAMO E.		11316	<u>(.</u>	- C RECOVERSO		EVRIED		DLEANED MAN DALES
C.TY		7	PSCPATIONE C		C REOVOLED		SLEANER 32		REMARED VAIN SREP.
P-10NE	785-1377	14 719 - R	5 -7	è?		مى يىلى بىلى بىلى بىلى بىلى بىلى بىلى بىل	SHARE		SLEANED BAN DRAIN
TECHN		1# 319-3 HOFIZED BY			RETURNED		APMAED EAK A STR. REAK A STR.		HEANNES FAN DRAN
	TREAT ANUMER				CISPOSAL	1	SAK IN COPI		PURN OR FAN
WORK :	to be performed No MEAT				COSMANTLEC	TOTEL S	DHEDREU DHEDREU NOTCH		ADJUSTED SELT
QTY.	MATERIALS & SERVICES	UNIT PRICE	AMOL	INT	DESCRIPTION OF W	ORK PERFORMED	GIANGED WORCH		AGPLACED
				T	Trada and	za set se	HERLACED BELT		ADJUSTEC PULLEY
					HENT MAY	yil dig	ACALETEC .		CLEANED
	† 1997 : Marine			। ∲	Cit, MAS	H UNHAGE	ACTOR CHE	: 	BEARINGS
1	RETARY				(delea) Shee	sch flee	AEPL START		OLEO BEADINGE
1	DUBAL G. A.L.			1	Theonestate	aceds	DANDITOR HEPLACED 9	<u>x</u>	CLEANED HEATEZCH
	S. T.HADW			+	· · · · · · · · · · · · · · · · · · ·		HEPLACED PL CARLINGH S.EARD CR AD CONTACT		REPLACED NEXT DICH
	2. Inter				1	112-11	HIPMINED WINNO		CLEANED LR
				: {	LINRGER TR	ANS/ CRIMEIS	AEPGADED FL		THERMCCCUSLE
	I		;	[ [	Also und.	A TRilled	EVAPORA	, and the state of	REPLACED
				1	HEAH RELAY	. Acplaced			CLEANFO SLEANFO
			, 				REPUACED EXP. WALVE ADJUSTED EXP. WALVE		DUCT
				<b>.</b>	Shit At Ligy 1	CHETHE T	CAP TURE		REPA ARC
	FRITERS A F				L'appendie K S	16	EN AND		ACUUSTED
	FILTERS X X		:		TURYLIE RO	UNIRS.	ACAN RED COLLEAK INTERED COMPLET GON	a 199 199	THERMOSTA
	BELTS		· · ··································		1 1		COMPLA GON		ADJUSTED
	TOTAL	MATERIALS	•				LEVIS EC CON		
				L			ELECT	H"R	CI.G TOWER
HRS	LABOR	RATE	L AMOU		RECOMME	NUATIONS	REPLACED LIN		CLEMEL
	Dingastic	144 25	4 44	75	- -		REPLACED KL		PUMP(S)
	•		1	ĺ			REPARED SO		OREASED
}	n na sean an an ann an ann an ann an ann an ann an a		ļ			****			REMAID
·	, Any <u>an and a set of the start and the set of the set</u>		÷		4		PILTERS	CLEAN	eg 🗋 replate
	······································	OTAL LABOR	L		LIMITED WARRANTY: - 640 BOURDARL BIG		1 T	OTAL SI	JMMARY
TERM	18 PALL OFFICE	<b>E</b>			i manufacturers' or eupp ; only, All labor performance	f by the edove herned	T	DTAL	
					dherwise successes in	sor 3C days o⊨ a∉	MATER	IALS	
	On ABUCE				named company makes	s no other warranties.		DTAL BOR	1
Sector rehe	heine iste in ensligeneenstereetere sutrepise ("sute drei-	beer extenses of the out	en:1001 16 0.01	742-5	express or implied rechnicians are not ap	thorized to make any			المراجعة (1999) - 1990 - 1990 - 1990 - 1990 - 1990 1 1 1 1 1
48 19,7940 4810 (417:04	ć, vatier seri neriova nek espaptionitrieterata el 3 nel estas not he tre negorialistic d'autar	allars suspenae Ary Ob	TADE THEFT	•••	such wenteries on pe	NAM OF ADOVE NAMES		AVE.	·····
					D ACO.A.GR	C WARRANTY	<u>сна</u>	RGE	<u></u>
	1 I I I I I I I I I I I I I I I I I I I					a a a a a a a a a a a a a a a a a a a	-/		
x	if Hume				SERVICE CONTRACT			TAX	ومرجب والمستحير والمستعا

88.	/ 21./ 200 € 05: 20 ≤ /8/5 090520CBB2638 Exhibit I	e 7324	Pa	ALFITEMPCCC ( age 3 of 3		94 <u>2</u>	
5					RVICE O	DNED	INNOIC
					HVICE	INVEN	
		e și					
			19	2 - 19 - 19 - 2017년 - 19 - 19 - 19 - 19 - 19 - 19 - 19 - 19			
					and the second second second		
	BILL TO				THIS WORK IS TO BE		
		Patt				CHARGE	<u>C NO CHARGE</u>
					Rund		
	1720 Wassi	rop	<u></u>		NODEL R. C. T	ACDE.	
	MAACON, CA				SERA. NUMEER 12211 1177	SEPIAL NO	MACH
			- and a Combay	an and a set and a set and a set of the	RE WARDER BOUCH	A CALIFORNIA CONTRAPO TO	FRAME - CONSTRUMENT OF THE PARTY OF
NAME				ENV RONMENT	AL CHECK LIST	WORK F	PERFORMED
BYREE	r		ATE DE UN	WORK PERFORMED OT	YPEDISPOSITION	CONSENSING JN	and a second
CUTY	م الم المراجع ا المراجع المراجع المراجع المراجع المراجع		ROMINED		•	CLEANED SOL	CLEANED MILL DRAC HERNAED MAIN DRAM
PHONE		EFOA:		T RECLAIMED		GHEDKED CHARGE	CLEANEL PAR SAAIN
TECHNI	LCIAN ATTIC	ALZEL BY		C RETURNED		REPAIRED	HEPAIPLE PAIPLE
. /	TO BE PERFORMED			C DISPOSAL		ASPARED	FURN, CR FAR GOS
WOAK	DEPENDENCE AIC HEAT	ng dinin transition to an airin the		C DISMANTLED	TOTAL \$	AET. CHECKED MCTDA	1 HEF AUED ELLT
QTY.	MATERIALS & SERVICES	UNIT PR/C	E AMOUNT	DESCRIPTION OF V	VORK PERFORMED	THANGED	MEPLACEC
,	PETRIGERANT S. LIS.			Chart Ports 1	Alter	ATPJACE )	ADJUSTED PULLEY
····		÷			and the second second second second second	ADJVE SD BELT	- SLEANEC 'SLOWEG
	The top and the			inter the second	י איין אינער איין אנער איין איינער איין איין איין איין איין איין איין איי	REPLACE COMMETTE NEFL START ALLAT	BEARINGE DE EC HOTOR
	1 the set set -	¦i		fort star	and the second	APPL BTART	OLES BEA HINGS
		<u>}</u>	i	-	man have have the	REPLACED R.N.	CLEANEN HEAT ENCO
	·			C. Later C.		CLEANED OR ADJ CONTACTOR REPURED	ASPLACED HEAT BACK
8%	1-21-09 CK. 4784	(m. ~ )				HEPLACED FURE	ALEANED TR ADJ FAN REPLACED
		F		777		COMPRESSOR	PEPARED
1.1					50 00	EVAPORATOR CO.	PEPLACES
<u> </u>	0-01 2 (.4 50	<del>.</del>		74	-	AEPLACED EXP VALUE ACJUBTED EXR VALUE	AURNEAS
	Balance	: ;		/ 7	· · · · · · · · · · · · · · · · · · ·	EXA UAL 78 AEPLACEC CAR TUBE	DUOT
	71LTY39 X			3-3-09 2	d 194-	CAP JUST	ACULITED
	FILTERB X X			ck man t	-1700	HEIMPIEL SOLLEAK	THERMOSTA"
	BELTS	7				COVPERCONN COVPERCONN CLEMMED COK	REPLACED ;
·	Landard and an operation of the second se	ATERIALS			andraan haba qaab aana kaana kaa ahaa ahaa ahaa kaba kaba kaba kaba	LEVELED CON	, st., sp., sp. i st., Marit i an anti-air ann an aiteann
1 200						ELEUT HTR	CLC TOWER
HRS.		RATE	AMOUNT	RECOMME	NUATIONS	NEPLAGED JAK	GURANED
	SUCCE HEAT		17 45		· · · · · · · · · · · · · · · · · · ·	REPARED VID	4.2MF:51
		1				REAMAED CONT	SREASE.
				na an ann an Anna an A			AEM 925
	- TO1	AL LABOF		LIMITED WARRANTY	. An melanaia made	FLIERS I JOLA	LNED CEREMON
TERMS PER TER CHEET Y CAR			and adminiment are	wananted by the	TOTAL S	SUMMARY	
				manufecturers' or supportional only. At labor performa-	o by the above named	TOTAL	······································
	Call I Sta care		~	ocmpany is warranied otherwise indicated in	writing. The above	MATERIALS TOTAL	ana ang bagga sa ang sang sa
	WE STORE THE WALL SAME AND A WALL THE THE		nostes E sóns and	named company makes	and its agents or	LABOR	an a
5-0	infre bills in developments beforens furnishing while the owner. 6. adher daht winner bare exceptionshimogenale as beiler	nternine traduce ??.	estelle searcest para : Servers in concounter	terningers sig not by 5.305 wettenties on de	Inorized to make any	TRAVEL	384
and here	na: Atali 151 Zertre magaznářství or Barg/		-	COMPANY.		CHARGE	
$\sim \gamma$	the first the second		x <sup>2</sup> - T	TO SERVICE CONTRACT	WARRAN'Y	TAX	
X //	1-5 12 The The State	<u></u>		Thank	K You	TOTAL	394 4
		-		7 3 254 7 27	<u> </u>		

# GE-Zurich Warranty Management, Inc. Service Contract

Contract issued To :

ADRIANA GANTT 1720 WINSTON DR. MACON GA 31206 Products Installed At :

ADRIANA GANTT 1720 WINSTON DR. MACON GA 31206

Sales Representative : HOME DEPOT - 2667 (Store Name) Contract Number : 233 - 4661975

This Contract covers the products listed below. See reverse side for terms and conditions. When You Need Service: Call the number listed below. You will need to give your Contract number when requesting service, so please keep this Contract in a safe place.

Product/Brand	Model/Serial	Coverage	Phone	Install Date	Coverage Dates
COOKTOP - ELEC OR GAS JENN-AIR	JEC8536ADF	In-Home Repair	(888) 571-3101	11/11/2004	Begins: 11/11/2005 Ends: 11/11/2009
				r	
	en e			2.	
					м <b>.</b>

Note - Your Contract sales receipt and these terms and conditions, including the provisions, limitations, definitions and exclusions on each side of this Contract, form the entire Contract.

State Regulations - Will control if inconsistent with any other terms and provisions:

GA Residents: Cancellation - You may cancel at any time and receive a refund of the excess of the consideration paid for the Contract above the customary short rate for the expired term of the Contract. The Contract shall be non-cancelable by GEZWM except for fraud, material misrepresentation, or failure to pay the consideration due therefor. Cancellation by GEZWM shall be in accordance with O.C.G.A. 33-24-44. Surety Bond = 11, within 60 days after the claim has been filed with GEZWM, GEZWM tails to perform the service provided for in this Contract, you shall be entitled to make a direct claim against the surety identified: Federal Insurance Company, 15 Mountain View Rd., Warren, NJ 07059. Exclusions - What is not Covered: repair or replacement caused by defects that existed prior to the Contract purchase and known to you or that easonably should have been known to you.



We bring good things to life.

- Hartin Contain 1 100-612-2772 - Dilligral



U.S. CONSUMER PRODUCT SAFETY COMMISSION NOTICE OF INSPECTION
1. DATE J. FROM (Area Office and Address)
5-27-09 Po Box 72357
2. TIME Newnon, GA 30271
A. NAME AND TITLE OF INDIVIDUAL
Art Wright, Manager on Duty
4. TO C. NUMBER AND STREET ADDRESS
4635 Presidential Pkury O. CITY. STATE AND ZIP CODE
Macon, GA 31206
Notice of Inspection is hereby given pursuant to
• Flammable Fabrics Act (15 U.S.C. 1191 et seq.):
Federal Trade Commission Act (15 U.S.C. 41 et seq.);
<ul> <li>Sections 16, 19 and 27 of the Consumer Product Safety Act (15 U.S.C. 2065, 2068 and 2076)</li> </ul>
<ul> <li>Section 704(a) of the Federal Food. Drug, and Cosmetic Act (21 U.S.C. 374(a)) [Authority for inspections in connection with the Poison Prevention Packaging Act of 1970 (15 U.S.C. 1471 er seq.)] and/or</li> </ul>
<ul> <li>Section 11(b) of the Federal Hazardous Substances Act as Amended (15 U.S.C. 1370(b))</li> </ul>
Refer to the back of this form for a discussion of inspectional authority and for pertinent statutory language.
5, PURPOSES OF INSPECTION AND NATURE OF INFORMATION TO BE OBTAINED AND/OR COPIED The purpose of trus inspection is to obtain information, to review and obtain copies of items including but not finited to records, reports, books, documents, and labeling; and to obtain samples, in order to enforce or de comine compliance with the Acts administered by the Consumer Product Safety Commission.
6. FREEDOM OF INFORMATION REQUIREMENTS Those from whom information is requested should state whether any of the information submitted is believed to contain or relate to a trade secret or other matter which should be considered by the Commission to be confidential and whether any of the information is believed to be eatilited to exemption from disclosure by the Commission under the provisions of the Freedom of Information Act (15 U.S.C. 552). Any statement asserting this claim of confidentiality must be in writing, and any request for exemption of the information from dis- closure must be made in accordance with the Commission's Freedom of Information Act regulations. 16 CFR Part 1015.
2. SIGNATURE (Authorized CPSC Official)

CPSQ Form 296 (9/79)

090520CBB2638 Exhibit L

> U.S. Consumer Product Safety Commission

# AUTHORIZATION FOR RELEASE OF NAME

Thank you for assisting us in collecting information on a potential product safety problem. The Consumer Product Safety Commission depends on concerned people to share product safety information with us. We maintain a record of this information, and use it to assist us in identifying and resolving product safety concerns.

We routinely forward this information to manufacturers and private labelers to inform them of the involvement of their product in an accident situation. We also give the information to others requesting information about specific products. Manufacturers need the individual's name so that they can obtain additional information on the product or accident situation.

Would you please indicate on the bottom of this page whether you will allow us to disclose your name? If you request that your name remain confidential, we will of course, honor that request. After you have indicated your preference, please sign your name and date the document on the lines provided.

I request that you do not release my name. My identity is to remain confidential.



You may release my name to the manufacturer but I request that you do not release it to the general public.



You may release my name to the manufacturer and to the public.

(dijana) faut 5/27/09 (Date)

CESC Found22

Task No.	090520CBB2638	
----------	---------------	--

Date:\_\_\_\_

# STATUS OF MISSING DOCUMENT(S)

The official records were requested for this investigation report but could not be obtained.

1. Medical Records	
2	
3	
4	
5	
June 3, 2009	2147
Date:	
Regional office:	Supervisor No:

090520CBB2638 Exhibit M



#### U.S. CONSUMER PRODUCT SAFETY COMMISSION ATLANTA FIELD OFFICE P.O. BOX 72357 NEWNAN, GA 30271

Justin McDonough Investigator Tel: (770) 252-9602 Fax: (866) 689-7190 Email: jmcdonough@cpsc.gov

May 28, 2009

Macon Family Health Center 1051 Pio Nono Avenue Macon, GA 31204

To whom it may concern,

The United States Consumer Product Safety Commission (CPSC) is a Federal Agency responsible for investigating deaths, injuries, and potential hazards associated with consumer products. I am an investigator with the U.S. Consumer Product Safety Commission in the Atlanta, Georgia, area.

Please see the attached medical records release form signed by Mrs. Adrianna Gantt. The records for Mrs. Gantt from 2005 to the present are needed. The records can be faxed to 866-689-7190, emailed to <u>imcdonough@cpsc.gov</u>, or mailed to me at:

Justin McDonough U.S. Consumer Product Safety Commission PO Box 72357 Newnan, GA 30271

Please do not hesitate to contact me if you have any questions. I appreciate your assistance in this matter.

Sincerely,

ZN

Justin McDonough Product Safety Investigator

#### APPENDIN VIED-7 MEDICAL RECORDS DISCLOSURE FORM

#### U.S. CONSUMER PRODUCT SAFETY COMMISSION

#### AUTHORIZATION FOR MEDRIAL RECORDS DISCLOSURF

the form onthorizes educe of information respectives existing Health Insertice Portal late, ad Accountability (2) FOR Probable and test between PRACE PRACE (See all VIII) and the model of the probability of the prob the internation represent on the tors accolutely in the independent that the Social Note (Note is not be used to reaction of a terral lease values as here have a probably compared to solve a new of a contradition method Established to the sound settlement of

TO MIGNED MAY	CONCLEN:		
Liquest and authors	Macon Family	Health Centre	e de la compañía de la
in a reason and the later	to many her aited	States Consumer Pris	est Salist. Commission
all'ender and conclusion	Care on Lal roomle ve	mmer have polyment	FORTH CASE HERE AND THE

Adriana Gantt

RoomName

Relationships to cour

Pathacherial Security Nonther


including, but not hanned to an abcal history, physical reports, laboratory reports and particles early sticks, and here reports and items

3. DEBRIZATION - confection discounsed has been mode the terrentiate and without conclusion and first developmentations are associated and competition the best of my known gets. I understand that I will a to avoid copy of this form, there is spiral. There is valo, the anthon zaroa, as with regulation time exception detected during to organized, been taken a complete opting. Wroney a compose is effective openational ecopy by the number office at the facility hearsney the records. Redschowing of my medical reports by those recommendary above multioneral automorphics pays be accomplished writered by thatk r which articitation and an accords num no langue is projected. Without the express revocation, the authorication will opportunally concerned appoint at all a next of the next for dechorate e2x or

6/1/09 note supplied by publicle, or counder the following conditions

5/27/09 

NUNS) CPSCFORM NO 176



Doc No: 10950711A

05/19/2009 01:09:49

Name = Adriana Gantt Address = 1720 Winston Drive City = Macon State = Georgia Zip = 31206 Email = dgantts@cox.net Telephone = 478-254-2969 Name of Victim = Various family members Victim's Address = 1720 Winston Drive Victim's City = Macon Victim's City = Macon Victim's State = Georgia Victim's Zip = 31206 Victim's Telephone = 478-254-2969

Incident Description = Upon being in our house and especially after sleeping there had been incidences of asthma like symptoms, heaviness of the chest, abdominal discomfort, tiredness, and lower back pain(kidney area); nose bleeds, stomach discomfort, headaches, general weakness, coughing and uncontrollable blood sugar in son (9). Lights flicker, fuses trip, motion lights work inappropriately, light bulbs blow very frequently, significant tarnish around metallic based mirrors, air conditioner ignitor replaced twice in short time. Digital thermostat prematurly expired, recessed lights go out in short periods of use, house stinks, stinks, stinks. We were forced to move out due to these circumstances.

Victim's age at time of incident = ages 8,10,11,37,41 Victim's sex = female Date of incident = from 2005 Product involved = Possibly dry wall Product brand name/manufacturer = ? Manufacturer street address = ? Place where manufactured (City and State or Country) = ? Product model and serial number, manufacture date = ? Product damaged, repaired or modified = no If yes, before or after the incident = Description of damage, repair or modification = Date product purchased = December 2004 Product involved still available = yes Have you contacted the manufacturer = no If not, do you plan to contact them = yes Name Release = Release name to manufacturer only