

Exhibit 78



United States
**CONSUMER PRODUCT
SAFETY COMMISSION**

Trimmers/Brushcutters Recalled by STIHL Incorporated Due to Injury Hazard (Recall Alert)



Recalled trimmer/brushcutter



**Name of Product:AAA**

STIHL FS 310 Bike Handle Trimmer/BrushcutterAAA

Hazard:AAA

Vibration from the ignition module may cause the trimmer head to loosen and detachAA from the mounting, posing an injury hazard.AAA

Remedy:AAA

ReplaceAAA

Recall Date:AAA

DecemberA6, 2010AAA

Units:AAA

About 1,000AAA

Consumer Contact

For more information, contact STIHL between 8 a.m. and 8 p.m. ET MondayAAA through Friday at (800) 610-6677 orAisit STIHL's website at www.stihlusa.comAAA

Recall Details

December 16, 2010

Alert #11-711

The following product safety recall was voluntarily conducted by the firm in cooperation with the CPSC. Consumers should stop using the product immediately unless otherwise instructed. It is illegal to resell or attempt to resell a recalled consumer product.

Name of Product: STIHL FS 310 Bike Handle Trimmer/Brushcutter

Units: About 1,000

Manufacturer: STIHL Incorporated, of Virginia Beach, Va.

Hazard: Vibration from the ignition module may cause the trimmer head to loosen and detach from the mounting, posing an injury hazard.

Incidents/Injuries: The company received three reports of incidents and no reports of injuries.

Description: The recalled bike handle trimmer/brushcutter has "STIHL" printed on the engine head. The model number FS 310 is located in two places, on the shaft and on the flywheel housing below the starter grip. This recall includes all units with serial

numbers ranging from 27961 1030 through 27961 1119 and 27984 3607 through 27984 4556, which can be found on an adhesive label affixed to the bottom of the fuel tank and etched into the metal frame on the bottom of the engine.

Sold at: Authorized STIHL dealers nationwide from June 2009 to April 2010 for about \$550.

Manufactured in: United States

Remedy: STIHL informed purchasers for whom they had addresses directly by letter after April 15, 2010. Consumers should stop using this trimmer/brushcutter immediately and take it to an authorized STIHL dealer for a new ignition module, which will be installed at no cost to the consumer.

Consumer Contact: For more information, contact STIHL between 8 a.m. and 8 p.m. ET Monday through Friday at (800) 610-6677 or visit STIHL's website at www.stihlusa.com

