

Exhibit 80



United States
CONSUMER PRODUCT
SAFETY COMMISSION

General Electric Recalls Gas Rangetop with Grill Due to an Explosion Hazard



Note: Health Canada's press release is available [here](#).



Recalled gas range top



Name of Product:

GE Monogram® Pro Rangetop with Grill

Hazard:

Burners on Rangetops operating on liquefied petroleum ("LP" or propane) may fail to ignite or light if the gas control knob is left in a position between OFF and LITE, posing a risk of delayed ignition or explosion.

Remedy:

Repair

Recall Date:

October 25, 2011

Units:

About 470

Consumer Contact

For additional information, contact General Electric toll free at (866) 645 3956 between 8 a.m. and 5 p.m. ET Monday through Friday, or visit the firm's website at www.geappliances.com/products/recall

Recall Details

Description:

The Grill units operate on liquefied petroleum ("LP" or propane) or natural gas. The Rangetop units are either 36 or 48 inches wide with a stainless steel finish and the GE Monogram® badge located on the front center of the unit. The burner control knobs are located on the front panel that overhangs the cabinet. The model and serial numbers can be found on a label located behind the far left burner knob, or on the bottom of the unit.

The following models and serials are included in this recall:

Brand	Model Number Begins With:	And Serial Number Begins With:
Monogram®	LP Model	Natural Gas
	ZGU364LRP	Model
	ZGU484LGP	ZGU364NRP
	ZGU486LRP	ZGU484NGP
		ZGU486NRP
		AS, AT, AV, DS, DT, DV, FS, FT, FV, GS, GT, GV, HR, HS, HT, HV, LR, LS, LT, LV, MR, MS, MT, RR, RS, RT, SR, SS, ST, TR, TS, TT, VR, VS, VT, ZR, ZS, ZT

All LP models and only natural gas models that have been converted for use with LP gas are included in the recall. GE will notify known owners of natural gas units and provide a free repair for any consumers who converted their Rangetop with Grill to LP gas.

Remedy:

Consumers who are operating the product on LP (propane) gas should stop using the product immediately, turn off the gas supply to the product, and contact GE to schedule a free repair.

Incidents/Injuries:

GE has received six reports involving explosions in units operating on LP gas, including reports of damage to kitchen cabinets beneath the Rangetop. No fires or injuries have been reported.

Sold At:

General Electric authorized representatives and distributors nationwide from May 2008 through August 2011 for between \$3,400 and \$4,700, as determined by retailers.

Manufacturer(s):

Leiser, Mexico

Manufactured In:

Mexico.

Recall number:

12-021