



U.S. Consumer Product Safety Commission

CPSC Stands for Safety

China Product Hazard Monthly Summary Bulletin

February 2023

中國 產品危害 每月小結 簡報

2023 年二月

The China Product Hazard Monthly Summary Bulletin advises Chinese manufacturers of the most commonly occurring hazards posed by products they produce, such as products including lithium-ion batteries and other electrical/electronic products, violations of U.S. flammability standards for children's sleepwear, excessive lead levels in children's products, small parts choking hazards, and others. More information on specific cases listed below is available by clicking on the link or going to: [CPSC's Recalls page](#).

《中國產品危害每月小結簡報》的目的是提示中國廠商注意一些他們生產的產品最常出現的危害，諸如包括鋰電池在內的電子/電器產品以及其它產品，違反美國聯邦兒童睡衣阻燃標準，兒童產品含鉛過量，因小部件而導致窒息等問題。簡報中相關個案的詳細情況，可以點擊 [CPSC's Recalls page](#)，查看公告全文。

23-134	The high chairs can break, posing a fall hazard to children. 兒童高椅會斷裂，對兒童構成跌倒危害。
23-729	The replacement lower blade guards do not sufficiently cover the saw blade and can break when making a cut, posing an injury hazard to the user. 更換的下面部分刀片防護罩不能充分覆蓋鋸刃，切割時可能會斷裂，對使用者構成受傷危害。
23-132	The slats metal platform bedframe assembly kit did not include reinforcing brackets for installation on the corners of the frame, which could lead to the frame collapsing, posing an injury hazard. 條狀金屬平台式床架套組不包括安裝時使用的床角加固配件，這會導致床架坍塌，構成受傷危害。
23-130	A wire connection in the air fryers can overheat, posing fire and burn hazards. 空氣炸鍋的連接線路會過熱，構成火災和燒傷危害。
23-127	The arms or legs on the figurines can detach, posing a small part choking hazard to children. 小雕像的胳膊和腿會與雕像分離，對兒童構成小部件窒息危害。

23-125	The probes can fail to operate when deployed by rescuers, posing a risk of severe injury or death to a person buried under snow following an avalanche. 救援人員在部署救援時， 探頭 未能工作，這對被雪崩埋在雪底下的人會構成嚴重受傷或死亡的風險。
23-123	The children's nightgowns fail to meet the U.S. flammability standards for children's sleepwear, posing a risk of burn injuries to children. 兒童睡衣不符合美國聯邦兒童睡衣阻燃標準，對兒童構成燒傷風險。
23-122	The children's pajamas fail to meet the U.S. flammability standards for children's sleepwear, posing a risk of burn injuries to children; and the children's headbands contain levels of lead that exceed the U.S. lead content ban. Lead is toxic if ingested by young children and can cause adverse health issues. 兒童浴袍不符合美國聯邦兒童睡衣阻燃標準，對兒童構成燒傷風險；兒童頭巾含鉛超過美國聯邦鉛含量禁令。鉛若被幼兒吞入口中是有毒的，會引起不良健康問題。
23-121	The children's nightgowns fail to meet the U.S. flammability standards for children's sleepwear, posing a risk of burn injuries to children. 兒童睡衣不符合美國聯邦兒童睡衣阻燃標準，對兒童構成燒傷風險。
23-120	A short in the wire on the night hunting headlamps can cause the wire to heat up and melt, posing a burn hazard. 夜間狩獵頭燈的電線會短路，從而導致電線發熱並熔化，構成燒傷危害。
23-727	The electric bicycle's front fork can crack, posing a crash hazard. 電動自行車的前叉會斷裂，構成衝撞危害。
23-724	The zipper can detach from the baby sleep sack , posing a choking hazard. 嬰兒睡袋的拉鍊會脫離睡袋，構成氣管堵塞危害。
23-117	The raindrops on the cloud toy included with the activity gym can detach from the ribbon, posing a choking hazard if a child places it in their mouth. 活動健身房附帶的雲彩玩具上的雨滴會從帶子上脫落，如果孩子將它放入口中，構成氣管堵塞危害。
23-113	The children's robes fail to meet the U.S. flammability standards for children's sleepwear, posing a risk of burn injuries to children. 兒童浴袍不符合美國聯邦兒童睡衣阻燃標準，對兒童構成燒傷風險。
23-112	The children's robes fail to meet the U.S. flammability standards for children's sleepwear, posing a risk of burn injuries to children. 兒童浴袍不符合美國聯邦兒童睡衣阻燃標準，對兒童構成燒傷風險。
23-111	The children's robes fail to meet the U.S. flammability standards for children's sleepwear, posing a risk of burn injuries to children. 兒童浴袍不符合美國聯邦兒童睡衣阻燃標準，對兒童構成燒傷風險。
23-110	The children's robes fail to meet the U.S. flammability standards for children's sleepwear, posing a risk of burn injuries to children. 兒童浴袍不符合美國聯邦兒童睡衣阻燃標準，對兒童構成燒傷風險。