



U.S. Consumer Product Safety Commission

CPSC Stands for Safety

China Product Hazard Monthly Summary Bulletin

中國 產品危害 每月小結 簡報

November 2021

2021 年十一月

The China Product Hazard Monthly Summary Bulletin advises Chinese manufacturers of the most commonly occurring hazards posed by products they produce, such as excessive lead levels in children's products, choking hazards caused by children's upper outerwear garments with drawstrings, and others. More information on specific cases listed below is available by clicking on the link or going to: [CPSC's Recalls page](#).

《中國產品危害每月小結簡報》的目的是提示中國廠商注意一些他們生產的產品最常出現的危害，諸如兒童產品含鉛過多，兒童上衣外套帶拉繩引起的窒息等問題。簡報中相關個案的詳細情況，可以點擊[CPSC 的召回頁面](#)，查看公告全文。

20-022	The locking collars on the dumbbell handles can slip, dropping weights when held perpendicular to the floor, posing an impact-injury hazard. 啞鈴握把的鎖套會滑動，使得啞鈴被握在與地板垂直位置時配重會掉落，構成衝撞危害。
22-708	The steps of the ladder for above-ground pools can loosen during use, posing fall and drowning hazards to the user. 地面泳池的梯子台階使用中會鬆脫，對使用者構成跌倒和溺水危害。
22-707	Fuel can leak from the top of the outdoor metal torch canister and ignite, posing a fire hazard. 燃料會從戶外金屬火炬罐頂部洩漏和起火，構成火災危害。
22-013	The youth helmets do not comply with the U.S. CPSC federal safety standard for bicycle helmets, posing a risk of head injury. 青少年頭盔不符合美國消費品安全委員會的自行車頭盔聯邦安全標準，構成頭部受傷危害。
22-706	The wooden parts used to reinforce and create a decorative gable design on the playset's wooden roof pose an entrapment hazard to children. Children can become trapped in the gap between the lower part of the roof structure and the bottom of the gable decoration. 用於將裝飾性的山牆設計固定和安裝在 遊戲組木屋頂 上的木頭部件對兒童構成羈絆危害。兒童會被困在屋頂下部和裝飾性山牆之間的空隙處。