

30. POOLS, PUBLIC SWIMMING (ANSI/NSPI-1)

Purpose - To participate in development of an ANSI American National Standard for public swimming pools **Status** - A new standard for public swimming pools (ANSI/NSPI) was approved on 2/18/91. This project is completed, except for reporting on completed diving research

31. POOLS, RESIDENTIAL SWIMMING (ANSI/NSPI-5)

Purpose - To participate in development of an ANSI American National Standard for residential swimming pools. **Status** - A new ANSI standard for residential swimming pools (ANSI/NSPI-5) was balloted and negative ballots are being resolved. The CPSC staff commented on the proposed standard. This project is completed, except for reporting on completed diving research

32. RIDING MOWERS (ANSI B71.1)

Purpose - To develop recommendations by 1994 for improvements, especially in the areas of dynamic stability and blade contact, to the ANSI B71.1 standard which will reduce deaths and injuries associated with riding mowers. **Status** - In 1992 CPSC staff released a Directorate for Economics exposure survey report, a Directorate for Epidemiology injury trend report, and an Human Factor's contractor's report on control placement. The Directorate for Engineering Sciences completed construction of a sloped test platform with an artificial surface for dynamic testing of riding mowers. The CPSC staff and the industry working group met on 3/23/92 to review the status of CPSC and Outdoor Power Equipment Institute activities.

33. SHOCK PROTECTORS (UL 943, UL 1664, ANSI C101.1)

Purpose - To enhance the shock protection from electric circuits and products by improving existing standards and developing new ones. **Status** - UL 1664 Immersion Detection Circuit Interrupter - A new standard was approved 5/8/90 to meet the need for shock protectors on appliances. Devices are currently being listed to this standard. ANSI C101.1 Leakage Current for Appliances - Updating of this standard is in progress. UL 943 Ground Fault Circuit Interrupter - The most recent UL revisions issued for this existing standard were approved 5/90.

34. SMOKE DETECTORS (UL 217)

Purpose - To reduce the deaths and injuries from residential fires by increasing the number of homes with working smoke detectors. **Status** - A coalition of concerned organizations has formed committees to describe the extent of the problem, conduct outreach efforts, increase detector use and maintenance, and evaluate applicable standards and codes. A field investigation study and a general operability survey are to determine the extent and causes of non-working detectors in homes. This information will be the basis for possible future changes in voluntary standards and building codes, or in technology to reduce the prevalence of non-working detectors.

35. SOFT GOODS/INFANT BEDDING (ASTM F15.40.26)

Purpose - To develop an ASTM voluntary standard addressing ingestion/choking on decorative items and entanglement/strangulation from strings or threads on infant bedding products and nursery soft goods. **Status** - The CPSC staff attended the first organizational meeting of this new activity on 8/6/91. The staff did not attend a second meeting that was held on 2/25/92.

36. STROLLERS (ASTM F15.40.08)

Purpose - To revise an ASTM voluntary standard, first published in 1983, to add provisions addressing the effectiveness of the restraining system, security of latching mechanisms, and entrapment/strangulation of infants in convertible carriages/strollers. **Status** - The standard was revised three times. The most recent revision, approved in 12/90, added a conspicuous warning label concerning recommended use of the restraining system.

37. TOY SAFETY (ASTM F15.22)

Purpose - To revise the "Standard Consumer Safety Specification on Toy Safety (ASTM F963)". **Status** - The standard was revised to add a provision calling for a warning label on balloon packaging and was republished in 5/91. CPSC staff and others are suggesting new and revised provisions to be considered during the routine review of the standard every five years.

38. INDOOR AIR QUALITY: UNVENTED GAS SPACE HEATERS (ANSI Z21.11.2)

Purpose - To revise the ANSI standard to incorporate emission rates for carbon monoxide. **Status** - CPSC staff has completed testing on nine unvented gas space heaters using a standard hood test system. A series of round robin tests will be conducted by industry. Testing will also be conducted in cooperation with industry to verify estimates of in-home concentrations using indoor air quality models. An emission factor for nitrogen dioxide was recommended to the ANSI Z21 Subcommittee on 9/25/92.

39. GAS WATER HEATERS (ANSI Z21.10)

Purpose - To revise the ANSI standard to protect consumers against ignition of flammable vapors by water heaters. **Status** - An ANSI working group is investigating this issue.

Appendix F:

992

**Voluntary
Corrective
Action Plans and
Product Recalls**

Subsection A/
Section 15 Recalls
Subsection B/
Regulatory Recalls

VOLUNTARY CORRECTIVE ACTION PLANS AND PRODUCT RECALLS

Voluntary Corrective Action Plans and Recall of Products Subject to Product Safety Standards and Other Specific Regulations Exclusive of Section 15 of the Consumer Product Safety Act

The Office of Compliance and Enforcement and the Regional Offices are jointly responsible for identification of consumer products which fail to comply with a specific product safety standard or other Commission product-related requirements mandated by statute or regulation. Commission staff works cooperatively with the responsible firms to obtain voluntary corrective action plans as appropriate to protect the public. Following is a list of these product recalls and corrective action plans monitored by the Commission staff during Fiscal Year 1992.

Consumers may find products on the market which resemble those appearing on this list. After manufacturers and importers correct violations, they may distribute complying versions of products which were recalled. CPSC monitors recalls to ensure that the noncomplying products have been removed from the market. It is unfair to responsible manufacturers and importers to conclude that toys and children's products on the list are still offered for sale.

VOLUNTARY CORRECTIVE ACTION PLANS UNDER THE FIVE STATUTES ENFORCED BY THE COMMISSION

DATE	PRODUCT	MODEL	VIOLATIONS	CITATION
10/91	Wooden Pull Toy	#7215-skunk	small parts	16 CFR 1501
10/91	Wooden Pull Toy	#7203-cow	small parts	16 CFR 1501
10/91	Wooden Pull Toy	#7207-small cat	small parts	16 CFR 1501
10/91	Wooden Pull Toy	#7202-zebra	small parts	16 CFR 1501
10/91	Wooden Pull Toy	#7216-large rabbit	small parts	16 CFR 1501
10/91	Wooden Pull Toy	#7204-small rabbit	small parts	16 CFR 1501
10/91	Wooden Pull Toy	#7213-large cat	small parts	16 CFR 1501
10/91	"Baby Slugger" Baseball Cap	Style #3155	small parts	16 CFR 1501
10/91	Coricidin	24 tablet size	crc & labeling	16 CFR 1700 5
10/91	Coricidin 'D'	24 tablet size	crc & labeling	16 CFR 1700 5
10/91	Halloween Plastic Trumpets	#9353-228	small parts	16 CFR 1501
10/91	Halloween Erasers	#5005	small parts	16 CFR 1501
10/91	Halloween Frightening Rings	#P301	small parts	16 CFR 1501
10/91	Rain or Shine Doll	#JP0137	small parts	16 CFR 1501
10/91	Diphenhydramine Hydrochloride	Formula 641	fails crc	16 CFR 1700 14
10/91	EZ Lite Firestarter	(None)	labeling	16 CFR 1500 3
11/91	Infant Pacifiers	#12647	pacifier	16 CFR 1511
11/91	Infant Pacifiers	#12646	pacifier	16 CFR 1511
11/91	Melody Milker	(None)	small parts	16 CFR 1501
12/91	Play & Learn Educational Train	#111-19229	small parts	16 CFR 1501
12/91	Play & Learn Educational Dog	#111-19229	small parts	16 CFR 1501
12/91	Space Ship Erasers	#8700	small parts	16 CFR 1501
12/91	Dump Truck (Action Toy)	#8888	small parts	16 CFR 1501
12/91	Helicopter (Action Toy)	#8888	small parts	16 CFR 1501
12/91	Baby Rattle	#323	rattle	16 CFR 1510
12/91	Jet Planes	#8715	small parts	16 CFR 1501
12/91	Cement Mixer (Action Toy)	#8888	small parts	16 CFR 1501
12/91	Push 'N' Roll Dino Toy	#38020	small parts	16 CFR 1501
12/91	Elephant Telephone Car	#YL-103E	small parts	16 CFR 1501
12/91	Dachshund Telephone Car	#YL-103D	small parts	16 CFR 1501
12/91	Animated Musical TV	#7750	small parts & sharp points	1501,1500.48
12/91	Swan Telephone Car	#YL-116	small parts	16 CFR 1501
12/91	Beetle Telephone Car	#YL-115	small parts	16 CFR 1501
12/91	Cartoon Telephone Car	#YL-111S	small parts	16 CFR 1501
12/91	Jumbos Pull-Along Turtle	#HA-118	small parts	16 CFR 1501
12/91	Little Big Haulers	#5016	small parts	16 CFR 1501
12/91	Penguin Telephone Car	#YL-117	small parts	16 CFR 1501
01/92	Sleep N Play Infant Sleepwear	Style #53342	flammability	16 CFR 1615
01/92	Jingle Bell Cat	#A0534	small parts	16 CFR 1501
01/92	Jingle Bell Dog	#A0533	small parts	16 CFR 1501
02/92	Mini Cars	#2084	small parts	16 CFR 1501

CFR - Code of Federal Regulations

FHSA - Federal Hazardous Substances Act

PPPA - Poison Prevention Packaging Act

ACTION	MANUFACTURER/IMPORTER	CITY & STATE	ZIP CODE
recall	Kubla Crafts	Hampton Bays, NY	11946
recall	Kubla Crafts	Hampton Bays, NY	11946
recall	Kubla Crafts	Hampton Bays, NY	11946
recall	Kubla Crafts	Hampton Bays, NY	11946
recall	Kubla Crafts	Hampton Bays, NY	11946
recall	Kubla Crafts	Hampton Bays, NY	11946
recall	Kubla Crafts	Hampton Bays, NY	11946
recall	T & B Novelty, Inc.	Brooklyn, NY	11211
recall	Schering-Plough Corp.	Memphis, TN	38151
recall	Schering-Plough Corp.	Memphis, TN	38151
recall	Wal-Mart Stores, Inc.	Bentonville, AR	72716
recall	Diener Industries	Chatsworth, CA	91311
recall	Wal-Mart Stores, Inc	Brentonville, AR	72716
recall	Jak Pak, Inc.	Milwaukee, WI	53202
recall	Xcel Laboratories	Kalamazoo, MI	49002
recall	Di-Bar Co.	San Antonio, TX	78265
recall	Claire's Boutique	Wood Dale, IL	06191
recall	Claire's Boutique	Wood Dale, IL	06191
recall	Daystone International Corp	Schaumburg, IL	60173
recall	Ramco Trading Corp	Hialeah, FL	33014
recall	Ramco Trading Corp.	Hialeah, FL	33014
recall	Unique Industries, Inc.	Philadelphia, PA	19144
recall	Kay Bee Toy & Hobby Shops	Pittsfield, MA	01201
recall	Kay Bee Toy & Hobby Shops	Pittsfield, MA	01201
recall	Luv'n care, Ltd.	Monroe, LA	71201
recall	Unique Industries, Inc.	Philadelphia, PA	19144
recall	Kay Bee Toy & Hobby Shops	Pittsfield, MA	01021
recall	Sears and Roebuck Co.	Chicago, IL	60684
recall	Norok Co.	Schwenkville, PA	19473
recall	Norok Co.	Schwenkville, PA	19473
recall	G & W Merchandise, Inc	Guaynabo, PR	00969
recall	Norok Co.	Schwenkville, PA	19473
recall	Norok Co.	Schwenkville, PA	19473
recall	Norok Co.	Schwenkville, PA	19473
recall	Gitty's Toys, Inc.	Mayaguez, PR	00709
recall	Unique Industries, Inc.	Philadelphia, PA	19144
recall	Norok Co	Schwenkville, PA	19473
recall	Obion Denton	New York, NY	10001
recall	Hyman Products	Maryland Heights, MO	63043
recall	Hyman Products	Maryland Heights, MO	63043
recall	Unique Industries, Inc.	Philadelphia, PA	19144

DATE	PRODUCT	MODEL	VIOLATIONS	CITATION
02/92	Play Cars	#25	small parts	16 CFR 1501
02/92	Pharmacy Mate Vials & Closures	dram sizes 6, 8	fails crc	16 CFR 1700.15(b)
02/92	Walk-Behind Lawn Mowers	#S22B, S24B, S26	lawn mowers	16 CFR 1205
02/92	Slide Flutes	#8651	small parts	16 CFR 1501
02/92	Play & Learn Education Toy	#5009 - Puppy	small parts	16 CFR 1501
02/92	Play & Learn Education Toy	#5007 - Train	small parts	16 CFR 1501
02/92	Play & Learn Education Toy	#5001 - Elephant	small parts	16 CFR 1501
02/92	Little Babies Dolls	#AR-1287	small parts	16 CFR 1501
02/92	Toy Piano Phone	(None)	small parts	16 CFR 1501
03/92	Cats Pajamas Stuffed Animal	#1162	small parts	16 CFR 1501
03/92	My First Buddy's Pop Pop Car	#4562	small parts	16 CFR 1501
03/92	Softeroo Pull-A-Long Farm	#62117	small parts & sharp points	1501, 1500 48
03/92	Lady Bug Pull Along	#FB9043	small parts	16 CFR 1501
03/92	Air Time Pogo Stick	#7730	lead-in-paint	16 CFR 1303
03/92	Cardigan and Sweatshirt	#817288 and 8172	flammability	16 CFR 1610
03/92	Workshop Tool Pouch	#0131	small parts	16 CFR 1501
03/92	Baby Teether Jolly Rattle	#84567	rattle	16 CFR 1510
03/92	Bump and Go Wonder Loco	#7801	small parts	16 CFR 1501
03/92	Busy Water Balls	#33012	small parts	16 CFR 1501
03/92	F A O Schwarz Slugger Bear	(None)	small parts	16 CFR 1501
03/92	Nu-Silver Pure Silver Plate	4 oz bottles	cyanide salts	16 CFR 1500 17
03/92	Clown Activity Center	#FB7052	small parts	16 CFR 1501
03/92	Pull-A-Long Robot Phone Bank	#689	small parts	16 CFR 1501
03/92	Pull-A-Long Take-A-Part Loco	#3211	small parts	16 CFR 1501
03/92	"Symphony Loco" Toy Train	#3037	small parts	16 CFR 1501
03/92	Sesame Street Separates	#332-8041,2,3,6	small parts	16 CFR 1501
03/92	Pajama Pals	#26646	small parts	16 CFR 1501
03/92	Puppy Phone w/Savings Bank	#1168	small parts	16 CFR 1501
03/92	Train Set	(None)	small parts	16 CFR 1501
03/92	Baby's Rattle	(None)	rattle	16 CFR 1510
03/92	Sweet Doll w/Accessories	(None)	small parts	16 CFR 1501
04/92	Pull Pal Rattle	#0019	rattle	16 CFR 1510
04/92	Lovely Sonny Doll in Basket	#1079	small parts	16 CFR 1501
04/92	F.A O. Clocktower Nightshirt	#364216	flammability	16 CFR 1616
04/92	F.A.O Bear Nightshirt	#441170	flammability	16 CFR 1616
04/92	Big Bird Push Power Asst	#75110	small parts	16 CFR 1501
04/92	13" White Bunny w/Pink Ears	#1011-1	small parts	16 CFR 1501
04/92	Twinkling Twins Rattle	#0017	rattle	16 CFR 1510
04/92	Toy Plush Bear	Koala Bear	small parts	16 CFR 1501
04/92	Prenatal Vitamins Folic Acid	100 Tablets of	fails crc	16 CFR 1700.14
04/92	Cookie Monster Push Power Asst	#75110	small parts	16 CFR 1501
04/92	Ernie Push Power Asst.	#75110	small parts	16 CFR 1501
04/92	Table Setting Puzzle	#MTC-2029	lead-in-paint	16 CFR 1303
04/92	Garden Tools Puzzle	#MTC-2028	lead-in-paint	16 CFR 1303
04/92	Butterfly Puzzle	#MTC-2030	lead-in-paint	16 CFR 1303
04/92	Turtle Puzzle	#MTC-2031	lead-in-paint	16 CFR 1303
04/92	Snail Puzzle	#MTC-2032	lead-in-paint	16 CFR 1303
04/92	Tools Puzzle	#MTC-2027	lead-in-paint	16 CFR 1303
04/92	Vegetable Puzzle	#MTC-2026	lead-in-paint	16 CFR 1303
04/92	Wind-Up Row N Row Boat	#172	small parts & sharp points	1501, 1500 48

ACTION	MANUFACTURER/IMPORTER	CITY & STATE	ZIP CODE
recall	McCory Corp	York, PA	17402
recall	Owens Brockway RX Products	Toledo, OH	43666
recall	Yazoo Manufacturing Co	Jackson, MS	39216
recall	Unique Industries, Inc.	Philadelphia, PA	19144
recall	Blue Whale International, Inc.	Davie, FL	33328
recall	Blue Whale International, Inc.	Davie, FL	33328
recall	Blue Whale International, Inc.	Davie, FL	33328
recall	Arrow Trading Co., Inc.	New York, NY	10010
recall	Broadway Agents, Corp	New York, NY	10010
recall	North American Bear Co	Chicago, IL	10601
recall	Target Stores	Minneapolis, MN	55440
recall	Jolly (U.S.A.) Inc.	W. Berlin, NJ	08091
recall	International Playthings	Riverdale, NJ	07457
recall	GPT Products	Elmhurst, IL	60126
recall	Victoria's Secret Catalog	Reynoldsburg, OH	43068
recall	Little Tikes Co	Hudson, OH	44236
recall	Everything's A Dollar, Inc.	Milwaukee, WI	10018
recall	Aldi, Inc (Nolte Co.)	Batavia, IL	60510
recall	Blue Box Toys	New York, NY	10010
recall	North American Bear Co	Chicago, IL	60610
recall	HKI Inc.	Boca Raton, FL	33432
recall	International Playthings	Riverdale, NJ	07457
recall	Kraemer Mercantile Corp	New York, NY	10010
recall	Kraemer Mercantile Corp.	New York, NY	10010
recall	Value Merchant's Inc.	New York, NY	10010
recall	Hickory Hills	Clifton, TN	38425
recall	Lovee Doll and Toy Co., Inc.	Brooklyn, NY	11207
recall	Amret Inc. dba Bargain Town	Montgomery, AL	36127
recall	TPI of IL/Dollar Bill	Crestwood, IL	53202
recall	TPI of IL/Dollar Bill	Crestwood, IL	53202
recall	TPI of IL/Dollar Bill	Crestwood, IL	53202
recall	Baby Plus Products, Inc	Farmingdale, NJ	07727
recall	Creative Products/Toy Time	Skokie, IL	60077
recall	F A.O Schwarz	New York, NY	10153
recall	F.A O. Schwarz	New York, NY	10153
recall	Tara Toys	Hauppauge, NY	11788
recall	Mathews/Hallmark	Baltimore, MD	37698
recall	Baby Plus Products, Inc	Farmingdale, NJ	07727
recall	Dollar Kraze, Inc.	Hammond, IN	46323
recall	Geneva Pharmaceuticals, Inc.	Broomfield, CO	80038
recall	Tara Toys	Hauppauge, NY	11788
recall	Tara Toys	Hauppauge, NY	11788
recall	Animal Quaker Ltd.	Greensboro, NC	27408
recall	Animal Quaker Ltd	Greensboro, NC	27408
recall	Animal Quaker Ltd.	Greensboro, NC	27408
recall	Animal Quaker Ltd	Greensboro, NC	27408
recall	Animal Quaker Ltd.	Greensboro, NC	27408
recall	Animal Quaker Ltd	Greensboro, NC	27408
recall	Animal Quaker Ltd.	Greensboro, NC	27408
recall	The Sail Harbor, Inc.	Freehold, NJ	07728

DATE	PRODUCT	MODEL	VIOLATIONS	CITATION
04/92	Tub Pets	#31-062	small parts	16 CFR 1501
04/92	Necklace	#134-035	hazardous substance	16 CFR 1500.4
04/92	Putt-Putt Orange Paint	#12432	lead-in-paint	16 CFR 1303
04/92	Rooster Puzzle	#MTC-2033	lead-in-paint	16 CFR 1303
04/92	Kiddy Phone	#888	small parts	16 CFR 1501
04/92	Toy Wooden Block Truck	#GW-25	small parts	16 CFR 1501
04/92	Toy Nursing Bottles	#6607,8	small parts	16 CFR 1501
04/92	Hungry Jack Bear	(None)	sharp point	16 CFR 1500 48
05/92	T-Shirts (Big Brother)	#214	small parts	16 CFR 1501
05/92	T-Shirts (Fishin' Buddy)	#204	small parts	16 CFR 1501
05/92	Plastic Trumpet	#2747/367	small parts	16 CFR 1501
05/92	Cotton Terry Cloth Robe Floral	#100-736	flammability	16 CFR 1610
05/92	Reverse Fleece Top Sweatshirt	#41-10886	flammability	16 CFR 1610
05/92	Evenflo Toy Nursers	#8075-9	small parts	16 CFR 1501
05/92	14" Plush Rabbit	#3692	small parts	16 CFR 1501
05/92	Sesame Street Nursery Set	#71700-Ernie	small parts	16 CFR 1501
05/92	Pull Along Choo Choo Phone	#368	small parts & sharp points	1501, 1500 48
05/92	Teaching Bear with Cap	#97799	small parts	16 CFR 1501
05/92	Bunny On A Stick	#0789742094090	rattle	16 CFR 1510
05/92	Oil Filled Lamps	3 oz "Li'l Lites"	fails crc	16 CFR 1700 14
05/92	Sesame Street Nursery Set	#71700-Big Bird	small parts	16 CFR 1501
06/92	Citrus Brake Parts Cleaner	#4001	labeling	16 CFR 1500 12
06/92	Hanging Checkerboard	#0Q099	lead-in-paint	16 CFR 1303
06/92	1992 Racing Bicycles	#2R800 & 2R900	handlebars	16 CFR 1512
06/92	Wind-Up Circus Toy	#9026W	small parts	16 CFR 1501
06/92	Cartoon Telephone Car	#UL-106S	small parts	16 CFR 1501
06/92	Telephone Car	#YL-111	small parts	16 CFR 1501
06/92	Baby on Swimming Ring	#1055	small parts	16 CFR 1501
06/92	Baseball Cap	#HS-9	small parts	16 CFR 1501
06/92	Turtle Telephone	#80997	small parts	16 CFR 1501
06/92	Pretty Mate (Tea Set w/Basket)	#E20	small parts	16 CFR 1501
06/92	Infant Cap	#600	small parts	16 CFR 1501
06/92	Lovely Telephone	#683	small parts	16 CFR 1501
06/92	BMX Style Bicycles	#875707 - Girls	stem closure	16 CFR 1512
06/92	BMX Style Bicycles	#875705 - Boys	stem closure	16 CFR 1512
06/92	Wind-Up Kiddy Phone	#997288	small parts	16 CFR 1501
07/92	Press and Go Baby Buggy	#7403	small parts	16 CFR 1501
07/92	Crib Center	#1525	lead-in-paints	16 CFR 1303
07/92	Stuffed Animal/Activity Toy	#34071 - Elephant	small parts	16 CFR 1501
07/92	Stuffed Animal/Activity Toy	#34070 - Bear	small parts	16 CFR 1501
07/92	Pull Along Loco	#T105002	small parts	16 CFR 1501
07/92	Evenflo Toy Nurser	#8567132	small parts	16 CFR 1501
07/92	16" Sidewalk Bicycle	(None)	brakes	16 CFR 1512
07/92	12" Sidewalk Bicycle	#901	brakes	16 CFR 1512
07/92	Woman's Scarf	#101-2558 and 1	flammability	16 CFR 1610
07/92	Plush Animal Stocking	#13845 - Bear	small parts	16 CFR 1501
07/92	Plush Animal Stocking	#13846 - Dog	small parts	16 CFR 1501
07/92	Plush Animal Stocking	#13847 - Panda	small parts	16 CFR 1501
07/92	Plush Animal Stocking	#13848 - Reindeer	small parts	16 CFR 1501

ACTION	MANUFACTURER/IMPORTER	CITY & STATE	ZIP CODE
recall	Toy Power	Los Angeles, CA	90013
recall	Rosecraft, Inc	Woonsocket, RI	02891
recall	Southern Gold Distributors	Fayetteville, NC	28303
recall	Animal Quaker Ltd.	Greensboro, NC	27408
recall	Toy Power	Los Angeles, CA	90013
recall	Everything's A Dollar, Inc	Milwaukee, WI	10018
recall	M. Ginsburg and Co	Chicago, IL	60607
recall	The Pillsbury Co	Minneapolis, MN	55414
recall	Adorable Originals	Phoenix, AR	85003
recall	Adorable Originals	Phoenix, AR	85003
recall	Almacenes Pitusa	San Juan, PR	00919
recall	Victoria's Secret Catalog	Reynoldsburg, OH	43068
recall	Sears and Roebuck, Co	Chicago, IL	60684
recall	Chilton-Globe, Inc	Manitowoc, WI	54220
recall	KMS, Inc.	Wichita, KS	67206
recall	Tara Toys	Hauppauge, NY	11788
recall	Charles Products, Inc.	Rockville, MD	20852
recall	Chadwick Miller, Inc.	Canton, MA	02021
recall	Wal-Mart Stores, Inc.	Bentonville, AR	72716
recall	Kaadon, Ltd	Lancaster, PA	17603
recall	Tara Toys	Hauppauge, NY	11788
recall	IG-LO, Inc	Lexington, KY	40509
recall	Cape Shore, Inc.	Yarmouth, ME	04096
recall	Cannondale Corp.	Georgetown, CT	06829
recall	Kraemer Mercantile Corp.	New York, NY	10010
recall	Kraemer Mercantile Corp.	New York, NY	10010
recall	Kraemer Mercantile Corp.	New York, NY	10010
recall	Polly-Gaz International	New York, NY	10001
recall	Polly-Gaz International	New York, NY	10001
recall	Kraemer Mercantile Corp	New York, NY	10010
recall	Polly-Gaz International	New York, NY	10001
recall	Sunset Hat Manufacturing Co	Brooklyn, NY	11211
recall	Kraemer Mercantile Corp	New York, NY	10010
recall	Kent International, Inc.	Kearny, NJ	07032
recall	Kent International, Inc	Kearny, NJ	07032
recall	Kraemer Mercantile Corp.	New York, NY	10010
recall	Unique Industries	Philadelphia, PA	19148
recall	Little Tikes Co.	Hudson, OH	44236
recall	ABC Distributing Inc.	North Miami, FL	33181
recall	ABC Distributing Inc.	North Miami, FL	33181
recall	Everlast Industrial Co.	New York, NY	10018
recall	Chilton-Globe, Inc.	Manitowoc, KS	67206
recall	Santa Fe Trading, Inc.	Houston, TX	77036
recall	Santa Fe Trading, Inc.	Houston, TX	77036
recall	A. Brod, Inc.	New York, NY	10016
recall	ABC Distributing Inc.	North Miami, FL	33181
recall	ABC Distributing Inc.	North Miami, FL	33181
recall	ABC Distributing Inc.	North Miami, FL	33181
recall	ABC Distributing Inc	North Miami, FL	33181

DATE	PRODUCT	MODEL	VIOLATIONS	CITATION
08/92	Totally Rad Flyer Bicycle	#TR12 - 12"	brakes	16 CFR 1512
08/92	Toy Magic Feeding Bottles	#330221	small parts	16 CFR 1501
08/92	Lil' Miss Flyer Bicycle	#LM13 - 12"	brakes	16 CFR 1512
08/92	Colortone Eight Crayon Box	#5-CL-850	lead	16 CFR 1303
09/92	100 Capsule Diphenhydramine	25mg	fails crc	16 CFR 1700 14
09/92	Thunder Max 2000 Ride-On Toy	#4031	lead-in-paint	16 CFR 1303
09/92	Wooden Baby Rattle	#G-TOY	rattle	16 CFR 1510
09/92	Plastic Rattle and Flute Toy	#42979	small parts	16 CFR 1501
09/92	My First Buddy's Pop Pop Car	#4562	small parts	16 CFR 1501
09/92	Action Train	#BB3157	small parts	16 CFR 1501
09/92	Melody Bus	#BB126	small parts	16 CFR 1501

<u>ACTION</u>	<u>MANUFACTURER/IMPORTER</u>	<u>CITY & STATE</u>	<u>ZIP CODE</u>
recall	Radio Flyer, Inc.	Chicago, IL	60635
recall	Toys "R" Us	Paramus, NJ	07652
recall	Radio Flyer, Inc.	Chicago, IL	60635
recall	Dynamic Stationery Manufacturing Inc	Hollis, NY	11423
recall	Moore Medical Corp.	New Britain, CT	06050
recall	SLM	Gloversville, NY	12078
recall	Pacific Spirit	Forest Grove, OR	97116
recall	The Dollywood Co.	Pigeon Forge, TN	37863
recall	Meijer Inc.	Grand Rapids, MI	49504
recall	Battat Inc.	Plattsburgh, NY	12901
recall	Battat Inc.	Plattsburgh, NY	12901

**VOLUNTARY CORRECTIVE ACTION PLANS UNDER
SECTION 15 OF THE CONSUMER PRODUCT SAFETY ACT AND
SECTION 15 OF THE FEDERAL HAZARDOUS SUBSTANCES ACT**

DATE	FIRM AND PRODUCT	ALLEGED HAZARD	REMEDY
10/91	S C. Johnson & Son Racine, WI Glade Plug-In Air Freshener, SCJ001	Possible fire hazard in units made prior to September 1990 due to error in winding the resistance wire on heater's core. Unit may overheat	Changes were made in the manufacturing process and quality control to correct future production
10/91	Lord Howards Newark, OH Super Jet Toy Helicopter, 32930	The unshielded tip of the helicopter rotor may strike user's eye	A free replacement rotor with a shielded tip is offered to consumers. For a free replacement part, contact company or place of purchase
10/91	Power Cords & Cables College Point, NY 11256 Extension Cords	Fire and shock hazard	Prospective corrective action. No recall
10/91	Maytag Corporation Newton, IA 50208 Magic Chef and Hardwick Gas Ranges Models 24 and 24V8	Misalignment of the broiler burner baffle may produce excessive amounts of potentially dangerous carbon monoxide.	Magic Chef conducted a field repair program and redesigned the baffle to prevent misalignment in future production.
10/91	Caloric Corporation Florence, SC Models RLS312 and RLS340 30-inch Freestanding Gas Ranges	Some ranges distributed in January and February 1990 may have an improper seal between the thermostat and the manifold pipe. If gas were to leak it could present a fire or inhalation hazard.	Caloric arranged for the free inspection and repair of all suspect units.

DATE	FIRM AND PRODUCT	ALLEGED HAZARD	REMEDY
10/91	Lam Lighting Systems Santa Ana, CA Luxxtra 1800 and 2400 Series 250 Watt Metal Halide Lighting Fixtures	Deformation of the Mogul Socket Cap can cause the lamp housing to fall from the ceiling stem attachment. If one is struck below, severe head or bodily injuries could result.	For light fixture installations from 1980 through 10/90, the company will provide a retrofit kit to hold the lamp housing in place should failure occur.
10/91	Schwinn Bicycle Company, c/o Keck, Mahin & Cate Chicago, IL 60606 Front Brake Stud on Cantilever Brake System	Brake failure could cause loss of bicycle control and subsequent fall to rider	The firm notified all dealers and consumers via letter of the potential problem and asked that the Hungarian made Woodlands models be recalled and replaced with the US made High Plains. Those Woodlands models not made in Hungary are not subject to the recall.
10/91	O'Brien International Wichita, KS 67201 Max Freeboard Ski Board	Instructions for use are not included with product, user may be injured by inappropriate use of product	Notice to all dealers and distributors to inform customers and insert instructions in current inventory Notice to warranty card holders.
10/91	Nationmark Inc. Carrollton, TX 75006 Magic/Excite 8 Shot Cap Gun, #706	Burns may occur from sparks emitted from barrel of guns missing a barrel plug.	Joint news release and retail posters recalling cap guns Refund of purchase price

DATE	FIRM AND PRODUCT	ALLEGED HAZARD	REMEDY
10/91	WSI Camarillo, CA 93012 Diamond Back; Prevail TG; Master TG; and Expert TG Bicycles Rear Wheels	Possible loss of control of bike resulting in a fall to the rider	The firm offers a replacement rear wheel free to consumers and dealers.
10/91	Skil Corporation Chicago, IL 60646 Models 7313 and 7320 Belt Sanders	The on/off switch may stick in the on position and could cause abrasions or possibly lacerations to users	Consumers can return their sanders to the place of purchase or to a service center for a no charge repair.
11/91	Harvard Interiors St Louis, MO Rotary Office Chairs	The chair seat could separate from its supporting base causing user to fall	Consumers will be sent a replacement spindle bracket upon request All units sold through mail order houses
11/91	Wells Technology Ivyland, PA 169974 Coal and wood burning stoves	Electrocution	The firm added a third ground wire to the Bumble Bee Unit and no longer offers it in consumer distribution channels The firm also revised instruction manuals to address the identified concerns
11/91	Tudo Electric Brooklyn, NY 18 awg size extension cords and related products	The firm's 18 awg size extension cords failed to incorporate over current protection devices	The firm terminated the purchase and sale of the subject extension cords and related products.

DATE	FIRM AND PRODUCT	ALLEGED HAZARD	REMEDY
11/91	Metro Marketing Gardena, CA Wok Skillet	A user may sustain thermal burn injuries if the handle of the wok turns spilling hot contents on user.	Firm corrected its inventory by improving assembly instructions clarifying need to properly engage the stabilizing fins of the handle.
11/91	Thermo Products North Judson, IN 46366 Model GL 16-160 Forced Air Central Gas Furnace	A baffle that was mistakenly inserted into the furnace flue could cause the production of dangerous levels of carbon monoxide.	The firm will repair the furnaces at no charge to consumers. Consumers can call 1-800-348-5130 (1-800-331-4352 in Indiana).
11/91	Kmart Corporation Troy, MI 48084 Gift Gallery Potpourri Burner, Item #22-00-21	The burning candle may scorch the surrounding surface area and/or present a risk of fire if near flammable objects.	The firm issued a joint news release recalling the product and offering consumers a full refund.
11/91	Standex International Corporation Salem, NH 03079 General Slicing food chopper models D,E,H,K,P,S, & 122 manufactured prior to 1979	If consumers use their hands to push food down the neck of the chopper, rather than the wooden pusher provided by the firm, their fingers may come in contact with the grinding mechanism and be severely injured	Consumers should call 1-800-321-7583 to receive a free replacement head that will lessen the potential for injury.

DATE	FIRM AND PRODUCT	ALLEGED HAZARD	REMEDY
12/91	First Alert Division of BRK Aurora, IL 60504-2495 Model 202A Smoke Detector	Certain smoke detectors were packed <i>with no English</i> language instructions Smoke detector instructions contain critical information such as placement and maintenance <i>information.</i>	Additional copies of the instruction <i>manuals were sent to</i> all retail locations Undistributed stock was inspected and corrected as necessary
12/91	Sears, Roebuck and Company Chicago, IL 60684 "Sears Kenmore" 90% + High Efficiency Gas Furnaces with a Durafused heat exchanger	Flaking and cracking of the ceramic coating on the heat exchanger could lead to corrosion <i>and sooting of furnace</i> components This may result in the production and migration of carbon monoxide into the living environment <i>which could present a</i> health hazard.	The firm is replacing the Durafused heat exchangers with new stainless steel heat exchangers Consumers may call toll free 800-237-5871 for information
12/91	Bard Manufacturing Bryan, OH 43506 Model CH100D60B Gas Furnace, serial nos H900653577 thru H900653676	Some of these furnaces were assembled without a <i>flue gas baffle in the</i> primary heat exchanger This could lead to the production of excessive amounts of carbon monoxide	Free inspection and repair of all units

DATE	FIRM AND PRODUCT	ALLEGED HAZARD	REMEDY
12/91	The Toro Company Minneapolis, MN 55420 Vision II Series Irrigation Controller, Model No. 189-66-01, 189-96-01, 189-06-01	The metal cabinet of the controller may not be electrically grounded. Contact with the non insulated energized parts of the metal cabinet, including the key lock, could present a severe electric shock or an electrocution hazard	Owners should contact Toro at 800-367-8676 or 800-255-8676 inside California for free repair
12/91	Kmart Corporation Troy, MI 48084-3163 "Moroccan Sand" Patio Chair	The chair may collapse possibly causing bodily injuries to its occupant.	The firm recalled the defective chairs offering owners replacement chairs.
12/91	Devan Designs, Inc Marion, NC Furniture	Easy gliding rollers on drawers may cause several drawers to extend fully, causing the furniture to tilt and fall forward.	Modification kit offered to prevent drawers from sliding open and to increase the stability of the units
12/91	Trailhawke Tree Stands LaCrosse, WI 54601 Trailhawke Vantage Point Tree Stand	Mounting pin failure causing possible fall to hunter who could incur broken bones or head injury.	The firm will replace mounting pins free of charge to all customers.
12/91	Bombardier, Inc. Quebec, Canada 1991 Safari Model Ski-Doo Snowmobiles	The improper tightening of steering bolts may result in the loss of steering control.	Consumers are instructed to return their vehicles to their dealer for proper tightening of the steering bolts.

DATE	FIRM AND PRODUCT	ALLEGED HAZARD	REMEDY
12/91	Mattel, Inc El Segundo, CA 90245-5012 Disney Poppin' Sounds Pull Train	During use, small balls enclosed in a dome on the toy train's smokestack may become accessible to young children and pose a potential choking/ingestion hazard.	Consumers should return the toy to Mattel Consumer Affairs, 15930 East Valley Boulevard, City of Industry, CA 91744 for a full refund.
12/91	Bombardier Inc Quebec, Canada 1992 Formula Plus XTC E and Mach 1 Snowmobiles	Hand brake cable is <i>improperly crimped</i> and may separate during use creating a no brake situation	Consumers are <i>instructed to return</i> their vehicle to their dealer for replacement of the brake cable
12/91	Bombardier Inc Quebec, Canada 1992 Safari LE Snowmobile	<i>Improper installation of</i> ski-leg circlip can result in a total loss of steering.	Consumers are instructed to return their vehicle to their dealer for proper installation of the circlips
12/91	U S. Divers/Aqua-Lung Santa Ana, CA 92799 Micra & Select 2nd Stage SCUBA regulator - mouthpieces	In certain dive situations it is possible to pull the mouthpiece from the 2nd stage This could pose a possible drowning or <i>air embolism in the</i> very worst scenario	The firm attached a plastic tie around the 2nd stage regulator mouthpiece to hold it in place. Repair is done free of charge with a \$1 credit to each dealer.
01/92	Better Electrical Products, Ltd Kowloon, Hong Kong Garment Steamer	Water fill plug can break causing steam or hot water to leak from the back of the steamer and burn the user.	Return unit to mail order company for refund

DATE	FIRM AND PRODUCT	ALLEGED HAZARD	REMEDY
01/92	W W. Grainger, Inc North Suburban, IL 60251 "Dayton" 90% + High Efficiency Gas Furnaces with a Durafused heat exchanger	Flaking and cracking of the ceramic coating on the heat exchanger could lead to corrosion and sooting of furnace components. This may result in the production and migration of carbon monoxide into the living environment which could present a health hazard.	The firm is replacing the Durafused heat exchangers with new stainless steel heat exchangers. Consumers may call toll free at 800-237-5871 for more information
01/92	Tiger Electronics Vernon Hills, IL Toy Action Figure "Planeteer Wheeler"	A spark generator in toy action figure's open chest emits sparks. If the toy is misused, combustible materials could ignite.	The open chest hole was covered with a transparent plastic shield beginning in July 1991
01/92	Micro-Dome San Ramon, CA 94583 Microwave food preserver, all models	The plastic container may explode during or after use in a microwave oven causing injury to users There is also concern of food poisoning resulting from the use of the device	The firm recalled the product offering a \$50 refund to owners
01/92	Johnson Controls Milwaukee, WI 53201 G53 Gas Valves	The valves were used on Trane propane furnace models XL80 and XL90 manufactured week 35 of 1987 through week 44 of 1988 (B35 through C44 serial numbers). Under certain circumstances the valves may leak and could present fire or explosion hazards.	The firm will replace the suspect valves. Contact Johnson Controls at 1-800-285-8085

DATE	FIRM AND PRODUCT	ALLEGED HAZARD	REMEDY
01/92	Sun Refining and Marketing Company Philadelphia, PA 19103-1699 "#2" heating oil contaminated with gasoline.	The gasoline in the heating oil could present a fire hazard	The firm identified all deliveries and distribution of the contaminated fuel and recovered the questionable fuel
01/92	Rubbermaid - Allibert, Inc. Wooster, OH 44691 Molded plastic stackable chair, model 42022	When used on a hard or slippery surface, the chair may collapse.	The firm recalled the chair offering refunds of the purchase price to consumers
01/92	Century Products Company Macedonia, OH 44056 1991 Wind-Up Infant Swing (Models: 12-319; 12-329, 12-344, 12-349)	<i>Injuries have occurred to consumers who were trying to open the plastic cover over the motor or repair swings that had stopped working</i> When the cover is removed, the coiled wind-up spring will unwind rapidly and forcefully and may cause serious injury.	Consumers should call 1-800-446-1366 for information and to arrange for a free replacement motor and instructions for repair
01/92	Milwaukee Electric Tool Corp. Brookfield, WI 53005 Hand held circular saws	A consumer could contact the unguarded portion of blade resulting in laceration or amputation.	Saws should be returned for free installation of missing blade guards.

DATE	FIRM AND PRODUCT	ALLEGED HAZARD	REMEDY
01/92	Namco-America, Inc. Santa Clara, CA 95054-3013 "Starblade" Arcade Video Game	The video game uses a large mirror in the display. If the video game is exposed to strong natural light, the focused sunlight could lead to a fire	All "Starblade" games will be retrofit with a new mirror to reduce the temperature of the focused light, and labels warning of the hazard
02/92	Softplay Charlotte, NC 29210 Cargo Climb Net on Model M3-5 Ball Pit	Size of net openings may allow children's heads to enter but not exit Potential for strangulation.	Firm provided all customers with new net (with 3.5 X 3 5" squares) for installation over old net to prevent head entry.
02/92	K&M Associates Providence, RI 02940 Kaleidoscope necklace for children	Cap end of kaleidoscope may come off, exposing small parts inside which may present a choking hazard.	Cash refund offered upon return of product to retailer. Notice through press release and recall posters.
02/92	Toastmaster Inc. Columbia, MO 65202 Four Slice Toaster, Model No. D126T (Date Codes EL101 through EL158)	Some toasters have defective double pole switches Switch failure could create a fire, contact burn, or severe electric shock hazard.	For a free replacement, consumers should call Toastmaster at 1-800-527-3069, or write Operations Manager, Toastmaster Inc., Second and Vine Streets, Boonville, MO 65233

DATE	FIRM AND PRODUCT	ALLEGED HAZARD	REMEDY
02/92	PCA Industries St Louis, MO 63120 Rubber sling seat #582-950 for public playground sets	Rivets on ends of seats may pull out. Potential exists for injuries to children from falls if the seat breaks during use.	Replacement seats provided to consumers who call 800 number
02/92	Lawrence Jewelry Eden Prairie, MN 55344 Kaleidoscope necklace for children	Cap end of kaleidoscope may come off, exposing small parts inside which may present a choking hazard.	Cash refund offered upon return of product to retailer Notice through press release and recall posters.
02/92	Kransco San Francisco, CA Power-Wheels Porsche, 18-volt, battery operated, ride-on toy	Foot switch sticks. Riding toy remains in the "on" position, moving forward	Return riding toy to retailer for full refund
02/92	McCrorry Corporation York, PA 1991 Solid Brass Electric Candle Light, Item No.889840	A defective candle light could short circuit when plugged in and turned on A short circuit could create a fire, thermal burn, or electric shock hazard for anyone nearby or holding the product or its power cord.	Refund for any recalled candle light returned to a McCrorry retail store
02/92	Rawlings Sporting Goods Company Willoughby, OH 44094 Rawlings Batting Tee	A metal stake that anchors a cord attached to a ball into the ground, may pull out and strike the head or body of participants	Free redesigned product for consumers Recall notices posted in retail stores

DATE	FIRM AND PRODUCT	ALLEGED HAZARD	REMEDY
02/92	Prym-Dritz Corp Spartanburg, SC 1991 Electric Welcome Lamp, Model No. 1401	A defective candle light could short circuit when plugged in and turned on. A short circuit could create a fire, thermal burn, or electric shock hazard for anyone nearby or holding the product or its power cord.	Refund for any recalled candle light returned to a House of Fabrics, Inc. retail store.
02/92	Hamakor Judaica Niles, IL 60648 Chanukah menorah (Noah's Ark)	The menorah may catch fire causing personal injury or property damage.	Consumers were asked to return product for refund of purchase price or credit towards other purchase.
03/92	Meijer Corporation Grand Rapids, MI 49504-9428 Molded plastic patio chair model 43-SC2134	When the chair is used aggressively or by a person in excess of 200 pounds, it may collapse	The firm recalled the chair offering consumers a refund of the purchase price.
03/92	Island Wood Products Mableton, GA 30059 Fort Apache, Kitty Hawk, Tree Top, Islander, Pirates Fort, Lookout Tower swing sets with gliders.	Protruding bolts on glider may cause head or body lacerations.	Free retrofit hardware kit provided to consumers who call 800 number

DATE	FIRM AND PRODUCT	ALLEGED HAZARD	REMEDY
03/92	Wisdom Manufacturing Inc. (WMI) Sterling, CO "Gravitron" amusement ride	If a ride failure occurs during use, patrons could be thrown from the ride and injured.	The firm has made design modifications to correct the problem and has notified all 120 ride owners and operators. Future production will have the design changes and inspection procedure changes
03/92	Ace Novelty Company Bellevue, WA 98009 Ninja Turtle Bean Bag chair, Model 28502, Little Mermaid, World Wrestling, Minnie & Me, Major League Baseball, and generic Red, Blue and Yellow	Chairs have two zippers which may be opened by small children The styrofoam pellets inside may be inhaled and are a potential choking hazard.	Denison locks will secure zippers to prevent access to styrofoam pellets A warning label will be attached to the lock
03/92	Eagle Electric Long Island City, NY Extension Cords	The firm's 18 AWG size and smaller extension cords failed to incorporate over protection devices.	The firm discontinued to manufacture 18 AWG size and smaller extension cords
03/92	Alston Quality Industries, Inc Linden, NJ 07036 MOBELSEDIA folding metal framed chairs Models IF1530, IF1532, IF1533	The chairs have the potential to collapse while in use	The firm implemented a replacement program offering consumers a safer chair

DATE	FIRM AND PRODUCT	ALLEGED HAZARD	REMEDY
03/92	Woods Wire Products Carmel, IN No. 1468 Remote Control Receiver	Some remote control receivers may have an internal wiring problem. The product could short circuit and present a fire hazard.	Receivers sold in 1991 should be returned to Woods Wire Products, Inc., P O. Box 2675, Carmel, IN 46032-6675 for inspection and replacement if needed. Owners may call the Woods toll-free Helpline at 1-800-447-4364 if questions arise.
03/92	Grumbacher Cranbury, NJ Art and Craft Paint Brushes	Potential exposure to the high lead content in the coating on the handle of the brush	Return to retail store for a refund.
03/92	Kenner Products Cincinnati, OH "ColorBlaster" Children's Spray Art Toy	Pump assembly can separate from air tank and strike user or bystander.	Call Kenner at 1-800-327-8264 to receive a new pump assembly, or return to place of purchase.
03/92	Apple Computer Cupertino, CA 95014 Model M5417 ni-cad Battery for Laptop Computers	If the contacts are accidentally shorted, a fire may occur	Apple is providing an insulating storage case and warning labeling to all owners.
04/92	BSN Corporation Dallas, TX 07752 Mobile Soccer Goals	Head trauma, broken bones and or death can result from a crushing blow by the goal tip-over.	The firm has labeled all post production mobile soccer goals and mailed labels to those customers with older production.

DATE	FIRM AND PRODUCT	ALLEGED HAZARD	REMEDY
04/92	Kwik Goals Ltd Quakertown, PA 18951 Mobile Soccer Goals	Head trauma, broken bones and or death can result from a crushing blow by the goal tip-over.	The firm has labeled all post production mobile soccer goals and mailed labels to those customers with older production.
04/92	Jayfro Corporation Waterford, CT 06385 Mobile Soccer Goals	Head trauma, broken bones and or death can result from a crushing blow by a goal tip-over.	The firm has labeled all post production mobile soccer goals and mailed labels to those customers with older production.
04/92	Goal Sporting Goods Essex, CT 06426 Mobile Soccer Goal	Head trauma, broken bones and or death can result from a crushing blow by the goal tip-over	The firm has labeled all post production mobile soccer goals and mailed labels to those customers with older production.
04/92	Newco Inc Janesville, WI 53545 Swing N Slide belted seat brackets	Serious lacerations to arms, legs, groin and face can result from open brackets on the belted swing seats	Consumers who call 800 number will receive new brackets, if they cannot completely close the bracket hooks

DATE	FIRM AND PRODUCT	ALLEGED HAZARD	REMEDY
04/92	Unical Enterprises City of Industry, CA 91745 100 Miniature Lights, Strata 5-Way Flashing	The product has no overcurrent protection, the #24 AWG wire size is deemed inadequate, and the current carrying wires can be broken by insertion of another light set plug into the female receptacle of the plug cap. Damage to the wire or product insulation during the life of the product could expose the conductors to overheating, arcing, or short circuit conditions, creating a fire hazard.	All shipments of the product in 1991 were to Mexican accounts
04/92	Unical Enterprises City of Industry, CA 91745 100 5-Way Flasher Light Set (100 Miniature Light Set)	The product has no overcurrent protection and the #24 AWG wire size is deemed inadequate. Damage to the wire or product insulation during the life of the product could expose the conductors to short circuit or arcing conditions, creating a fire hazard	All shipments of the product in 1991 were to Mexican accounts
04/92	Allan Herschell Co. North Tonawanda, NY Childrens Skyfighter Amusement Ride	Moving parts can experience metal fatigue and break. A child could be thrown from the ride or the airplane tub could fall.	Notices to state officials, insurance companies, and national amusement ride organizations.

DATE	FIRM AND PRODUCT	ALLEGED HAZARD	REMEDY
04/92	Sybo Crib World Dallas, TX Tie back ribbon for crib canopy drape	The long ribbon on the canopy drape could create a strangulation hazard.	The firm offered a shorter replacement bow to crib owners.
04/92	Amana Refrigeration Amana, IA Electric Room Air Conditioner	Configuration of the control switch may, if contamination is present, permit arcing and possible fire	Control switches are being replaced with a redesigned switch to prevent the hazard
04/92	Catalina Lighting Miami, FL 33015 1991 Dana Brass Candle Lamp, Model 941	A defective candle light could short circuit when plugged in and turned on. A short circuit could create a fire, thermal burn, or electric shock hazard for anyone nearby or holding the product or its power cord	Refund for any recalled candle light returned to a Bradlees retail store
04/92	Mitsubishi Electric America, Inc Cypress, CA 90630 AC power adaptors (model DA-U1) for use with video camcorders	If a consumer contacts <i>exposed metal on a</i> defective unit while it is in use, there is a possibility of electric shock.	Consumers to return <i>defective units for</i> replacement.
04/92	McCulloch Corp. Tucson, AZ 85706 Gasoline powered string trimmers (11 models).	Clutch components <i>might break through</i> the housing and strike an operator or bystander.	Consumers who return <i>affected models will</i> receive a free replacement.

DATE	FIRM AND PRODUCT	ALLEGED HAZARD	REMEDY
04/92	Delair Group, Inc Delair, NJ "A" Frame Pool Ladder	Fingers or hands can get caught in the spacing between the handrail and sideplate and get injured.	Delair will supply replacement parts for home repair
04/92	Monsanto Company St. Louis, MO 63167 Greensweep lawn care products	When used or operated improperly, the valve on the applicator bottle may leak product and contact the skin or the valve might under certain circumstances be forcibly ejected and strike someone	Firm added hang tag and label with more detailed instructions and added an instructional message to television commercials. Valve has also been redesigned to prevent improper operation
04/92	Ektelon, Inc San Diego, CA 92123 Raquetball eyeguards "Interceptor"	When hit directly by a raquetball, the lens could pop inward and cause injury to the eye and surrounding facial area.	The firm recalled to the consumer level, with notice of the recall published in Consumer Reports and in the American Raquetball Association Magazine.
05/92	Kawasaki Motor Co Irvine, CA 4 wheel ATV	Loss of control due to failure of steering column.	Firm examined remaining inventory and found no failures similar to the one noninjury report which prompted the investigation.
05/92	C & A Trading Co. Hayward, CA Bunk Beds	Head entrapment and body crushing injury due to deviations from voluntary industry standard and lack of foundation supports.	Free replacement kits for bunk beds offered to owners through newspaper ads.

DATE	FIRM AND PRODUCT	ALLEGED HAZARD	REMEDY
05/92	Bruce Loader Designs Emeryville, CA 94608 Bunk Bed Item #6151	Guard rail head entrapment causing a strangulation hazard	Firm to provide free safety guard rails to all consumers that purchased the bunk beds
05/92	Milwaukee Electric Tool Corporation Brookfield, WI 53005 Electric cord set	Electric shock due to miswiring	Consumers to receive a free replacement cord set
05/92	Hamilton Beach/Proctor-Silex Glen Allen, VA 23060 Models 230 and 232 hand-held mixers	Broken fan blade pieces may contaminate food and cause mouth and tooth injuries.	Consumers to receive newly designed mixers
05/92	Duracraft Corp Sudbury, MA 01776 16 in. Brass or Platinum plated Fans, DP-161, DP-1601 and DP-1602	The fan blades may fracture while in use possibly hitting someone nearby.	The firm offered replacement blades to owners of the fans
05/92	Wagner Spray Tech Corporation Minneapolis, MN 55440 System 425 and 525 Airless Paint Sprayers	Sparks from the product's motor may ignite certain flammable fumes which might be used for painting or cleanup This could present a fire hazard	Wagner redesigned the unit in August 1991, and will retrofit existing units at no charge 1-800-328-8251, ext 7170
05/92	Bushwacker Back Pack Missoula, MT 59806 Counter Assault Personal Defense Sprays	This aerosol canister of red pepper may not activate when needed possibly allowing the user to be attacked	The firm recalled the product and redesigned it to correct the problem.

DATE	FIRM AND PRODUCT	ALLEGED HAZARD	REMEDY
05/92	Fingerhut Corporation Minnetonka, MN Steam Iron - "Steamagic"	Severe electrical failures may result in fire or electrical shock.	Each consumer is notified by mail. Those who return the "Steamagic" cord and handle will receive credit or a free replacement electric clothes steamer.
05/92	Roper Corporation LaFayette, GA 30728 Electric Slide-In Range	Cooktop may be energized and pose an electric shock hazard.	Firm notified all warranty card holders of problem and offered to fix defect free of charge. All newly manufactured models were fixed during production.
05/92	Sellner Manufacturing Company, Inc. Fairbault, MN Spin-The-Apple & Berry-Go-Round Amusement Rides	Steering wheel rod holding the ride's tubs to the carriage arm could break during transport.	Carnival owners required to replace steering wheel shafts with larger diameter shafts.
05/92	Norelco Consumer Products Company Stamford, CT 06904 Norelco Fabric Steamer/Wrinkle Remover Model TS 60	Insulation on the product's cord may have been damaged during the packaging process, leaving a small amount of the wiring exposed. The exposed wiring presents a possible shock hazard.	Customers and consumers who return the steamers will receive a free replacement steamer or full refund. All postage costs will be refunded.

DATE	FIRM AND PRODUCT	ALLEGED HAZARD	REMEDY
06/92	Murphy Bros Expositions Tulsa, OK 74105 Amusement Ride - "Gravitron"	Riders could be injured or killed if they are thrown from the ride due to a failure to properly assemble, inspect or operate the ride.	The firm will abide by manufacturer and Commission safety bulletins; inspect the ride on a regular basis, and have only authorized and appropriately skilled personnel operate and assemble the "Gravitron".
06/92	Dragons Are Too Seldom, Inc Rapid City, SD Snooze Zoo Instant Heating Pads For Babies, Safe Heating Pad For Babies, Snoopy Safe Heating Pad For Babies	Pad may cause thermal burns to infants if used immediately after removal from microwave oven	Return product to manufacturer for replacement with another infant product of equal value.
06/92	Long Island Consortium Holbrook, NY 9 ft. electric extension cords	Fire and shock hazard	Recall to the consumer level
06/92	Carver Corporation Lynwood, WA 98046 Power Amplifier model M-1 0+	Potential shock hazard	Reposition power transformer and insert fish paper to preclude contact with chassis.
06/92	MTD Products, Inc. Cleveland, OH 44135 Riding lawn mowers	Brake/shift lever assembly separation could diminish operator's control of the vehicle.	Consumers to contact firm for free repair or replacement with correct size screws.

DATE	FIRM AND PRODUCT	ALLEGED HAZARD	REMEDY
06/92	Scripto-Tokai Corporation Fontana, CA Alpha Blue disposable butane cigarette lighter	Persons may suffer thermal burns or property damage may result if a broken lighter is used.	Commercial customers asked to return any unused merchandise for replacement Product was redesigned for later sales
06/92	Nutone, Inc. Cincinnati, OH Ceiling Fans: Models PFD-36, PFD-52, PFH-36, PFH-52, PFL-36, PFL-52, PFM-52, and PFMB-52	Die cast hanger could break causing fan to disconnect from the ceiling and fall to the floor.	Home visit to replace die cast hanger with a sheet metal hanger
06/92	Caldor, Inc. Norwalk, CT 9" Brass Electric Candle, SKU #1949089	A defective candle light could short circuit when plugged in and turned on. A short circuit could create a fire, thermal burn or electric shock hazard for anyone nearby or holding the product or its power cord	Refund for any recalled candle light returned to a Caldor retail store
06/92	Caldor, Inc. Norwalk, CT 11" Brass Electric Candle, SKU #2204743	A defective candle light could short circuit when plugged in and turned on. A short circuit could create a fire, thermal burn, or electric shock hazard for anyone nearby or holding the product or its power cord.	Refund for any recalled candle light returned to a Caldor retail store.

DATE	FIRM AND PRODUCT	ALLEGED HAZARD	REMEDY
06/92	E-Z-GO Division of Textron Inc Augusta, GA E-Z-GO TC III and IV Battery Chargers	An improperly routed electric wire could short circuit to the metal case. If not electrically grounded, the product could present a severe electric shock or an electrocution hazard.	For inspection and repair of their unit(s), owners should contact the E-Z-GO Product Service Dept. at 1-800-241-5855.
07/92	King of Fans Ft Lauderdale, FL 33311 Ceiling Fan Blade Brackets	The blade brackets fail allowing the fan blade to fly off The blades may then cause cuts and bruises if they strike people	King of Fans provided replacement brackets for the failed units.
07/92	Space Age Manufacturing Co. South Pittsburg, TN 37380 Dixie Delight Fireworks Device #RP745	This device may tip over during operation and fire its charges horizontally, resulting in possible serious injury or death to persons nearby	A joint press release was issued 6/29/92 announcing the firm's recall of these devices Consumers should return the devices to the store where purchased for a full refund Consumers may call 800-247-4713 for more information
07/92	Zenith Specialties Clinton, MO 64735 Black Cat Finale Board Fireworks Device	This device may tip over during operation and fire its charges horizontally, resulting in possible serious injury or death to persons nearby	A joint press release was issued 6/29/92 announcing the firm's recall of these devices. Consumers should return the devices to the store where purchased for a full refund

DATE	FIRM AND PRODUCT	ALLEGED HAZARD	REMEDY
07/92	Tracers Furniture Mt. Vernon, NY 10550 Rimini Cribs	The knobs may come off while in use and may pose a choking hazard to infants	Retrofits kits were provided for consumer repairs
07/92	Longhorn Mfg Co Roswell, NM "LH" triple display rack firework device	The device may tip over during operation and fire its charges horizontally. These charges could strike the operator or persons nearby, resulting in possible serious injury or death.	The firm recalled to the consumer level.
07/92	Campbell Hausfeld/Scott Fetzer Company Westlake, OH 44145-1197 U S. Air vertical tank air compressors with Emerson or Doerr 5hp motors.	When wire sheathing between the motor and capacitor is abraded, the current carrying conductors may contact non-current carrying parts of the compressor causing it to become electrified which could present a shock hazard if the unit is not properly grounded	Firm supplied a repair kit for consumer installation to all consumers returning warranty cards.
07/92	Emerson Electric Company St. Louis, MO 63136 5hp Doerr Emerson electric motors used on U.S. Air brand air compressors	Conductors exposed due to vibration may contact noncurrent-carrying parts and cause them to become energized, creating a potential shock hazard if the unit is not properly grounded.	Firm will make changes in future production runs of this and other motors used in high vibration applications. Firm has also provided repair kits to Campbell Hausfeld for units currently in use

DATE	FIRM AND PRODUCT	ALLEGED HAZARD	REMEDY
07/92	Associated Transport and Trading Company Denver, CO 80202 Propane Gas	1 4 million gallons of propane that lacked adequate odorant were distributed April-May 1992. Odorant is an important warning signal in case of a potentially hazardous gas leak	The firm tested locations that received shipments of the gas. If adequate odorant was lacking, the firm added odorant Owners of portable tanks were instructed to bring in their tanks for free refills. 1-800-972-2885
07/92	Aviva Sport, Inc San Francisco, CA 94105 Sound Swing Bat	The sound producing mechanism may break and become a possible projectile hazard	Return to place of purchase for a full refund or mail to Aviva Sport, Attn Nancy Nelson, 15930 East Valley Blvd, City of Industry, CA 91744 for full refund and discount coupon
07/92	American Honda Motor Company, Inc Torrance, CA 90501 Harmony 215 walk behind lawn mower	Foreign objects may be ejected from underneath the mower housing as a result of trailing shield failure	Consumers will receive notice of the defect and be provided a free replacement shield
07/92	Yazoo Mfg Co. Jackson, MS Kawasaki Motors Corp., U S.A. Skakopee, MN Yazoo Model SV26KI-2 26" Walk-Behind Lawn Mower	Heat generated by <i>deflection of exhaust</i> muffler may cause fuel tank to melt and leak fuel Fuel may ignite on hot parts and cause a fire	Return to place of purchase for addition of a deflector plate to prevent overheating.

DATE	FIRM AND PRODUCT	ALLEGED HAZARD	REMEDY
08/92	Diversified Specialist, Inc. Houston, TX 77098 Toy electric guitar with plastic strap	Strap may become entangled around young child's neck and may result in strangulation.	Firm developed a breakaway strap and placed a warning on packaging for future production.
08/92	Funtime Playgrounds Albermarle, NC 28001 Cargo net play equipment at fast food restaurants.	Head entrapment leading to possible strangulation may occur in 5" openings if help is not available to extricate child	Web net with 2 1/2"x3" openings installed by firm over existing cargo nets.
08/92	Venture Stores O'Fallon, MO 37086 Walk "N" Roll Baby Walker, model 882003, style 11484	The brackets holding the baby walker in position may break causing the walker to collapse. An occupant in the walker could sustain an injury.	A joint press release was issued 10/19/92 announcing the firm's recall of these baby walkers. Consumers should return the baby walker to the Venture store where purchased for a full refund
08/92	Family Dollar Stores Matthews, NC 28201 Walk "N" Roll Baby Walker, #882003-1, item 28.96.84	The brackets holding the baby walker in position may break causing the walker to collapse. An occupant in the walker could sustain an injury.	A joint press release was issued 10/19/92 announcing the firm's recall of these baby walkers. Consumers should return the baby walker to the Family Dollar store where purchased for a full refund.
08/92	Lamplight Farms Menomenee Falls, WI Liquid Candle Lamps	Lamps have a bright pumpkin face which is attractive to children. Contents of lamps is toxic.	Product was redesigned to eliminate pumpkin face from lamps. Press release issued warning of hazard.

DATE	FIRM AND PRODUCT	ALLEGED HAZARD	REMEDY
08/92	Northeastern Plastics (NPI) Brooklyn, NY 11215 Extension Cords	Fire and shock hazards.	The firm implemented a prospective corrective action plan
08/92	Parker Hannifin Corporation Wickliffe, Ohio 44092 Gas Hose	Gas hose may leak, posing a fire or explosion hazard.	Firm corrected manufacturing error and undertook recall to recover the defective hose
08/92	Honeywell Inc Golden Valley, MN 55422-3992 V48 and V88 Diaphragm Gas Valves	Valves manufactured in March and April 1991 could stick open, which could cause overheating, fire or delayed ignition.	Honeywell will replace all affected valves. Call 1-800-328-8194 or 1-800-722-0033 (Minnesota)
08/92	J. Kinderman and Sons, Inc. Philadelphia, PA Electric Candle Lamp, Item No. 42-990	A defective candle light could short circuit when plugged in and turned on. A short circuit could create a fire, thermal burn, or electric shock hazard for anyone nearby or for anyone holding the product or its power cord	Refund for any recalled candle light returned to the retail store where purchased
08/92	Brite Star Christmas Decoration (Taiwan) Ltd Taiwan Electric Candle Lamp, Item No. 42-990	A defective candle light could short circuit when plugged in and turned on. A short circuit could create a fire, thermal burn, or electric shock hazard for anyone nearby or for anyone holding the product or its power cord	Refund for any recalled candle light returned to the retail store where purchased.

DATE	FIRM AND PRODUCT	ALLEGED HAZARD	REMEDY
08/92	Honeywell Inc Minneapolis, MN 55422 V48 and V88 Diaphragm Gas Valves	Defects in valves manufactured in September and October 1991 could cause the valves to stick open, which could cause overheating, fires or delayed ignitions.	Honeywell will replace all affected valves Call 1-800-328-8194 or 1-800-722-0033 (Minnesota)
08/92	Diversified Products Opelika, AL Megaflex Home Exerciser	A metal bar on press mechanism rotates allowing a users feet to slip off while performing a leg press exercise. The press mechanism may strike a user in the leg as it forcefully returns to the start position for the exercise.	The firm has designed a repair kit that prevents the bar on the press mechanism from rotating Consumers are being offered the repair kit free of charge The firm also excluded the leg press exercise from the product's owner manuals.
08/92	Scandinavian Designs Petaluma, CA 94952 Bunk Beds	Horizontal rails (siderails) connecting the bed's two headboards may collapse Consumers may then consequently fall from the bed when the siderails collapse	Firm notified all purchasing customers of the defect Firm will provide a replacement siderail at no cost to the consumer.
08/92	Toys "R" Us Rochelle Park, NJ 07662 Musical Toothbush Trainer	Small parts may pose a choking hazard if they separate from the product	In conjunction with the CPSC, the firm issued a press release offering a full refund to consumers with proof of purchase.
08/92	Softplay, Inc. Charlotte, NC 28216 Play equipment-plastic "Fun Run"tunnel	Top edge of tube may cause lacerations to children's heads when they enter tube.	Retrofit of entrance pad to cover top edge of tube.

DATE	FIRM AND PRODUCT	ALLEGED HAZARD	REMEDY
08/92	Braun, Inc Lynnfield, MA Models E200T/E260T Electric Espresso/Cappuccino Maker	Filter holder can dislodge from unit and spray coffee grounds or steam, or shatter glass carafe below	Labels affixed to unit to indicate proper positioning of filter holder handle
08/92	Rainbow Play Systems Prior Lake, MN 55372 Swing hanger (514-004) on Sunshine Castle, Clubhouse, Twin Towers swing sets 5/91 to 6/92.	Hanger may break and may result in falls, serious injuries	Replacement hangers offered to purchasers of sets with defective model hanger
09/92	Blazon-Flexible Flyer, Inc West Point, MS Slide with angled handrail (T-type swing set).	Handrail attachment to slide may present a catch point for clothing strings, which may lead to strangulation	Plastic guard offered to consumers and retailers for present and future units Press Release 8/6/92.
09/92	Omni Arcadia, CA 91006 Cargo net play equipment at restaurants	Child's head may become entrapped in 6"X6" squares and strangulation may occur if help is not available	Free retrofit overlay net of 2"X2" squares sent to each location, with disposable camera to return to firm to verify installation.
09/92	Faultless, Mfg Company Ontario, Canada T-700 Chair Control Mechanism	Control may develop stress cracks causing separation of the chair seat from the supporting spindle.	Notice to customers offering to replace units showing stress failure.

DATE	FIRM AND PRODUCT	ALLEGED HAZARD	REMEDY
09/92	<p>Starr Display Fireworks Fargo, ND 58102</p> <p>Three #100 large display rack fireworks devices</p>	<p>These devices may tip over during operation and fire their charges horizontally, resulting in possible serious injury or death to persons nearby</p>	<p>A joint press release was issued 6/30/92 announcing the firm's recall of these devices. Consumers should return the devices to the store where purchased for a full refund</p>
09/92	<p>Hedstrom Corporation Bedford, PA 15522</p> <p>Hedstrom & Sears "Big T" gym sets</p>	<p>Handrail attachment to slide may present a catch point for clothing strings, which may lead to strangulation</p>	<p>Plastic guard offered to consumers and retailers to correct all present and future units. Press Release 8/6/92. Retail notices with 800 number to obtain retrofit kit.</p>
09/92	<p>Robertshaw Controls Company Richmond, VA 23261</p> <p>Models BV and BP manual gas valves used on certain Maytag, Magic Chef, Admiral, Norge, Hardwick, Crosley, Sears Kenmore, Amana, General Electric, Whirlpool and Wedgewood brand gas ranges</p>	<p>Some of these valves have screws that may loosen, which could lead to a gas leak and possible fire</p>	<p>Free inspection and replacement of gas valves. 1-800-847-7160 - Wedgewood 1-800-544-2538 - other brands</p>
09/92	<p>Service Cycle Supply Commack, NY 11725</p> <p>1992 Mongoose Bicycles</p>	<p>Loss of brakes and possible fall to rider due to brake cable disattachment.</p>	<p>The firm notified all its dealers and distributors to stop sale and provided replacement cables for dealer installation free of charge.</p>

DATE	FIRM AND PRODUCT	ALLEGED HAZARD	REMEDY
09/92	Great Plains Coca Cola Oklahoma City, OK 73120 Aluminum caps on 3 liter bottles	The cap may prematurely release from the bottle possibly exposing users to bodily injury	The firm recalled the bottles offering consumers replacement products.

Appendix G:



**Litigation
and
Settlements**

LITIGATION AND SETTLEMENTS

Part I of this appendix summarizes the federal court cases, categorized by type, to which the Commission was a party during fiscal year 1992. Part II summarizes the civil penalty settlement agreements accepted by the Commission during FY 1992.

PART I

INJUNCTION CASES

1. United States v. Illco Toy Co., USA and Martin Schemann, Civil Action No. 90-C-5405 (JFK) (S.D.N.Y.) On August 20, 1990 the government filed a complaint and motion for preliminary injunction against an importer of toys. Following discovery and the filing of briefs, U.S. District Judge John F. Keenan on January 17, 1991 denied the government's motion for a preliminary injunction. He did so "reluctantly," and primarily because of the government's "inability, despite inspections of defendants' products, to establish that there have been any violations since October 1989." On March 4, 1991 the Judge decided to keep the case on his docket, until November 18, 1991, to see whether Illco committed any additional violations. On April 9, 1991 Illco wrote a letter to the Judge asking for an order that its counsel be permitted to be present, on five days notice, for all government sampling and testing of Illco's toys. The Judge signed the order on April 10, 1991, before the government even knew that Illco had proposed it. On April 16, 1991 the government sent a letter to the Judge asking that he vacate the order pending a hearing on this issue. On September 9, 1991 the Judge vacated the order and directed the Commission to videotape its tests of Illco's toys when requested by Illco to do so. The Commission sampled and tested (and videotaped) three Illco toys. Since all three passed the tests, the government did not oppose the Judge's dismissal of the case on November 18, 1991.
2. United States v. American Honda Motor Co., Inc., et al., Civil Action No. 87-3525 (D.D.C.). On December 30, 1987 the government filed a case seeking an imminent hazard injunction against five distributors of all-terrain vehicles (ATVs), along with a preliminary consent decree. The court approved the preliminary decree the same day, and approved a final consent decree on April 28, 1988. On September 17, 1991 four organizations -- Public Interest Research Group, Consumer Federation of America, American Academy of Pediatrics, and Public Citizen -- moved to intervene and to modify and enforce the consent decree. The government and industry parties filed memoranda in opposition on October 16, 1991. The proposed intervenors filed a reply memorandum on November 8, 1991, requesting amici status if the court denied intervention. On November 25, 1991 the court held a hearing on the motions. On December 12, 1991 the court issued a Memorandum and Order providing proposed intervenors until January 15, 1992 to file a different suggested decree change, providing all parties until April 1, 1992 to supplement the record, and providing all parties until April 15, 1992 to comment on any proposal. On January 15, 1992 the proposed intervenors requested that the court (1) order the defendants to show cause why they are not in violation of the existing decree and/or (2) modify the decree in ways that the proposed intervenors contended will provide additional protection for the public, and especially children. By April 1, 1992 the government and industry

parties had filed supplemental materials, and proposed intervenors had filed a notice that they would file materials with their April 15, 1992 submission. The government filed a response to that notice stating it might need to file an additional memorandum to respond to the proposed intervenors' supplementary materials. On April 15, 1992 the government, industry and proposed intervenors filed additional memoranda on proposed intervenors' requested remedies. Also on April 15, 1992 the attorneys general of 35 states applied for leave to file an amicus curiae brief. All parties and the proposed intervenors filed final briefs on May 6, 1992, and the court held a hearing on May 15, 1992. On May 28, 1992 the court denied the motion to intervene, ruling that intervention would not be appropriate and that, in any case, the proposed intervenors had not shown any grounds for reopening or modifying the decree. Based on its review of the steps taken to implement the consent decree, the court expressed its satisfaction that "the provisions of the decree have been implemented in a manner consistent with the judgment" and that "[t]he terms of the settlement appear not to have been breached in any material respect."

SEIZURE CASES

1. U.S. v. Articles of Banned Hazardous Substances Consisting of an Undetermined Number of Cans of Rainbow Foam Paint, Civil Action No. 3:91CV00230 (PCD) (D. Conn.). On April 26, 1991 the government filed an action seeking the seizure of self-pressurized containers of banned children's paint. On April 29, 1991 U.S. Marshals seized the cans of paint. Following the May 9, 1991 due date for filing claims for the paint, the government moved for default and judgment on June 6, 1991. On June 11, 1991 Linda Weill filed an opposition to that motion. On the same day, however, Judge Peter Dorsey signed an order granting judgment against the paint, which was entered on June 13, 1991. On June 20, 1991 Ms. Weill and X-Tra Art, Inc. filed a motion to intervene in the case and to vacate the default judgment. On July 10, 1991 the government filed an opposition. On July 31, 1991 Judge Dorsey granted the motion to intervene and to vacate the judgment. On September 18, 1991 the government moved to strike X-Tra Art's claim and answer. The Judge denied that motion on January 16, 1992. From August 1991 through April 1992 the parties engaged in discovery, during that time, the Judge denied a government motion to compel adequate responses and a government motion to reconsider the denial. On May 8, 1992 X-Tra Art filed a motion for summary judgment on one issue. The government opposed that motion and filed its own motion for summary judgment on May 28, 1992. On September 9, 1992 the Judge granted X-Tra Art's motion and denied the government's, ruling that the paint is an art material exempt from Federal Hazardous Substances Act requirements. On September 18, 1992 the government moved for reconsideration of the ruling.
2. United States v. Articles of Banned Hazardous Substances Consisting of an Undetermined Number of Aqua Tech Safety Bath Seats, Civil Action Nos. 1:92-CV-1217 (RLV) and 1:92-CV-1218 (RLV) (N.D. Ga.). On May 25, 1992 the government filed actions (two companion cases) seeking the seizure of children's bath seats made by Pansy Ellen Products, Inc. On June 3 and 4, 1992 U.S. Marshals seized the seats. Pansy Ellen filed a claim on June 12 and an answer on June 18, 1992. The parties engaged in discovery during the summer and fall of 1992.

CRIMINAL CASE

During fiscal year 1990 the government presented to a grand jury information concerning possible violations of a CPSC statute. The grand jury continued through fiscal year 1992 to consider this matter. No additional details can be disclosed.

CIVIL PENALTY CASES

1. United States v. Division Sales, Inc. and Justen Products, Civil Action No. 91-C5203 (N.D. Ill.). On August 16, 1991 the government filed a complaint seeking civil penalties against two toy firms based on the sale of banned lawn darts and the failure to report to the Commission. On October 18, 1991 the firms filed an answer. Following four settlement conferences held with the judge (two of them by telephone) between November 1, 1991 and January 7, 1992, the parties agreed to settle the case. The firms paid a penalty of \$35,000, and the case was dismissed on February 11, 1992.
2. United States v. Paty, Inc., Civil Action No. H-92-1773 (S D Tex.). On June 15, 1992 the government filed a complaint seeking a civil penalty against a manufacturer of children's sleepwear for violation of an administrative cease and desist order. The parties signed a consent decree, filed with the complaint and approved by the court on June 18, 1992, and the firm paid a penalty of \$12,500.

FREEDOM OF INFORMATION ACT CASE

Peter L. Wechsler, James E. Strates Shows, Inc. and E. James Strates, individually v. Consumer Product Safety Commission, Civil Action No. 92-0402-CIV-ATKINS (S.D. Fla.) On March 3, 1992 the plaintiffs filed a complaint seeking documents, withheld by the Commission under the Freedom of Information Act, on an incident involving the "Monster" amusement ride. The government answered the complaint on April 8, 1992, and moved for summary judgment on June 2, 1992. The plaintiffs responded on June 19, and the government replied on June 26.

OTHER CASES AGAINST THE COMMISSION

1. X-Tra Art, Inc. and Linda Weill v. Consumer Product Safety Commission, Civil Action No. 91-1336MHP (N.D. Cal.) and No. 91-16027 (9th Cir.) On May 3, 1991 the distributors of self-pressurized containers of paint for children, Rainbow Foam Paint, filed a complaint against the Commission seeking declaratory relief, a temporary restraining order (TRO), and a preliminary and permanent injunction. (In a separate action in Connecticut in April 1991, the government had seized cans of the paint which it found to be banned hazardous substances under the Federal Hazardous Substances Act.) Following a hearing on May 7, 1991 in San Francisco, Judge Marilyn Hall Patel granted a TRO prohibiting the Commission from further acting against or disclosing information on Rainbow Foam Paint. Both sides filed briefs on May 14, 1991. Following a hearing, Judge Patel entered orders denying the preliminary injunction and dismissing the case on June 12, 1991. In an accompanying opinion, she ruled that in issuing the letter of advice to X-Tra Art and declaring the paint to be a banned hazardous substance, the Commission had followed the Federal Hazardous Substances Act, and that no proceeding to issue a rule specifically banning the paint was required. The Judge also rejected X-Tra Art's due process, equal protection, and 6(b)

arguments. She did not consider the merits of the Commission staff's determination that the paint was a banned hazardous substance, holding that that determination could be challenged only in an enforcement action. On July 3, 1991 X-Tra Art filed a notice of appeal to the U.S. Court of Appeals for the Ninth Circuit. X-Tra Art's brief was filed on October 17, 1991, the government's brief was filed on November 29, and X-Tra Art's reply brief was filed on December 16. On January 3, 1992 X-Tra Art asked for an expedited date for oral argument, a request which the government did not oppose. On January 14, 1992 X-Tra Art filed a motion for summary reversal of the district court's order, based on documents released by CPSC under the Freedom of Information Act. The government opposed this motion on January 24, and X-Tra Art filed a reply on February 3. On February 14, 1992 the appellate court denied the motions for summary reversal and expedited oral argument. The court heard oral argument on June 11, 1992, and on July 8, 1992 affirmed the district court's dismissal of the case. The court held that (1) the Commission can act against banned hazardous substances without engaging in rulemaking, (2) the Commission acted properly by proceeding informally through its staff and then by referring the seizure case to the U.S. Attorney's office, and (3) the firm is not entitled to review under the Administrative Procedure Act. On July 22, 1992 X-Tra Art filed a motion for rehearing on the Administrative Procedure Act issue.

2. Writing Instrument Manufacturers Association, Inc., et al. v. Consumer Product Safety Commission, et al., Civil Action No. 4-91-048 (E.D. Tenn.). On July 1, 1991 a trade association and some of its members filed an action against the government seeking an injunction to prevent the Commission from enforcing chronic hazard labeling requirements, as well as an order that the Commission issue final chronic hazard guidelines. On September 3, 1991 the government filed a motion to dismiss the case and/or for summary judgment. The Association filed an opposition to the motion on September 30, the government filed a reply on October 10, and the Association filed a surreply on October 22. On November 13, 1991 the judge filed an opinion and order dismissing the case. The judge based his decision on the finding that the case was not ripe for judicial review and that the Association was not entitled to mandamus as a matter of law. He also observed that Congress had not made the effective date of the chronic hazard labeling requirements contingent on the Commission's issuance of guidelines and that the Commission may enforce the requirements as of the effective date.
3. Consumer Federation of America and U.S. Public Interest Research Group v. Consumer Product Safety Commission, Civil Action No. 91-1551 (D.C. Cir.). On November 18, 1991 two organizations filed a petition for review of the Commission's decision to terminate its rulemaking proceeding concerning all-terrain vehicles. On December 23, 1991 the petitioners filed a docketing statement, a statement on issues to be raised, and a statement concerning an appendix. On January 7, 1992 the government filed a Certified List of the Record. On January 27, 1992 the court granted a motion by ATV distributors to intervene. Petitioners filed their brief on September 25, 1992, and the government was scheduled to file its brief on October 26, 1992.
4. Hollander Home Fashions Corp. v. Consumer Product Safety Commission, Civil Action No. 92-1346 (D.C. Cir.). On August 10, 1992 a firm filed a petition for review of the Commission's rule banning certain infant cushions (and a corrected petition on August 17). On September 17, 1992 the firm filed a statement on issues to be raised, a statement concerning an appendix and other papers.

PART II

CIVIL PENALTY SETTLEMENT AGREEMENTS ACCEPTED BY THE COMMISSION

1. *In the Matter of General Electric Company, Inc.,* CPSC Docket No. 92-C0002. General Electric agreed to pay a civil penalty of \$400,000 in settlement of Commission staff allegations that the manufacturer failed to report in a timely manner a defect in its countertop automatic drip coffeemakers which could create a substantial product hazard as required by 15 U.S.C. § 2064(b). The staff alleged that GE knew that a thermal fuse, designed to prevent the coffeemaker from overheating, was unreliable; that the firm received hundreds of overheating claims and several reports of fire resulting in death and serious injury. The firm denied that it violated the statutory reporting requirements.
2. *In the Matter of E. Davis, Inc.,* CPSC Docket No. 93-C0001. E Davis, Inc agreed to pay a civil penalty of \$225,000 in settlement of Commission staff allegations that the New Jersey importer failed to report a defect in its "Extra Thick Super String" which could create a substantial product hazard, as required by 15 U S C. § 2064 (b). The staff alleged that E. Davis knew that its party favor, aerosol string streamer in a can produced and sold in 1988 and 1989, contained a flammable propellant, and that use of the product, at birthday parties and other celebrations where candles were in use was reasonably foreseeable and extremely dangerous. The company denied that it violated the statutory reporting requirement and alleged that any use of the product near a flame constituted product misuse. The final order was issued on September 30, 1992.
3. *In the Matter of Figgie International, Inc.,* CPSC No. 92-C0004. Figgie International, Inc. agreed to pay a civil penalty of \$175,000 in settlement of the Commission staff allegations that its Badger Powhatan division failed to report defects in two models (P250MA and P275RA) of its fire extinguishers that caused the valve bodies to blow off the fire extinguishers. The firm denied that it violated the statutory reporting requirement. The order was issued on September 15, 1992.
4. *In the Matter of Hamilton Beach/Proctor-Silex, Inc.,* CPSC No. C0001. Hamilton Beach/Proctor-Silex, Inc. agreed to pay a civil penalty of \$50,000 in settlement of the Commission staff allegations that the firm failed to report, in a timely manner, a defect in the clock of its models 816-2 and 816-3 drip coffee makers. The defect could cause the housing of the coffee makers to ignite, with the possibility of fire spreading to adjacent cabinets or counter tops. The firm denied that it violated the statutory reporting requirement. The order was issued on February 14, 1992.

Appendix H:



**Index of
Products
Regulated
by CPSC**

INDEX OF PRODUCTS REGULATED BY CPSC

PRODUCT	ACT	TYPE OF REGULATION	REFERENCE SOURCE TITLE 16 CFR PART NUMBER
Acetaminophen	PPPA	special packaging exemption	1700.14(a)(16) 1700.14(a)(16)(1), (11)
Acetic acid	HSA	labeling	1500.129(g)
Adhesives, containing methyl alcohol	HSA	labeling	1500.133
	HSA	exemption from labeling	1500.83(a)(34)
nitrocellulose base	HSA	exemption from labeling	1500.83(a)(10)
floor covering	HSA	exemption from labeling	1500.83(a)(13)
extremely flammable contact	CPSA	ban	1302
	CPSA	to be regulated under CPSA	1145.3
Aerosols (see self-pressurized products)	HSA	suggested labeling	1500.130
Aluminized polyester film kite	HSA	ban	1500.18(c)(1)
Ammonia, ammonia water (household), ammonium hydroxide	HSA	labeling	1500.129(g)
Antennas (CB base station and TV) (Omnidirectional CB base station)	CPSA	labeling requirement	1402
	CPSA	performance and certification	1204
Antifreeze, ethylene glycol-base	HSA	labeling	1500.132
	PPPA	special packaging	1700.14(a)(11)
Antiquing kits	HSA	exemption from labeling	1500.83(a)(25)
Appliances, coal and wood-burning	CPSA	provision of performance and technical data	1406
Architectural glazing materials	CPSA	safety standard	1201
Art materials	HSA	exemption from ban	1500.85(a)(4)
Artist's paints	CPSA	exemption from lead limit	1303.3(c)(2)
Asbestos-containing patching compounds	CPSA	ban	1304
	CPSA	to be regulated under the CPSA	1145.4

PRODUCT	ACT	TYPE OF REGULATION	REFERENCE SOURCE
			TITLE 16 CFR PART NUMBER
Asbestos-containing garments for general use	HSA	ban	1500.17(a)(7)
Asbestos-containing artificial emberizing materials	CPSA	ban	1305
	CPSA	to be regulated under the CPSA	1145.5
Aspirin products	PPPA	special packaging	1700.14(a)(1)
		effervescent tablet exemption	1700.14(a)(1)(i)
		unflavored powders exemption	1700.14(a)(1)(ii)
Baby bouncers and walkers	HSA	standard and ban	1500.18(a)(6)
		exemption from banning	1500.86(a)(4)
Balloons, plastic mixtures	HSA	exemption from banning	1500.85(a)(4)
Bassinet legs	CPSA	to be regulated under the CPSA	1145.15
Batteries, storage, wet-cell	PPPA	exemption from special packaging	1700.14(a)(9)
Benzene (benzol)	HSA	special labeling	1500.14(b)(3)(i)
Benzene (paint solvents)	PPPA	special packaging	1700.14(a)(15)
Bergamot oil	HSA	labeling	1500.13(e)
Betamethasone	PPPA	exemption from special packaging	
Bicycles	HSA	ban	1500.18(a)(12)
		safety requirements	1512
Biological specimens, preserved	HSA	exemption from ban	1500.85(a)(4)
Blasting caps	HSA	exemption from labeling	1500.83(a)(35)
Butane in cigarette lighters	HSA	exemption from labeling	1500.83(a)(29)
Carbolic acid (phenol)	HSA	labeling	1500.129(d)
Carbon tetrachloride	HSA	ban	1500.17(a)(2)
Carpets and rugs (large)	FFA	standard (FF 1-70)	1630
Carpets and rugs (small)	FFA	standard (FF 2-70)	1631

PRODUCT	ACT	TYPE OF REGULATION	REFERENCE SOURCE
			TITLE 16 CFR PART NUMBER
Caustic poisons potash soda	HSA	labeling	1500.129
	HSA	labeling	1500.129
	PPPA	special packaging	1700.14(a)(5)
	HSA	labeling	1500.29(j)
	PPPA	special packaging	1700.14(a)(5)
Cellulose sponges	HSA	exemption from labeling	1500.83(a)(15)
Cellulose insulation	CPSA	standard	1209
	CPSA	labeling	1404
Charcoal briquettes	HSA	classification as hazardous	1500.12(a)(1)
		special labeling	1500.14(b)(6)
Chemistry sets	HSA	exemption from labeling	1550.83(a)(23)
		exemption from banning	1500.85(a)(1)
Child-resistant packaging and see special packaging)	PPPA	criteria and substances subject	1700
Chlorofluorocarbons, self pressurized products containing	CPSA	labeling requirement	1401
Cholestyramine, anhydrous	PPPA	exemption from special packaging	1700.14(A)(10)(v)
Cigarette lighters	HSA	exemption from labeling	1500.83(a)(29)
		exemption from labeling	1500.83(a)(20)
Cleaning products	HSA	exemption from labeling	1500.83(a)(11)
Clothing (see wearing apparel, sleepwear)			
Coal burning appliances (see appliances)			
Coldwave permanent neutralizers containing sodium bromate or potassium bromate	PPPA	special packaging	1700.14(a)(19)
Colestipol	PPPA	exemption from special packaging	1700.14(a)(10)(xv)
Combustible hazardous substances	HSA	definition	1500.3(c)(iii)
		flashpoint testing	1500.43a

PRODUCT	ACT	TYPE OF REGULATION	REFERENCE SOURCE TITLE 16 CFR PART NUMBER
Conjugated estrogens tablets	PPPA	exemption from special packaging	1700.14(a)(10)(xvii)
Consumer product	CPSA	reporting of substantial product hazards	1115
Containers, consumer-owned (portable)	HSA	exemption from full labeling	1500.83(a)(14)
Controlled drugs	PPPA	special packaging	1700.14(a)(4)
Corrosive substances (c)(3)	HSA	definition	1500.3(b)(7),
Cosmetics	HSA	exemption	1500.81(a)
Crib hardware	CPSA	to be regulated under the CPSA	1145.14
Cribs (full-size)	HSA	ban safety requirements	1500.18(a)(13) 1508
Crib (non full-size)	HSA	ban safety requirements	1500.18(a)(14) 1509
Crib, mesh-sided	CPSA	to be regulated under the CPSA	1145.12
Cushions, infant	HSA	ban	1500.18(a)(16)
Cyanide salts	HSA	ban	1500.17(a)(5)
Dietary supplements, iron-containing	PPPA	special packaging	1700.14(a)(13)
Diethylene glycol	HSA	labeling special labeling exemption from labeling	1500.14(a)(1) 1500.14(b)(1) 1500.83(a)(15)
Diethylenetriamine	HSA	labeling	1500.13(c)
Diglycidyl ethers	HSA	labeling	1500.13(c)
Diphenhydramine preparations	PPPA	special packaging	1700.14(a)(17)
Disclaimer deceptive use of	HSA	misbranded	1500.122

PRODUCT	ACT	TYPE OF REGULATION	REFERENCE SOURCE TITLE 16 CFR PART NUMBER
Drain cleaners, liquid	HSA PPPA	ban special packaging	1500.17(a)(4) 1700.14(a)(5), (9)
Drugs, controlled	PPPA	special packaging	1700.14(a)(4)
Drugs, oral prescription Except:	PPPA	special packaging	1700.14(a)(10)
Nitroglycerin tablets (sublingual)			1700.14(a)(10)(i)
Isosorbide dinitrate (10 mg. sub- lingual and chewable tablets)			1700.14(a)(10)(ii)
Erythromycin ethylsuccinate (8 gm oral suspension and granules for oral suspensions)			1700.14(a)(10)(iii)
Erythromycin ethylsuccinate tablets (no more than 16 gm)			1700.14(a)(10)(xvi)
Cyclical oral contraceptives			1700.14(a)(10)(iv)
Anhydrous cholestyramine (powder form)			1700.14(a)(10)(v)
Potassium supplements (containing not more than 50 MEq potassium per unit dose package)			1700.14(a)(10)(vi)
Sodium fluoride (264 mg per package of liquid forms and tablet forms)			1700.14(a)(10)(vii)
Betamethasone (12.6 mg per package)			1700.14(a)(10)(viii)
Pancrelipase in tablet, capsule or powdered form			1700.14(a)(10)(ix)
Prednisone tablets (not more than 105 mg per package)			1700.14(a)(10)(x)
Mebendazole (600 mg per package)			1700.14(a)(10)(xi)
Methylprednisolone tablets (not more than 84 mg per package)			1700.14(a)(10)(xiv)
Colestipol (packages containing not more than 5 grams of powder)			1700.14(a)(10)(xv)
Conjugated estrogens tablets (not more than 32 mg per package)			1700.14(a)(10)(xvii)
Norethindrone acetate tablets (not more than 50 mg per package)			1700.14(a)(10)(xviii)
Medroxyprogesterone acetate tablets			1700.14(a)(10)(xix)
Drugs, iron containing	PPPA	special packaging	1700.14(a)(12)
Dry-cleaning solvents	HSA	exemption from labeling	1500.83(a)(18)
Emberizing materials, artificial containin asbestos	CPSA	ban	1305

PRODUCT	ACT	TYPE OF REGULATION	REFERENCE SOURCE
			TITLE 16 CFR PART NUMBER
Epoxy resins	HSA	labeling	1500.13(c)
Erythromycin ethylsuccinate, suspension and granules for suspension chewable tablets	PPPA	exemption from special packaging	1700.14(a)(10)(111) 1700.14(a)(10)(xvi)
Ethylenediamine	HSA	labeling	1500.13(c)
Ethylene glycol in felt pads	HSA	exemption from labeling special labeling	1500.83(a)(28) 1500.14(b)(4)
Ethylene glycol	HSA	labeling special packaging	1500.14(a)(2), (b)(2) 1700.14(a)(11)
Ethylene glycol antifreeze	HSA	labeling	1500.132
Expandable children's enclosures	CPSC	to be regulated under the CPSA	1145.13
Exports (noncomplying products)	All	reporting requirements	1019
Extremely flammable contents of self-pressurized containers	HSA	definition method to determine flashpoint testing exemption from labeling	1500.3(c)(6)(vii) 1500.45 1500.46 1500.83(a)(1)
Extremely flammable 1500.3(c)(6)(1) hazardous substances	HSA	definition testing method	 1500.43a
Extremely flammable solids	HSA	definition testing method	1500.3(c)(6)(v) 1500.44
Eye irritants	HSA	testing method definition	1500.3(b)(8), (c)(4) 1500.42
Fabrics	FFA	flammability	1602-1632
Felt-tip marking devices	HSA	labeling exemption	1500.83(a)(9)
Ferrous oxalate	HSA	exemption from labeling	1500.83(a)(17)
Fertilizers, dry granular	HSA	exemption from labeling	1500.83(a)(21)
Fire extinguishers	HSA	exemption from labeling labeling, warning	1500.83(a)(24) 1500.15(a)(b)

PRODUCT	ACT	TYPE OF REGULATION	REFERENCE SOURCE TITLE 16 CFR PART NUMBER
Fireworks	HSA	ban (more than 2 grains pyrotechnic material for audible reports)	1500.17(a)(3)
		ban (firecrackers more than 50 mg.)	1500.17(a)(8) & 9
		exemption from labeling	1500.83(a)(27)
		agricultural exemption	1500.17(a)(3)
		exemption from classification	1500.85(a)(2)
		special labeling	1500.14(b)(7)
		ban reloadable tube	1500.17(a)(11)
		aerial shells more than 1.7 inches in outer diameter)	
		safety requirements	1507
First Aid	HSA	policy for emesis labeling	1500.134
Flammable contents of self- pressurized containers	HSA	definition	1500.3(c)(6)(viii)
		method for determining	1500.45
		flashpoint testing	1500.46
		exemption from labeling	1500.83(a)(1)
Flammable solids	HSA	definition	1500.3(c)(6)(vi)
		testing method	1500.44
Flammable substances	HSA	definition	1500.3(c)(6)(iii)
		flashpoint testing	1500.43a
Food	HSA	exemption from specific labeling	1500.81(a)
Formaldehyde	HSA	labeling	1500.13(d)
Fuel	HSA	exemptions	1500.81(b)
		exemptions from banning	1500.85(a)(5)
		special packaging	1700.14(a)(7)
Fuel kits with difluorodi- chloromethane	HSA	exemption from banning warning label	1500.85(a)(12), (13)
Furniture, painted with lead- containing paint	CPSA	ban	1303
Furniture polish, liquid	PPPA	special packaging	1700.14(a)(2)

PRODUCT	ACT	TYPE OF REGULATION	REFERENCE SOURCE
			TITLE 16 CFR PART NUMBER
Furniture polish, paste	HSA	exemption from labeling	1500.83(a)(8)
Garage Door Openers automatic residential	CPSA	requirements for equipment protector	1211
Gasoline	HSA	exemption from labeling special labeling labeling	1500.83(a)(14) 1500.14(b)(3) 1500.14(a)(3)
Glazing compounds	HSA	exemption from labeling	1500.83(a)(13)
Glue remover containing acetonitrile (household)	PPPA	special packaging	1700.14(a)(18)
Harishorn	HSA	labeling	1500.129(1)
Heaters (see appliances)			
Highly toxic substances	HSA	definition testing method labeling	1500.3(e) 1500.40 1500.121
Household substances	HSA	definition	1500.3(c)(10)
Hydrochloric acid	HSA	labeling	1500.129(a)
Hypochlorous acid	HSA	labeling	1500.129(h)
Ibuprofen	PPPA	special packaging	1700.14(a)(20)
Imported products & importers	ALL	policy	1009.3
Imports	HSA	various	1500.265-272
Industrial supplies	HSA	exemption	1500.3(c)(10)(1)
Infant cushions	HSA	ban	1500.18(a)(16)
Ink, cartridges	HSA	exemption from labeling	1500.83(a)(7), (38)
dry concentrate containers	HSA	exemption from labeling	1500.83(a)(12)
Ink-marking devices	HSA	exemption	1500.83(a)(9)
Insulation, cellulose	CPSA	standard	1209
Iron preparations (13)	PPPA	special packaging	1700.14(a)(12),

PRODUCT	ACT	TYPE OF REGULATION	REFERENCE SOURCE
			TITLE 16 CFR PART NUMBER
Irritant substances	HSA	definition testing method	1500.3(g) 1500.41
Isobutane in cigarette lighters	HSA	exemption from labeling	1500.83(a)(29)
Isosorbide dinitrate, pre- scription sublingual and chewable forms	PPPA	exemption from special packaging	1700.14(a)(10)(ii)
Kerosene	HSA	labeling special labeling exemption from labeling special packaging	1500.1 4(a)(4) 1500.14(b)(3) 1500.83(a)(14) 1700.14(a)(7)
Kindling and illuminating preparations	PPPA	special packaging	1700.14(a)(7)
Kites, aluminized polyester film	HSA	ban	1500.18(c)(1)
Labels	HSA	requirements condensation informal comment on exemption from labeling	1500.121 1500.123 1500.128 1500.83(a)(5)
Laboratory chemicals, if educational	HSA	exemption from banning and labeling	1500.85(a)(4) 1500.85(a)(5)
Lacquers	HSA	exemption from labeling	1500.83(a)(13)
Lawn darts	HSA CPSA	ban ban	1500.18(a)(4) 1306
Lawnmowers, power	CPSA	performance standard, labeling rule, and certification rule	1205
Lead in paint	HSA	ban over 0.5% (pre- 1978)	1500.17(a)(6)
	CPSA	ban over 0.06% (1978 and later)	1303
Lighter fluid, etc.	PPPA	special packaging	1700.14(a)(7)
Lunar caustic (silver nitrate)	HSA	labeling	1500.129(k)
Lye	HSA PPPA	labeling special packaging	1500.129(j) 1700.14(a)(5)
Matchbooks	CPSA	standard	1202
Matches	HSA	exemption from flamma- bility labeling	1500.83(a)(2)

PRODUCT	ACT	TYPE OF REGULATION	REFERENCE SOURCE
			TITLE 16 CFR PART NUMBER
Mattresses	FFA	standard (FF 4-72)	1632
Mebendazole	PPPA	exemption from special packaging	1700.14(a)(10)(xiii)
Medroxyprogesterone acetate tablets	PPPA	exemption from special packaging	1700.14(a)(10)(xix)
Methyl alcohol (methanol)	HSA	exemption from labeling	1500.83(a)(10)
		labeling	1500.14(a)(4), (b)(4)
		exemption from labeling	1500.83(a)(19)
		exemption from labeling	1500.83(a)(34)
	PPPA	special packaging	1700.14(a)(8)
Methylprednisolone	PPPA	exemption from special packaging	1700.14(a)(10)(xiv)
Methyl salicylate	PPPA	special packaging	1700.14(a)(3)
Mineral oil (in toys)	HSA	exemption from labeling	1500.83(a)(33)
Mineral seal oil	HSA	labeling	1500.14(a)(3)
		special labeling	1500.14(b)(3)
	PPPA	special packaging	1700.14(a)(2)
Mineral spirits	HSA	labeling	1500.14(a)(3)
		special labeling	1500.14(b)(3)
		special packaging	1700.14(a)(15)
Mirrors	CPSA	exemption from lead limit	1303.3(c)(2)
Mixtures of hazardous substances	HSA	labeling	1500.5
Multiple hazard, substances with	HSA	labeling	1500.127
Naphtha	HSA	labeling	1500.14(a)(3)
		special labeling	1500.14(b)(3)
Nitric acid	HSA	labeling	1500.129(c)
Nitroglycerine, prescription, sublingual dosage	PPPA	exemption from special packaging	1700.14(a)(10)(i)
Norethindrone acetate tablets	PPPA	exemption from packaging	1700.14(a)(10)(xviii)

PRODUCT	ACT	TYPE OF REGULATION	REFERENCE SOURCE
			TITLE 16 CFR PART NUMBER
Oral contraceptives, cyclical	PPPA	exemption from special packaging	1700.14(a)(10)(iv)
Orris root, powdered	HSA	labeling	1500.13(b)
Oxalic acid and salts of	HSA	labeling	1500.129(e),(f)
Packages, child-resistant(see child-resistant packaging)			
Packages, sample	PPPA	submission	1700.14(b)
Paint, .lead in	HSA	ban over 0.5% (pre-1978)	1500.17(a)(6)
	CPSA	ban over 0.06% (1978 and later)	1303
	CPSA	to be regulated under the CPSA	1145.2
Paint solvents	PPPA	special packaging	1700.14(a)(15)
Painting kits	HSA	exemption	1500.83(a)(25)
Pancrelipase	PPPA	exemption from special packaging	1700.14(a)(10)(ix)
Paper items	HSA	exemption from labeling list	1500.83(a)(3)
Paraphenylenediamine	HSA	labeling	1500.13(a)
Patching compounds, containing asbestos	CPSA	ban	1304
Perchloroethylene in visual	HSA	exemption from labeling	1500.83(a)(31)
Percussion explosives	HSA	definition	1500.3(c)(7)(1)(a)
Petroleum distillates	HSA	labeling	1500.14(a)(3)
		special labeling	1500.14(b)(3)
		exemption from labeling	1500.83(a)(8),(9),(11),(13),(14),(20)
	PPPA	special packaging	1700.14(a)(7),(2),(15)
Phenol (carbolic acid)	HSA	labeling	1500.129(d)

PRODUCT	ACT	TYPE OF REGULATION	REFERENCE SOURCE
			TITLE 16 CFR PART NUMBER
Photodynamic sensitizer	HSA	definition	1500.3(b)(9)
Photographic color processing kits	HSA	exemption from labeling	1500.83(a)(25)
Plant foods, dry granular	HSA	exemption from labeling	1500.83(a)(21)
Playpens: expandable mesh-sided	CPSA	to be regulated under the CPSA	1145.13
	CPSA	to be regulated under the CPSA	1145.11
Poisons, caustic	HSA	labeling requirements	1500.129
Polishing products	HSA	exemption from labeling	1500.83(a)(11)
Potash, caustic	HSA	labeling special packaging	1500.129(1) 1700.14(a)(5)
Potassium hydroxide	HSA PPPA	labeling special packaging	1500.129(1) 1700.14(a)(5)
Potassium supplements, effervescent	PPPA	exemption from special packaging	1700.14(a)(10)(vi)
Prednisone	PPPA	exemption from special packaging	1700.14(a)(10)(x)
Pressure-generating substances	HSA	definition	1500.3(c)(7)(1)
Primary irritant	HSA	definition testing method	1500.3(g)(2) 1500.41
Propellant devices for model rockets	HSA	exemption from banning	1500.85(a)(8),(9),(12) (12), (13)
Radiator cleaners	HSA	as household substance	1500.3(c)(10)(1)
Radioactive substances	HSA	defined exemption	1500.3(b)(11),(c)(8)
Refrigerator doors	RSA	standard to permit opening from inside	1750

PRODUCT	ACT	TYPE OF REGULATION	REFERENCE SOURCE
			TITLE 16 CFR PART NUMBER
Refuse bins, unstable	CPSA	ban	1301
Roof coatings	HSA	exemption from labeling	1500.83(a)(13), (34)
Rope, cord, string, etc.	HSA	exemption from labeling	1500.83(a)(4)
Rugs (see Carpets)			
Rubber vulcanizing	HSA	exemption from labeling	1500.83(a)(13)
Salt (sodium chloride)	HSA	exemption from labeling	1500.83(a)(1)
Self-pressurized products	HSA	exemption from full labeling testing method for flammable or extremely flammable contents information statements required	1500.83(a)(1) 1500.45,46 1500.130
containing chlorofluoro carbons	CPSA	labeling requirement	1401
containing vinyl chlorides	HSA	ban	1500.17(a)(10)
Sensitizers	HSA	definitions	1500.3(b)(9), (c)(5)
Signal words	HSA	labeling requirements	1500.121
Silver nitrate (lunar caustic)	HSA	labeling	1500.129(k)
Sleepwear, children's sizes 0-6x sizes 7-14	HSA	FFA standard (FF 3-71) standard (FF 5-74)	1615 1616
Sodium arsenite	HSA	labeling	1500.132(b)
Sodium fluoride (pre-scription aqueous solutions)	PPPA	exempting from special packaging	1700.14(a)(10)(vii)
Sodium hydroxide	HSA	labeling	1500.129(j)
Sodium/potassium hydroxide	PPPA	special packaging	1700.14(a)(5)
Solder kit	HSA	exemption from labeling	1500.83(a)(30)

PRODUCT	ACT	TYPE OF REGULATION	REFERENCE SOURCE
			TITLE 16 CFR PART NUMBER
Solder paste	HSA	exemption from labeling	1500.83(a)(22)
Special packaging	PPPA	standards	1700.15
		re-use prohibited	1700.15(c)
		test procedure	1700.20
		restricted flow	1700.15(d)
		requirement	
Spot removers, single-use	HSA	exemption from labeling	1500.83(a)(18),(19),(26)
Spot removing kits	HSA	exemption from labeling	1500.83(a)(25)
Sponges, cellulose	HSA	exemption from labeling	1500.83(a)(15)
Squeeze toys	CPSA	to be regulated under the CPSA	1145.10
Stoddard solvent	HSA	labeling	1500.14(a)(4)
		special labeling	1500.14(b)(3)(11)
Stoves, coal and wood burning (see appliances)			
Strong sensitizers	HSA	definition	1500.3(b)(9)
		list of	1500.13
Sulfuric acid	HSA	labeling	1500.129(b)
	PPPA	special packaging	1700.14(a)(9)
Swimming pool slides	CPSA	standard	1207
Tank coatings	HSA	exemption from labeling	1500.83(a)(34)
Thread, string, twine, etc.	HSA	exemption from labeling	1500.83(a)(4)
Toluene (toluol)	HSA	labeling	1500.14(a)(3)
		special labeling	1500.14(b)(3)(11),(111)
		exemption from labeling	1500.83(a)(8),(9),(11),(13)
Toluene (paint solvents)	PPPA	special packaging	1700.14(a)(15)
Toxic substances	HSA	definition	1500.3(b)(5),(c)(2)
		labeling	1500.121,129
		test method	1500.40

PRODUCT	ACT	TYPE OF REGULATION	REFERENCE SOURCE
			TITLE 16 CFR PART NUMBER
Toys			
caps and toy guns producing impulse-type sound	HSA	ban testing method exemption from banning	1500.18(a)(5) 1500.47 1500.85(a)(2) 1500.86(a)(6)
clacker balls	HSA	ban exemption from banning	1500.18(a)(7) 1500.85(a)(5)
dolls presenting hazards	HSA	ban exemption from banning	1500.18(a)(3) 1500.86(a)(2)
electrically operated toys and children's articles	HSA	ban requirements labeling performance	1500.18(b) 1505 1505.3 1505.6
games, self-pressur- ized hollow plastic toys	HSA	exemption from banning	1500.85(a)(7)
mineral oil mechanical hazards (various)	HSA	exemption from banning	1500.83(a)(32)
pacifiers	HSA	ban	1500.18(a)
	HSA	ban safety requirements	1500.18(a)(8) 1511
noisemaking toys	HSA	ban	1500.18(a)(2)
toys painted with lead	HSA	ban, over 0.5% (pre- 1978)	1500.17(a)(6)
	CPSA	ban, over 0.06% (1978 and later)	1303
squeeze	CPSA	to be regulated under the CPSA	1145.10
rattles	HSA	bans exemption from banning safety requirements	1500.18(a)(1) & (15) 1500.86(a)(1) 1510
sharp edges	HSA	technical requirements	1500.49
sharp points	HSA	technical requirements	1500.48
small parts	HSA	ban safety requirements	1500.18(a)(9) 1501
model rockets	HSA	exemption from labeling	1500.83(a)(36)
model rockets, pro- pellant	HSA	exemption from labeling	1500.85(a)(8), (9), (10), (11), (12), (13)
sewing machines	HSA	requirements	1505.4(h)(3)
stuffed animals with laceration hazard	HSA	ban	1500.18(a)(3)
stuffed toys to be suspended	CPSC	to be regulated under the CPSA	1145.9
train smoke	HSA	exemption from labeling	1500.83(a)(33)
use and abuse tests	HSA	testing procedures	1500.50.53

PRODUCT	ACT	TYPE OF REGULATION	REFERENCE SOURCE
			TITLE 16 CFR PART NUMBER
Turpentine	HSA	special labeling	1500.14(b)(5)
		labeling	1500.14(a)(5)
		exemption	1500.83(a)(8)
	PPPA	special packaging	1700.14(a)(6)
Tubes, collapsible metal	HSA	labeling	1500.121(e)
Unpackaged hazardous substances	HSA	labeling requirements	1500.121(f)
Varnish	HSA	exemption from labeling	1500.83(a)(13)
Vienna paste	HSA	labeling	1500.129(1)
Vinyl chloride	HSA	ban	1500.17(a)(10)
Vinyl plastic film	FFA	standard (CS 192-53)	1611
Visual novelty devices containing perchloroethylene	HSA	exemption	1500.83(a)(31)
Volatile flammable materials	HSA	flashpoint testing method	1500.43
Walker-jumper	HSA	ban	1500.18(a)(6)
		exemption from classification	1500.86(a)(4)
Water-repellant mixtures, masonry	HSA	ban	1500.17(a)(1)
Wax containers	HSA	exemption from labeling	1500.83(a)(8)
Waxes, paste for autos, furniture, floors, shoes	HSA	exemption from labeling	1500.83(a)(8)
Wearing apparel	FFA	standard (CS 191-53)	1610
Wood burning appliances (see appliances)			
Writing instruments	HSA	exemption from labeling	1500.83(a)(38)

PRODUCT	ACT	TYPE OF REGULATION	REFERENCE SOURCE
			TITLE 16 CFR PART NUMBER
Xylene (xylol)	HSA	labeling	1500.14(a)(3)
		special labeling	1500.14(b)(3)(i), (iii)
		exemption from labeling	1500.83(a)(8), (9), (11), (13)
Xylene (paint solvents)	PPPA	special packaging	1700.14(a)(15)

Appendix I:



**Federal-State
Cooperative
Mechanisms**

FEDERAL-STATE COOPERATIVE PROGRAM

The Commission is required by Section 29 of the Consumer Product Safety Act to establish "a program to promote Federal-State cooperation for purposes of carrying out the Act."

The goal for the federal-state Cooperative Program is to reduce consumer product related deaths and injuries by leveraging CPSC resources through cost-effective cooperation with state and local governments.

The Directorate for Field Operations plans, organizes, directs and controls the Commission's federal-state Cooperative Program. This program receives overall direction through the Field Operating Plan which is formulated directly from the Commission's yearly Operating Plan. The federal-state plan provides direction to the three Regional Centers which provide operational day-to-day contact with the states.

A key part of the federal-state plan is the provision for Regional Centers to conduct a yearly planning workshop in each state. Agenda items in these meetings include: 1) discussion of Commission programs; 2) discussion of Commission priorities, 3) input into future Commission planning and priorities, 4) joint opportunities, 5) training needs, 6) communication and reporting; and 7) others

The Directorate sets program policy in conjunction with Commission priorities and manages resource allocations carefully to assure effective performance in supporting federal-state programs.

The three Regional Centers are the Commission's front-line contact with state and local agencies involved in product safety efforts. These Centers initiate and maintain liaison and develop cooperative agreements between the Commission and state and local agencies.

State Designees are the Commission's primary liaison with state and local officials. State Designees are appointed, at the Commission's request, by the Governor of each state. This individual serves as a liaison for product safety efforts within the state.

State Designees are selected after analyzing each state's structure. Each represents that department of state government most compatible with the CPSC mission. In most states it is the Department of Health. In others, it is the Office of the Attorneys General or the Department of Agriculture or Consumer Protection.

In addition to working with State Designees, CPSC Regional Centers regularly cooperate with local government officials, as well. Keeping up with Designees in 50 states and territories is demanding, but working with thousands of local officials is most difficult. To solve this problem, CPSC always works with State Designees and selectively works with local officials. "Selectively" is defined as meaning the proper official at the proper place at the proper time.

The Regional Directors are responsible for providing direction to the states that perform CPSC related work. This direction is provided in the annual state planning sessions and in frequent written, telephonic and personal contacts. Direction for the work done under contract is very specific and is spelled out in the statement of work portion of the contract.

The funded work done by the states is subject to the same quality assurance and is held to the same high standards as work done by the CPSC field staff. The progress and direction of the state work is monitored through weekly conference calls, quarterly reports and a final report at the end of the fiscal year. This enables the Regional Centers to assure that the state contract work is proceeding in accordance with the Commission's Operating Plan and is of adequate quality to meet the Commission's needs. The states report on other product safety work, not funded by CPSC, by providing highlights and summaries to CPSC field offices for input into their required program reports.

State/Local Contracts Program

Cost-effective contracts with state and local agencies for needed services provide a basis upon which greater cooperation can grow. Because our missions are compatible, state and local governments usually match our funds with their own money to accomplish the objective. In addition, state/local contracts allow us to accomplish product safety work in places across our nation that we would not get to otherwise ... our reach is expanded.

In FY-1992, the Commission supported the state and local contracts program in the amount of \$260,000 -- for Compliance and Enforcement, Hazard Identification and Analysis, and Consumer Information activities in seven program areas.