

5. Clothing Strings

Purpose - To develop a new ASTM voluntary safety standard to reduce strangulation and entanglement hazards associated with drawstrings on children's clothing

Highlights -

- o In 1/95, the ASTM Drawstrings on Children's Clothing Subcommittee (ASTM F15.37), which was established 9/17/94, approved the use of ASTM fast track provisional standard-setting procedures to expedite development of a safety standard
- o After three meetings, the subcommittee issued a ballot of a provisional standard in 4/95. In a 5/3/95 letter to the ASTM subcommittee members, CPSC staff expressed concern that the draft standard did not eliminate drawstrings in the neck area of children's outerwear garments. Staff also recommended that the standard include requirements to address drawstrings at the waist and bottom of upper outerwear garments.
- o At a 6/2/95 subcommittee meeting, negative votes requesting the elimination of drawstrings were ruled non-persuasive, and the ballot was withdrawn on the basis that technical requirements for "safer" drawstrings could be developed and a greater level of consensus could be achieved.
- o A revised provisional standard was balloted in 8/95 CPSC staff notified all subcommittee members that (1) the CPSC staff continued to oppose the use of drawstrings at the neck area of children's upper outerwear and (2) the staff was in agreement with the inclusion of requirements to address vehicular dragging hazards associated with waist and bottom drawstrings of upper outerwear.
- o The 8/95 ballot failed and at a subcommittee meeting on 9/22/95, a task group was formed to explore the possibility of having an independent testing laboratory develop safety requirements to address clothing string hazards.

6. Ranges and Ovens

Purpose - To revise both the UL standard for electric ranges (UL 858) and the ANSI standard for gas ranges (ANSI Z21.1) to reduce the number of cooking-related fire injuries and deaths.

Highlights -

- o In 2/95, CPSC signed an Interagency Agreement (IAG) with the National Institute for Standards and Technology (NIST) to: (1) identify the physical characteristics associated with imminent cooking fires and (2) identify sensing devices with the potential to sense those characteristics.
- o In 6/95, members of industry and voluntary standards organizations attended a demonstration of the NIST testing.
- o In 9/95, the NIST report on their research effort to identify the physical characteristics associated with imminent cooking fires neared completion.
- o Subsequent to the completion of Phase I research, NIST will begin Phase II of this work. Sensing devices will be tested for their potential to: (1) sense the characteristics identified in Phase I, (2) detect a pre-ignition condition, and (3) warn of approaching ignition.

7. Shock Protection Devices (GFCIs)

Purpose - To improve the Standard for Ground-Fault Circuit-Interrupters (GFCIs), UL 943, by identifying installation and reliability issues which may affect the proper operation of GFCIs and by revising the standard accordingly.

Highlights - The following activities were undertaken to address installation errors associated with receptacle-type GFCIs:

- o Effective 7/4/95, GFCI load terminals were required to be covered with a warning label explaining that load terminals are to feed additional receptacles only. Instructions describing how to differentiate "Line" from "Load" conductors and how to determine whether the GFCI has been wired properly were also required.
- o The National Electrical Manufacturers Association (NEMA) previously volunteered to oversee development of improved installation instructions. The results of the study conducted by CPSC staff to determine consumer behavior during GFCI installation are being used by NEMA in the development of the instructions. In 7/95, CPSC staff met with NEMA to review proposed new installation instructions. Testing by NEMA is planned in 1996.

8. Smoke Detectors

Purpose - To revise the Standard for Single and Multiple Station Smoke Detectors (UL 217) to improve the reliability and remove impediments to essential consumer maintenance practices.

Highlights -

- o CPSC staff met with the UL Industry Advisory Council on 1/24/95 and presented specific recommendations for improvements to the UL standard. The recommendations included:
 - (1) Require a means to silence the alarm so consumers will not permanently disable the smoke detector,
 - (2) Standardize mounting plates and electrical connections to alleviate problems that consumers experience in replacing and mounting the detector,
 - (3) Include markings on the detector to identify the date of manufacture so that consumers can replace detectors at the appropriate time intervals,
 - (4) Require an acoustic signal frequency range so that elderly adults can hear the detector's alarm,
 - (5) Improve the dust, smoldering, and corrosion tests to better replicate the household environment,
 - (6) Create a survivability test to ensure smoke detectors will survive the early stages of fire,
 - (7) Require critical components in the detector to meet reliability specifications.
- o UL formally responded to the recommendations on 5/30/95 and indicated they would propose some of the recommendations to the fifth edition of the standard and consider the others.
- o CPSC staff will continue participation with UL, industry and other interested parties during meetings to discuss the proposed recommendations. In addition, staff will continue to work with UL to modify the standard to include proposals for all the recommendations.

9. Baby Walkers

Purpose - To review and revise the existing voluntary standard for walkers (ASTM F977-89) in accordance with the ASTM requirement for a 5-year review and to advocate additional performance requirements to address the hazard of children falling down stairs in walkers.

Highlights -

- o Background - Existing Standard - The voluntary standard for infant walkers contains performance requirements addressing tip overs and structural failure. Falls down stairs are currently addressed by a warning label on the product. The existing standard is in the 5-year review process required by ASTM.
- o A subcommittee ballot of a revision to the entire ASTM walker standard closed on 3/26/95. Three negative votes were discussed at a 3/29/95 walker section meeting and two were ruled persuasive, including one about the stair-warning label. Changes to the standard in response to these negative votes were discussed and issues resolved at a 6/9/95 meeting. The proposed revisions were balloted to the subcommittee in 9/95.
- o Background - Performance Requirements to Address Stair-Falls - In 12/94, manufacturers representing a significant portion of the sales of traditional walkers formed an ASTM working group to accomplish the technical work necessary to develop new performance requirements to address the stair-fall hazard. At the 6/9/95 meeting the technical working group provided an initial draft of the new performance requirements for discussion.

10. Water Heaters, Gas

Purpose - To revise the ANSI gas water heater standard (ANSI Z21.10) in order to eliminate or reduce ignition of flammable vapors by residential gas water heaters.

Highlights -

- o Significant progress was made by industry during 1995 toward developing a voluntary standard to eliminate the risk of ignition of flammable vapors.
- o Industry formed a Joint Product Development Consortium to evaluate and test all possible technical solutions to the problem. Consortium activities are proprietary at this time, but the Consortium is briefing the CPSC staff regularly and work is on schedule and progressing.

- o Work has begun to develop a test protocol for submittal to the ANSI water heater subcommittee for inclusion in the ANSI water heater standard. A sophisticated test facility has been constructed. Shakedown testing has been successfully completed on the facility. Test method verification is awaiting delivery of new technology water heaters from the Consortium.
- o The Gas Research Institute (GRI) has increased funding for this project from \$800,000 to \$1,400,000.
- o The GRI is addressing the CPSC staff's concerns and is investigating a "worst case" test method

B. Other Significant Activities

During 1995, the staff monitored and advocated safety improvements in 30 additional voluntary standards activities. These included new voluntary standards activities which were initiated at the request of CPSC staff. A few highlights follow:

- o On 1/10/95, ANSI approved a revised national consensus standard on **hardwood plywood** which provides limits on **formaldehyde** emissions.
- o The ASTM **toy safety** standard was revised on 1/15/95 to provide for improved safety features dealing with flammability tests, toxicology, protrusions on crib toys, small parts, labeling, battery operated toys, and miscellaneous items such as clarification of test procedures for riding toys. Additional safety provisions, including those relating to pre-school play figures and pompons, were in the voting process at the end of 1995.
- o An ANSI Canvas Committee was established to develop a national consensus safety standard for **blind cords**.
- o A revision of the ASTM **stroller** standard (ASTM F833) was approved in 3/95 which added requirements addressing entrapment in leg openings and inadvertent collapse of certain umbrella style strollers.
- o The National Electrical Code for 1996 was approved on 5/25/95 and provides safety features for **electric heat tape, spas/hot tubs and GFCI's**.
- o UL proposed major improvements to its **Christmas-tree lights** standard (UL 588) which become effective 1/97.

- o The revised ANSI safety standard on (electric) cord sets and power-supply cords was approved on 5/26/95 and maintains a minimum six foot length for **extension cords**.
- o A revised ASTM standard on **playground surfacing** was approved on 8/15/95 which provides new safety requirements for impact tests on fasteners or anchoring devices used on manufactured mats that may have less than optimal shock attenuation characteristics.
- o A new ASTM provisional standard with consumer safety specifications for **toddler beds** was approved on 8/22/95. Work continues on a full standard, while the provisional standard remains in effect
- o On 8/30/95, ASTM established a subcommittee (ASTM F15.38) to develop a national consensus safety standard for **window guards**.
- o On 8/31/95, ASTM initiated a new group (ASTM F15.39) to develop a national consensus safety standard on **bean bag chairs**.
- o ANSI interim safety provisions for **20lb. gas grills** were superseded by final provisions which become effective on 10/1/95. These provisions provide for leak and overpressure protection.

Also during the reporting period, the CPSC staff worked with national consensus voluntary standards coordinating groups to improve consumer product safety. Highlights of these activities follow:

- o ASTM further expedited the standards development process by permitting simultaneous voting at the Committee and Society levels. At a minimum, this should save several months in the approval process.
- o UL responded to CPSC staff's request to further open the standards development process by announcing a new program whereby Technical Advisory Panels (TAPs) will include CPSC staff at the earliest stage of a UL consumer product safety standard's development.
- o ANSI asked its standards developers to speed adoption of critical standards by using fast track procedures to develop "Draft Standards For Trial Use".
- o ANSI's Consumer Interest Council proceeded with its priority project to improve conformance to consumer product safety standards. This involves a market research study to determine the causes of why safety standards are or are not used and the identification of specific ways to enhance the use of safety standards

- o The CPSC voluntary standards conformance monitoring program on **wooden bunk beds** was completed. Over 250 letters were mailed to those believed to be manufacturers and importers of bunk beds in order to determine the degree of conformance to the ASTM bunk bed safety standard. Twenty-five companies which manufactured, imported, or sold wooden bunk beds with potential entrapment hazards were requested to provide immediate corrective action. The results of these activities were provided to the Commission during 1995.
- o The CPSC staff performed tests on **backyard playsets** to determine the extent of conformance to the ASTM national consensus safety standard. A meeting with manufacturers was held in 9/95 to review final testing results.

SUMMARY LISTING OF FY 1995 VOLUNTARY STANDARDS PROJECTS

Product/Project (1)

PARTICIPATION LEVEL

1. Five Gallon Buckets

FIRE/GAS CODES & STDS.

2. CO Detectors
3. Gas Water Heaters
4. Ranges
5. Smoke Detectors

SPORTS & RECREATION

6. Baseball Equipment
7. Camping Equipment

CHILDREN'S PRODUCTS

8. Clothing Strings
9. Walkers, Baby

ELEC./POWER CODES & STDS.

10. Shock Protection Devices

MONITORING LEVEL

1. Fireworks Devices

ELEC./POWER CODES & STDS

2. Elec. Reinspection
3. National Elec. Code
4. Heat Tapes
5. Chain Saws
6. Garage Door Operators
7. Riding Mowers

CHILDREN'S PRODUCTS

8. Bath Rings
9. Beds, Toddler
10. Bicycle Helmets
11. Blind Cords
12. Cribs, Non-Full-Size
13. Playground Equip Home
14. Playground Equip Public
15. Playground Equip Soft
16. Playground Surfacing
17. Play Yards
18. Soft Goods/Infant Bedding
19. Strollers
20. Toy Safety
21. Child Resistant Pkg.
22. Lead Abatement
23. Sleepwear, Children's

INDOOR AIR QUALITY

24. ASHRAE IAQ Stds.

FIRE/GAS CODES & STDS

25. Central Furnaces
26. Gas Systems;
Overpressurization
27. Gas Venting System
28. 20lb Systems
29. Vented Gas Heaters
30. Upholstered Furniture

Note. (1) Definitions of participation and monitoring levels of involvement follow on next page.

**Definitions of Participation and Monitoring Levels of Involvement
(See 16 CFR 1031.10(b) and (c)).**

Participation includes one or more of the following and is greater involvement than monitoring: regularly attending meetings of a standards development group; taking an active part in discussions; research; engineering, health sciences, economics, or epidemiology support, information and education programs; and administrative assistance.

Monitoring includes one or more of the following and is lesser involvement than participation: maintaining awareness of the standards development activities through written and oral inquiries; receiving and reviewing minutes of meetings and copies of draft standards; attending meetings and making comments, as appropriate; and responding to requests for information on risks of injury.

APPENDIX F: Voluntary Corrective Action Plans and Product Recalls

Subsection A/Regulatory Recalls

Subsection B/Section 15 Recalls

Voluntary Corrective Action Plans And Product Recalls

Voluntary Corrective Action Plans and Recall of Products Subject to Product Safety Standards and Other Specific Regulations Exclusive of Section 15 of the Consumer Product Safety Act

The Office of Compliance and Enforcement and the Regional Offices are jointly responsible for identification of consumer products that fail to comply with a specific product safety standard or other CPSC product-related requirements mandated by statute or regulation. CPSC works cooperatively with the responsible companies to obtain voluntary corrective action plans monitored by the commission during Fiscal Year 1995.

Consumers may find products on the market that resemble those appearing on this list. After manufacturers and importers correct violations, they may distribute complying versions of products which were recalled. CPSC monitors recalls to ensure that the noncomplying products have been removed from the market. It is unfair to responsible manufacturers and importers to conclude that toys and children's products on the list are still offered for sale.

Voluntary Corrective Action Plans and Product Recalls Regulatory Recalls

Date	Product/Model	Violation	Manufacturer/Imp.
10/3/94	Ferro-Tone Liquid Plus*Herbs #55373	child resistant closure 16 CFR 1700.14	World Organics, Inc. Hungington Beach, CA 92649
10/3/94	Ferro-Tone Liquid Plus Herbs unknown	child resistant closure 16 CFR 1700.14	World Organics, Inc. Hungington Beach, CA 92649
10/3/94	Ferro-Tone Liquid Plus Herbs unknown	child resistant closure 16 CFR 1700.14	World Organics, Inc. Hungington Beach, CA 92649
10/4/94	Missile Antifreeze & Solvent N/A	child resistant closure 16 CFR 1700.14	Felton Oil Company, Inc. El Dorado, AR 71731
10/4/94	Rayon Sheer Skirt N/A	flammability 16 CFR 1610	Prime Time Sportswear, Inc. New York, NY 10001
10/12/94	Rayon Sheer Skirt #100s/100p	flammability 16 CFR 1610	Gunter by Nash New York, NY 10018
10/12/94	Rayon Chiffon Skirts N/A	flammability 16 CFR 1610	Primitive Arts Ltd. New York, NY 10016
10/12/94	Rayon Sheer Skirt N/A	flammability 16 CFR 1610	Vini of New York, Inc. New York, NY 10001
10/14/94	Rayon Chiffon Skirts N/A	flammability 16 CFR 1610	Aviation & Travel Consultants Pleasantville, NY 10570
10/14/94	Rayon Chiffon Skirts N/A	flammability 16 CFR 1610	Azizsons International, Inc. Elmhurst, NY 11373
10/14/94	Rayon Crepe Style Ghagra Skirt #3502	flammability 16 CFR 1610	Creative Clothing New York, NY 10018
10/14/94	Rayon Chiffon Skirts #932/792, 258	flammability 16 CFR 1610	Geeta of India, Inc. Loconia, NH 03246
10/14/94	Rayon Chiffon Skirts #S4057	flammability 16 CFR 1610	Hobnob, Inc. New York, NY 10018
10/14/94	Rayon Chiffon Skirts #8456, 8396,	flammability 16 CFR 1610	I.E Industries Fashions, Inc. New York, NY 10018

Date	Product/Model	Violation	Manufacturer/Imp.
10/17/94	Rayon Sheer Skirt N/A	flammability 16 CFR 1610	Pan Am Fashions (USA), Inc. New York, NY 10001
10/17/94	Rayon Skirt #5016	flammability 16 CFR 1610	Roohi Designs, Inc. New York, NY 10001
10/17/94	Rayon Skirt N/A	flammability 16 CFR 1610	Roohi Designs, Inc. New York, NY 10001
10/17/94	Rayon Skirt N/A	flammability 16 CFR 1610	Roohi Designs, Inc. New York, NY 10001
10/17/94	Rayon Sheer Skirt N/A	flammability 16 CFR 1610	Takli Collections, Inc. Jamaica, NY 11434
10/18/94	Chiffon Short Skirt #2834	flammability 16 CFR 1610	Asprey, Inc. New York, NY 10018
10/18/94	Crinkle Skirt #2833	flammability 16 CFR 1610	Asprey, Inc. New York, NY 10018
10/18/94	Rayon Sheer Skirt N/A	flammability 16 CFR 1610	Atul Parekh Jersey City, NJ 07307
10/18/94	Rayon Chiffon Skirt #1309JG-BRN,	flammability 16 CFR 1610	British Khaki New York, NY 10018
10/18/94	Rayon Sheer Skirt N/A	flammability 16 CFR 1610	Fashion Barn Towaco, NJ 07082
10/18/94	Rayon Sheer Skirt Sportique	flammability 16 CFR 1610	Hind Indian Cottage Emporium New York, NY 10001
10/18/94	Rayon Chiffon Sheer Skirt N/A	flammability 16 CFR 1610	Johnny's Signature, Inc. New York, NY 10018
10/18/94	Rayon Sheer Skirt #401	flammability 16 CFR 1610	Santa Cruz Fashions Daytona Beach, FL 32120
10/24/94	Rayon Chiffon Skirt-Chaus Woman #244435, 244436	flammability 16 CFR 1610	Bernard Chaus, Inc. Seacaucus, NJ 07094
10/24/94	Chiffon Skirt unknown	flammability 16 CFR 1610	Oriental Plus, Inc. New York, NY 10001

Date	Product/Model	Violation	Manufacturer/Imp.
10/24/94	5 x 8 Ft Border Rugs #74-3033	flammability 16 CFR 1630	Spiegel, Inc Downers Grove, IL 60515
10/24/94	Brain Quest for Threes #3633	small parts 16 CFR 1501	Workman Publishing Co., Inc. New York, NY 10003
10/24/94	My First Brain Quest #3634	small parts 16 CFR 1501	Workman Publishing Co., Inc New York, NY 10003
10/31/94	Stack & Dump Truck #0484B	sharp points 16 CFR 1500 48	Newfield Child Development, Inc. Shelton, CT 06484
10/31/94	Stack & Dump Truck #0494B	sharp points 16 CFR 1500 48	Newfield Child Development, Inc. Shelton, CT 06484
10/31/94	Stack & Dump Truck #0524B	sharp points 16 CFR 1500.48	Newfield Child Development, Inc. Shelton, CT 06484
10/31/94	Bread/Sausage/Cheese/Apple #KSAL/FOO	lead-in-paint 16 CFR 1303	Pleasant Company Middleton, WI 53562
10/31/94	Fruit tarts/Lemons/Oranges/Cake #EBAP/FOO	lead-in-paint 16 CFR 1303	Pleasant Company Middleton, WI 53562
10/31/94	Gingerbread cookie #SSAL/GIN	lead-in-paint 16 CFR 1303	Pleasant Company Middleton, WI 53562
10/31/94	Saint Lucia Buns #KCAT/BUN	lead-in-paint 16 CFR 1303	Pleasant Company Middleton, WI 53562
10/31/94	Sandwich/Cookie/Carrot/Celery #MSAL/FOO	lead-in-paint 16 CFR 1303	Pleasant Company Middleton, WI 53562
10/31/94	Sandwich/Peach/Egg #SSAL/FOO	lead-in-paint 16 CFR 1303	Pleasant Company Middleton, WI 53562
11/1/94	My Alphabet Truck #SHYE-AT-002	small parts 16 CFR 1501	DS-MAX U.S.A INC. Irvine, CA 92718
11/2/94	Chiffon Skirts N/A	flammability 16 CFR 1610	Express, Inc. Columbus, OH 43230
11/9/94	Reindeer Christmas Stocking 74503	small parts 16 CFR 1501	Price Costco, Inc. Kirkland, WA 98033

Date	Product/Model	Violation	Manufacturer/Imp.
11/9/94	Reindeer Christmas Stocking 79750	small parts 16 CFR 1501	Price Costco, Inc. Kirkland, WA 98033
11/17/94	Bear Pendant #YC/W1016	small parts 16 CFR 1501	Colossal Jewelry & Accessories Saddle Brook, NJ 07662
11/17/94	Chiffon Skirts N/A	flammability 16 CFR 1610	International Fashions Fridley, MN 55432
11/21/94	11" Color Bear #CB 9311	small parts 16 CFR 1501	Link & Pan of Texas Houston, TX 77013
11/21/94	11" I Love You Bear w/Red Shirt #BL 9311	small parts 16 CFR 1501	Link & Pan of Texas Houston, TX 77013
11/21/94	11" I Love You Panda w/Red Shirt #PL 9311	small parts 16 CFR 1501	Link & Pan of Texas Houston, TX 77013
11/21/94	Rayon Chiffon Skirt #10936XXL	flammability 16 CFR 1610	Mahudi International Corp. Miami, FL 33172
11/21/94	Rayon Chiffon Skirt #9-10936	flammability 16 CFR 1610	Mahudi International Corp. Miami, FL 33172
11/21/94	Rayon Chiffon Skirt #9-10936XL	flammability 16 CFR 1610	Mahudi International Corp. Miami, FL 33172
11/21/94	Rayon Chiffon Skirt #99710XXL	flammability 16 CFR 1610	Mahudi International Corp. Miami, FL 33172
11/21/94	Rayon Chiffon Skirt #N-37	flammability 16 CFR 1610	Mahudi International Corp. Miami, FL 33172
11/21/94	Rayon Chiffon Skirt #N-37XL	flammability 16 CFR 1610	Mahudi International Corp. Miami, FL 33172
11/21/94	Crinkle Pants #72-1008	flammability 16 CFR 1610	Spiegel, Inc. Downers Grove, IL 60515
11/21/94	Halter Top #72-1007	flammability 16 CFR 1610	Spiegel, Inc. Downers Grove, IL 60515
11/21/94	Ombre Skirt #14-1400	flammability 16 CFR 1610	Spiegel, Inc. Downers Grove, IL 60515

Date	Product/Model	Violation	Manufacturer/Imp.
11/21/94	India Chiffon Skirt #906	flammability 16 CFR 1610	Sunbelt Sportswear San Antonio, TX 78247
11/22/94	Rayon Chiffon Skirt #4025	flammability 16 CFR 1610	Eastern Trends New York, NY 10016
11/25/94	Gerber NUK Orthodontic Pacifiers NUK	pacifier failure 16 CFR 1511	Gerber Products Company Fremont, MI 49413
11/30/94	Necklace Party Favor #39116	small parts 16 CFR 1501	Amscan Inc. Harrison, NY 10528
11/30/94	Rayon Chiffon Skirt #101RN 88707	flammability 16 CFR 1610	Renuka Inc New York, NY 10001
12/1/94	Play Tool Truck #3009	small parts 16 CFR 1501	Big Save International Corp. Los Angeles, CA 90058
12/1/94	Fun Music Center #1062	small parts 16 CFR 1501	Imaginarium, Inc Walnut Creek, CA 94596
12/1/94	Roll-Back Toy w/Bear Figure #K2539	small parts 16 CFR 1501	The Berton Company Commerce, CA 90022
12/5/94	Bracelets #39231	small parts 16 CFR 1501	Amscan, Inc. Harrison, NY 10528
12/5/94	Fire Engine #39137	small parts 16 CFR 1501	Amscan, Inc. Harrison, NY 10528
12/5/94	Rayon Chiffon Skirt #2890	flammability 16 CFR 1610	H K. Garmarian & Co., Inc. New Rochelle, NY 10801
12/5/94	Extra Large Learn-the-Alphabet #3044	small parts 16 CFR 1501	Kam Kee Trading Brooklyn, NY 11222
12/12/94	Sesame Street Sleepwear N JT332-1379D	flammability 16 CFR 1615/16	Salant Children's Apparel Group New York, NY 10036
12/13/94	Wooden Rocking Horses #1000S	small parts 16 CFR 1501	Target Stores Minneapolis, MN 55440
12/19/94	Necklace #8847	small parts 16 CFR 1501	M. Pressner & Co., Inc. Brooklyn, NY 11201

Date	Product/Model	Violation	Manufacturer/Imp.
12/20/94	Glow in the Dark Bracelets #ND48901	small parts 16 CFR 1501	Small World Toys Culver City, CA 90230
12/20/94	Mini-Charmy Necklace #8008	small parts 16 CFR 1501	Small World Toys Culver City, CA 90230
12/21/94	Basic Skills Puzzle Set #QB448	small parts 16 CFR 1501	Troll Associates, Inc. Mahwah, NJ 07430
12/21/94	Set of Four Pegged Puzzles #QP340	small parts 16 CFR 1501	Troll Associates, Inc. Mahwah, NJ 07430
12/27/94	Christmas in the Manger book ISBN069400605X	small parts 16 CFR 1501	Harper Collins Publishers New York, NY 10022
12/28/94	Christmas Shaky Pals #14001	small parts 16 CFR 1501	Great Atlantic & Pacific Tea Co. Montvale, NJ 07645
12/30/94	Decorator Pacifiers #34505	pacifier failure 16 CFR 1511	Target Stores Minneapolis, MN 55440
12/30/94	Inflatable Snoopy Christmas Toys #B650	small parts 16 CFR 1501	Target Stores Minneapolis, MN 55440
1/9/95	Ghost Blaster Zapper N/A	small parts 16 CFR 1501	Premier Promotions & Marketing Van Nuys, CA 91411
1/10/95	Halloween Toy Eraser Assortment N/A	small parts 16 CFR 1501	Oriental Trading Company, Inc. Omaha, NE 68137
1/11/95	Wooden Toy Trucks #340042	small parts 16 CFR 1501	Dollar Tree, Inc. Norfolk, VA 23501
1/11/95	Wooden Toy Trucks #393736	small parts 16 CFR 1501	Dollar Tree, Inc. Norfolk, VA 23501
1/12/95	Necklace w/Mercury Ampule N/A	labeling 15 CFR 1500	Doreau Designs Carlsbad, CA 92009
1/18/95	Bracelet #351-036	small parts 16 CFR 1501	Dan Brechner & Co., Inc. Floral Park, NY 11001
1/18/95	Bracelet #351-038	small parts 16 CFR 1501	Dan Brechner & Co., Inc. Floral Park, NY 11001

Date	Product/Model	Violation	Manufacturer/Imp.
1/18/95	Train #652-031	small parts 16 CFR 1501	Dan Brechner & Co , Inc. Floral Park, NY 11001
1/18/95	Truck #TS-805	small parts 16 CFR 1501	Dan Brechner & Co , Inc. Floral Park, NY 11001
1/18/95	14-Piece Baby Bottle Bank w/NUK #40382D12	pacifier failure 16 CFR 1511	Ralphco, Inc Worcester, MA 01602
1/19/95	Just Cruzing Chiffon Skirt #RN 74748	flammability 16 CFR 1610	Radhika Imports, Inc. Los Angeles, CA 90015
1/19/95	Playhouse Prop #5300	lead-in-paint 16 CFR 1303	The Angeles Group Pacific, MO 63069
1/19/95	Put-Away Prop #5400	lead-in-paint 16 CFR 1303	The Angeles Group Pacific, MO 63069
1/19/95	Table Town Prop #5786	lead-in-paint 16 CFR 1303	The Angeles Group Pacific, MO 63069
1/20/95	Chiffon Skirts N/A	flammability 16 CFR 1610	Neelam Fashions Union, NJ 07083
1/24/95	12" Red Child's Stool #202KRN12C	lead-in-paint 16 CFR 1303	Atlantic Flyway/Saunders Bros. Westbrook, ME 04098
1/26/95	Zap Zap Racetrack N/A	small parts 16 CFR 1501	Kidpower, Inc Brentwood, TN 37027
2/6/95	Revco Pain Reliever #ZB4K010D	child resistant closure 16 CFR 1700 14	Revco D S , Inc. Twinsburg, OH 44087
2/6/95	Revco Pain Reliever #ZB4K046D	child resistant closure 16 CFR 1700.14	Revco D.S., Inc Twinsburg, OH 44087
2/7/95	Chiffon Skirt #1101	flammability 16 CFR 1610	Zanana Fashions, Inc New York, NY 10001
2/8/95	Littlest Pet Shop Toy Tea Set #27310	small parts 16 CFR 1501	Kid Dimension/Hasbro, Inc. Pawtucket, RI 02862
2/9/95	Fudge Pop Rattle #04 Fudge Pop	rattle failure 16 CFR 1510	Zoll Woodworks Wurtsboro, NY 12790

Date	Product/Model	Violation	Manufacturer/Imp.
2/9/95	Lollipop Rattle #05 Lollipop	rattle failure 16 CFR 1510	Zoll Woodworks Wurtsboro, NY 12790
2/15/95	Hey Diddle Diddle Children's Book ISBN0374330611	small parts 16 CFR 1501	Farrar, Straus & Giroux, Inc. New York, NY 10003
2/16/95	Inflatable Snoopy Christmas Toys #B650/1-99	small parts 16 CFR 1501	Remco Baby/Azrak-Hamway New York, NY 10010
2/16/95	Inflatable Snoopy Christmas Toys #B650/2-99	small parts 16 CFR 1501	Remco Baby/Azrak-Hamway New York, NY 10010
2/16/95	Inflatable Snoopy Christmas Toys #B650/3-99	small parts 16 CFR 1501	Remco Baby/Azrak-Hamway New York, NY 10010
2/16/95	Inflatable Snoopy Christmas Toys #B650/4-99	small parts 16 CFR 1501	Remco Baby/Azrak-Hamway New York, NY 10010
2/21/95	Sweaters #7384, 7384X,et	flammability 16 CFR 1610	Michael Simon, Inc. New York, NY 10018
2/21/95	Wompkee Plush Animal N/A	sharp point 16 CFR 1500.48	Wompkee, Inc Townsend, VT 05353
2/27/95	Funny Beetle Toy #ZH-907	small parts 16 CFR 1501	K.T. Toys Co. Los Angeles, CA 90013
2/27/95	Sound Locomotive Toy #F1012P	small parts 16 CFR 1501	K.T. Toys Co Los Angeles, CA 90013
2/27/95	Touch & Learn Toy #CS-9033	small parts 16 CFR 1501	K.T. Toys Co. Los Angeles, CA 90013
3/13/95	Speed Boats #27526	small parts 16 CFR 1501	Division Sales, Inc. Itasca, IL 60143
3/14/95	Rolling Ball Rattle Teether #520-E	rattle failure 16 CFR 1510	Sanitoy, Inc. Fitchburg, MA 01420
3/14/95	Rolling Ball Rattle Teether #520-Z	rattle failure 16 CFR 1510	Sanitoy, Inc. Fitchburg, MA 01420
3/16/95	Penguin #69405	small parts 16 CFR 1501	Patagonia Ventura, CA 93002

Date	Product/Model	Violation	Manufacturer/Imp.
3/20/95	3 Toy Baby Bottles w/Nipples #D942	small parts 16 CFR 1501	G. Suarez and Son, Inc San Juan, Puerto Rico 00936
3/20/95	Telephone Pull Toy Train #KW9201	small parts 16 CFR 1501	G. Suarez and Son, Inc. San Juan, Puerto Rico 00936
3/21/95	Pom Pom Drum #808	small parts 16 CFR 1501	Hebron Imports, Inc. Chicago, IL 60625
3/23/95	Buffalo Hooded Sweatshirt #317	flammability 16 CFR 1610	Back Country Clothing Boulder, CO 80301
3/23/95	Crew Neck Sweat Shirt #PF501	flammability 16 CFR 1610	LongHdleShirt/KlondikeDryGds Monroe, NC 28112
3/23/95	Quilted Pique Sweatshirt #8000	flammability 16 CFR 1610	Lortex for Native Origins Des Moines, IA 50309
3/23/95	Women's Wrap Robes #498G20,498G20M	flammability 16 CFR 1610	MGT Industries/CaliforniaDyna Los Angeles, CA 90061
3/23/95	Zip Up Robe #498G21	flammability 16 CFR 1610	MGT Industries/CaliforniaDyna Los Angeles, CA 90061
3/23/95	Highlander Fleece Fabric #N15LF1,N23HFL1	flammability 16 CFR 1610	Nancy's Notions, Ltd. Beaver Dam, WI 53916
3/23/95	Crew Neck Top #980	flammability 16 CFR 1610	T Hayes Salt Lake City, UT 84106
3/23/95	Henley Top #1010	flammability 16 CFR 1610	T. Hayes Salt Lake City, UT 84106
3/23/95	Crew Neck #950	flammability 16 CFR 1610	Terrific/Embroidery Services Erlanger, KY 41018
3/23/95	Zippered Pullover #1155	flammability 16 CFR 1610	TheSandGeneration/Surf theEarth Garden City Beach, SC 29576
3/24/95	Button Front Big Shirt #1779x761	flammability 16 CFR 1610	Alias New York, NY 10018
3/24/95	Cuff Pant #2547x761	flammability 16 CFR 1610	Alias New York, NY 10018

Date	Product/Model	Violation	Manufacturer/Imp.
3/24/95	Solid Crop Top #1778x761	flammability 16 CFR 1610	Alias New York, NY 10018
3/24/95	Stripe Crop Top #1778x073	flammability 16 CFR 1610	Alias New York, NY 10018
3/24/95	Hooded Top #44133	flammability 16 CFR 1610	American Fashion Group, Ltd. New York, NY 10018
3/24/95	Top #44130	flammability 16 CFR 1610	American Fashion Group, Ltd. New York, NY 10018
3/24/95	Top #44131	flammability 16 CFR 1610	American Fashion Group, Ltd. New York, NY 10018
3/24/95	Top #44132	flammability 16 CFR 1610	American Fashion Group, Ltd. New York, NY 10018
3/24/95	Hooded Sweatshirt #2003	flammability 16 CFR 1610	Austins Sportswear, Inc W. Yarmouth, MA 02673
3/24/95	Hooded Sweatshirt #4003	flammability 16 CFR 1610	Austins Sportswear, Inc. W Yarmouth, MA 02673
3/24/95	Sweatshirt #2002	flammability 16 CFR 1610	Austins Sportswear, Inc. W Yarmouth, MA 02673
3/24/95	Sweatshirt #4002	flammability 16 CFR 1610	Austins Sportswear, Inc. W. Yarmouth, MA 02673
3/24/95	Fleece Jumper #1380	flammability 16 CFR 1610	Black Parrot Elkins Park, PA 19027
3/24/95	Fleece Overalls #1388	flammability 16 CFR 1610	Black Parrot Elkins Park, PA 19027
3/24/95	Fleece Pants #3131	flammability 16 CFR 1610	Black Parrot Elkins Park, PA 19027
3/24/95	Fleece Pullover #4510	flammability 16 CFR 1610	Black Parrot Elkins Park, PA 19027
3/24/95	Reversible 3-Season Jacket #121	flammability 16 CFR 1610	Black Parrot Elkins Park, PA 19027

Date	Product/Model	Violation	Manufacturer/Imp.
3/24/95	Reversible Classic Jacket #111	flammability 16 CFR 1610	Black Parrot Elkins Park, PA 19027
3/24/95	Marquesas Fleece-Out Pullover #305K	flammability 16 CFR 1610	Orvis Company, Inc Manchester, VT 05254
3/24/95	Malachite-button shirt #1615	flammability 16 CFR 1610	Spyder Active Sports Inc (Stryke) Boulder, CO 80301
3/24/95	Shroud-hooded sweatshirt #1611	flammability 16 CFR 1610	Spyder Active Sports Inc.(Stryke) Boulder, CO 80301
3/24/95	Sweatshirt-pullover #1116	flammability 16 CFR 1610	Spyder Active Sports Inc (Stryke) Boulder, CO 80301
3/24/95	Thermite-pant #1612	flammability 16 CFR 1610	Spyder Active Sports Inc (Stryke) Boulder, CO 80301
3/24/95	Turret-button vest #1613	flammability 16 CFR 1610	Spyder Active Sports Inc (Stryke) Boulder, CO 80301
3/24/95	Vest-zipper front #1115	flammability 16 CFR 1610	Spyder Active Sports Inc.(Stryke) Boulder, CO 80301
3/27/95	Adventure Short in Natural #M536M	flammability 16 CFR 1610	Cannondale Corporation Georgetown, CT 06829
3/27/95	Sherpa Lamb Sweatshirt in Natural #U542	flammability 16 CFR 1610	Cannondale Corporation Georgetown, CT 06829
3/27/95	Anorak Jacket One Size #12801	flammability 16 CFR 1610	Carushka, Inc Van Nuys, CA 91405
3/27/95	Black or White Lamb-One Size #12813	flammability 16 CFR 1610	Carushka, Inc Van Nuys, CA 91405
3/27/95	Drawstring Short One Size #12793	flammability 16 CFR 1610	Carushka, Inc. Van Nuys, CA 91405
3/27/95	Embroidered Top One Size #12800	flammability 16 CFR 1610	Carushka, Inc. Van Nuys, CA 91405
3/27/95	Hooded Vest One Size #12792	flammability 16 CFR 1610	Carushka, Inc Van Nuys, CA 91405

Date	Product/Model	Violation	Manufacturer/Imp.
3/27/95	Oversize Sweatshirt #12763	flammability 16 CFR 1610	Carushka, Inc. Van Nuys, CA 91405
3/27/95	Pull-On Pant (S, M, L) #12723	flammability 16 CFR 1610	Carushka, Inc. Van Nuys, CA 91405
3/27/95	Crewneck Fleece Sweatshirt #14002	flammability 16 CFR 1610	Charles Sakmann Golf, Inc Laureldale, PA 19605
3/27/95	Long Sleeve Shirt w/Reverse Collar #MS 3480, BS 34	flammability 16 CFR 1610	San Diego Apparel Group San Diego, CA 92121
3/27/95	Oversized Mock Neck w/Draw Cord #51944M	flammability 16 CFR 1610	San Diego Apparel Group San Diego, CA 92121
3/27/95	Zip Mock w/Draw Cord Waist #56944B, 56944M	flammability 16 CFR 1610	San Diego Apparel Group San Diego, CA 92121
3/27/95	Button Front Big Shirt #R1101	flammability 16 CFR 1610	Spot International Irvine, CA 92714
3/27/95	Zip Jacket w/Hood #R1071	flammability 16 CFR 1610	Spot International Irvine, CA 92714
3/27/95	Hooded Pullover #100	flammability 16 CFR 1610	Squiggly Rags Chicago, IL 60639
3/27/95	Polo Shirt #101	flammability 16 CFR 1610	Squiggly Rags Chicago, IL 60639
3/27/95	Sweatpants #002	flammability 16 CFR 1610	Squiggly Rags Chicago, IL 60639
3/27/95	Sweatshirt #001	flammability 16 CFR 1610	Squiggly Rags Chicago, IL 60639
3/27/95	Vest #300	flammability 16 CFR 1610	Squiggly Rags Chicago, IL 60639
3/27/95	Zipper Polo #102	flammability 16 CFR 1610	Squiggly Rags Chicago, IL 60639
3/27/95	Hooded Shirt #LM106	flammability 16 CFR 1610	Surf Style, Inc. Dania, FL 33004

Date	Product/Model	Violation	Manufacturer/Imp.	
3/27/95	Pants #LM201	flammability 16 CFR 1610	Surf Style, Inc. Dania, FL	33004
3/27/95	Pullover #LM102	flammability 16 CFR 1610	Surf Style, Inc Dania, FL	33004
3/27/95	Shirt #LM103	flammability 16 CFR 1610	Surf Style, Inc Dania, FL	33004
3/27/95	Shorts #LM303	flammability 16 CFR 1610	Surf Style, Inc Dania, FL	33004
3/27/95	Shorts (reversed) #LM301	flammability 16 CFR 1610	Surf Style, Inc Dania, FL	33004
3/27/95	Hooded Shirt #3 DORI	flammability 16 CFR 1610	Surfival, Inc Hollywood, FL	33021
3/27/95	Zipper Front Shirt #1ELI	flammability 16 CFR 1610	Surfival, Inc Hollywood, FL	33021
3/27/95	Crew-Neck Top #1764,1864,M612	flammability 16 CFR 1610	Susan Barry Design Seattle, WA	98101
3/27/95	Cropped V-Neck Shirt #1755, 1856	flammability 16 CFR 1610	Susan Barry Design Seattle, WA	98101
3/27/95	Hooded Sweatshirt #UI968,UK968	flammability 16 CFR 1610	Susan Barry Design Seattle, WA	98101
3/27/95	Hooded Dress #UI956,UN956,UY	flammability 16 CFR 1610	Susan Barry Design Seattle, WA	98101
3/27/95	Shorts #1725,UH941,UK9	flammability 16 CFR 1610	Susan Barry Design Seattle, WA	98101
3/27/95	Skirts #1755,M511,M512	flammability 16 CFR 1610	Susan Barry Design Seattle, WA	98101
3/27/95	Turtleneck Top #1778x073	flammability 16 CFR 1610	Susan Barry Design Seattle, WA	98101
3/27/95	Vest #1783, 1883	flammability 16 CFR 1610	Susan Barry Design Seattle, WA	98101

Date	Product/Model	Violation	Manufacturer/Imp.
3/27/95	Crew Neck Crop Top #2162	flammability 16 CFR 1610	Suzy Phillips Originals, Inc. Staten Island, NY 10305
3/27/95	Crew Neck Crop Top #3023	flammability 16 CFR 1610	Suzy Phillips Originals, Inc. Staten Island, NY 10305
3/27/95	Crew Neck w/Side Vents #2167	flammability 16 CFR 1610	Suzy Phillips Originals, Inc. Staten Island, NY 10305
3/27/95	Hooded Top #3086	flammability 16 CFR 1610	Suzy Phillips Originals, Inc. Staten Island, NY 10305
3/27/95	Crop Jacket #HP 9173	flammability 16 CFR 1610	Swept Away Santa Barbara, CA 93121
3/27/95	Oversized Top #HP 9042	flammability 16 CFR 1610	Swept Away Santa Barbara, CA 93121
3/27/95	V-Neck #HP 9172	flammability 16 CFR 1610	Swept Away Santa Barbara, CA 93121
3/28/95	Hooded Sweatshirt #9-1197	flammability 16 CFR 1610	Showmart Los Angeles, CA 90015
3/28/95	Zippered Front Sweatshirt #11-1117	flammability 16 CFR 1610	Showmart Los Angeles, CA 90015
3/29/95	Adult Lamb Fleece Sweatshirt #2808TM	flammability 16 CFR 1610	Durango Threadworks Durango, CO 18301
3/29/95	Adult Lamb Fleece Sweatshirt #2809CG	flammability 16 CFR 1610	Durango Threadworks Durango, CO 18301
3/29/95	Adult Lamb Fleece Sweatshirt #2809MV	flammability 16 CFR 1610	Durango Threadworks Durango, CO 18301
3/29/95	Adult Lamb Fleece Sweatshirt #2809NY	flammability 16 CFR 1610	Durango Threadworks Durango, CO 18301
3/29/95	Adult Lamb Fleece Sweatshirt #2809QA	flammability 16 CFR 1610	Durango Threadworks Durango, CO 18301
3/29/95	Adult Lamb Fleece Sweatshirt #2809RA	flammability 16 CFR 1610	Durango Threadworks Durango, CO 18301

Date	Product/Model	Violation	Manufacturer/Imp.	
3/29/95	Child Lamb Fleece Sweatshirt N/A	flammability 16 CFR 1610	Durango Threadworks Durango, CO	18301
3/29/95	Eyelet Polo w/Drawstring #1046	flammability 16 CFR 1610	Gibraltar, P R , Inc San Lorenzo, PR	00754
3/29/95	Eyelet Polo w/Stripe Collar #1045	flammability 16 CFR 1610	Gibraltar, P R., Inc. San Lorenzo, PR	00754
3/29/95	Hood Top w/Kangaroo Pockets #1043	flammability 16 CFR 1610	Gibraltar, P R., Inc. San Lorenzo, PR	00754
3/29/95	Long Sleeve Turtle Neck Polo #1053	flammability 16 CFR 1610	Gibraltar, P R., Inc San Lorenzo, PR	00754
3/29/95	Steep Sweat Top #72709	flammability 16 CFR 1610	The North Face, Inc Berkeley, CA	94710
3/30/95	Fleece Top and Bottom Set #H4B805	flammability 16 CFR 1610	Funny Bunny, Inc Santa Ana, CA	92705
3/30/95	Basic Crew N/A	flammability 16 CFR 1610	North Shore Trading Danvers, MA	01923
3/30/95	Four Button Placket N/A	flammability 16 CFR 1610	North Shore Trading Danvers, MA	01923
3/30/95	Pullover w/Zipper N/A	flammability 16 CFR 1610	North Shore Trading Danvers, MA	01923
3/30/95	Vest N/A	flammability 16 CFR 1610	North Shore Trading Danvers, MA	01923
3/30/95	Zip Cowl Neck N/A	flammability 16 CFR 1610	North Shore Trading Danvers, MA	01923
3/30/95	Sherpa Boxy Crew #71520	flammability 16 CFR 1610	Ojai Ventrua, CA	93001
3/30/95	Sherpa Cardigan #71522	flammability 16 CFR 1610	Ojai Ventrua, CA	93001
3/30/95	Sherpa Long Sleeve Cardigan #708	flammability 16 CFR 1610	PA Company Brookline, MA	02146

Date	Product/Model	Violation	Manufacturer/Imp.	
3/30/95	Sherpa Long Sleeve Crop Scoop #1074	flammability 16 CFR 1610	PA Company Brookline, MA	02146
3/30/95	Sherpa Long Sleeve Crop w/Pockets #1043	flammability 16 CFR 1610	PA Company Brookline, MA	02146
3/30/95	Sherpa Long Sleeve Mock #253	flammability 16 CFR 1610	PA Company Brookline, MA	02146
3/30/95	Sherpa Vest #1041	flammability 16 CFR 1610	PA Company Brookline, MA	02146
3/30/95	Fleece Pant N/A	flammability 16 CFR 1610	Pippers America Bellport, NY	11713
3/30/95	Snap Cardigan N/A	flammability 16 CFR 1610	Pippers America Bellport, NY	11713
3/30/95	Cargo Pant #NM3	flammability 16 CFR 1610	Psycho Graphics Chicago, IL	60622
3/30/95	Kickaround Short #NM4	flammability 16 CFR 1610	Psycho Graphics Chicago, IL	60622
3/30/95	The Lumberjack #NM1	flammability 16 CFR 1610	Psycho Graphics Chicago, IL	60622
3/30/95	Three Button Hood #NM2	flammability 16 CFR 1610	Psycho Graphics Chicago, IL	60622
3/30/95	Unisex V #NM5	flammability 16 CFR 1610	Psycho Graphics Chicago, IL	60622
3/30/95	Children's Top with Fleece Trim #3533	flammability 16 CFR 1610	Sea Isle Sportswear New York, NY	10001
3/30/95	Children's Top with Fleece Trim #3539	flammability 16 CFR 1610	Sea Isle Sportswear New York, NY	10001
3/30/95	Children's Top with Fleece Trim #539	flammability 16 CFR 1610	Sea Isle Sportswear New York, NY	10001
3/30/95	Children's Top with Fleece Trim #6538	flammability 16 CFR 1610	Sea Isle Sportswear New York, NY	10001

Date	Product/Model	Violation	Manufacturer/Imp.	
3/30/95	Children's Top with Fleece Trim #6539	flammability 16 CFR 1610	Sea Isle Sportswear New York, NY	10001
3/30/95	Cross Crew LS #4-413	flammability 16 CFR 1610	Turnberry, Ltd. Delaware, OH	43501
3/30/95	3-Button Hooded Top #6450Q	flammability 16 CFR 1610	USL Corporation Donaldsonville, GA	31745
3/30/95	Button Front Shirt #6609Q	flammability 16 CFR 1610	USL Corporation Donaldsonville, GA	31745
3/30/95	Cuffed Legging #657Q	flammability 16 CFR 1610	USL Corporation Donaldsonville, GA	31745
3/30/95	Drawstring Vest #644Q	flammability 16 CFR 1610	USL Corporation Donaldsonville, GA	31745
3/30/95	Laced Front Top #635Q	flammability 16 CFR 1610	USL Corporation Donaldsonville, GA	31745
3/30/95	Long Sleeve Slouch Top #6610Q	flammability 16 CFR 1610	USL Corporation Donaldsonville, GA	31745
3/30/95	Pull On Pant #6400Q	flammability 16 CFR 1610	USL Corporation Donaldsonville, GA	31745
3/30/95	Raglan Sleeve Placket Top #636Q	flammability 16 CFR 1610	USL Corporation Donaldsonville, GA	31745
3/30/95	Roll Cuff Shorts #678Q	flammability 16 CFR 1610	USL Corporation Donaldsonville, GA	31745
3/30/95	Pant w/Pockets #7703	flammability 16 CFR 1610	Victory Sport Greer, SC	29651
3/30/95	Saddlerag Top #7700	flammability 16 CFR 1610	Victory Sport Greer, SC	29651
3/30/95	Short w/Pockets #7702	flammability 16 CFR 1610	Victory Sport Greer, SC	29651
3/30/95	Work Out Top #7701	flammability 16 CFR 1610	Victory Sport Greer, SC	29651

Date	Product/Model	Violation	Manufacturer/Imp.
3/30/95	Cazzual Sweatshirt #FL103	flammability 16 CFR 1610	Western Niches Westminster, CO 80030
3/30/95	Hooded Sweatshirt #FL105	flammability 16 CFR 1610	Western Niches Westminster, CO 80030
3/30/95	Polo Sweatshirt #FL104	flammability 16 CFR 1610	Western Niches Westminster, CO 80030
3/30/95	Summit Sweatshirt #FL102	flammability 16 CFR 1610	Western Niches Westminster, CO 80030
3/30/95	Tundra Sweatshirt #FL101	flammability 16 CFR 1610	Western Niches Westminster, CO 80030
3/31/95	Child's Fleece Pants #5173	flammability 16 CFR 1610	Dallco Industries, Inc. York, PA 17405
3/31/95	Child's Fleece Top #5172	flammability 16 CFR 1610	Dallco Industries, Inc. York, PA 17405
3/31/95	Adult Sherpa V-Neck Sweat #3017	flammability 16 CFR 1610	Fresh Produce Sportswear, Inc. Boulder, CO 80301
3/31/95	Youth Sherpa V-Neck Sweat #Y6037	flammability 16 CFR 1610	Fresh Produce Sportswear, Inc. Boulder, CO 80301
3/31/95	Newport Cardigan #NNE1250	flammability 16 CFR 1610	Pawtucket Foam Products Pawtucket, RI 02860
3/31/95	Rangeley Top #NNE4002	flammability 16 CFR 1610	Pawtucket Foam Products Pawtucket, RI 02860
3/31/95	Searsport Pant #NNE3304	flammability 16 CFR 1610	Pawtucket Foam Products Pawtucket, RI 02860
3/31/95	Pile Fleece Crew Neck #601	flammability 16 CFR 1610	Rowley & Miller/Straight Down San Luis Obispo, CA 93401
3/31/95	Pile Fleece Pants #607	flammability 16 CFR 1610	Rowley & Miller/Straight Down San Luis Obispo, CA 93401
3/31/95	Pile Fleece Placket #600	flammability 16 CFR 1610	Rowley & Miller/Straight Down San Luis Obispo, CA 93401

Date	Product/Model	Violation	Manufacturer/Imp.
3/31/95	Pile Fleece Shorts #608	flammability 16 CFR 1610	Rowley & Miller/Straight Down San Luis Obispo, CA 93401
4/3/95	Baby Trolls w/Two Bottles #8011	small parts 16 CFR 1501	Ocean State Jobbers, Inc. North Kingstown, RI 02852
4/7/95	Rayon Chiffon Skirt #73451	flammability 16 CFR 1610	Hanover Direct, Inc. Weehawken, NJ 07087
4/7/95	For Kids Only 60-Chewable Wafers #300	child resistant closure 16 CFR 1700.14	Only Natural, Inc Island Park, NY 11558
4/10/95	Geoffrey Flyer Frisbee #0101	lead-in-paint 16 CFR 1303	Toys-R-Us Paramus, NJ 07652
4/24/95	Lip Pacifier #00002	pacifier failure 16 CFR 1511	Pacifaces, Inc. Atlantic Highlands, NJ 07716
4/24/95	Mustache Pacifier #00001	pacifier failure 16 CFR 1511	Pacifaces, Inc. Atlantic Highlands, NJ 07716
4/24/95	Smile Pacifier #00003	pacifier failure 16 CFR 1511	Pacifaces, Inc Atlantic Highlands, NJ 07716
5/8/95	Wooden 6 Piece Puzzles #YT049	small parts 16 CFR 1501	Consolidated Sales Corp. Columbus, OH 43228
5/10/95	Plastic Slide Flute #6113	small parts 16 CFR 1501	M Pressner & Co., Inc. Brooklyn, NY 11201
5/13/95	20 Squeeze Toys #TOY2006	small parts 16 CFR 1501	The Bazaar, Inc. River Grove, IL 60171
5/25/95	Hello Baby 3 Rattle Set #8003	rattle failure 16 CFR 1510	Jade Express, Inc. Los Angeles, CA 90021
5/25/95	Hello Baby 6 Rattle Set #8006	rattle failure 16 CFR 1510	Jade Express, Inc. Los Angeles, CA 90021
6/15/95	Wooden Learn the Alphabet #26742	small parts 16 CFR 1501	Division Sales, Inc. Itasca, IL 60143
6/19/95	Hello Baby Squeeze Toy/Rattle N/A	rattle failure 16 CFR 1510	Division Sales, Inc. Itasca, IL 60143

Date	Product/Model	Violation	Manufacturer/Imp.	
6/19/95	M-1 Deck & Roof Cleaner gallon	labeling 16 CFR 1500	Jomaps, Inc Alpharetta, GA	30201
6/19/95	M-1 Deck & Roof Cleaner quart	labeling 16 CFR 1500	Jomaps, Inc. Alpharetta, GA	30201
7/10/95	Baby Rattle #34674	rattle failure 16 CFR 1510	All For A Dollar, Inc. Springfield, MA	01107
7/10/95	Baby Rattle #35082	rattle failure 16 CFR 1510	All For A Dollar, Inc. Springfield, MA	01107
7/10/95	Sparkling Air Taxi Toy Helicopter #848	small parts 16 CFR 1501	All For A Dollar, Inc. Springfield, MA	01107
7/24/95	Sherpa Fabric #TF 194	flammability 16 CFR 1610	Benetti, Inc Charlotte, NC	28273
7/28/95	Child's Water Timer (2 Column) #3494	chemical hazard 16 CFR 1500.18	Four Seasons Gen Merchandise Vernon, CA	90058
7/28/95	Child's Water Timer (3 Column) #3491	chemical hazard 16 CFR 1500.18	Four Seasons Gen Merchandise Vernon, CA	90058
7/28/95	Magic Diamond Paperweight #CB85002	chemical hazard 16 CFR 1500.18	Four Seasons Gen. Merchandise Vernon, CA	90058
7/28/95	Pull-A-Long Wooden Snail Wagons	small parts 16 CFR 1501	Four Seasons Gen. Merchandise Vernon, CA	90058
8/1/95	Mattress Pad #13410	flammability 16 CFR 1632	RiegelProductst/Mt Vernon Mills Johnston, SC	29832
8/3/95	Kindle Charcoal Starter #17220	child resistant closure 16 CFR 1700.14	Save-A-Lot, Ltd St. Louis, MO	63115
8/3/95	Kindle Charcoal Starter #17220	child resistant closure 16 CFR 1700.14	Save-A-Lot, Ltd. St. Louis, MO	63115
8/3/95	Kindle Charcoal Starter #17220	child resistant closure 16 CFR 1700.14	Save-A-Lot, Ltd. St. Louis, MO	63115
8/7/95	Racer's Choice TQ8+ #7018	child resistant closure 16 CFR 1700.14	R.C. Products Medinah, IL	60157

Date	Product/Model	Violation	Manufacturer/Imp.
8/14/95	Rayon Chiffon Scarves #63408	flammability 16 CFR 1610	Sago Imports, Inc New York, NY 10001
8/14/95	Rayon Chiffon Scarves #63408	flammability 16 CFR 1610	Sago Imports, Inc New York, NY 10001
8/15/95	Rayon Chiffon Scarves #701-22	flammability 16 CFR 1610	I Shalom & Co , Inc. New York, NY 10016
8/15/95	Rayon Chiffon Scarves #701-22	flammability 16 CFR 1610	I Shalom & Co , Inc New York, NY 10016
8/15/95	Rayon Chiffon Scarves #701-22	flammability 16 CFR 1610	I Shalom & Co , Inc. New York, NY 10016
8/15/95	Rayon Chiffon Scarves #701-22	flammability 16 CFR 1610	I Shalom & Co , Inc New York, NY 10016
8/15/95	Rayon Chiffon Scarves #701-22	flammability 16 CFR 1610	I Shalom & Co , Inc. New York, NY 10016
8/15/95	Rayon Chiffon Scarves #701-22	flammability 16 CFR 1610	I. Shalom & Co., Inc. New York, NY 10016
8/15/95	Rayon Chiffon Scarves #701-22	flammability 16 CFR 1610	I. Shalom & Co , Inc. New York, NY 10016
8/15/95	Scarves #138-6064,et al	flammability 16 CFR 1610	Pier 1 Imports Fort Worth, TX 76102
8/22/95	Sheer Rayon Scarves #1609	flammability 16 CFR 1610	Accessories Int'l/India Boutique Daly City, CA 94015
8/22/95	Sheer Rayon Scarves #R2024	flammability 16 CFR 1610	Accessories Int'l/India Boutique Daly City, CA 94015
8/22/95	Sheer Rayon Scarves #R6113	flammability 16 CFR 1610	Accessories Int'l/India Boutique Daly City, CA 94015
8/22/95	Sheer Rayon Scarves #R763	flammability 16 CFR 1610	Accessories Int'l/India Boutique Daly City, CA 94015
8/23/95	Rayon Scarves #4242	flammability 16 CFR 1610	India Cottage Emporium New York, NY 10001

Date	Product/Model	Violation	Manufacturer/Imp.
8/23/95	Rayon Scarves #4242	flammability 16 CFR 1610	India Cottage Emporium New York, NY 10001
8/23/95	Rayon Scarves #4242	flammability 16 CFR 1610	India Cottage Emporium New York, NY 10001
8/31/95	Rayon Chiffon Scarves #79756	flammability 16 CFR 1610	Amee Sales, Inc. New York, NY 10018
9/6/95	Bleach/Ammonia #E15295	labeling 16 CFR 1500	Excelex Corporation Dallas, TX 75220
9/6/95	Bleach/Ammonia #E15295	labeling 16 CFR 1500	Excelex Corporation Dallas, TX 75220
9/7/95	Fuzz and Fur ISBN0811803775	small parts 16 CFR 1501	Chronicle Books of San Francisco San Francisco, CA 94103
9/7/95	Splish Splash ISBN0811803465	small parts 16 CFR 1501	Chronicle Books of San Francisco San Francisco, CA 94103
9/7/95	Rayon Chiffon Scarves #701-260	flammability 16 CFR 1610	I Shalom & Co, Inc. New York, NY 10016
9/13/95	Children's Plastic Jewelry Bracelet #10418	small parts 16 CFR 1501	Ace Novelty Co. Bellevue, WA 98005
9/15/95	Rayon Chiffon Scarf #07671	flammability 16 CFR 1610	Women's Specialty Retailing Div Enfield, CT 06082
9/18/95	Rayon Sheer Scarf #0396	flammability 16 CFR 1601	Cejon Accessories, Inc. New York, NY 10018
9/20/95	Rayon Cheer Scarf #1072	flammability 16 CFR 1610	Associated Merchandising Corp. New York, NY 10018
9/21/95	Color Collection Bracelets #BD100	small parts 16 CFR 1501	Small World Toys Culver City, CA 90230
9/21/95	Golden Bell #9371-79 Series	small parts 16 CFR 1501	Small World Toys Culver City, CA 90230
9/21/95	Loco #92865	small parts 16 CFR 1501	Small World Toys Culver City, CA 90230

Date	Product/Model	Violation	Manufacturer/Imp.
9/21/95	Mini Charmy Bracelets #4008	small parts 16 CFR 1501	Small World Toys Culver City, CA 90230
9/25/95	Xylophone #510	small parts 16 CFR 1501	TPI/Dollar Bill\$ Woodridge, IL 60517
9/26/95	Rayon Chiffon Scarf #17816	flammability 16 CFR 1610	Sud Amerique Trading Corp. New York, NY 10012
9/27/95	Harmony Silver Rattle #1RT	rattle failure 16 CFR 1510	Harmony Ball Co. Columbus, OH 43215
9/29/95	Sheer Rayon Scarves #65782	flammability 16 CFR 1610	Sonali Corp. Princeton Jct, NJ 08550
9/29/95	Sheer Rayon Scarves #65782	flammability 16 CFR 1610	Sonali Corp. Princeton Jct, NJ 08550
9/29/95	Sheer Rayon Scarves #65782	flammability 16 CFR 1610	Sonali Corp. Princeton Jct., NJ 08550

**Voluntary Corrective Action Plans Under
Section 15 Of The Consumer Product Safety Act And
Section 15 Of The Hazardous Substances Act**

Date	Firm and Product	Alleged Hazard	Remedy
10/94	Japan Worksystems Company, Ltd Tokyo, Japan Edge brand 486 notebook computer	The screen hinge mounting may crack, releasing the hinge which can short circuit the computer and cause the unit to catch fire	The firm is refunding the purchase price to all owners.
10/94	Jade Tree Laurel Fork, VA 11434 Pistol cigarette lighter	The unit is overly attractive to children which could present a fire hazard.	The firm distributed only one shipment of 500 units. Recall signs were posted at retail stores and inventory and returned units were destroyed.
10/94	Roohi Designs New York, NY 10001 Rayon skirt	The skirts are dangerously flammable.	The firm recalled to the consumer level.
10/94	Hill's Department Stores Canton, MA 02021 Infant/toddler plaid flannel coveralls, #8018 and #9932	Buttons may detach and present possible choking/ingestion risk.	Consumers should return items to store for refund.

Certain corrective actions may not rise to the level of a substantial product hazard, but a firm still chooses to undertake a voluntary corrective action plan. In some of those cases, the corrective action plan may not be listed.

Date	Firm and Product	Alleged Hazard	Remedy
10/94	R & G Marine Products Buffalo, NY 14225 Boat hoists	The units present an electrocution hazard due to the common wet environment	The firm redesigned the units to include ground fault protection and warning statements. Corrections were made to the units in distribution.
10/94	Fashion Bed Group Chicago, IL 60638 Dreshner brass bench, item B21E50	The bench has the potential to sag in the center or collapse during use.	The firm directly notified owners offering refunds of the purchase price.
10/94	Morrone Company Macon, GA 31206 Morrone Smoker & Grill, model #SG-1	Hot coals and ashes could fall through the holes in the bottom of the exposed charcoal pan and on to the surface below. If this surface is combustible, a fire could result.	The firm provided consumers a free kit that includes a plate to cover the holes in the pan.
10/94	Brinkman Corporation Dallas, TX 75244 Outdoor gas cooker fryers	The cooking basket and pan may tip over allowing spillage of hot liquid and food which poses a potential burn hazard to the user and/or nearby persons.	Future product was redesigned to make accidental tipping of the basket and pan more difficult.
10/94	Starr Fireworks, Inc. Fargo, ND 58106 7 Shot Bombard Aerial fireworks device	Multi-shot device may tip over during use and fire its charge horizontally.	Consumers are to return device for refund of purchase price.

Date	Firm and Product	Alleged Hazard	Remedy
10/94	Stihl Incorporated Virginia Beach, VA Series 1127, models 029 and 039 chain saws	Sparks from a broken ground wire could ignite the fuel and cause a fire.	Consumers are to return the chain saw to an authorized Stihl dealer for a free repair.
11/94	The Lyons Group Richardson, TX 6" Barney with Santa Hat	The hat's pom-pom may detach presenting a choking risk	The firm removed the pom-pom from the design of the hat.
11/94	Datong, Inc. Cerritos, CA Model 74230 tubular metal bunk bed	The upper level can fall unexpectedly causing the bunk bed to collapse.	Contact the retailer to receive a repair kit which will reinforce the bed.
11/94	Sunrise Importer & Wholesale Co., Inc. Mableton, GA 30059 Tubular metal bunk beds, model 2606	The upper level can fall unexpectedly causing the bunk bed to collapse	Consumers are to contact the retailer to receive a repair kit which will reinforce the bed.
11/94	Beekman Partners, Inc. San Francisco, CA Models 500 and 520 tubular metal bunk beds	The upper level can fall unexpectedly causing the bunk bed to collapse	Contact the retailer to receive a repair kit which will reinforce the bed.
11/94	Maryland State Specialty Products North East, MD 21522 Multi tube firework devices	The devices are unstable and will fall over firing their charges laterally into bystanders.	The firm recalled the units distributed and made design changes to its base to increase its stability.

Date	Firm and Product	Alleged Hazard	Remedy
11/94	AGA Warehouse Co. Hayward, CA 94545 Model 4701 twin over full tubular metal bunk bed	The upper level can fall unexpectedly causing the bunk bed to collapse.	Contact the retailer to receive a repair kit which will reinforce the bed.
11/94	Baseline Design Fort Smith, AR 72903 Zippered bean bag chair	Young children may unzip the bean bag, inhale the small foam pellets and suffocate.	The firm initiated a program to retrofit zippered bean bag chairs.
11/94	El Rancho Furniture Lutts, TN 38471 Wooden bunk bed models 24 & 31	A child may become entrapped between the guardrail and mattress support.	Consumers should contact the company to receive replacement guardrails
11/94	Hallmark At Home, Inc. Kansas City, MO 64141 Daydreams baby throw	The throw may readily ignite when near a flame.	The firm recalled the baby throw.
11/94	Gracious Living Industries, Inc. Concord, Ontario, Canada Maui model 1025 plastic monoblock chair	Chair may collapse causing user to fall to the ground.	The firm recalled the chairs offering owners a refund of the purchase price.

Date	Firm and Product	Alleged Hazard	Remedy
11/94	Tech Mart, Inc. Houston, TX 77036 35 miniature lights, 2-way flasher	The set has no overcurrent protection and the current carrying wires in the plug could be broken. The identified design defects create a fire hazard.	The firm offered consumers a refund for light sets returned to retailers
11/94	Tech Mart, Inc. Houston, TX 77036 100 light decoration set, 5-way flasher	The light set has no overcurrent protection, and the current carrying wires in the plug could be broken. The identified design defects could create a fire hazard.	The firm offered consumers a refund for light sets returned to the retailer.
11/94	Tech Mart, Inc. Houston, TX 77036 50 miniature lights, 3-way flasher	The light set has no overcurrent protection and the current carrying wires in the plug could be broken. The identified design defects could create a fire hazard.	The firm offered consumers a refund for light sets returned to retailers.
11/94	Under Seas Industries Rancho Domingues, CA 90221 MK 15 1st stage scuba regulator	Regulator may free-flow air due to a faulty high pressure seat. Drowning or air embolism could result.	The firm corrected the technical problem with the regulators and recalled the product.
11/94	The Toro Company Bloomington, MN Model 59167 recycler kit for models 71140 and 71182 lawn tractors	Recycler kit can interfere with the idler pulley. The blade-stop safety could fail to operate properly.	Contact a Toro dealer to schedule a repair of the recycler kit.

Date	Firm and Product	Alleged Hazard	Remedy
11/94	World Tableware Wallingford, CT 06942 Tankless electric water heater	Defective pressure switches may cause the heaters to explode presenting a fire hazard.	The firm is out of business. Issued a safety alert advising consumers to terminate use of the product.
12/94	R. Brown & Co. Missoula, MT 09801 Gorilla Bomb Super Star Shell firework device	The base of the device is not secure and will tip over during firing shooting its charges horizontally into persons nearby.	In March of 1995 the firm secured the base of the device by melting plastic between the firework device and it's base.
12/94	Lee Scientific, Inc. St. Louis, MO Head Up! lead detection kit	An error in kit's instruction booklet may cause consumers to misinterpret test results.	The firm mailed new instructions to consumers and offered free replacement kits to retest products.
12/94	R.J. Reynolds Tobacco Winston Salem, NC Camel metal match cigarette lighters	Flint is located on the bottom on the lighter. Striking the match may result in lighter fluid spillage and burn injuries.	The firm is providing postage paid mailers and a \$5 check to consumers who return the lighters.
12/94	The Right Start, Inc. Westlake Village, CA Infant Wedge Pillow, model No B019	Potential head entrapment and asphyxiation if head of infant becomes caught in gap between pillow and side of crib.	Consumers are to return the pillow to firm for refund of purchase price and mailing costs

Date	Firm and Product	Alleged Hazard	Remedy
12/94	Reichenbach Fireworks Billings, MT Bombard 7 shots firework device	The base of the device is not secure and will tip over during use firing charges horizontally into persons nearby or start a fire.	In August of 1995 the firm's 20 cases of the violative devices were destroyed.
12/94	Division Sales, Inc. Itasca, IL 60143 Santa Clause candle holder, item #66539	Paint used on candle holders is flammable. Potential fire hazard.	The firm instructed consumers to return the product to retail stores for full refund.
12/94	Carol Wright Sales, Inc. Lincoln, NE 68544 9-Plug extention cord item K1B	Lack of strain relief at switch and receptacles, lack of overcurrent protection, undersize conductors, and lack of polarized plug can cause a fire or shock hazard.	Customers were instructed by direct mail to return the cords for a full refund. All sales were mail order, no press release was issued.
12/94	Pagoda Trading Company St. Louis, MO 63146 Child's shoe, Baby Mickey #69586	Separating filament may present a choking risk.	The firm stopped distribution and requested its four customers to remove the shoe from inventory and destroy it.
12/94	Embraco North America Norcross, GA Embraco compressor 'F' type	A potential shock hazard exists if metal burr abrades the electrical wire insulation and shorts to the metal casing.	The compressor was redesigned to eliminate the burr. Units containing burrs were replaced with redesigned units.

Date	Firm and Product	Alleged Hazard	Remedy
12/94	Polaroid Corporation Cambridge, MA 02139 5 1/2" ABS blue plastic flashlight promotion with film	Flashlight may short-circuit and overheat or melt.	The firm instructed consumers to discard the flashlight and to call its hotline at 800-343-5000 for further information.
12/94	Whirlpool Corporation Benton Harbor, MI 49022 Compressor component on top mount and side-by-side refrigerators and dehumidifiers	A metal burr or sliver may abrade internal wires of the compressor resulting in an electric shock injury.	Service representatives replaced defective compressors in consumers' homes.
01/95	Scentex, Inc. Chicago, IL 60651 Earth Scents Natural Potpourri candles	The wick of the candle is positioned in such a way that the potpourri inside the candle wax may ignite resulting in a fire hazard.	The firm recalled the candles offering consumers a refund or a replacement candle.
01/95	Fay's & Fielding, Incorporated Liverpool, NY 13088 Spirit of Christmas 200 Super Brite christmas light set	A short circuit caused by connecting fuses can result in arcing, excessive heat or potential fire.	Consumers are to return the lights to the place of purchase for a refund or replacement.
01/95	Krups North America New York, NY 10017 Expresso/Cappuccino Machine	The filter holder does not fasten properly and will eject downward from the boiler housing presenting a burn hazard	The firm issued revised instructions, inserted warning labels and offered consumers a \$5.00 rebate on other Krups products.

Date	Firm and Product	Alleged Hazard	Remedy
01/95	Kellner Firework Harrisville, PA 16038 Multi tube firework device	The device is unstable and may fall over firing its charges laterally into bystanders.	The firm recalled the units distributed and made design changes to its base to increase its stability.
01/95	The Toro Company Bloomington, MN Models 70040 and 80040 rear engine riding mowers	A missing weld on the front axle support could allow the collapse of the front end during use.	Contact dealer for repair of the mower.
01/95	China Pyrotechnics Florence, AL 35631 7 shot fireworks device: Gold Rush #CP279	The device may tip over during operation and fire its charge horizontally, resulting in possible serious injury to persons nearby	The firm imported one shipment that was never sold.
01/95	Liberty Fireworks Fairfax, MO 7 Shot Night Shell fireworks device, #W-800	The device could tip over during use firing its charge horizontally or at various angles. People nearby may be hit by the charge.	The firm imported 40 units of this device that were never sold. The entire inventory was voluntarily destroyed.
01/95	China Pyrotechnics Florence, AL 35631 7 shot fireworks device: Magnum Force #CP298	The device may tip over during operation and fire its charge horizontally, resulting in possible serious injury to persons nearby.	The firm imported one shipment of this device that was never sold.

Date	Firm and Product	Alleged Hazard	Remedy
01/95	Brinkman Corporation Dallas, TX 75244 S-80 Smoker Grill	Potential hot water burns are possible due to misaligned handles.	The firm recalled the product and replaced effected parts.
01/95	Happy Kids, Ltd. New York, NY 10001 Toddler girls overalls sold by Sears Roebuck & Co.	Detached snaps present a potential risk of choking/ingestion.	Consumers should return the overalls to Sears for a refund of the purchase price.
01/95	Colgate-Palmolive Company New York, NY Fab Ultra Liquid With Color Plus, date code 4213	A certain production may cause abnormal skin and eye irritation upon physical contact with the detergent.	The firm recalled the defective production offering consumers exchanges or refunds of the purchase price.
01/95	Gilbert Manufacturing Long Island City, NY 10119 E73208 7 amp line cord fuseholder (used on miniature Christmas light sets and other light set products)	With only one of the two fuseholder cover latches fastened, or snapped in place, marginal contact and arcing could occur. Any resulting sparking or short circuit could present a fire hazard.	Consumers may call the firm at 1-800-899-7584 to obtain one more line cord attachment warning label.
01/95	North Central Industries Muncie, IN 47307 Alien Invasion WG014 fireworks device	The device may tip over during use and fire its charge horizontally.	The firm voluntarily withheld distribution of the device. Product was exported back to the supplier in Hong Kong.

Date	Firm and Product	Alleged Hazard	Remedy
01/95	Turtle Wax, Inc Chicago, IL Turtle Wax protectants T-118, T-97	The protectants were exposed to bacterial contamination.	Firm changed manufacturing procedures to eliminate chance of contamination by bacteria.
01/95	The Singer Sewing Company Edison, NJ Juice Giant Juicer, model nos. 774 and 774B	The juicer's plastic cover and basket may explode from the machine during use.	The firm is offering consumers free replacement baskets.
01/95	Melitta USA, Inc. Cherry Hill, NJ 08003 ACM-10S Aroma Brew automatic drip coffee maker	Cracked or broken filter cup hinges and missing filter cup latch mechanisms in combination with unclear directions create potential burn hazard.	The firm offered consumers a filter holder replacement kit and installation instructions.
01/95	Amana Refrigeration Inc. Amana, IA 52204 Side-by-Side refrigerator	A mounting screw restraining the light cover on the refrigerator ceiling may contact a concealed wire. A shock hazard is present to consumers who touch the electrified screw.	A free screw replacement kit is available to consumers who call a toll-free number. Future production contains a design change.
02/95	The Gap, Inc. San Bruno, CA 94066 Candle in metal container	When burned near the end of their 40- hour life cycle, excess heat may ignite the paper wrapper and the cork bottom of the candle.	The firm recalled the candles offering consumers a refund and a \$10 gift certificate.

Date	Firm and Product	Alleged Hazard	Remedy
02/95	Waring Products New Hartford, CT 06057 Dualit-Plus toaster	When power is restored after an interruption, the toaster can self-start creating a potential fire hazard	Consumers can opt for either a full refund or a repair including a \$25 gift certificate.
02/95	Plaza Marine Palm City, FL 34997 Boat hoists	The units presents an electrocution hazard due to the common wet environment.	The firm redesigned the units to inside ground fault protection and added warning statements.
02/95	Wis-Con Total Power Memphis, TN 38118 HDI model WE180 gasoline engine	The fuel valve-shut-off leaks after a period of time.	The firm replaced the fuel valve.
02/95	Hills Department Stores Canton, MA 02021 Beacon Hill children's wooden lamp, item #EA300018 & SKU #8001	A short circuit could create a fire, thermal burn, or electric shock hazard for anyone nearby or holding the lamp or its power cord.	Consumers should return product to the store for a full refund.
02/95	Northwestern Industries Seattle, WA 98199 Annealed glass	The annealed glass was labeled improperly as tempered glass.	The firm contacted the consignees and offered expenses to remove and return the glass.

Date	Firm and Product	Alleged Hazard	Remedy
02/95	Grandrich Corporation Cerritos, CA 90703 Halogen work light, model #HLK500Q	The plastic junction box may melt presenting a potential fire hazard.	The firm advertised to recall all units from consumers and retail stores.
02/95	Starr Display Firework Walcott, ND 8, 12 and 16 shot firework devices with each set of four tubes linked together with a single fuse	The burning debris from the device could accidentally ignite another fuse. A person approaching the device to light another row of tubes could be struck by a charge propelled from a tube of burning debris.	The firm recalled the devices changing the designs to eliminate the paper disc. All old inventory will be used only in professional shows.
02/95	MPC Trading Co. So. El Monte, CA 91733 Tubular metal bunk beds, models 3012 and 3013	The upper level can fall unexpectedly causing the bunk bed to collapse.	The firm is out of business. Consumers should contact the retailer to obtain a repair or replacement of the bed.
02/95	Starr Display Fireworks Walcott, ND 8, 12 and 16 shot firework devices with each set of four tubes linked together with a single fuse	The burning debris from the device could accidentally ignite another fuse. A person approaching the device to light another row of tubes could be struck by a charge propelled from a tube of burning debris.	The firm recalled the devices changing the designs to eliminate the paper disc. All old inventory will be used only in professional shows.

Date	Firm and Product	Alleged Hazard	Remedy
02/95	Starr Display Fireworks Walcott, ND 8, 12 and 16 shot fireworks devices with each set of four tubes linked together with a single fuse	The burning debris from the device could accidentally ignite another fuse. A person approaching the device to light another row of tubes could be struck by a charge propelled from a tube of burning debris.	The firm recalled the devices changing the designs to eliminate the paper disc. All old inventory will be used only in professional shows.
02/95	Davit Master Cleanwater, FL 34620 Boat hoists	The units present an electrocution hazard due to the common wet environment.	The firm redesigned the units to include ground fault protection and added warning statements. Corrections were made to the units in chain of distribution.
02/95	Mike's Fireworks, Inc. Riverside, MO 64168 Bombard 7 shot firework device #W243-7	The device may tip over during use firing its charges horizontally hitting persons nearby.	Mike's Fireworks has posted a sign in its retail location announcing the recall of the firework device.
02/95	Mad Catz, Inc. El Cajon, CA 92021 Model 14050 "High Frequency" Ni-Cad battery pack for GameBoy	An internal short could result in overheating with risks of fires or burns.	Owners may return product to retailer for exchange or refund.

Date	Firm and Product	Alleged Hazard	Remedy
02/95	Cannondale Corp Georgetown, CT 06829 Bicycle frames	If the frame breaks or separates at the junction of the head and down tubes, the rider could fall from the bike and be injured.	Life time warranty replacement on all bike frames. Press release and notice to all dealers and distributors.
02/95	Rival Manufacturing Co. Kansas City, MO 64131 Rival Indoor Electric Crock Grill models 5740 and 5750	The heating elements on these indoor grills, which were not sealed during production, can expose consumers to electric shock.	Consumers are to send Rival an end pin from the recalled element to receive a free replacement heating element.
02/95	Davit Service Pompano Beach, FL Boat hoists	The units present an electrocution hazard due to the common wet environment.	The firm redesigned the units to include ground fault protection and warning statements. Corrections were made to the units in distribution.
02/95	Rubbermaid, Inc. Wooster, OH 44691 Children's hampers: Li'l Roughneck Humphrey the Dinosaur (item 2792), Li'l Roughneck Bubbles the Whale (item 2793)	A small child could lodge its head in the hollow tail of the whale hamper or the head of the dinosaur hamper and become entrapped.	The firm recalled the products.

Date	Firm and Product	Alleged Hazard	Remedy
03/95	A. O Smith Water Products Co. Irving, TX 75038 Residential natural gas water heaters models FGR-75, FGR-100, FSG-75, FSG-100, PGC-75, PGC-100, (BT-80 & BT-100 are commercial heaters), manufactured 12/93 through 1/94	Undertorqued/missing screws can allow burner assemblies to separate resulting in gas accumulating before it ignites. When the accumulated gas ignites it may flashback singe people nearby.	The firm implemented a retrofit program to inspect all affected units held by the manufacturer, dealers and distributors as well as all consumer installations. A retrofit kit was provided by the firm.
03/95	Conair Corporation Stanford, CT 06904 Hand-held hair dryer	An electrocution hazard is present due to lack of immersion protection device.	Consumers are to send dryers to Conair to be equipped with imersion protection devices free of charge.
03/95	Derby States Shows Rosewell, GA 30077 Mobile amusement ride "Octopus"	Riders could be thrown or dragged by a tub or car which breaks apart due to improper inspection and maintenance.	The ride owner has replaced the tubs on the failed ride and has agreed to inspect the critical areas of the ride periodically in conjunction with CPSC and the parts suppliers recommendations.
03/95	Glass Dimensions Essex, MS 01929 Oil lamp	The units leak oil and could catch fire.	The firm implemented a consumer level recall.

Date	Firm and Product	Alleged Hazard	Remedy
03/95	Dunedin Engineering Dunedin, FL 34690 Boat hoists	The units present an electrocution hazard due to the common wet environment.	The firm redesigned the units to include ground fault protection and warning statements. Corrections were made to the units in distribution.
03/95	Keibler Tech Jensen Beach, FL Electrically operated boat hoists	The units present an electrocution hazard due to the common wet environment.	The firm redesigned the units to include ground fault protection and added warning statements. Corrections were made to the units in chain of distribution.
03/95	Kenner Products, Division of Hasbro Cincinnati, OH 45202 Spray art toy, Colorblaster 3-D model 14290.11	The handle can strike the user of the toy	Consumers should return the product to the retailer for a refund.
03/95	Makita U.S.A., Inc. La Mirada, CA 90638 Model B05000 Random Orbit Sander	Pieces of the fan can be projected from the sander and strike the operator of the tool.	Consumers should return the sander to a Makita authorized service center for repair.

Date	Firm and Product	Alleged Hazard	Remedy
03/95	Atlantic Boat Lifts Dania, FL 33004 Boat lifts	The units present an electrocution hazard due to the wet environment.	The firm redesigned the units to include ground fault protection and added warning statements. Corrections were made to the units in chain of distribution.
03/95	Lauderdale Boat Lifts Ft. Lauderdale, FL 33312 Boat hoists	The units present an electrocution hazard due to the common wet environment.	The firm redesigned the units to include ground fault protection and added warning statements. Corrections were made to the units in chain of distribution.
03/95	Amercan Honda Motor Torrance, CA 90501 Rear engine riding mowers, models H1011RSA and H1011HSA	A broken clutch rod would prevent the operator from disengaging power to the rear wheels and result in a loss of brakes.	Consumers should return mowers to dealer for replacement of the clutch rod.
03/95	Club Car, Inc. Augusta, GA 33714 Power drive system, 48 model electric golf car	A short circuit in the charger plug can present a fire hazard.	Contact a Club Car representative for repair.
03/95	Howard Berger Brooklyn, NY Extension cords	The extension cords present an electrocution/over heating hazard.	The firm terminated the sale of the items and exported its inventory.

Date	Firm and Product	Alleged Hazard	Remedy
03/95	Wal-Mart Stores, Inc. Bentonville, AR 72716 Plastic "ice cubes"	The product may present a choking and asphyxiation hazard resulting in death	Wal-Mart recalled previously sold "ice cubes", destroyed them and offered a full refund to customers.
03/95	Trango USA Boulder, CO 80304 Carabiner	Climber could fall under certain conditions if a carabiner opened during a climb.	Firm recalled all product at retail level.
03/95	Welsch Company St. Louis, MO 63104 Jenny Lind crib, styles 6982 and 6983	Use of the cribs may present an entrapment hazard in the side rails.	The firm offered consumers replacement side rails for cribs with loose or missing spindles.
03/95	Taito American Corp. Wheeling, IL 60090 Sonic Blastman arcade video boxing game	Striking target on game with fist may cause injury to hand, wrist or arm	Owners of game to be notified to discontinue use and deactivate game. Bounty to be paid to game owner upon receipt of game's circuit board and evidence of destruction.
03/95	Jordon Manufacturing Co. Monticello, IN 47960 Zippered bean bag chair	Young children may unzip the bean bag chair, inhale the foam pellets and die of suffocation.	Consumers should return the bags to the retailer to be retrofitted.

Date	Firm and Product	Alleged Hazard	Remedy
03/95	American Home Furnishings Fort Wayne, IN 46806 Zippered bean bag chair	Young children may gain access to the inner foam pellets, inhale them and die of suffocation.	Consumers should contact the firm to have their bean bag chairs retrofitted.
03/95	Colortex USA Fort Smith, AR 72901 Zippered bean bag chair	Young children may open the zipper, inhale the foam pellets and die of suffocation.	Consumers should contact the firm to have their bags retrofitted.
03/95	Ace Acme Bellvue, WA Zipperd bean bag chair	Young children may open the zipper, inhale the foam pellets and die of suffocation.	Consumers should return the bags to the retailer to be retrofitted.
03/95	Gold Metal Richmond, VA 23224 Zippered bean bag chair	Young children may open the zipper, inhale the foam pellets and die of suffocation.	Consumers should contact the firm to have their bean bag chairs retrofitted.
03/95	Mr. Bean Bag Garland, TX 75041 Zippered bean bag chair	Young children may open the zipper, inhale the foam pellets and die of suffocation.	Consumers should return the bags to the retailer to be retrofitted.
03/95	Now Products Chicago, IL 60650 Zippered bean bag chair	Young children may open the zipper, inhale the foam pellets and die of suffocation.	Consumers should return the bags to the retailer to be retrofitted.
03/95	Ace Bayou New Orleans, LA Zippered bean bag chair	Young children may gain access to the inner foam pellets, inhale them and die of suffocation.	Consumers should return the bags to their retailer to be retrofitted.

Date	Firm and Product	Alleged Hazard	Remedy
03/95	American Bean Bag Co. Corona, CA 91720 Zippered bean bag chair	Young children may open the bag's zipper, inhale the foam pellets and die of suffocation	Consumers should return the chairs to the retailer to be retrofitted.
03/95	Progress Lighting Spartansburg, SC Glass shade chandeliers and ceiling mounted lighting fixtures	The four to nine pound glass shade could fall creating a laceration hazard.	Consumers identified through distributors and buyers are being sent replacement retention rings.
04/95	Hedstrom Corp Bedford, PA 15522 Ball pit tent, model 8-440	The zipper slider may come off presenting a potential choking hazard.	The firm stitched and stapled the bottom end of the zipper track on future products.
04/95	The Coleman Company Wichita, KS 67202 Camping table stand	The table may crack causing it to flip over dropping objects onto users.	The firm recalled the product.
04/95	Kmart Corporation Troy, MI 48084 Rotary desk chair code 21 86 61	Chair may collapse during use if seat adjustment rod separates from chair's pedestal base.	Consumers are to return the chair to any Kmart store for a refund or a replacement.
04/95	Snapper Power Equipment McDonough, GA 30352 Type 1 "Ninja" lawn mower mulching blade	The blade may break during use propelling broken pieces out from under the lawn mower, possibly injuring someone nearby.	The firm recalled the mulching blades.

Date	Firm and Product	Alleged Hazard	Remedy
04/95	Gainsborough Hardware Industries, Inc. Norcross, GA Metaline 600 series porcelain door knob, Empire style	The door knob may crack or break during use, resulting in hand lacerations.	The firm announced a consumer level recall of the door knob.
04/95	Seasons, Inc. Little Rock, AR Potpourri Pillar candle	The botanical material inside the wax candle's walls may ignite from the burning candle wick causing a fire hazard.	The firm recalled the candle offering consumers a refund or a replacement.
04/95	Cottontail Original Stillwater, OK 74075 Infant and Toddler sizes: boy's one piece romper set, style #GE123 and girl's dress, style #GE420	Potential choking and aspiration hazard on the button and the metal, staple-like attachment.	The firm recalled styles #GE123 and #GE420 in infant and toddler sizes only, and offered a full refund to consumers.
04/95	Hefty Hoist, Inc. Aqua Marine Supply Millersport, OH Electric boat lift	Lack of a ground fault circuit interrupter in a marine environment may cause electric shock hazard.	The firm incorporated a ground fault circuit interrupter into current product design. Previous customers were notified of hazard.

Date	Firm and Product	Alleged Hazard	Remedy
04/95	Hi-Tide, Inc. Ft. Pierce, FL Boat hoists	The units present an electrocution hazard due to the common wet environment.	The firm redesigned the units to include ground fault protection and added warning statements. Corrections were made to the units in chain of distribution.
04/95	Quality Boat Lifts, Inc. Ft. Meyers, FL Boat hoists	The units present an electrocution hazard due to the common wet environment	The firm redesigned the units to include ground fault protection and added warning statements. Corrections were made to the units in chain of distribution.
04/95	Murray Ohio Manufacturing Company Brentwood, TN 37027 Blade mounting hardware on "Murray" Gasoline powered walk behind lawn mowers	The #5 retaining bolt used to attach the blade could break when the mower is used as a mulcher or in some other heavy load operation. The blade could separate and possibly fly out from the deck of the mower.	On 4/27/94, the firm made a change in its blade mounting hardware which included the use of the stronger #8 bolt in place of the #5 retaining bolt.
04/95	Larami Corporation Philadelphia, PA 19107 Water gun	The tank may separate resulting in a explosion/projectile hazard.	The firm redesigned the tank locking mechanism.

Date	Firm and Product	Alleged Hazard	Remedy
04/95	Maytag Corporation Newton, IA 50208 Magic Chef 64 Series 30" slide-in gas range	Use of the range may present a fire hazard as a result of hot air escaping from the unit during self-cleaning cycle.	The firm sent direct mail to consumers and retailers notifying of potential problem. New units were redesigned and units with manufacturer, retailers, and consumers were repaired.
04/95	Fireplace Technologies Louisville, KY Lock Top chimney cap and damper	Springs on the vent damper may deform causing chimney vent damper to close. Carbon monoxide may accumulate in household air.	The firm provided a free retrofit of the vent damper.
04/95	ShoreMaster, Inc. Fergus Fall, NY Electric boat lift	The lack of a ground fault circuit interrupter in a marine environment may cause an electric shock hazard.	A ground fault circuit interrupter was incorporated into current product design. Previous customers notified of hazard.
04/95	SeaQuest, Inc. Carlsbad, CA 92009 Spectrum" scuba regulator	In the worst scenario a novice diver could drown due to a defect associated with the regulator	The firm provided an adequate fix for consumers.

Date	Firm and Product	Alleged Hazard	Remedy
04/95	Honeywell Inc Minneapolis, MN V48/V88 diaphragm gas valve	Leaking gas could present fire or explosion hazards	The firm sent recall notices to customers and distributed press release to the trade press.
04/95	Hunter Fan Company Memphis, TN 38114 Ceiling fan remote control	Consumers may receive a shock if they touch the antenna and are properly grounded.	The firm is offering a free replacement unit.
05/95	New Creative Enterprises Cincinnati, OH 45242 Electric Potpourri Cookers, item 92891, 32872, 32881, 32882, 32883.	Use of the product may present an electric shock.	The firm recalled the product. Consumers should return the product to the retailer for a refund of the purchase price.
05/95	J C. Penney Company Dallas, TX 75301 Close-to-Ceiling" ceiling fan, catalog no. 832-1796	A potential shock hazard is present if a consumer wires the fan according to an incorrect diagram included in the installation instructions.	The firm is contacting all owners by mail informing them to read and follow new directions and diagram attached to notice.
05/95	Maruyama, Inc. Redmond, WA 98052 Maruyama BL471 backpack leaf blower	Gas caps lack an internal check valve and can leak gasoline.	The firm will provide a redesigned (red) gas cap to replace the faulty (black) gas cap.

Date	Firm and Product	Alleged Hazard	Remedy
05/95	Yamaha Motor Manufacturing Corp. of America Newnan, GA 30265 G8A and G11A gas powered golf carts	The fuel line may leak gasoline presenting a fire hazard.	Dealers will replace the involved fuel line free of charge.
05/95	Watkins Mfg. Corp.-A Masco Company Vista, CA 92083 Hot Spring model portable spa	A malfunctioning control system may cause water to reach high temperatures.	Dealers will conduct home visits to repair or replace the system.
05/95	Chadwick Industries, Inc. DesPlaines, IL 60016 Fisher-Price child's shoe no. 229382	The shoe contains a buckle that will detach and present a choking risk.	The firm recalled the shoe from the retailer.
05/95	Krups North America Closter, NJ 07624 Blenders, models 238 and 239	Blades can weaken and break off while being used to crush ice, causing serious injury to the throat or mouth if swallowed or taken into the mouth.	The blades have been modified and manufactured with a larger bend radius and approximately 45% thicker metal.

Date	Firm and Product	Alleged Hazard	Remedy
05/95	Krups North America Closter, NJ 07624 VitaMini compact juice extractor	The strainer basket can break while in use, possibly injuring people nearby.	The basket was redesigned using sturdier mesh, the lid is made of a stronger type of plastic and an altered interlock system was added to prevent the lid from slipping out of position.
05/95	Dolphin Leeco Ft. Myers, FL Boat hoists	The units present an electrocution hazard due to the common wet environment.	The firm redesigned the units to include ground fault protection and warning statements. Corrections were made to the units in distribution.
05/95	The West Bend Company West Bend, WI 53095 Automatic Bread & Dough Maker	The bread maker can overheat, presenting a fire hazard.	The firm recalled the bread maker and implemented a repair program with free pickup of the units from consumers' homes. Each repaired unit had its warranty extended for an additional 12 months.
05/95	Fine Pine Vinemont, AL 35179 Wooden bunk bed models 1010, 1020, 1060, 1100, and 1130	Children may become entrapped between spaces in the top.	Consumers should contact the company to receive replacement guardrails.

Date	Firm and Product	Alleged Hazard	Remedy
05/95	Brothers Brothers Provo, UT 84601 Wooden bunk bed model 480	Children may become entrapped between spaces in the top bunk	Consumers should contact the company to receive replacement guardrails.
05/95	Houston Wood Products Arley, AL 35541 Stackable wooden bunk beds	Children may become entrapped between spaces in the top bunk.	Consumers should contact the company to receive replacement guardrails.
05/95	Sumter Cabinet Company Sumater, SC 29151 Model 1880 wooden bunk bed	Children may become entrapped between spaces in the top bunk.	Consumers should contact the company to receive replacement guardrails.
05/95	H&H Furniture Manufacturers, Inc Seagrove, NC 27341 Wooden bunk beds model 5000 series	Children may become entrapped between spaces in the top bunk.	Consumers should contact the company to receive replacement guardrails.
05/95	TECH Designs Bridgeport, CT 06605 Model 200 wooden bunk bed	Children may become entrapped between spaces in the top bunk.	Consumers should contact the company to receive replacement guardrails.

Date	Firm and Product	Alleged Hazard	Remedy
05/95	Lexington Furniture Industries Lexington, NC 27293 Models 194-187c, 950-187c, 224-187c, 730-187c wooden bunk beds	Children may become entrapped between spaces in the top bunk.	Consumers should contact the company to receive replacement guardrails.
05/95	Brill Manufacturing Co. Ludington, MI 49431-0310 Models 648, 2048, 880 wooden bunk beds	Children may become entrapped between spaces in the top bunk.	Consumers should contact the company to receive replacement guardrails.
05/95	Dover Furniture Manufacturing Company Arley, AL 35541 Wooden bunk bed models Dover 501 and 550	Children may become entrapped between spaces in the top bunk.	Consumers should contact the company to receive replacement guardrails.
05/95	Mafco, Inc. Houston, TX 77215 Models T/18, T/19, and T/28 wooden bunk beds	Children may become entrapped between spaces in the top bunk.	Consumers should contact the company to receive replacement guardrails.
05/95	Service Cycle Supply Commack, NY 11725 Handlebars on Mongoose BMX bicycles	Welds crack on the handlebars nearest the stem and steer tube.	Handlebars replaced at consumer and dealer levels.

Date	Firm and Product	Alleged Hazard	Remedy
05/95	Woodcrest Manufacturing Peru, IN 46970 Models 2602, WW200, PB300, PB400, BK2000, BK1000 wooden bunk beds	Children may become entrapped between spaces in the top bunk.	Consumers should contact the company to receive replacement guardrails.
05/95	ABL Boat Lifts Ft Lauderdale, FL Boat hoists	The units present an electrocution hazard due to the common wet environment	The firm redesigned the units to include ground fault protection and warning statements. Corrections were made to the units in distribution.
05/95	Girvin, Inc. Woonsocket, RI 02895 1800 Hodaka Fastrax suspension forks	If the bond at the fork fails, loss of steering could occur and the bike rider could fall from the bike.	The firm recalled the product.
05/95	GT Bicycle, Inc. Santa Fe, CA 92106 Polygon suspension fork on "Aggressor" mountain bikes	The cyclist could loose control of the bike and fall, suffering severe or minor injuries.	The firm did a joint press release announcing an inspection and repair/replacement program.
05/95	Monarch Industries, Inc. Minneapolis, MN Monarch and Red Lion well water jet pumps	There is no ground connection between the pressure switch and the motor. A severe electric shock or electrocution hazard is present.	Consumers may notify the firm by a toll-free number to arrange for a repair, replacement or refund of the affected well pump.

Date	Firm and Product	Alleged Hazard	Remedy
05/95	Philip Morris Management Corp New York, NY 10017 Parliament promotional keychains	The keychains contain liquid petroleum which can pose a hazard to young children if they ingest the liquid or inhale it into their lungs.	The firm is offering \$5 00 for the return of each keychain.
05/95	Arcotoys, Inc., A Mattel Company Westbury, NY 11590 Disney Play 'n Pop Activity Toy, No. 66004 with "China" molded into bottom of toy	The activator key, shaped like Mickey Mouse's head, may break off and present a choking risk.	Consumers should mail to Arcotoys, Attn: Nancy Nelson, 15920 East Valley Boulevard, City of Industry, CA 91744 for refund, plus postage. 1-800- 442-2664
05/95	Just Toys, Inc. New York, NY 10010 Quick N' Easy Micro-Bake cake set for children	The cake set may catch fire in microwave	Consumers may call 1-800-514-8697 to obtain refund.
05/95	Torpedo South Paris, MA 04281 Dolphin baby float	Water may leak into the hollow center of the float resulting in a child tipping over and potentially drowning.	Consumers may return defective floats to Torpedo, postage free for a free replacement.
05/95	Answer Products, Inc. Valencia, CA 91355 Suspension fork for AT bicycles, Manitou 2	The crown has the potential to separate from the fork legs.	The firm provided replacement forks to all dealers and consumers.

Date	Firm and Product	Alleged Hazard	Remedy
05/95	Univega/Lawee Long Beach, CA 90807 Bicycle handlebars and seat posts	The rider could suffer a fall due to loss of bicycle control when handlebars or seat posts break.	The firm is offering free replacement parts to consumers.
06/95	Buddy L Inc. Gloversville, NY 12078 Metal clamps on above-ground pools models 1213, 1214, and 1215	If the metal hose clamps are improperly installed inside the pool, they present a laceration hazard to bathers.	The firm recalled the metal clamps offering consumers plastic replacement clamps.
06/95	Morgan and Company Fresno, CA 93704 Culinary Art	Internal pressure could cause bottles to vent exposing consumers to flying debris.	The firm made changes in production techniques and quality control procedures to reduce the possibility of contamination.
06/95	Spencer Gifts, Inc. Pleasantville, NJ 08232 Neon Prints: New Night Hawks, Fabulous Four, and Hollywood Diner	Wiring on the back of the neon prints is not properly insulated. A potential fire hazard is present.	Consumers who return the prints to a Spencer Gifts or DAPY store will receive a full refund.
06/95	American Lighting Company City of Commerce, CA 90040 Peach colored touch lamps	The proper gage wiring was not used, there are no bulb specifications on wattage and triac fuse burnout may occur.	All units were recalled from the retail level.

Date	Firm and Product	Alleged Hazard	Remedy
06/95	TV Guard, Inc. Manaplan, NJ 07726 19"x4"x4" plastic guard	If the television is close to the edge of the shelf where it is sitting, young children who pull on the TV Guard may pull the television onto themselves.	The firm improved both the warning label that will be permanently attached to the TV Guard and the package insert.
06/95	East Coast Norfolk, VA 23502 Boat hoists	The units present an electrocution hazard due to the common wet environment.	The firm redesigned the units to inside ground faults protection and added warning statements. Corrections were made to the units in distribution.
06/95	Holbrook & Patterson Coldwater, MI 49036 Zippered bean bag chair	Young children may gain access to the inner foam pellets, inhale them and die of suffocation.	The firm recalled the zippered bean bag chairs.
06/95	The Little Tikes Company Hudson, OH 44691 High Back Toddler Swing, model 4309	Fall injuries may result without a seat belt.	The firm offered a free replacement seat to consumers.
06/95	HSN Marketing Inc. Boonton, NJ 07005 Juice Master XTIV Chef's Choice electric juicer	The juicer's grater may contact the bottom of the plastic funnel causing the funnel and the plastic cover to break apart in an explosive manner.	The firm recalled the juicer offering consumers a refund of the purchase price.

Date	Firm and Product	Alleged Hazard	Remedy
06/95	American Yard Products Division of White Consolidated Cleveland, OH Sears Craftsman model 917.37289 lawn mower	Gas leaking from the float bowl may pose a fire hazard	All purchasers are being contacted to arrange free inspection and repair as necessary.
06/95	Gilbert Manufacturing Long Island City, NY Christmas light string with Paramount fuseplug	The lights were wired with reverse polarity.	The firm re-worked the lights to correct the polarity.
06/95	Tidal Wave Boat Lifts Ft Myers, FL Boat hoists	The units present an electrocution hazard due to the common wet environment.	The firm redesigned the units to include ground fault protection and warning statements. Corrections were made to the units in distribution.
06/95	B. J. Alan Company Youngstown, OH 44502 Ballistic Blast G274A fire works device	If the base of the device is cracked or broken the device may tip-over during use and fire its charge horizontally at the user or bystanders.	Retailers were notified to check inventory for cracked or broken bases returned for refund and/or correction.
06/95	Specialized Bicycle Components Inc. Morgan Hills, CA 95037 Polygon PM 215 bicycle seat post	Rider could fall from bike if seat separated from seat post during riding.	The firm replaced the seat post clamp and bolt.