



# U.S. Consumer Product Safety Commission

CPSC Stands for Safety

## China Product Hazard Monthly Summary Bulletin

## 中国 产品危害 每月小结 简报

January 2023

2023 年一月

The China Product Hazard Monthly Summary Bulletin advises Chinese manufacturers of the most commonly occurring hazards posed by products they produce, such as batteries including lithium-ion batteries and other electrical/electronic products, violations of U.S. flammability standards for children’s sleepwear, excessive lead levels in children’s products, small parts choking hazards, and others. More information on specific cases listed below is available by clicking on the link or going to: [CPSC’s Recalls page](#).

《中国产品危害每月小结简报》的目的是提示中国厂商注意一些他们生产的产品最常出现的危害，诸如包括锂电池在内的电池以及其它电子和电器产品，违反美国联邦儿童睡衣阻燃标准，儿童产品含铅过量，因小部件而导致窒息等问题。简报中相关个案的详细信息，可以点击 [CPSC’s Recalls page](#)，查看公告全文。

<a href="#">23-107</a>	The oven of the <b>30-inch, 36-inch and 48-inch gas ranges</b> can emit dangerous levels of carbon monoxide (CO) while in use, posing a serious risk of injury or death from carbon monoxide poisoning. <b>30, 36 和 48 英寸</b> 煤气炉灶的烤箱使用中会散发危险的一氧化碳气体，构成因一氧化碳中毒而受伤和死亡的严重风险。
<a href="#">23-106</a>	The <b>children’s sleepwear</b> fails to meet the U.S. flammability standards for children’s sleepwear, posing a risk of burn injuries to children. 儿童睡衣不符合美国联邦儿童睡衣阻燃标准，对儿童构成烧伤风险。
<a href="#">23-104</a>	The <b>children’s sleepwear</b> fails to meet the U.S. flammability standards for children’s sleepwear, posing a risk of burn injuries to children. 儿童睡衣不符合美国联邦儿童睡衣阻燃标准，对儿童构成烧伤风险。
<a href="#">23-103</a>	The <b>children’s sleepwear</b> fails to meet the U.S. flammability standards for children’s sleepwear, posing a risk of burn injuries to children. 儿童睡衣不符合美国联邦儿童睡衣阻燃标准，对儿童构成烧伤风险。
<a href="#">23-102</a>	The <b>children’s sleepwear</b> fails to meet the U.S. flammability standards for children’s sleepwear, posing a risk of burn injuries to children. 儿童睡衣不符合美国联邦儿童睡衣阻燃标准，对儿童构成烧伤风险。

<u>23-101</u>	The <b>children's sleepwear</b> fails to meet the U.S. flammability standards for children's sleepwear, posing a risk of burn injuries to children. 儿童睡衣不符合美国联邦儿童睡衣阻燃标准，对儿童构成烧伤风险。
<u>23-100</u>	The <b>children's sleepwear</b> fails to meet the U.S. flammability standards for children's sleepwear, posing a risk of burn injuries to children. 儿童睡衣不符合美国联邦儿童睡衣阻燃标准，对儿童构成烧伤风险。
<u>23-099</u>	The <b>children's sleepwear</b> fails to meet the U.S. flammability standards for children's sleepwear, posing a risk of burn injuries to children. 儿童睡衣不符合美国联邦儿童睡衣阻燃标准，对儿童构成烧伤风险。
<u>23-098</u>	The <b>multi-purpose helmets</b> do not comply with the positional stability and retention system requirements of the U.S. CPSC safety standard for bicycle helmets. The helmets can fail to protect in the event of a crash, posing a risk of head injury. 多功能头盔不符合美国消费品安全委员会对自行车的位置性稳定和保持系统安全标准规定。头盔在冲撞时未能起到保护作用，构成头部受伤风险。
<u>23-096</u>	The <b>hot chocolate pots</b> are mislabeled as microwave safe. If microwaved, the metallic paint on the pots can spark, posing a fire hazard. 热巧克力壶被错误地标为可以在微波炉里安全使用。如果壶被放在微波炉里，壶上的金属漆会引起火花，构成火灾危害。
<u>23-095</u>	The <b>children's robes</b> fail to meet the U.S. flammability standards for children's sleepwear, posing a risk of burn injuries to children. 儿童浴袍不符合美国联邦儿童睡衣阻燃标准，对儿童构成烧伤风险。
<u>23-094</u>	The <b>six-wick scented candles</b> can combust while lit and cause the glass container to break, thus posing fire and injury hazards. 六灯芯香味蜡烛在点燃时会燃烧，使得装蜡烛的玻璃容器碎裂，从而引起火灾和受伤危害。
<u>23-093</u>	The gas hose used in the <b>42-inch fire tables</b> can come into contact with the heat shield, melting the hose and igniting the fire table, posing a fire hazard. 用于42英寸火炉桌的煤气管会接触到防热罩，从而熔化煤气管并点燃火炉桌，构成火灾危害。
<u>23-091</u>	The circuit board inside the <b>cordless multi-surface wet dry vacuum's battery pack</b> can overheat and smoke, posing a fire hazard. 用于无线多功能干湿两用吸尘器的电池包电路板会过热和冒烟，构成火灾危害。
<u>23-089</u>	Infant fatalities have occurred in the <b>rocking sleepers</b> , after the infants rolled from their back to their stomach or side while unrestrained, or under other circumstances. 婴儿在摇摇婴儿篮里翻身滚动或滚到一边时或在其他情况下发生了死亡事故。
<u>23-088</u>	Infant fatalities have occurred in the <b>rock and play sleepers</b> , after the infants rolled from their back to their stomach or side while unrestrained, or under other circumstances. 婴儿在摇玩睡篮里翻身滚动或滚到一边时或在其他情况下发生了死亡事故。
<u>23-085</u>	The <b>children's pajamas</b> fail to meet the U.S. federal flammability standards for children's sleepwear, posing a risk of burn injuries to children. 儿童睡衣不符合美国联邦儿童睡衣阻燃标准，对儿童构成烧伤风险。