



U.S. Consumer Product Safety Commission

CPSC Stands for Safety

China Product Hazard Monthly Summary Bulletin

March 2021

中国 产品危害 每月小结 简报

2021 年三月

The China Product Hazard Monthly Summary Bulletin advises Chinese manufacturers of the most commonly occurring hazards posed by products they produce, such as excessive lead levels in children's products, choking hazards caused by children's upper outerwear garments with drawstrings, and others. More information on specific cases listed below is available by clicking on the link or going to: [CPSC's Recalls page](#).

《中国产品危害每月小结简报》的目的是提示中国厂商注意一些他们生产的产品最常出现的危害，诸如儿童产品含铅过量，儿童上衣外套带拉绳引起的窒息等问题。简报中相关个案的详细情况，可以点击 [CPSC's Recalls page](#)，查看公告全文。

21-731	The pool pump motors can overheat, posing a fire hazard. 泳池泵马达会过热，构成火灾危害。
21-730	An incorrect engine ignition coil and flywheel of the log splitter can lead to hard starting and engine kick back, posing an injury hazard to the operator. 劈木机的点火线圈和飞轮有误，导致引擎启动困难和反冲，对操作者构成受伤危害。
21-098	The garden sprayer's lithium-ion battery can overheat, posing a fire hazard. 花园喷雾器的锂电池会过热，构成火灾危害。
21-728	The metal wire in the plush toy can become exposed, posing a laceration hazard. 毛绒玩具的金属线会暴露在外，构成割伤危害。
21-090	The bicycle's fork steerer tube can break, causing the rider to lose control, fall and suffer injuries. 自行车叉式转向管会断裂，使得骑车人失去控制而跌倒，因而受伤。