



# U.S. Consumer Product Safety Commission

CPSC Stands for Safety

## China Product Hazard Monthly Summary Bulletin

## 中国 产品危害 每月小结 简报

November 2021

2021年十一月

*The China Product Hazard Monthly Summary Bulletin advises Chinese manufacturers of the most commonly occurring hazards posed by products they produce, such as excessive lead levels in children's products, choking hazards caused by children's upper outerwear garments with drawstrings, and others. More information on specific cases listed below is available by clicking on the link or going to: [CPSC's Recalls page](#).*

《中国产品危害每月小结简报》的目的是提示中国厂商注意一些他们生产的产品最常出现的危害，诸如儿童产品含铅过量，儿童上衣外套带拉绳引起的窒息等问题。简报中相关个案的详细情况，可以点击 [CPSC's Recalls page](#)，查看公告全文。

<a href="#">20-022</a>	The locking collars on the <b>dumbbell handles</b> can slip, dropping weights when held perpendicular to the floor, posing an impact-injury hazard. 哑铃握把的锁套会滑动，使得哑铃被握在与地板垂直位置时配重会掉落，构成冲撞危害。
<a href="#">22-708</a>	The steps of the <b>ladder for above-ground pools</b> can loosen during use, posing fall and drowning hazards to the user. 地面泳池的梯子台阶使用中会松脱，对使用者构成跌倒和溺水危害。
<a href="#">22-707</a>	Fuel can leak from the top of the <b>outdoor metal torch canister</b> and ignite, posing a fire hazard. 燃料会从户外金属火炬罐顶部泄漏和起火，构成火灾危害。
<a href="#">22-013</a>	The <b>youth helmets</b> do not comply with the U.S. CPSC federal safety standard for bicycle helmets, posing a risk of head injury. 青少年头盔不符合美国消费品安全委员会的自行车头盔联邦安全标准，构成头部受伤危害。
<a href="#">22-706</a>	The wooden parts used to reinforce and create a decorative gable design on the <b>playset's wooden roof</b> pose an entrapment hazard to children. Children can become trapped in the gap between the lower part of the roof structure and the bottom of the gable decoration. 用于将装饰性的山墙设计固定和安装在游戏组木屋顶上的木头部件对儿童构成羁绊危害。儿童会被困在屋顶下部和装饰性山墙之间的空隙处。