

SAFETY NEWS

From the
U.S. Consumer Product Safety Commission (CPSC)
4330 East West Highway
Bethesda, Md. 20814

This edition of Safety News is a compilation of recalls
announced by CPSC during the
1st Quarter of 2017.



UNITED STATES OF AMERICA
CONSUMER PRODUCT
SAFETY COMMISSION



Walt Disney Parks and Resorts Recalls Minnie and Mickey Mouse Infant Hoodie Sweatshirts Due to Choking Hazard

Recall date: January 4, 2017

Recall number: 17-063



Recall Summary

Name of product:

Infant hoodie sweatshirts

Hazard:

The snaps on the **infant hoodie sweatshirts** can detach, posing a choking hazard to young children.

Remedy:

\$ Refund

Consumer Contact:

Walt Disney Parks and Resorts US, Inc. toll-free at 844-722-1444 from 9 a.m. to 5:30 p.m. ET Monday through

Friday or online at

www.disney.com

and click on "Safety Recall" at the bottom of the page or at

www.disneystore.com/disney-parks-merchandise/mn/1029804/

for more information.

Recall Details

Units:

About 15,000

Description:

This recall involves Minnie and Mickey Mouse infant hoodie sweatshirts with a three snap closure. The garments are cotton and polyester blend. They were sold in four sizes:

6M, 12M, 18M and 24M. The size and "Disney Parks" are printed on the inside back of the hoodie's neck.

The Minnie Mouse hoodie is black with ears attached to hood of the sweatshirt. A red fabric bow with white polka dots is attached to the top of the hood between the ears. The artwork shows a screen print of Minnie's body up to neck. The date code FAC-010635-16194 or FAC-010635-16015 is printed on a label sewn into the left side seam. The UPC code is printed on a hangtag at the time of purchase. UPC codes include (6M) 400000175669, (12M) 400000175676, (18M) 400000175683, and (24M) 400000175690.

The Mickey Mouse hoodie is black with ears attached to hood of the sweatshirt. The artwork shows a screen print of Mickey's body up to neck. The date code FAC-010635-16220, FAC-010635-16015 or FAC-010635-16280 is printed on a label sewn into the left side seam. The UPC code is printed on a hangtag at the time of purchase. UPC codes include: (6M) 400000145433, (12M) 400000145440, (18M) 400000145457 and (24M) 400000145464.

Incidents/Injuries:

None reported

Remedy:

Consumers should immediately stop using the recalled infant hoodies and contact Walt Disney Parks and Resorts US, Inc. for instructions on returning them for a full refund.

Sold Exclusively At:

Walt Disney World® Resort in Lake Buena Vista, Fla., Disneyland® Resort in Anaheim, Calif., and on the Shop Disney Parks mobile app from April 2016 through October 2016 for about \$30.

Importer(s):

Disney Destinations, LLC, d/b/a Disney Theme Park Merchandise, of Lake Buena Vista, Fla.

Manufactured In:

China






This recall was conducted, voluntarily by the company, under CPSC's Fast Track Recall process. Fast Track recalls are initiated by firms, who commit to work with CPSC to quickly announce the recall and remedy to protect consumers.



Toshiba Expands Recall of Laptop Computer Battery Packs Due to Burn and Fire Hazards

Recall date: January 4, 2017

Recall number: 17-064



Recall Summary

Name of product:

Lithium-ion battery packs used in laptop computers

Hazard:

The **lithium-ion battery packs** used in laptop computers can overheat, posing burn and fire hazards to consumers.

Remedy:

↻ Replace

Consumer Contact:

Toshiba America Information Systems toll-free at 866-224-1346 any day between 5 a.m. and 11 p.m. PT, online at

<http://go.toshiba.com/battery>

or at

www.us.toshiba.com

and click on "Consumer Notices" under the Support heading at the bottom of the page.

Recall Details

In Conjunction With:



Units:

About 83,000 (91,000 units were previously recalled on March 30, 2016). In addition, 10,000 were sold in Canada and 5,000 in Mexico.

Description:

This expanded recall involves Panasonic lithium-ion battery packs installed in 41 models of Toshiba Satellite laptops, including the Satellite models affected by the March 2016 recall. Toshiba has expanded the number of battery packs to include those sold between June 2011 and November 2016. The battery packs also were sold separately and installed by Toshiba as part of a repair. Battery packs included in this recall have part numbers that begin with G71C (G71C*****). Part numbers are printed on the battery pack. A complete list of battery pack part numbers included in this recall can be found on the firm's website at <http://go.toshiba.com/battery>.

Incidents/Injuries:

The firm has received five reports of the battery pack overheating and melting, including one additional report since the first recall announcement. No injuries have been reported.

Remedy:

Consumers should immediately go to the firm's website and click on the battery pack utility link in the first shadowed box on the page. Consumers also can perform a manual check using the laptop and battery pack's model, part and serial numbers. If it is part of the recall, consumers should power off the laptop, remove the battery and follow the instructions to obtain a free replacement battery pack. Until a replacement battery pack is received, consumers should use the laptop by plugging into AC power only.

Battery packs previously identified as not affected by the March 30, 2016 recall are included in this expanded announcement.

Sold At:

Office Depot, Staples and other electronics stores nationwide, and online at Toshibadirect.com and other websites from June 2011 through November 2016 for between \$500 and \$1,000 for the laptop and between \$70 and \$130 for the battery pack.

Manufacturer(s):

Panasonic, of Japan

Importer(s):

Toshiba America Information Systems Inc., of Irvine, Calif.

Manufactured In:


China



Michaels Recalls Rock Salt Lamps Due to Shock and Fire Hazards

Recall date: January 10, 2017

Recall number: 17-065



Recall Summary

Name of product:

Rock Salt Lamps

Hazard:

The dimmer switch and/or outlet plug can overheat and ignite, posing shock and fire hazards.

Remedy:

\$ Refund

Consumer Contact:

Michaels at 800-642-4235 from 9 a.m. to 7 p.m. CT Monday through Friday or online at

www.michaels.com

and click on "Product Recalls" at the bottom of the page for more information.

Recall Details

Units:

About 80,000

Description:

This recall involves three rock salt lamps sold under the Lumière brand. The lamps are pink in color and are mounted on a wooden base or in a black metal basket. The lamps were sold in black cardboard boxes with a photo of the lamp on the front of the box and the UPC bar code on the bottom of the box.

Description	SKU	UPC
Rock of Gibraltar Lamp	495144	00886946056253
Carnival of Lights	495433	00886946058325
Basket of Rocks	495146	00886946056277

Incidents/Injuries:

None reported

Remedy:

Consumers should immediately stop using the lamps and return them to any Michaels store for a full refund.

Sold At:

Michaels stores from July 2016 through November 2016 for between \$15 and \$30.

Distributor(s):

SporTex US, of New York

Manufactured In:

Pakistan

Retailer:

Michaels, of Irving, Texas



This recall was conducted, voluntarily by the company, under CPSC's Fast Track Recall process. Fast Track recalls are initiated by firms, who commit to work with CPSC to quickly announce the recall and remedy to protect consumers.



Dunkin' Donuts Recalls Glass Tumblers Due to Laceration and Burn Hazards

Recall date: January 10, 2017

Recall number: 17-066



Recall Summary

Name of product:

Glass Tumblers

Hazard:

The **glass tumblers** can crack or break, posing laceration and burn hazards.

Remedy:

\$ Refund

Consumer Contact:

Dunkin' Donuts at 800-859-5339 from 7 a.m. to 7 p.m. ET Monday through Friday, or online at

www.dunkindonuts.com

and click on "Learn More" next to the safety recall alert for more information.

Recall Details

Units:

About 8,300

Description:

This recall involves 16 ounce glass tumblers for hot and cold beverages, sold in three styles. They are approximately 8 inches tall and approximately 3 inches in diameter. The first style has "BUT FIRST, DUNKIN" written in white font on the inside layer of glass, a clear lid and pink plastic where the lid connects with the base of the tumbler. The second style has "BUT FIRST, DUNKIN" written in white font on the inside layer of glass, a clear lid, and orange plastic where the lid connects with the base of the tumbler. The third style has a black and gray plaid pattern on the inside layer of glass, a black silicone grip with the letters "DD" embossed on it, and a black lid.

Incidents/Injuries:

Dunkin Donuts has received 19 reports of the glass tumblers cracking or breaking. No injuries have been reported.

Remedy:

Consumers should immediately stop using the recalled glass tumblers and return them to the Dunkin' Donuts restaurant where purchased for a full refund.

Sold At:

Dunkin' Donuts stores from September 2016 through November 2016 for between \$13 and \$15

Importer(s):

Moderne Glass, of Aliquippa, Pa.

Distributor(s):

Dunkin' Brands, Inc., of Canton, Mass.

Manufactured In:

China



This recall was conducted, voluntarily by the company, under CPSC's Fast Track Recall process. Fast Track recalls are initiated by firms, who commit to work with CPSC to quickly announce the recall and remedy to protect consumers.



Textron Specialized Vehicles Recalls Bad Boy Off-Road Utility Vehicles Due to Risk of Serious Injury or Death; One Death and One Injury Reported

Recall date: January 11, 2017

Recall number: 17-067



Recall Summary

Name of product:

Bad Boy off-road utility vehicles

Hazard:

The off-road utility vehicles lack seat belts, posing a risk of serious injury or death to the operator and passengers in the event of a vehicle accident.

Remedy:

🔧 Repair

Consumer Contact:

Textron Specialized Vehicles toll-free at 855-738-3711 from 8 a.m. to 5 p.m. ET Monday through Friday or online at www.badboyoffroad.com and click on "Recall Information" for more information.

Recall Details

Description:

WASHINGTON, D.C. – The U.S. Consumer Product Safety Commission (CPSC) and Textron Specialized Vehicles, Inc., of Augusta, Georgia, are announcing the recall of about 1,100 Bad Boy off-road utility vehicles. As a result of the vehicles rolling over, a 14-year-old male passenger died in Toombs County, Georgia in 2014 and, in a separate rollover incident, an adult male operator suffered a serious leg injury.

The vehicles lack seat belts, posing a risk of serious injury or death to the operator and passengers in the event of a vehicle accident.

This recall involves Bad Boy XTO and Bone Collector XTO model off-road utility vehicles manufactured by Textron Specialized Vehicles. The recalled four-wheeled vehicles are battery-powered and have a bench seat for a driver and one passenger and a two-passenger, rear-facing bench seat on the back.

The vehicles were sold in camouflage, black, white, forest green, flame red, and patriot blue and the brand and model name are printed on the side and front panels. The recalled vehicles have serial numbers ranging from 8000020 through 8004934. The serial number is located on the steering column connected to the wheel.

The recalled utility vehicles were sold at Bad Boy dealers nationwide from November 2010 through June 2013 for between \$13,200 and \$14,200 and manufactured in the United States.

Consumers should immediately stop using the recalled vehicles and contact Textron Specialized Vehicles or an authorized dealer for a free installation of seat belts. Textron Specialized Vehicles is contacting all known purchasers directly.

Contact Textron Specialized Vehicles toll-free at 855-738-3711 from 8 a.m. to 5 p.m. ET Monday through Friday or online at www.badboyoffroad.com and click on “Recall Information” for more information.



This recall was conducted, voluntarily by the company, under CPSC's Fast Track Recall process. Fast Track recalls are initiated by firms, who commit to work with CPSC to quickly announce the recall and remedy to protect consumers.



Boosted Recalls Electric Skateboards Due to Fire Hazard

Recall date: January 12, 2017

Recall number: 17-068



Recall Summary

Name of product:

ILithium ion battery pack of the electric-powered skateboards

Hazard:

The **lithium ion battery pack** of the **electric-powered skateboards** can overheat and smoke, posing a fire hazard.

Remedy:

↻ Replace

Consumer Contact:

Boosted toll-free at 844-395-0070 from 9 a.m. to 5 p.m. PT Monday through Friday or online at

<https://boostedboards.com>

and click on Battery Pack Recall for more information.

Recall Details

In Conjunction With:



Units:

About 3,200 (in addition, about 100 units sold in Canada)

Description:

This recall involves 2nd Generation Boosted Dual+ electric skateboards with lithium ion battery packs. "Boosted" is printed on the wooden skateboards. Serial numbers that start with S2634 through S2644 are located on a white sticker on the bottom of the boards. The battery packs were sold as original equipment with the skateboards and are attached to the bottom of the board in a black thermoplastic enclosure. Model number B2SR and "Boosted Lithium" are printed on the battery pack. The battery packs have an orange power button.

Incidents/Injuries:

Boosted has received two reports of the battery packs overheating and smoking. No injuries have been reported.

Remedy:

Consumers should immediately stop using the recalled skateboards and contact Boosted for a free replacement battery pack.

Sold At:

Online at boostedboards.com from September 2016 through November 2016 for about \$1,500.

Manufacturer(s):

Boosted Inc., of Mountain View, Calif.

Importer(s):

Boosted Inc., of Mountain View, Calif.

Manufactured In:

China



This recall was conducted, voluntarily by the company, under CPSC's Fast Track Recall process. Fast Track recalls are initiated by firms, who commit to work with CPSC to quickly announce the recall and remedy to protect consumers.



Trek Recalls Disc Bicycles Due to Fall Hazard

Recall date: January 19, 2017

Recall number: 17-070



Recall Summary

Name of product:

Disc bicycles and wheel sets

Hazard:

The front brake caliper of the **disc bicycles and wheel sets** can come into contact with a broken spoke, posing a fall hazard to the rider.

Remedy:

🔄 Replace

Consumer Contact:

Trek at 800-373-4594 from 8 a.m. to 6 p.m. CT Monday through Friday or online at

www.trekbikes.com

and click on Safety & Recalls at the bottom of the page for more information.

Recall Details

In Conjunction With:



Units:

About 800 bicycles and 300 wheels (in addition, about 160 bicycles and 40 wheels were sold in Canada)

Description:

This recall involves model year 2015, 2016, and 2017 Trek model 720 Disc bicycles and Bontrager Approved TLR disc 700C 24H Front and Rear Wheels with silver spokes. Trek's model 720 Disc have a lightweight aluminum frame and vibration-damping carbon fork. The bicycle models were sold in 49 through 61 cm frame sizes. "Trek" is printed across the bicycle frame. The model number can be found on the down tube. The aftermarket wheels are marked "Bontrager TLR" on the rim, and will have 24 silver spokes.

Incidents/Injuries:

Trek has received reports of 10 incidents where either the wheel spoke contacted the bike's brake caliper or the spokes broke at the hub. There has been one reported injury involving a broken vertebra.

Remedy:

Consumers should immediately stop using the recalled bicycles and wheel sets and return the bicycles to a Trek retailer for a free inspection and free replacement wheels.

Sold At:

Bicycle stores nationwide from November 2014 through October 2016 for between \$1,500 and \$1,900 for bikes and March 2015 through November 2016 for aftermarket wheels for between \$80 and \$90.

Importer(s):

Trek Bicycle Corp., of Waterloo, Wis.

Manufactured In:

China



This recall was conducted, voluntarily by the company, under CPSC's Fast Track Recall process. Fast Track recalls are initiated by firms, who commit to work with CPSC to quickly announce the recall and remedy to protect consumers.



HP Expands Recall of Batteries for HP and Compaq Notebook Computers Due to Fire and Burn Hazards

Recall date: January 24, 2017

Recall number: 17-071



Recall Summary

Name of product:

Lithium-ion batteries used in HP notebook computers

Hazard:

The **lithium-ion batteries** used in notebook computers can overheat, posing fire and burn hazards.

Remedy:

↻ Replace

Consumer Contact:

HP toll-free at 888-202-4320 from 8 a.m. to 7 p.m. CT Monday through Friday or online at

www.HP.com/go/batteryprogram2016

or

www.hp.com

and click "Recalls" at the bottom of the page for more information.

Recall Details

In Conjunction With:



Units:

About 101,000 (An additional 41,000 batteries were previously recalled in June 2016. About 3,000 were sold in Canada and 4,000 in Mexico.)

Description:

This expanded recall involves lithium-ion batteries containing Panasonic cells that are used in HP notebook computers. The batteries are compatible with HP, Compaq, HP ProBook, HP ENVY, Compaq Presario, and HP Pavilion notebook computers. HP has expanded the number of recalled batteries, which were shipped with notebook computers sold between March 2013 and October 2016. The black batteries measure about 8 to 10.5 inches long, 2 inches wide and about 1 inch high. The battery bar code is printed on the back of the battery. "HP Notebook Battery" and the model number are printed on the battery. The batteries included in this expanded recall have bar codes starting with: 6BZLU, 6CGFK, 6CGFQ, 6CZMB, 6DEMA, 6DEMH, 6DGAL and 6EBVA.

Incidents/Injuries:

HP has received one additional report of the battery overheating, melting and charring and causing about \$1,000 in property damage

Remedy:

Consumers should immediately stop using the recalled batteries, remove them from the notebook computers and contact HP for a free replacement battery. Until a replacement battery is received, consumers should use the notebook computer by plugging it into AC power only.

Batteries previously identified as not affected by the June 2016 recall could be included in this expanded announcement. Consumers are urged to recheck their batteries.

Sold At:

Best Buy, Walmart, Costco, Sam's Club and authorized dealers nationwide and online at www.hp.com and other websites from March 2013 through October 2016 for between \$300 and \$1,700. The batteries were also sold separately for between \$50 and \$90.

Importer(s):

HP Inc., of Palo Alto, Calif.

Manufactured In:

China




This recall was conducted, voluntarily by the company, under CPSC's Fast Track Recall process. Fast Track recalls are initiated by firms, who commit to work with CPSC to quickly announce the recall and remedy to protect consumers.



Pulse Performance Recalls Children's Electric Scooters Due to Fall Hazard; Sold Exclusively at Target

Recall date: January 24, 2017

Recall number: 17-072



Recall Summary

Name of product:

Children's electric scooters

Hazard:

The knuckle that joins the wheel of the **children's electric scooters** to the axle can break, posing a fall hazard to the rider.

Remedy:

\$ Refund

Consumer Contact:

Pulse Performance Products toll-free at 844-287-8711 from 7:30 a.m. to 4 p.m. PT Monday through Friday or online at www.pulsescooters.com and click on "CPSC Safety Recalls" for more information.

Recall Details

Units:

About 8,900

Description:

This recall involves Pulse Safe Start Transform electric scooters for children with manufacturing date codes between September 10, 2016 and October 11, 2016. The date code is printed on a label located under the platform in format XX(month)/XX(day)/2016 – 066QY. The scooters were sold in blue and have two wheels in front and one in the rear.

Incidents/Injuries:

None reported

Remedy:

Consumers should immediately take the recalled scooters away from children and contact Pulse Performance Products for a full refund.

Sold Exclusively At:

Target stores nationwide from October 2016 through November 2016 for about \$100.

Manufacturer(s):

Pulse Performance Products, a division of Bravo Sports, of Santa Fe Springs, Calif.

Importer(s):

Target Corp., of Minneapolis, Minn.

Distributor(s):

Target Corp., of Minneapolis, Minn.

Manufactured In:

China



This recall was conducted, voluntarily by the company, under CPSC's Fast Track Recall process. Fast Track recalls are initiated by firms, who commit to work with CPSC to quickly announce the recall and remedy to protect consumers.



Country Home Products Recalls Field & Brush Mowers Due to Fire and Burn Hazards

Recall date: January 25, 2017

Recall number: 17-073



Recall Summary

Name of product:

Field & brush mowers

Hazard:

The fuel tank valve can malfunction and cause the fuel tank to expand and gasoline liquid or vapors to be unexpectedly released, posing fire and burn hazards.

Remedy:



Repair

Consumer Contact:

Country Home Products toll-free at 877-271-5677 from 8 a.m. to 7 p.m. ET Monday through Friday, email at

tbmrecall@chp.com

or online at

www.DRPower.com

and click on "Product Recalls" at the bottom of the page for more information.

Recall Details

Units:

About 830

Description:

This recall involves the Pro-XL-44 model of the DR® brand tow-behind field and brush mower manufactured by Country Home Products. The mowers are towed behind a riding mower or ATV to clear acres of thick grass and brush. The recalled mowers have an electric start 20 HP Briggs & Stratton engine and a serial number between TB21001001 – TB21002555. The recalled mowers are black and orange and have two blades and four wheels and are 44 inches wide. There is a large label below the machine's fuel tank that with "DR Field and Brush Mower" printed on it and a round DR logo is in the right hand corner. The serial number is printed on the rear right corner of the frame near the engine control panel.

Incidents/Injuries:

The firm has received 10 reports of fires, including one report of a burn injury to a consumer's hand.

Remedy:

Consumers should immediately stop using the recalled mowers and contact Country Home Products to schedule a free repair from a dealer. Country Home Products is sending a repair kit to all registered owners.

Sold At:

Country Home Products catalog, website and authorized independent DR dealers nationwide from October 2015 through July 2016 for about \$3,600.

Manufacturer(s):

Country Home Products Inc., of Vergennes, Vt.

Manufactured In:

U.S.




This recall was conducted, voluntarily by the company, under CPSC's Fast Track Recall process. Fast Track recalls are initiated by firms, who commit to work with CPSC to quickly announce the recall and remedy to protect consumers.



IKEA Recalls Beach Chairs Due to Fall and Fingertip Amputation Hazards

Recall date: January 27, 2017

Recall number: 17-074



Recall Summary

Name of product:

MYSINGSÖ beach chairs

Hazard:

The beach chairs can collapse, posing fall and fingertip amputation hazards.

Remedy:

\$ Refund

↻ Replace

Consumer Contact:

IKEA toll-free at 888-966-4532 anytime or online at

www.ikea-usa.com

and click on Press Room at the bottom of the page, then on Product Recalls at the top of the page for more Information.

Recall Details

In Conjunction With:



Units:

About 33,400

Description:

This recall involves IKEA MYSINGSÖ beach chairs. The chairs are foldable with a wood base and an attached polyester fabric seat. The following article numbers are included in this recall. The article numbers are on labels on the wooden frame and sewn into the fabric.

Seat Fabric Color & Pattern	Article Number
Light Red/Blue Striped	902.280.08
Red/Blue Striped	302.580.79
Solid White	502.851.66
Solid Red	802.873.95
Solid Green	002.931.40
Grey/White Chevron	303.120.24
Light Blue/White Chevron	503.120.23
Light Red/White Chevron	003.120.25

Incidents/Injuries:

IKEA has received 13 reports worldwide of incidents, including 10 reports of injuries, six of which resulted in fingertip amputations. Three of the incidents, including one fingertip amputation injury, were reported in the U.S.

Remedy:

Consumers should immediately stop using the recalled chairs and return them to any IKEA store for a free replacement or full refund. Replacement MYSINGSÖ beach chairs are labeled with article numbers 703.380.17 and 903.380.16 and have plastic stoppers that prevent incorrect re-assembly.

Sold At:

IKEA stores nationwide and online at www.ikea-usa.com from February 2013 through December 2016 for about \$25.

Importer(s):

IKEA Supply AG, of Switzerland

Distributor(s):

IKEA North America Services LLC, of Conshohocken, Pa.

Manufactured In:

Bosnia and Herzegovina



Bolton Furniture Recalls Dressers Due to Serious Tip-Over and Entrapment Hazards

Recall date: January 31, 2017

Recall number: 17-075



Recall Summary

Name of product:

Two Over Two 4-drawer dressers

Hazard:

The **Two-Over-Two 4-drawer dressers** are unstable if they are not anchored to the wall, posing serious tip-over and entrapment hazards that can result in death or injuries to children. The dressers do not comply with the performance requirements of the U.S. voluntary industry standard (ASTM F2057-14).

Remedy:



Repair

Consumer Contact:

Bolton Furniture at 800-545-8982 from 8 a.m. to 4:30 p.m. ET Monday through Friday or online at

www.boltonfurniture.biz

and click on the "News" section and then Safety Recall.

Recall Details

Units:

About 1,000

Description:

This recall involves Bolton Furniture two over two style 4-drawer dressers. Models included in the recall are Cambridge 8614, Emma 8314, Essex 6614, Wakefield 8014 and Woodridge 8414. The dressers were sold in cherry, chestnut, espresso, honey, ivory, natural, and white. Model names and numbers can be found on the QC/production sticker located on back of the dresser.

Incidents/Injuries:

None reported

Remedy:

Consumers should immediately stop using any recalled dresser that is not properly anchored to the wall and place it into an area that children cannot access. Consumers should contact Bolton Furniture for a free retrofit kit. Consumers can install the retrofit kit or the tip-restraint strap sold with the dressers themselves, or contact Bolton who will provide a one-time, free in-home installation.

Sold At:

Full Line Furniture and children's specialty stores nationwide and online at Amazon.com, Overstock.com, Target.com, ToysRUs.com, Wayfair.com, Zulilly.com and other online retailers from February 2011 to October 2016 for about \$700.

Importer(s):

Bolton Furniture, of Morrisville, Vt.

Manufactured In:

China and Vietnam



Casual Living Worldwide Recalls Swivel Patio Chairs Due to Fall Hazard; Sold Exclusively at Home Depot

Recall date: January 31, 2017

Recall number: 17-076



Recall Summary

Name of product:

Swivel Patio Chairs

Hazard:

The base of the **swivel patio chair** can break during normal use, posing a fall hazard to users.

Remedy:

✍ Repair

Consumer Contact:

Casual Living Worldwide toll-free at 855-899-2127 from 8 a.m. to 5 p.m. ET on Monday through Friday or online at www.casuallivingoutdoors.com and click on "Recall Information" for more information.

Recall Details

In Conjunction With:



Units:

About 2 million (in addition, about 30,000 were sold in Canada and about 14,000 were sold in Mexico)

Description:

This recall involves Hampton Bay Anselmo, Calabria, and Dana Point chairs as well as Martha Stewart Living branded Cardona, Grand Bank and Wellington swivel patio chairs. The chairs are made of aluminum and steel with a round swivel base and arm rests. The chairs were sold as a pair and as part of a seven-piece patio set with accompanying tables.

Incidents/Injuries:

The firm has received 25 reports of the chairs breaking, resulting in bruising and scrapes from falls.

Remedy:

Consumers should immediately stop using the recalled chairs and contact Casual Living Worldwide for a free repair kit.

Sold Exclusively At:

Home Depot stores nationwide and online at HomeDepot.com from January 2007 to February 2016 for about \$190 for two-piece patio set and \$500 for a seven-piece patio set.

Manufacturer(s):

Casual Living Worldwide, of Simpsonville, Ky.

Importer(s):

The Home Depot, of Atlanta, Ga.

Distributor(s):

The Home Depot, of Atlanta, Ga.

Manufactured In:

China



Brown Jordan Services Recalls Swivel Patio Chairs Due to Fall Hazard; Sold Exclusively at Sears.com

Recall date: January 31, 2017

Recall number: 17-077



Recall Summary

Name of product:

Swivel Patio Chairs

Hazard:

The base of the **swivel patio chair** can break during normal use, posing a fall hazard to users.

Remedy:

✂ Repair

Consumer Contact:

Brown Jordan Services toll-free at 855-899-2127 from 8 a.m. to 5 p.m. ET on Monday through Friday or online at www.bjsoutdoor.com can click on "Customer Care" and then "Recall Information" for more information.

Recall Details

Units:

About 1,500

Description:

This recall involves La-Z-Boy Kayla swivel dining and lounge patio chairs. The chairs are made of aluminum and steel with a round swivel base. The chairs have dark blue fabric covered cushions. La-Z-Boy is printed on a gold-colored tag on the back of the chairs. The chairs were sold in a four-piece lounge set and a five-piece dining set.

Incidents/Injuries:

The firm has received 16 reports of the swivel chairs breaking. No injuries have been reported.

Remedy:

Consumers should immediately stop using the recalled chairs and contact Brown Jordan Services for a free repair kit.

Sold Exclusively Online:

At Sears.com from January 2016 through July 2016 for about \$1,260 for the four-piece lounge set and \$1,300 for the five-piece dining set.

Manufacturer(s):

Brown Jordan Services, Inc., of Simpsonville, Ky.

Importer(s):

Sears, of Hoffman Estates, Ill.

Distributor(s):

Sears, of Hoffman Estates, Ill.

Manufactured In:

China



Bar Chairs Sold at Lowe's Stores Recalled Due to Fall Hazard; Made by 3i Corporation

Recall date: January 31, 2017

Recall number: 17-078



Recall Summary

Name of product:

Bar chairs

Hazard:

The legs of the **bar chair** can become detached from the center post at the weld, posing a fall hazard.

Remedy:

✎ Repair

Consumer Contact:

3i Corporation toll-free at 866-267-7772 between 9 a.m. and 5 p.m. ET Monday through Friday or online at www.lakeview-safford.com

Recall Details

In Conjunction With:



Units:

About 315,000 (in addition, about 2,100 were sold in Canada)

Description:

This recall involves alienoroth brand Safford model and Garden Treasures brand Lakeview model bar chairs sold in sets of four. The chairs have a brown, aluminum frame and a beige sling fabric cover. The 4-foot-tall chairs swivel 360 degrees and have arm rests on each side of the chair.

Incidents/Injuries:

The firm has received 457 reports of the bar stool base breaking, resulting in ten reports of injury including head injuries, broken ribs, bruising and scrapes.

Remedy:

Consumers should immediately stop using the recalled chairs and contact 3i Corporation for a free replacement base and a repair kit.

Sold Exclusively At:

Lowe's stores nationwide and online at www.lowes.com from November 2008 to August 2016 for about \$700 for the set.

Manufacturer(s):

3i Corporation, of Hong Kong

Importer(s):

L G Sourcing, Inc., of Wilkesboro, N.C.

Manufactured In:

China



This recall was conducted, voluntarily by the company, under CPSC's Fast Track Recall process. Fast Track recalls are initiated by firms, who commit to work with CPSC to quickly announce the recall and remedy to protect consumers.



Teufelberger Recalls Rescue Ropes and Throwlines Due to Fall and Injury Hazards

Recall date: January 31, 2017

Recall number: 17-079



Recall Summary

Name of product:

Static ropes and throwlines

Hazard:

The recalled static ropes and throwlines are mislabeled as being certified to specific voluntary NFPA safety standards and cannot be relied upon for any purpose, posing fall and injury hazards to users.

Remedy:

🔄 Replace

Consumer Contact:

Teufelberger Fiber Rope Corp. toll-free at 844-361-7041 from 8 a.m. to 5 p.m. ET Monday through Friday or online at

www.teufelberger.com

and click on the "Static Rope Safety Notice" link for more information.

Recall Details

Units:

About 95

Description:

This recall involves CMC and New England Ropes brand 7.5 mm and 8 mm static ropes and throwlines used for rescue operations. The recalled rope models are the CMC Escape Line 5/16"/8mm (orange with yellow tracer), New England Ropes Aramid 7.5mm (tan with black tracer) and New England Ropes KM-III 5/16"/8mm (white with blue tracer). The recalled throwline model is New England Ropes NFPA (yellow with red tracer). Only ropes and throwlines with lot numbers that begin with 160101 through 1609915 are included in this recall. The model name and lot number is printed on the end band label on the rope and on the product's packaging. The ropes and throwlines were sold in lengths ranging from 150 to 2,400 feet.

Incidents/Injuries:

None reported

Remedy:

Consumers should immediately stop using the recalled ropes and throwlines and contact Teufelberger for a free replacement.

Sold At:

CMC Rescue in Goleta, Calif., Extractor Sled in Escondido, Calif., Excalibur in Sandy, Utah, Liberty Mountain in Sandy, Utah, Rescue Technology in Carrollton, Ga., Rock-n-Rescue in Butler, Pa., Tahoe Sports in South Lake Tahoe, Calif., and West Marine in Watsonville, Calif. from January 2016 through September 2016 for between \$140 and \$1,800.

Manufacturer(s):

TEUFELBERGER Fiber Rope Corp., of Fall River, Mass.

Manufactured In:

U.S.



This recall was conducted, voluntarily by the company, under CPSC's Fast Track Recall process. Fast Track recalls are initiated by firms, who commit to work with CPSC to quickly announce the recall and remedy to protect consumers.



Barnes & Noble Recalls Power Adapters Sold with NOOK Tablet 7 Due to Shock Hazard

Recall date: February 1, 2017

Recall number: 17-080



Recall Summary

Name of product:

Power adapter casing

Hazard:

The **power adapter casing** can break when plugged into an electrical outlet, exposing its metal prongs, posing an electric shock hazard.

Remedy:

↻ Replace

Consumer Contact:

Barnes & Noble toll-free at 877-886-5025 from 8 a.m. to 11 p.m. ET, Monday through Friday, or 9 a.m. to 11 p.m. ET on Saturday and Sunday, or online at

www.barnesandnoble.com

and click on "Product Recalls" listed at the bottom of the page.

Recall Details

Units:

About 147,000

Description:

This recall involves the black power adapter sold with the NOOK Tablet 7". The adapter bears markings: model number TPA-95A050100UU, manufacture date 201610. The NOOK Tablet 7" model number BNTV450 is located on the back of the NOOK.

Incidents/Injuries:

Barnes & Noble has received four reports of the power adapter breaking or pulling apart exposing the metal prongs. No injuries have been reported.

Remedy:

Consumers should immediately stop using the recalled power adapters and register online for a free replacement adapter along with a Barnes & Noble \$5 gift card. Once registered, consumers will be able to print a pre-paid UPS label to return the recalled adapters to Barnes & Noble. Consumers will receive replacement adapters in the mail. Until a replacement adapter is received, consumers are advised to charge their NOOK Tablet 7" through their computer using a USB cable.

Sold At:

Barnes & Noble stores and online at www.barnesandnoble.com from November 2016 to January 2017 for about \$50.

Importer(s):

Barnes & Noble, Inc., of New York

Manufactured In:

China



This recall was conducted, voluntarily by the company, under CPSC's Fast Track Recall process. Fast Track recalls are initiated by firms, who commit to work with CPSC to quickly announce the recall and remedy to protect consumers.



Walt Disney Parks and Resorts Recalls Mickey Mouse Nightlights Due to Fire Hazard

Recall date: February 2, 2017

Recall number: 17-081



Recall Summary

Name of product:

Nightlights

Hazard:

Liquid from the **nightlight** can leak onto the electrical outlet, posing a fire hazard.

Remedy:

\$ Refund

Consumer Contact:

Walt Disney Parks and Resorts US, Inc. toll-free at 844-722-1444 from 9 a.m. to 5:30 p.m. ET Monday through Friday, or online at

www.disneyparks.com

and click on "Safety Recall" at the bottom of the page for more information.

Recall Details

Units:

About 3,000

Description:

This recall involves the Happy Holidays! Mickey Mouse Nightlight with a Mickey Mouse face and red and white Santa hat filled with liquid and glitter. The date code FAC # 019808-16150 is printed on the bottom rear of the nightlight. The UPC code, 400009489637, is printed on a sticker on the bottom of the product packaging.

Incidents/Injuries:

Walt Disney Parks and Resorts have received two reports of incidents, including one electrical fire. No injuries have been reported.

Remedy:

Consumers should immediately stop using the recalled nightlights and contact Walt Disney Parks and Resorts US, Inc. for instructions on returning them for a full refund.

Sold Exclusively At:

Walt Disney World® Resort in Lake Buena Vista, Fla., Disneyland® Resort in Anaheim, Calif., Shop Disney Parks mobile app, and online at DisneyStore.com from July 2016 through November 2016 for about \$15.

Importer(s):

Disney Destinations, LLC, d/b/a Disney Theme Park Merchandise, of Lake Buena Vista, Fla.

Manufactured In:

China




This recall was conducted, voluntarily by the company, under CPSC's Fast Track Recall process. Fast Track recalls are initiated by firms, who commit to work with CPSC to quickly announce the recall and remedy to protect consumers.



Restoration Hardware Recalls Mirrors Due to Laceration Hazard

Recall date: February 2, 2017

Recall number: 17-082



Recall Summary

Name of product:

Glass mirrors

Hazard:

The mirrors are not properly glued to the backing and the mirror can fall, posing a laceration hazard.

Remedy:

\$ Refund

Consumer Contact:

Restoration Hardware toll-free at 888-728-8419 from 8 a.m. to 5 p.m. PT Monday through Friday or online at

www.restorationhardware.com

and click on Safety Recalls at the bottom of the page for more information.

Recall Details

Units:

About 1,400

Description:

This recall involves Restoration Hardware’s 18th Century Venetian style glass beveled mirrors. The recalled mirrors are antiqued silver with a wood backing and come in the following shapes and sizes. This recall only affects mirrors with a Hangman hanging system on the back. Mirrors with a production date after April 1, 2015 are included in this recall. The month and year of production (04/2015) are located on a green sticker affixed to the back of the mirrors.

SKU	Framed/Unframed	Shape	Size	Retail Price
40200969SIL	Framed	Rectangle	36 x 48	\$845
40200565SIL	Framed	Rectangle	36 x 48	\$895
40200968SIL	Framed	Rectangle	42 x 78	\$1595
40200967SIL	Framed	Rectangle	24x 80	\$895
40200966SIL	Framed	Rectangle	32 x 64	\$945
40200965SIL	Unframed	Round	60	\$1795
40200964SIL	Unframed	Rectangle	36x 48	\$895
40200963SIL	Unframed	Rectangle	30x 40	\$645
40200962SIL	Unframed	Rectangle	30x 48	\$695
40200563SIL	Unframed	Rectangle	42 x 78	\$1595
40200562SIL	Unframed	Rectangle	24 x 80	\$995
40200561SIL	Unframed	Round	60	\$1795
106373SIL	Framed	Rectangle	30 x 40	\$659
106372SIL	Unframed	Round	30	\$579

Incidents/Injuries:

Restoration Hardware has received four reports of the mirror detaching from the wood backing, resulting in two laceration injuries.

Remedy:

Consumers should immediately stop using the recalled mirrors and contact Restoration Hardware for a full refund.

Sold At:

Restorationhardware.comand Rhbabyandchild.com from April 2015 through May 2016 for between \$650 and \$1,800.

Importer(s):

Restoration Hardware (RH), of Corte Madera, Calif.

Manufactured In:


India



La-Z-Boy Recalls Power Supplies Sold With Lift Chairs Due to Shock Hazard

Recall date: February 8, 2017

Recall number: 17-083



Recall Summary

Name of product:

Power supplies sold with lift chairs

Hazard:

The **lift chair's power supply cover** can crack within the screw housing and break, causing the cover to detach and expose the power supply's electrical components, posing a shock hazard to users.

Remedy:

↻ Replace

Consumer Contact:

La-Z-Boy toll-free at 855-592-9087 from 9 a.m. to 5 p.m. ET Monday through Friday or online at www.la-z-boy.com
and click on the **Recall** button for more information.

Recall Details

In Conjunction With:



Units:

About 2,290 (In addition, 210 were sold in Canada)

Description:

The recall involves the power supplies sold with Gold Series electric Lift Chairs, the Clayton Luxury-Lift (Model 1HL562) and Power Lift (Model 1ML562), and Luxury-Lift (Models 1LF505 and 1LF819). They were also part of conversion kits for older lift chairs with Models 1LL320, 1LL508, 1LL515, 1LM320, 1LM508 and 1LM515. The power supply enables the chair's seat to lift a consumer from a seated into a standing position. The power supply casing is a black, plastic rectangular box measuring approximately 6 inches by 3½ inches by 3½ inches. Only power supplies with LOT #150113 are included in this recall. The model name, model number and lot number are printed on the back of the power supply.

Incidents/Injuries:

None reported

Remedy:

Consumers should immediately stop using the power supplies to power the lift chairs and contact La-Z-Boy for a free replacement power supply.

Sold At:

La-Z-Boy Furniture Galleries and independent furniture stores nationwide and online at la-z-boy.com from September 2015 through November 2016 for between \$1,900 and \$2,800. The power supplies were also sold separately for about \$170 and provided free under warranty as replacements for use with previously-purchased chairs.

Importer(s):

LogicData North America, of Grand Rapid, Mich. (power supply)

Distributor(s):

La-Z-Boy Incorporated, of Monroe, Mich.

Manufactured In:

China (power supplies), U.S. (lift chairs)



This recall was conducted, voluntarily by the company, under CPSC's Fast Track Recall process. Fast Track recalls are initiated by firms, who commit to work with CPSC to quickly announce the recall and remedy to protect consumers.



Feld Entertainment Recalls Toy Wands Due to Injury Hazard; Sold Exclusively at Disney On Ice and Disney Live Shows

Recall date: February 9, 2017

Recall number: 17-084



Recall Summary

Name of product:

Light-spinner toy wands

Hazard:

The top component of the **light-spinner toy wands** can detach and expose an 8-inch metal rod, posing an injury hazard to young children.

Remedy:

\$ Refund

Consumer Contact:

Feld Entertainment at 800-755-1530 or 703-448-3683 from 9 a.m. to 5 p.m. ET Monday through Friday, email at Recall@feldinc.com and online at www.feldentertainment.com and click Recall for more information.

Recall Details

Units:

About 30,100

Description:

This recall involves light-spinner wands with lot numbers 954544 and 954603 imprinted on the bottom of the toy. The light-spinner wands have either Mickey Mouse or Minnie Mouse at the top. The Mickey Mouse wands are yellow, red and black. The Minnie Mouse wands are pink, white and blue. The wands measure about 18 inches tall.

Incidents/Injuries:

None reported

Remedy:

Consumers should immediately stop using the recalled wands and contact Feld Entertainment to receive a full refund.

Sold Exclusively At:

Disney On Ice and Disney Live shows from October 2016 through November 2016 for about \$22.

Show	Location	Dates
Disney Live	Buffalo, N.Y.	October 23, 2016
	Allentown, Pa.	October 27-28, 2016
	Erie, Pa.	October 21, 2016
	Hershey, Pa.	October 22, 2016
	Pittsburgh, Pa.	October 14, 2016
	Reading, Pa.	October 30, 2016
	Wilkes Barre, Pa.	October 29, 2016
	Charleston, W.Va.	October 15, 2016
	Wheeling, W.Va.	October 16, 2016
Disney On Ice	Baltimore, Md.	October 27-30, 2016
	Fairfax, Va.	October 19-23, 2016
	Knoxville, Tenn.	November 2-6, 2016
	Worcester, Mass.	November 2-6, 2016
	Salt Lake City, Utah	November 10-13, 2016

Importer(s):

Feld Entertainment Inc., of Vienna, Va.

Distributor(s):

Feld Entertainment Inc., of Vienna, Va.

Manufactured In:

China



This recall was conducted, voluntarily by the company, under CPSC's Fast Track Recall process. Fast Track recalls are initiated by firms, who commit to work with CPSC to quickly announce the recall and remedy to protect consumers.



Target Recalls Patio Benches Due to Fall Hazard

Recall date: February 13, 2017

Recall number: 17-087



Recall Summary

Name of product:

Threshold patio benches

Hazard:

The **patio benches** can collapse while in use, posing a fall hazard to consumers.

Remedy:

\$ Refund

Consumer Contact:

Target at 800-440-0680 from 7 a.m. to 8 p.m. CT Monday through Sunday, online at www.target.com

and click on "Recalls" at the bottom of the page, then on "Patio/Garden" on for more information, or the "Product Recalls" tab on Target's Facebook page.

Recall Details

Units:

About 1,300

Description:

This recall involves Threshold Aluminum Top/Steel X Base patio benches that were sold both individually and as part of a six-piece dining set. The model number can be found on the front page of the product's assembly instructions or on the product's packaging.

Name	Model Number	Bench Size
Threshold Aluminum Top/Steel X Base Bench	009-00-3894	56.875" (L) x 17.625" (W) x 18" (H)
Threshold Mayhew 6 piece Wicker Dining Set-Turquoise	009-00-2005	56.875" (L) x 17.625" (W) x 18" (H)
Threshold Mayhew 6 piece Wicker Dining Set-Seafoam	009-00-2006	56.875" (L) x 17.625" (W) x 18" (H)
Threshold Mayhew 6 piece Wicker Dining Set-Orange	009-00-2007	56.875" (L) x 17.625" (W) x 18" (H)
Threshold Mayhew 6 piece Wicker Dining Set-Green	009-00-2008	56.875" (L) x 17.625" (W) x 18" (H)
Threshold Mayhew 6 piece Wicker Dining Set-Navy	009-00-4568	56.875" (L) x 17.625" (W) x 18" (H)
Threshold Mayhew 6 piece Wicker Dining Set-Tan	009-00-4573	56.875" (L) x 17.625" (W) x 18" (H)

Incidents/Injuries:

Target has received six reports of the patio benches collapsing, including one report of a knee injury.

Remedy:

Consumers should immediately stop using the recalled patio benches and return them to any Target store for a full refund for the bench. The benches were sold individually and as part of a set. Purchasers can continue to use the other pieces of the set which, in addition to the bench, included a table and four chairs. Purchasers of individual benches will be refunded the purchase price. Purchasers of sets will be refunded the price of the individual bench.

Sold At:

Target stores nationwide and online at Target.com from January 2016 through July 2016 for about \$150 for the benches and \$1,000 for the dining sets when sold with the benches.

Importer(s):

Target Corp., of Minneapolis, Minn.

Manufactured In:

China



Britax Recalls Strollers Due to Fall Hazard

Recall date: February 16, 2017

Recall number: 17-088



Recall Summary

Name of product:

Britax B-Agile and BOB Motion Strollers with Click & Go receivers

Hazard:

A damaged receiver mount on the **stroller** can cause the car seat to disengage and fall unexpectedly, posing a fall hazard to infants in the car seat.

Remedy:



Consumer Contact:

Britax online at

www.us.britax.com

and click on the Safety Notice on the homepage or visit us.britax.com/recall, call toll-free at 844-227-0300 from 8:30 a.m. to 5:45 p.m. ET Monday through Thursday and from 8:30 a.m. to 4:45 p.m. ET Friday or email

Britax at

stroller.recall@britax.com

Recall Details

In Conjunction With:



Units:

About 676,000 (in addition, about 36,400 were sold in Canada and about 4,600 were sold in Mexico)

Description:

This recall involves Britax B-Agile and BOB Motion strollers (when used as a travel system with a car seat carrier attached). All models are folding, single or double occupant strollers and have Click & Go receiver mounts that attach the car seat carrier to the stroller frame. All colors of the stroller are included. The model number can be found on the inside of the stroller's metal frame near the right rear wheel for single strollers and in the front middle underside of the frame on double strollers. Recalled model numbers include:

B-Agile:

S01298600, S01298700, S01635200, S02063600, S02063700, S02063800, S02063900, S02064000, S03803400, S03803500, S03803700, S03803800, S03803900, S04144400, S04144500, S04144600, S04144700, S04144800, S04144900, S04145000, S04183700, S04183800, S04184000, S04281200, S04281300, S04402800, S04437700, S04628500, S04884200, S04884300, S04884400, S04884500, S04975600, S04978900, S05060600, S05260200, S05511600, S05511700, S865800, S865900, S874300, S874400, S874500, S877200, S890100, S896000, S896200, S896600, S907200, S907300, S907400, S907500, S907600, S910200, S910300, S910400, S910500, S912300, S914300, S914500, S914700, S914900, S915200, S915400, S917400, S921800, S921900, S923700, DJ341763, DJ341764, DJ341782, DJ341783, DJ341825, U341826, U341828, DJ341X82, DJ34X782, DJ361763, DJ361818, U361819, U361825, DJ391875, U451835, U451837, DJ451841, DJ461763, DJ461764, DJ461782, DJ461783, DJ461825, U461826, U461828, U471818, DJ471819, DJ491842, DJ491843, DJ491844, U491908, DJ491909, DJ491910, DJ511875, DJ511877, U551835, DJ551837, U551841, U551861, U551862, DJ551863, DJ551864, DJ551865, DJ551905, U551906, DJ691878, DJ691879, DJ691881, DJ691882, U691884, DJ691904, DJ691905, U721895, U721896

BOB Motion:

S888600, S890200, S890300, S890400, S890500, S909700, S910600, S910700, S910800, S910900, S912600, U391820, DJ391821, DJ391822, U481820, DJ481821, DJ481822, U501820, U501821, U501822, U501907

Incidents/Injuries:

Britax has received 33 reports of car seats unexpectedly disconnecting from the strollers and falling to the ground, resulting in 26 reports of injuries to children, including scratches, bruises, cuts and bumps to the head. In addition, Britax is aware of 1,337 reports of strollers with damaged Click & Go receiver mounts.

Remedy:

Consumers should immediately stop using their Click & Go receiver mounts and contact Britax for a free repair kit for single strollers. Owners of the recalled double strollers should stop using them with car seats attached. Consumers can continue to use their stroller or car seat independently without the car seat attached to the stroller.

Sold At:

Babies R Us, buy buy Baby, Target and other stores nationwide, and online at Amazon.com, albeebaby.com, buybuybaby.com, diapers.com, ToysRUs.com and other websites from May 2011 through February 2017 for between \$250 and \$470 for the strollers and travel systems.

Importer(s):

Britax Child Safety Inc., of Fort Mill, S.C.

Manufactured In:

China



Yamaha Corporation of America Recalls Benches Sold With Grand Pianos Due to Violation of Federal Lead Paint Standard

Recall date: February 21, 2017

Recall number: 17-090



☐ No. 31
☐ Model PM or PAW
☐ Manufacture Date Code



Recall Summary

Name of product:

Piano benches sold with Yamaha grand piano

Hazard:

The paint on the piano bench's interior compartment contains an excessive level of lead. This is a violation of the federal lead paint standard.

Remedy:

↻ Replace

Consumer Contact:

Yamaha Corporation of America toll-free at 844-703-5446 from 8:30 a.m. to 4:30 p.m. PT Monday through

Friday, email the firm at

Benchrecall@yamaha.com

online at

www.usa.yamaha.com

and click on "Support" or

<http://4wrd.it/benchrecall>

for more information.

Recall Details

Units:

About 900

Description:

This recall involves piano bench model number 3 I PM& PAW sold with one model of Yamaha grand piano GB1K PM& PAW. The recalled benches are brown wood with a brown padded leather seat and a compartment under the seat. The recalled bench has a manufacturing date code between 08 07 and 16 08 ("YY MM" for year and month). The model number, manufacturing date code and "Yamaha Corporation" are printed on a white label on the interior compartment. Consumers can also find a list of piano serial numbers sold with a bench that is being recalled is at <http://4wrd.it/benchrecall>.

Incidents/Injuries:

None reported

Remedy:

Consumers should immediately remove the recalled piano benches from areas with children and contact Yamaha Corporation of America for instructions on returning the piano bench for a free replacement bench.

Sold At:

Piano stores nationwide from January 2009 through November 2016 for about \$15,000.

Importer(s):

Yamaha Corporation of America, of Buena Park, Calif.

Distributor(s):

Yamaha Corporation of America, of Buena Park, Calif.

Manufactured In:

Indonesia



SodaStream Recalls Carbonating Bottles Due to Injury Hazard

Recall date: February 21, 2017

Recall number: 17-091



Recall Summary

Name of product:

Carbonating bottles

Hazard:

The bottles can burst under pressure, posing an injury hazard to the user or bystanders.

Remedy:

\$ Refund

Consumer Contact:

SodaStream USA toll-free at 866-272-9417 between 9 a.m. to 7 p.m. ET Monday through Friday or online at www.sodastream.com

and click on the recall at the top of the page or

www.sodastreamvoluntaryrecall.com

for more information.

Recall Details

In Conjunction With:



Units:

About 51,000 (in addition, about 7,600 were sold in Canada)

Description:

This recall involves SodaStream one liter, blue tinted, plastic carbonating bottles. "SodaStream" and "Dishwasher safe" are printed on the recalled bottles. Only bottles with an expiration date of "4/2020" printed on the warning label are included in the recall. The recalled bottles have a blue cap and blue bottom base.

Incidents/Injuries:

None reported

Remedy:

Consumers should immediately stop using the recalled carbonating bottles and contact SodaStream for a full refund.

Sold At:

Bed Bath & Beyond, Target, Walmart and other stores and online at www.amazon.com and www.sodastream.com from February 2016 through January 2017 for about \$15.

Importer(s):

SodaStream USA Inc., Mount Laurel, N.J.

Manufactured In:

Israel




This recall was conducted, voluntarily by the company, under CPSC's Fast Track Recall process. Fast Track recalls are initiated by firms, who commit to work with CPSC to quickly announce the recall and remedy to protect consumers.



Calphalon Recalls Cutlery Knives Due to Laceration Hazard

Recall date: February 22, 2017

Recall number: 17-092



Recall Summary

Name of product:

Contemporary Cutlery knives

Hazard:

The blade on the **Contemporary Cutlery knives** can break during use, posing a laceration hazard.

Remedy:

↺ Replace

Consumer Contact:

Calphalon at 800-809-7267 from 8 a.m. to 5 p.m. ET Monday through Friday or online at www.calphalon.com

and click on "Customer Support" at the bottom of the page then "Recalls" for more information.

Recall Details

In Conjunction With:



Units:

About 2 million (in addition, about 7,000 were sold in Canada)

Description:

This recall involves Calphalon Contemporary Cutlery carving, chef, paring, santoku and utility knives sold individually and in sets made between August 2008 and March 2016. The following models are included in the recall:

<i>Product</i>	<i>Item</i>	<i>Item Number</i>
Calphalon Contemporary Cutlery	4.5" Parer	KNR10045C
Calphalon Contemporary Cutlery	7" Santoku	KNR0007C
Calphalon Contemporary Cutlery	Contemporary Paring Knife Set	1821332
Calphalon Contemporary Cutlery	5" Santoku	KNR0005C
Calphalon Contemporary Cutlery	8" Chef Knife	KNR4008C
Calphalon Contemporary Cutlery	Fruit/Vegetable Set - 3.5" parer & 6" utility	KNSR002C
Calphalon Contemporary Cutlery	Carving Set - 6" fork & 8" slicer	KNSR0102C
Calphalon Contemporary Cutlery 21-piece set	3½" parer, 5" boning knife, 5" santoku, 5½" tomato/bagel knife, 6" fork, 6" utility, 7" santoku, 8" bread, 8" chef's knife, 8" slicer, 10" steel, kitchen shears, 8 steak knives, and knife block	1808009
Calphalon Contemporary Cutlery 17-piece set	4½" parer, 6" utility, 7" santoku, 8" bread, 8" chef's knife, 8" slicer, 10" steel, kitchen shears, 8 steak knives, and knife block	1808008
Calphalon Contemporary SharpIN Cutlery 14-piece set	4.5" Parer, 6" Utility, 8" Bread, 8" Chef's Knife, 8 Steak Knives, Kitchen Shears, Sharpening Knife Block	1922890
Calphalon Contemporary SharpIN Cutlery 15-piece set	4.5" Parer, 6" Utility, 7" Santoku, 8" Bread, 8" Chef's Knife, 8 Steak Knives, Kitchen Shears, Sharpening Knife Block	1922971
Calphalon Contemporary SharpIN Cutlery 18-piece set	4.5" Parer, 5" Boning, 5.5" Tomato, 6" Utility, 7" Santoku, 8" Bread, 8" Chef's Knife, 8" Slicer, 8 Steak Knives, Kitchen Shears, Sharpening Knife Block	1932810
Calphalon Contemporary SharpIN Cutlery 20-piece set	4.5" Parer, 5" Boning, 5" Santoku, 5.5" Tomato, 6" Fork, 6" Utility, 7" Santoku, 8" Bread, 8" Chef's Knife, 8" Slicer, 8 Steak Knives, Kitchen Shears, Sharpening Knife Block	1922976

Incidents/Injuries:

Calphalon has received 27 reports of finger or hand lacerations; including four injuries requiring stitches. In addition, the firm has received about 3,150 reports of broken knives.

Remedy:

Consumers should immediately stop using the recalled cutlery and contact Calphalon for a replacement cutlery product.

Sold At:

J.C. Penney, Kohl's, Macy's and other stores nationwide and online at www.Amazon.com from September 2008 through December 2016. The recalled knives were sold from September 2008 through December 2016 for \$25 for a single knife to \$300 for a knife block set.

Manufacturer(s):

Calphalon Corp., of Atlanta, Ga.

Manufactured In:


China



Moose Toys Recalls Toy Frogs Due to Chemical and Injury Hazards

Recall date: February 22, 2017

Recall number: 17-093



Recall Summary

Name of product:

Little Live Pets Lil Frog and Lil Frog Lily Pad toys

Hazard:

When the **button batteries** are removed from the **toy frogs**, the battery's cap can become a projectile and the battery's chemicals can leak, posing chemical and injury hazards.

Remedy:

↻ Replace

Consumer Contact:

Moose Toys toll-free at 844-575-0340 from 8 a.m. to 5 p.m. Monday through Friday PT or online at www.moosetoys.com and click on "Product Safety" for more information.

Recall Details

In Conjunction With:



Units:

About 427,000 (in addition, 17,800 were sold in Canada)

Description:

This recall involves the Little Live Pets Lil Frog plastic toys. They operate with four button batteries and jump. Little Live Pets Lil Frog has SKU: 28217 and Lil Frog Lily Pad has SKU: 28218 printed on the frog's lower belly near its left thigh with a manufacture date code under it. The date code range is WS112016 to WS123216. The toy frogs were sold in pink, blue and green colors.

Incidents/Injuries:

The firm has received 17 reports of the battery's cap becoming a projectile or battery chemicals leaking, including two injuries that resulted in emergency room and doctor's office visits for eye irritation from the battery chemicals.

Remedy:

Consumers should immediately stop using the toy frogs, refrain from opening the battery compartment and contact Moose Toys for a free replacement Little Live Pet product.

Sold At:

AAFES, Target, Toys "R" Us and Walmart stores nationwide and online at Amazon.com from August 2016 through February 2017 for about \$15 for the Lil Frog and \$25 for the Lil Frog Lily Pad.

Manufacturer(s):

Moose Toys Proprietary Ltd., of Australia

Importer(s):

Regal Logistics, of Fife, Wash.

Manufactured In:


China



STIHL Recalls Chain Saws Due to Fire and Burn Hazards

Recall date: February 23, 2017

Recall number: 17-095



Recall Summary

Name of product:

STIHL gas-powered chain saws

Hazard:

The fuel line can leak, posing fire and burn hazards.

Remedy:

✚ Repair

Consumer Contact:

STIHL Inc. at 800-233-4729 between 8 a.m. and 8 p.m. ET Monday through Friday, email

stihlrecall@stihl.us

or online at

www.stihlusa.com

and click on Information and then Product Recalls for more information.

Recall Details

Units:

About 100,000

Description:

This recall involves STIHL MS 461 gas-powered chain saws, and the MS 461 R chain saw with a wrap handle. The model number is on the model plate, located on the starter cover. The chain saws are gray and orange with "STIHL" on the engine cover. Recalled chain saws have a serial number between 173092800 and 181993952, under the front hand guard on the engine housing's sprocket side.

Incidents/Injuries:

STIHL Inc. has received 117 reports of pinched or leaking fuel lines. No fires, property damage or injuries have been reported.

Remedy:

Consumers should immediately stop using the recalled chain saws and return them to an authorized STIHL dealer for a free inspection and free repair.

Sold At:

Authorized STIHL dealers nationwide from July 2012 through December 2016 for about \$1000.

Manufacturer(s):

ANDREAS STIHL AG & Co. KG

Importer(s):

STIHL Inc., of Virginia Beach, Va.

Manufactured In:


Germany



Carrier Expands Recall of Packaged Terminal Air Conditioners and Heat Pumps Due to Fire Hazard

Recall date: February 23, 2017

Recall number: 17-094



Recall Summary

Name of product:

Packaged Terminal Air Conditioners (PTAC) and Packaged Terminal Heat Pumps (PTHP)

Hazard:

The **power cord plug** of the **packaged terminal air conditioners (PTAC)** and **packaged terminal heat pumps (PTHP)** can overheat, posing a fire hazard to consumers.

Remedy:



Consumer Contact:

Carrier at 800-761-8492 from 8 a.m. to 6 p.m. ET Monday through Friday or online at

<http://www.carrier.com>

and click on Important Product Safety Recall for more information.

Recall Details

In Conjunction With:



Units:

About 94,000 (in addition, about 285,000 were previously recalled in December 2015 and 185,000 were previously recalled in November 2007)

Description:

This expanded recall involves Packaged Terminal Air Conditioners (PTAC) and Packaged Terminal Heat Pumps (PTHP) sold under the Bryant, Carrier and Fast brand names. Recalled units include those with original power cords and those that received a replacement power cord as part of the 2007 recall.

The recalled units have capacities of 7,000; 9,000; 12,000 and 15,000 BTUs and plug into 208/230 volt outlets. The following brands and eight models are being recalled:

- Carrier models 52CE, 52CQ, 52PE, 52PQ, 52PC, 52ME, 52MQ;
- Bryant models 840, 841, and 842; and
- Fast models 840, 841, and 842.

Model and serial numbers are located on the ratings/data plate on the right front of the unit, underneath the removable front panel. A complete list of the serial numbers involved in this recall is available by calling Carrier or at www.carrier.com.

Incidents/Injuries:

Carrier has received 14 additional reports of overheating. No injuries have been reported in the additional incidents.

Remedy:

Consumers should stop using and unplug the recalled units and contact Carrier to receive a free replacement cord.

Sold At:

HVAC dealers and factory-direct sales nationwide from January 2002 through December 2009 for between \$425 and \$675.

Manufacturer(s):

Carrier Corporation, of Jupiter, Fla.

Manufactured In:

Mexico and China



Little Tikes Recalls Toddler Swings Due to Fall Hazard

Recall date: February 23, 2017

Recall number: 17-096



Recall Summary

Name of product:

Little Tikes™ 2-in-1 Snug 'n Secure Pink toddler swings

Hazard:

The plastic seat can crack or break, posing a fall hazard.

Remedy:

\$ Refund

Consumer Contact:

Little Tikes toll-free at 855-284-1903 from 8 a.m. to 8 p.m. ET Monday through Friday or online at

www.littletikes.com

and click on Product Recalls under the At Your Service menu for more information.

Recall Details

Units:

About 540,000

Description:

This recall involves Little Tikes 2-in-1 Snug'n Secure pink toddler swings. The swings have a pink T-shaped restraint in front with a Little Tikes logo. The swing is suspended by four yellow ropes. The model number 615573 is molded on the back of the swing seat and there is a manufacturing date code stamp on the back of the seat. The molded INNER arrow of the date code stamp points to "10", "11", "12" or "13", it is included in the recall. In addition, swings with a date code stamp of "9" on the INNER arrow combined with "43" or higher number stamped on the OUTER are included in this recall. No other date codes or other colored swings are affected.

Incidents/Injuries:

The firm has received about 140 reports of the swing breaking, including 39 injuries to children including abrasions, bruises, cuts and bumps to the head. Two of the reported injuries included children with a broken arm.

Remedy:

Consumers should immediately stop using the recalled swings and contact Little Tikes for a refund in the form of a credit towards the purchase of another Little Tikes product.

Sold At:

Walmart, Toys "R" Us and other stores nationwide and online at www.littletikes.com and other websites from November 2009 through May 2014 for about \$25.

Manufacturer(s):

Little Tikes, of Hudson, Ohio

Manufactured In:

U.S.



S.R. Smith Recalls Helix Pool Slides Due to Fall Hazard

Recall date: February 28, 2017

Recall number: 17-098



Recall Summary

Name of product:

Helix pool slides

Hazard:

A child can fall off the side of the slide before reaching the pool entry point, posing a fall hazard that can result in serious injury.

Remedy:

✂ Repair

Consumer Contact:

S.R. Smith at 800-611-4750 from 6:30 a.m. to 5 p.m. PT Monday through Friday, or online at

www.srsmith.com

and click on "Helix Slide Info" for more information. Consumers can also email the firm at

helixslideinfo@srsmith.com

Recall Details

Units:

About 800

Description:

This recall involves Helix residential pool slides with serial numbers from SR-HX13-01001 to SR-HX13-01488 and SR-HX14-01001 to SR-HX14-01602. "S.R. Smith," "Helix" and the serial number can be found on the product label located on the top right side of the slide near the staircase rail. The recalled slides are 7-feet, 4 inches-tall at the highest point and have a helix (corkscrew) shape to its slide or flume.

Incidents/Injuries:

The firm has received 16 reports of users falling from the slide, resulting in 15 reports of injuries including a 4-year-old girl who sustained a concussion. Other reports included damaged/loosened teeth, cuts to the chin that required stitches, bruising and scrapes.

Remedy:

Consumers should immediately stop using the recalled slides and contact S.R. Smith for a free slide rail extension kit that will increase the height of the rail sides. Consumers can install the extension kit or contact S.R. Smith for a one-time, free installation of the kit.

Sold At:

In The Swim, Leslies Swimming Pool Supply, SCP Distributors and other pool product distributors nationwide and online at Amazon.com and Intheswim.com between May 2013 and March 2015 for about \$3,000.

Distributor(s):

S.R. Smith LLC, of Canby, Ore.

Manufactured In:

U.S.



Dillard's Recalls Baby Jackets Due to Choking Hazard

Recall date: February 28, 2017

Recall number: 17-099



Recall Summary

Name of product:

Faux-Fur Hooded Bear Coats

Hazard:

The metal snaps on the **faux-fur hooded bear coats** can detach, posing a choking hazard to children.

Remedy:

\$ Refund

Consumer Contact:

Dillard's at 800-345-5273 from 8 a.m. to 1 a.m. ET Monday through Saturday and 10 a.m. to 8 p.m. ET Sunday,

by email at

bearcoat.recall@dillards.com

or online at

www.dillards.com

and click on "Product Recalls" at the bottom of the page for more information.

Recall Details

Units:

About 1,800

Description:

This recall involves the Starting Out Baby Girls 3-24 Months Faux-Fur Hooded Bear Coat with style numbers F64CI801I and F64CI801N. The coat is labeled for children aged 3-24 months and has metal snap closures. It is an ivory faux fur coat with animal ears on the hood. The "Starting Out" logo and style number can be found on the tag sewn into the garment.

Incidents/Injuries:

Dillard's has received one report of snaps detaching. No injuries have been reported.

Remedy:

Consumers should immediately stop using the recalled coat and return it to the nearest Dillard's store for a full refund. To obtain a prepaid envelope to return the product by mail, customers can contact Dillard's.

Sold At:

Dillard's stores nationwide and online at www.dillards.com from September 2016 through December 2016 for about \$40.

Importer(s):

Dillard's Inc., of Little Rock, Ark.

Distributor(s):

Dillard's Inc., of Little Rock, Ark.

Manufactured In:

China




Search CPSC



Pier 1 Imports Recalls Glass Knobs Due to Laceration Hazard

Recall date: March 1, 2017

Recall number: 17-097



Recall Summary

Name of product:

Glass knobs

Hazard:

The glass knobs can break while in use, posing a risk of laceration to users from broken pieces.

Remedy:

\$ Refund

Consumer Contact:

Pier 1 Imports toll-free at 855-513-5140 from 8 a.m. to 7 p.m. CT Monday through Friday, 9 a.m. to 5 p.m. CT

Saturday or 10 a.m. to 6 p.m. CT Sunday, or online at

www.pier1.com

and click on "Product Notes & Recalls" at the bottom of the page for more information.

Recall Details

In Conjunction With:



Units:

About 363,000 units in the U.S. (in addition, about 41,000 units in Canada)

Description:

This recall involves Pier 1 Imports glass knobs commonly used with dressers, cabinets and small drawers. The decorative glass knobs have a metal stem affixed to one side and were sold in 26 styles.

Incidents/Injuries:

Pier 1 Imports has received six reports of incidents including two laceration injuries from a broken glass knob.

Remedy:

Consumers should immediately stop using the recalled glass knobs and return them to any Pier 1 Imports store for a full refund or a merchandise credit.

Sold Exclusively At:

Pier 1 Imports stores nationwide and online at www.Pier1.com from August 2010 to February 2016 for between \$5 and \$14.

Importer(s):

Pier 1 Imports, of Fort Worth, Texas

Manufactured In:

India




This recall was conducted, voluntarily by the company, under CPSC's Fast Track Recall process. Fast Track recalls are initiated by firms, who commit to work with CPSC to quickly announce the recall and remedy to protect consumers.



Philips Lighting Expands Recall of Metal Halide Lamps Due to Fire and Laceration Hazards

Recall date: March 1, 2017

Recall number: 17-100



Recall Summary

Name of product:

Metal Halide Lamps

Hazard:

The outer bulbs can shatter, resulting in hot internal pieces of glass falling from the lamps, posing fire and laceration hazards.

Remedy:

↻ Replace

Consumer Contact:

Philips Lighting toll-free at 866-253-5503 from 9 a.m. to 5 p.m. ET Monday through Friday, email at ceramicmh@philips.com or online at www.philips.com and click on "For Professionals" and then "Recalls" for more information.

Recall Details

Units:

About 256,000 (in addition, about 87,000 were previously recalled on May 24, 2016).

Description:

This expanded recall involves Philips Energy Advantage Ceramic Metal Halide Lamps model CDM330 manufactured from May 2011 through March 2014. They are designed as energy efficient replacements for traditional 400W quartz metal halide lamps installed in magnetic ballasts and intended for use in high-ceiling industrial, retail and commercial applications. The lamps were sold in both clear and coated versions. Each lamp includes an etching, located either on the base of the lamp or the glass bulb that displays the date code in the format of a number followed by a letter representing the year and month, "Philips", wattage (330W) and the model number (CDM330). Lamps with the following date codes are included in the recall:

May 2011	1E	July 2012	2G	September 2013	3J
June 2011	1F	August 2012	2H	October 2013	3K
July 2011	1G	September 2012	2J	November 2013	3L
August 2011	1H	October 2012	2K	December 2013	3M
September 2011	1J	November 2012	2L	January 2014	4A
October 2011	1K	December 2012	2M	February 2014	4B
November 2011	1L	January 2013	3A	March 2014	4C
December 2011	1M	February 2013	3B		
January 2012	2A	March 2013	3C		
February 2012	2B	April 2013	3D		
March 2012	2C	May 2013	3E		
April 2012	2D	June 2013	3F		
May 2012	2E	July 2013	3G		
June 2012	2F	August 2013	3H		

Incidents/Injuries:

The firm has received twelve new reports of lamps shattering including one incident involving a fire. No injuries have been reported.

Remedy:

Consumers should immediately stop using the recalled lamps and contact Philips for a free replacement.

Sold At:

Electrical supply distributors, including Grainger, Rexel and Voss from May 2011 through August 2014 for about \$40.

Distributor(s):

Philips Lighting North America Corp., of Somerset, N.J.

Manufactured In:

United States



Polaris Recalls RZR and GENERAL Recreational Off-Highway Vehicles Due to Burn and Fire Hazards

Recall date: March 2, 2017

Recall number: 17-102



Recall Summary

Name of product:

Polaris recreational off-highway vehicles (ROVs)

Hazard:

The vehicle engine can misfire and the temperatures of the exhaust and nearby components can get too hot and cause the components to melt, and/or a contaminated brake master cylinder may cause unintended brake drag, posing burn and fire hazards.

Remedy:

✂ Repair

Consumer Contact:

Polaris at 800-765-2747 from 7 a.m. to 7 p.m. CT Monday through Friday or online at

www.polaris.com

and click on “Off-Road Safety Recalls” at the bottom of the page for more information. In addition, check your vehicle Identification number (VIN) on the “

Product Safety Recalls

” page to see if your vehicle is included in any recalls.

Recall Details

Units:

About 13,500 (The RZR Turbo and RZR 900 and 1000 have previously been recalled.)

Description:

This recall involves model year 2016 and 2017 RZR 900, 1000, Turbo and GENERAL 1000 recreational off-road vehicles (ROVs). "Polaris" is printed on the front grill and "RZR" or "GENERAL" is printed on the side of the rear cargo area. The ROVs were sold in various colors. The following models are included in the recall.

Model Year	Model Number	Model
2016	R16RGE99A7	POLARIS GENERAL 1000 EPS INDY RED
2016	R16RGE99AE	POLARIS GENERAL 1000 EPS DELUXE ORANGEBURST
2016	R16RGE99AV	POLARIS GENERAL 1000 EPS VELOCITY BLUE LE
2017	R17RGE99A7	POLARIS GENERAL 1000 EPS INDY RED
2017	R17RGE99A9	POLARIS GEN 1000 EPS HUNTER ED CAMO
2017	R17RGE99AM	POLARIS GEN 1000 EPS DXE TITANMATMETAL
2017	R17RGE99AW	POLARIS GENERAL 1000 EPS WHITE LIGHTNING
2017	R17RHE99AU	POLARIS GENERAL 4 1000 EPS SILVER PEARL
2016	Z16VAA87A2	RZR 900 WHITE LIGHTNING
2016	Z16VAE87AL	RZR 900 EPS TRAIL STEALTH BLACK
2016	Z16VAE87AU	RZR 900 EPS TRAIL MATTE TURBO SILVER
2016	Z16VAX87AM	RZR 900 EPS XC EDITION TITANIUM M METALLIC
2016	Z16VBA87A2	RZR S 900 WHITE LIGHTNING
2016	Z16VBA87AB	RZR S 900 PAINT BLUE FIRE
2016	Z16VBE87AE	RZR S 900 EPS SPECTRA ORANGE
2016	Z16VBE87AS	RZR S 900 EPS MATTE SUNSET RED
2016	Z16VBE99AB	RZR S 1000 EPS BLUE FIRE METALLIC
2016	Z16VBE99AK	RZR S 1000 EPS BLACK PEARL
2016	Z16VBE99AW	RZR S 1000 EPS MATTE WHITE LIGHTNING
2016	Z16VCE87AE	RZR 4 900 EPS SPECTRA ORANGE
2016	Z16VCE87AS	RZR 4 900 EPS MATTE SUNSET RED
2016	Z16VDE99AM	RZR XP 1000 EPS TITANIUM MATTE METALLIC
2016	Z16VDE99AS	RZR XP 1000 EPS SUNSET RED
2016	Z16VDM99AM	RZR XP 1000 EPS HIGH LIFTER TITANIUM MATTE
2016	Z16VFE92AE	RZR XP 4 TURBO EPS SPECTRA ORANGE

2016	Z16VFE92AH	RZR XP 4 TURBO EPS GRAPHITE CRYSTAL
2016	Z16VFE92AS	RZR XP 4 TURBO EPS MATTE SUNSET RED
2016	Z16VFE92AW	RZR XP 4 TURBO EPS MATTE WHITE LIGHTNING
2016	Z16VFE99AM	RZR XP 4 1000 EPS TITANIUM MATTE METALLIC
2016	Z16VFE99AS	RZR XP 4 1000 EPS SUNSET RED
2016	Z16VFM99AM	RZR XP 4 1000 EPS HIGH LIFTER ED TITANIUM M
2017	Z17VAA87A2	RZR 900 WHITE LIGHTNING
2017	Z17VAE87AB	RZR 900 EPS BLUE FIRE
2017	Z17VAE87AK	RZR 900 EPS BLACK PEARL
2017	Z17VAX87AK	RZR 900 EPS XC BLACK PEARL
2017	Z17VBA87A2	RZR S 900 WHITE LIGHTNING
2017	Z17VBE87AB	RZR S 900 EPS VELOCITY BLUE
2017	Z17VBE87AK	RZR S 900 EPS BLACK PEARL
2017	Z17VBE99AL	RZR S 1000 EPS STEALTH BLACK
2017	Z17VBE99AR	RZR S 1000 EPS INDY RED
2017	Z17VCE87AB	RZR 4 900 EPS VELOCITY BLUE
2017	Z17VCE87AK	RZR 4 900 EPS BLACK PEARL
2017	Z17VDE92AK	RZR XP TURBO EPS CRUISER BLACK
2017	Z17VDE92AM	RZR XP TURBO EPS TITANIUM MATTE METALLIC
2017	Z17VDE99AM	RZR XP 1000 EPS TITANIUM MATTE METALLIC
2017	Z17VDE99AW	RZR XP 1000 EPS WHITE LIGHTNING
2017	Z17VDK99AK	RZR XP 1000 EPS VELOCITY BLUE LE
2017	Z17VDM99AB	RZR XP 1000 EPS HIGH LIFTER VEL BLUE
2017	Z17VDR99AZ	RZR XP 1000 EPS BOULDERS ED MATTE GOLD
2017	Z17VFE92AK	RZR XP 4 TURBO EPS CRUISER BLACK
2017	Z17VFE92AM	RZR XP 4 TURBO EPS TITANIUM MATTE METALLIC
2017	Z17VFE99AM	RZR XP 4 1000 EPS TITANIUM METALLIC
2017	Z17VFE99AW	RZR XP 4 1000 EPS WHITE LIGHTNING
2017	Z17VFM99AB	RZR XP 4 1000 EPS HIGH LIFTER ED VEL BLUE

Incidents/Injuries:

Polaris has received 14 reports of vehicles catching fire related to the brake master cylinder and one report of fire and two reports of melting vehicle components related to an engine misfire. No injuries have been reported.



One World Technologies Recalls Electric Blowers Due to Laceration Hazard; Sold Exclusively at Home Depot

Recall date: March 2, 2017

Recall number: 17-101



Recall Summary

Name of product:

Ryobi Electric Jet Fan Blowers

Hazard:

The plastic fan inside the blower can break causing the fan blades to be discharged from either end of the blower tube, posing a laceration hazard.

Remedy:

↻ Replace

Consumer Contact:

One World Technologies at 800-860-4050 between 8 a.m. to 8 p.m. ET Monday through Friday or 9 a.m. to 6 p.m. ET Saturday and Sunday or online at

www.ryobitools.com

and click on "Important Recall Notice" for more information.

Recall Details

In Conjunction With:



Units:

About 121,000 (In addition, about 1,900 were sold in Canada and 1,100 in Mexico)

Description:

This recall involves the Ryobi 8amp Electric Jet Fan Blowers with model number RY42102 and a serial number between EU15401D170001 and EU16239N999999. The model and serial numbers are printed on the data label on the bottom of the blower. The blower is black and green with "RYOBI" printed on the side of the blower. "8amp JET FAN" is also printed on the side of the blower.

Incidents/Injuries:

One World has received reports of 10,681 incidents, including 25 reports of minor injuries, such as lacerations to the face, hands and legs from fan blade pieces being discharged from either end of the blower. No property damage has been reported.

Remedy:

Consumers should immediately stop using the recalled electric blowers and contact One World Technologies, Inc. for a free replacement.

Sold Exclusively At:

Home Depot stores nationwide, in Canada and Mexico and online at www.homedepot.com from December 2015 through December 2016 for about \$40.

Manufacturer(s):

Techtronic Industries (Dongguan) Co. Ltd., of China

Importer(s):

One World Technologies Inc., of Anderson, S.C.

Manufactured In:


China



Goodman Recalls Air Handlers Due to Electrical Shock Hazard

Recall date: March 2, 2017

Recall number: 17-103



Recall Summary

Name of product:

Air handlers

Hazard:

The pull-out disconnects may not disable power to the air handler, posing an electrical shock hazard to individuals servicing the units.

Remedy:

✚ Repair

Consumer Contact:

Goodman toll-free at 888-386-2075 from 8 a.m. to 5 p.m. ET Monday through Friday or online at www.goodmanmfg.com and click on "Air Handler Product Recall" at the top of the page for more information.

Recall Details

In Conjunction With:



Units:

About 210,000 (in addition, 20 were sold in Canada)

Description:

This recall involves Goodman air handler models AWUF and ACNF (A = Air Handler; W = Wall Mount; C = Ceiling Mount; U = Unpainted; N = Uncased; F = Flowrater). The recalled air handlers are most often installed in apartment and condominium units and are used with heating and cooling systems to provide climate control. The AWUF model units are wall mounted, while ACNF model units are ceiling mounted. The recalled air handlers have serial numbers beginning with 1511, 1512, or 1601 through 1610. The serial number is located on the label found by removing the wall panel (for AWUF units) or ceiling panel (for ACNF units).

Incidents/Injuries:

Goodman has received reports involving six units at two locations of the air handlers remaining powered when the disconnect handles were removed. No injuries have been reported.

Remedy:

Consumers should immediately contact Goodman for a free inspection and free repair. Goodman is contacting all known commercial owners directly.

Sold At:

Goodman heating and cooling equipment dealers nationwide from November 2015 through October 2016 for between \$300 and \$600 per unit. Apartment complexes, townhouse and condominium associations and individuals then generally purchased a bundled product including the unit, the installation and ancillary parts and supplies.

Manufacturer(s):

Goodman Company L.P., of Fayetteville, Tenn. and Goodman Manufacturing Company L.P., of Houston, Texas

Manufactured In:

U.S.




This recall was conducted, voluntarily by the company, under CPSC's Fast Track Recall process. Fast Track recalls are initiated by firms, who commit to work with CPSC to quickly announce the recall and remedy to protect consumers.



Kids II Recalls Oball Rattles Due to Choking Hazard

Recall date: March 2, 2017

Recall number: 17-104



Recall Summary

Name of product:

Oball Rattles

Hazard:

The clear plastic disc on the outside of the ball can break, releasing small beads, posing a choking hazard to young children.

Remedy:

\$ Refund

Consumer Contact:

Kids II toll-free at 877-243-7314 from 8 a.m. to 5 p.m. ET Monday through Friday or visit

www.kidsii.com

and click on "Recalls" at the bottom of the page for more information.

Recall Details

In Conjunction With:



Units:

About 680,000 (in addition, about 17,000 were sold in Canada)

Description:

This recall involves Oball Rattles in pink, blue, green and orange with model number 81031 printed on the inner surface of one of the plastic discs and on the packaging. The balls have 28 finger holes and measure four inches in diameter. Embedded in the rattles are a clear plastic disc with all orange beads and two clear plastic discs with beads of varying colors on the perimeter. Only rattles with date codes T0486, T1456, T2316, T2856 and T3065 located on a small triangle on the inner surface of the rattle are included in the recall. The first three numbers represent the day of the year and the last digit represents the year of production.

Incidents/Injuries:

The firm has received 42 reports of the plastic disc breaking releasing small beads including two reports of beads found in children's mouths and three reports of gagging.

Remedy:

Consumers should immediately take these recalled rattles away from young children and contact the firm to receive a full refund.

Sold At:

Target, Walgreens, Walmart and other retailers nationwide and online at Amazon.com, Babyhaven.com, Diapers.com, ToysRUs.com, Walgreens.com and other online retailers from January 2016 through February 2017 for between \$5 and \$7.

Importer(s):

Kids II Inc., of Atlanta, Ga.

Manufactured In:

China





This recall was conducted, voluntarily by the company, under CPSC's Fast Track Recall process. Fast Track recalls are initiated by firms, who commit to work with CPSC to quickly announce the recall and remedy to protect consumers.



Craftsman Portable Table Saws Made by Rexion Recalled Due to Laceration and Impact Injury Hazards; Sold Exclusively at Sears

Recall date: March 7, 2017

Recall number: 17-105



Recall Summary

Name of product:

Craftsman portable table saws

Hazard:

The table saw's stand can collapse unexpectedly, posing laceration and impact injury hazards to the operator.

Remedy:

↺ Replace

Consumer Contact:

Rexion toll-free at 866-934-6360 from 8:30 a.m. to 5 p.m. ET Monday through Friday or online at

www.sears.com

and clicking "Product Recalls" for more information.

Recall Details

Units:

About 46,000

Description:

The recall involves model number 137.415030 Craftsman brand 10-inch table saws. The table saws sit on a black metal foldable stand. "15 AMP 10-inch table saw," "Sears Brands Mgt. Corp." and the model and serial numbers are printed on a silver label on the front. Serial numbers included in the recall begin with the following letters:

RSN	RSP	RSQ	RSR	RSS	RST	RSU	RSV	RSW	RSX
RSY	RSZ	RTN	RTP	RTQ	RTR	RTS	RTT	RTU	RTV
RTW	RTX	RTY	RTZ	RUN	RUP	RUQ	RUR	RUS	RUT

Incidents/Injuries:

The firm has received 11 reports of the table saw collapsing, including nine reports of injuries to fingers and hands, including broken bones, lacerations, a shoulder strain, and a partial fingernail amputation.

Remedy:

Consumers should immediately stop using the recalled table saws and contact Rexon for a free replacement stand.

Sold At:

Sears stores nationwide and online at www.sears.com from April 2014 through October 2016 for about \$200.

Manufacturer(s):

Rexon Industrial Corp., Ltd. of Taiwan

Distributor(s):

Sears Holding Corp. of Hoffman Estates, Ill.

Manufactured In:

China



RDG Global Recalls Girls' Hooded Sweatshirts Due to Strangulation Hazard; Sold Exclusively at Nordstrom

Recall date: March 9, 2017

Recall number: 17-106



Recall Summary

Name of product:

Girls' hooded sweatshirts

Hazard:

The hooded sweatshirts have a drawstring in the hood, which poses a strangulation hazard to children. Drawstrings can become entangled or caught on playground slides, hand rails, school bus doors or other moving objects, posing a significant strangulation or an entanglement hazard to children.

Remedy:

\$ Refund

Consumer Contact:

RDG Global at (844) 851-9979 from 10 a.m. to 4 p.m. ET Monday through Friday or online at

www.rdgglobal.nyc

and click on "Product Recalls" at the bottom of the page for more information.

Recall Details

Units:

About 2,600

Description:

This recall involves RDG Global girls' olive green-colored hooded sweatshirts with drawstrings inside the lining of the hood. The sweatshirts are polyester and spandex with a sherpa-lined hood. There is an asymmetric zipper on the front of the garment. They were sold in girls' sizes S (6-7), M (8-10), and L (12). A blue size label with "Freshman 1996" and "Made in China" is located at the center back neck of the sweatshirts. Another label in the neck seam has the words RDG Global LLC and VB740 and 8K80375N. A label in the side seam has the care instructions and RN# 146919.

Incidents/Injuries:

None reported

Remedy:

Consumers should immediately remove the drawstrings from the garment to eliminate the hazard or contact RDG Global or Nordstrom for a full refund.

Sold Exclusively At:

Nordstrom stores nationwide and online at www.Nordstrom.com from November 2016 through January 2017 for about \$60.

Importer(s):

RDG Global LLC, of New York

Manufactured In:

China



Pier 1 Imports Recalls Bistro Chairs Due to Fall Hazard

Recall date: March 9, 2017

Recall number: 17-107



Recall Summary

Name of product:

Neely and Dahlia Bistro Chairs

Hazard:

The bolts and/or nuts connecting the chair legs to the chair base can loosen and make the chair unstable, posing a fall hazard to consumers.

Remedy:



Repair

Consumer Contact:

Pier 1 Imports toll-free at 855-513-5140 from 8 a.m. to 7 p.m. CT Monday through Friday, 9 a.m. to 5 p.m. CT

Saturday or 10 a.m. to 6 p.m. CT Sunday or online at

www.pier1.com

and click on "Product Notes & Recalls" at the bottom of the page for more information.

Recall Details

In Conjunction With:



Units:

About 13,300 sets and 700 individual chairs in the U.S. (in addition, about 760 sets and 40 individual chairs in Canada).

Description:

This recall involves Neely and Dahlia bistro chairs sold separately and as part of a set. The chairs are made from powder coated cast aluminum, and were sold in eight colors. The chairs are approximately 33 inches high by 20 inches deep by 18.25 inches wide. A metal Pier 1 Imports brand plate is attached to the support ring on the underside of the bistro table. Only the chairs are included in this recall.

Incidents/Injuries:

Pier 1 Imports has received six reports of incidents of the chair legs loosening and/or collapsing, resulting in four reports of injuries including bruises and abrasions from falls.

Remedy:

Consumers should immediately stop using the recalled chairs and contact Pier 1 Imports for a free repair kit.

Sold Exclusively At:

Pier 1 Imports stores nationwide and online at www.Pier1.com from January 2013 through July 2016 for between \$100 and \$380.

Importer(s):

Pier 1 Imports, of Fort Worth, Texas

Manufactured In:

China



R.W. Beckett Recalls Fuel Oil Valves Due to Fire Hazard

Recall date: March 10, 2017

Recall number: 17-108



Recall Summary

Name of product:

Firomatic® fusible safety valves

Hazard:

The safety valve stem does not properly seal and shut off the flow of fuel, allowing fuel to leak and posing a fire hazard.

Remedy:

↺ Replace

🔧 Repair

Consumer Contact:

R.W. Beckett at 800-645-2876 from 8 a.m. to 5 p.m. ET, Monday through Friday or online at

www.beckettcorp.com

and click on Support/Technical Bulletins for more information.

Recall Details

Units:

About 18,000

Description:

This recall involves Firomatic ½ inch FPT Fusible Safety Valves series 200 Fusible Inline valve, 1/2F X 1/2F Out. The valves are located on the fuel lines that lead to oil-burning appliances. The valves have a UL metal ring on top of the body of the valve stamped with “FIROMATIC SERIES 200.” “Firomatic” is cast into the body of the recalled valves.

Incidents/Injuries:

None reported

Remedy:

Consumers should immediately contact R.W. Beckett for a free repair kit or a replacement valve and free installation.

Sold At:

HVAC wholesale distributors including Ferguson Enterprises, FW Webb, Johnstone Supply, RE Michel Co and Sid Harvey Industries nationwide and from September 2011 through September 2016 for about \$40.

Manufacturer(s):

Shanghai Minmetals, of China

Importer(s):

R.W. Beckett Corp., of North Ridgeville, Ohio

Manufactured In:

China



LIVLY Recalls Children's Sleepwear Due to Violation of Federal Flammability Standard

Recall date: March 14, 2017

Recall number: 17-110



Recall Summary

Name of product:

Children's robes and two-piece pajama sets

Hazard:

The children's robes and pajama sets fail to meet federal flammability standards for children's sleepwear, posing a risk of burn injuries to children.

Remedy:

\$ Refund

Consumer Contact:

LIVLY toll-free at 844-350-7728 from 9 a.m. to 5 p.m. Monday through Friday or online at

www.livlyclothing.com

and click on "Product Recall" at the bottom of the page for more information.

Recall Details

Units:

About 1,200

Description:

This recall involves children’s robes and two-piece pajama sets. The recalled two-piece sets are a long-sleeve top and pants and have a sewn-in side fabric label that has “LIVLY,” “www.livlyclothing.com” and RN number 146214 printed on it. The two-piece sets also have a printed label with “LIVLY” on the back of the neck and at the back of the pants. The recalled robes have a chest pocket on the left side with the word “Mini” embroidered on it, two pockets at the bottom and one snap-closure on the right side above the abdomen for closure. A belt is attached to the center back of the robe and an outline of a sleeping face is embroidered on the back of the robe. A fabric label with “LIVLY” and the size is sewn on the inside of the neck of the robe.

Clothing Item	Color/Print	Fabric	Sizes
Children’s two-piece (long-sleeve top and pants) sleepwear sets	Princess Land Pink, Princess Land Blue, Mauve Flower, Pink, Blue Dots, Clouds, Reptiles, Neon Roses, Green Fog, Grey and Black Stars, Pink and Grey Stars, Grey to the Moon and Back, Black to the Moon and Back, and Mini Sleeping Cutie	100% cotton	12-18 months through 12
Children’s long-sleeve robes	White with black piping trim	100% cotton	S,dM, L

Incidents/Injuries:

None reported

Remedy:

Consumers should immediately take the recalled children’s clothing away from children and contact LIVLY for a full refund.

Sold At:

Baby Elaine, Bluebelle, Le Bambini, The Hosiery Boutique, LIVLY and other specialty stores and online at Gilt.com, LivlyClothing.com and other websites from February 2016 through January 2017 for about \$55 for the children’s two-piece pajama sets and \$78 for the children’s robes.

Importer(s):

LCK Design LLC d/b/a Livly Clothing, Sunny Isles, Fla.

Manufactured In:

Peru



Battery Chargers for XBOX ONE Video Game Controllers Recalled by Performance Designed Products Due to Burn Hazard

Recall date: March 14, 2017

Recall number: 17-109



Recall Summary

Name of product:

Energizer® XBOX ONE 2X Smart Chargers

Hazard:

The battery chargers can overheat and damage the XBOX ONE video game controller, posing a burn hazard to consumers.

Remedy:

\$ Refund

Consumer Contact:

Performance Designed Products at 800-263-1156 from 10 a.m. to 4 p.m. PT Monday through Friday, or online at

www.pdp.com

and click on Safety Recall for more information.

Recall Details

In Conjunction With:



Units:

About 121,000 in the U.S. (In addition, about 7,250 were sold in Canada and 2,560 in Mexico)

Description:

This recall involves Energizer® XBOX ONE 2X Smart Chargers used to charge XBOX ONE video game controllers. The chargers are black plastic and measure about 3.5 inches long, 5 inches wide and 11 inches tall. "Energizer®" is printed on the charger's label. Item number 048-052-NA is printed on the bottom of the chargers. The chargers hold up to two XBOX controllers.

Incidents/Injuries:

The company has received 24 reports of the chargers overheating and deforming the charger's plastic cover, including 6 reports of chargers emitting a burning odor. No injuries have been reported.

Remedy:

Consumers should immediately stop using the recalled battery chargers and contact Performance Designed Products to return the chargers for a full refund.

Sold At:

Best Buy, GameStop and other stores nationwide and online at Amazon.com and other online retailers from February 2016 through February 2017 for about \$40.

Importer(s):

Performance Designed Products LLC, of Burbank, Calif.

Distributor(s):

Performance Designed Products LLC, of Burbank, Calif.

Manufactured In:

China



This recall was conducted, voluntarily by the company, under CPSC's Fast Track Recall process. Fast Track recalls are initiated by firms, who commit to work with CPSC to quickly announce the recall and remedy to protect consumers.



Advanced Sports International Recalls Fuji Bicycles Due to Fall Hazard

Recall date: March 15, 2017

Recall number: 17-111



Recall Summary

Name of product:

Fuji bicycles

Hazard:

The rear wheel freehub can slip while pedaling, posing a fall hazard.

Remedy:

↻ Replace

Consumer Contact:

Advanced Sports International toll-free at 888-286-6263 from 9 a.m. to 5 p.m. ET Monday through Friday or online at

fujibikes.com

or ovalconcepts.com and click on "Recall Notice" at the bottom of the page for more information.

Recall Details

Units:

About 650

Description:

This recall involves Advanced Sports International's 2017 Fuji bicycles with Oval Concepts Rear Wheels. The aluminum or carbon fiber bicycles come in a variety of colors. The bicycle model name is printed on the frame of the bicycle. The wheel model number is printed on the rim of the wheel. The hub model number is printed on the drive-side hub flange.

Recalled models include:

Bike Model	Wheel Model	Hub Model
Fuji Altamira CX 1.1	Oval 950 Disc	3LLR
Fuji Altamira CX 1.3	Oval 723 Disc	
Fuji Brevet 1.1 Disc		
Fuji Cross 1.1		
Fuji Gran Fondo 1.1 Disc		
Fuji Gran Fondo 1.3 Disc		
Fuji SL 1.3 Disc		
Fuji Gran Fondo Elite Disc	Oval 924 Disc	3NVR
Fuji SL 1.1 Disc		
Fuji Norcom Straight 1.1	Oval 980	
Fuji Norcom Straight 1.3		
Fuji SL 1.1	Oval 935	
Fuji SL 1.3		
Fuji Transonic Elite	Oval 950	

Incidents/Injuries:

Advanced Sports International has received four reports of freehub slipping while pedaling. No crashes or injuries have been reported.

Remedy:

Consumers should immediately stop riding the recalled bicycles and contact Advanced Sports International to receive a free replacement freehub body.

Sold At:

Fuji Bicycle and Authorized Oval Concept dealers from April 2016 through October 2016 for between \$2000 to \$8000.

Importer(s):

Advanced Sports International, of Philadelphia, Pa.

Distributor(s):

Advanced Sports International, of Philadelphia, Pa.

Manufactured In:

China and Taiwan



Polaris Recalls Sportsman 850 and 1000 All-Terrain Vehicles Due to Burn and Fire Hazards

Recall date: March 21, 2017

Recall number: 17-112



Recall Summary

Name of product:

Sportsman 850 and 1000 all-terrain vehicles (ATVs)

Hazard:

The right side panel heat shield can melt, posing burn and fire hazards to riders. In addition, in 2015 Sportsman 1000 ATVs, the exhaust springs can stretch and damage the exhaust seal, which can result in exhaust leaks and pose burn and fire hazards.

Remedy:



Consumer Contact:

Polaris at 800-765-2747 from 7 a.m. to 7 p.m. CT Monday through Friday or online at

Polaris

and click on “

Off-Road Safety Recalls

” for more information. In addition, check your vehicle identification number (

VIN

) on the “Product Safety Recalls” page to see if your vehicle is included in any recalls.

Recall Details

Units:

About 19,200

Description:

This recall involves all model year 2015 and 2016 Polaris Sportsman 850 and 1000 model all-terrain vehicles (ATVs). "Polaris" is printed on the front grill and "Sportsman 850" or "Sportsman 1000" is printed on the side of the steering column. The ATVs were sold in several colors. The model number is located on the fuel tank cover. The following models are included in the recall:

Model Year	Model Number	Model/Color
2015	A15SXA85AJ	Sportsman 850 White Lightning
2015	A15SXA85AA	Sportsman 850 Sage Green
2015	A15SXA85AC	Sportsman 850 Polaris Pursuit Camo
2015	A15SXE85AS	Sportsman 850 SP Sunset Red
2015	A15SXE85AM	Sportsman 850 SP Titanium Matte Metallic
2015	A15SYE85AS	Sportsman Touring 850 SP Sunset Red
2015	A15SYE85AV	Sportsman Touring 850 SP Blue Fire
2015	A15SXE95AW	Sportsman XP 1000 Matte White Le
2015	A15SXE95AK	Sportsman XP 1000 SP Black Pearl Metallic
2015	A15SXE95AC	Sportsman XP 1000 Polaris Pursuit Camo
2015	A15SYE95AX	Sportsman Touring XP 1000 Bronze Mist
2015	A15SXL95AM	Sportsman XP 1000 Titanium Matte Metallic
2015	A15SYL95AP	Sportsman XP 1000 Touring White Pearl Metal
2016	A16SXA85A2	Sportsman 850 White Lightning
2016	A16SXA85A1	Sportsman 850 Sage Green
2016	A16SXA85A9	Sportsman 850 Polaris Pursuit® Camo
2016	A16SXE85AB	Sportsman 850 SP Velocity Blue
2016	A16SXE85AS	Sportsman 850 SP Sunset Red
2016	A16SXN85A3	Sportsman 850 High Lifter Edition
2016	A16SXE85AM	Sportsman 850 SP Titanium Matte Metallic
2016	A16SYE85AS	Sportsman Touring 850 SP Sunset Red
2016	A16SXE95AG	Sportsman XP 1000 Matte Sagebrush Green
2016	A16SXE95AR	Sportsman XP 1000 Havasu Red Pearl
2016	A16SXD95A9	Sportsman XP 1000 Hunter Edition
2016	A16SYE95AK	Sportsman Touring XP 1000 Black Pearl
2016	A16SXM95AL	Sportsman XP 1000 High Lifter Edition
2016	A16SYE95AP	Sportsman Touring XP 1000 Pearl White Le

Incidents/Injuries:

Polaris has received at least 793 incidents, including reports of warped, melted or burned side panels, 47 fires and four minor burn injuries.

Remedy:



Wing Enterprises Recalls Little Giant Ladders Due to Fall Hazard

Recall date: March 23, 2017

Recall number: 17-113



Recall Summary

Name of product:

Little Giant multipurpose ladders

Hazard:

The ladder's locking pins/rung fasteners can fail, posing a fall hazard to consumers on the ladder.

Remedy:

✂ Repair

Consumer Contact:

Wing Enterprises toll-free at 855-595-3378 from 8 a.m. to 5 p.m. MT Monday through Friday or online at www.littlegiantladders.com

and click on RECALL at the top of the home page for more Information.

Recall Details

Units:

About 37,000

Description:

This recall involves Little Giant Velocity™, LT™ and Liberty™ multipurpose ladders. The ladders have joints that allow it to bend and lock in various positions. "Little Giant," the model name, model number and part number are printed on the side of the ladder.

Little Giant Velocity	Part Number	Little Giant LT	Part Number
Model 13	15413-001	Model 13	14313-001
Model 13	15413-025	Model 17	14317-001
Model 17	15417-001	Model 17	14317-303
Model 17	15417-161	Model 22	14322-001
Model 22	15422-001		
Model 22	15422-014	Little Giant Liberty	
Model 26	15426-001	Model 17	14717-139

Ladders included in the recall have one of the following date codes stamped on the outer rail below the red locking pin.

Date Codes						
10361P	10463P	10661P	10763P	10961P	11063P	11254P
10362P	10464P	10662P	10764P	10962P	11064P	11261P
10363P	10561P	10663P	10861P	10963P	11161P	11262P
10364P	10562P	10664P	10862P	10964P	11162P	11263P
10461P	10563P	10761P	10863P	11061P	11163P	11264P
10462P	10564P	10762P	10864P	11062P	11164P	
10361S	10463S	10661S	10763S	10961S	11063S	11254S
10362S	10464S	10662S	10764S	10962S	11064S	11261S
10363S	10561S	10663S	10861S	10963S	11161S	11262S
10364S	10562S	10664S	10862S	10964S	11162S	11263S
10461S	10563S	10761S	10863S	11061S	11163S	11264S
10462S	10564S	10762S	10864S	11062S	11164S	

Incidents/Injuries:

Wing Enterprises has received two reports of locking pins/rung fasteners failing. No injuries have been reported.

Remedy:

Consumers should immediately stop using recalled ladders and contact Wing Enterprises for a free repair kit with ABS nylon inserts that the customer can install without the use of tools.

Sold At:

AAFES, NEXCOM, PPG Paints stores nationwide and online at Amazon.com, DirectBuy.com, Eladders.com, Grainger.com, Groupon.com, Homedepot.com, Houzz.com, Laddersales.com, LittleGiantLadder.com, Lowes.com, Overstock.com, Samsclub.com, Target.com, Wayfair.com, Zoro.com 1800ladders.com and other Web retailers from March 2016 through February 2017 for between \$200 and \$320



Haibike Recalls Electric Bicycles Due to Fall Hazard

Recall date: March 23, 2017

Recall number: 17-114



Recall Summary

Name of product:

Electric bicycles

Hazard:

The fork on the front wheel of the bicycles can rupture or break while in use, posing a fall hazard to the rider.

Remedy:

🔧 Repair

Consumer Contact:

Accell North America at 800-222-5527 from 8 a.m. to 5 p.m. PT Monday through Friday or online at

www.haibike.com

and click on "Current recalls" on the right side of the page for more information.

Recall Details

In Conjunction With:



Units:

About 250 (in addition, 17 were sold in Canada)

Description:

This recall involves Haibike XDURO Urban, Race and Superrace models of electric bicycles. The recalled bicycles have an aluminum frame, hydraulic disc brakes, and a lithium battery. The recalled bicycles have a letter/number combination ('HAERA' followed by at least three numbers and characters) printed on the front of the frame. Remove the battery to locate the letter/number combination on the frame. The following models are included in the recall.

Model	Model Year	Color	Letter/Number
Haibike XDURO Urban	2014, 2015	Gray	'HAERA' followed by three numbers and characters
Haibike XDURO Urban RC	2016	Gray	
Haibike XDURO Race	2014, 2015	Black	
Haibike XDURO Superrace	2014, 2015	Black	
Haibike XDURO Race S RX	2016	Gray	
Haibike XDURO Urban S RX	2016	White	

Incidents/Injuries:

None reported

Remedy:

Consumers should immediately stop using the recalled bicycles and contact Accell North America for a free repair.

Sold At:

Independent bicycle dealers nationwide from January 2014 through February 2017 for about \$4,000.

Importer(s):

Haibike, of Denver, Colo., owned by Accell North America

Manufactured In:

Germany and Taiwan



This recall was conducted voluntarily by the company, under CPSC's Fast Track Recall process. Fast Track recalls are initiated by firms, who commit to work with CPSC to quickly announce the recall and remedy to protect consumers.



Vecaro LifeStyle Recalls Self-Balancing Scooters/Hoverboards Due to Fire Hazard

Recall date: March 23, 2017

Recall number: 17-115



Recall Summary

Name of product:

Self-balancing scooters/hoverboards

Hazard:

The lithium-ion battery packs in the self-balancing scooters/hoverboards can overheat, posing a risk of smoking, catching fire and/or exploding.

Remedy:

↺ Replace

🔧 Repair

Consumer Contact:

Vecaro toll-free at 855-637-4061 from 9 a.m. to 5 p.m. PT Monday through Friday or online at

www.VecaroLifeStyle.com

and click on Recall Notice at the bottom of the page for more information.

Recall Details

Units:

About 500

Description:

This recall involves the Vecaro brand Glide65, Drift8, and Trek10 self-balancing scooter, commonly referred to as hoverboards. Hoverboards have one wheel at each end of a platform and are powered by lithium-ion battery packs. The boards have "Vecaro" printed on the front outer casing and come in black, white, red, blue, metallic gold, metallic silver, graffiti white print, and red flame print. The model number is on the right for both the Glide65 and Drift8. The Trek10 model number is on top of the board.

Incidents/Injuries:

Vecaro has received three reported incidents of hoverboards smoking. No injuries or property damage have been reported.

Remedy:

Consumers should immediately stop using these recalled scooters/hoverboards and contact Vecaro to return their unit to receive a free repair or a credit toward the purchase of a UL 2272 certified Vecaro Glide or Glide-X.

Sold At:

The Audio Shop and Stereo Zone in California and online at VecaroLifeStyle.com from November 2015 through November 2016 for between \$300 and \$400.

Manufacturer(s):

Vecaro LifeStyle, of Cerritos, Calif.

Importer(s):

Vecaro LifeStyle, of Cerritos, Calif.

Manufactured In:

China



OPW Recalls Gas Station Hose Swivel Connectors Due to Fire, Explosion Hazards

Recall date: March 24, 2017

Recall number: 17-116



Recall Summary

Name of product:

Gas station hose swivel connectors

Hazard:

The swivel connectors can separate from the hose or nozzle of the gas station pump and cause fuel spillage, posing fire and explosion hazards.

Remedy:

↻ Replace

Consumer Contact:

OPW toll-free at 866-562-5931 from 8 a.m. to 5 p.m. ET Monday through Friday or online at www.opwglobal.com and click on "Swivel Recall" for more information.

Recall Details

Units:

About 824,000

Description:

The recall involves metal swivel connectors installed between the nozzle and hose of gas station pumps that dispense refined fuels such as gasoline, diesel, ethanol blends, and biodiesel blends. The recalled swivel connectors have a “MFG date” printed on the end in the format of: MM YY or MM-DD-YEAR or MM-YEAR. The model number is printed on the center body of the swivel connector. The following models are included in the recall.

Model	MFG Date
241TPS-0241C (3/4 inch)	01-01-2013 through 03-12-2017
241TPS-0241 (3/4 inch)	01 13 through 03 17
36S (3/4 inch)	01-01-2013 through 03-12-2017
241-1000 (1 inch)	01 13 through 03 17
241-1000C (1 inch)	01-01-2013 through 03-12-2017
36S (1 inch)	01-2013 through 03-2017

Incidents/Injuries:

OPW has received two reports of the swivel connectors separating from the hose or nozzle. No injuries have been reported.

Remedy:

Gas station owners should immediately stop using and remove the recalled swivel connectors and contact OPW for a free replacement. The hose and nozzle can continue to be used without the swivel connector until the replacement is installed.

Sold At:

OPW through distributors and direct to gas stations as individual units and as part of hose kits from January 2013 through January 2017 for about \$33.

Distributor(s):

OPW, of Hamilton, Ohio

Manufactured In:

Taiwan




This recall was conducted, voluntarily by the company, under CPSC’s Fast Track Recall process. Fast Track recalls are initiated by firms, who commit to work with CPSC to quickly announce the recall and remedy to protect consumers.



Look Cycle Recalls Aerostems and Road Bikes Due to Fall, Crash Hazards

Recall date: March 28, 2017

Recall number: 17-117



Recall Summary

Name of product:

Look Cycle road bikes and Aerostems

Hazard:

The stainless steel clamp that secures the stem to the handlebars can corrode and break, posing a fall and crash hazard.

Remedy:



Consumer Contact:

Look Cycle at 800-822-1980 from 8 a.m. to 5 p.m. ET Monday through Friday, email at aerostemrecall@hawleylambert.com

or online at

<http://www.lookcycle.com/>

click on the Safety Notice tab for more information.

Recall Details

Units:

About 800

Description:

This recall involves Look Cycle Aerostems sold either as an after-market component or installed as original equipment on Look Cycle model 695 and 795 road bikes for model years 2014 through 2017. The Look Aerostems are made of black carbon fiber material with a black steel clamp around the handlebars. Recalled models have either no number or the number 380706 printed in white on the bottom of the clamp. A complete list of photos of the recalled stems and bike models can be found on the firm's website at <http://www.lookcycle.com/en/safety-notice>.

Incidents/Injuries:

The firm has received one report of the stainless steel clamp on an Aerostem breaking. No injuries have been reported.

Remedy:

Consumers should immediately stop using bicycles with the recalled Aerostems and return them to the place of purchase for a free repair.

Consumers unable to return their bicycles should contact Look Cycle for instructions on receiving a free repair.

Sold At:

Independent bike stores nationwide from July 2013 through December 2016 for about \$500 for the stems sold individually and for between \$5,500 and \$16,000 installed as original equipment on Look Cycle road 695 and 795 road racing bicycles.

Importer(s):

Hawley LLC, of Lexington, S.C.

Manufactured In:

France and Switzerland



This recall was conducted, voluntarily by the company, under CPSC's Fast Track Recall process. Fast Track recalls are initiated by firms, who commit to work with CPSC to quickly announce the recall and remedy to protect consumers.



Target Recalls Magnetic Tic Tac Toe Games Due to Choking and Magnet Ingestion Hazards

Recall date: March 29, 2017

Recall number: 17-119



Recall Summary

Name of product:

Magnetic tic tac toe games

Hazard:

The magnets can come off the tic tac toe game pieces, posing a choking hazard. In addition, when two or more magnets are swallowed, they can link together inside the intestines and clamp onto body tissues, causing intestinal obstructions, perforations, sepsis and death. Internal injury from magnets can pose serious lifelong health effects.

Remedy:

\$ Refund

Consumer Contact:

Target at 800-440-0680 between 7 a.m. to 8 p.m. CT any day or online at

www.target.com

and click on "Recalls" at the bottom of the page, then on "School/Stationery/Seasonal" or the "Product Recalls" tab on Target's Facebook page for more information.

Recall Details

Units:

About 19,000

Description:

This recall involves a magnetic tic tac toe 10 x 10 inch plywood board with nine "X" and "Heart" game pieces. The game pieces have a magnet on the back. Model number "234-25-1089" is printed on the bottom right corner of the product.

Incidents/Injuries:

Target has received one report of the magnets falling off the game piece. No injuries have been reported.

Remedy:

Consumers should immediately stop using the recalled tic tac toe game and return it to any Target store for a full refund.

Sold Exclusively At:

Target stores nationwide from December 2016 through February 2017 for about \$5.

Importer(s):

Target Corp., of Minneapolis, Minn.

Manufactured In:

China



This recall was conducted, voluntarily by the company, under CPSC's Fast Track Recall process. Fast Track recalls are initiated by firms, who commit to work with CPSC to quickly announce the recall and remedy to protect consumers.



Juratoys Recalls Toy Trolleys Due to Impact Injury Hazard

Recall date: March 29, 2017

Recall number: 17-120



Recall Summary

Name of product:

Bricolo by Janod ® Push toy trolleys

Hazard:

The toy trolleys can tip backwards, posing an impact injury hazard to children.

Remedy:

✂ Repair

Consumer Contact:

Juratoys toll free at 877-277-1663 from 8:30 a.m. to 5 p.m. ET Monday through Friday, or online at

www.janod.com

and click on "Product Recall" under the "Janod Express" tab at the top of the page for more information.

Recall Details

In Conjunction With:



Units:

About 9,900 (in addition about 640 were sold in Canada)

Description:

This recall involves four Bricolo by Janod® -push toy trolleys. The French Cocotte Cooker trolley is red with orange wheels and includes a cooktop with fried egg shapes, an oven and eight accessories, including pots and pans "Janod" printed on the side and front of the trolley and J06544 printed on the base of the toy. The DIY-Magnetic trolley is gray and black with red wheels with work station and tools. "Bricolo" is printed on the front of the DIY-Magnetic trolley and J06505 is printed on the base of the toy. The Redmaster-Magnetic DIY trolley is black and gray with red wheels and 21 accessories, including three magnetic tools and a set of gears. J06493 is printed on the base of the toy. The Barbecue trolley is brightly colored and comes with a magnetic spatula, magnetic barbecue fork, one piece of pork, two sausages, one fish, one piece of beef, and three tomatoes. J06523 is printed on the base of the toy. The trolleys measure approximately 17 inches tall and have a 1 foot by 1 foot base.

Item Number	Description	Years Sold
J06493	Janod Redmaster –Magnetic DIY Trolley	2015–2017
J06505	Janod DIY – Magnetic Trolley	2014–2017
J06544	Janod French Cocotte Cooker Trolley	2015–2017
J06523	Janod Barbecue Trolley	2012–2014

Incidents/Injuries:

Juratoys has received two reports of trolleys falling backwards, both resulting in ER visits. One involved a tooth extraction the other a laceration to the child's nose.

Remedy:

Consumers should immediately stop using the recalled trolleys and keep them out of the reach of young children until they have installed a repair kit. Contact Juratoys for a free repair kit that includes instructions, tools, and footers to prevent the toy from tipping backwards.

Sold At:

Various toy stores nationwide including Giggie and Saks Fifth Avenue, and online at Zulily.com from September 2012 to March 2017 for about \$100. The Janod Barbecue trolley sold for about \$70.

Importer(s):

Juratoys U.S. of Fairfield, N.J.

Manufactured In:

China



BlenderBottle Recalls Whiskware Glass Dressing Shaker Bottles Due to Laceration Hazard

Recall date: March 30, 2017

Recall number: 17-121



Recall Summary

Name of product:

Whiskware™ glass dressing shaker bottles

Hazard:

The bottom of the glass dressing shaker bottle can break when the metal agitator strikes the glass bottom, posing a laceration hazard.

Remedy:

↻ Replace

Consumer Contact:

BlenderBottle toll-free at 855-906-5717 from 9 a.m. to 5 p.m. MT Monday through Friday or online at www.whiskware.com/recall

or

www.whiskware.com

and click on "Product Recall" at the bottom of the page for more information.

Recall Details

In Conjunction With:



Units:

About 48,000 (in addition, about 800 were sold in Canada)

Description:

This recall involves Whiskware glass dressing shaker bottles with a white plastic combination lid and pour spout and an internal stainless steel, round wire agitator used to mix the shaker's contents. "Whiskware™" and a volume measurement scale are written in white letters on the side of the glass bottle. Only glass shakers that measure 8.7 inches tall by about 3 inches in diameter and hold 2.5 cups of liquid are included in the recall.

Incidents/Injuries:

The firm has received 12 reports of the bottom of the glass shakers breaking. No injuries have been reported

Remedy:

Consumers should immediately stop using the recalled shakers and contact BlenderBottle to receive two free replacement plastic shakers for each returned glass dressing shaker.

Sold At:

Bed Bath & Beyond and other specialty stores nationwide and online at www.Amazon.com and other online retailers from July 2016 through January 2017 for between about \$18 and \$20.

Distributor(s):

Sundesha LLC, dba BlenderBottle Company, of Lehi, Utah

Manufactured In:

China



humangear Recalls Bottle Caps Due to Burn Hazard

Recall date: March 30, 2017

Recall number: 17-124



Recall Summary

Name of product:

humangear capCAP bottle caps

Hazard:

The capCAP can leak, dislodge or come off, posing a burn hazard to consumers when the bottles are used to hold hot liquids.

Remedy:

\$ Refund

Consumer Contact:

humangear at 800-604-1926 from 1 p.m. to 7 p.m. ET Monday through Friday, email

capcap@humangear.com

or online at

www.humangear.com

and click on "RECALL INFORMATION" at the bottom of the page for more information.

Recall Details

In Conjunction With:



Units:

About 61,000 (in addition, about 360 were sold in Canada)

Description:

This recall involves humangear's capCAP accessory bottle cap. The capCAPs were sold in green/gray, blue/gray, black/gray and black/black color combinations for standard wide-mouth stainless steel bottles and in black/gray for glass mason jars. humangear is stamped on the top of the capCAP. Only caps with model numbers HG0501, HG0502, HG0505, HG0505-DSG and HG0515 printed above the UPC code on the package are included in the recall. The recalled capCAP has a silicone seal, a rubber coating on the large cap, and a tab/slot feature on the strap. This recall only includes the newer version of capCAPs sold between November 2016 and February 2017.

Incidents/Injuries:

humangear has received one report of liquid leakage. No injuries have been reported.

Remedy:

Consumers should immediately stop using the recalled capCAP and contact humangear to receive a full refund.

Sold At:

Dicks Sporting Goods, REI, SCHEELS and other sporting goods stores nationwide from November 2016 through February 2017 for between \$7 and \$8.

Importer(s):

humangear inc., of San Francisco, Calif.

Distributor(s):

humangear inc., of San Francisco, Calif.

Manufactured In:

China



This recall was conducted, voluntarily by the company, under CPSC's Fast Track Recall process. Fast Track recalls are initiated by firms, who commit to work with CPSC to quickly announce the recall and remedy to protect consumers.



Infant Caps Recalled by Sock and Accessory Brands Due to Choking Hazard

Recall date: March 30, 2017

Recall number: 17-122



Recall Summary

Name of product:

Infant caps

Hazard:

The button on the top of the infant cap can detach, posing a choking hazard.

Remedy:

\$ Refund

Consumer Contact:

Sock and Accessory Brands Global toll-free at 877-429-7637 from 8 a.m. to 5 p.m. ET Monday through Friday or online at

www.wearsabg.com

and click on Infant Cap Recall icon on top of home page for more information.

Recall Details

In Conjunction With:



Units:

About 14,500 (in addition, about 50 were sold in Canada)

Description:

This recall involves John Deere gray infant baseball caps with a green tractor design. The caps were sold in one size (infant 6-12 months). Style number "JSH721HF" and manufacture date 11/2016 are printed on the sewn in care label inside the back of the caps.

Incidents/Injuries:

None reported

Remedy:

Consumers should immediately take the infant caps away from young children and contact the firm to receive a full refund, including shipping cost.

Sold At:

Tractor Supply Company and farm and ranch stores nationwide from January 2017 through March 2017 for between \$10 and \$16.

Importer(s):

Sock and Accessory Brands Global, of Advance, N.C.

Distributor(s):

Sock and Accessory Brands Global, of Advance, N.C.

Manufactured In:

China



Black+Decker Portable Table Saws Made by Rexon Recalled Due to Laceration and Impact Injury Hazards; Sold Exclusively at Walmart

Recall date: March 31, 2017

Recall number: 17-118



Recall Summary

Name of product:

Black+Decker portable table saws

Hazard:

The table saw stand can collapse unexpectedly, posing laceration and impact injury hazards to the operator.

Remedy:

↻ Replace

Consumer Contact:

Rexon toll-free at 866-934-6360 from 8:30 a.m. to 5 p.m. ET Monday through Friday or

www.rexon.net

and clicking "Safety Information" for more information.

Recall Details

Units:

About 400

Description:

The recall involves model number JT2504BD Black+Decker brand 10-inch table saws. The table saws sit on a black metal foldable stand. Black+Decker and JT2504BD are printed on the front right side of the table saw.

Incidents/Injuries:

None reported

Remedy:

Consumers should immediately stop using the recalled table saws and contact REXON for a free replacement stand.

Sold Exclusively At:

Walmart stores nationwide and online at Walmart.com from February 2016 through August 2016 for about \$190.

Manufacturer(s):

REXON Industrial Corp., Ltd. of Taiwan

Distributor(s):

Walmart, of Bentonville, Arkansas

Manufactured In:

China

**U.S. CONSUMER PRODUCT SAFETY COMMISSION
4330 EAST WEST HIGHWAY
BETHESDA, MD. 20814**

**OFFICIAL BUSINESS
PENALTY FOR PRIVATE USE, \$300**

CPSC HOTLINE 1-800-638-2772