073009fl01

ENVIRONMENTAL HEALTH & ENGINEERING

Environmental Health & Engineering, Inc.

117 Fourth Avenue
Needham, MA
02494-2725

TEL 800-825-5343
781-247-4300
FAX 781-247-4305

www.eheinc.com

Home Inspection/Questionnair Form

Date July 30

Field Technician(s) MAF WEC TMM

House Address (b)(6)

General Weather Description Hot humid

1. Questions for the home Owner

1) Interviewed YES NO

2) Age of the House 2006 (b)(3):CPSA Section 6(b) Home.

3) Estimated Floor Area 2350.

4) Was as there any demo's to the house? If so, when? Please explain.

None.

5) Has there been any fire in the building?

NO.

6) Any pesticides/herbicides been applied around the building or in the yard? If yes, when and which chemicals?

bug guy sprays 4x per year.

7) Has there been any recent painting/staining done in the home?

Small amount of painting in great room.

8) Has any work been done on the AC system since construction?

2nd set of coils just recharged after 9 months then changed.

9) Are all the AC system components original?

~~NO~~ AC added to the garage for classic car

10) What is the age of your refrigerator?

New with hose, mother board replaced

11) Has any piping been replaced in the home?

NO

2. Building Characteristics

1) Residential Type (Single/Multi-Family Building) If multi-family, how many?

2) Number of rooms

(10) 4 bedrooms 3 bath Livingroom / kitchen den. Laundry

3) Above grade Construction

interior exterior walls

(Wood Frame) (Concrete) Stone Brick

4) Basement

Full Crawlspace (Slab) Other _____

5) Foundation

Concrete Cinder Block Stone Other_____

6) Garage

(YES) NO

If yes, (Attached) Detached and Art work

If yes, (Used for Car Parking) No Car

If yes, Any gas-powered equipment or cans of gasoline/fuels stored? NO

YES NO

7) Type of HVAC System

All (b)(3):CPSA Section 6(b)

8) Primary Type of Fuel

Natural Gas Fuel Oil Kerosene (Electric) All electric

Propane Solar Wood Coal

9) Water Supply

(Public) Well Other _____

10) Sewage

(Public) Septic Leach Field Other _____

11) Attic

Finished (Unfinished)

3. Interior Characteristics

1) Any odors upon entering the building?

(Yes) No

If yes, describe sulfur like burt match

2) Fireplace

Yes (No) br Living room

3) Floors

Hardwood (Carpet) Tile all other

4) Walls

Wall Paper Paint (Skim Coat) orange peel (Textured)

5) Ceiling

Wall Paper Paint Skim Coat (Textured) knockdown

House Address (b)(6)

Page 1/5

MASTER BATH



House Address (b)(6)



House Address (b)(6)



House Address [redacted]



House Address (b)(6)



VOC SAMP FIELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CRSC

Date: 7/30/09

Home Address: (b)(6)

Project#: 16512

Field Person(s): TMM, MAF, WEC

SAMPLE ID	CANISTER ID	FLOW CONTROL ID	GAUGE ID	FLOOR	LOCATION	SAMPLE TYPE	GAUGE PRESSURE START	START TIME	GUAGE PRESSURE END	END TIME	NOTES
99441	AC00897	FC00589			LIVING ROOM	S		928			
99442	AC01257	FC00544			DUPLICATE 99441	D					
99443	AC00297	FC00163			OUTDOORS	S					
99444	AC00214	FC00548			GUEST BED	S					
99445	AC01312	FC00536			MASTER BED	S					
99446	AC01082				BLANK						

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

ACTIVE SAM E FIELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CRSC

Home Address: (b)(6)

Field Person(s): TMH, JMT, WLC

Date: 7/30/09

Project#: 16512

ROTA ID #: R06

SAMPLE ID	FLOOR	LOCATION	TARGET ANALYTE	SAMPLE TYPE	PUMP ID	ROTA READ START	START TIME	ROTA READ END	END TIME	SAMPLE DURATION (MINS)	NOTES
99236		LIVING ROOM	ORGANICS	S	G07	.51	928	.48		201	
99237		DUPLICATE 99236		D	G17	.51		.41		200	
99238		OUTDOORS		S	G16	.51		.37		203	
99239		GUEST BED		S	G09	.50		.37		205	
99240		MASTER BED		S	G15	.50		.39		206	
99241				FB							

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

ACTIVE SAM E FIELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CRSC

Home Address: (b)(6)

Field Person(s): JHM, MAP, WEL

Date: 7/30/09

Project#: 10512

ROTA ID #: R06

SAMPLE ID	FLOOR	LOCATION	TARGET ANALYTE	SAMPLE TYPE	PUMP ID	ROTA READ START	START TIME	ROTA READ END	END TIME	SAMPLE DURATION (MINS)	NOTES
99230		LIVING ROOM	INORGANICS	S	G05	.50	928	.43		201	
99231		DUPLICATE 99230		D	P02	.50		.43		201	
99232		OUTDOORS		S	G04	.52		.38		203	
99233		GUEST BED		S	G11	.51		.40		203	
99234		MASTER BED		S	G14	.50		.43		206	
99235				FB							

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

ACTIVE SAM E FIELD DATA

Page __ of ___

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CRSC

Home Address: (b)(6)

Field Person(s): TMM, MAF, WEG

Date: 7/30/09

Project#: 16512

ROTA ID #: R06

SAMPLE ID	FLOOR	LOCATION	TARGET ANALYTE	SAMPLE TYPE	PUMP ID	ROTA READ START	START TIME	ROTA READ END	END TIME	SAMPLE DURATION (MINS)	NOTES
99242		LIVING ROOM	ALDEHYDE	S	G06	.51	928	.48		200	
99243		DUPLICATE 99242		D	G08	.56		.49		201	
99244		OUTDOORS		S	G10	.51		.40		203	
99245		GUEST ROOM		S	G13	.51		.47		205	100.45
99246		MASTER BED		S	G09	.50		.45		207	98.33
99247				FB							

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

ACTIVE SAM E FIELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CSC

Home Address: (b)(6)

Field Person(s): THM, WC, MAF

Date: 7/30/09

Project#: 16512

ROTA ID #:

SAMPLE ID	FLOOR	LOCATION	TARGET ANALYTE	SAMPLE TYPE	PUMP ID	ROTA READ START	START TIME	ROTA READ END	END TIME	SAMPLE DURATION (MINS)	NOTES
99269		LIVING ROOM	SULFUR	AIR	G16		1551			5	30 SEC GRAB
99270		DUPLICATE 99269					1552				
99271		OUTDOORS					1553				
99272		GUEST BED 1					1554				
99273		MASTER BED					1556				
~~99274~~	THM										

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

XRF SCAN FIELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CRSC

Home Address (b)(6)

Field Person(s): TMM, MAF, WEC

Date: 7/30/09
Project#: 16512

XRF Serial #: 10755
XRF Scan Time 20 Sec

SAMPLE ID	FLOOR	LOCATION	WALL COOR.	SAMPLE LOCATION	SURFACE TYPE	Wall ID	SAMPLE TYPE	TIME	XRF Reading	NOTES
5		LIVING ROOM	S	6 FEET ↑	TEXTURED	LR4	SCAN	944	938	
6		SOCKET	S	18"				945	480	x
7			S	6 FEET				946	651	
8		SOCKET	S	18"		LR4		947	981	x
9			E	6 FEET		LR1		948	330	
10			E	2 FEET				949	1135	
11		DUPLICATE 10	E	2 FEET				950	1155	
12		LIVING ROOM	N	4 FEET		LR2		951	167	ON DETAIL
13			N	4 FEET				952	1148	
14			N	5 FEET		LR5		953	943	
15		SOCKET	~~WN~~	~~18" FEET~~		LR3		954	291	x
16			W	6 FEET				955	378	
17		KITCHEN	N	5 FEET		K3		956	560	
18		SOCKET	N	18"				957	165	x
19			S	6 FEET		K6		958	616	
20		SOCKET	S	18"				959	279	
21			S	5 FEET		K4		1000	243	
22		SOCKET	S	18"				1002	344	
23		DUPLICATE 22	S	18"				1003	348	

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

XRF SCAN FIELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CRSC

Home Address: (b)(6)

Field Person(s): _____

Date: 7/30/09
Project#: 16517

XRF Serial #: 10755
XRF Scan Time _____

SAMPLE ID	FLOOR	LOCATION	WALL COOR.	SAMPLE LOCATION	SURFACE TYPE	Wall ID	SAMPLE TYPE	TIME	XRF Reading	NOTES
24	1	KITCHEN	W	6 FEET	TEXTURED	K3	SCAN	10:06	213	
25		SOCKET *	W	18"				10:07	597	*
26			N	7 FEET		K2		10:08	1160	
27			N	2 FEET				10:09	761	
28			N	3 FEET				10:10	708	
29		SOCKET	N	4 FEET				10:11	315	*
30		DUPLICATE 29	N	4 FEET				10:12	311	
31		GUEST BED 3	E	6 FEET		GB3, 1		10:13	1308	
32			E	2 FEET				10:14	1250	
33			S	6 FEET		GB3, 4		10:15	1205	
34		SOCKET	S	18"				10:16	499	*
35			S	3 FEET				10:17	1304	BLOOD SEAM
36			N	6 FEET		GB3, 2		10:18	1186	ABORTED
37			N	4 FEET				10:20	459	
38			W	4 FEET		GB3, 3		10:21	483	CLOSET
39			W	4 FEET				10:22	932	
40		DUPLICATE 39	W	4 FEET				10:23	911	
41		SOCKET	W	18"				10:24	370	
42		BATHROOM 2	E	4 FEET		BZ, 1		1025	1240	

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

XRF SCAN

THM ~~VISUAL~~ CORROSION INSPECTION FIELD DATA Page ____ of ____

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

Date: 7/30/09

Home Address: (b)(6)

Project#: 16512

Field Person(s): THM, MAF, WEC

SAMPLE ID	FLOOR	LOCATION	WALL COOR.	SAMPLE LOCATION	CORROSION RATING (THM / XRF)	NOTES
43	1	BATHROOM 2, WALL 3	W	4 FEET	1254	TEXTURED
44			W	4 FEET	212	SWITCH
45			W	4 FEET	262	OUTLET X
46		WALL 4	S	5 FEET	613	
47		CORRIDOR, WALL 1	N	5 FEET	243	
48		DUPLICATE	N	5 FEET	262	
49		MASTER BED, WALL 2	N	6 FEET	1228	
50			N	2 FEET	942	PREVIOUS BULK LOCATION X
51			N	18"	1230	OUTLET X
52		WALL 1	E	6 FEET	———	INACCESS
53			E	6 FEET	499	
54			E	18"	579	OUTLET X
55		WALL 4	S	5 FEET	1020	
56			W	5 FEET	1163	
57			W	18"	1237	OUTLET
58			W	6 FEET	236	
59		MASTER BATH, WALL	N	5 FEET	475	
60		1 , WALL	S	4 FEET	450	
61		CLOSET LEFT	W	4 FEET	887	
62			S	4 FEET	214	
63			S	2 FEET	1360	BULK X
64			S	2 FEET	1250	PREVIOUS BULK
65			E	5 FEET	1179	
66		CLOSET RIGHT	W	6 FEET	1151	
67			W	18"	454	OUTLET
68			W	4 FEET	1028	
69			W	3 FEET	312	OUTLET
70			W	3 FEET	558	SWITCH

CORROSION RATING: 0 = No Grounding Wire, 1 = No Corrosion, 2 = Some Corrosion, 3 = Heavy Corrosion

XRF SCAN

VISUAL CORROSION INSPECTION FIELD DATA Page ___ of ___

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

Date: 7/30/09

Home Address: (b)(6)

Project#: 16512

Field Person(s): TMH, MRF, WEC

SAMPLE ID	FLOOR	LOCATION	WALL COOR.	SAMPLE LOCATION	CORROSION RATING XRF THT	NOTES
71	1	DUPLICATE	W	3 FEET	524	TEXTURED
72		MASTER BATH, TOILET	N	5 FEET	366	
73		MASTER BATH	E	4 FEET	182	
74		SHOWER	N	7 FEET	563	
75		HALLWAY	E	4 FEET	1116	
76		OUTLET	E	18"	870	OUTLET X
77			S	4 FEET	315	
78		GUEST ROOM 2	S	6 FEET	1155	
79			S	18"	666	OUTLET
80			S	2 FEET	931	PREVIOUS BOOK X
81			N	18"	464	OUTLET X
82		GUEST	E	4 FEET	1096	
83			N	5 FEET	1121	
84			W	5 FEET	1065	
85			S	18"	324	OUTLET
86		BATHROOM 1	N	6 FEET	1101	
87			W	6 FEET	739	
88			E	7 FEET	1207	
89			E	4 FEET	1104	
90		GUEST ROOM 3	S	4 FEET	166	
91		DUPLICATE 90	S	4 FEET	176	
92			W	6 FEET	1242	
93			W	18"	863	OUTLET X
94			N	5 FEET	235	
95			E	4 FEET	726	
96			W	4 FEET	1195	
97			W	3 FEET	216	SWITCH X
98		DUPLICATE 97	N	3 FEET	247	

CORROSION RATING: 0 = No Grounding Wire, 1 = No Corrosion, 2 = Some Corrosion, 3 = Heavy Corrosion

XRF SCAN

VISUAL CORROSION INSPECTION FIELD DATA

Page ____ of ____

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

ent: CASC

Date: 7/30/09

Home Address: (b)(6)

Project#: 16512

Field Person(s): THH, MAF, WCL

SAMPLE ID	FLOOR	LOCATION	WALL COOR.	SAMPLE LOCATION	CORROSION RATING XRF	NOTES
99	1	LAUNDRY	N	5 FEET	710	TEXTURED
100		|	N	18"	934	OUTLET
101		|	S	6 FEET	1162	
102		|	E	3 FEET	413	SWITCH
103		DUPLICATE 102	E	3 FEET	351	|
104		GARAGE	W	6 FEET	693	
105		|	W	3 FEET	626	OUTLET X
106		|	N	3 FEET	800	
109		Living Rm	-	ceiling	440	
110		Living Rm	-	ceiling	533	
111		kitchen	-	ceiling	MAF 1H	507
112		kitchen	-	ceiling	305	
113		Den	-	ceiling	201	
114		Den	-	ceiling	334	
115		Hall	-	ceiling	269	
116		Bath 2	-	ceiling	238	
117		Guest Bd 3	-	ceiling	267	
118		Guest Bed 3	-	ceiling	314	
119		Hall	-	ceiling	471	
120		Hall	-	ceiling	555	
121		Bathroom	-	ceiling	185	
122		Guest BR 2	-	ceiling	514	
123		Guest BR 2	-	ceiling	309	
124		Guest BR 1	-	ceiling	325	
125		Guest BR 1	-	ceiling	495	
126		Master BR	-	ceiling	502	
127		Master BR	-	ceiling	301	
128		Master BR Hall	-	ceiling	524	

CORROSION RATING: 0 = No Grounding Wire, 1 = No Corrosion, 2 = Some Corrosion, 3 = Heavy Corrosion

XRF

VISUAL CORROSION INSPECTION FIELD DATA

Page ____ of ____

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CBSC

Date: 7/30/09

Home Address: (b)(6)

Project#: 16512

Field Person(s): TMM, MAF, NEC

SAMPLE ID	FLOOR	LOCATION	WALL COOR.	SAMPLE LOCATION	CORROSION RATING (XRF)	NOTES
129		Master Bath	—	Ceiling	151	
130		Master Bath Dup	—	Ceiling	189	
131		Laundry Rm		Ceiling	453	
132		Laundry Rm Dup		Ceiling	199	
133		Garage		ceiling	377	
134		Garage ceiling Dup		Ceiling	323	

CORROSION RATING: 0 = No Grounding Wire, 1 = No Corrosion, 2 = Some Corrosion, 3 = Heavy Corrosion

VISUAL CORROSION INSPECTION FIELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

(b)(6)

Home Address

Date: 7/30/09

Project#: 16512

Field Person(s): MAF / TMM / NEC

SAMPLE ID	FLOOR	LOCATION	WALL COOR.	SAMPLE LOCATION	CORROSION RATING	NOTES
~~KIT 001 / 002~~		~~AHU~~		~~GARAGE~~		
		AHU COIL		GARAGE	2+	
		WATER HEATER		GARAGE	2	HOT + COLD COPPER WATER FITTINGS
		MASTER BATH SINK	FAUCETS -	BRASS LOOKS CORRODED	1-2	
		KITCHEN SINK FAUCET			0-1	
		BATTERY END CAP SPRING -	KITCHEN		1-2	
		WALL ARTWORK -	COPPER/STEEL		2+	NE WALL
		COPPER BOWL -	LR E. WALL		1-2	NOT AS CORRODED AT ~~WOODEN BASE AREA~~
	FRIDGE	WATER HAMMER	ARRESTOR		0	? NO CORROSION SURROUNDED BY PLASTIC AN WRK
	FRIDGE	EXPANSION TUBE			2+	
	NW	BATH SINK LINES			1-2	
	NW	BATH TOILET SHUT OFF	VALVE		0-1	
KIT.	REFRIGERATOR	OUTLET			2	
	KITCHEN/DEN	OUTLET	S		1-2	
		DEN OUTLET	W		2	
		W BEDROOM OUTLET	E		2	
		LR OUTLET	SW		2	
		LR OUTLET	SE		2	
		MASTER BR	SW	OUTLET	2	
		MASTER BATH	SE	OUTLET	2	
		NE BEDROOM	BS	OUTLET	2	
		NNE BEDROOM	W	OUTLET	2	
		HALL OUTLET	E	OUTLET	2	
		LAUNDRY SWITCH OUTLET	E		2	
		GARAGE OUTLET	W		2	

CORROSION RATING: 0 = No Grounding Wire, 1 = No Corrosion, 2 = Some Corrosion, 3 = Heavy Corrosion

~~VISUAL CORROSION INSPECTION FIELD DATA~~ Page ____ of ____

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

BULK — 16 + 2 DUP

...ent: CRSC

Date: 7/20/07

Home Address: (b)(6)

Project#: 16512

Field Person(s): TMH, WEC, MAP

SAMPLE ID	FLOOR	LOCATION	WALL COOR.	SAMPLE LOCATION MAP	CORROSION RATING	NOTES
99249	1	KITCHEN	N	29		
99250			W	25		
99251		LIVING ROOM	S	6		
99252		~~DINING~~	S	8		
99253		DUPLICATE 99252	S	8		
99254		BED ROOM 3	S	34		
99255		BATHROOM 2	W	45		
99256		KITCHEN	N	18		
99257		MASTER BED	N	50		
99258			N	51		
99259			E	54		
99260		MASTER ~~CLOSET~~	S	63		
99261		HALLWAY	E	76		
99262		DUPLICATE 99261	E	76		
99263		GUEST ROOM 2	S	80		
99264			N	81		
99265		GUEST ROOM 1	W	93		
99266			W	97		
99267		GARAGE	W	105		
99268		LAUNDRY	N	100		

CORROSION RATING: 0 = No Grounding Wire, 1 = No Corrosion, 2 = Some Corrosion, 3 = Heavy Corrosion

(b)(6)

Equpt list next week

- CO2 tanks - purchase more? 3 per team?
- Coolers for single shipment / ice paks
- ~~Foil tape~~
- USB adapter for Trakpro download / laptop
- Hobo Software / Cable F

Hour #3 7/30/09

QT 12 reads 990/1000 LR
QT 11 reads 1000/1000 BR meeting
QT 13 QT reads 997/1000 BR2

HOBOS LR S/N 2375360
Meeting BR 2375362
BR2 2375358

073009FL01

PASSIVE SAMPLE FIELD DATA

Page ____ of ____

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

Date: 8/20/09

Home Address (b)(6)

Project#: 16512

Field Person(s): TMM

SAMPLE ID	FLOOR	LOCATION	TARGET ANALYTE	SAMPLE TYPE	START DATE	START TIME	END DATE	END TIME	NOTES
103137		LIVING ROOM	OZONE	S	8/20/09	1235	9/3/09	955	
103138		DUPLICATE	"	D	"	"	"	"	
103139		OUTDOORS	"	S	"	"	"	"	
103140		GUEST	"	"	"	"	"	"	
103141		MASTER	"	"	"	"	"	"	
103142				FB					

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

073009FL01

PASSIVE SAMPLE FIELD DATA

Page ____ of ____

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

Date: 8/20/09

Home Address: (b)(6)

Project#: 16512

Field Person(s): TMM

SAMPLE ID	FLOOR	LOCATION	TARGET ANALYTE	SAMPLE TYPE	START DATE	START TIME	END DATE	END TIME	NOTES
102171		LIVING ROOM	H_2S	S	8/20/09	1235	9/3/09	955	
102172		DUPLICATE		D					
102173		OUTDOORS		S					
102174		GUEST							
102175		MASTER							
102176				FB					

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

073009FL01

PASSIVE SAM.. LE FIELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CFSC

Home Address: (b)(6)

Field Person(s): THM

Date:

Project#: 16512

SAMPLE ID	FLOOR	LOCATION	TARGET ANALYTE	SAMPLE TYPE	START DATE	START TIME	END DATE	END TIME	NOTES
102165		LIVING ROOM	SO_2NO_2HF	S	8/20/09	1235	9/3/09	955	
102166		DUPLICATE	"	D	"	"	"	"	
102167		OUTDOORS	"	S	"	"	"	"	
102168		GUEST	"	"	"	"	"	"	
102169		MASTER	"	"	"	"	"	"	
102170	—	—	—	FB	—	—	—	—	

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

073009FL01

PASSIVE SAM.. _E FIELD DATA

Page ____ of ____

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CRSC

Date: 8/20/09

Home Address: (b)(6)

Project#: 16512

Field Person(s): TMM

SAMPLE ID	FLOOR	LOCATION	TARGET ANALYTE	SAMPLE TYPE	START DATE	START TIME	END DATE	END TIME	NOTES
102159		LIVING ROOM	ALDEHYDE	S	8/20/09	1135	9/3/09	955	
102160		DUPLICATE		D					
102161		OUTDOORS		S					
102162		GUEST							
102163		MASTER							
102164				FB					

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

073009FL01

PASSIVE SAMPLE FIELD DATA

Page ____ of ____

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

Date: 8/20/09

Home Address: (b)(6)

Project#: 16512

Field Person(s): TM

SAMPLE ID	FLOOR	LOCATION	TARGET ANALYTE	SAMPLE TYPE	START DATE	START TIME	END DATE	END TIME	NOTES
103143		LIVING ROOM	COUPON	S	8/20/09	1235	9/3/09	955	
103144		DUPLICATE	"	D	"	"	"	"	
103145		OUTDOORS		S					
103146		SUPPLY		"					
103147		MASTER		"					

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

PASSIVE SAMPLE FIELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CDSC

Home Address: (b)(6)

Field Person(s): TMH, WEC, MAF

Date: 7/30/09

Project#: 16512

SAMPLE ID	FLOOR	LOCATION	TARGET ANALYTE	SAMPLE TYPE	START DATE	START TIME	END DATE	END TIME	NOTES
99279		LIVING ROOM	CO/FORM	S	7/30/09	15[35]	8/20		
99280		DUPLICATE @ 99279		D		15[35]			
99281		OUTDOORS		S		15[36]			
99282		GUEST ROOM 1		S		15[37]			
99283		MASTER BED		S		15[38]			
99284		BLANK							
99286		SUPPLY LIVING ROOM	CO/FORM	S		16[06]			

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

PHOTO FIELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

Date: 7/30/09

Home Address: (b)(6)

Project#: 16512

Field Person(s): MAF/TMM/WEC

Camera ID: _____

PHOTO NO.	FLOOR	LOCATION	NOTES
100-0001 -0009		AHU - GARAGE	
0010		WATER HEATER - GARAGE	
0011-14		GARAGE - GENERAL SPACE	SIDE WALLS MASONRY
15-21		EXTERIOR OF HOUSE	
22-25		LIVING ROOM	
26-30		KITCHEN / DEN	
31-32		NW BATH	
33-35		NW BEDROOM	
36-42		MASTER SUITE	
43-44		LAUNDRY	
45-47		NE BR	
48-49		NE BATH	
50-52		N CENTRAL BR	
53		MASTER BATH SINK RIGHT	
54		" " " LEFT	
55-56		KITCHEN SINK - WATER HAMMER ARRESTOR FAUCET	
57		BATTERY CAP - SPRING - KITCHEN	
58		WALL ARTWORK - COPPER / STEEL	NE WALL
59/60		CU BOWL	NOT AS CORRODED AT BASE
61	KITCHEN	FRIDGE EXPANSION TUBE	2+ CORRODED
62	KITCHEN	FRIDGE WALL WATER HAMMER ARRESTOR / SHUT OFF VALVE	NO CORROSION
63/64		NW BATH SINK LINES	
65		NW BATH TOILET SHUTOFF VALVE	
66-69		GARAGE ATTIC	
70-71		KITCHEN REFRIGERATOR OUTLET	
72		GUEST BED, SKIM COAT THICK OUTLET	