ENVIRONMENTAL
HEALTH & ENGINEERING

Environmental Health & Engineering, Inc.

117 Fourth Avenue
Needham, MA
02494-2725

TEL 800-825-5343
781-247-4300
FAX 781-247-4305

www.eheinc.com

Home Inspection/Questionnair Form

House ID 081709fl02

Date 8/17/09

Field Technician(s) WEC/ADAM/FEMI

House Address (b)(6) PARKLAND, FL

DAN & DONNA POLISEO

General Weather Description SUNNY, HUMID, ≈90°F

1. Questionnaire

1) Interviewed home owner (YES) NO

2) Age of the House (years)

MOVED IN 2007, BUILT IN 2006

3) Estimated Floor Area (sqft)

2700

4) Was as there any demo's to the house?

YES (NO)

If YES, when was it done? Please Explain.

5) Has there been any fire in the building?

YES (NO)

If YES, when did it happen? Please Explain.

6) Any pesticides/herbicides been applied around the building or in the yard?

(YES) NO

If YES, when was it applied? Please list the type of chemicals used.

Spray for ants once per month, last done ≈ 1 wk ago

Round up weed/grass killer

Ortho home defense bug killer

7) Has there been any recent painting/staining done in the home?

(YES) NO

If YES, when, where and what type of paint/stain was used?

all Rooms repainted except 1 BR (not doors/trim)

8) Has any work been done on the AC system since construction?

(YES) NO

If YES, please describe?

ON THIRD EVAP COIL, DRAIN PAN has cracked, replaced several times

9) Are all the AC system components original?

YES (NO)

If NO, please describe?

3rd Evap has been dipped in a protective Coating - green seems to be helping prevent further Corrosion.

10) What is the age of your refrigerator?

NEW '06 - Same as house years

11) Has any piping been replaced in the home?

YES (NO)

If YES, please describe?

2. Building Characteristics

1) Residential Type (Single/Multi-Family Building) If multi-family, how many units?

_____.

2) Number of rooms

4 BR, 3 BATHS 8 TOTAL.

3) Above grade Construction

Wood Frame Concrete Stone Brick Other CMU

4) Basement

Full Crawlspace Slab Other _____

5) Foundation

Concrete Cinder Block Stone Other SLAB

6) Garage

YES NO

If YES, Attached Detached

If YES, Used for Car Parking? YES NO

If YES, Any gas-powered equipment or cans of gasoline/fuels stored? YES NO LAWN MOWER, WEEDWACKER CAN OF GAS

7) Type of HVAC System

DX split system, Elect resistive heating.

Mal(b)(3):CPSA Section 6(b)C Model FK4DNB006 Condenser Model 24ABR360A330 5-TON

8) Typ ly)

Natural Gas Fuel Oil Kerosene Electric

Propane Solar Wood Coal

9) Water Supply

Public Well Other _____

10) Sewage

Public Septic Leach Field Other _____

11) Attic

Finished Unfinished

3. Interior Characteristics

1) Any odors upon entering the building?

YES (circled) NO

If YES, describe SULFUR-LIKE

2) Fireplace

YES NO (circled)

3) Floors (circle all that apply)

Hardwood Carpet (circled) Ceramic Tile (circled) Vinyl Tile

Unfinished Wood Unfinished Concrete Other MARBLE

4) Walls (circle all that apply)

Wall Paper Paint Skim Coat Textured (circled)

Wood or Wood Paneling Other _____

5) Ceiling (circle all that apply)

Wall Paper Paint (circled) Skim Coat Textured (circled)

Wood or Wood Paneling Other _____

House Address (b)(6)



House Address (b)(6)

House Address (b)(6)



House Address (b)(6)



House Address (b)(6)

Page 5/5



ACTIVE SAM. E FIELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: (b)(6) SC

Home Address: (b)(6)

Field Person(s): _____

Date: 08/17/2009

Project#: 16512

ROTA ID #: _____

SAMPLE ID	FLOOR	LOCATION	TARGET ANALYTE	SAMPLE TYPE	PUMP ID	ROTA READ START	START TIME	ROTA READ END	END TIME	SAMPLE DURATION (MINS)	NOTES
100749		LIVING	Organic		64	.51	10:04	.45	13:29	203	97.44 L
100750		DUPLICATE			613	.43		.35		204	~~DUPLICATE~~ 79.56 L
100751		OUTDOOR			617	.50		.44		200	94 L
100752		MASTER			608	.51		.49		205	102.50 L
100753		GUEST			614	.50		.44		207	97.29 L
100754											

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

ACTIVE SAM. Ξ FIELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

Home Address: (b)(6)

Field Person(s): _____

Date: 08/17/2009

Project#: 16512

ROTA ID #: _____

SAMPLE ID	FLOOR	LOCATION	TARGET ANALYTE	SAMPLE TYPE	PUMP ID	ROTA READ START	START TIME	ROTA READ END	END TIME	SAMPLE DURATION (MINS)	NOTES
100743		LIVING	Inorganic		610	.51	10:04	.44	13:29	204	96.9 L
100744		DUPLICATE			P02	.51		.50		202	102.01 L
100745		OUTDOOR			602	.52		.49		201	100.51 L
100746		MASTER			615	.51		.44		205	Low battery 97.38 L
100747		GUEST			~~FB~~	.50		.45		208	98.8 L
100748					FB						

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

ACTIVE SAM. E FIELD DATA

Page __ f ____

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

Home Address: (b)(6)

Field Person(s): _____

Date: 08/17/2009
Project#: 16512

ROTA ID #: _____

SAMPLE ID	FLOOR	LOCATION	TARGET ANALYTE	SAMPLE TYPE	PUMP ID	ROTA READ START	START TIME	ROTA READ END	END TIME	SAMPLE DURATION (MINS)	NOTES
100737		Living	Aldehyde		607	.51	10:04	.51	13:29	202	103.02 L
100738		Duplicate			616	.52		.50		202	103.02 L
100739		Outdoor			605	.50	.46	.46		201	96.48 L
100740		Master			606	.51		.51		205	104.55 L
100741		Guest			611	.52		.49		207	104.54 L
100742	—	Field Blank			FB						

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

ACTIVE SAM Ξ FIELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

Home Address: (b)(6)

Field Person(s): SAG, WCE, OTA

Date: 8/17/09

Project#: 16512

ROTA ID #: G01

SAMPLE ID	FLOOR	LOCATION	TARGET ANALYTE	SAMPLE TYPE	PUMP ID	ROTA READ START	START TIME	ROTA READ END	END TIME	SAMPLE DURATION (MINS)	NOTES
100805		LIVING	Sulfur				16:41				
100806		DUPLICATE	↓				16:43				
100807		OUTDOOR	↓				16:45				
100808		MASTER	↓				16:48				
100809		GUEST	↓				16:52				

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

HOUSEID: 081709FL02

XRF SCAN FIELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

Home Address: (b)(6)

Field Person(s): WEC, SAG, OTA

Date: 08/17/2009
Project#: 16512

XRF Serial #: 10755
XRF Scan Time 20 Sec

LOCATION ID	FLOOR	LOCATION	WALL COOR.	SAMPLE LOCATION	SURFACE TYPE	Wall ID	SAMPLE TYPE	SAMPLE SIZE	TIME	XRF Reading	NOTES
#2	1	DINING Room	S	6ft	Tatured		Scan		10 18	770	
#3	1	"	S	18in					10 19	152	
#4	1	"	S	4ft					10 19	187	
#5	1	"	S	18in					10 20	123	
#6	1	"	E	6ft					10 20	114	
*#7	1	"	E	18in					10 21	1042	
#8	1	Dup of #7	E	18in					1023	770	
#9	1	Dining Room	N	4ft					10 24	126	
#10	1	"	N	18in					10 24	871	
#11	1	"	N	18in					10 25	529	
#12	1	Kitchen	S	6ft					10 26	444	
#13	1	Kitchen	W	4ft					1027	152	
#14	1	Eating Area	S	18in					10 28	817	
#15	1	"	W	6ft					10 29	170	
*#16	1	"	W	18in					10 29	705	
#17	1	Dup of #17	W	18in					10 30	695	
#18	1	Eating Area	N	4ft					10 31	132	
#19	1	"	N	18in					10 31	211	
#20	1	Family room	W	6ft					10 32	1011	

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

XRF SCAN FIELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

Home Address: (b)(6)

Field Person(s): MEC, SAG, DTA

Date: 08/17/2009
Project#: 16512

XRF Serial #: 10755
XRF Scan Time

LOCATION ID	FLOOR	LOCATION	WALL COOR.	SAMPLE LOCATION	SURFACE TYPE	Wall ID	SAMPLE TYPE	SAMPLE SIZE	TIME	XRF Reading	NOTES
#21	1	Family room	W	2ft	Textured		Scan		1033	1032	
#22	1	"	W	4ft					1034	613	
#23	1	"	W	18in					1035	149	
#24	1	"	N	18in					1036	159	
#25	1	"	N	6ft					1036	481	
*#26	1	"	N	18in					1037	144	
#27	1	"	E	6ft					1038	1147	
#28	1	"	E	4ft					1039	521	
#29	1	Dup of #28	E	4ft					1039	523	
*#30	1	Family room	E	18in					1040	731	
#31	1	kitchen Pantry	S	2ft					1042	695	
#32	1	Living Room	S	48in					1044	104	
#33	1	"	S	2ft					1045	293	
#34	1	"	W	6ft					1046	1362	
#35	1	"	W	2ft					1046	1256	
#36	1	Dup of #35	W	2ft					1047	1293	
#37	1	LR (Passage to Master BR)	N	48in					1048	172	
#38	1	Living room	W	6ft					1049	1441	
*#39	1	"	W	18in					1050	1277	

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

XRF SCAN FIELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

Home Address: (b)(6)

Field Person(s): WEC, SAG, OTA

Date: 08/17/2009
Project#: 16512
XRF Serial #: 10755
XRF Scan Time

LOCATION ID	FLOOR	LOCATION	WALL COOR.	SAMPLE LOCATION	SURFACE TYPE	Wall ID	SAMPLE TYPE	SAMPLE SIZE	TIME	XRF Reading	NOTES
#40	1	Family room	N	48in	Textured		Scan		10 51	111	
*#41	1	"	N	18in					1052	1021	
#42	1	"	E	6ft					1053	445	
#43*	1	"	E	48in					1054	146	
#44	1	Foyer	E	6ft					1054	638	
#45*	1	"	E	18in					1055	141	
#46	1	"	W	6ft					1056	657	
#47*	1	"	W	18in					1058	932	
#48	1	Dup of #47	W	18in					1059	904	
#49	1	foyer	W	4ft					1100	693	
#50*	1	Master Bedroom	S	48in					1102	134	
*#51	1	"	S	18in					1103	138	
#52	1	"	W	6ft					1103	1087	
#53*	1	"	W	18in					1105	139	
#54	1	"	W	6ft					1106	570	
#55*	1	"	W	18in					1106	139	
#56	1	"	N	4ft					1107	152	
#57	1	"	E	6ft					1108	925	
#58	1	Dup of 57	E	6ft					1109	1251	

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

XRF SCAN FIELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

Home Address: (b)(6)

Field Person(s): WEC, SAG, DTA

Date: 08/17/2009
Project#: 16512

XRF Serial #: 1075S
XRF Scan Time

LOCATION ID	FLOOR	LOCATION	WALL COOR.	SAMPLE LOCATION	SURFACE TYPE	Wall ID	SAMPLE TYPE	SAMPLE SIZE	TIME	XRF Reading	NOTES
59	1	Master Bedroom	E	18in	Textured		Scan		11:09	168	
60	1	"	E	48in	"		"		11:10	134	
61*	1	"	N	18in	"		"		11:11	1031	
62	1	"	E	~~6ft~~ 48in	"		"		11:12	147	
63	1	"	E	6ft	"		"		11:12	1173	
64	1	"	S	6ft	"		"		11:13	998	
65	1	"	S	18in	"		"		11:14	178	
66	1	Master Bedroom Closet (W)	E	2ft	"		"		11:16	624	
67	1	"	S	4ft	"		"		11:16	148	
68	1	"	W	2ft	"		"		11:17	463	
69	1	~~Mas~~ "	N	6ft	"		"		11:18	433	
70	1	Master Bedroom Closet (E)	W	48in	"		"		11:19	792	
71	1	Dup of 70	W	48in	"		"		11:19	740	
72	1	Master Bedroom Closet (E)	N	2ft	"		"		11:20	686	
73	1	"	E	4ft	"		"		11:21	723	
74	1	"	S	2ft	"		"		11:21	904	
75	1	Master BR Closet Passage	W	6ft	"		"		11:22	847	
76	1	"	W	18in	"		"		11:23	156	
77	1	Master Bathroom	W	6ft	Wallpaper		"		11:24	1115	

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

XRF SCAN FIELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

Home Address: (b)(6)

Field Person(s): WEC, SAG, OTA

Date: 08/17/2009
Project#: 16512

XRF Serial #: 10755
XRF Scan Time

LOCATION ID	FLOOR	LOCATION	WALL COOR.	SAMPLE LOCATION	SURFACE TYPE	Wall ID	SAMPLE TYPE	SAMPLE SIZE	TIME	XRF Reading	NOTES
78	1	Master Bathroom	W	48in	Wallpaper		Scan		11:24	134	
79	1	"	N	2ft	"				11:25	119	
80	1	"	E	48in	"				11:29	236	
81	1	Dup of 80	E	48in	"				11:29	231	
82	1	Master Bathroom	E	4ft	"				11:30	1312	
83	1	"	S	4ft	"				11:31	1007	
84	1	Master Bathroom (Toilet)	W	48in	"				11:32	241	
85	1	"	S	6ft					11:32	1141	
86	1	"	E	2ft	"				11:33	1272	
87	1	Laundry	S	48in	Textured				11:36	285	
88	1	"	E	48in	"				11:36	181	
89	1	"	N	6ft	"				11:37	767	
90	1	"	N	2ft	"				11:38	246	
91	1	"	W	6ft					11:38	697	
92	1	"	W	2ft					11:39	1055	
93	1	~~Hall~~ Hallway ~~passageway~~ by ~~Laund~~ laundry	N	48in					11:39	128	
Dup of 93 94		Hallway by laundry	N	48in					11:40	139	Dup of 93
95*	1	"	N	18in					11:41	145	
96*	1	Bedroom 2	E	48in					11:42	174	

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

XRF SCAN FIELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

Home Address: (b)(6)

Field Person(s): WEC, SAG, DTA

Date: 08/17/2009
Project#: 16512

XRF Serial #: 10755
XRF Scan Time

LOCATION ID	FLOOR	LOCATION	WALL COOR.	SAMPLE LOCATION	SURFACE TYPE	Wall ID	SAMPLE TYPE	SAMPLE SIZE	TIME	XRF Reading	NOTES
97	1	Bedroom 2	S	6ft	Textured		Scan		1143	769	
98*	1	"	S	18in	"				1144	165	
99	1	"	E	4ft	"				1144	638	
100	1	"	E	2ft	"				1145	1203	
101	1	"	N	6ft	"				1146	143	
102	1	Dup of 101	N	6ft	"				1147	124	
103	1	Bedroom 2 closet	N	6ft	"				1148	1021	
104	1	(Bedroom 2) Bath 2	N	48in	Wallpaper				1149	149	
105	1	"	W	6ft	"				1150	679	
106	1	"	S	4ft	"				1151	1825	
107	1	"	N	48in	"				1151	138	
108	1	"	W	2ft	"				1152	140	
109	1	"	S	7ft	"				1153	146	
110	1	"	E	4ft	"				1154	1142	
111	1	Bedroom 3	N	48in	Textured				1155	129	
112*	1	"	N	18in	"				1156	935	
113	1	Dup of 112	N	18in	"				1156	888	
114	1	Bedroom 3	N	6ft	"				1157	303	
115	1	"	N	18in	"				1158	730	

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

XRF SCAN FIELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

Home Address: (b)(6)

Field Person(s): WEC, SAG, OTA

Date: 08/17/2009
Project#: 16512

XRF Serial #: 10755
XRF Scan Time

LOCATION ID	FLOOR	LOCATION	WALL COOR.	SAMPLE LOCATION	SURFACE TYPE	Wall ID	SAMPLE TYPE	SAMPLE SIZE	TIME	XRF Reading	NOTES
116	1	Bedroom 3	E	6ft	Textured		Scan		11:59	204	
117*	1	"	E	18in	"				12:00	648	
118	1	"	E	18in	"				12:01	1004	
119	1	"	S	6ft	"				12:02	140	
120	1	"	S	2ft	"				12:02	945	
121	1	Bedroom 3 Closet	W	4ft	"				12:03	545	
122	1	Dup of 121	W	4ft	"				12:04	540	
123	1	Hallway by Bedroom 3	W	6ft	"				12:07	691	
124*	1	"	W	18in	"				12:08	1090	
125	1	~~Bedroom~~ Bath 3	W	6ft	Wallpaper				12:11	1128	
126	1	"	W	48in	"				12:12	205	
127	1	"	N	6ft	"				12:13	192	
128	1	"	N	2ft	"				12:13	332	
129	1	"	E	7ft	"				12:14	227	
130	1	"	S	4ft	"				12:16	716	
131	1	Garage	N	6ft	Textured				12:17	175	
132	1	"	N	48in	"				12:17	525	
133	1	Dup of 132	N	48in	"				12:18	588	
134	1	Bedroom 4	S	6ft	"				12:19	803	

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

XRF SCAN FIELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

Home Address: (b)(6)

Field Person(s): WEC, SAG, DTA

Date: 08/17/2009
Project#: 16512

XRF Serial #: 10755
XRF Scan Time

LOCATION ID	FLOOR	LOCATION	WALL COOR.	SAMPLE LOCATION	SURFACE TYPE	Wall ID	SAMPLE TYPE	SAMPLE SIZE	TIME	XRF Reading	NOTES
135*	1	Bedroom 4	S	18in	Textured		Scan		1219	231	
136	1	"	S	4ft	"				1220	939	
137	1	"	E	6ft	"				1221	170	
138	1	"	E	18in	"				1221	186	
139	1	"	N	6ft	"				1222	652	
140	1	"	N	18in	"				1222	284	
141	1	Dup of 140	N	18in	"				1223	288	
142	1	Bedroom 4	W	6ft	"				1225	556	
143	1	"	W	48in	"				1225	126	
144	1	Closet (Bedroom 4)	N	4ft	"				1226	1204	
145	1	"	N	2ft	"				1227	851	
146	1	Dup of 145	N	2ft	"				1228	735	
		~~Passageway b/w Mstr BR closets~~							~~1245~~	~~423~~	
147	1	~~Ceiling~~ (Passageway b/w BR closets)	C	Ceiling	"				1245	423	
148	1	Master Bath	C	Ceiling (west)	"				1247	133	
149	1	"	C	Ceiling (east)	"				1248	140	
150	1	Dup of 149	C	"	"				1248	155	
151	1	Hallway by laundry	C	Ceiling	"				1250	465	
152	1	Laundry	C	Ceiling	"				1251	184	

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

XRF SCAN FIELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: EPS C

Home Address: (b)(6)

Field Person(s): WEC, SAG, OTA

Date: 08/17/2009
Project#: 16512

XRF Serial #: 10755
XRF Scan Time

LOCATION ID	FLOOR	LOCATION	WALL COOR.	SAMPLE LOCATION	SURFACE TYPE	Wall ID	SAMPLE TYPE	SAMPLE SIZE	TIME	XRF Reading	NOTES
153	1	Hallway by laundry	C	Ceiling	Textured		Scan		1252	245	
154	1	Bath 2	C	"					1254	538	
155	1	Bedroom 2 (south)	C	"					1255	570	
156	1	Bedroom 2 (north)	C	"					1256	464	
157	1	Bath 3	C	"					1258	395	
158	1	Bedroom 4	C	"					100	426	
159	1	Dup of 158	C	"					101	338	
160	1	Bedroom 4	C	"					101	173	
161	1	Garage (west)	C	"					103	482	
162	1	" (east)	C	"					105	479	

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

VISUAL CORROSION INSPECTION FIELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

0 = NO GND WIRE
1 = NO CORROSION
2 = SOME CORROSION
3 = HEAVY CORROSION

Client: CPSC

Date: 08/17/2009

Home Address: (b)(6)

Project#: 1651.2

Field Person(s): _____

LOCATION ID	FLOOR	LOCATION	WALL COOR.	SAMPLE LOCATION	CORROSION RATING	NOTES
	1	GARAGE		AHU COIL	1-2	EVAP COIL DIPPED W/ PROTECTIVE COATING 5/09
		GARAGE		WATER HEATER FITTINGS	1	BRASS/PLASTIC
		GARAGE		AHU LIQUID LINE	1-2	LOOKS NORMAL
		MASTER BATH		SINK FAUCET	2-3	BRASS - DARK SPOTS
		MASTER BATH		TOILET SHUTOFF	1	DIRTY BUT LOOKS OK
		KITCHEN SINK		CU HAMMER ARRESTOR	1	
		KITCHEN SINK		LINES-FAUCET	1-2	LOOKS NORMAL
		KITCHEN SINK		SHUTOFF VALVE	1	CHROME
		BATH 3 SINK FAUCET		BRASS	2-3	BLACKENED IN AREAS
		LAUNDRY SHUTOFF/ARRESTORS		CU/BRASS	1-2	NORMAL
		LAUNDRY - DRYER OUTLET			1	NORMAL
		DINING RM. OUTLET		#7	2-3	
		KITCHEN OUTLET		#30	2-3	
		FAMILY RM. OUTLET		#26	2-3	
		KITCHEN OUTLET		#16	2-3	
		LIVING ROOM OUTLET		#41	3	
		LIVINGROOM SW.		#43	3	
		FOYER OUTLET		#47	3	
		FOYER OUTLET		#45	3	
		MASTER BR OUTLET		#61	2-3	
		MASTER B R SW.		#50	3	
		MASTER BATH SW		#84	3	
		BR #2 OUTLET		#98	2-3	
		BATH 2 SWITCH		#107	3	
		HALLWAY OUTLET		#95	3	
		LAUNDRY SW.		#87	3	
		BR #3 OUTLET		#117	2-3	
		BR 4 SW.		#143	3	

CORROSION RATING: 0 = No Grounding Wire, 1 = No Corrosion, 2 = Some Corrosion, 3 = Heavy Corrosion

GARAGE OUTLET #132 1 NORMAL

VISUAL CORROSION INSPECTION FIELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

Date: 08/17/2009

Home Address: (b)(6)

Project#: 16512

Field Person(s):

LOCATION ID	FLOOR	LOCATION	WALL COOR.	SAMPLE LOCATION	CORROSION RATING	NOTES
		LR OUTLET		#39	3	
		PHOTO FRAME			2-3	PLATING CORRODING

BULK SAMPLE FIELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

Date: 08/17/2009

Home Address: (b)(6)

Project#: 16512

Field Person(s):

SAMPLE ID	FLOOR	LOCATION	WALL COOR.	LOCATION ID (SAME AS XRF LOG)	NOTES
100755	1	Dining room (7)	E	7	
100756	1	Eating area (16)	W	16	
100757	1	Family room (26)	N	26	
100758	1	Family room (30)	E	30	
100759	1	Living room (35)	W	39	
100760	1	Living room (39)	W	39	Duplicate of 100759
100761	1	Living room (41)	N	41	
100762	1	Living room (43)	E	43	
100763	1	Foyer (45)	E	45	
100764	1	Foyer (47)	W	47	
100765	1	Master BR (50)	S	50	
100766	1	Master BR (61)	N	61	
100767	1	Master Bathroom (toilet) (84)	W	84	
100768	1	Laundry 87	S	87	
100769	1	Hallway by Laundry (95)	N	95	
100770	1	Bedroom 2 (98)	S	98	
100771	1	Bath 2 (107)	N	107	
100772	1	Bedroom 3 (117)	E	117	
100773	1	Bedroom 4	~~S~~W	~~134~~ 143	
100774	1	Garage	N	132	Dup
100775	1	Garage	N	132	Duplicate of 100774
100810	1	Bedroom #4 Closet	N	8×8 Bulk	

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

QT / HOBO

~~VISUAL CORROSION INSPECTION~~ FIELD DATA Page ____ of ____

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

Date: 08/17/2009

Home Address: (b)(6)

Project#: 16512

Field Person(s):

LOCATION ID	FLOOR	LOCATION	WALL COOR.	SAMPLE LOCATION	CORROSION RATING	NOTES
		LR HOBO		S/N 2415787		
		LR QTRAK 11				
		MASTER BR HOBO		2415788		
		QTRAK 12				
		BR4 HOBO		2415789		
		BR4 QT		ASHEAD R11370		

CORROSION RATING: 0 = No Grounding Wire, 1 = No Corrosion, 2 = Some Corrosion, 3 = Heavy Corrosion

ID: 081709FL02

PASSIVE SAMPLE FIELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

Home Address: (b)(6)

Field Person(s): WEC, SAG, OTA

Date: 8/17/09

Project#: 16512

SAMPLE ID	FLOOR	LOCATION	TARGET ANALYTE	SAMPLE TYPE	START DATE	START TIME	END DATE	END TIME	NOTES
100782	1	LIVING ROOM	Aldehyde	S	8/17/09	5:25	9/1/09	8:15	
100783	1	DUPLICATE		D					
100784	1	OUTDOOR		S					
100785	1	MASTER		〃					
100786	1	GUEST		〃			〃	〃	
100787	1	Field Blank	〃	FB	〃	〃			

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

ID: 081709FL02

PASSIVE SAMPLE FIELD DATA

Page ___ of ___

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

Home Address: (b)(6)

Field Person(s): WEE, SAG, OTA

Date: 8/17/09

Project#: 16512

SAMPLE ID	FLOOR	LOCATION	TARGET ANALYTE	SAMPLE TYPE	START DATE	START TIME	END DATE	END TIME	NOTES
100794		LIVING ROOM	H_2S	S	8/17/09	17:25	8/18/09	8:15	
100795		DUPLICATE		D					
100796		OUTDOOR		S					
100797		MASTER							
100798		GUEST							
100799		Field Blank		FB					

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

ID:081709FL02

PASSIVE SAMPLE FIELD DATA

Page ___ of ___

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

Home Address: (b)(6)

Field Person(s): WEC, SAB, OTA

Date: 8/17/09

Project#: 16512

SAMPLE ID	FLOOR	LOCATION	TARGET ANALYTE	SAMPLE TYPE	START DATE	START TIME	END DATE	END TIME	NOTES
100776	1	LIVING	O_3	S	8/17/09	5:25	9/1/09	815	
100777	1	DUPLICATE		D					
100778	1	OUTDOOR		S					
100779	1	MASTER		〃					
100780	1	GUEST		〃			〃	〃	
100781	1	Field Blank	〃	FB	〃	〃			

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

ID: 081709FL02

PASSIVE SAMPLE FIELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

Home Address: (b)(6)

Field Person(s): WEC, SAG, OTA

Date: 8/17/09

Project#: 16512

SAMPLE ID	FLOOR	LOCATION	TARGET ANALYTE	SAMPLE TYPE	START DATE	START TIME	END DATE	END TIME	NOTES
100788	1	LIVING ROOM	SO_2 NO_2 HF	S	8/17/09	17:25	9/1/09	815	
100789	1	DUPLICATE		D					
100790	1	OUTDOOR		S					
100791	1	MASTER							
100792	1	GUEST							
100793		Field Blank		FB					

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

ID: 081709FL02

PASSIVE SAMPLE FIELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

Home Address: (b)(6)

Field Person(s): WEC, SAG, OTA

Date: 8/17/09

Project#: 16512

SAMPLE ID	FLOOR	LOCATION	TARGET ANALYTE	SAMPLE TYPE	START DATE	START TIME	END DATE	END TIME	NOTES
100800		LIVING ROOM	Coupon	S	8/17/09	15:56	9/1/09	8[illegible]	
100801		OUTDOOR				15:57			
100802		MASTER				16:00			
100803		GUEST				16:00			
100804		SUPPLY				16:04			

SAMPLE TYPES: S = Sample, D = Duplicate, FB = Field Blank, MB = Media Blank

PHOTO FIELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

Date: 8/17/09

Home Address: (b)(6)

Project#: 16512

Field Person(s): Wee / Adam / Fermi

Camera ID: ECAMP22

PHOTO NO.	FLOOR	LOCATION	NOTES
100-0070-0078		AHU - GARAGE	
79-84		OUTSIDE - GENERAL	
85		PESTICIDE BOTTLES IN YARD	
86-90		CONDENSER UNIT	
91-92		ENTRYWAY - OUTSIDE	
93-97		FOYER	
98-102		LIVING ROOM / DINING ROOM	
103-107		KITCHEN / FAMILY ROOM	
108-114		MASTER SUITE	
115		HALLWAY TO BR 2/3/LAUNDRY	
116		LAUNDRY	
117-120		BR 2	
121		BATH 2	
122-123		BR 3	
124		BATH 3	
125-127		BR 4	
128-132		GARAGE	
132		WATER HEATER - GARAGE	
133-134		AHU LINE	
135		MASTER BATH FAUCET - BRASS	
136		MASTER BATH TOILET SHUTOFF	
		[BUILT IN FRIDGE - CAN'T CHECK]	
137		KITCHEN SINK SUPPLY HAMMER ARRESTOR - CU	
138		KITCHEN SINK CU LINES - FAUCET	
139		KITCHEN SINK SHUTOFF - CHROME	
140		BATH 3 FAUCET - BRASS	
141		LAUNDRY SHUTOFF VALVES	
142		LAUNDRY - DRYER RECEPTACLE	

PHOTO FIELD DATA

Environmental Health & Engineering, Inc.
117 Fourth Avenue, Needham, MA 02494
TEL: (781) 247-4300
FAX: (781) 247-4305

Client: CPSC

Date: 8/17/09

Home Address: (b)(6)

Project#: 16512

Field Person(s): WEC / ADAM / FEEMI

Camera ID: ECAMP 22

PHOTO NO.	FLOOR	LOCATION	NOTES
143-144	1	DR OUTLET #7	
145		KITCHEN OUTLET #30	
146		LR # 41	
147		LR # 43	
148		HALLWAY OUTLET # 95	
149		PHOTO FRAME #150	