

**U.S. CONSUMER PRODUCT SAFETY COMMISSION
LOG OF TELEPHONE CALL**

RECEIVED
6/18/12
NO. 100-111812
PRODUCT IDENTIFIED
ACCEPTED BY DIVISION
REL. TO REG. ADMIN. PROC. G
WITH PORTIONS REMOVED: _____

SUBJECT: Call with Chairman Tenenbaum and Michael Dwyer, JPMA Executive Director regarding CPSIA §104: Safety Standard for Play Yards

DATE OF TELEPHONE CALL: June 13, 2012

LOG ENTRY SOURCE: Dottie Lee

DATE OF LOG ENTRY: June 13, 2012

LOCATION: Phone Call

CPSC PARTICIPANT(S): Chairman Tenenbaum

NON-CPSC PARTICIPANT(S): Michael Dwyer, JPMA Executive Director

SUMMARY OF TELEPHONE CALL: Chairman Tenenbaum called Michael Dwyer to discuss his letter dated June 13, 2012, regarding CPSIA §104: Safety Standard for Play Yards, which was scheduled for a Commission Briefing on June 13, 2012. Mr. Dwyer writes in his letter, "[...] JPMA strongly suggests that the new Bassinet/Cradle Accessories Missing Key Structural Elements requirement not be included in the final rule until it is subject to adequate notice with an opportunity for comment and it is established as appropriate based upon a strong, reasonable evidentiary record."