

CPSC FOIA 19-F-00215

Production Part II of III

pp 256-515 of 765

DRAFT – FOR OFFICIAL USE ONLY

Attachment 1

Mold Assessment for Fisher Price PSA

I. Background

Mold is a fungus that is ubiquitously found in both indoor and outdoor environments. The number of species of fungi is unknown; however, it is estimated to be in the range of tens of thousands to upwards of hundreds of thousands¹. Common mold species found in homes are Cladosporium, Penicillium, Alternaria, and Aspergillus. These fungal species are considered opportunistic fungi, in that if there is sufficient moisture and oxygen, these species can grow on any organic substance^{2, 3}.

Mold exposure has been associated with health effects, including allergic reactions, asthma, and other respiratory issues³. Some people may react to mold and experience nasal stuffiness, eye and skin irritation, and wheezing. More severe reactions include shortness of breath and fever. Those individuals who are immuno-compromised and/or have chronic lung diseases are at increased risk for opportunistic infections upon mold exposure⁴. Some molds produce mycotoxins, which are cytotoxic or have other toxic properties¹. Stachybotrys, the species classically thought of as “toxic mold”, can be found in buildings and homes, although to a lesser extent than Cladosporium, Penicillium, Alternaria, and Aspergillus⁴. In addition, mold cell walls contain β -D-glycans which have inflammatory properties, and mold spore and mycelia fragments contain allergens⁵.

II. Discussion

A. Review Reports

A review by the Institute of Medicine (IOM) in 2004, found associations between two risk factors, exposure to indoor dampness and presence of mold, and upper respiratory tract symptoms, cough, wheeze, and asthma symptoms in sensitized persons, but no association for the development of asthma. The World Health Organization (WHO) in 2009, reviewed epidemiological, clinical, and laboratory studies and found associations between dampness and dampness related agents, including mold, and the development of asthma, a current diagnosis of asthma, dyspnea (shortness of breath), and respiratory infections. In the WHO review, associations were found in atopic and non-atopic individuals. Neither review reported finding causal relationships between indoor dampness or mold and the development of and/or appearance of health effects.

¹ <http://www.cdc.gov/mold/basics.htm>

² http://ww5.stlouisco.com/doh/pollen_site/MoldInfo.html

³ <http://www.epa.gov/mold/index.html>

⁴ <http://www.cdc.gov/mold/stachy.htm>

⁵ Health Canada (2007) Residential Indoor Air Quality Guideline for Moulds; Canada Gazette; 141(13).

DRAFT – FOR OFFICIAL USE ONLY

Mendell et al. (2011) reviewed all currently available evidence, including studies reviewed in the IOM report, recently published studies, and findings from quantitative meta-analysis studies. Mendell et al. classified hundreds of studies into the following four categories based on the strength of evidence between dampness, mold, dampness related agents and health: 1) sufficient evidence of a causal relationship, 2) sufficient evidence of an association, 3) limited or suggestive evidence of an association, or 4) inadequate or insufficient evidence to determine if an association existed. An association was found between indoor dampness or mold and the four health outcomes defined in the IOM report. In addition, the authors concluded that the studies were, "...strongly suggestive of causality" between asthma exacerbation and dampness or mold in children. This latter finding was especially evident in a controlled experimental intervention study on the exacerbation of asthma in homes with highly symptomatic children (Kercsmar et al., 2006). In this study, removal of sources of dampness and visible mold resulted in dramatic reductions in the exacerbation of asthma. (b)(5)

Mendell et al. also found sufficient evidence of associations between indoor dampness or mold and the development of asthma, a current diagnosis of asthma, having ever been diagnosed with asthma, dyspnea, respiratory infections, bronchitis, allergic rhinitis, and eczema.

The measured microbiological agents had limited associations with health effects; this was thought to be due to measurement errors in exposure assessment (i.e., non-standardized methods of measurement used in the different studies) as well as other factors such as age at exposure and interaction effects that occur with multiple chemical exposures. Limitations in the measurement techniques themselves were also highlighted. Although the authors report that their current findings cannot define causal microbiological exposure or dose-response relations that can be used to determine safe levels of exposure, quantifying dampness objectively has shown some promise for future research. In the meantime, the present method of subjectively assessing dampness or presence of mold has the most consistently documented associations with respiratory and allergic disease. Therefore, HS staff believes that it is appropriate to utilize this approach for assessing the potential for health effects due to exposure to mold.

B. Studies on Specific Mold Species

Health Sciences staff reviewed the current literature related to the mold species found in (b)(1) (A) (b)(1) (2) (A) (b)(3) (A), (b)(4) The literature review consisted of primary, peer reviewed studies that specifically identified one or more of the four mold species of interest.

Studies published within the last 11 years with sufficient data related to mold concentrations, species, and health outcomes were reviewed. The studies revealed limited information for the four mold species of interest (See Table 1). These mold

DRAFT – FOR OFFICIAL USE ONLY

species included Cladosporium, Alternaria, Aspergillus, and Phoma. Four relatively recent epidemiological studies were also reviewed.

All epidemiological studies showed a statistically significant association between increased mold exposure and respiratory effects. Stark et al. (2003) showed that exposure during the first year of life to high mold concentrations increases the incidence of doctor diagnosed lower respiratory illness (LRI)¹⁴.

In addition, the authors found specific connections to “LRI without wheezing” and airborne Penicillium exposure, and “LRI with wheezing” and Alternaria and Zygomycetes exposures. The relationship between Penicillium exposure and “LRI without wheezing” showed the strongest association through relative risk (RR). “LRI with wheezing” might represent an early allergic response. However, for many children in infancy wheezing can represent a non-allergic inflammation of the small airways. Therefore, although children who show repeated “LRI with wheezing” during infancy are more likely to develop allergic asthma, the trigger for developing this type of LRI during infancy is likely to be non-allergic.

When the authors investigated any associations between visible mold or mildew (a thin, discoloring growth pattern produced by mold in damp environments) and increased mold exposure, they found that there was little to no correlation between the two variables. This lack of correlation suggests that dampness-related factors, in addition to increased mold exposure, are also important in the development of adverse health effects. However, the visible presence of mold, mildew, or water damage did show a strong trend for association with increased LRI, though less of an association compared to the statistically significant association between high mold exposure and LRI. Therefore, these two variables, the visible presence of mold or mildew and high mold exposure, are independent predictors of LRI during infancy.

In a paper describing the continuation of their 2003 study, Stark et al. (2005) found an association between the presence of high levels of mold and the development of doctor diagnosed allergic rhinitis by the age of 5 years. The authors controlled for factors significantly associated with allergic rhinitis, including the presence of water damage, mold and mildew during the first year of life, and LRI during the first year of life. Therefore, these findings are independent of these factors. During a multivariate adjusted proportional hazards regression analysis, the authors found that some mold species were highly correlated with each other, meaning that when one species is found, it is likely that the second species will also be found, increasing the levels of mold exposure. These species included Alternaria with Aureobasidium, as well as Cladosporium with Alternaria.

In a previous paper by Gent et al. in 2002, the authors found that Penicillium and Cladosporium were significantly associated with persistent cough. Only Penicillium was associated with wheezing. Upon further review of the data, high exposure to Penicillium was also associated with an increase in the number of days in the first year of life that persistent cough is experienced (statistics not shown). When controlled for confounding

studies

(b)(5)

DRAFT – FOR OFFICIAL USE ONLY

factors, including water leaks, humidifiers or dehumidifiers, and smoking in the home, the *Penicillium* and *Cladosporium* associations with persistent cough remained.

Taskinen et al. (2001) studied school children, ages 7 – 13, who attended either schools with moisture problems (index group) or schools with no moisture problems (i.e., healthy, control schools) to determine if associations existed between moisture problems and sensitization¹ of the children. Sensitization was identified by mold specific serum IgE, as well as other clinical outcomes. The authors noted that more children from the index group showed mold specific serum IgE to at least one of the ten species studied. However, the number of children with elevated IgE was low, 14 (15%) out of 93, with 2 children being from control schools. However, 12 of the 14 children with elevated IgE also showed some reaction (positive or weak) to mold specific skin prick testing (SPT). In examining associations with specific clinical outcomes, the authors found increased IgE to be significantly associated with doctor diagnosed asthma and parent reported wheezing, but not persistent cough as reported by parent. In addition, other allergic manifestations, such as allergic rhinitis, conjunctivitis, or eczema, and sensitization to common inhalation allergens, dander, pollen, and mites, were also significantly associated. Although the authors found that those with mold specific IgE or SPT reactions were mostly from the schools with moisture problems (84%), they found no species specific mold associations with any of the responses. It is important to note that this study did not control for confounding factors, such as home environment considerations, exposure to smoking, parental atopy status, or other mold exposures, during their statistical analysis. (b)(5)

(b)(5)

(b)(5)

Upon reviewing these studies, HS staff concludes that (b)(5)

(b)(5)

(b)(5)

There is a known association with parental sensitization and allergic responses in children. Although the Stark et al. (2005) study did control for parental sensitization during the statistical analysis, due to lack of supporting studies, the conclusion (b)(5)

(b)(5)

Given that two of the four studies reviewed showed respiratory responses in infants, it is likely that (b)(5)

(b)(5)

DRAFT – FOR OFFICIAL USE ONLY

Therefore, HS staff concludes (b)(5)

(b)(5)

Table 1: Reviewed Mold Studies

Author	Study Type	Mold Concentration	Species	Health Outcome
Stark, et al. (2003)	Epidemiological (First year of life)	High (189 cfu/m ³)	Airborne Penicillium	LRI (RR=1.73)
		High ⁷ (31,579 cfu/g)	Dust-borne Cladosporium	LRI (RR=1.52)
		High ⁷ (870 cfu/g)	Dust-borne Zygomycetes	LRI (RR=1.96)
		High ⁷ (8,333 cfu/g)	Dust-borne Alternaria	LRI (RR=1.51)
		Multiple High ⁷	Multiple Species	LRI (RR=1.86)
		High ⁷	Any Species	LRI Wheezing (RR=1.58) Non-wheezing (RR=3.88)
Stark, et al. (2005)	Epidemiological (By 5 years of age)	High ⁷ (8,333 cfu/g)	Dust-borne Alternaria	DDAR (HR=2.34)
		High ⁷ (33,333 cfu/g)	Dust-borne Aspergillus	DDAR (HR=2.57) ¹⁰
		High ⁷ (24,000 cfu/g)	Dust-borne Aureobasidium	DDAR (HR=3.12) ¹⁰
		High ⁷ (250,000 cfu/g)	Total Dust-borne	DDAR (HR=3.13) ¹⁰
Gent, et al. (2002)	Epidemiological (First year of life)	High	Airborne Penicillium	Wheeze (RR=2.46) Persistent cough (RR=1.84) ¹²
		Medium	Airborne Cladosporium	Persistent cough (RR=1.62) ¹²
			Reported Mold	Persistent cough (RR=1.49)

DRAFT – FOR OFFICIAL USE ONLY

		High ¹¹	Airborne Penicillium	Wheeze (RR=2.15) Persistent cough (RR=2.06) ¹⁴
		Medium ¹³	Airborne Cladosporium	Persistent cough (RR=1.45) ¹⁴
Taskinen et al. (2001)	Epidemiological (School children ages 7 – 13)	Elevated Serum IgE Antibodies	10 molds mixture	Respiratory morbidity (asthma and/or wheezing) – 86% Clinical Atopy (rhinoconjunctivitis and/or eczema) – 71% SPT reactivity (danders, pollens, and/or mites) – 93%

III. Conclusions

(b)(5)

Works Cited

Gent et al. (2002) Levels of Household Mold Associated with Respiratory Symptoms in the First Year of Life in a Cohort at Risk for Asthma. *Environmental Health Perspectives*. 110:A781-A786.

Kercsmaer et al. (2006) Reduction in Asthma Morbidity in Children as a Result of Home Remediation Aimed at Moisture Sources. *Environmental Health Perspective*. 114:1574-1580.

Mendell et al. (2011) Respiratory and Allergic Health Effects of Dampness, Mold, and Dampness Related Agents: A Review of the Epidemiologic Evidence. *Environmental Health Perspectives*. 119:748-756.

DRAFT – FOR OFFICIAL USE ONLY

Stark et al. (2002) Fungal Levels in the Home and Lower Respiratory Tract Illnesses in the First Year of Life. *American Journal of Respiratory and Critical Care Medicine*. 168:232-237.

Stark et al. (2005) Fungal Levels in the Home and Allergic Rhinitis by 5 Years of Age. *Environmental Health Perspectives*. 113:1405-1409.

Taskinen et al. (2001) Mold-specific IgE Antibodies in Relation to Exposure and Skin Test Data in Schoolchildren. *Allergology International*. 50:239-245.

DRAFT – FOR OFFICIAL USE ONLY

Attachment 2

Fisher-Price Data

Fisher-Price (FP) provided two sources of data on microbial contamination of Rock 'n Play (RNP) sleepers: (1) ~~four Bureau Veritas reports~~; and (2) ~~one Building Dynamics, LLC report dated March 1, 2012 which is summarized in two Goldberg Segalla reports dated February 24, 2012 and March 5, 2012~~

Bureau Veritas (BV) Reports

- (1) Report #(5111)164-0165, dated June 20, 2011
- (2) Report #(5111)336-0079, dated December 12, 2011
- (3) Report #(5111)354-0251, dated January 4, 2012
- (4) Report #(5112)005-0086, dated January 17, 2012

(1) In the first BV report, (b)(4); (b)(3):CPSA Section 6(a); (b)(3):CPSA Section 6(b)

June 2011

(b)(4); (b)(3):CPSA Section 6(a); (b)(3):CPSA Section 6(b)

(b)(4); (b)(3):CPSA Section 6(a); (b)(3):CPSA Section 6(b)

Dec 2011 (2)

(b)(4); (b)(3):CPSA Section 6(a); (b)(3):CPSA Section 6(b)

Jan 2012 (3)

(b)(4); (b)(3):CPSA Section 6(a); (b)(3):CPSA Section 6(b)

DRAFT – FOR OFFICIAL USE ONLY

(b)(4); (b)(3);CPSA Section 6(a); (b)(3);CPSA Section 6(b)

(4) (b)(4); (b)(3);CPSA Section 6(a); (b)(3);CPSA Section 6(b)

Jan
2012

(b)(5)

Due to the poor quality of the pictures provided in the four reports, a determination cannot be made whether the microbial growth is located in the same area of each RNP sleeper. For some of the full-size RNP sleepers,

(b)(4); (b)(3);CPSA Section 6(a); (b)(3);CPSA Section 6(b)

(b)(5)

(b)(5)

The primary purpose of the ~~tape-lift sampling method~~ is to confirm the existence of mold growth and to identify the type of fungi at the sampling site, referred to as source sampling. In this case, the “source” is the RNP sleeper, since we have no information on the consumers from whom FP received the samples. Tape sampling is also the simplest method of source sampling. Compared with swab sampling¹, tape-lift sampling better preserves fungal structure, which may allow for higher resolution identification. However, tape-lift sampling is destructive testing and thus the samples are neither available nor suitable for subsequent culture analysis.

Bureau Veritas indicates (b)(4); (b)(3);CPSA Section 6(a); (b)(3);CPSA Section 6(b)

(b)(4); (b)(3);CPSA Section 6(a); (b)(3);CPSA Section 6(b)

¹ Swab sampling in an indoor air quality (IAQ) investigation is usually done in combination with other methods, such as air and bulk sampling. It is normally done when the surface is a non-porous (smooth) material, and cutting it is undesirable or not an option (countertops, poles, floors, etc.). Swab sampling is most commonly done by wiping or swabbing a designated area. Surface samples can be analyzed for microbial identification and semi-quantification by direct microscopy, quantitative polymerase chain reaction (qPCR), and/or culture methods. The analysis of surface samples can provide information about whether a suspect area is supporting microbial growth.

DRAFT – FOR OFFICIAL USE ONLY

Building Dynamics, LLC (BD)

(b)(4); (b)(3):CPSA Section 6(a); (b)(3):CPSA Section 6(b)

(1) (b)(4); (b)(3):CPSA Section 6(a); (b)(3):CPSA Section 6(b)


(2) (b)(4); (b)(3):CPSA Section 6(a); (b)(3):CPSA Section 6(b)

(b)(4); (b)(3):CPSA Section 6(a); (b)(3):CPSA Section 6(b)


(b)(4); (b)(3):CPSA Section 6(a); (b)(3):CPSA Section 6(b)

DRAFT – FOR OFFICIAL USE ONLY

(b)(4), (b)(3):CPSA Section 6(a); (b)(3):CPSA Section 6(b)

A large rectangular area that has been redacted, leaving a blank white space within a black border.

(b)(4), (b)(3):CPSA Section 6(a); (b)(3):CPSA Section 6(b)

A large rectangular area that has been redacted, leaving a blank white space within a black border.

DRAFT – FOR OFFICIAL USE ONLY

(b)(4), (b)(3):CPSA Section 6(a), (b)(3):CPSA Section 6(b)

(b)(4), (b)(3):CPSA Section 6(a), (b)(3):CPSA Section 6(b)

(b)(5)

(b)(5) (b)(4), (b)(3):CPSA Section 6(a), (b)(3):CPSA Section 6(b)

(b)(4), (b)(3):CPSA Section 6(a), (b)(3):CPSA Section 6(b)

(b)(4), (b)(3):CPSA Section 6(a),
(b)(3):CPSA Section 6(b)

(b)(5)

(b)(5) (b)(4), (b)(3):CPSA Section 6(a), (b)(3):CPSA Section 6(b)

(b)(4), (b)(3):CPSA Section 6(a), (b)(3):CPSA Section 6(b)

(b)(5)

(b)(5) (b)(4), (b)(3):CPSA Section 6(a), (b)(3):CPSA Section 6(b)

(b)(4), (b)(3):CPSA Section 6(a), (b)(3):CPSA Section 6(b)

DRAFT – FOR OFFICIAL USE ONLY

(b)(5) It is well known that seasonal variation will occur with not only the type of microbial species collected but also the total counts of microbiota (i.e., increased in warmer months). (b)(5)

(b)(5)

Discussion

(b)(5)

(b)(5)

DRAFT – FOR OFFICIAL USE ONLY

(b)(5)

In summary, (b)(5)

(b)(5)

-
- ⁱ A sensitizer is a substance that will induce an immunologically-mediated (allergic) response, including allergic photosensitivity. This allergic reaction will become evident upon re-exposure to the same substance. Occasionally, a sensitizer will induce and elicit an allergic response on first exposure by virtue of active sensitization.

*****FOR OFFICIAL USE ONLY*****

PRODUCT SAFETY ASSESSMENT (PSA) TECHNICAL EVALUATION REQUEST

PSA ACTION (FOR PSA
COORDINATOR USE ONLY)

PSA Number : 0481.12

Date Processed : 3/20/12

Date Requested : 3/27/12

Due Date: :

Field Off :FOER

Org. Code :CRC

(b)(6)

Case # :P1110066

Priority :b

Requested Completion Date : 3/27/2012 (Staff has agreed to completion date.)

PRODUCT INFORMATION:

Assigned to

Organization: : HS

State :NY

City :East Aurora

Manufacturer : Fisher-Price, Inc.

NEISS Code :1549 , 1537, 1558

Product : Fisher-Price Rock 'N Play Sleeper

Brand name, model, etc. : Fisher-Price

Technical Off. :

Request Summary:

Sample number :

Sample Disposition: _ Return to Requester _ Store at Warehouse _ Other :

IDI Number :

EVALUATION REQUESTED: [REDACTED] mold issue with this product as it relates to current research and literature. Also include staff's assessment of the firm's study disputing the hazards of mold in this product.

Comments:

EPI ASSESSMENT: Dates: From : To : Sort by Mfg.: _ Yes _ No

_ IDI _ IPI _ NEISS Comments _ NEISS Estimates _ Death _ NFIRS

HAZARD :Concern of infant's developing head plagiocephaly and/or neck torticollis from sleeping in product. Also development of mold in plastic liner could be harmful to infants. **HAZARD CODE** : 203

LOCATIONS OF

Samples: SSF

Files:

(MSWordRev 2/99 rp/jb/bh)

Nelson, Theresa

From: Nelson, Theresa
Sent: Thursday, March 01, 2012 4:01 PM
To: Cheryl Possenti
Cc: Moore, Kelly; Thomas, Treye; Matheson, Joanna; Johnson, Dominique
Subject: FW: FP Rock N Play - BV reports - additional test request

(b)(5)

Cheryl,

(b)(5)

Thank you for your cooperation.

Regards,

Terri Nelson

Compliance Officer
Office of Compliance & Field Operations
U.S. Consumer Product Safety Commission
Phone: 301-504-7509 or
1-800-638-8095 ext. 7509

Fax: 301-504-0359
tnelson@cpsc.gov

SIGN UP FOR RECALL NOTICES: <http://www.cpsc.gov/cpsclist.aspx>

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a)

of the Freedom of Information Act

FOR OFFICIAL USE ONLY



**UNITED STATES
CONSUMER PRODUCT SAFETY COMMISSION
WASHINGTON, DC 20207
DIRECTORATE FOR EPIDEMIOLOGY**

TO: Theresa Nelson, CRC
FROM: Ted Yang, EPHA
DATE: 6/5/2012
RE: Data Review for PSA # 0621.12 Case # PI110066

Date due: 6/6/2012

Priority: c

Request: Determine any incidents to children (victims 6-and-under) in which the word "mold" was present in reports received from 1/1/2009 - 5/15/2012. Sort by mfr.

Hazard Pattern: mold in products

Selection Criteria:

Product Code(s):

Manufacturer/Model Text:

Narrative Text: mold

Time Frame: 09/01/2008 - 05/15/2012 (covers dt_ent: 1/1/2009 - 5/15/2012)

NFIRS Search Criteria:

Incidents Identified:

Databases	Incident Count* (see notes below)	Death Count*
Incident Investigations (INDP)	2	0
Reported Incidents (IPII)	26 (43)	0
Death Certificates (DTHS)	0	0
NEISS reports (count)	N/A	N/A
Fire reports (NFIRS)	N/A	N/A
Total	28	0

* For INDP, IPII and DTHS, duplicate reports have been removed, i.e. counted only once, in the database listed first. The reports enumerated in the table have been identified from CPSC databases on the date the search was completed. These should be considered neither a statistical sample nor a complete count of all such incidents, but only a count of those in CPSC databases on the search date.

NOTES:

Search yielded 2 INDP records and 26 IPII reports involving incidents to children (victims 6-and-under) in which the word "mold" was present in reports received from 1/1/2009 - 5/15/2012. All records indicating incidents with children ages 6-and-under include age of victim in bold.

Also, 43 additional IPII reports involving mold were retained; the incidents described in these reports either mention mold with respect to a children's product, involve a consumer expressing concern of a product's danger to children, or involve a child victim whose age is unknown.

FOR OFFICIAL USE ONLY

Mold incidents (age ≤ 6)
Dr_ent: 1/1/2009 - 5/15/2012

docno	state	city	age	dtap	dt ent	dt inf	p. dth	sex	prod t	prod	infrname1	infrname2	modname1	modname2	infrname1	infrname2	modname1	modname2	typecon	narrative	docno
H110298A	NJ		211	0	12/30/2011	12/28/2011	D	F	1381		B / BATTAT INCORPORATED		B ZANY ZOO /SN CH061001050611						21	CONSUMER REPORTS THAT THE BOTTOM OF THE WOODEN ACTIVITY TOY HER 11-MONTH-OLD DAUGHTER HAD BEEN PLAYING WITH WAS FOUND COVERED IN A THICK LAYER OF MOLD. CONSUMER IS UNSURE IF HER DAUGHTER WAS LICKING MOLD OR IF SHE WAS INGESTING IT.	H110298A
H108022A	OH		210	0	12/2/2010	11/29/2010	D	F	1555		CHICCO		0504903260070, SC 1160066262, POLLY 2 IN-1 HIGH-CHAIR						47	THE 10 MOF CHILD'S HIGH-CHAIR TRAY IS 2 PIECES PUT TOGETHER BY SCREWS. THERE IS A SCREW IN THE BACK OF THE TRAY. WHEN OWNER TRIED TO LOOSEN THE SCREWS TO CLEAN THE SEAM, SHE NOTICED IT HAD TURNED BLACK & DARK DISCOLORATION ON THE INSIDE & NOTICED LOTS OF MOLD SPOTS.	H108022A
H020345A	FL		204	1	4/8/2009	3/10/2009	D	M	1545		DELTA ENTERPRISES / WALMART		0						47	THE CONSUMER NOTICED MOLD ON THE SIDE OF THE CRIB WHICH WAS NOT THERE AT THE TIME OF PURCHASE. THE CONSUMER STATED THAT A 4-MONTH-OLD SON HAD BEEN GETTING SICK ALL OF WHILE HE HAS BEEN SLEEPING IN THE CRIB.	H020345A
H110279A	NC		3	1	1/22/2011	5/15/2011	M	M	140		ELECTROLUX/WHITE CONSOLIDATED		GLTF2940FS /SN X089602104						21	26 YOF, HER 3 YOM SON AND HER 5 MOF DAUGHTER ARE EXPERIENCING SKIN RASHES, FEVERS WITH SINUS INFECTIONS & OTHER RESPIRATORY PROBLEMS DUE TO BLACK MOLD GROWING IN HER WASHER, WHICH TURNED LIGHTER WHITE GREEN. WASHER IS PART OF SIDE BY SIDE WASHER/DRYER COMBO.	H110279A
H071132A	MN		6	0	8/3/2010	10/1/2009	D	M	140		FRIGIDAIRE		FAFW537KW						47	6 YOM HAS ASTHMA AND EXPOSURE TO MOLD WORSENS HIS SYMPTOMS. PARENT DISCOVERED A LARGE AMOUNT OF MOLD UNDER THE FRONT SEAL OF FRONT LOAD WASHER THAT SHE CANNOT GET RID OF. HAZARD TO HER SON.	H071132A
H230657A	NY		213	0	4/3/2012	3/31/2012	D	M	1350		GARANNALS / I DONT KNOW		03112028149101						21	CONSUMER REPORTS THAT 12 MOF AND 3 YOM WERE PLAYING WITH A WATER SQUEEZE TOY WHEN THE CONSUMER NOTICED DISCOLORATION IN THE WATER BEING SQUEEZED OUT. CONSUMER BELIEVES THAT WATER LEFT TRAPPED IN THE TOYS AND CAUSE MOLD TO GROW. CONSUMER CONSIDERS THE TOYS UNSAFE.	H230657A
X093744A	GA		6	1	4/23/2009	3/28/2009	D	M	140		KENMORE		ELITE HEAT 110-45081400, CSS00864						47	BLACK MOLD CONTINUOUSLY FORMS ON THE OUTSIDE OF THE FRONT LOAD WASHER. THE 10-MONTH-OLD FEMALE CLEANS IT & IT RETURNS WORSE THAN BEFORE. SHE ATTRIBUTES HER SINUS INFECTIONS & HER 8-YEAR-OLD SON'S SEVERE ALLERGIES & ASTHMA TO THE MOLD.	X093744A
H22482A	TX		6	1	2/2/2012	2/1/2012	M	M	140		KENMORE / KENMORE		MODEL M4174H102701 /SN X084905519						21	WASHING MACHINE HAS LEFT CLOTHES WITH MOLY ODOR. THERE'S BLACK GUNK ON HM. WASHER HAD STOPPED DRAINING WATER 5 TIMES & HAS BEEN REPAIRED FOR THAT. 8 YOM HAS ALLERGY/ASTHMA/ECZEMA & HAD SEVERAL ATTACKS OVER LAST FEW YEARS & RECEIVED FIRST AID BY NON-MEDICAL PROFESSIONAL.	H22482A
Y1018016A	VA		0	1	2/19/2010	1/5/2010	D	M	140	127	I.G. APPLIANCES	LG	UPC 07SKUUNK7WM2668HNM						10	CUSTOMER IS STATING THAT HE PURCHASED A WASHER AND DRYER FROM THE STORE. HE STATES HIS UNITS ARE INFESTED WITH MOLD AND MOLD CAUSING HEALTH ISSUES WITH HIS 3 CHILDREN UNDER THE AGE OF 5 YEARS OLD.	Y1018016A
Y128563A	VA		2	0	3/29/2012	10/14/2011	M		1913		LOWING NATURAL'S / LOVING NATURAL'S		LOVING NATURAL'S HAND & BODY LOTION						10	CONSUMER USED LOTION DAILY ON 2 CHILDREN, AGES 2 & 4 FOR SEVERAL MONTHS. ABOUT WEEK AGO, CONSUMER STARTED NOTICING WHAT LOOKED LIKE FEW PIECES OF LINT/DIRT. CONSUMER OPENED CAP & SAW LAYER OF BLACK MOLD ON LOTION.	Y128563A
H040402A	MA		212	0	10/14/2010	9/22/2010	D	F	474		LUVIN' CARE		NUBY BO SPILL MEGA FLIP-IT CUP						47	CONSUMERS REPORT THAT THEY NOTICED MOLD GROWING IN A RUBBERIZED STRAW THAT IS A PART OF A SIPPING CUP USED BY 1 YOF. CONSUMERS STOPPED USING THE CUP.	H040402A

Mold Incidents (age ≤ 6)
Dt_ent: 1/1/2009 - 5/15/2012

docno	stno	state	city	age	slp	dt_ent	dt_int	pr_dth	sex	prod1	prod2	infrname1	infrname2	modname1	modname2	typecon	narrative	docno
1102435A		FL	(b)(6)	2;2	1	3/18/2010	9/1/2009	M		1876	361	MANUFACTURER UNKNOWN	MANUFACTURER UNKNOWN	0	0	47	AN ONE YEAR OLD BABY HAS FREQUENT COLD LIKE SYMPTOMS DUE TO DEFECTIVE DRYWALL INSTALLED IN THE HOUSE. CONSUMER REPORTED METAL CORROSION OF THE AIR CONDITIONER METAL PIPES & THE DOOR METALS. ONE OF THE ROOM WALLS IS FILLED WITH MOLD & SOME STRONG SMELL.	1102435A
11053264A		FL	(b)(6)	5	1	5/18/2010	12/4/2008	D	F	1876	557	MANUFACTURER UNKNOWN	MANUFACTURER UNKNOWN	0	0	47	3 YOF & A 18 YEAR OLD SUFFERED HEALTH PROBLEMS INCLUDING ALLERGY TO MOLD & MUST DUE TO CHINESE DRYWALL COPPER PLUMBING, LIGHT FIXTURES BLACKENED. COMPUTERS STOPPED WORKING.	11053264A
Y1134353A		MO	(b)(6)	207	4	4/29/2011	2/4/2011	D	M	1537		MATTEL / FISHER PRICE				10	WHILE USING THE BASSINET 7 MOM GOT SICK WITH AN UPPER RESPIRATORY ILLNESS & WAS SEEN BY THE DOCTOR 4 TIMES. THE ILLNESS WORSENEO & HE WAS ADMITTED TO HOSPITAL FOR 3 DAYS. AFTER 3 DAYS HE RECEIVED BRONCHING TREATMENTS. THE MOLDY PAD CAUSED THE ILLNESS.	Y1134353A
Y1185745A		CA	(b)(6)	204	0	12/8/2011	6/16/2011	D	M	1537	689	MATTEL / FISHER PRICE			MM R6070 / NEWBORN ROCK 'N PLAY SLEEPER	10	CONSUMER EXPRESSED CONCERN THAT THE SLEEPER DEVELOPED BLACK MILDEW MOLD SPOTS BETWEEN THE PAD & LINER. THIS HAPPENED BECAUSE SHE ALLOWED HER 4 MONTH-OLD SON TO SLEEP DIAPER-FREE FOR SEVERAL DAYS IN PRODUCT. USING ONLY A RECEIVING BLANKET TO ABSORB ANY URINE.	Y1185745A
Y1235553A		IN	(b)(6)	203	1	3/14/2012	2/1/2012	D	M	1544		MATTEL / FISHER PRICE			MM N3429 / WHALE OF A TUB	10	THE CONSUMER EXPRESSED CONCERN THAT MOLD IS FORMING UNDER THE INFANTSUPPORT. SHE BELIEVES THIS HAS CAUSED 3 MOM TO HAVE AN UPPER RESPIRATORY ISSUE. THE CHILD WAS TAKEN TO THE EMERGENCY ROOM TO BE EXAMINED. AN ANTIBIOTIC WAS PRESCRIBED FOR HIM.	Y1235553A
Y1165664A		MA	(b)(6)	202	1	6/22/2011	10/11/2010	D	F	1537		MATTEL / FISHER PRICE / MATTEL / FISHER PRICE			MM R6070 / NEWBORN ROCK 'N PLAY SLEEPER	10	CONSUMER NOTICED BLACK MOLD UNDER THE SEAT PAD AND IN THE SEAT LINING WHEN SHE WENT TO REMOVE THE PAD TO WASH IT FOR THE FIRST TIME. CONSUMER STATED HER 2 MONTH OLD DAUGHTER HAS HAD RESPIRATORY ISSUES SINCE SHE WAS 10 DAYS OLD, AND SHE BELIEVES IT IS RELATED TO THE MOLD.	Y1165664A
Y1165659A		IN	(b)(6)	201	0	6/22/2011	4/1/2011	M		1537		MATTEL / FISHER PRICE / MATTEL / FISHER PRICE			MM R6070 / NEWBORN ROCK 'N PLAY SLEEPER	10	THE CONSUMER EXPRESSED CONCERN THAT THE ROCKING SLEEPER'S FABRIC SEAT IS MOLDY. THE BABY IS 8 WEEKS OLD.	Y1165659A
11160185A		IL	(b)(6)	204	0	6/11/2011	5/7/2011	D	M	1526		NUBY / LUV N' CARE LTD				21	THE PACIFIERS HAVE DEVELOPED MOLD BETWEEN THE PLASTIC & THE PART THAT ANOM SUCKS ON. THERE IS NO WAY TO CLEAN THESE IN THAT AREA.	11160185A
11010450A		PA	(b)(6)	220	1	2/19/2010	12/14/2009	D	F	1636		SAFETY 1ST			SAFETY 1ST COMFY CUSHY 3 IN 1 POTTY PRETTY IN PINK / MM07034	47	CONSUMER REPORTS THE PADDED RING ON THE TOP OF THE POTTY ABSORBS LIQUID CAUSING MOLD & MILDEW TO GROW. THIS HAS CAUSED A FUNGUS TO BREAK OUT ON HER 20-MONTH-OLD DAUGHTER'S LEGS AND BUTTOCKS. THE SAME THING HAPPENED WITH A SECOND POTTY OF THE SAME TYPE ALSO.	11010450A
H10A0337A		SC	(b)(6)	3	1	10/25/2010	10/12/2010	D	F	474		TUMMAY TEXLER			TUMMAY TICKLE EMO-KNO-KNO	21	3 YOF SUFFERED DIARRHEA, VOMIT, FEVER AFTER USING A CHILD'S SIPPY CUP. CONSUMER NOTICED THE MOLD IN THE SPOT/CHARACTER OF THE SIPPY CUP.	H10A0337A
109030370A		NJ	(b)(6)	4	1	1/11/2010	10/8/2008	D		140		WHIRL POOL			DUET M4 WFWH400SW00 S# CSUR06296	47	MOLD IS GROWING INSIDE OF WASHING MACHINE. 2 ADULTS & 4 & 6 YEAR OLDS HAVE BEEN SICK MORE OFTEN SINCE USING THE WASHER. CONSUMER HAS DEVELOPED ASTHMA.	109030370A
110A0702A		CA	(b)(6)	4	1	10/26/2010	10/21/2010	D	M	140	1658	WHIRL POOL	MANUFACTURER UNKNOWN		DUET SPORT / FSEBHLW2087650	47	CONSUMER REPORTS THAT HER FRONT LOAD WASHING MACHINE HAS MOLD ALL OVER THE RUBBER RING INSIDE THE UNIT WHERE THE DOOR CLOSSES. HER 4-YEAR-OLD SON HAS BAD ASTHMA AND MOLD ALLERGIES AND WASHING HIS CLOTHES IN THE MACHINE IS MAKING IT WORSE AND FLARE UP.	110A0702A
10980623A		CA	(b)(6)	3	1	9/19/2009	1/1/2009	Y	F	140		WHIRL POOL DUET			M4GHW6160PW0 S#CSS9802601	47	CONSUMERS 7 & 3 YEAR OLD GIRLS HAVE BEEN TREATED FOR SEVERE ALLERGIES, CHRONIC COUGH & SKIN RASHES. THE WASHING MACHINE IN THE HOME HAS STARTED GROWING MOLD ON THE INSIDE & OUTSIDE & HAS A BAD ODOR.	10980623A

Mold incidents (age ≤ 6)
Dt_ent: 1/1/2009 - 5/15/2012

docno	tkno	state	city	age	diag	dt ent	dt inj	pr dtln	sex	prod1	prod2	infrname1	infrname2	modname1	modname2	typecon	narrative	docno
11140516A		FL		2	1	10/24/2011	10/21/2011	M	F	140		WHIRPOOL / WHIRLPOOL CORPORATION			GW4830PNA / SN C513720383	21	CONSUMER REPORT THAT THE BLACK MOLD GROWING INSIDE THE WASHING MACHINE. CONSUMER REPORT THAT HER 2 & 7 YEAR OLD DAUGHTERS CLOTHES AFTER BEING WASHED ARE STILL DIRTY & HAVE CAUSED THEM TO HAVE YEAST INFECTIONS & SINUS INFECTIONS	11140516A
11180533A		PA		6	0	8/28/2011	8/6/2010	M		1897	134					21	LIVING IN NEW HOUSE FAMILY MEMBERS (W/ 6YOM) STARTED GETTING ILL: HEADACHES, SHORTNESS IN BREATH, FOGGINESS, STINKY, ROTTEN EGG SMELLS, ETC. ALSO LIGHT SWITCHES IN KITCHEN & BATHROOMS WERE TURNING OFF. CONSUMER BELIEVES THAT MOLD IS PART OF PROBLEM & ALSO DRYWALL MIGHT BE CULPIT.	11180533A
The 43 reports below																		
11030186A		CA		0	0	3/31/2010	2/22/2010	D	F	304		ARO-SWISS			ARO-SWISS UNKNOWN	21	BABY HANDWIPE HAS A STICK THAT KEEPS MOLD & BACTERIA FROM GROWING IN WATER. PART IS CALLED LONG SILVER STICK & ITS A REPLACEMENT PART. BUT NEW REPLACEMENT STICK IS NOT SILVER SINCE THERE IS SOME SORT OF SOIL GROWING IN UNIT.	11030186A
11174122A		NC		0	0	7/21/2011	12/30/2010	M		471		BEABA / BEABA			MM NA / UPC# NM BABY COOK BABY FOOD MAKER	10	BABY FOOD - CONSUMER REPORT THAT THE BABY FOOD MAKER IS A MOLD INGESTION HAZARD.	11174122A
10010564A		FL		0	0	2/10/2009	1/17/2009	D		1526		BILLY BOB PACIFIER			MM 04 GRILL	47	CONSUMER REPORTS THAT WITHIN LESS WEEK OF OWNING THE PACIFIER, IT HAD BLACK MOLD GROWING INSIDE THE SILICONE NIPPLE. NO INJURY.	10010564A
11104186A		WA		0	0	12/17/2011	2/13/2011	D		1506		CHOCO			MM NA / UPC# NM / DU	10	CONSUMER REPORTS THAT CHILD'S SPT CAN GET INTO THE ELECTRONIC COMPONENTS OF THE WALKER. CONSUMER OPENED UP THE WALKER TO CLEAN IT AND SAW THAT THE ENTIRE INSIDE WAS COVERED WITH A POWDERY SUBSTANCE. CONSUMER THREW AWAY THE PRODUCT.	11104186A
11170288A		WI		201	1	7/13/2011	7/11/2011	M		1509		DR. BROWN'S BOTTLES / HANDICRAFT COMPANY				21	AFTER USING BOTTLES, CONSUMER NOTICED BLACK MOLD GROWING ON THE INNER BEIGE COLORED VENT. CONSUMER WASHES BOTTLES BY HAND EVERY DAY IN HOT SOAPY WATER AND IS NOT SURE HOW LONG MOLD HAS BEEN THERE.	11170288A
10002640A		NC		0	0	1/13/2010	12/6/2009	D	F	1509		DR. BROWN'S BY HANDICRAFT			DR. BROWN'S NATURAL FLOW BOTTLES AND WIDE NIPPLE BOTTLES	47	CONSUMER NOTICED SMALL BLACK MOLD SPOTS ON THE RUBBER VENT INSERTS OF THE BABY BOTTLES AND IS CONCERNED THAT THE MOLD MAY POSE A HEALTH RISK FOR HER DAUGHTER.	10002640A
11024186A		IL		0	0	1/29/2010	10/6/2010	D		1365		EJE			DUCK 4 PIECE BATH SET - PHTHALATE FREE / UPC# 43178921176	10	BATH TOY - THE TOY RETAINS WATER AND PROMOTES MOLD GROWTH. THERE IS ABSOLUTELY NO EASY WAY TO REMOVE ALL THE WATER THAT THIS TOY SUCKS IN. MOLD HAZARD.	11024186A
11184804A		WA		0	1	5/11/2011	5/6/2011	D		1637		FISHER PRICE / FISHER PRICE / FISHER PRICE			UPC# 74675015028 / NEWBORN ROCK 'N' PLAY SLEEPER	10	CONSUMER REMOVED SLEEPER PADDING TO WASH. CONSUMER SAW MOLD MOSTLY AROUND THE HEAD AND THE LEG PART. FORMED A YELLOW COLORED MOLD. BATH IS NOW COLORED. SO SET IS TAKING CHILD TO DOCTOR. NOT SURE OF CAUSE OF COUGH.	11184804A
10002644A		CA		212	0	10/12/2009	9/4/2009	D	M	140		GE			WB19460100000	47	CONSUMER DISCOVERED MOLD MOLD IN THE FRONT LONG WASHING MACHINE. CONSUMER SAYS THAT LEAVING THE DOOR OPEN AS SUGGESTED BY THE MANUFACTURER DURING THE WASHING CYCLE. CONSUMER WOULD BE DANGEROUS FOR CHILDREN AND PETS IN THE HOME.	10002644A
11020318A		NY		0	1	3/11/2010	2/3/2010	D		140		GE			WPD4800J000W / HR20015T	47	THE WASHING MACHINE HAS A BAD ODOR AFTER WASHING CLOTHES. THE RUBBER GASKET HAS BLACK STUFF IN IT. THE DETERGENT TRAY HAD BLACK MOLD IN IT. CONSUMERS KIDS HAVE BEEN HAVING RASHES ALL OVER THE BODY & HAVE HAD RUNNY NOSES.	11020318A
11140026A		VA		0	0	5/18/2011	3/31/2011	D		954		HOME DEPOT			UPC 048110 / UNKNOWN	10	MOLD AND MOLD SPRAY ENTERED EYES DUE TO CHILD PLAYING WITH THE PRODUCT.	11140026A
10004122A		TX		206	0	12/10/2009	1/10/2009	D	M	1647		J.J. COLE COLLECTIONS			P.O. 1721	47	BLACK MOLD WAS FOUND GROWING INSIDE FEEDING BB WITH A POCKET ON FRONT.	10004122A

Page 4

Mold Incidents (age ≤ 6)
Dt_entl: 1/1/2009 - 5/15/2012

doono	date	city	age	disap	dt ent	dt inj	sex	prod1	prod2	infrname1	infrname2	modname1	modname2	typecon	narrative	doono
Y1165656A	WA	(b)(6)	0	0	8/22/2011	5/1/2011 D		1537	WATTEL / FISHER-PRICE / WATTEL / FISHER-PRICE			MAF R6070 / NEWBORN ROCK N PLAY SLEEPER		10	THE CONSUMER IS CONCERNED BECAUSE THE PAD AND THE LINER ON THE ROCKING SLEEPER WERE MOLDED.	Y1165656A
Y1165656A			0	0	8/22/2011	5/31/2011 M		1537	WATTEL / FISHER-PRICE / WATTEL / FISHER-PRICE			MAF R6070 / NEWBORN ROCK N PLAY SLEEPER		10	THE PARENTS REPORTED THAT WHEN THE CONSUMER REMOVED THE ROCKING SLEEPER FROM THE LINER, SHE NOTICED A MOLDED AREA AROUND THE HEAD AND NECK AREA. THE MOLDED AREA WAS YELLOW AND THE CONSUMER WAS CONCERNED THAT THE MOLDED AREA WAS THE CAUSE OF A COUGH THAT THE BABY HAS DEVELOPED.	Y1165656A
Y1165656A	TX		0	0	8/22/2011	5/31/2011 M		1537	WATTEL / FISHER-PRICE / WATTEL / FISHER-PRICE			MAF R6070 / NEWBORN ROCK N PLAY SLEEPER		10	THE CONSUMER EXPRESSED CONCERN THAT THE MATERIAL ON THE SEAT OF THE ROCKING SLEEPER HAD DEVELOPED MOLDED NEAR THE PLASTIC SUPPORT.	Y1165656A
Y1165656A			0	0	3/31/2011	3/2/2011 D		140	MAYTAG NEPTUNE WASHER / WHEELPOOL CORPORATION			MAH187004WW / S4117516023L		21	CONSUMER REPORTED ABOUT BLACK MOLD ON THE FRONT WHEEL BEHIND THE FRONT WHEELS. CONSUMER WAS CONCERNED ABOUT THE CHILDREN AND VERY CONCERNED ABOUT THE EXPOSURE TO BLACK MOLD.	Y1165656A
Y1054953A	CA		0	0	4/2/2010	3/4/2010 D		1385	SANJOHN INC. / SANJOHN			MANCHUNK SQUARTER TOWER / UPCA 73523210040		10	PRODUCT HOLES / BRISHE WANTED TO RETURN THE BATH TOY. SHE SAID THAT RECENTLY ON THE TV THE TOYS THAT HAVE HOLES GET BLACK MOLD. SHE COULDN'T PROVIDE THE INFORMATION OF THE SHOW. HER ITEM DID NOT HAVE MOLD.	Y1054953A
Y1055392A	CA		0	0	5/20/2010	5/11/2010 D		1381	ORIENTAL TRADING			ORIENTAL TRADING CO. / #271837		21	CONSUMER REPORTS THAT WHEN SHE RECEIVED THE TOY WHISTLE ORDERED ONLINE, SHE NOTICED THAT IT HAD BLACK MOLD AROUND THE MOUTH AREA.	Y1055392A
Y1055392A	CA		0	0	4/14/2010	3/24/2010 D		1137	PARENT'S CHOICE			ORIENTAL TRADING CO. / #271837		21	TOYDLE WIFE HAD BLACK MOLD IN THE MIDDLE OF THE PACK.	Y1055392A
Y030204A	NY		0	0	4/3/2009	3/2/2009 D		5004	TOYS R US / ANIMAL PLANET			BN6000021228 1840		47	ANIMAL TOYS GAVE OFF A STRONG CHEMICAL SMELL WHEN THE CANISTERS WERE OPENED. CONSUMER IS CONCERNED THAT THEY MAY NOT BE SAFE FOR CHILD TO PLAY WITH.	Y030204A
Y051112A	MD		0	0	6/18/2008		1617	VERANDA				SPRAY		47	EXTREME MOLD PROBLEM OCCURRED AFTER EACH RAINFALL. VENDOR WAS CONTACTED LAST YEAR & THEY ADVISED TO CLEAN WITH BLEACH. THE STILL HAS MOLD SPORES WHICH WILL APPEAR USUALLY AFTER CLEANING. CHILDREN DO USE THE DECK EACH DAY & DECKING MAY BE A HEALTH HAZARD.	Y051112A
Y030204A	VA		212	0	11/12/2005	10/13/2009 D	F	140	WHEELPOOL	MANUFACTURER UNKNOWN		GMW9150PM4, CST1026102	0	47	CONSUMER FOUND MOLD ON THE GASKET OF THE WASHING MACHINE. ALSO ON THE INTERIOR OF THE WASHING MACHINE. SHE FOUND SEVERAL CHILDREN'S SOCKS THAT WERE COVERED WITH MOLD, AS WELL AS OTHER MOLDED DEERS.	Y030204A
Y0046123A	LA		0	4	4/22/2005	1/1/2005 D	M	140	WHEELPOOL / KENNEDY			MAF 110450915		10	CONSUMER REPORTS THAT MOLD BUILDS UP CONTINUOUSLY IN THE WASHING MACHINE, CAUSING HIS GRANDSON TO BECOME ILL WITH MOLD RELATED ASTHMA. CONSUMER REPORTS THAT HIS GRANDSON WAS HOSPITALIZED AS A RESULT OF THE DRESS.	Y0046123A
Y1003096A	FL		0	0	10/4/2011	10/25/2010 D		1304	YOUNG EXPLORERS.COM	MANUFACTURER UNKNOWN		K'S KIDS HUNGRY PELICAN ACTIVITY TOY PACMAN / 12202025N-UNKNOWN	0	21	WHEN THE BOX CONTAINS THE TOY WAS OPENED, THERE WAS STRONG SMELL SIMILAR TO MOLD & THE INSIDE BOX & INTERIOR PACKING MATERIAL HAD THE SAME BLACK POWDERY SUBSTANCE THAT CONSUMER BELIEVES IS MOLD. THE CONSUMER STATES THAT THIS TOY MAY CAUSE ILLNESS FOR A CHILD.	Y1003096A
Y1100618A			0	0	12/30/2011	12/26/2011 D		1301	ZANY ZOO / BATTAT / BATTAT INCORPORATED			CH0810-01 / UPC 062543219870		21	CONSUMER REPORTS THAT AFTER REMOVING THE ACTIVITY CUBE TOY FROM THE BOX IT WAS NOTICED TO HAVE SEVERE MOLD ON THE UNDERSIDE. CONSUMER SAYS THE SIDES OF THE TOY SEEM TO BE MADE FROM A MATERIAL THAT IS SUSCEPTIBLE TO MOLD GROWTH.	Y1100618A

FOR OFFICIAL USE ONLY



UNITED STATES
CONSUMER PRODUCT SAFETY COMMISSION
WASHINGTON, DC 20207
DIRECTORATE FOR EPIDEMIOLOGY

TO: Theresa Nelson, CRC
FROM: Angie Qin, EPHA
DATE: 7/11/11
RE: Data Review for PSA # 0792.11 Case # PI110066

Date due: 7/12/11

Priority: c

Request: Data search for all incidents involving ~~Fisher-Price Rock 'N Play Sleeper~~ model R6070 (b)(5)

Hazard Pattern: Infants can fall from Sleeper, even when buckled in. Also, concern of infant's developing head plagiocephaly and/or neck torticollis from sleeping in product

Selection Criteria:

Product Code(s): 1549 1537 1558

Manufacturer/Model Text: fisher-price/fisher price (6070) *change*

Narrative Text: (b)(5)

Time Frame: 6/1/09-6/15/11 *change*

NFIRS Search Criteria: N/A

Incidents Identified:

Databases	Incident Count* (see notes below)	Death Count*
Incident Investigations (INDP)	2	0
Reported Incidents (IPII)	14	0
Death Certificates (DTHS)	0	0
NEISS reports (count)	N/A	N/A
Fire reports (NFIRS)	N/A	N/A
Total	16	0

* For INDP, IPII and DTHS, duplicate reports have been removed, i.e. counted only once, in the database listed first. The reports enumerated in the table have been identified from CPSC databases on the date the search was completed. These should be considered neither a statistical sample nor a complete count of all such incidents, but only a count of those in CPSC databases on the search date.

NOTES:

Search found 16 incidents associated with Fisher-Price Rock 'N Play Sleeper R6070.

FOR OFFICIAL USE ONLY

SUMMARY

itemNum	item
1	Epidemiology Data Search by AQin 06JUL11
1	Search time frame of 6/1/09-6/15/11
1	-----
2	Investigations database searched
2	Previous search data cleared
2	Included product codes 1549 1537 1558
2	Included manufacturers and models FISHER-PRICE/FISHER PRICE/6070
2	9 observations saved in data set psa0792_11Indp
2	-----
3	Injury and Potential Injury database searched
3	Previous search data cleared
3	Included product codes 1549 1537 1558
3	Included manufacturers and models FISHER-PRICE/FISHER PRICE/6070
3	834 observations saved in data set psa0792_11Ipii
3	-----
4	Death Certificate database searched
4	Previous search data cleared
4	Included product code(s) 1549 1537 1558
4	Included narrative text FISHER-PRICE/FISHER PRICE/6070
4	0 observations saved in data set psa0792_11Dths
4	-----
5	INDP repulled for task numbers found elsewhere
5	8 investigations added to psa0792_11Indp
5	-----
6	Duplicate task numbers removed
6	10 observations kept in data set psa0792_11Indp
6	825 observations kept in data set psa0792_11Ipii
6	0 observations kept in data set psa0792_11Dths
6	-----
7	Death reports counted
7	0 death reports in DTHS
7	1 death reports in INDP
7	2 death reports in IPII
7	-----
8	Excel export attempted
8	-----
9	Total processing time was 0:34

Fisher-Price Rock N Play Sleepr (IPII Data)
6/1/09-6/15/11

docno	tkno	state	city	age	dis	dt_ent	dt_inj	pr_dtnj	sex	RI883	mtfrname2	mtfrname2	typecon	narrative
Y1150455A	170524C(OH)			201	1	5/25/2011	12/20/2010	M	F	1537		NEWBORN ROCK 'N PLAY SLEEPER, MODEL NO. R6070 /UPC 027084834	21	CONSUMER REPORTS THAT AFTER JUST 3 WEEKS OF THE BABY SLEEPER'S OVERNIGHT USE, BUT NOT DIAGNOSED UNTIL 4 MONTHS, CAUSED HER 3-WEEKS-OLD DAUGHTER TORTICOLLIS BECAUSE OF IT FORCING A CHILD TO TURN HEAD TO ONE SIDE. SHE ALSO DEVELOPED FLAT HEAD CAUSED BY ITS HARD PLASTIC BACKING.
Y1065872A	NY			0	0	6/24/2010	5/1/2010	D		1537		M# R6070 / NEWBORN ROCK 'N PLAY SLEEPER	10	THE CONSUMER STATED ONE OF THE BUCKI ON THE PAD OF THE BABY BASSINET BROKE OFF.
Y1125609A				0	1	3/16/2011	1/24/2011	M	M	1558		M# R6070 / NEWBORN ROCK 'N PLAY SLEEPER	10	CONSUMER REPORTED THAT SHE FEELS TH' NEWBORN ROCKER SLEEPER CONTRIBUTED SIGNIFICANTLY TO HER SON'S PLAGIOCEPHALY (FLAT HEAD). SHE USED THE ROCKER FOR OVER NIGHT SLEEPING AS ADVERTISED ON THE PACKAGING. HERSON IS NOW IN PHYSICAL THERAPY 3 TIMES A WEEK & HAS A CORRECTIVE HELM.
Y1165516A	110606C(MO)			204	1	6/4/2011	3/1/2011	D		1537		M# R6070 / NEWBORN ROCK 'N PLAY SLEEPER	10	CONSUMER'S SON HAS DEVELOPED FLATTENING ON THE BACK OF HIS HEAD FROM USING THE SLEEPER. HE ALSO HAS WEAKENING OF THE MUSCLES IN HIS NECK AND FAVORS ONE SIDE WHEN SLEEPING. HE USED THE PRODUCT 12 HOURS PER DAY FOR 4 MONTHS. DOCTOR RECOMMENDED PHYSICAL THERAPY AND HELMET.
Y1165656A				0	9	6/22/2011	5/31/2011	M		1537		M# R6070 / NEWBORN ROCK 'N PLAY SLEEPER	10	THE RETAILER'S REPORT STATED THAT WHEN THE CONSUMER REMOVED THE ROCKING SLEEPER'S PAD FOR LAUNDERING SHE NOTICED MOLD AROUND THE HEAD AND LEG AREA. THE MOLD WAS YELLOW IN COLOR. CONCERN WAS EXPRESSED THAT THE MOLD MAY BE THE CAUSE OF A COUGH THAT THE BABY HAS DEVELOPED.
Y1165657A	TN			0	0	6/22/2011	5/31/2011	M		1537		M# R6070 / NEWBORN ROCK 'N PLAY SLEEPER	10	THE CONSUMER EXPRESSED CONCERN THAT THE MATERIAL ON THE SEAT OF THE ROCKING SLEEPER HAS DEVELOPED MOLD NEAR THE PLASTIC SUPPORT.
Y1165658A	WA			0	0	6/22/2011	5/1/2011	D		1537		M# R6070 / NEWBORN ROCK 'N PLAY SLEEPER	10	THE CONSUMER IS CONCERNED BECAUSE THE HEAD AND THE LINER ON THE ROCKING SLEEPER ARE MOLDY.
Y1165659A	IN			0	0	6/22/2011	4/1/2011	M		1537		M# R6070 / NEWBORN ROCK 'N PLAY SLEEPER	10	THE CONSUMER EXPRESSED CONCERN THAT THE ROCKING SLEEPER'S FABRIC SEAT IS MOLDY. THE BABY IS 6 WEEKS OLD.

Fisher-Price Rock N Play Sleepr (IPII Data)
6/1/09-6/15/11

docno	tkno	state	city	age	disp	dt_ent	dt_inj	pr_dtnj	sex	prod3	refname2	refname2	typecon	narrative
Y1165660A		CA	(b)(6)	0	9	6/22/2011	4/23/2011	D		1537	Mattel / Fisher-Price / Mattel / Fisher-Price	M# R6070 / NEWBORN ROCK 'N PLAY SLEEPER	10	THE CONSUMER EXPRESSED CONCERN THAT SHE FOUND BLACK MOLD BETWEEN THE PAD AND THE SEAT ON THE ROCKING SLEEPER. THE CONSUMER ALSO STATED THAT HER CHILD HAS HAD RESPIRATORY PROBLEMS FOR TWO MONTHS AND SHE IS NOW ATTRIBUTING THIS TO THE SLEEPER.
Y1165661A		IN		0	0	6/22/2011	4/4/2011	D		1537	Mattel / Fisher-Price / Mattel / Fisher-Price	M# R6070 / NEWBORN ROCK 'N PLAY SLEEPER	10	THE CONSUMER EXPRESSED CONCERN THAT MOLD IS ON THE PAD AND LINER OF THE ROCKING SLEEPER.
Y1165662A		IL		0	0	6/22/2011	1/1/2011	M		1537	Mattel / Fisher-Price / Mattel / Fisher-Price	M# R6070 / NEWBORN ROCK 'N PLAY SLEEPER	10	THE CONSUMER EXPRESSED CONCERN BECAUSE THERE IS MOLD ON THE ROCKING SLEEPER'S LINER NEAR THE SUPPORT.
Y1165663A		IL		0	0	6/22/2011	1/1/2011	M		1537	Mattel / Fisher-Price / Mattel / Fisher-Price	M# R6070 / NEWBORN ROCK 'N PLAY SLEEPER	10	THE CONSUMER EXPRESSED CONCERN BECAUSE THERE IS MOLD ON THE ROCKING SLEEPER'S LINER NEAR THE SUPPORT.
														CONSUMER NOTICED BLACK MOLD UNDER THE SEAT PAD AND IN THE SEAT LINING WHEN SHE WENT TO REMOVE THE PAD TO WASH IT FOR THE FIRST TIME. CONSUMER STATED HER 2 MONTH OLD DAUGHTER HAS HAD RESPIRATORY ISSUES SINCE SHE WAS 10 DAYS OLD, AND SHE BELIEVES IT IS RELATED TO THE MOLD.
Y1165664A		MA		202	1	6/22/2011	10/11/2010	D	F	1537	Mattel / Fisher-Price / Mattel / Fisher-Price	M# R6070 / NEWBORN ROCK 'N PLAY SLEEPER	10	THE CONSUMER EXPRESSED CONCERN THAT THE ROCKING SLEEPER'S PAD AND SEAT ARE MOLDY.
Y1165665A		IN		0	0	6/22/2011	9/15/2010	D		1537	Mattel / Fisher-Price / Mattel / Fisher-Price	M# R6070 / NEWBORN ROCK 'N PLAY SLEEPER	10	MOLDY.

Fisher-Price Rock N Play Sleepr (INDP Data)

6/1/09-6/15/11

tkno	docno	dt_ent	dt_acc	prod1	prod2	mrname1	modname1	bdpt	diag	disp	sex	state	city	num_vict	age	narrative
21CNE0795110C0687A		1/28/2011	12/18/2010	1549	#	MATTEL, INC.	FISHER PRICE ROCK'N PLAY R6070	75	53	1	M	TN	ANTIOCH	1	204	A A FEMALE CONSUMER PUT HER FOUR MONTH OLD SON IN AN INFANT SEAT DESIGNED FOR NIGHTTIME AND DAYTIME USE. SHE BUCKLED HIM IN THE SEAT WITH THE THREE-POINT WAIST RESTRAINT. WHILE SHE WAS OUT OF THE BEDROOM, THE INFANT GOT OUT OF THE RESTRAINT AND FELL FROM THE SEAT. THE INFANT SUFFERED A CONTUSION AND SCRATCH TO HIS HEAD. THE INJURIES HAVE HEALED.
9426CNE900011090528A		5/16/2011	7/1/2010	1537		MATTEL, INC.	PRICE ROCK N PLAY R6070	75	71	1	M	CA	SANTA CLARIT	1	204	5 A FOUR MONTH OLD MALE WAS DIAGNOSED WITH PLAGIOCEPHALY AFTER THREE MONTHS OF PLAYPEN/SLEEPER USE.

Fisher-Price Rock N Play Sleeper (INDP Data)
6/1/09-6/15/11

tkno	docno	dt_ent	dt_acc	prod1	prod2	in1name3	modname1	bdpt	diag	disp	sex	state	city	num_vict	age_group	narrative
101221CNE0795	110C0687A	1/28/2011	12/18/2010	1549	##	MATTEL, INC.	FISHER PRICE ROCK'N PLAY R6070	75	53	1	M	TN	(b) (6)	1	204	A FEMALE CONSUMER PUT HER FOUR MONTH OLD SON IN AN INFANT SEAT DESIGNED FOR NIGHTTIME AND DAYTIME USE. SHE BUCKLED HIM IN THE SEAT WITH THE THREE-POINT WAIST RESTRAINT. WHILE SHE WAS OUT OF THE BEDROOM, THE INFANT GOT OUT OF THE RESTRAINT AND FELL FROM THE SEAT. THE INFANT SUFFERED A CONTUSION AND SCRATCH TO HIS HEAD. THE INJURIES HAVE HEALED.
110426CNE9000	11090528A	5/16/2011	7/1/2010	1537		MATTEL, INC.	PRICE ROCK N PLAY R6070	75	71	1	M	CA	(b) (6)	1	204	A FOUR MONTH OLD MALE WAS DIAGNOSED WITH PLAGIOCEPHALY AFTER THREE MONTHS OF PLAYPEN/SLEEPER USE.

Fisher-Price Rock N Play Sleepr (INDP Data)
6/1/09-6/15/11

		tkno
101221CNE0795		
110426CNE9000		

Nelson, Theresa

From: Wanna-Nakamura, Suad
Sent: Tuesday, November 08, 2011 11:43 AM
To: Nelson, Theresa
Cc: Moore, Kelly
Subject: RE: Favor RE: FP Rock N Play Sleeper incident - FW: IDI Number: 110906CCC1997

(b)(5)

Suad Wanna-Nakamura, PhD
Physiologist
U.S Consumer Product Safety Commission
4330 East West Highway
Suite 600-E
Bethesda MD 20814-4421
Tel 301 504 7252
Mobile (b)(6)
Fax 301 504 0079
<mailto:snakamura@cpsc.gov>

-----Original Message-----

From: Nelson, Theresa
Sent: Tuesday, October 18, 2011 8:20 AM
To: Wanna-Nakamura, Suad
Subject: FW: Favor RE: FP Rock N Play Sleeper incident - FW: IDI Number: 110906CCC1997

(b)(5)

Thanks, Terri

-----Original Message-----

From: Nelson, Theresa
Sent: Tuesday, October 04, 2011 9:34 AM
To: Wanna-Nakamura, Suad
Cc: Moore, Kelly
Subject: RE: Favor RE: FP Rock N Play Sleeper incident - FW: IDI Number: 110906CCC1997

Thanks Suad, I'll look forward to your response on this IDI. This is the one with 51 pages that cannot be emailed due to the size. Do you want me to scan it today and send it to you?

Terri

-----Original Message-----

From: Wanna-Nakamura, Suad
Sent: Tuesday, October 04, 2011 9:28 AM
To: Nelson, Theresa
Subject: RE: Favor RE: FP Rock N Play Sleeper incident - FW: IDI Number: 110906CCC1997

(b)(6)

and respond to you sometime today.. yesterday was a very busy day here with play yards crios bassinets etc Suad

Suad Wanna-Nakamura, PhD
 Physiologist
 U.S Consumer Product Safety Commission
 4330 East West Highway
 Suite 600-E
 Bethesda MD 20814-4421
 Tel 301 504 7252
 Mobile 301 768 2915
 Fax 301 504 0079
<mailto:snakamura@cpsc.gov>

-----Original Message-----

From: Nelson, Theresa
 Sent: Tuesday, September 27, 2011 5:18 PM
 To: Wanna-Nakamura, Suad
 Subject: FW: Favor RE: FP Rock N Play Sleeper incident - FW: IDI Number: 110906CCC1997

Suad

Can you let me know if you're in this week? I need your review of the IDI linked below based on your PSA on this product.

(b)(6)

Terri

-----Original Message-----

From: Nelson, Theresa
 Sent: Tuesday, September 20, 2011 1:36 PM
 To: Wanna-Nakamura, Suad
 Subject: FW: Favor RE: FP Rock N Play Sleeper incident - FW: IDI Number: 110906CCC1997

Suad - When I try to send it via pdf, I get the message "over size limit" (it's 50 pages with lots of pictures) and it won't attach. Could you wait and view it via the link below when you get back in the office? I could scan it and send it to you, but

(b)(6)

Terri

-----Original Message-----

From: Wanna-Nakamura, Suad
 Sent: Tuesday, September 20, 2011 1:15 PM
 To: Nelson, Theresa
 Subject: Favor RE: FP Rock N Play Sleeper incident - FW: IDI Number: 110906CCC1997

Terri, I do not have access to CPSC net yet when I am off site ... I only get email could you please send me the pdf version... (b)(6) thanks a lot Suad Suad Wanna-Nakamura, PhD U.S Consumer Product Safety Commission 4330 East West Highway Suite 600-E Bethesda MD

20814-4421 Tel 301 504 7252 Fax 301 504 0079 <mailto:snakamura@cpsc.gov>

From: Nelson, Theresa
Sent: Tuesday, September 20, 2011 11:23 AM
To: Wanna-Nakamura, Suad
Cc: Moore, Kelly
Subject: FW: FP Rock N Play Sleeper incident - FW: IDI Number: 110906CCC1997

(b)(5)

Terri

-----Original Message-----

From: cca,
Sent: Friday, September 16, 2011 3:32 PM
To: Nelson, Theresa
Subject: IDI Number: 110906CCC1997

IDI is from investigator ID: 2118 - Shawn M. Cerruti

A two week old male victim began sleeping overnight inside a portable rocking sleeper. After several months his mother noticed that his head was becoming flat on the back and right side. A specialist diagnosed him with severe brachycephaly and plagiocephaly (flattening of the head). He wore a medical helmet for 23 hours a day for three months and his head has resumed its normal shape.

If you wish to view the entire IDI click on the link below.

(b) (6)

Withheld pursuant to exemption

(b)(5)

of the Freedom of Information Act

DRAFT - FOR OFFICIAL USE ONLY - DRAFT

CONSUMER PRODUCT SAFETY COMMISSION PRODUCT SAFETY ASSESSMENT TECHNICAL EVALUATION DIVISION FOR HEALTH SCIENCES DRAFT - FOR OFFICIAL USE ONLY - DRAFT	PSA No. 0933.11	FOER
	CASE No: PI110066	
	REQUESTER: Theresa Nelson	
	SAMPLE No:	
	CPSC SEAL:	
	IDI No: 01221CNE0795, 110426CNE9000, 110524CCC2557	
FIRM: Fisher-Price, Inc.		
PRODUCTS: Fisher-Price Rock 'N Play Sleeper		
REQUEST: Concern of infant's developing head plagiocephaly and/or neck torticollis from sleeping in product. Infants can fall from Sleeper, even when buckled in.		
POTENTIAL HAZARD: Plagiocephaly and/or neck torticollis		
INCIDENTS: The CPSC staff is aware of three incidents.		
PREPARED BY: Suad Wanna-Nakamura, PhD, Physiologist, 301 504 7252		DATE: 9/12/2011

Health Sciences Staff (HS) Assessment:

The subject product Fisher-Price Rock 'N Play Sleeper (Figure. 1) is advertised as a child seat and a rocking cradle. The firm suggests consumers use the product from birth until the child is able to pull-up or sit unassisted. The manufacturer's suggested weight limit is twenty-five pounds. The Consumer Product Safety Commission's (CPSC) staff is aware of 3 consumer incidents associated with the product; one incident involved the fall of a 4.5 month old child from the product (101221CNE0795) and two concerned children diagnosed with plagiocephaly and torticollis (110426CNE9000 and 110524CCC2557). The incidents occurred between the period of July 2010 and December 2010. The infants' age ranged from 4.5 to 6 months.

Figure 1. Fisher-Price Rock 'N Play Sleeper.

Plagiocephaly and Muscular Torticollis: Positional or deformational plagiocephaly (DP), commonly known as flat head, is a condition that may be present at birth due to mechanical constraint of fetal head in the womb, especially in multiple birth infants¹. It may also develop after birth in the first few months of life². The incidence of DP has increased since 1992 and it has been suggested that it is associated with the introduction of the "Back to Sleep" campaign³⁻⁵, which recommends that infants be placed in the supine position for sleeping because of evidence that this reduces the risk for SIDS. Although the flattened appearance of an infant's head

DRAFT - FOR OFFICIAL USE ONLY – DRAFT

can be worrying to parents there is no current scientific evidence to show that plagiocephaly interferes with brain development or function. This condition appears to improve with time and it is often reversible: the only lasting effect may be the physical shape/deformity of the head⁶. Muscular torticollis (turtle neck) is a known risk factor sometimes associated with plagiocephaly and is caused by constraint of head neck movement or congenital defect⁷⁻⁸.

Despite the increase in the number of children with plagiocephaly and the risk of physical deformity associated with this condition, the American Academy of Pediatrics has not reversed its recommendations to place infants to sleep on their backs, mostly because the condition can be reversed and has no lasting health effects on children.

However, to help prevent the development of flat head the AAP presently recommends a certain amount of prone positioning, or "tummy time," during the day while the infant is awake and under supervision. Alternating the orientation of supine head position from right to left is another effective measure; i.e., sleeping with head turned to the right side one night and changing to the left side position on a consecutive night⁹.

Falls: The injury potential of any fall is dependent on several factors including height of the fall, nature of the impact surface, and orientation of the body at impact. The orientation of the body at impact is one of the most important factors in determining the type and severity of injury. Injuries could range from minor abrasions, lacerations and contusions, to more severe injuries such as bone fractures, concussions, spine and/or skull fractures, possibly resulting in death. HS staff notes that the likelihood of severe head injury is possible should a child fall head first onto a hard floor surface.

HS Conclusion: (b)(5)

(b)(5)

(b)(5)

References:

1. Littlefield TR, Kelly KM, Pomatto JK, Beals SP. Multiple-birth infants at higher risk for development of deformational plagiocephaly. *Pediatrics* 1999; **103**:565–569
2. Argenta LC, David LR, Wilson JA, Bell WO. An increase in infant cranial deformity with supine sleeping position. *Journal of Craniofacial Surgery* 1996; **7**:5–11
3. Turk AE, McCarthy JG, Thorne CH, Wisoff JH. The 'back to sleep campaign' and deformational plagiocephaly: is there cause for concern? *Journal of Craniofacial Surgery* 1996; **7**:12–18

DRAFT - FOR OFFICIAL USE ONLY – DRAFT

4. Christy M. McKinney, Cunningham ML, Holt VL, Leroux B, Starr JR. A case-control study of infant, maternal and perinatal characteristics associated with deformational plagiocephaly Article first published online: 21 APR 2009
<http://www.familyop.com/Library/Cranial%20Research%20Articles/Characteristics%20of%202733%20cases%20of%20DP%20and%20changes%20in%20risk%20factors...pdf>
5. Peitsch WK, Keefer CH, LaBrie RA, Mulliken JB. Incidence of cranial asymmetry in healthy newborns. *Pediatrics* 2002; **110**:e72
6. Pollack IF, Losken WH, Fasick P. Diagnosis and Management of Posterior Plagiocephaly. February 1, 1997 *Pediatrics* Vol. 99 No. 2 pp. 180 -185
7. Dunn PM. Congenital postural deformities. *British Medical Bulletin* 1976; **32**:71–76
8. Öhman A, Mårdbrink EL, Stensby J, Beckung E. Evaluation of treatment strategies for muscle function in infants with congenital muscular torticollis. October 2011; **27**(7): 463-470
9. Persing J, James H, Swanson J, Kattwinkel J. Prevention and management of positional skull deformities in infants. American Academy of Pediatrics Committee on Practice and Ambulatory Medicine, Section on Plastic Surgery and Section on Neurological Surgery. *Pediatrics* 2003; **112**:199–202

*****FOR OFFICIAL USE ONLY*****

PRODUCT SAFETY ASSESSMENT (PSA) TECHNICAL EVALUATION REQUEST

PSA ACTION (FOR PSA COORDINATOR USE ONLY)			
PSA Number : 0933.1.1			
Date Processed : 8/11/11			
Requested by : Theresa Nelson, (301) 504-7509		Org. Code : CRC	Field Off : FOER
Date Submitted : 8/10/2011		Priority : c	Case # : P1110066
Requested Completion Date : 9/07/2011			
PRODUCT INFORMATION:			
Manufacturer : Fisher-Price, Inc.	City : East Aurora	State : NY	
Product : Fisher-Price Rock 'N Play Sleeper	NEISS Code : 1549		
Brand name, model, etc. : Fisher-Price, R6070			
Sample number : 11-810-6684 (ask CO prior to requesting sample)			
Sample Disposition: <input checked="" type="checkbox"/> Return to Requester <input type="checkbox"/> Store at Warehouse <input type="checkbox"/> Other :			
IDI Number : 101221CNE0795, 110426CNE9000, 110524CCCC2557 & Amazon product reviews (see Compliance Officer)			
EVALUATION REQUESTED: HS- Review incident reports, IDI's, product reviews and product sample. Conduct a HS evaluation on product and determine likelihood of injury and severity of injury. Discuss your safety concerns. Please provide a written report using the Product Safety Assessment Report form.			
EPI ASSESSMENT: Dates: From : To :		Sort by Mfg.: <input type="checkbox"/> Yes <input type="checkbox"/> No	
<input type="checkbox"/> IDI	<input type="checkbox"/> IPI	<input type="checkbox"/> NEISS Comments	<input type="checkbox"/> NEISS Estimates <input type="checkbox"/> Death <input type="checkbox"/> NFIRS
HAZARD : Concern of infant's developing head plagiocephaly and/or neck torticollis from sleeping in product. Infants can fall from Sleeper, even when buckled in.		HAZARD CODE : 203	
LOCATIONS OF		Files: 613-28	(MSWordRev 2/99 rp/jb/bh)

Fisher Price ROCK N PLAY SLEEPER incidents (April 2010- January 2012)- Includes incidents reported to Fisher Price + CPSC (UPDATED 2/29/2012)

case count	doono	state	city	age	diep	dt_ent	dt_inj	sex	prod1	mfname1	modname1	narrative	docno	hazard
1	Y1165690A	CA		0	9/6/22/2011	4/23/2011		D	1537	PRICE / MATTEL / FISHER-PRICE / MATTEL / FISHER-PRICE	M# R6070 / NEWBORN / ROCK N PLAY SLEEPER	THE CONSUMER EXPRESSED CONCERN THAT SHE FOUND BLACK MOLD BETWEEN THE PAD AND THE SEAT ON THE ROCKING SLEEPER. THE CONSUMER ALSO STATED THAT HER CHILD HAS HAD RESPIRATORY PROBLEMS FOR TWO MONTHS AND SHE IS NOW ATTRIBUTING THIS TO THE SLEEPER.	Y1165690A	mold
2	Y11B5745A	CA		204	0/12/9/2011	6/16/2011		M	1537	PRICE / MATTEL / FISHER-PRICE	M# R6070 / NEWBORN / ROCK N PLAY SLEEPER	CONSUMER EXPRESSED CONCERN THAT THE SLEEPER DEVELOPED BLACK MOLD SPOTS BETWEEN THE PAD & LINER. THIS HAPPENED BECAUSE SHE ALLOWED HER 4 MONTH-OLD SON TO SLEEP DIAPER-FREE FOR SEVERAL DAYS IN PRODUCT, USING ONLY A RECEIVING BLANKET TO ABSORB ANY URINE.	Y11B5745A	mold
3	Y11B5743A	FL		0	0/12/9/2011	6/30/2011		D	1537	PRICE / MATTEL / FISHER-PRICE	M# R6070 / NEWBORN / ROCK N PLAY SLEEPER	THE CONSUMER EXPRESSED CONCERN THAT MOLD HAS DEVELOPED BETWEEN THE LINER AND THE FABRIC PAD.	Y11B5743A	mold
4	Y11B5737A	FN		0	0/12/9/2011	11/1/2011		D	1537	PRICE / MATTEL / FISHER-PRICE	M# R6070 / NEWBORN / ROCK N PLAY SLEEPER	THE CONSUMER IS CONCERNED BECAUSE THERE IS MOLD ON THE LINER OF THE PRODUCT.	Y11B5737A	mold
5	Y11B5741A	FN		0	0/12/9/2011	9/8/2011		D	1537	PRICE / MATTEL / FISHER-PRICE	M# R6070 / NEWBORN / ROCK N PLAY SLEEPER	THE CONSUMER EXPRESSED CONCERN THAT THERE IS MOLD ON THE SEAT PAD AND LINER.	Y11B5741A	mold
6	Y11B5742A	GA		0	0/12/9/2011	7/14/2011		D	1537	PRICE / MATTEL / FISHER-PRICE	M# R6070 / NEWBORN / ROCK N PLAY SLEEPER	THE CONSUMER EXPRESSED CONCERN THAT MOLD HAS FORMED ON THE PAD AND LINER OF THE PRODUCT.	Y11B5742A	mold
7	Y1165662A	IL		0	0/6/22/2011	1/7/2011		M	1537	PRICE / MATTEL / FISHER-PRICE	M# R6070 / NEWBORN / ROCK N PLAY SLEEPER	THE CONSUMER EXPRESSED CONCERN BECAUSE THERE IS MOLD ON THE ROCKING SLEEPER'S LINER NEAR THE SUPPORT.	Y1165662A	mold
8	Y1165659A	IN		201	0/6/22/2011	4/1/2011		M	1537	PRICE / MATTEL / FISHER-PRICE	M# R6070 / NEWBORN / ROCK N PLAY SLEEPER	THE CONSUMER EXPRESSED CONCERN THAT THE ROCKING SLEEPER'S FABRIC SEAT IS MOLDY. THE BABY IS 6 WEEKS OLD.	Y1165659A	mold
9	Y1165691A	IN		0	0/6/22/2011	4/4/2011		D	1537	PRICE / MATTEL / FISHER-PRICE	M# R6070 / NEWBORN / ROCK N PLAY SLEEPER	THE CONSUMER EXPRESSED CONCERN THAT MOLD IS ON THE PAD AND LINER OF THE ROCKING SLEEPER.	Y1165691A	mold

(b)(6)

2287

(b)(5)

**Clearinghouse Format - With Manufacturer
Reported Incidents
U.S. Consumer Product Safety Commission
National Injury Information Clearinghouse**

(b)(5)

11/2/2012

(b)(5)

Page 1

(b)(5)

LS
PSB
1/24/2012

Document Number : H1220229A **Task Number :** **Issue :** 0
Date Received : 02/17/2012 **Confirmed :** **Date Entered :** 02/22/2012
City : **State :** **Zip :** **Date Notified :**
Source : 0 **Type Of Contact :** 21 CONSUMER COMPLAINTS
Prod : 1537 BASSINETS OR CRADLES
Prod : 0 NO SECOND PRODUCT INVOLVEMENT
Date Injured : 02/15/2012 D **Work Related :** N
Age : 0 **Sex :** 0 UNKNOWN
Disposition : 0 0=NO INJURY **Haz Type :** F OTHER
Brand : FISHER-PRICE / FISHER-PRICE **Screened? :**
Model : ROCK 'N PLAY SLEEPER / R6070

Narrative :

CONSUMER STATED THAT CHILDREN WHO USE THE BASSINET DEVELOP TORTICOLLS, WHICH IS A FLATTENING OF THE CRANIUM & RESULTS IN CHILD HAVING TO WEAR A HELMET TO SUPPORT THE AFFECTED AREA. HER CHILD HAS NOT DEVELOPED THIS CONDITION BUT FEARS IT CAN HAPPEN. PRODUCT HAS HARD SURFACE.

Document Number : H1280549A **Task Number :** **Issue :** 0
Date Received : 08/26/2012 **Confirmed :** **Date Entered :** 08/28/2012
City : SACRAMENTO **State :** CA **Zip :** (b)(6) **Date Notified :**
Source : 0 **Type Of Contact :** 21 CONSUMER COMPLAINTS
Prod : 1537 BASSINETS OR CRADLES
Prod : 0 NO SECOND PRODUCT INVOLVEMENT
Date Injured : 08/20/2012 M **Work Related :** N
Age : 203 **Sex :** 1 MALE
Disposition : 1 1=TREATED & RELEASED, OR EX/Haz Type : F OTHER
Brand : FISHER PRICE / MATTEL, INC. **Screened? :**
Model :

Narrative :

CONSUMER NOTICED THAT 3 YOM HEAD HAS BECOME EXTREMELY FLAT OF BACK. CONSUMER ATTRIBUTING THIS TO USE OF BASSINET WHICH WAS USED SINCE BABY WAS BORN. DOCTOR IS TREATING FLAT HEAD WITH PILLOWS TRYING TO RESHAPE IT.

Document Number : H1290178A **Task Number :** 120913CCCC2975 **Issue :** 0
Date Received : 09/09/2012 **Confirmed :** **Date Entered :** 09/11/2012
City : (b)(6) **State :** AL **Zip :** (b)(6) **Date Notified :**
Source : 0 **Type Of Contact :** 21 CONSUMER COMPLAINTS
Prod : 1537 BASSINETS OR CRADLES
Prod : 0 NO SECOND PRODUCT INVOLVEMENT
Date Injured : 09/08/2012 D **Work Related :** N
Age : 205 **Sex :** 2 FEMALE
Disposition : 1 1=TREATED & RELEASED, OR EX/Haz Type : F OTHER
Brand : FISHER PRICE / FISHER-PRICE BRAND **Screened? :**
Model : R6070

Narrative :

5 MOF HAD FALLEN OUT OF SLEEPER BUT HAD HER LEG TANGLED IN THE SAFETY RESTRAINT. THE RESTRAINT HAD CUT OFF THE CIRCULATION TO HER LEFT LEG FROM HER KNEE DOWN. SHE WAS HANGING UPSIDE DOWN & HER HEAD WAS BARELY TOUCHING THE GROUND. SHE HAD A BURN MARK ON HER LEG.

**Clearinghouse Format - With Manufacturer
Reported Incidents
U.S. Consumer Product Safety Commission
National Injury Information Clearinghouse**

11/2/2012

Page 2

Document Number : I1290333A **Task Number :** **Issue :** 0
Date Received : 09/15/2012 **Confirmed :** **Date Entered :** 09/18/2012
City : (b)(6) **State :** SC **Zip :** (b)(6) **Date Notified :**
Source : 0 **Type Of Contact :** 21 CONSUMER COMPLAINTS
Prod : 1537 BASSINETS OR CRADLES
Prod : 1807 FLOORS OR FLOORING MATERIALS
Date Injured : 09/15/2012 D **Work Related :** N
Age : 206 **Sex :** 1 MALE
Disposition : 0 0=NO INJURY **Haz Type :** 9 FALLS
Brand : SIMPLICITY (BY GRACO) / SIMPLICITY **Screened? :**
Model : 3040SPR

Narrative :

CONSUMER SAYS THE BAR ON THE BASSINET THAT COLLAPSES TO CONVERT IT TO A CO-SLEEPER DOESN'T SEEM LONG ENOUGH TO BE SECURE WHEN USED AS A REGULAR BASSINET. SHE SAYS SHE HEARD HER 6-MONTH-OLD SON CRYING AND FOUND THE BAR WAS HANGING DOWN AND THE BABY WAS ON THE FLOOR.

Document Number : Y1225729A **Task Number :** **Issue :** 0
Date Received : 02/15/2012 **Confirmed :** **Date Entered :** 02/24/2012
City : (b)(6) **State :** MI **Zip :** (b)(6) **Date Notified :**
Source : 6 **Type Of Contact :** 10 OFFICE OF COMPLIANCE
Prod : 1537 BASSINETS OR CRADLES
Prod : 0 NO SECOND PRODUCT INVOLVEMENT
Date Injured : 09/01/2011 D **Work Related :** N
Age : 202 **Sex :** 1 MALE
Disposition : 1 1=TREATED & RELEASED, OR EX/ **Haz Type :** F OTHER
Brand : MATTEL / FISHER-PRICE **Screened? :**
Model : M# V9197 / RNP SLEEPER-CIRCLES

Narrative :

THE CONSUMER STATED HER SON HAS BEEN DIAGNOSED WITH PLAGIOCEPHALY SINCE USE IN THIS SLEEPER. IT WAS FIRST NOTICED WHEN HE WAS TWO MONTHS OLD. THE CHILD HAS SEEN A REHABILITATION SPECIALIST, WHO PRESCRIBED A HELMET TO CORRECT THE ISSUE.

Document Number : Y1225926A **Task Number :** **Issue :** 0
Date Received : 02/23/2012 **Confirmed :** **Date Entered :** 03/03/2012
City : (b)(6) **State :** LA **Zip :** (b)(6) **Date Notified :**
Source : 6 **Type Of Contact :** 10 OFFICE OF COMPLIANCE
Prod : 1537 BASSINETS OR CRADLES
Prod : 0 NO SECOND PRODUCT INVOLVEMENT
Date Injured : 12/01/2011 D **Work Related :** N
Age : 204 **Sex :** 2 FEMALE
Disposition : 1 1=TREATED & RELEASED, OR EX/ **Haz Type :** F OTHER
Brand : MATTEL / FISHER-PRICE **Screened? :**
Model : M# V9102 / ROCK 'N PLAY SLEEPER

Narrative :

THE CONSUMER STATED THAT THE BACK OF HER DAUGHTER'S HEAD HAS FLATTENED SINCE USE OF THIS PRODUCT. SHE HAS SEEN HER PEDIATRICIAN REGARDING THE ISSUE. SHE HAS A PRESCRIPTION TO TAKE HER FOR X-RAYS AND SCANS FOR POSSIBLE HELMET USAGE IF NEEDED.

**Clearinghouse Format - With Manufacturer
Reported Incidents
U.S. Consumer Product Safety Commission
National Injury Information Clearinghouse**

11/2/2012

Page 3

Document Number : Y1225927A **Task Number :** **Issue :** 0
Date Received : 02/23/2012 **Confirmed :** **Date Entered :** 03/03/2012
City : (b)(6) **State :** MA **Zip :** (b)(6) **Date Notified :**
Source : 6 **Type Of Contact :** 10 OFFICE OF COMPLIANCE
Prod : 1537 BASSINETS OR CRADLES
Prod : 0 NO SECOND PRODUCT INVOLVEMENT
Date Injured : 07/01/2011 D **Work Related :** N
Age : 203 **Sex :** 2 FEMALE
Disposition : 1 1=TREATED & RELEASED, OR EX/Haz Type : F OTHER
Brand : MATTEL / FISHER-PRICE **Screened? :**
Model : M# V9102 / ROCK 'N PLAY SLEEPER

Narrative :

THE CONSUMER STATED THAT HER DAUGHTER DEVELOPED A FLAT SPOT ON HER HEAD WHILE USING THE SLEEPER. SHE USED THE SLEEPER 2-3 HOURS PER DAY DURING THE WEEK AND MORE DURING THE WEEKENDS. THE CHILD WAS TAKEN TO THE PEDIATRICIAN.

Document Number : Y1225928A **Task Number :** **Issue :** 0
Date Received : 02/23/2012 **Confirmed :** **Date Entered :** 03/03/2012
City : (b)(6) **State :** LA **Zip :** (b)(6) **Date Notified :**
Source : 6 **Type Of Contact :** 10 OFFICE OF COMPLIANCE
Prod : 1537 BASSINETS OR CRADLES
Prod : 0 NO SECOND PRODUCT INVOLVEMENT
Date Injured : 12/07/2010 D **Work Related :** N
Age : 202 **Sex :** 1 MALE
Disposition : 1 1=TREATED & RELEASED, OR EX/Haz Type : F OTHER
Brand : MATTEL / FISHER-PRICE **Screened? :**
Model : M# V9102 / ROCK 'N PLAY SLEEPER

Narrative :

THE CONSUMER STATED THAT HE HAS USED THE SLEEPER FOR HIS CHILD TO SLEEP IN. THIS HAS RESULTED IN HIS SON RECEIVING A FLAT SPOT ON THE LEFT SIDE OF THE BACK OF HIS HEAD. HE WAS TAKEN TO THE DOCTOR & TOLD TO USE A CRIB.

Document Number : Y1235488A **Task Number :** **Issue :** 0
Date Received : 03/01/2012 **Confirmed :** **Date Entered :** 03/06/2012
City : (b)(6) **State :** AR **Zip :** (b)(6) **Date Notified :**
Source : 6 **Type Of Contact :** 10 OFFICE OF COMPLIANCE
Prod : 1537 BASSINETS OR CRADLES
Prod : 0 NO SECOND PRODUCT INVOLVEMENT
Date Injured : 08/01/2011 D **Work Related :** N
Age : 202 **Sex :** 1 MALE
Disposition : 1 1=TREATED & RELEASED, OR EX/Haz Type : F OTHER
Brand : MATTEL / MATTEL / FISHER-PRICE **Screened? :**
Model : M# R6070 / NEWBORN ROCK 'N PLAY SLEEPER

Narrative :

THE CONSUMER STATED THAT THE BACK OF HER SON'S HEAD HAS BECOME FLATTENED SINCE THE USE OF THE PRODUCT. THE CHILD HAS SEEN THE PEDIATRICIAN AND A NEUROLOGIST, AND HAD X-RAYS. SHE OWNS TWO OF THE SAME PRODUCTS WITH THE SAME ISSUE WITH HER TWIN BOYS.

10	Y1165656A	IN	0	0/6/22/2011	9/15/2010	D	1537	MATTEL / FISHER-PRICE / MATTEL / FISHER-PRICE	M# R6070 / NEWBORN / ROCK 'N' PLAY SLEEPER	THE CONSUMER EXPRESSED CONCERN THAT THE ROCKING SLEEPERS PAD AND SEAT ARE MOLDY.	Y1165656A	mod
11	Y1165656A	MA	202	1/6/22/2011	10/11/2010	F	1537	MATTEL / FISHER-PRICE / MATTEL / FISHER-PRICE	M# R6070 / NEWBORN / ROCK 'N' PLAY SLEEPER	CONSUMER NOTICED BLACK MOLD UNDER THE SEAT PAD AND IN THE SEAT LINING WHEN SHE WENT TO REMOVE THE PAD TO WASH IT FOR THE FIRST TIME. CONSUMER STATED HER 2 MONTH OLD DAUGHTER HAS HAD RESPIRATORY ISSUES SINCE SHE WAS 10 DAYS OLD, AND SHE BELIEVES IT IS RELATED TO THE MOLD.	Y1165656A	mod
13	Y1165656A	MD	206	1/9/2012	9/16/2011	M	1537	FISHER-PRICE / MATTEL / FISHER-PRICE	FISHER-PRICE / ROCK 'N' PLAY V9197	A CONSUMER REPORTED THAT MOLD BEGAN TO GROW ON THE FABRIC OF TWO IDENTICAL BAGGIES AFTER THEY HAD BEEN USED FOR SEVERAL MONTHS. THE CONSUMERS SIX MONTH OLD SON DOES NOT SHOW ANY SIGNS OF ILLNESS AS A RESULT OF BEING EXPOSED TO THE MOLD.		mod
14	Y11B5746A	NC	0	0/12/9/2011	5/1/2011	D	1537	MATTEL / FISHER-PRICE / MATTEL / FISHER-PRICE	M# R6070 / NEWBORN / ROCK 'N' PLAY SLEEPER	THE RETAILER'S REPORT STATED THAT WHEN THE CONSUMER REMOVED THE ROCKING SLEEPER'S PAD FOR LAUNDERING SHE NOTICED MOLD AROUND THE HEAD AND LEG AREA. THE MOLD WAS YELLOW IN COLOR. CONCERN WAS EXPRESSED THAT THE MOLD MAY BE THE CAUSE OF A COUGH THAT THE BABY HAS DEVELOPED.	Y11B5746A	mod
15	Y1165657A	TN	0	0/6/22/2011	5/31/2011	M	1537	MATTEL / FISHER-PRICE / MATTEL / FISHER-PRICE	M# R6070 / NEWBORN / ROCK 'N' PLAY SLEEPER	THE CONSUMER EXPRESSED CONCERN THAT THE MATERIAL ON THE SEAT OF THE ROCKING SLEEPER HAS DEVELOPED MOLD NEAR THE PLASTIC SUPPORT.	Y1165657A	mod
17	Y1165658A	WA	0	0/12/9/2011	10/13/2011	M	1537	MATTEL / FISHER-PRICE / MATTEL / FISHER-PRICE	M# R6070 / NEWBORN / ROCK 'N' PLAY SLEEPER	THE CONSUMER EXPRESSED CONCERN THAT HER SLEEPER HAS DEVELOPED MOLD ON THE SEAT.	Y11B5740A	mod
18	Y1215512A, IDI not yet completed 120109CC0140Z	NY	205	1/12/2012	12/25/2011	M	1512	FISHER-PRICE	M# R6070 / NEWBORN / ROCK 'N' PLAY SLEEPER	WIFE NOTICED HIVES ON BACK OF SMOOM'S LEGS. SHE CHANGED HIS DIAPER & HE WAS TAKEN TO EMERGENCY ROOM WHERE HE WAS GIVEN MEDICATION. WHEN THEY ARRIVED HOME THEY NOTICED MOLE ON SEAT. THEY TOOK HIM TO PEDIATRICIAN FOLLOWING DAY FOR FOLLOW UP EXAM. Infant undergoing testing for allergies. Firm collected sample sleeper with mold growth. CONSUMER REPORTED MOLD BEGAN TO APPEAR ON THE SEAT AND THE STRAPS. CONSUMER EXPRESSED CONCERN BECAUSE SHE CANNOT REMOVE THE SEAT FOR LAUNDERING. THE CONSUMER OWNS TWO NEWBORN ROCK 'N' PLAY SLEEPERS AND IS REPORTING THIS SAME ISSUE WITH EACH ONE.		mod - hives
19	Y11B5738A	MD		11/25/2011	9/15/2011	na	1537	MATTEL / FISHER-PRICE	M# R6070 / NEWBORN / ROCK 'N' PLAY SLEEPER		Y11B5738A	mod

(6)

2 Regu.

3 Cough

4 Regu.
hives

20	101221CNE0795	TN		204	1/28/2011	12/18/2010	M	1549	MATTEL, INC.	FISHER PLAY R6070	A FEMALE CONSUMER PUT HER FOUR MONTH OLD SON IN AN INFANT SEAT DESIGNED FOR NIGHTTIME AND DAYTIME USE. SHE BUCKLED HIM IN THE SEAT WITH THE THREE-POINT WAIST RESTRAINT. WHILE SHE WAS OUT OF THE BEDROOM, THE INFANT GOT OUT OF THE RESTRAINT AND FELL FROM THE SEAT. THE INFANT SUFFERED A CONTUSION AND SCRATCH TO HIS HEAD. THE INJURIES HAVE HEALED.	1000687A	other - Fall out
21	Y1065872A	NY		0	0 6/24/2010	5/1/2010	D	1537	MATTEL / FISHER-PRICE	M# R6070 / NEWBORN ROCK 'N' PLAY SLEEPER	THE CONSUMER STATED ONE OF THE BUCKLES ON THE PAD OF THE BABY BASSINET BROKE OFF.	Y1065872A	Other -buckle
23	reported to FP - not to CPSC	CA		202	4/8/2010 web review to FP	4/8/2010	M		MATTEL / FISHER-PRICE	M# R6070 / NEWBORN ROCK 'N' PLAY SLEEPER	Consumer reported chair tipped over with grandson in it.		other- tipover
24	reported to FP - not to CPSC	CT		201	6/15/2010 call to FP	6/00/2010	M		MATTEL / FISHER-PRICE / MATTEL / FISHER-PRICE	M# R6070 / NEWBORN ROCK 'N' PLAY SLEEPER	Consumer stated that while her 3 week on, 8 lb. son was kicking his legs while he was in the product, as a result, the sleeper tipped over.		other -tipover
25	Y1215802A	AL		0	9 1/21/2012	12/27/2011	M	1537	MATTEL / FISHER-PRICE / MATTEL / FISHER-PRICE	M# R6070 / NEWBORN ROCK 'N' PLAY SLEEPER	THE FOLLOWING REPORT WAS RECEIVED VIA EMAIL: THE CONSUMER STATED THAT HER BABY HAS DEVELOPED A FLAT SPOT ON HIS HEAD SINCE USING THE BABYHAMMOCK TO SLEEP IN.	Y1215802A	p-flat head
	Y1215808A	FN		0	9 1/20/2012	3/1/2011	F	1537	MATTEL / FISHER-PRICE	M# R6070 / NEWBORN ROCK 'N' PLAY SLEEPER	THE CONSUMER STATED THAT HIS DAUGHTER RECEIVED A FLAT SPOT ON THE BACK OF HER HEAD FROM SLEEPING IN THE SOOTHER. HIS DAUGHTER SLEEPS ANYWHERE FROM 2-6 HOURS IN IT.	Y1215808A	p-flat head
27	Y1215807A	ID		0	9 1/20/2012	5/25/2011	M	1537	MATTEL / FISHER-PRICE	M# R6070 / NEWBORN ROCK 'N' PLAY SLEEPER	THE CONSUMER STATED THAT THE PLASTIC SUPPORT UNDER THE LINER IS TOO HARD. AS A RESULT, HER SON HAS DEVELOPED A FLAT SPOT ON THE BACK OF HIS HEAD. THE CHILD ONLY USES THE PRODUCT TO SLEEP IN OVER NIGHT.	Y1215807A	p-flat head
28	Y1215804A	ID		202	9 1/21/2012	11/11/2011	F	1537	MATTEL / FISHER-PRICE	M# R6070 / NEWBORN ROCK 'N' PLAY SLEEPER	REPORTED VIA EMAIL: CONSUMER STATED THAT THE BABY HAMMOCK'S HEADRESTS TOO HARD, RESULTING IN A SLIGHT FLAT SPOT ON HER 2-MONTH-OLD DAUGHTER'S HEAD. THE CONSUMER STATED THAT HER DAUGHTER HAS A SLIGHT FLATSPOT ON THE RIGHT SIDE OF HER HEAD.	Y1215804A	p-flat head
29	Y1215805A	NC		0	1 1/20/2012	7/1/2011	F	1537	MATTEL / FISHER-PRICE	M# R6070 / NEWBORN ROCK 'N' PLAY SLEEPER	THE CONSUMER STATED THAT HER BABY DEVELOPED A FLAT SPOT ON THE BACK OF HER HEAD. HER PEDIATRICIAN ADVISED HER TO DISCONTINUE USE OF THE SLEEPER. AFTER STOPPING USE, THE FLAT SPOT IS DIMINISHING.	Y1215805A	p-flat head

(9)

30	Y11B5736A	NY		202	9	12/9/2011	12/1/2010	M	1537	MATTEL / FISHER-PRICE SLEEPER	M# R6070 / NEWBORN ROCK 'N PLAY SLEEPER	THE CONSUMER EXPRESSED CONCERN THAT HER SON'S HEAD IS FLATTENED FROM SLEEPING IN THE PRODUCT. THIS WAS NOTICED IN DECEMBER OF 2010.	Y11B5736A	p-flat head
31	reported to FP - not to CPSC	KY				11/8/2011	NS	M		MATTEL / FISHER-PRICE SLEEPER	V9102 / Rock 'N Play Sleeper	THE CONSUMER STATED THAT AFTER TAKING HER SON TO THE PEDIATRICIAN, HE WAS DIAGNOSED WITH A FLAT HEAD. STATED SHE BELIEVES THIS IS FROM THE USE OF THIS PRODUCT SINCE IT IS THE ONLY PLACE HE SLEEPS. THE PEDIATRICIAN STATED HE WOULD LIKE TO SEE HER BABY IN A FEW WEEKS AND MAY NEED TO PRESCRIBE A HELMET TO CORRECT THE SITUATION.		p-head harness
32	reported to FP - not to CPSC	LA		0	1	1/10/2011	NS	M		MATTEL / FISHER-PRICE SLEEPER	V9102 / Rock 'N Play Sleeper	Consumer reported that his son received a flat spot on left side of back of his head. Doctor evaluated on Jan 5, 2010 and stated to use a regular crib to have him sleep in, using a wedge to force him to sleep on the other side of his head. They are to do this for two months and have him re-evaluated.		p-head harness
33	Firm not CPSC	MA		202	1	8/11/2011	ns	m		MATTEL / FISHER-PRICE SLEEPER	V9197	THE CONSUMER STATED THAT HER SON HAS DEVELOPED A FLAT SPOT ON THE RIGHT SIDE OF HIS HEAD. SHE ALSO STATED HIS NECK HAS THE TENDENCY TO TURN TO ONE SIDE. THE CHILD WAS TAKEN FOR A CHECK UP RECENTLY AND THE PEDIATRICIAN NOTED THESE ISSUES.	Reported to firm - not to CPSC	p-head harness
34	Y11B5733A	MA		205	1	12/9/2011	7/22/2010	M	1537	MATTEL / FISHER-PRICE SLEEPER	M# R6070 / NEWBORN ROCK 'N PLAY SLEEPER	CONSUMER STATED THAT THE HARD SLEEPING SURFACE OF THE PRODUCT HAS CAUSED LEFT SIDE OF HER SON'S HEAD TO BE FLAT. HE HAS BEEN DIAGNOSED WITH PLAGIOCEPHALY. HE HAS SEEN A PLASTIC SURGEON, AND HAS HAD EXTENDED TREATMENT AT CHILDREN'S HOSPITAL.	Y11B5733A	plagiocephaly
35	Y1215801A	MD		205	1	1/21/2012	11/1/2011	M	1537	MATTEL / FISHER-PRICE SLEEPER	M# R6070 / NEWBORN ROCK 'N PLAY SLEEPER	THE CONSUMER STATED THAT THE BACK OF HER 5-MONTHS-OLD SON'S HEAD WAS FLAT FROM THE USE OF THE BABY HAMMOCK. THE CONSUMER ADDRESSED HER CONCERN WITH THE PEDIATRICIAN. SHE DISCONTINUED USE OF THE PRODUCT AND HAS NOTICED AN IMPROVEMENT IN THE AREA OF CONCERN.	Y1215801A	plagiocephaly
36	Y11B5734A	MI		0	9	12/9/2011	5/1/2011	M	1537	MATTEL / FISHER-PRICE SLEEPER	M# R6070 / NEWBORN ROCK 'N PLAY SLEEPER	A LAW FIRM REPRESENTS GUARDIAN AND NATURAL PARENT OF MALE TWINS ALLEGING BABIES SKULLS BECAME MISSHAPEN AND/OR FLATTENED AS A RESULT OF USING THE SLEEPER FROM 4/29/2011 - 6/29/2011.	Y11B5734A	plagiocephaly
37	Y11B5735A	MI		203	1	12/9/2011	7/1/2011	M	1537	MATTEL / FISHER-PRICE SLEEPER	M# R6070 / NEWBORN ROCK 'N PLAY SLEEPER	THE CONSUMER STATED THAT HER CHILD WAS DIAGNOSED WITH FLAT HEAD AT HIS TWO MONTH CHECKUP WITH THEIR PEDIATRICIAN. THE DOCTOR ADVISED THE CONSUMER TO DISCONTINUE USE OF THE SLEEPER.	Y11B5735A	plagiocephaly
38	Y11B5441A	OK		204	1	11/18/2011	10/25/2011	M	1558	MATTEL / FISHER-PRICE SLEEPER	M# R6070 / NEWBORN ROCK 'N PLAY SLEEPER	THE CONSUMER STATED THAT HER SON HAS DEVELOPED A FLAT HEAD FROM USING THE ROCKER. THE CHILD WAS EXAMINED BY A DOCTOR WHO HAS RECOMMENDED THAT THE CHILD RECEIVE PHYSICAL THERAPY TO ALLEVIATE THE SYMPTOMS. HE HAS ALWAYS TILTED HIS HEAD TO ONE SIDE.	Y11B5441A	plagiocephaly
39	111114HCC3129	OK	(b)(6)	202		12/14/2011	7/2/2011	M	1537	FISHER-PRICE, INC.	NEWBORN ROCK 'N SLEEPER R6070	A 2 MOM WAS DIAGNOSED WITH PLAGIOCEPHALY BY THREE (3) DIFFERENT MEDICAL FACILITIES. THE MOTHER OF THE VICTIM BELIEVES THE CAUSE OF THE CONDITION IS FROM SLEEPING, RESTING, AND PLAYING IN THE SUBJECT SLEEPER/BASSINET DURING A 4 TO 5 MONTH PERIOD.	Y11A5703A	plagiocephaly

40	Y11C5646A	TX		202	1	12/24/2011	9/1/2011	M	1537	MATTEL / FISHER-PRICE	M# R6070 / ROCK 'N PLAY SLEEPER	CONSUMER'S SON RECEIVED FLAT HEAD DURING USE OF THE SLEEPER. WHEN HE WAS TAKEN TO PEDIATRICIAN CONSUMER WAS GIVEN SUGGESTIONS TO HELP THE CONDITION LIKE TUMMY TIME & POSITIONING HIM DIFFERENTLY. THE CONDITION HASN'T IMPROVED & THEY MEASURED FOR HELMET.	Y11C5646A	plagiocephaly
41	110906CCC199Z	VA		202		9/20/2011	12/26/2010	M	1558	FISHER-PRICE	ROCK 'N PLAY SLEEPER R6070	A TWO WEEK OLD MALE VICTIM BEGAN SLEEPING OVERNIGHT INSIDE A PORTABLE ROCKING SLEEPER. AFTER SEVERAL MONTHS HIS MOTHER NOTICED THAT HIS HEAD WAS BECOMING FLAT ON THE BACK AND RIGHT SIDE. A SPECIALIST DIAGNOSED HIM WITH SEVERE BRACHYCEPHALY AND PLAGIOCEPHALY (FLATTENING OF THE HEAD). HE WORE A MEDICAL HELMET FOR 23 HOURS A DAY FOR THREE MONTHS AND HIS HEAD HAS RESUMED ITS NORMAL SHAPE.	Y11C5646A	plagiocephaly
	Firm not CPSC	MA		unk	1		11/16/2011	F			V9102	CONSUMER STATED THAT HER DAUGHTER DEVELOPED A FLAT SPOT ON HER HEAD WHILE USING THE SLEEPER. SHE USED IT 2-3 HOURS PER DAY DURING THE WEEK AND MORE DURING WEEKENDS. THE CHILD WAS TAKEN TO THE PEDIATRICIAN WHO TOLD HER THAT SHE COULD USE A HELMET TO RE-FORM THE CHILD'S HEAD, HOWEVER, CONSUMER COULD NOT AFFORD IT.	Reported to firm - not to CPSC	plagiocephaly
43	Y11C5648A	TX		207	1		8/1/2011	M	1537	MATTEL / FISHER-PRICE	ROCK 'N PLAY SLEEPER R6070	THE CONSUMER STATED THAT HER SON RECEIVED A FLAT HEAD DURING THE USE OF ROCK 'N PLAY SLEEPER. HE WAS IN IT ABOUT TEN HOURS A DAY ON AND OFF INCLUDING NIGHTTIME SLEEP. HE AS TAKEN TO THE PEDIATRICIAN AND WAS GIVEN INSTRUCTIONS ON TUMMY TIME AND POSITIONING TO DO BUT HE ENDED UP HAVING TO GET A HELMET. THE CONSUMER HAS TWO SLEEPERS BECAUSE SHE HAS TWINS.	Y11C5648A	plagiocephaly
44	Y11C4336A	VA		203	1	12/23/2011	3/13/2011	M	1529	FISHER-PRICE	NEWBORN ROCK 'N PLAY SLEEPER M# N/A / UIC# N/A	CONSUMER NOTICED THAT 3 MOM SLouching DOWN & LOOKED CRUNCHED UP IN SLEEPER. CONSUMER IMMEDIATELY STOPPED USING IT. BABY WAS DIAGNOSED WITH SEVERE BRACHYCEPHALY & MODERATE PLAGIOCEPHALY. CONSUMER BELIEVES THAT THIS SLEEPER CAUSED THESE PROBLEMS.	Y11C4336A	plagiocephaly & brachycephaly
	110426CNE9000	CA		204		5/16/2011	7/1/2010	M	1537	MATTEL, INC.	FISHER-PRICE ROCK 'N PLAY R6070	A FOUR MONTH OLD MALE WAS DIAGNOSED WITH PLAGIOCEPHALY AFTER THREE MONTHS OF PLAYPEN/SLEEPER USE. Mom also reported on sleeper by this consumer.	110906378A	plagiocephaly & MOLD
46	Y1165515A	MO		204	1	6/4/2011	3/1/2011	M	1537	MATTEL / FISHER-PRICE	M# R6070 / NEWBORN ROCK 'N PLAY SLEEPER	CONSUMER'S SON HAS DEVELOPED FLATTENING ON THE BACK OF HIS HEAD FROM USING THE SLEEPER. HE ALSO HAS WEAKENING OF THE MUSCLES IN HIS NECK AND FAVORS ONE SIDE WHEN SLEEPING. HE USED THE PRODUCT 12 HOURS PER DAY FOR 4 MONTHS. DOCTOR RECOMMENDED PHYSICAL THERAPY AND HELMET.	Y1165515A	plagiocephaly & torticollis
47	Y11B5538A	IL		202	1	11/23/2011	7/23/2011	M	1537	MATTEL / FISHER-PRICE	M# R6070 / NEWBORN ROCK 'N PLAY SLEEPER	THE CONSUMER STATED THAT HER SON HAS BEEN SLEEPING IN THE PRODUCT 10-14 HOURS PER DAY SINCE BIRTH. HE DEVELOPED A FLAT HEAD AT 2 MONTHS OLD & DEVELOPED TORTICOLLIS AT 4 MONTHS OLD. HIS DOCTOR REFERRED HIM TO A SPECIALIST WHO STATES ISSUES ARE FROM SLEEPER.	Y11B5538A	plagiocephaly & torticollis
48	Y1215840A	PA	(9)(b)	206	1	1/20/2012	9/1/2011	F	1543	MATTEL / FISHER-PRICE	ROCK 'N PLAY SLEEPER BUTTERFLY	THE CONSUMER STATED THAT HER 6 MOF DAUGHTER HAS ACID REFLUX AND HAD BEEN SLEEPING IN SLEEPER. AT THIS TIME, SHE NOTICED THAT THE SIDE OF HER CHILD'S HEAD WAS FLAT AND SHE LEANED HER HEAD TO ONE SIDE. SHE WAS DIAGNOSED WITH TORTICOLLIS AND PLAGIOCEPHALY.	Y1215840A	plagiocephaly & torticollis

49	Y11C5649A	GA		202	1	12/24/2011	1/1/2011	M	1537	MATTEL / FISHER-PRICE	M# R6070 / NEWBORN ROCK 'N SLEEPER	BOTH OF CONSUMERS SONS HAVE BEEN DIAGNOSED BY THEIR PEDIATRICIAN WITH FLAT HEAD & HAVE BEEN REFERRED TO A SPECIALIST. CONSUMER BELIEVES THIS IS FROM USE OF THE SLEEPER. BOTH CHILDREN'S CONDITION IMPROVED ONCE USE OF THE SLEEPER WAS DISCONTINUED.	Y11C5649A	plagiocephaly x2
50	Y1215799A	NY		204	1	1/21/2012	10/1/2011	D	1537	MATTEL / FISHER-PRICE / MATTEL / FISHER-PRICE	M# R6070 / NEWBORN ROCK 'N SLEEPER	THE CONSUMER STATED THAT SHE HAS 4 MONTHS-OLD TRIPLETS THAT HAVE VARYING DEGREES OF PLAGIOCEPHALY (FROM USE OF THE BABY HAMMOCK). THEIR DOCTOR HAS EXAMINED THE CHILDREN AND ADVISED HER THAT THEY WILL GROW AND DEVELOP OUT OF THE FLAT SPOTS. THE BABIES ARE 16, 15, AND 10 LBS.	Y1215799A	plagiocephaly x3
51	Y1215513A	NY		204	1	1/12/2012	12/21/2011	F	1537	MATTEL / FISHER-PRICE / MATTEL / FISHER-PRICE	M# R6070 / NEWBORN ROCK 'N SLEEPER	THE CONSUMER STATED THAT HER DAUGHTER WAS DIAGNOSED BY THE PEDIATRICIAN WITH TORTICOLLIS AND WILL REQUIRE PHYSICAL THERAPY. HER PEDIATRICIAN ADVISED HER THAT IT IS A DIRECT RESULT OF USING THE SLEEPER.	Y1215513A	torticollis
52	Y1215803A	NY		0	9	1/21/2012	12/1/2011	F	1537	MATTEL / FISHER-PRICE / MATTEL / FISHER-PRICE	M# R6070 / NEWBORN ROCK 'N SLEEPER	THE CONSUMER STATED THAT HER DAUGHTER'S UPPER TORSO AND NECK LEANS FORWARD SINCE USING THE BABY HAMMOCK. THE CONSUMER AND HER HUSBAND BELIEVE IT MAY HAVE BEEN CAUSED FROM CONTINUED USAGE WITH THIS PRODUCT.	Y1215803A	torticollis
53	110524CQC255Z	OH		206		7/12/2011	12/1/2010	F	1537	FISHER-PRICE, INC.	NEWBORN ROCK 'N SLEEPER	A SIX-MONTH-OLD FEMALE DEVELOPED TORTICOLLIS AFTER SLEEPER USE. THE VICTIM WAS PLACED IN THE SLEEPER AT VICTIM'S HOME FOR NAPS AND OVERNIGHT SLEEP EVERYDAY FROM ZERO TO SIX MONTHS OLD. THE TORTICOLLIS WAS EVIDENT AT THREE WEEKS OLD BUT VICTIM WAS NOT DIAGNOSED WITH TORTICOLLIS UNTIL FOUR MONTHS OLD. THE CONNECTION BETWEEN THE SLEEPER AND THE TORTICOLLIS WAS NOT DISCOVERED UNTIL VICTIM WAS SIX MONTHS OLD.	11150455A	torticollis
54	Y1185609A	OH		204	1	8/25/2011	12/20/2010	D	1558	MATTEL / FISHER-PRICE	M# R6070 / NEWBORN ROCK 'N SLEEPER	CPSC REPORT STATED THAT CHILD DEVELOPED TORTICOLLIS AFTER USING THE SLEEPER EVERYDAY FOR 6 MONTHS. SLEEPER WAS USED FOR NAPS AND OVERNIGHT SLEEP. THE TORTICOLLIS WAS EVIDENT AT THREE WEEKS OLD BUT NOT DIAGNOSED UNTIL 4 MONTHS OLD. CHILD WAS SEEN BY PEDIATRICIAN & P.T.	Y1185609A	torticollis
56	Y11C5645A	VA		203	1	12/24/2011	9/1/2011	F	1537	MATTEL / FISHER-PRICE	M# R6070 / NEWBORN ROCK 'N SLEEPER	THE CONSUMER STATED THAT SHE STARTED USING THIS PRODUCT WHEN HER DAUGHTER WAS 6 WEEKS OLD & WHEN SHE WAS ALMOST 4 MONTHS OLD SHE TOOK HER TO THE DOCTOR BECAUSE SHE NOTICED SOME HEAD ISSUES. SHE WAS DIAGNOSED WITH TORTICOLLIS & HAS STARTED PHYSICAL THERAPY.	Y11C5645A	torticollis
57	Y11C5645A	NY		ns	1	12/14/2011	NS	F	1537	FISHER-PRICE, INC.	V0197	CONSUMER STATED THAT HER TWIN DAUGHTERS HAVE BOTH BEEN DIAGNOSED WITH TORTICOLLIS AND PLAGIOCEPHALY. THEY ARE CURRENTLY UNDERGOING HELMET THERAPY. THE DOCTOR HAS ADVISED THAT THIS COULD BE A RESULT OF USING THE ROCK 'N PLAY SLEEPER. THE CONSUMER HAS TWIN DAUGHTERS AND TWO PRODUCTS. A SEPARATE CASE WILL BE ESTABLISHED.	Reported to firm - not to CPSC	torticollis/plagiocephaly

(b)(6)

ns

1 12/14/2011

NS

F

1537

V0197

SEE INCIDENT REPORT ABOVE.

Reported to firm - not to CPSC

torticollis/plagiocephaly

**Clearinghouse Format - With Manufacturer
Reported Incidents
U.S. Consumer Product Safety Commission
National Injury Information Clearinghouse**

11/2/2012

Page 4

Document Number : Y1235489A **Task Number :** **Issue :** 0
Date Received : 03/01/2012 **Confirmed :** **Date Entered :** 03/06/2012
City : (b)(6) **State :** AR **Zip :** (b)(6) **Date Notified :**
Source : 6 **Type Of Contact :** 10 OFFICE OF COMPLIANCE
Prod : 1537 BASSINETS OR CRADLES
Prod : 0 NO SECOND PRODUCT INVOLVEMENT
Date Injured : 08/01/2011 D **Work Related :** N
Age : 202 **Sex :** 1 MALE
Disposition : 1 1=TREATED & RELEASED, OR EX/Haz Type : F OTHER
Brand : MATTEL / MATTEL / FISHER-PRICE **Screened? :**
Model : M# R6070 / NEWBORN ROCK 'N PLAY SLEEPER

Narrative :

THE CONSUMER STATED THAT THE BACK OF HER SON'S HEAD HAS BECOME FLATTE
 NED SINCE THE USE OF THE PRODUCT. THE CHILD HAS SEEN THE PEDIATRICIA
 N AND A NEUROLOGIST, AND HAD X-RAYS. SHE OWNS TWO OF THE SAME PRODUC
 TS WITH THE SAME ISSUE WITH HER TWIN BOYS.

Document Number : Y1235854A **Task Number :** **Issue :** 0
Date Received : 03/29/2012 **Confirmed :** **Date Entered :** 04/04/2012
City : SANTA CLARITA **State :** CA **Zip :** (b)(6) **Date Notified :**
Source : 6 **Type Of Contact :** 10 OFFICE OF COMPLIANCE
Prod : 1537 BASSINETS OR CRADLES
Prod : 0 NO SECOND PRODUCT INVOLVEMENT
Date Injured : 03/22/2012 D **Work Related :** N
Age : 0 **Sex :** 1 MALE
Disposition : 1 1=TREATED & RELEASED, OR EX/Haz Type : F OTHER
Brand : MATTEL / FISHER-PRICE **Screened? :**
Model : M# R6070 / NEWBORN ROCK 'N PLAY SLEEPER

Narrative :

THE CONSUMER STATED THAT HER SON USED THE PRODUCT FOR 4 MONTHS FOR NA
 PS AND OVERNIGHT SLEEPING. THE CHILD DEVELOPED TORTICOLLIS AND PLAGI
 OCEPHALY WHICH RESULTED IN 18 MONTHS OF PHYSICAL THERAPY & 2 DIFFEREN
 T HELMETS.

Document Number : Y1235887A **Task Number :** **Issue :** 0
Date Received : 03/29/2012 **Confirmed :** **Date Entered :** 04/04/2012
City : SAN JOSE **State :** CA **Zip :** (b)(6) **Date Notified :**
Source : 6 **Type Of Contact :** 10 OFFICE OF COMPLIANCE
Prod : 1537 BASSINETS OR CRADLES
Prod : 0 NO SECOND PRODUCT INVOLVEMENT
Date Injured : 01/10/2012 D **Work Related :** N
Age : 207 **Sex :** 1 MALE
Disposition : 1 1=TREATED & RELEASED, OR EX/Haz Type : F OTHER
Brand : MATTEL / FISHER-PRICE **Screened? :**
Model : M# V9197 / RNP SLEEPER-CIRCLES

Narrative :

CONSUMER'S CHILD SLEPT IN THE SLEEPER EVERY NIGHT BEGINNING AUGUST 10
 , 2011 UNTIL JANUARY 10, 2012. THE CHILD WAS DIAGNOSED HIM WITH OCC
 IPITAL PLAGIOCEPHALY & PRESCRIBED AN ORTHOPEDICS HELMET TO RESHAPE HI
 S HEAD. THE PEDIATRICIAN STATED THAT THE SLEEPER CAUSED FLAT SPOTS

**Clearinghouse Format - With Manufacturer
Reported Incidents
U.S. Consumer Product Safety Commission
National Injury Information Clearinghouse**

11/2/2012

Page 5

Document Number : Y1245544A **Task Number :** **Issue :** 0
Date Received : 04/05/2012 **Confirmed :** **Date Entered :** 04/10/2012
City : (b)(6) **State :** CA **Zip :** (b)(6) **Date Notified :**
Source : 6 **Type Of Contact :** 10 OFFICE OF COMPLIANCE
Prod : 1537 BASSINETS OR CRADLES
Prod : 0 NO SECOND PRODUCT INVOLVEMENT
Date Injured : 12/15/2011 D **Work Related :** N
Age : 202 **Sex :** 1 MALE
Disposition : 1 1=TREATED & RELEASED, OR EX/Haz Type : F OTHER
Brand : MATTEL / FISHER-PRICE **Screened? :**
Model : M# V9197 / RNP SLEEPER-CIRCLES

Narrative :

CONSUMER'S SON SLEPT IN THE SLEEPER 8 HOURS A NIGHT FROM BIRTH UNTIL 8 WEEKS OLD. HE NOW HAS BRACHYCEPHALY & THE PEDIATRICIAN SAID THAT IT WILL NOT CORRECT ITSELF & TO TRY RE-POSITIONING FOR A PERIOD OF TIME AND IF IT DID NOT SELF-CORRECT A HELMET WILL BE NEEDED.

Document Number : Y1245545A **Task Number :** **Issue :** 0
Date Received : 04/05/2012 **Confirmed :** **Date Entered :** 04/10/2012
City : LEXINGTON **State :** KY **Zip :** (b)(6) **Date Notified :**
Source : 6 **Type Of Contact :** 10 OFFICE OF COMPLIANCE
Prod : 1537 BASSINETS OR CRADLES
Prod : 0 NO SECOND PRODUCT INVOLVEMENT
Date Injured : 10/01/2011 D **Work Related :** N
Age : 203 **Sex :** 1 MALE
Disposition : 1 1=TREATED & RELEASED, OR EX/Haz Type : F OTHER
Brand : MATTEL / FISHER-PRICE **Screened? :**
Model : M# V9197 / RNP SLEEPER-CIRCLES

Narrative :

CONSUMER'S SON WAS DIAGNOSED BY PEDIATRICIAN WITH A FLAT HEAD. SHE BELIEVES THIS IS FROM THE USE OF THIS PRODUCT SINCE IT IS THE ONLY PLACE HE SLEEPS. THE PEDIATRICIAN STATED HE WOULD LIKE TO SEE THE HER BABY IN A FEW WEEKS AND MAY NEED TO PRESCRIBE A HELMET TO CORRECT IT.

Document Number : Y1245546A **Task Number :** **Issue :** 0
Date Received : 04/05/2012 **Confirmed :** **Date Entered :** 04/10/2012
City : (b)(6) **State :** MA **Zip :** (b)(6) **Date Notified :**
Source : 6 **Type Of Contact :** 10 OFFICE OF COMPLIANCE
Prod : 1537 BASSINETS OR CRADLES
Prod : 0 NO SECOND PRODUCT INVOLVEMENT
Date Injured : 07/01/2011 D **Work Related :** N
Age : 202 **Sex :** 1 MALE
Disposition : 1 1=TREATED & RELEASED, OR EX/Haz Type : F OTHER
Brand : MATTEL / FISHER-PRICE **Screened? :**
Model : M# V9197 / RNP SLEEPER-CIRCLES

Narrative :

THE CONSUMER STATED THAT HER SON HAS DEVELOPED A FLAT SPOT ON THE RIGHT SIDE OF HIS HEAD. SHE ALSO STATED HIS NECK HAS THE TENDENCY TO TURN TO ONE SIDE. THE CHILD WAS TAKEN FOR A CHECK UP RECENTLY AND THE PEDIATRICIAN NOTED THESE ISSUES.

**Clearinghouse Format - With Manufacturer
Reported Incidents
U.S. Consumer Product Safety Commission
National Injury Information Clearinghouse**

11/2/2012

Page 6

Document Number : Y1245843A **Task Number :** **Issue :** 0
Date Received : 04/26/2012 **Confirmed :** **Date Entered :** 05/02/2012
City : (b)(6) **State :** VA **Zip :** (b)(6) **Date Notified :**
Source : 6 **Type Of Contact :** 10 OFFICE OF COMPLIANCE
Prod : 1537 BASSINETS OR CRADLES
Prod : 0 NO SECOND PRODUCT INVOLVEMENT
Date Injured : 02/01/2012 D **Work Related :** N
Age : 208 **Sex :** 0 UNKNOWN
Disposition : 1 1=TREATED & RELEASED, OR EX/Haz Type : F OTHER
Brand : MATTEL / FISHER-PRICE **Screened? :**
Model : M# R6070 / NEWBORN ROCK 'N PLAY SLEEPER

Narrative :

THE CONSUMER STATED THAT HER 8 MONTH OLD CHILD WAS DIAGNOSED WITH PHA
GIOCEPHALY. IT WAS DETERMINED THAT THE CHILD NEEDED A HELMET.

Document Number : Y1265488A **Task Number :** **Issue :** 0
Date Received : 06/07/2012 **Confirmed :** **Date Entered :** 06/13/2012
City : (b)(6) **State :** CA **Zip :** (b)(6) **Date Notified :**
Source : 6 **Type Of Contact :** 10 OFFICE OF COMPLIANCE
Prod : 1537 BASSINETS OR CRADLES
Prod : 0 NO SECOND PRODUCT INVOLVEMENT
Date Injured : 05/24/2012 D **Work Related :** N
Age : 204 **Sex :** 0 UNKNOWN
Disposition : 1 1=TREATED & RELEASED, OR EX/Haz Type : F OTHER
Brand : MATTEL / FISHER-PRICE **Screened? :**
Model : M# V9197 / RNP SLEEPER-CIRCLES

Narrative :

CONSUMER STATED THAT 4 MONTH OLD CHILD SLEPT IN THE SLEEPER EVERY NIG
HT. THE CHILD HAD 4 MONTH CHECK UP & DOCTOR STATED THAT CHILD HAS A
FLAT SPOT ON HEAD & TORTICOLLIS FROM THE USE OF THE SLEEPER. HE PRESC
RIBED IN-HOME STRETCHING EXERCISES & ADVISED TO STOP USING THE UNIT.

Document Number : Y1265709A **Task Number :** 120627CCC1774 **Issue :** 0
Date Received : 06/21/2012 **Confirmed :** **Date Entered :** 06/26/2012
City : STATEN ISLAND **State :** NY **Zip :** (b)(6) **Date Notified :**
Source : 6 **Type Of Contact :** 10 OFFICE OF COMPLIANCE
Prod : 1537 BASSINETS OR CRADLES
Prod : 0 NO SECOND PRODUCT INVOLVEMENT
Date Injured : 06/07/2012 D **Work Related :** N
Age : 201 **Sex :** 1 MALE
Disposition : 1 1=TREATED & RELEASED, OR EX/Haz Type : 7 ALLERGIC REACTION
Brand : MATTEL / MATTEL / FISHER-PRICE **Screened? :**
Model : M# X3840 / NEWBORN ROCK 'N PLAY SLEEPER

Narrative :

THE CONSUMER STATED THAT 1 MOM HAS BEEN TAKEN TO THE DOCTOR ON SEVERA
L OCCASIONS FOR CONGESTION AND COUGHING. THE DOCTOR PRESCRIBED A LIQU
ID MEDICATION TO TREAT THE CONGESTION. SHE BELIEVES IT HAS BEEN CAUS
ED BY MOLD FOUND ON THE BACK OF THE PAD OF THE BASSINET.

**Clearinghouse Format - With Manufacturer
Reported Incidents
U.S. Consumer Product Safety Commission
National Injury Information Clearinghouse**

11/2/2012

Page 7

Document Number : Y1265790A **Task Number :** **Issue :** 0
Date Received : 06/28/2012 **Confirmed :** **Date Entered :** 07/04/2012
City : (b)(6) **State :** KY **Zip :** (b)(6) **Date Notified :**
Source : 6 **Type Of Contact :** 10 OFFICE OF COMPLIANCE
Prod : 1537 BASSINETS OR CRADLES
Prod : 0 NO SECOND PRODUCT INVOLVEMENT
Date Injured : 06/12/2012 D **Work Related :** N
Age : 203 **Sex :** 1 MALE
Disposition : 1 1=TREATED & RELEASED, OR EX/Haz Type : F OTHER
Brand : MATTEL / FISHER-PRICE **Screened? :**
Model : M# R6070 / NEWBORN ROCK 'N PLAY SLEEPER

Narrative :

THE CONSUMER STATED THAT 3 MOM WAS TAKEN TO THE DOCTOR AND DIAGNOSED WITH PLAGIOCEPHALY. THE CHILD IS IN THE PRODUCT ABOUT 10 HOURS A DAY. HE IS REQUIRED TO WEAR A HELMET. THE CONSUMER IS LOOKING FOR COMPENSATION FOR THE COST OF THE HELMET.

Document Number : Y1265836A **Task Number :** **Issue :** 0
Date Received : 06/28/2012 **Confirmed :** **Date Entered :** 07/04/2012
City : (b)(6) **State :** AR **Zip :** (b)(6) **Date Notified :**
Source : 6 **Type Of Contact :** 10 OFFICE OF COMPLIANCE
Prod : 1537 BASSINETS OR CRADLES
Prod : 0 NO SECOND PRODUCT INVOLVEMENT
Date Injured : 12/01/2011 D **Work Related :** U
Age : 202 **Sex :** 2 FEMALE
Disposition : 1 1=TREATED & RELEASED, OR EX/Haz Type : F OTHER
Brand : MATTEL / FISHER-PRICE **Screened? :**
Model : M# X3840 / NEWBORN ROCK 'N PLAY SLEEPER

Narrative :

CONSUMER STATED THAT HER DAUGHTER DEVELOPED A FLAT SPOT ON THE BACK OF HER HEAD FROM SLEEPING IN THE ROCKER FOR MORE THAN 12 HOURS PER DAY. SHE WAS REFERRED TO A SPECIALIST AT FOUR MONTHS OLD, & WAS PRESCRIBED AN ORTHODIC HELMET TO WEAR FOR 23 HOURS PER DAY.

Document Number : Y1275888A **Task Number :** **Issue :** 0
Date Received : 07/26/2012 **Confirmed :** **Date Entered :** 08/09/2012
City : (b)(6) **State :** CA **Zip :** (b)(6) **Date Notified :**
Source : 6 **Type Of Contact :** 10 OFFICE OF COMPLIANCE
Prod : 1537 BASSINETS OR CRADLES
Prod : 0 NO SECOND PRODUCT INVOLVEMENT
Date Injured : 07/19/2012 D **Work Related :** N
Age : 204 **Sex :** 2 FEMALE
Disposition : 1 1=TREATED & RELEASED, OR EX/Haz Type : F OTHER
Brand : MATTEL / FISHER-PRICE **Screened? :**
Model : M# R6070 / NEWBORN ROCK 'N PLAY SLEEPER

Narrative :

GENDER: FEMALE; INJURY TYPE: PLAGIOCEPHALY/FLATHEAD; THE CONSUMER STATED THAT HER 4 MONTHS OLD GRANDDAUGHTER'S HEAD IS DEFORMED FROM SLEEPING IN THIS SLEEPER. THE BABY'S PEDIATRICIAN STATED THAT AN ORTHOTIC HELMET WILL BE NECESSARY TO RESHAPE HER HEAD.

**Clearinghouse Format - With Manufacturer
Reported Incidents
U.S. Consumer Product Safety Commission
National Injury Information Clearinghouse**

11/2/2012

Page 8

Document Number : Y1275889A **Task Number :** **Issue :** 0
Date Received : 07/26/2012 **Confirmed :** **Date Entered :** 08/09/2012
City : (b)(6) **State :** PA **Zip :** (b)(6) **Date Notified :**
Source : 6 **Type Of Contact :** 10 OFFICE OF COMPLIANCE
Prod : 1537 BASSINETS OR CRADLES
Prod : 0 NO SECOND PRODUCT INVOLVEMENT
Date Injured : 04/23/2011 D **Work Related :** N
Age : 218 **Sex :** 1 MALE
Disposition : 9 9=UNKNOWN, NOT STATED, ETC. **Haz Type :** F OTHER
Brand : MATTEL / FISHER-PRICE **Screened? :**
Model : M# R6070 / NEWBORN ROCK 'N PLAY SLEEPER

Narrative :

AGE AT THE TIME OF INCIDENT: 1YEAR(S) 6MONTH(S); GENDER: MALE; DATE OF INCIDENT: 04/23/2011; INJURY FLAG : YES; INJURY # 1 INJURY TYPE: P LAGIOCEPHALY/FLATHEAD; THE CONSUMER STATED THAT SHE USED THE SLEEPER AND AFTER A FEW MONTHS OF USE HER SON'S HEAD STARTED TO FLATTEN.

Document Number : Y1275890A **Task Number :** **Issue :** 0
Date Received : 07/26/2012 **Confirmed :** **Date Entered :** 08/09/2012
City : (b)(6) **State :** TX **Zip :** (b)(6) **Date Notified :**
Source : 6 **Type Of Contact :** 10 OFFICE OF COMPLIANCE
Prod : 1537 BASSINETS OR CRADLES
Prod : 0 NO SECOND PRODUCT INVOLVEMENT
Date Injured : 07/10/2012 D **Work Related :** N
Age : 0 **Sex :** 2 FEMALE
Disposition : 1 1=TREATED & RELEASED, OR EX/Haz Type : F OTHER
Brand : MATTEL / FISHER-PRICE **Screened? :**
Model : M# R6070 / NEWBORN ROCK 'N PLAY SLEEPER

Narrative :

INJURY FLAG : YES; INJURY TYPE: PLAGIOCEPHALY/FLATHEAD; THE CONSUMER STATED THAT AFTER CONTINUOUS USE OF THE SLEEPER THE BACK OF HER DAUGHTER'S HEAD FLATTENED. HER DOCTOR ADVISED THAT SHE DISCONTINUE USE OF THE PRODUCT.

Document Number : Y1275891A **Task Number :** **Issue :** 0
Date Received : 07/26/2012 **Confirmed :** **Date Entered :** 08/09/2012
City : (b)(6) **State :** SC **Zip :** (b)(6) **Date Notified :**
Source : 6 **Type Of Contact :** 10 OFFICE OF COMPLIANCE
Prod : 1537 BASSINETS OR CRADLES
Prod : 0 NO SECOND PRODUCT INVOLVEMENT
Date Injured : 03/01/2012 D **Work Related :** N
Age : 202 **Sex :** 1 MALE
Disposition : 9 9=UNKNOWN, NOT STATED, ETC. **Haz Type :** F OTHER
Brand : MATTEL / FISHER-PRICE **Screened? :**
Model : M# R6070 / NEWBORN ROCK 'N PLAY SLEEPER

Narrative :

THE CONSUMER STATED THAT HER 2 MONTHS OLD SON DEVELOPED A FLAT SPOT ON THE BACK OF HIS HEAD FROM USING THIS SLEEPER.

**Clearinghouse Format - With Manufacturer
Reported Incidents
U.S. Consumer Product Safety Commission
National Injury Information Clearinghouse**

11/2/2012

Page 9

Document Number : Y1275892A **Task Number :** **Issue :** 0
Date Received : 07/26/2012 **Confirmed :** **Date Entered :** 08/09/2012
City : (b)(6) **State :** FL **Zip :** (b)(6) **Date Notified :**
Source : 6 **Type Of Contact :** 10 OFFICE OF COMPLIANCE
Prod : 1537 BASSINETS OR CRADLES
Prod : 0 NO SECOND PRODUCT INVOLVEMENT
Date Injured : 02/01/2012 D **Work Related :** N
Age : 202 **Sex :** 1 MALE
Disposition : 1 1=TREATED & RELEASED, OR EX/ **Haz Type :** F OTHER
Brand : MATTEL / FISHER-PRICE **Screened? :**
Model : M# R6070 / NEWBORN ROCK 'N PLAY SLEEPER

Narrative :

THE CONSUMER STATED THAT HER 2 MONTHS OLD SON HAS DEVELOPED A FLAT SPOT ON THE RIGHT SIDE OF HIS HEAD FROM SLEEPING IN THE SLEEPER FOR APPROXIMATELY 6-7 HOURS PER DAY. HER PEDIATRICIAN EXAMINED THE CHILD AND ADVISED HER TO DISCONTINUE USE OF THE ITEM.

Document Number : Y1275893A **Task Number :** **Issue :** 0
Date Received : 07/26/2012 **Confirmed :** **Date Entered :** 08/09/2012
City : (b)(6) **State :** CA **Zip :** (b)(6) **Date Notified :**
Source : 6 **Type Of Contact :** 10 OFFICE OF COMPLIANCE
Prod : 1537 BASSINETS OR CRADLES
Prod : 0 NO SECOND PRODUCT INVOLVEMENT
Date Injured : 03/01/2012 D **Work Related :** N
Age : 201 **Sex :** 2 FEMALE
Disposition : 9 9=UNKNOWN, NOT STATED, ETC. **Haz Type :** F OTHER
Brand : MATTEL / FISHER-PRICE **Screened? :**
Model : M# R6070 / NEWBORN ROCK 'N PLAY SLEEPER

Narrative :

THE CONSUMER STATED THAT THE BACK OF HER 1 MONTH OLD DAUGHTER'S HEAD HAS FLATTENED SINCE USE OF THIS SLEEPER.

Document Number : Y1275894A **Task Number :** **Issue :** 0
Date Received : 07/26/2012 **Confirmed :** **Date Entered :** 08/09/2012
City : (b)(6) **State :** SC **Zip :** (b)(6) **Date Notified :**
Source : 6 **Type Of Contact :** 10 OFFICE OF COMPLIANCE
Prod : 1537 BASSINETS OR CRADLES
Prod : 0 NO SECOND PRODUCT INVOLVEMENT
Date Injured : 12/01/2010 D **Work Related :** N
Age : 202 **Sex :** 1 MALE
Disposition : 1 1=TREATED & RELEASED, OR EX/ **Haz Type :** F OTHER
Brand : MATTEL / FISHER-PRICE **Screened? :**
Model : M# R6070 / NEWBORN ROCK 'N PLAY SLEEPER

Narrative :

THE CONSUMER STATED THAT AT HER SON'S TWO MONTH CHECKUP, HER PEDIATRICIAN NOTICED THAT THE CHILD HAD DEVELOPED A FLAT SPOT ON HIS HEAD. THE DOCTOR TOLD HER TO DISCONTINUE USING THE SLEEPER. SINCE THAT TIME, THE FLAT SPOT HAS BECOME MORE ROUNDED NATURALLY.

**Clearinghouse Format - With Manufacturer
Reported Incidents
U.S. Consumer Product Safety Commission
National Injury Information Clearinghouse**

11/2/2012

Page 10

Document Number : Y1275895A **Task Number :** **Issue :** 0
Date Received : 07/26/2012 **Confirmed :** **Date Entered :** 08/09/2012
City : (b)(6) **State :** FL **Zip :** (b)(6) **Date Notified :**
Source : 6 **Type Of Contact :** 10 OFFICE OF COMPLIANCE
Prod : 1537 BASSINETS OR CRADLES
Prod : 0 NO SECOND PRODUCT INVOLVEMENT
Date Injured : 01/11/2012 D **Work Related :** N
Age : 204 **Sex :** 2 FEMALE
Disposition : 1 1=TREATED & RELEASED, OR EX/Haz Type : F OTHER
Brand : MATTEL / FISHER-PRICE **Screened? :**
Model : M# R6070 / NEWBORN ROCK 'N PLAY SLEEPER

Narrative :

THE CONSUMER STATED THAT HER 4 MONTHS OLD DAUGHTER HAS BEEN DIAGNOSED WITH FLATHEAD AND NECK ISSUES. THE CONSUMER'S PEDIATRICIAN IS ATTRIBUTING THIS TO USE OF THE SLEEPER. THE CHILD HAS BEEN REFERRED TO A PHYSICAL THERAPIST.

Document Number : Y1275896A **Task Number :** **Issue :** 0
Date Received : 07/26/2012 **Confirmed :** **Date Entered :** 08/09/2012
City : (b)(6) **State :** PA **Zip :** (b)(6) **Date Notified :**
Source : 6 **Type Of Contact :** 10 OFFICE OF COMPLIANCE
Prod : 1537 BASSINETS OR CRADLES
Prod : 0 NO SECOND PRODUCT INVOLVEMENT
Date Injured : 12/01/2011 D **Work Related :** N
Age : 203 **Sex :** 2 FEMALE
Disposition : 9 9=UNKNOWN, NOT STATED, ETC. Haz Type : F OTHER
Brand : MATTEL / FISHER-PRICE **Screened? :**
Model : M# R6070 / NEWBORN ROCK 'N PLAY SLEEPER

Narrative :

THE CONSUMER STATED THAT HER 3 MONTH OLD DAUGHTER HAS DEVELOPED A FLAT SPOT ON THE BACK OF HER HEAD WHERE HER HEAD RUBS ON THE PLASTIC SEAT INSERT OF THE SLEEPER.

Document Number : Y1275897A **Task Number :** **Issue :** 0
Date Received : 07/26/2012 **Confirmed :** **Date Entered :** 08/09/2012
City : (b)(6) **State :** NY **Zip :** (b)(6) **Date Notified :**
Source : 6 **Type Of Contact :** 10 OFFICE OF COMPLIANCE
Prod : 1537 BASSINETS OR CRADLES
Prod : 0 NO SECOND PRODUCT INVOLVEMENT
Date Injured : 10/01/2011 D **Work Related :** N
Age : 204 **Sex :** 0 UNKNOWN
Disposition : 1 1=TREATED & RELEASED, OR EX/Haz Type : F OTHER
Brand : MATTEL / FISHER-PRICE **Screened? :**
Model : M# R6070 / NEWBORN ROCK 'N PLAY SLEEPER

Narrative :

THE CONSUMER STATED THAT SHE HAS 4 MONTH OLD TRIPLETS THAT HAVE VARYING DEGREES OF PLAGIOCEPHALY. THEIR DOCTOR HAS EXAMINED THE CHILDREN AND ADVISED HER THAT THEY WILL GROW AND DEVELOP OUT OF THE FLAT SPOTS DUE TO SLEEPER. THE BABIES ARE 16, 15, AND 10 LBS.

**Clearinghouse Format - With Manufacturer
Reported Incidents
U.S. Consumer Product Safety Commission
National Injury Information Clearinghouse**

11/2/2012

Page 11

Document Number : Y1275961A **Task Number :** **Issue :** 0
Date Received : 07/26/2012 **Confirmed :** **Date Entered :** 08/03/2012
City : SPOKANE **State :** WA **Zip :** (b) (6) **Date Notified :**
Source : 6 **Type Of Contact :** 10 OFFICE OF COMPLIANCE
Prod : 1537 BASSINETS OR CRADLES
Prod : 0 NO SECOND PRODUCT INVOLVEMENT
Date Injured : 04/01/2012 D **Work Related :** U
Age : 203 **Sex :** 2 FEMALE
Disposition : 1 1=TREATED & RELEASED, OR EX/Haz Type : F OTHER
Brand : MATTEL / FISHER-PRICE **Screened? :**
Model : M# W9443 / NEWBORN ROCK N' PLAY SLEEPER

Narrative :

CONSUMER STATED THAT HER DAUGHTER HAS DEVELOPED A FLAT SPOT ON THE BACK OF HER HEAD SINCE USE OF THIS PRODUCT. THE PRODUCT WAS USED FOR NAPS & NIGHT TIME SLEEPING. SHE TOOK HER DAUGHTER TO THE PEDIATRICIAN, NEUROLOGIST & AN ORTHOTIC SPECIALIST. SHE WAS FITTED FOR HELMET.

Document Number : Y1285566A **Task Number :** **Issue :** 0
Date Received : 08/09/2012 **Confirmed :** **Date Entered :** 08/18/2012
City : (b) (6) **State :** NY **Zip :** (b) (6) **Date Notified :**
Source : 6 **Type Of Contact :** 10 OFFICE OF COMPLIANCE
Prod : 1537 BASSINETS OR CRADLES
Prod : 0 NO SECOND PRODUCT INVOLVEMENT
Date Injured : 04/01/2012 D **Work Related :** N
Age : 207 **Sex :** 1 MALE
Disposition : 1 1=TREATED & RELEASED, OR EX/Haz Type : F OTHER
Brand : MATTEL / FISHER-PRICE **Screened? :**
Model : M# R6070 / NEWBORN ROCK 'N PLAY SLEEPER

Narrative :

AGE AT THE TIME OF INCIDENT: 7MONTH(S); MALE; DATE OF INCIDENT: 04/01/2012; THE CONSUMER STATED THAT HER SON DEVELOPED A FLAT HEAD FROM USING THE SLEEPER. HE WAS TAKEN TO THE DOCTOR WHEN HE WAS 4 MONTHS OLD AND WAS PRESCRIBED A HELMET TO CORRECT THE SHAPE OF HIS HEAD.

Document Number : Y1285589A **Task Number :** **Issue :** 0
Date Received : 08/09/2012 **Confirmed :** **Date Entered :** 08/15/2012
City : (b) (6) **State :** OH **Zip :** (b) (6) **Date Notified :**
Source : 6 **Type Of Contact :** 10 OFFICE OF COMPLIANCE
Prod : 1537 BASSINETS OR CRADLES
Prod : 0 NO SECOND PRODUCT INVOLVEMENT
Date Injured : 02/01/2012 D **Work Related :** N
Age : 201 **Sex :** 1 MALE
Disposition : 1 1=TREATED & RELEASED, OR EX/Haz Type : F OTHER
Brand : MATTEL / FISHER-PRICE **Screened? :**
Model : M# V9102 / ROCK 'N PLAY SLEEPER

Narrative :

AGE 1MONTH; WEIGHT: 9LBS; MALE; DATE: 02/01/2012; INJURY: PLAGIOCEPHALY/FLATHEAD; THE CONSUMER STATED THAT HER SON DEVELOPED A FLAT HEAD AFTER USING THE SLEEPER. HE HAS BEEN PRESCRIBED A HELMET TO RESHAPE HIS HEAD. HE USED THE SLEEPER OVERNIGHT FOR THE FIRST MONTH THEN NAPS.

**Clearinghouse Format - With Manufacturer
Reported Incidents
U.S. Consumer Product Safety Commission
National Injury Information Clearinghouse**

11/2/2012

Page 12

Document Number : Y1285701A **Task Number :** **Issue :** 0
Date Received : 08/16/2012 **Confirmed :** **Date Entered :** 08/24/2012
City : (b)(6) **State :** IL **Zip :** (b)(6) **Date Notified :**
Source : 6 **Type Of Contact :** 10 OFFICE OF COMPLIANCE
Prod : 1537 BASSINETS OR CRADLES
Prod : 0 NO SECOND PRODUCT INVOLVEMENT
Date Injured : 08/03/2012 D **Work Related :** N
Age : 206 **Sex :** 2 FEMALE
Disposition : 1 1=TREATED & RELEASED, OR EX/Haz Type : F OTHER
Brand : MATTEL / FISHER-PRICE **Screened? :**
Model : M# V9196 / ROCK 'N PLAY SLEEPER-BUTTERFLY

Narrative :

6 MOF; CONSUMER STATED THAT HER DAUGHTER SLEPT IN THE PRODUCT EVERY NIGHT FOR 2 MONTHS & THEN TOOK NAPS IN IT. SHE WAS DIAGNOSED BY A PLASTIC SURGEON WITH TORTICOLLIS & PLAGIOCEPHALY. SHE WILL BE IN PHYSICAL THERAPY AND WILL UNDERGO CRANIAL HELMET THERAPY FOR 4-6 MONTHS

Document Number : Y1285702A **Task Number :** 120824CCC2930 **Issue :** 0
Date Received : 08/16/2012 **Confirmed :** **Date Entered :** 08/24/2012
City : (b)(6) **State :** MN **Zip :** (b)(6) **Date Notified :**
Source : 6 **Type Of Contact :** 10 OFFICE OF COMPLIANCE
Prod : 1537 BASSINETS OR CRADLES
Prod : 0 NO SECOND PRODUCT INVOLVEMENT
Date Injured : 07/11/2012 D **Work Related :** N
Age : 206 **Sex :** 1 MALE
Disposition : 1 1=TREATED & RELEASED, OR EX/Haz Type : 7 ALLERGIC REACTION
Brand : MATTEL / FISHER-PRICE **Screened? :**
Model : M# W9443 / NEWBORN ROCK N' PLAYT SOOTHER

Narrative :

6 MOM; MOLD HAS FORMED ON THE LINER OF THEIR SLEEPER. CONSUMER BELIEVES HER SON ACQUIRED A COUGH AND UNEXPLAINABLE VOMITING FROM USAGE WITH THIS PRODUCT. THEY HAVE BEEN TO THEIR EMERGENCY ROOM ON THREE OCCASIONS FOR THIS ISSUE. HER SON RECEIVED A CHEST X-RAY.

Document Number : Y1285710A **Task Number :** **Issue :** 0
Date Received : 08/16/2012 **Confirmed :** **Date Entered :** 08/24/2012
City : BRONX **State :** NY **Zip :** (b)(6) **Date Notified :**
Source : 6 **Type Of Contact :** 10 OFFICE OF COMPLIANCE
Prod : 1537 BASSINETS OR CRADLES
Prod : 0 NO SECOND PRODUCT INVOLVEMENT
Date Injured : 07/01/2012 D **Work Related :** N
Age : 205 **Sex :** 1 MALE
Disposition : 0 0=NO INJURY **Haz Type :** 7 ALLERGIC REACTION
Brand : MATTEL / FISHER-PRICE **Screened? :**
Model : M# W9443 / NEWBORN ROCK N' PLAYT SOOTHER

Narrative :

AGE : 5MONTH(S); WEIGHT: (b)(6) GENDER: MALE; DATE OF INCIDENT: 07/01/2012; INJURY FLAG : NO; EVENT DESCRIPTION: THE CONSUMER EXPRESSED CONCERN THAT WHEN SHE REMOVED THE PAD FROM THE SLEEPER SHE DISCOVERED THAT THE BACK OF THE PAD AND THE SEAT WERE COVERED IN MOLD.

**Clearinghouse Format - With Manufacturer
Reported Incidents
U.S. Consumer Product Safety Commission
National Injury Information Clearinghouse**

11/2/2012

Page 13

Document Number : Y1285787A **Task Number :** **Issue :** 0
Date Received : 08/23/2012 **Confirmed :** **Date Entered :** 08/31/2012
City : (b)(6) **State :** NC **Zip :** (b)(6) **Date Notified :**
Source : 6 **Type Of Contact :** 10 OFFICE OF COMPLIANCE
Prod : 1537 BASSINETS OR CRADLES
Prod : 0 NO SECOND PRODUCT INVOLVEMENT
Date Injured : 01/12/2012 D **Work Related :** N
Age : 202 **Sex :** 2 FEMALE
Disposition : 1 1=TREATED & RELEASED, OR EX/Haz Type : F OTHER
Brand : MATTEL / FISHER-PRICE **Screened? :**
Model : M# R6070 / NEWBORN ROCK 'N PLAY SLEEPER

Narrative :

THE CONSUMER STATED THAT AFTER USING THE PRODUCT FOR TWO MONTHS SHE BEGAN NOTICING A FLAT SPOT ON THE BACK OF 2 MOF'S HEAD. AT HER CHECK-UP THE DOCTOR DIAGNOSED THE ISSUE AS PLAGIOCEPHALY AND PRESCRIBED HELMET FOR THE CHILD.

Document Number : Y1285956A **Task Number :** **Issue :** 0
Date Received : 08/30/2012 **Confirmed :** **Date Entered :** 09/12/2012
City : (b)(6) **State :** CA **Zip :** (b)(6) **Date Notified :**
Source : 6 **Type Of Contact :** 10 OFFICE OF COMPLIANCE
Prod : 1537 BASSINETS OR CRADLES
Prod : 0 NO SECOND PRODUCT INVOLVEMENT
Date Injured : 07/19/2012 D **Work Related :** N
Age : 203 **Sex :** 2 FEMALE
Disposition : 1 1=TREATED & RELEASED, OR EX/Haz Type : F OTHER
Brand : MATTEL / FISHER-PRICE **Screened? :**
Model : M# V9196 / ROCK 'N PLAY SLEEPER-BUTTERFLY

Narrative :

AGE AT THE TIME OF INCIDENT: 3MONTH(S); GENDER: FEMALE; DATE OF INCIDENT: 07/19/2012; INJURY LOCATION: HEAD/NECK: THE CONSUMER STATED THAT HER DAUGHTER SLEEPS IN THIS PRODUCT EVERY NIGHT AND HAS DEVELOPED TORTICOLLIS. SHE IS CURRENTLY RECEIVING PHYSICAL THERAPY.

Document Number : Y1285978A **Task Number :** 120910CCC3836 **Issue :** 0
Date Received : 08/30/2012 **Confirmed :** **Date Entered :** 09/07/2012
City : (b)(6) **State :** CA **Zip :** (b)(6) **Date Notified :**
Source : 6 **Type Of Contact :** 10 OFFICE OF COMPLIANCE
Prod : 1537 BASSINETS OR CRADLES
Prod : 0 NO SECOND PRODUCT INVOLVEMENT
Date Injured : 08/09/2012 D **Work Related :** N
Age : 203 **Sex :** 2 FEMALE
Disposition : 1 1=TREATED & RELEASED, OR EX/Haz Type : 7 ALLERGIC REACTION
Brand : MATTEL / FISHER-PRICE **Screened? :**
Model : M# W9443 / NEWBORN ROCK N' PLAYT SOOTHER

Narrative :

3 MO MALE & FEMALE TWINS HAD RESPIRATORY ISSUES & X-RAYED AT HOSPITAL. THEY WERE DIAGNOSED WITH BACTERIAL INFECTION. DOCTOR STATED IT WAS PROBABLY DUE TO MOLD ON THE PAD OF THE SLEEPER.

① mold

**Clearinghouse Format - With Manufacturer
Reported Incidents
U.S. Consumer Product Safety Commission
National Injury Information Clearinghouse**

11/2/2012

Page 14

Document Number : Y1285980A Task Number : Issue : 0
 Date Received : 08/30/2012 Confirmed : Date Entered : 09/07/2012
 City : (b)(6) State : NJ Zip : (b)(6) Date Notified :
 Source : 6 Type Of Contact : 10 OFFICE OF COMPLIANCE
 Prod : 1537 BASSINETS OR CRADLES
 Prod : 0 NO SECOND PRODUCT INVOLVEMENT
 Date Injured : 08/23/2012 D Work Related : N
 Age : 204 Sex : 1 MALE
 Disposition : 1 1=TREATED & RELEASED, OR EX/Haz Type : F OTHER
 Brand : MATTEL / FISHER-PRICE Screened? :
 Model : M# X3840 / NEWBORN ROCK 'N PLAY SLEEPER

Narrative :

4 MOM SLEPT IN THE SLEEPER FOR 4 MONTHS COULD NOT RAISE HIS HEAD. PED
 IATRICIAN DIAGNOSED HIM WITH TORTICOLLIS AND PLAGIOCEPHALY AND PUT IN
 PHYSICAL THERAPY FOR WEAK NECK MUSCLES. HE HAS UNDERGONE OTHER TEST
 BECAUSE WEAK MUSCLES HAVE CAUSED DEVELOPMENTAL DELAYS

Document Number : Y1295523A Task Number : Issue : 0
 Date Received : 09/05/2012 Confirmed : Date Entered : 09/13/2012
 City : (b)(6) State : IL Zip : (b)(6) Date Notified :
 Source : 6 Type Of Contact : 10 OFFICE OF COMPLIANCE
 Prod : 1537 BASSINETS OR CRADLES
 Prod : 0 NO SECOND PRODUCT INVOLVEMENT
 Date Injured : 04/01/2012 D Work Related : N
 Age : 202 Sex : 1 MALE
 Disposition : 1 1=TREATED & RELEASED, OR EX/Haz Type : F OTHER
 Brand : MATTEL / FISHER-PRICE Screened? :
 Model : M# R6070 / NEWBORN ROCK 'N PLAY SLEEPER

Narrative :

THE CONSUMER STATED THAT HER 2 MONTHS OLD SON SLEPT IN THIS SLEEPER F
 OR ROUGHLY 5 HRS PER DAY. AT 8 WEEKS OLD THE DOCTOR NOTICED THAT HE O
 NLY TURNED HIS HEAD TO THE LEFT. AT 12 WEEKS OLD HE HAD A FLAT SPOT O
 N THE BACK OF HIS HEAD AND WAS DIAGNOSED WITH TORTICOLLIS.

Document Number : Y1295524A Task Number : Issue : 0
 Date Received : 09/05/2012 Confirmed : Date Entered : 09/13/2012
 City : (b)(6) State : KS Zip : (b)(6) Date Notified :
 Source : 6 Type Of Contact : 10 OFFICE OF COMPLIANCE
 Prod : 1537 BASSINETS OR CRADLES
 Prod : 0 NO SECOND PRODUCT INVOLVEMENT
 Date Injured : 08/20/2012 D Work Related : N
 Age : 0 Sex : 0 UNKNOWN
 Disposition : 0 NO INJURY Haz Type : 7 ALLERGIC REACTION
 Brand : MATTEL / FISHER-PRICE Screened? :
 Model : M# R6070 / NEWBORN ROCK 'N PLAY SLEEPER

Narrative :

AGE AT THE TIME OF INCIDENT: YEAR(S) MONTH(S); DATE OF INCIDENT: 08/2
 0/2012; INJURY FLAG : NO; EVENT DESCRIPTION : THE CONSUMER EXPRESSED
 CONCERN THAT WHEN SHE REMOVED THE PAD FROM HER SLEEPER FOR LAUNDERING
 , SHE NOTICED MOLD UNDERNEATH THE PAD.

② mold

**Clearinghouse Format - With Manufacturer
Reported Incidents
U.S. Consumer Product Safety Commission
National Injury Information Clearinghouse**

11/2/2012

Page 15

Document Number : Y1295525A **Task Number :** **Issue :** 0
Date Received : 09/05/2012 **Confirmed :** **Date Entered :** 09/13/2012
City : (b)(6) **State :** CA **Zip :** (b)(6) **Date Notified :**
Source : 6 **Type Of Contact :** 10 OFFICE OF COMPLIANCE
Prod : 1537 BASSINETS OR CRADLES
Prod : 0 NO SECOND PRODUCT INVOLVEMENT
Date Injured : 08/08/2012 D **Work Related :** N
Age : 203 **Sex :** 1 MALE
Disposition : 0 0=NO INJURY **Haz Type :** 7 ALLERGIC REACTION
Brand : MATTEL / FISHER-PRICE **Screened? :**
Model : M# R6070 / NEWBORN ROCK 'N PLAY SLEEPER

Narrative :

AGE AT THE TIME OF INCIDENT: YEAR(S) 3MONTH(S); GENDER: MALE; DATE OF INCIDENT: 08/08/2012; INJURY FLAG: NO; EVENT DESCRIPTION: THE CONSUMER EXPRESSED CONCERN THAT MOLD FORMED ON THE LINER AND BACK OF THE SEAT PAD.

3 mold

Document Number : Y1295526A **Task Number :** **Issue :** 0
Date Received : 09/05/2012 **Confirmed :** **Date Entered :** 09/13/2012
City : (b)(6) **State :** MI **Zip :** (b)(6) **Date Notified :**
Source : 6 **Type Of Contact :** 10 OFFICE OF COMPLIANCE
Prod : 1537 BASSINETS OR CRADLES
Prod : 0 NO SECOND PRODUCT INVOLVEMENT
Date Injured : 07/15/2012 D **Work Related :** N
Age : 203 **Sex :** 1 MALE
Disposition : 0 0=NO INJURY **Haz Type :** 7 ALLERGIC REACTION
Brand : MATTEL / FISHER-PRICE **Screened? :**
Model : M# R6070 / NEWBORN ROCK 'N PLAY SLEEPER

Narrative :

AGE AT THE TIME OF INCIDENT: YEAR(S) 3MONTH(S); GENDER: MALE; THE CONSUMER EXPRESSED CONCERN THAT WHEN SHE REMOVED THE PAD FROM HER SLEEPER FOR LAUNDERING, SHE NOTICED MOLD ON THE FABRIC UNDERNEATH. IT DID NOT COME OFF IN THE WASH.

4 mold

Document Number : Y1295527A **Task Number :** **Issue :** 0
Date Received : 09/05/2012 **Confirmed :** **Date Entered :** 09/13/2012
City : (b)(6) **State :** HI **Zip :** (b)(6) **Date Notified :**
Source : 6 **Type Of Contact :** 10 OFFICE OF COMPLIANCE
Prod : 1537 BASSINETS OR CRADLES
Prod : 0 NO SECOND PRODUCT INVOLVEMENT
Date Injured : 06/01/2012 D **Work Related :** N
Age : 205 **Sex :** 1 MALE
Disposition : 0 0=NO INJURY **Haz Type :** 7 ALLERGIC REACTION
Brand : MATTEL / FISHER-PRICE **Screened? :**
Model : M# R6070 / NEWBORN ROCK 'N PLAY SLEEPER

Narrative :

AGE AT THE TIME OF INCIDENT: 0YEAR(S) 5MONTH(S); GENDER: MALE; DATE OF INCIDENT: 06/01/2012; INJURY FLAG: NO; EVENT DESCRIPTION: THE CONSUMER EXPRESSED CONCERN THAT THE SEAT IS MOLDY AND WILL NOT WIPE CLEAN.

5 mold

**Clearinghouse Format - With Manufacturer
Reported Incidents
U.S. Consumer Product Safety Commission
National Injury Information Clearinghouse**

11/2/2012

Page 16

Document Number : Y1295528A **Task Number :** **Issue :** 0
Date Received : 09/05/2012 **Confirmed :** **Date Entered :** 09/13/2012
City : ST LOUIS **State :** MO **Zip :** (b) (6) **Date Notified :**
Source : 6 **Type Of Contact :** 10 OFFICE OF COMPLIANCE
Prod : 1537 BASSINETS OR CRADLES
Prod : 0 NO SECOND PRODUCT INVOLVEMENT
Date Injured : 07/11/2012 M **Work Related :** N
Age : 0 **Sex :** 0 UNKNOWN
Disposition : 0 0=NO INJURY **Haz Type :** 7 ALLERGIC REACTION
Brand : MATTEL / FISHER-PRICE **Screened? :**
Model : M# R6070 / NEWBORN ROCK 'N PLAY SLEEPER

Narrative :

THE CONSUMER EXPRESSED CONCERN THAT THERE IS MOLD ON THE LINER.

6 mold

Document Number : Y1295529A **Task Number :** **Issue :** 0
Date Received : 09/05/2012 **Confirmed :** **Date Entered :** 09/13/2012
City : HUNTINGTON BEACH **State :** CA **Zip :** (b) (6) **Date Notified :**
Source : 6 **Type Of Contact :** 10 OFFICE OF COMPLIANCE
Prod : 1537 BASSINETS OR CRADLES
Prod : 0 NO SECOND PRODUCT INVOLVEMENT
Date Injured : 06/12/2012 M **Work Related :** N
Age : 202 **Sex :** 0 UNKNOWN
Disposition : 0 0=NO INJURY **Haz Type :** 7 ALLERGIC REACTION
Brand : MATTEL / FISHER-PRICE **Screened? :**
Model : M# R6070 / NEWBORN ROCK 'N PLAY SLEEPER

Narrative :

THE CONSUMER EXPRESSED CONCERN THAT THE LINER IS MOLDY.

7 mold

Document Number : Y1295530A **Task Number :** **Issue :** 0
Date Received : 09/05/2012 **Confirmed :** **Date Entered :** 09/11/2012
City : (b) (6) **State :** TX **Zip :** (b) (6) **Date Notified :**
Source : 6 **Type Of Contact :** 10 OFFICE OF COMPLIANCE
Prod : 1537 BASSINETS OR CRADLES
Prod : 0 NO SECOND PRODUCT INVOLVEMENT
Date Injured : 04/19/2012 D **Work Related :** N
Age : 208 **Sex :** 0 UNKNOWN
Disposition : 0 0=NO INJURY **Haz Type :** 7 ALLERGIC REACTION
Brand : MATTEL / FISHER-PRICE **Screened? :**
Model : M# R6070 / NEWBORN ROCK 'N PLAY SLEEPER

Narrative :

THE CONSUMER EXPRESSED CONCERN THAT THE LINER IS MOLDY.

8 mold

**Clearinghouse Format - With Manufacturer
Reported Incidents
U.S. Consumer Product Safety Commission
National Injury Information Clearinghouse**

11/2/2012

Page 17

Document Number : Y1295531A **Task Number :** 120913CCC3860 **Issue :** 0
Date Received : 09/05/2012 **Confirmed :** **Date Entered :** 09/11/2012
City : HOUSTON **State :** TX **Zip :** (b) (6) **Date Notified :**
Source : 6 **Type Of Contact :** 10 OFFICE OF COMPLIANCE
Prod : 1537 BASSINETS OR CRADLES
Prod : 0 NO SECOND PRODUCT INVOLVEMENT
Date Injured : 02/24/2012 M **Work Related :** N
Age : 0 **Sex :** 1 MALE
Disposition : 1 1=TREATED & RELEASED, OR EX/Haz Type : 7 ALLERGIC REACTION
Brand : MATTEL / FISHER-PRICE **Screened? :**
Model : M# R6070 / NEWBORN ROCK 'N PLAY SLEEPER

Narrative :

THE CONSUMER EXPRESSED CONCERN THAT MOLD IS FORMING ON THE LINER. SHE BELIEVES THIS HAS CAUSED HER SON TO BE SICK WITH RESPIRATORY ISSUES FOR FIVE WEEKS. HE HAS BEEN TO THE DOCTORS ON THREE OCCASIONS FOR THIS ISSUE.

Document Number : Y1295532A **Task Number :** **Issue :** 0
Date Received : 09/05/2012 **Confirmed :** **Date Entered :** 09/11/2012
City : (b) (6) **State :** NJ **Zip :** (b) (6) **Date Notified :**
Source : 6 **Type Of Contact :** 10 OFFICE OF COMPLIANCE
Prod : 1537 BASSINETS OR CRADLES
Prod : 0 NO SECOND PRODUCT INVOLVEMENT
Date Injured : 01/16/2012 D **Work Related :** N
Age : 208 **Sex :** 0 UNKNOWN
Disposition : 0 0=NO INJURY **Haz Type :** 7 ALLERGIC REACTION
Brand : MATTEL / FISHER-PRICE **Screened? :**
Model : M# R6070 / NEWBORN ROCK 'N PLAY SLEEPER

Narrative :

THE CONSUMER EXPRESSED CONCERN THAT THERE IS MOLD ON THE SEAT AND STRAPS NEAR THE SEAT.

Document Number : Y1295533A **Task Number :** 120914CCC1972 **Issue :** 0
Date Received : 09/05/2012 **Confirmed :** **Date Entered :** 09/11/2012
City : (b) (6) **State :** PA **Zip :** (b) (6) **Date Notified :**
Source : 6 **Type Of Contact :** 10 OFFICE OF COMPLIANCE
Prod : 1537 BASSINETS OR CRADLES
Prod : 0 NO SECOND PRODUCT INVOLVEMENT
Date Injured : 12/01/2011 D **Work Related :** N
Age : 202 **Sex :** 1 MALE
Disposition : 1 1=TREATED & RELEASED, OR EX/Haz Type : 7 ALLERGIC REACTION
Brand : MATTEL / FISHER-PRICE **Screened? :**
Model : M# R6070 / NEWBORN ROCK 'N PLAY SLEEPER

Narrative :

CONSUMER STATED THAT HER 2 MONTH OLD SON HAD FEVERS & VOMITING SO SHE TOOK HIM TO THE DOCTOR AND HE TOLD HER THAT THE CHILD WAS SICK DUE TO MOLD. UPON INSPECTION OF THE SLEEPER SHE DISCOVERED THAT THE PAD HAD AS BLACK MOLD ON IT WHERE THE CHILD'S BOTTOM SITS.

**Clearinghouse Format - With Manufacturer
Reported Incidents
U.S. Consumer Product Safety Commission
National Injury Information Clearinghouse**

11/2/2012

Page 18

Document Number : Y1295628A **Task Number :** **Issue :** 0
Date Received : 09/13/2012 **Confirmed :** **Date Entered :** 09/15/2012
City : (b)(6) **State :** AL **Zip :** (b)(6) **Date Notified :**
Source : 6 **Type Of Contact :** 10 OFFICE OF COMPLIANCE
Prod : 1537 BASSINETS OR CRADLES
Prod : 0 NO SECOND PRODUCT INVOLVEMENT
Date Injured : 07/01/2012 D **Work Related :** N
Age : 203 **Sex :** 1 MALE
Disposition : 1 1=TREATED & RELEASED, OR EX/Haz Type : F OTHER
Brand : MATTEL / FISHER-PRICE **Screened? :**
Model : M# R6070 / NEWBORN ROCK 'N PLAY SLEEPER

Narrative :

THE CONSUMER STATED THAT HER SON, 3MOM, HAS BEEN DIAGNOSED WITH PLAGI
 OCEPHALY AND TORTICOLLIS. HE SLEPT IN THIS PRODUCT AT NIGHT AND FOR N
 APS DURING THE DAY. HE IS RECEIVING PHYSICAL THERAPY AND WEARING A CR
 ANIAL BAND.

Document Number : Y1295923A **Task Number :** **Issue :** 0
Date Received : 09/27/2012 **Confirmed :** **Date Entered :** 10/03/2012
City : (b)(6) **State :** LA **Zip :** (b)(6) **Date Notified :**
Source : 6 **Type Of Contact :** 10 OFFICE OF COMPLIANCE
Prod : 1537 BASSINETS OR CRADLES
Prod : 0 NO SECOND PRODUCT INVOLVEMENT
Date Injured : 09/19/2012 D **Work Related :** N
Age : 204 **Sex :** 1 MALE
Disposition : 4 4=TREATED & ADMITTED FOR HO Haz Type : 7 ALLERGIC REACTION
Brand : FISHER PRICE / MATTEL / FISHER-PF Screened? :
Model : M# W9442 / NEWBORN ROCK 'N PLAY SLEEPER

Narrative :

THE CONSUMER STATED THAT SHE REMOVED THE PAD TO WASH IT WHEN SHE NOTI
 CED THAT THERE WAS MOLD GROWING UNDER THE PAD ON THE SEAT LINER. SHE
 BELIEVES THE MOLD IN THE PRODUCT CONTRIBUTED TO HER 4 MOM INFANT'S HE
 ALTH ISSUES. HE SUFFERS FROM INTESTINAL ISSUES & WAS HOSPITALIZED.

Document Number : Y12A5460A **Task Number :** 121025CCC2062 **Issue :** 0
Date Received : 10/04/2012 **Confirmed :** **Date Entered :** 10/12/2012
City : (b)(6) **State :** MN **Zip :** (b)(6) **Date Notified :**
Source : 6 **Type Of Contact :** 10 OFFICE OF COMPLIANCE
Prod : 1537 BASSINETS OR CRADLES
Prod : 1542 BABY MATTRESSES OR PADS
Date Injured : 09/24/2012 D **Work Related :** U
Age : 208 **Sex :** 1 MALE
Disposition : 1 1=TREATED & RELEASED, OR EX/Haz Type : 6 POISONING
Brand : MATTEL / FISHER-PRICE **Screened? :**
Model : M# R6070 / NEWBORN ROCK 'N PLAY SLEEPER

Narrative :

CONSUMER STATED THAT HIS 8-MONTH-OLD SON WAS TAKEN TO THE HOSPITAL FO
 R BREATHING PROBLEMS. THEY DID AN XRAY, A MUCCOUS LAB TEST, ADMINISTER
 ED STEROIDS AND A NEBULIZER TREATMENT. WHEN THEY GOT HOME AND REMOVED
 THE PAD FOR LAUNDERING THEY NOTICED MOLD ON THE SEAT.

Clearinghouse Format - With Manufacturer
Reported Incidents
U.S. Consumer Product Safety Commission
National Injury Information Clearinghouse

11/2/2012

Page 19

Document Number : Y12A5752A Task Number : Issue : 0
Date Received : 10/24/2012 Confirmed : Date Entered : 10/26/2012
City : HUNTINGTON BEACH State : CA Zip : (b) (6) Date Notified :
Source : 6 Type Of Contact : 10 OFFICE OF COMPLIANCE
Prod : 1537 BASSINETS OR CRADLES
Prod : 0 NO SECOND PRODUCT INVOLVEMENT
Date Injured : 10/14/2012 D Work Related : N
Age : 205 Sex : 2 FEMALE
Disposition : 0 0=NO INJURY Haz Type : 7 ALLERGIC REACTION
Brand : MATTEL / FISHER-PRICE Screened? :
Model : M# W9443 / NEWBORN ROCK N' PLAYT SOOTHER

*14 mold***Narrative :**

AGE AT THE TIME OF INCIDENT: YEAR(S) 5MONTH(S); WEIGHT AT THE TIME OF
INCIDENT: (b) (6); GENDER: FEMALE; DATE OF INCIDENT: 10/14/2012; I
NJURY FLAG : NO; EVENT DESCRIPTION : THE CONSUMER EXPRESSED CONCERN
THAT THERE WAS MOLD ON THE SEAT OF THE SLEEPER.

Clearinghouse Format - With Manufacturer
Reported Incidents
U.S. Consumer Product Safety Commission
National Injury Information Clearinghouse

11/2/2012

Page 1

Document Number : I1230273A Task Number : Issue : 0
Date Received : 03/13/2012 Confirmed : Date Entered : 03/15/2012
City : (b)(6) State : CA Zip : (b)(6) Date Notified :
Source : 0 Type Of Contact : 21 CONSUMER COMPLAINTS
Prod : 1558 BABY BOUNCER SEATS (EXCL. JUMPERS)
Prod : 0 NO SECOND PRODUCT INVOLVEMENT
Date Injured : 01/10/2012 D Work Related : N
Age : 205 Sex : 1 MALE
Disposition : 1 1=TREATED & RELEASED, OR EX/Haz Type : F OTHER
Brand : FISHER PRICE / FISHER-PRICE BRA Screened? :
Model : FISHER PRICE ROCK'N PLAY SLEEPER V9102 V9196 V9197 /SN 0097

Narrative :

A 5 MOM'S HEAD WAS DAMAGED FROM THE ROCKER/ SLEEPER. THE CHILD SLEPT
IN THE SLEEPER UNTIL HE WAS DIAGNOSED WITH OCCIPITAL PLAGIOCEPHALY.
THE SURGEON PRESCRIBED HELMET TO RESHAPE HIS HEAD. AS PER CALLER, TH
E SLEEPER HAD A HARD SHELL AS WELL AS NO ROOM FOR HEAD MOVEMENT.

42 total
head
playis

FOR OFFICIAL USE ONLY



UNITED STATES
CONSUMER PRODUCT SAFETY COMMISSION
WASHINGTON, DC 20207
DIRECTORATE FOR EPIDEMIOLOGY

TO: Theresa Nelson, CRC

FROM: Angie Qin, EPHA

DATE: 11/19/12

RE: Data Review for PSA # 0120.13 Case # CA120159

Date due: 11/20/12

Priority: c

Request: Data search for all incidents regarding Fisher-Price Rock 'N Play Sleeper

Hazard Pattern: Development of mold in plastic liner is harmful to infant's respiratory system. Also incidents of head plagiocephaly and neck torticollis reported from infant's lying on their back in sleeper.

Selection Criteria:

Product Code(s): 1549 1537 1558 1529 1543

Manufacturer/Model Text: fisher-price/fisher price/sleeper

Narrative Text:

Time Frame: 8/9/2012-11/9/2012 (date of entry)

NFIRS Search Criteria: N/A

(b)(5)

Incidents Identified:

Databases	Incident Count* (see notes below)	Death Count*
Incident Investigations (INDP)	0	0
Reported Incidents (IPII)	47	0
Death Certificates (DTHS)	0	0
NEISS reports (count)	N/A	N/A
Fire reports (NFIRS)	N/A	N/A
Total	* 47	0

(b)(5)

* For INDP, IPII and DTHS, duplicate reports have been removed, i.e. counted only once, in the database listed first. The reports enumerated in the table have been identified from CPSC databases on the date the search was completed. These should be considered neither a statistical sample nor a complete count of all such incidents, but only a count of those in CPSC databases on the search date.

NOTES:

Search found 47 incidents involving Fisher-Price Rock 'N Play Sleepers (including 1 RNP Sleeper-circles). Of these, 12 incidents were related to head plagiocephaly and/or neck torticollis and 35 incidents were related to mold.

(b)(5)

FOR OFFICIAL USE ONLY

Y1295524/PII		9/13/2012	8/20/2012	1537	MATTEL / FISIM# R6070 / NEWBORN ROCK N	KS	THE CONSUMER EXPRESSED CONCERN THAT MOLD IS FORMING ON THE LINER. SHE BELIEVES THIS HAS CAUSED HER SON TO BE SICK WITH RESPIRATORY ISSUES FOR FIVE WEEKS. HE HAS BEEN TO THE DOCTORS ON THREE OCCASIONS FOR THIS ISSUE.	mold	resp
Y1295525/PII		9/13/2012	8/8/2012	1537	MATTEL / FISIM# R6070 / NEWBORN ROCK N	CA	CONSUMER STATED THAT HER 2 MONTH OLD SON HAD FEVERS & VOMITING SO SHE TOOK HIM TO THE DOCTOR AND HE TOLD HER THAT THE CHILD WAS SICK DUE TO MOLD. UPON INSPECTION OF THE SLEEPER SHE DISCOVERED THAT THE PAD HAS BLACK MOLD ON IT WHERE THE CHILD'S BOTTOM SITS.	mold	resp
Y1295526/PII		9/13/2012	7/15/2012	1537	MATTEL / FISIM# R6070 / NEWBORN ROCK N	MI	CONSUMER STATED THAT HIS 8-MONTH-OLD SON WAS TAKEN TO THE HOSPITAL FOR BREATHING PROBLEMS. THEY DID AN XRAY, A MUCOUS LAB TEST, ADMINISTERED STEROIDS AND A NEBULIZER TREATMENT. WHEN THEY GOT HOME AND REMOVED THE PAD FOR LAUNDERING THEY NOTICED MOLD ON THE SEAT.	mold	resp
Y1295527/PII		9/13/2012	6/1/2012	1537	MATTEL / FISIM# R6070 / NEWBORN ROCK N	HI	THE CONSUMER STATED THAT SHE REMOVED THE PAD TO WASH IT WHEN SHE NOTICED THAT THERE WAS MOLD GROWING UNDER THE PAD ON THE SEAT LINER. SHE BELIEVES THE MOLD IN THE PRODUCT CONTRIBUTED TO HER 4 MOM INFANTS HEALTH ISSUES. HE SUFFERS FROM INTESTINAL ISSUES & WAS HOSPITALIZED.	mold	resp
Y1295528/PII		9/13/2012	7/1/2012	1537	MATTEL / FISIM# R6070 / NEWBORN ROCK N	MO	6 MOM: MOLD HAS FORMED ON THE LINER OF THEIR SLEEPER. CONSUMER BELIEVES HER SON ACQUIRED A COUGH AND UNEXPLAINABLE VOMITING FROM USAGE WITH THIS PRODUCT. THEY HAVE BEEN TO THEIR EMERGENCY ROOM ON THREE OCCASIONS FOR THIS ISSUE. HER SON RECEIVED A CHEST X-RAY.	mold	resp
Y1295529/PII		9/13/2012	6/12/2012	1537	MATTEL / FISIM# R6070 / NEWBORN ROCK N	CA	3 MO MALE & FEMALE TWINS HAD RESPIRATORY ISSUES & X-RAYED AT HOSPITAL. THEY WERE DIAGNOSED WITH BACTERIAL INFECTION. DOCTOR STATED IT WAS PROBABLY DUE TO MOLD ON THE PAD OF THE SLEEPER.	mold	resp

b(6)

Y12965304/PII		9/11/2012	4/19/2012	1537	MATTEL / FIS	M# R6070 / NEWBORN ROCK N	TX			THE CONSUMER STATED THAT HER 8 MONTH OLD SON WAS EXPERIENCING DIFFICULTY BREATHING. SHE FEELS THIS IS DUE TO THE MOLD THAT HAS GROWN ON THE SEAT LINER. CHILD HAS HAD RESPIRATORY ISSUES SINCE AGE OF 2 TO 3 MONTHS. PRESCRIBED ANTIBIOTIC & NEBULIZER FOR REACTIVE AIRWAY.	mold	resp
Y12965314/PII 120913CCC3860		9/11/2012	2/24/2012	1537	MATTEL / FIS	M# R6070 / NEWBORN ROCK N	TX			AGE AT THE TIME OF INCIDENT: (YEARS) MONTH(S); DATE OF INCIDENT: 08/20/2012; INJURY FLAG : NO; EVENT DESCRIPTION : THE CONSUMER EXPRESSED CONCERN THAT WHEN SHE REMOVED THE PAD FROM HER SLEEPER FOR LAUNDERING, SHE NOTICED MOLD UNDERNEATH THE PAD.	mold	
Y12965324/PII		9/11/2012	1/16/2012	1537	MATTEL / FIS	M# R6070 / NEWBORN ROCK N	NJ			AGE AT THE TIME OF INCIDENT: (YEARS) 3MONTH(S); GENDER: MALE; DATE OF INCIDENT: 08/08/2012; INJURY FLAG : NO; EVENT DESCRIPTION : THE CONSUMER EXPRESSED CONCERN THAT MOLD FORMED ON THE LINER AND BACK OF THE SEAT PAD.	mold	
Y12965334/PII 120914CCC1972		9/11/2012	12/1/2011	1537	MATTEL / FIS	M# R6070 / NEWBORN ROCK N	PA			AGE AT THE TIME OF INCIDENT: (YEARS) 3MONTH(S); GENDER: MALE; THE CONSUMER EXPRESSED CONCERN THAT WHEN SHE REMOVED THE PAD FROM HER SLEEPER FOR LAUNDERING, SHE NOTICED MOLD ON THE FABRIC UNDERNEATH. IT DIDNOT COME OFF IN THE WASH.	mold	
Y1296534/PII 121025CCC2062	Received 11/24/12	10/12/2012	9/24/2012	1537	MATTEL / FIS	M# R6070 / NEWBORN ROCK N	MN			AGE AT THE TIME OF INCIDENT: (YEARS) 5MONTH(S); GENDER: MALE; DATE OF INCIDENT: 06/01/2012; INJURY FLAG : NO; EVENT DESCRIPTION : THE CONSUMER EXPRESSED CONCERN THAT THE SEAT IS MOLDY AND WILL NOT WIPE CLEAN.	mold	Sage
Y129659234/PII		10/3/2012	9/19/2012	1537	FISHER PRICE	M# W9442 / NEWBORN ROCK N	LA			THE CONSUMER EXPRESSED CONCERN THAT THERE IS MOLD ON THE LINER.	mold	
Y12857024/PII 120824CCC2930		8/24/2012	7/11/2012	1537	MATTEL / FIS	M# W9443 / NEWBORN ROCK N	MN			THE CONSUMER EXPRESSED CONCERN THAT THE LINER IS MOLDY.	mold	
Y12857034/PII		8/24/2012	7/25/2012	1537	MATTEL / FIS	M# W9443 / NEWBORN ROCK N	NJ			THE CONSUMER EXPRESSED CONCERN THAT THE LINER IS MOLDY.	mold	
Y12857044/PII		8/24/2012	8/8/2012	1537	MATTEL / FIS	M# W9443 / NEWBORN ROCK N	IN			THE CONSUMER EXPRESSED CONCERN THAT THERE IS MOLD ON THE SEAT AND STRAPS NEAR THE SEAT.	mold	
Y12857054/PII		8/24/2012	8/8/2012	1537	MATTEL / FIS	M# W9443 / NEWBORN ROCK N	IN			AGE AT THE TIME OF INCIDENT: (YEARS) 1MONTH(S); WEIGHT AT THE TIME OF INCIDENT: 16LBS 0OZ; GENDER: FEMALE; DATE OF INCIDENT: 07/25/2012; INJURY FLAG : NO; EVENT DESCRIPTION: THE CONSUMER EXPRESSED CONCERN THAT THE SEAT HAS MOLD ON IT.	mold	

(b)(6)

Y1285706/PII		8/24/2012	8/2/2012	1537	MATTEL / FISIM# W9443 / NEWBORN ROCK N	CT	AGE: YEAR(S) MONTH(S); GENDER: ; DATE OF INCIDENT: 08/08/2012; INJURY FLAG: NO; EVENT DESCRIPTION: THE CONSUMER EXPRESSED CONCERN THAT SHE REMOVED THE THE PAD FOR LAUNDERING AND NOTICED MOLD ON THE PAD AND SEAT. SHE OWNS TWO AND IS NOTICING THE SAME ISSUE WITH EACH ONE.	mold	
Y1285707/PII		8/24/2012	6/1/2012	1537	MATTEL / FISIM# W9443 / NEWBORN ROCK N	CA	AGE: 7 MONTH(S); GENDER: FEMALE; DATE OF INCIDENT: 08/08/2012; INJURY FLAG: NO; EVENT DESCRIPTION: THE CONSUMER EXPRESSED CONCERN THAT SHE REMOVED THE THE PAD FOR LAUNDERING AND NOTICED MOLD ON THE PAD AND SEAT. SHE OWNS TWO AND IS NOTICING THE SAME ISSUE WITH EACH ONE.	mold	
Y1285708/PII		8/24/2012	7/29/2012	1537	MATTEL / FISIM# W9443 / NEWBORN ROCK N	TX	AGE AT THE TIME OF INCIDENT: YEAR(S) 4MONTH(S); WEIGHT AT THE TIME OF INCIDENT: 14LBS 0OZ; GENDER: MALE; DATE OF INCIDENT: 08/02/2012; EVENT DESCRIPTION: THE CONSUMER EXPRESSED CONCERN BECAUSE HIS WIFE FOUND BLACK MOLD ON THE SEAT FABRIC UNDER THE PAD.	mold	
Y1285709/PII		8/24/2012	7/17/2012	1537	MATTEL / FISIM# W9443 / NEWBORN ROCK N	PA	PRODUCT IN CONSUMER POSSESSION: YES; AGE AT THE TIME OF INCIDENT: 0YEAR(S) 3MONTH(S); WEIGHT AT THE TIME OF INCIDENT: 17LBS 0OZ; GENDER: MALE; DATE OF INCIDENT: 06/01/2012; INJURY FLAG: NO; EVENT DESCRIPTION: THE CONSUMER EXPRESSED CONCERN THAT MOLD HAS FORMED ON THE LINER	mold	
Y1285710/PII		8/24/2012	7/1/2012	1537	MATTEL / FISIM# W9443 / NEWBORN ROCK N	NY	AGE 4MONTH(S); WEIGHT <u>16.6</u> MALE; DATE OF INCIDENT: 07/29/2012. THE CONSUMER EXPRESSED CONCERN THAT WHEN SHE REMOVED THE PAD TO WASH IT SHE DISCOVERED THAT THE SEAT IS MOLDY. SHE TRIED TO CLEAN IT WITH BLEACH BUT THE MOLD WILL NOT COME OUT.	mold	

(b)(6)

Y12A5714 PII		8/24/2012	6/21/2012	1537	MATTEL / FISIM# W9443 / NEWBORN ROCK N	CA	AGE : 3MONTH(S); WEIGHT <u>9.6</u> GENDER: FEMALE; DATE OF INCIDENT: 07/17/2012; THE CONSUMER EXPRESSED CONCERN THAT THE SEAT AND THE BACK OF THE PAD ARE MOLDY. THIS WAS NOTICED WHEN SHE REMOVED THE PAD TO WASH IT.	mold	
Y12A5714 PII		8/24/2012	5/2/2012	1537	MATTEL / FISIM# W9443 / NEWBORN ROCK N	OH	AGE : 5MONTH(S); WEIGHT: 13LBS 12OZ. GENDER: MALE; DATE OF INCIDENT: 07/01/2012; INJURY FLAG : NO; EVENT DESCRIPTION: THE CONSUMER EXPRESSED CONCERN THAT WHEN SHE REMOVED THE PAD FROM THE SLEEPER SHE DISCOVERED THAT THE BACK OF THE PAD AND THE SEAT WERE COVERED IN MOLD.	mold	
Y12A5714 PII	Eliminated	8/24/2012	5/2/2012	1537	MATTEL / FISIM# W9443 / NEWBORN ROCK N	CA	THE CONSUMER EXPRESSED CONCERN THAT THERE IS MOLD ON THE LINER OF THE PRODUCT.	mold	
Y12A5714 PII		9/7/2012	8/9/2012	1537	MATTEL / FISIM# W9443 / NEWBORN ROCK N	CA	THE CONSUMER EXPRESSED CONCERN BECAUSE SHE REMOVED THE PAD TO WASH IT FOR THE FIRST TIME AND SHE FOUND BLACK COLORED MOLD GROWING ON THE SEAT LINER. N/A	mold	
Y12A5665 PII		10/23/2012	10/10/2012	1537	MATTEL / FISIM# W9443 / NEWBORN ROCK N	TX	AGE AT THE TIME OF INCIDENT: YEAR(S) 5MONTH(S); WEIGHT AT THE TIME OF INCIDENT: <u>9.6</u> GENDER: FEMALE; DATE OF INCIDENT: 10/14/2012; INJURY FLAG : NO; EVENT DESCRIPTION : THE CONSUMER EXPRESSED CONCERN THAT THERE WAS MOLD ON THE SEAT OF THE SLEEPER.	mold	
Y12A5752 PII		10/26/2012	10/14/2012	1537	MATTEL / FISIM# W9443 / NEWBORN ROCK N	CA	AGE AT THE TIME OF INCIDENT: YEAR(S) MONTH(S); WEIGHT AT THE TIME OF INCIDENT: 0LBS 0OZ; GENDER: ; DATE OF INCIDENT: ; INJURY FLAG : NO; EVENT DESCRIPTION : THE CONSUMER EXPRESSED CONCERN THAT THERE IS MOLD ON THE SEAT.	mold	
Y12A5753 PII		10/26/2012	10/12/2012	1537	MATTEL / FISIM# W9443 / NEWBORN ROCK N	NY	AGE AT THE TIME OF INCIDENT: 0YEAR(S) 6MONTH(S); WEIGHT AT THE TIME OF INCIDENT: 0LBS 0OZ; GENDER: MALE; DATE OF INCIDENT: 07/15/2012; INJURY FLAG : NO; EVENT DESCRIPTION : THE CONSUMER STATED THAT BLACK MOLD HAS GROWN ON THE SEAT LINER.	mold	
Y12A5754 PII		10/26/2012	7/15/2012	1537	MATTEL / FISIM# W9443 / NEWBORN ROCK N	TX		mold	

(b)(6)

Y12A57556	IP11	10/26/2012	10/10/2012	1537	MATTEL / FIS	M# W9443 / NEWBORN ROCK N	DE	(b)(6)	CONSUMER EXPRESSED CONCERN THAT WHILE WASHING THE PRODUCT SHE DISCOVERED MOLD ON THE SEAT STRAPS AND BOTTOM. SHE IS FRUSTRATED THAT HER SON HAS BEEN SLEEPING ON MOLD AND SAYS HE HAS HAD BREATHING ISSUES FOR 3 NIGHTS.	mold	
Y12A57556	IP11	10/26/2012	10/6/2012	1537	MATTEL / FIS	M# W9443 / NEWBORN ROCK N	CA		AGE AT THE TIME OF INCIDENT: 0YEAR(S) 3MONTH(S); WEIGHT AT THE TIME OF INCIDENT: 10.6 OZ; GENDER: MALE; DATE OF INCIDENT: 10/06/2012; INJURY FLAG : NO; EVENT DESCRIPTION : THE CONSUMER EXPRESSED CONCERN THAT THERE IS MOLD ON THE SEAT.	mold	
Y12A5757	IP11	10/26/2012	9/27/2012	1537	MATTEL / FIS	M# W9443 / NEWBORN ROCK N	GA		AGE AT THE TIME OF INCIDENT: 0YEAR(S) 2MONTH(S); WEIGHT AT THE TIME OF INCIDENT: 12.0 OZ; GENDER: FEMALE; DATE OF INCIDENT: 09/27/2012; INJURY FLAG : NO; EVENT DESCRIPTION : THE CONSUMER EXPRESSED CONCERN THAT MOLD HAS FORMED ON THE LINER OF THE PRODUCT	mold	
Y12A5757	IP11	10/26/2012	9/16/2012	1537	MATTEL / FIS	M# W9443 / NEWBORN ROCK N	TX		AGE: YEAR(S) 6MONTH(S); WEIGHT: 16LBS 0OZ; GENDER: MALE; DATE OF INCIDENT: 09/16/2012; INJURY FLAG : NO; EVENT DESCRIPTION : THE FOLLOWING WAS REPORTED TO US BY E-MAIL. THE CONSUMER EXPRESSED CONCERN THAT SHE FOUND BLACK MOLD ON THE LINER OF THE PRODUCT.	mold	
Y12A5759	IP11	10/26/2012	8/1/2012	1537	MATTEL / FIS	M# W9443 / NEWBORN ROCK N	CA	(b)(6)	AGE AT THE TIME OF INCIDENT: 0YEAR(S) 4MONTH(S); WEIGHT AT THE TIME OF INCIDENT: 12.6 OZ; GENDER: MALE; DATE OF INCIDENT: 08/01/2012; INJURY FLAG : NO; EVENT DESCRIPTION : THE CONSUMER EXPRESSED CONCERN THAT THERE IS MOLD ON THE LINER OF THE PRODUCT	mold	
Y12A5760	IP11	10/26/2012	9/1/2012	1537	MATTEL / FIS	M# W9443 / NEWBORN ROCK N	GA		AGE: 2MONTH(S); WEIGHT: 12LBS 0OZ; GENDER: FEMALE; DATE OF INCIDENT: 09/01/2012; THE PAD IS MOLDY. THIS WAS NOTICED WHEN CONSUMER REMOVED THE PAD FOR LAUNDERING. THE MOLD IS LOCATED ON THE SEAT.	mold	

****FOR OFFICIAL USE ONLY****

PSA ACTION (FOR PSA
COORDINATOR USE ONLY)

PRODUCT SAFETY ASSESSMENT (PSA) TECHNICAL EVALUATION REQUEST

PSA Number : 0120.13
Date Processed : 11/5/12

Requested by : Theresa Nelson, (301) 504-7509

Org. Code : CRC Field Off : FOER

Date Requested : 11/20/12

Date Submitted : 11/2/2012

Priority : Case # : CA120159

Due Date :

Requested Completion Date : 11/20/2012

PRODUCT INFORMATION:

Manufacturer : Fisher-Price, Inc.

City : East Aurora State : NY

Assigned to
Organization : EP

Product : Fisher-Price Rock 'N Play Sleeper

NEISS Code : 1549, 1537, 1558,
1529, 1543

Technical Off. :

Brand name, model, etc. : Fisher-Price

Request Summary:

Sample number :

Sample Disposition: Return to Requester Store at Warehouse Other :

IDI Number :

EVALUATION REQUESTED: HA - Conduct a data search for all incidents using the following criteria: Fisher Price, name Rock 'N Play Sleeper (any model) entered between 8/9/2012 and 11/2/2012.

Comments:

Case refer to PSA# 0873.12 and use same criteria *except* dates of Time Frame.

EPI ASSESSMENT: Dates: From 8/9/2012 To : 11/2/2012 Sort by Mfg.: X Yes No

X IDI X IPI NEISS Comments NEISS Estimates X Death NFIRS

HAZARD : Development of mold in plastic liner is harmful to infant's respiratory system. Also incidents of head plagiocephaly and neck torticollis reported from infant's lying on their back in sleeper.

HAZARD CODE : 203

LOCATIONS OF Samples: SSF

Files:

(MSWordRev 2/99 rp/jb/bh)

FOR OFFICIAL USE ONLY



**UNITED STATES
CONSUMER PRODUCT SAFETY COMMISSION
WASHINGTON, DC 20207
DIRECTORATE FOR EPIDEMIOLOGY**

.00.

TO: Theresa Nelson, CRC**FROM:** Angie Qin, EPHA**DATE:** 8/17/12**RE:** Data Review for PSA #0873.12 Case # PI110066

Date due: 8/17/12 (scheduled as fast track)

Priority: c

Request: Data search for all incidents regarding Fisher-Price Rock 'N Play Sleeper

Hazard Pattern: Concern of infant's developing head plagiocephaly and/or neck torticollis from sleeping in product; also development of mold in plastic liner could be harmful to infants.

Selection Criteria:

Product Code(s): 1549 1537 1558 1529 1543

Manufacturer/Model Text: fisher-price/fisher price/sleeper

Narrative Text:

Time Frame: 6/1/09-8/8/12

NFIRS Search Criteria: N/A

Incidents Identified:

Databases	Incident Count* (see notes below)	Death Count*
Incident Investigations (INDP)	6	0
Reported Incidents (IPII)	83	0
Death Certificates (DTHS)	0	0
NEISS reports (count)	N/A	N/A
Fire reports (NFIRS)	N/A	N/A
Total	89	0

* For INDP, IPII and DTHS, duplicate reports have been removed, i.e. counted only once, in the database listed first. The reports enumerated in the table have been identified from CPSC databases on the date the search was completed. These should be considered neither a statistical sample nor a complete count of all such incidents, but only a count of those in CPSC databases on the search date.

NOTES:

Search found 89 incidents involving Fisher-Price Rock 'N Play Sleepers (including 8 RNP Sleeper-circles).

FOR OFFICIAL USE ONLY

FOR OFFICIAL USE ONLY



2012
**UNITED STATES
 CONSUMER PRODUCT SAFETY COMMISSION
 WASHINGTON, DC 20207
 DIRECTORATE FOR EPIDEMIOLOGY**

TO: Theresa Nelson, CRC
FROM: Angie Qin, EPHA
DATE: 1/30/12
RE: Data Review for PSA # 0305.12 Case # PI110066

Date due: 2/3/12

Priority: c

Request: Data search for all incidents involving Fisher-Price Rock 'N Play Sleeper

Hazard Pattern: Concern of infant's developing head plagiocephaly and/or neck torticollis from sleeping in product, also development of mold in plastic liner could be harmful to infants

Selection Criteria:

Product Code(s): ~~1519 1527 1552 1520 1515~~ ✓ ✓ ✓ ✓ ✓

Manufacturer/Model Text: fisher-price/fisher price/sleeper

Narrative Text:

Time Frame: 5/1/10-1/24/12

NFIRS Search Criteria: N/A

Date
Entered

Incidents Identified:

Databases	Incident Count* (see notes below)	Death Count*
Incident Investigations (INDP)	6	0
Reported Incidents (IPII)	43	0
Death Certificates (DTHS)	N/A	N/A
NEISS reports (count)	N/A	N/A
Fire reports (NFIRS)	N/A	N/A
Total	49	0

* For INDP, IPII and DTHS, duplicate reports have been removed, i.e. counted only once, in the database listed first. The reports enumerated in the table have been identified from CPSC databases on the date the search was completed. These should be considered neither a statistical sample nor a complete count of all such incidents, but only a count of those in CPSC databases on the search date.

NOTES:

Search found 49 incidents involving Fisher-Price Rock 'N Play Sleeper. Incidents that could be determined to have duplicate reports are counted only once and noted on the spreadsheets.

FOR OFFICIAL USE ONLY

****FOR OFFICIAL USE ONLY****				PSA ACTION (FOR PSA COORDINATOR USE ONLY)	
PRODUCT SAFETY ASSESSMENT (PSA) TECHNICAL EVALUATION REQUEST					
Requested by	:Theresa Nelson, (301) 504-7509	Org. Code	:CRC	Field Off	:FOER
Date Submitted	: 1/25/2012	Priority	:c	Case #	:PI110066
Requested Completion Date		: 2/3/2012			
PRODUCT INFORMATION:					
Manufacturer	:Fisher-Price, Inc.	City	:East Aurora	State	:NY
Product	:Fisher-Price Rock 'N Play Sleeper	NEISS Code	:1549 , 1537, 1558		
Brand name, model, etc.	: Fisher-Price				
Sample number	:				
Sample Disposition:	Return to Requester	Store at Warehouse	Other :		
IDI Number	:				
EVALUATION REQUESTED/HA Conduct a data search for all incidents using the following criteria: Fisher Price, PC 1549, 1537, 1558 between 6/17/2009 to 1/25/2012, name Rock N' Play Sleeper (any model).					
EPI ASSESSMENT: Dates:		From	: 6/1/2009	To	: 1/25/2012
		Sort by Mfg.:		X Yes	No
X IDI	X IPI	NEISS Comments	NEISS Estimates	X Death	NFIRS
HAZARD		:Concern of infant's developing head plagiocephaly and/or neck torticollis from sleeping in product. Also development of mold in plastic liner could be harmful to infants.			
HAZARD CODE		: 203			
LOCATIONS OF		Samples: SSF		Files:	
Comments:					
Request Summary:					
Assigned to					
Organization: : EP					
Technical Off. :					
PSA Number : 0305.12					
Date Processed : 1/25/12					
Date Requested : 2/3/12					
Due Date: :					
(MSWordRev 2/99 rp/jb/bh)					

Nelson, Theresa

From: Nelson, Theresa
Sent: Friday, September 07, 2012 8:46 AM
To: Pilarz, Kitty (Kitty.Pilarz@Fisher-Price.com)
Cc: Moore, Kelly; Rauchschtwalbe, Renae; Simmons, Scott; Schoem, Marc
Subject: PD letter re Rock N Play Sleeper CA120159
Attachments: PDltr8-6-12.pdf

Kitty

The attached letter explains the Commission staff's decision of a Preliminary Determination that the exposure of "mold growth" on the Rock 'N Play Sleeper presents a substantial product hazard under section 15(a) of the Consumer Product Safety Act and the Federal Substances Act.

This letter is also being sent to you via FedEx (tracking number #8770 5220 2947) and will be delivered today, Friday, September 7, 2012. We look forward to receiving the firm's corrective action plan (CAP) by Friday, September 21, 2012.

Regards, Terri

Terri Nelson

Compliance Officer
Office of Compliance & Field Operations
U.S. Consumer Product Safety Commission
Phone: 301-504-7509 or
1-800-638-8095 ext. 7509

Fax: 301-504-0359
tnelson@cpsc.gov

SIGN UP FOR RECALL NOTICES: <http://www.cpsc.gov/cpsclist.aspx>

SENDER: COMPLETE THIS SECTION

- Complete items 1, 2, and 3. Also complete item 4 if Restricted Delivery is desired.
- Print your name and address on the reverse so that we can return the card to you.
- Attach this card to the back of the mailpiece, or on the front if space permits.

1. Article Addressed to:

**Partner Goldberg Segalla
Ms. Cheryl Possenti, Esq.
665 Main St, Ste 400
Buffalo NY 14203**

COMPLETE THIS SECTION ON DELIVERY

A. Signature

X

☒ Agent☐ Addressee

B. Received by (Printed Name)

W. S. S. S. S. S.

C. Date of Delivery

MAY - 3 2013

D. Is delivery address different from item 1? ☐ Yes
If YES, enter delivery address below: ☒ No

3. Service Type

☒ Certified Mail☐ Express Mail☐ Registered☐ Return Receipt for Merchandise☐ Insured Mail☐ C.O.D.

4. Restricted Delivery? (Extra Fee)

☐ Yes

2. Article Number

7010 1870 0003 4102 9290

CA120159

102595-02-M-1540



U.S. CONSUMER PRODUCT SAFETY COMMISSION

4330 EAST WEST HIGHWAY

BETHESDA, MD 20814

Office of Compliance and Field Operations
Defect Investigations Division
Email: tnelson@cpsc.gov

SEP - 6 2012

Theresa Nelson
Compliance Officer
Tel: 301-504-7509
Fax: 301-504-0060

Via Certified Mail/Email: Kitty.Pilarz@Fisher-Price.com

Ms. Kitty Pilarz
Senior Director,
Product Safety and Regulatory Affairs
Fisher-Price, Inc.
636 Girard Avenue
East Aurora, NY 14052

Re: CPSC File No. CA120159
Fisher-Price, Inc.
Rock 'N Play Sleepers
Model #'s: R6070, V9102, V9196, V9197, W9442, W9443,
X2532, X2897

Dear Ms. Pilarz:

The staff of the Office of Compliance and Field Operations of the U.S. Consumer Product Safety Commission ("Commission") has reviewed the information that you have provided concerning Rock 'N Play Sleepers.

After careful consideration and in accordance with 16 C.F.R. § 1115.12(a), the staff has made a preliminary determination that the exposure of "mold growth" on the Rock 'N Play Sleepers ("Subject Product") presents a substantial product hazard under section 15(a) of the Consumer Product Safety Act* ("CPSA"), 15 U.S.C. § 2064(a) and the Federal Hazardous Substances Act* ("FHSA"). Specifically, infant's exposure to the mold growth on the Subject Product can increase infants' susceptibility to asthma and other respiratory illnesses due to their immature immune and respiratory systems.

*Links provided at the end of letter.

The staff welcomes and will give full consideration to any comments or additional information from the firm concerning the staff's preliminary determination. The staff will meet with the firm as necessary to discuss its comments or corrective action.

Voluntary Corrective Actions

The Office of Compliance and Field Operations acknowledges and encourages the actions that Fisher-Price, Inc. has already taken to correct this problem in future productions. However, the staff believes that the following additional actions are necessary to assure the maximum notification for subject products previously purchased by consumers.

- Joint press release announcing recall informing consumers to check their model of the Subject Products for "mold growth";
- Direct recall notice to identified purchasers;
- Approved repair/replacement or refund remedy if consumer discovers mold in the Subject Product;
- Recall posters at retail locations;
- Recall notice posted on the firm's Web site;
- Future production:
 - Improved design to prevent mold growth;
 - Improved cleaning instructions to avoid mold growth.

Please provide the Office of Compliance and Field Operations with a written corrective action plan describing the actions which the firm is taking and plans to take. This written plan should contain the elements listed in 16 C.F.R. § 1115.20(a).

Additionally, rather than the Commission unilaterally issuing a press release, the staff believes it would be appropriate for the firm and the Commission to issue a joint press release announcing the corrective action or recall. The staff will work with the firm to develop and issue a mutually acceptable release.

A voluntary corrective action plan must include an agreement that the Commission may publicize the terms of the plan and inform the public of the nature and the extent of the alleged substantial product hazard. Please see 16 C.F.R. § 1115.20 and Part 1101, Information Disclosure.

When the corrective action program begins, the Office of Compliance and Field Operations will monitor the progress of the program.

Compliance With Reporting Obligations

The staff will also investigate and assess whether it believes the firm has complied with the reporting requirements of section 15(b) of the Consumer Product Safety Act ("CPSA"), 15 U.S.C. § 2064(b). That section requires every manufacturer, importer, distributor, and retailer of a consumer product, or of any other product or substance over which the Commission has

jurisdiction under any other statute enforced by the Commission, who obtains information which reasonably supports the conclusion that the product (1) contains a defect which could create a substantial product hazard, (2) creates an unreasonable risk of serious injury or death, (3) fails to comply with an applicable consumer product safety rule or with a voluntary consumer product safety standard upon which the Commission has relied under section 9 of the CPSA, 15 U.S.C. § 2058, or (4) fails to comply with any other rule, regulation, standard, or ban under the CPSA or any other statute enforced by the Commission, to immediately inform the Commission of the defect, risk, or failure to comply, unless the firm has actual knowledge that the Commission has been adequately informed of the defect, risk, or failure to comply. See 16 C.F.R. Part 1115. The CPSA makes it a prohibited act to violate the reporting requirements. Firms may be liable for a civil penalty of \$100,000 for each violation involved up to a maximum of \$15,000,000 for any related series of violations. The maximum penalty increases to \$15.15 million after January 1, 2012. Sections 15(b), 19(a)(4), 20, and 21 of the CPSA, 15 U.S.C. §§ 2064(b), 2068(a)(4), 2069, and 2070, describe the duties of manufacturers, importers, distributors, and retailers to furnish information to the Commission and the penalties for failing to furnish such information.

Continuing Obligations

The staff requests that the firm continue to implement its corrective action plan until as many Subject Products as possible have been removed from the marketplace. Please continue to maintain your toll-free recall number as a means for consumers to reach you about your recall. Should the firm decide to change or discontinue the toll-free number, you must notify the Office of Compliance and Field Operations and provide a new recall contact number for the firm. This information will be maintained by the Commission staff and provided to consumers and others seeking information on your recall.

If the firm receives or learns of any information concerning complaints, claims, incidents, or injuries that the firm did not report, or other information affecting the scope, prevalence, or seriousness of the reported problem, issue, or potential defect or hazard, the firm must immediately report that information to the Office of Compliance and Field Operations. Additionally, if the firm receives information that might indicate that its corrective actions are not satisfactory in eliminating the risk of injury or the potential defect or hazard, or that the effectiveness of the corrective action plan was less than what had been reported, it must immediately report that information to the Office of Compliance and Field Operations. In addition, under section 19(a)(2)(B) of the CPSA, 15 U.S.C. § 2068(a)(2)(B), it is unlawful to sell, offer for sale, manufacture for sale, distribute in commerce, or import into the United States a product that it is covered by a manufacturer's corrective action plan created in consultation with, and publicized by, the Commission.

Until this matter and any related matters are resolved, there will remain the possibility of further enforcement action, including reasonably anticipated litigation. Therefore, the firm must abide by the continuing legal obligation to preserve all information, documents, records, and samples, now in existence or created hereafter, related to the Subject Product.

Page 4
CA120159

Due Date and Contact Information

The staff requests that the firm respond in writing and in full by providing all requested documents, records, and information **within 10 working days from receipt of this letter.** **Please also send an electronic copy of all documents you are providing to the email address listed on the letterhead of this letter.** Please reference the file number CA120159 in your response.

The staff will make every effort to work closely and cooperatively with the firm to assure a successful corrective action plan which will protect the public while at the same time create a minimum of burden and inconvenience for the firm. If you have any questions or desire assistance in responding to this letter, you may contact me at 301-504-7509. Please address your correspondence to the following: Office of Compliance and Field Operations, U.S. Consumer Product Safety Commission, Room 613, 4330 East West Highway, Bethesda, MD 20814-4408. The Office of Compliance and Field Operations telefax number is (301) 504-0359.

Thank you for your cooperation.

Sincerely,



Theresa Nelson
Compliance Officer
Defect Investigations Division

Enclosed:

Consumer Product Safety Act - <http://www.cpsc.gov/about/cpsia/legislation.html>
16 C.F.R. Part 1101, Information Disclosure -
<http://www.cpsc.gov/ABOUT/guide.html> Part 1115, Substantial Product Hazard
Reports -- <http://www.cpsc.gov/BUSINFO/frnotices/fr06/E611758.pdf>
Part 1116, Section 37 Reports - <http://www.cpsc.gov/BUSINFO/cpsa37.pdf>
Federal Hazardous Substances Act - <http://www.cpsc.gov/businfo/fhsa.pdf>
Recall Handbook - <http://www.cpsc.gov/businfo/8002.html>
Recall Checklist - <http://www.cpsc.gov/businfo/recallcheck>

U.S. CONSUMER PRODUCT SAFETY COMMISSION
Office of Compliance and Field Operations

PRELIMINARY STAFF DETERMINATION	
--	--

(b)(5)

*****OFFICIAL USE ONLY*****

(b)(5)

OFFICIAL USE ONLY

(b)(5)

OFFICIAL USE ONLY

(b)(5)

Date of Preliminary Determination Panel Meeting: **8/21/2012**

PDP Attendees (Name and Office Represented):

Name Office

Name Office

*****OFFICIAL USE ONLY*****



Sample Tracking System



Version 2.11 - 04/15/2011 Production Environment - DBDBNew Logged in as: TNelson

Sample Collection Data

[Go Back](#)
[View Sample History](#)

1. Sample Flag:	2. Date Collected: 04/27/2011	3. Sample Number and Type: 11-810-6684 <input checked="" type="checkbox"/> Physical <input type="checkbox"/> Documentary	
4a. Product Name: NEWBORN ROCK N PLAY SLEEP	4b. Model: R6070	4c. NEISS: 1549 4d. UPC Code:	5. Assignment Number: 110425ERC2472
6. For Import Samples Port of Entry: Country of Origin: Entry No. and Date: Customs Contact:			
7. MIS: 32202	8. Hours - Activity: 2 Travel: 0.5	9a. Home RO: CFIE	9b. Collecting RO: ISU
10. Sample Cost: \$55.19	11. Invoice Value of Lot: \$55.19	12. Size of Lot: 1	Units: unt
13. Manufacturer/Importer: # FIS044 FISHER PRICE, INC. 636 GIRARD AVE. EAST AURORA 14052			
14. Shipper/Foreign Manufacturer: UPS			
15. Dealer/Importer Broker: # AMA051 AMAZON.COM LLC 172 TRADE STREETLEXINGTON, KY 40511			
16. Supporting documents attached: Invoice No. and Date : Shipping Record and Date: Affidavit Signer's Name, Title and Date:			
17. Product Identification: The product is a Fisher Price Newborn Rock 'n Play Sleeper. The product requires assembly, comes with metal assembly base, sling and pad cover. The product is packaged in a box with			

labeling which states in part, "***Nighttime Sleeper and playtime seat all in one***Maximum weight birth to 25 lbs.***All new material Made in China***Reg. No. PA-27960(CO)***Fisher Price Inc. a subsidiary of Mattel Inc. East Aurora, NY 14052 U.S.A.***" Model number R6070. A bar code on the box reads, 027084834185.

18. Reason Collection Analysis Needed:

☐ FHSA ☒ CPSA ☐ FFA ☐ PPA ☐ RSA ☐ VGBA ☐ CGBP

collected under ISU team in support of open case PI110066

19. Summary of Field Screening:

none

20. Sample size/Method of Collection:

The product was ordered through online retailer amazon.com, shipped to this investigator's local UPS box store, and was collected at the UPS store on 04/27/2011 and transported by this investigator's vehicle to the Miami Resident Post where it was identified as in Box #21 and officially sealed as in Box #22. Sample remained under lock & key, or in investigator's possession from the time of collection until submission through UPS to T. Nelson through the SSF.

21. Identification on Sample: 11-810-6684 SUB 1 RXM 04/27/2011

22. Identification on Seal and Date: 11-810-6684 Renee Y. Morelli 05/02/2011

23. Sample Delivered To: UPS 33175 **23b. Date:** 05/02/2011

24. Report/Record Sent To: CFIE

25. Laboratory/Office:

☐ LSE ☐ LSM ☒ CRC ☐ SIU ☐ LSC ☐ LS ☐ CLD ☐ SSF
☒ Other SSF TO T. NELSO

26. Remarks:

Attach#1: photos, online purchase invoice, packing list

27. Related Samples:

28a. Collector's Name/Title/Date: Renee Y. Morelli - Acting Supervisor - 05/02/2011

29a. Reviewer's Name/Title/Date: Michelle A. Mach - Supervisor - 05/02/2011

*Hand meeting notice to
Lett*

Nelson, Theresa

From: Cheryl Possenti [cpossenti@goldbergsegalla.com]
Sent: Monday, July 23, 2012 10:26 AM
To: Nelson, Theresa; Moore, Kelly; Thomas, Treye
Cc: Pilarz, Kitty; Dzialga, Dan; Schoem, Marc
Subject: RE: Fisher-Price Rock 'n Play Sleeper PI11066 CONFIDENTIAL

Hi Terry,

Thank you very much. We would be able to meet at 1:30 p.m. on Tuesday, August 14, 2012, if that is convenient for you and the other staff members.

(b)(4); (b)(3); CPSA Section 6(a); (b)(3); CPSA Section 6(b)

We look forward to meeting with you and other members of the staff to share this information and to discuss these issues.

Best regards,

Cheryl



GOLDBERG SEGALLA

New York London Philadelphia Princeton Hartford Buffalo
 Rochester Syracuse Albany White Plains Garden City

Cheryl A. Possenti, Esq.
 Partner
 665 Main Street / Suite 400
 Buffalo, NY 14203
 716.566.5444/FAX 716.566.5401
cpossenti@goldbergsegalla.com
<http://www.goldbergsegalla.com>

*This email message and any attachments are confidential.
 If you are not the intended recipient, please immediately
 reply to the sender and delete the message from your email
 system. Thank you.*

Privileged Attorney-Client Communication / Attorney's Work Product

From: Nelson, Theresa [mailto:TNelson@cpsc.gov]
Sent: Wednesday, July 18, 2012 11:07 AM
To: Cheryl Possenti; Moore, Kelly; Thomas, Treye
Cc: Pilarz, Kitty; Dzialga, Dan; Schoem, Marc
Subject: RE: Fisher-Price Rock 'n Play Sleeper PI11066 CONFIDENTIAL

Cheryl

February 28, 2012

Via Overnight Mail

Theresa Nelson
 Compliance Officer
 Office of Compliance & Field Operations
 U.S. Consumer Product Safety Commission
 4330 East West Highway
 Bethesda, MD 20814

Trey A. Thomas, Ph.D.
 Office of Hazard Identification & Reduction
 U.S. Consumer Product Safety Commission
 4330 East West Highway
 Bethesda, MD 20814

**Re: CPSC File No. PI110066
 Fisher-Price Rock 'n Play Sleeper™**

RECEIVED
 CPSC
 OFFICE OF COMPLIANCE
 2012 FEB 29 PM 2:27

Dear Ms. Nelson and Dr. Thomas:

Enclosed herewith is a courtesy copy of the supplemental submission we forwarded on February 24, 2012.

Very truly yours,



Cheryl A. Possenti

CAP/tb
 Enclosure

cc: Kitty Pilarz
 Senior Director, Mattel Product Safety
 Fisher-Price, Inc.

Daniel Dzialga, Esq.
 Senior Counsel
 Fisher-Price, Inc.

839636.1

(b)(5)

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Copy *Rock N Play*

Nelson, Theresa

From: Moore, Kelly
Sent: Monday, February 27, 2012 8:08 AM
To: Nelson, Theresa; Thomas, Treye
Subject: FP Rock N Play Sleeper
Attachments: DOC.PDF

Dr. Gots/mold

This just in from FP's lawyer.

(b)(4); (b)(3);CPSA Section 6(a); (b)(3);CPSA Section 6(b)

Please

review, and let's plan to circle up a few minutes before our call with the firm this afternoon.

FEB. 24. 2012 4:21PM

GOLDBERG SEGALLA LLP

NO. 6756 P. 1

**GOLDBERG SEGALLA^{LLP}**
*Attorneys at Law***Buffalo: 665 Main Street / Suite 400, Buffalo, New York 14203-1425**
716.566.5400 / FAX 716.566.5401

To: Kelly M. Moore, Esq.
Office of the General Counsel
Division of Compliance
U.S. Consumer Product Safety Commission

Fax No.: 301-504-0121

Telephone No.:

From: Cheryl A. Possenti, Esq.

Date: February 24, 2012

Comments: Enclosures to follow via overnight mail

Matter: CPSC File No. PI110066
Fisher Price Rock 'n Play SleeperTM

Number of Pages (including fax cover): 22
Please call 716.566.5400
if there are any problems with this transmission.

This document contains privileged and confidential information. This document is intended for the addressee. If you received this document in error, please notify this office and we will instruct you on its proper handling. Thank you.

Philadelphia
267.519.6800
FAX 267.519.6801

New York
646.253.5400
FAX 646.253.5500

Buffalo
716.566.5400
FAX 716.566.5401

Princeton
609.986.1300
FAX 609.986.1301

Hartford
860.760.3300
FAX 860.760.3301

Rochester
585.295.5400
FAX 585.295.8300

Syracuse
315.413.5400
FAX 315.413.5401

Albany
518.463.5400
FAX 518.463.5420

White Plains
914.798.5400
FAX 914.798.5401

Long Island
516.281.9800
FAX 516.281.9801

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Monthly Progress Reports FISHER-PRICE - "Rock 'N Play Sleeper" -recall to inspect for Mold January 8, 2013 (703,167 products sent to retailers between September 2009 - August 2012)							
REMEDY:	JAN18-March 31, 2013	April 1-30, 2013	May	June	July	August	TOTALS
Accept Cleaning Instructions							
Returned Product for Replacement							
Returned Product for Refund							
Returned Product for Voucher							
Replacement Pad Sent							
Resolution Pending*							
*Indicates firm is working through a remedy with consumer, consumer may be calling back, returning product to retail, etc.							updated 5/14/2013

(b)(4), (b)(3):CPSA Section
6(a), (b)(3):CPSA Section
6(b)

April 1 - April 30, 2013

Monthly Progress Report for Corrective Action Plan & Incident Update

CASE #: CA120159

Company Name: Fisher-Price, Inc.

Reporting Dates, From: 4/1/2013 To: 4/30/2013

Compliance Officer: Theresa Nelson

Product: Newborn Rock 'n Play Sleeper

Total# of Affected Products: 800,000

I) PRODUCTS CORRECTED/CAPTURED BY YOUR FIRM

Remedy Options

Accepted Cleaning Instructions
 Returned Product for Replacement Product
 Returned Product for Refund
 Returned Product for Voucher
 Replacement Pad Sent
 Resolution Pending*
 TOTALS:

Corrections this Period

(b)(4); (b)(3); CPSA Section 6(a); (b)(3); CPSA Section 6(b)

* Indicates the Firm is working through a remedy with consumer, consumer may be calling back, returning product to retail, etc.

II) Reports of Mold

This Period

Reports

(b)(4); (b)(3); CPSA Section 6(a); (b)(3); CPSA Section 6(b)

III) NOTIFICATION MEASURES:

(Using the categories listed below, record the number of notifications attempted by your firm during this reporting period, and record the total number of notifications to date.)

Direct Mail Letter to Known Owners

Direct email to Known Owners

Email to All Members of "Fisher-Price Family"

Social Media (Facebook) Posting (no. of followers)

Note: Retail posters were not necessary with this action as products at retail were unaffected

Number for this Reporting Period

(b)(4);
 (b)(3); C
 PSA
 Section
 6(a);
 (b)(3); C
 PSA
 Section
 6(b)

Total

(b)(4); (b)(3); CPSA
 Section 6(a);
 (b)(3); CPSA
 Section 6(b)

IV) Consumer Correspondence

From Customers This Reporting Period

Phone Contacts

E-mail Contacts

"Live Chats"

Web Site "Hits"

Written Inquiries

(b)(4);
 (b)(3); CPSA
 Section 6(a);
 (b)(3); CPSA
 Section 6(b)

NOTE: Submit completed by the FIRST of EACH MONTH to Judy Smith, Recall Coordinator at:
 United States Consumer Product Safety Commission, Office of Compliance
 4330 East West Highway, Room 613 Bethesda, MD 20814
 OR, fax report to (301) 504-0359 or email to jsmith@cpsc.gov. Address any questions to Ms. Smith at 301-504-7525

Nelson, Theresa

From: Crosby, Deb <Deb.Crosby@Fisher-Price.com>
Sent: Wednesday, May 01, 2013 4:17 PM
To: Nelson, Theresa; Moore, Kelly; Smith, Judy
Subject: Monthly Progress Report - Fisher-Price, Inc. - Newborn Rock 'n Play Sleeper - CA120159
Attachments: RocknPlay Sleeper-MPR-April 2013.pdf

Attached is our Monthly Progress Report for the above mentioned product for the period 4/1/2013 to 4/30/2013.

Thanks,

Deb Crosby
Sr. Safety Data Coordinator
Product Integrity

Fisher-Price, Inc.
636 Girard Avenue
East Aurora, NY 14052
716-687-3970 / Fax-3599
Deb.Crosby@Fisher-Price.com

This is Mattel confidential and proprietary information and is intended only for the person to whom it is addressed. Access, disclosure, copying, printing or distribution by anyone else is prohibited and may be a criminal offense.

This message (including any attachments) is only for the use of the person(s) for whom it is intended. It may contain Mattel confidential and/or trade secret information. If you are not the intended recipient, you should not copy, distribute or use this information for any purpose, and you should delete this message and inform the sender immediately.

Jan 1 - March 31, 2013

Monthly Progress Report for Corrective Action Plan & Incident Update

CASE #: CA 120159
 Company Name: Fisher-Price, Inc.
 Reporting Dates, From: 1/8/2013 To: 3/31/2013

Compliance Officer: Theresa Nelson
 Product: Newborn Rock 'n Play Sleeper
 Total# of Affected Products: 800,000

I) PRODUCTS CORRECTED/CAPTURED BY YOUR FIRM

Remedy Options

Accepted Cleaning Instructions
 Returned Product for Replacement Product
 Returned Product for Refund
 Returned Product for Voucher
 Replacement Pad Sent
 Resolution Pending*
 TOTALS:

Corrections this Period

_____	(b)(4); (b)(3) CPSC Section 6(a); (b)(3) CPSC Section 6(b)

* Indicates the Firm is working through a remedy with consumer, consumer may be calling back, returning product to retail, etc.

II) Reports of Mold

This Period

Reports _____

(b)(4); (b)(3) CPSC Section 6(a);

III) NOTIFICATION MEASURES:

(Using the categories listed below, record the number of notifications attempted by your firm during this reporting period, and record the total number of notifications to date.)

	Number for this Reporting Period	Total
Direct Mail Letter to Known Owners	_____	_____
Direct email to Known Owners	_____	_____
Email to All Members of "Fisher-Price Family"	_____	_____
Social Media (Facebook) Posting (no. of followers)	_____	_____

Note: Retail posters were not necessary with this action as products at retail were unaffected

IV) Consumer Correspondence

From Customers This Reporting Period

Phone Contacts	_____	(b)(4); (b)(3) CPSC Section 6(a); (b)(3) CPSC Section 6(b)
E-mail Contacts	_____	
"Live Chats"	_____	
Web Site "Hits"	_____	
Written Inquiries	_____	

NOTE: Submit completed by the FIRST of EACH MONTH to Judy Smith, Recall Coordinator at:
 United States Consumer Product Safety Commission, Office of Compliance
 4330 East West Highway, Room 613 Bethesda, MD 20814
 OR, fax report to (301) 504-0359 or email to jsmith@cpsc.gov. Address any questions to Ms. Smith at 301-504-7525

Nelson, Theresa

From: Crosby, Deb <Deb.Crosby@Fisher-Price.com>
Sent: Thursday, April 04, 2013 9:54 AM
To: Smith, Judy
Cc: Nelson, Theresa; Moore, Kelly
Subject: Monthly Progress Report - Newborn Rock 'n Play Sleeper - Fisher-Price - 1/8/13 to 3/31/13
Attachments: DOC.PDF

Follow Up Flag: Follow up
Flag Status: Flagged

Any questions can be directed to (b)(4); (b)(3) CPSA Section 6(a);
(b)(3) CPSA Section 6(b). This was also faxed to Ms. Smith on 4/3 and mailed first class.

Thanks,

Deb Crosby
Sr. Safety Data Coordinator
Product Integrity

Fisher-Price, Inc.
636 Girard Avenue
East Aurora, NY 14052
E 716-687-3970 / Fax-3599
Deb.Crosby@Fisher-Price.com

This is Mattel confidential and proprietary information and is intended only for the person to whom it is addressed. Access, disclosure, copying, printing or distribution by anyone else is prohibited and may be a criminal offense.

This message (including any attachments) is only for the use of the person(s) for whom it is intended. It may contain Mattel confidential and/or trade secret information. If you are not the intended recipient, you should not copy, distribute or use this information for any purpose, and you should delete this message and inform the sender immediately.

Nelson, Theresa

From: Crosby, Deb <Deb.Crosby@Fisher-Price.com>
Sent: Thursday, April 04, 2013 9:54 AM
To: Smith, Judy
Cc: Nelson, Theresa; Moore, Kelly
Subject: Monthly Progress Report - Newborn Rock 'n Play Sleeper - Fisher-Price - 1/8/13 to 3/31/13
Attachments: DOC.PDF

Follow Up Flag: Follow up
Flag Status: Flagged

Any questions can be directed to Don Fest (716-687-3653). This was also faxed to Ms. Smith on 4/3 and mailed first class.

Thanks,

Deb Crosby
Sr. Safety Data Coordinator
Product Integrity

Fisher-Price, Inc.
636 Girard Avenue
East Aurora, NY 14052
E 716-687-3970 / Fax-3599
Deb.Crosby@Fisher-Price.com

This is Mattel confidential and proprietary information and is intended only for the person to whom it is addressed. Access, disclosure, copying, printing or distribution by anyone else is prohibited and may be a criminal offense.

This message (including any attachments) is only for the use of the person(s) for whom it is intended. It may contain Mattel confidential and/or trade secret information. If you are not the intended recipient, you should not copy, distribute or use this information for any purpose, and you should delete this message and inform the sender immediately.

Nelson, Theresa

From: Fest, Don <Don.Fest@Fisher-Price.com>
Sent: Thursday, March 21, 2013 3:55 PM
To: Nelson, Theresa
Cc: Pilarz, Kitty; Moore, Kelly
Subject: RE: Rock n' Play Sleeper Monthly Progress Report

Hi Terry,

So glad you like the report.

I'll eliminate the cumulative data as you requested and submit the first report on (or shortly after) April 1.

Thanks,

Don Fest
Regulatory Project Manager
Product Integrity

Fisher-Price, Inc.
 636 Girard Ave.
 East Aurora, NY 14052
 ☎ 716.687.3653

From: Nelson, Theresa [<mailto:TNelson@cpsc.gov>]
Sent: Sunday, March 17, 2013 9:56 PM
To: Fest, Don
Cc: Pilarz, Kitty; Moore, Kelly
Subject: FW: Rock n' Play Sleeper Monthly Progress Report

Don – I apologize for not getting back to you sooner and yes, I'm sorry we missed meeting at ICPHSO as well. Yes, this proposed monthly report is much better and more accurate for reporting the returns since the recall. Instead of adding and sending a cumulative report each month added to the previous month, could you please send the numbers for the month that you are reporting? Other than that, this method would be great.

I will be out of the office this week. Feel free to email me if you have any questions.

Thanks, Terri

Terri Nelson

Compliance Officer
 Office of Compliance & Field Operations
 U.S. Consumer Product Safety Commission
 Phone: 301-504-7509 or
 1-800-638-8095 ext. 7509

Fax: 301-504-0359
tnelson@cpsc.gov

SIGN UP FOR RECALL NOTICES: <http://www.cpsc.gov/cpsclist.aspx>

From: Fest, Don [<mailto:Don.Fest@Fisher-Price.com>]
Sent: Monday, March 11, 2013 11:56 AM
To: Nelson, Theresa
Cc: Pilarz, Kitty
Subject: RE: Rock n' Play Sleeper Monthly Progress Report

Hello again Terri,

It was a pleasure speaking with you last week. Sorry I missed you at the ICPHSO conference. Regarding the Rock 'n Play, I spoke with our team regarding your thought that the current format of the Monthly Progress Report form will not work with the variety of "remedies" we offered. I have attached a proposed alternate form we could use for monthly reporting and we have entered data into it as of March 7, 2013 as an example. We have replaced the "incident" and "injury" categories with "Reports of Mold".

Thanks for your consideration. Please don't hesitate to contact me if you have any questions. Unless we hear anything to the contrary from you, we'll use this form to submit our first monthly progress report on April 1, 2013.

Don Fest
Regulatory Project Manager
Product Integrity

Fisher-Price, Inc.
636 Girard Ave.
East Aurora, NY 14052
716.687.3653

From: Nelson, Theresa [<mailto:TNelson@cpsc.gov>]
Sent: Sunday, March 10, 2013 8:21 PM
To: Fest, Don
Cc: Pilarz, Kitty
Subject: RE: Rock n' Play Sleeper Monthly Progress Report

Don – Thanks for the update. I need to be out of the office on Monday, but will check mail for your response.

Thanks, Terri

Terri Nelson

Compliance Officer
Office of Compliance & Field Operations
U.S. Consumer Product Safety Commission
Phone: 301-504-7509 or
1-800-638-8095 ext. 7509

Fax: 301-504-0359
tnelson@cpsc.gov

SIGN UP FOR RECALL NOTICES: <http://www.cpsc.gov/cpsclist.aspx>

From: Fest, Don [<mailto:Don.Fest@Fisher-Price.com>]
Sent: Friday, March 08, 2013 12:31 PM
To: Nelson, Theresa
Cc: Pilarz, Kitty
Subject: Rock n' Play Sleeper Monthly Progress Report

Hi Terri,

I just wanted to let you know that our team has been working on this and we're still finishing up.
I should have something for you on Monday.
Sorry for the delay.
Hope you have a great weekend.

Nelson, Theresa

From: Nelson, Theresa
Sent: Monday, April 29, 2013 5:06 PM
To: Cheryl Possenti (cpossenti@goldbergsegalla.com)
Cc: Fest, Don (Don.Fest@Fisher-Price.com); Pilarz, Kitty (Kitty.Pilarz@Fisher-Price.com); Moore, Kelly
Subject: CAP letter & reporting
Attachments: CAPacceptLtr.pdf

Cheryl – Attached is the Corrective Action Plan (CAP) accept letter with reporting obligations. I have worked with Don Fest since he has reported the firm's feedback from consumers since the recall on January 8th. Don submitted the Monthly Report on April 4th as included in the last page of the attached letter and will continue the monthly reporting obligation.

Please let me know if you have any questions.

Terri

Terri Nelson

Compliance Officer
Office of Compliance & Field Operations
U.S. Consumer Product Safety Commission
Phone: 301-504-7509 or
1-800-638-8095 ext. 7509

Fax: 301-504-0359
tnelson@cpsc.gov

SIGN UP FOR RECALL NOTICES: <http://www.cpsc.gov/cpsclist.aspx>

7010 1870 0003 4102 9290

U.S. Postal Service TM
CERTIFIED MAIL TM **RECEIPT**
 (Domestic Mail Only; No Insurance Coverage Provided)

For delivery information visit our website at www.usps.com

OFFICIAL USE

Postage	\$	F.I.
Certified Fee		
Return Receipt Fee (Endorsement Required)		
Restricted Delivery Fee (Endorsement Required)		
Total Postage & Fees	\$	

Postmark Here

Sent To
 CA 120159
 Street, Apt. No.,
 or PO Box No.
 City, State, ZIP+4

PS Form 3800, August 2006 See Reverse for Instructions



U.S. CONSUMER PRODUCT SAFETY COMMISSION
4330 EAST WEST HIGHWAY
BETHESDA, MD 20814

Office of Compliance and Field Operations
Defect Investigations Division
Email: tnelson@cpsc.gov

Theresa Nelson
Compliance Officer
Tel: 301-504-7509
Fax: 301-504-0060

APR 29 2013

Certified Mail/Email:
cpossent@goldbergsegalla.com
Don.Fest@Fisher-Price.com
Kitty.Pilarz@Fisher-Price.com

Ms. Cheryl Possenti, Esq.
Partner, Goldberg Segalla
665 Main Street, Suite 400
Buffalo NY 14203

Re: CPSC File No. CA120159
Fisher-Price, Inc.
Rock 'N Play Sleepers

Dear Ms. Possenti,

The staff of the Office of Compliance and Field Operations of the U.S. Consumer Product Safety Commission ("CPSC" or "Commission") has reviewed the corrective actions by Fisher-Price, Inc. ("the Firm") concerning Rock 'N Play Sleepers for the recall on January 8, 2013: <http://www.cpsc.gov/en/Recalls/2013/Fisher-Price-Recalls-to-Inspect-Rock-N-Play-Infant-Sleepers-Due-to-Risk-of-Exposure-to-Mold/>

Acting under delegation from the Commission, the staff has accepted the corrective action plan ("CAP") as adequate. The CAP accepted by the staff includes the following actions:

- Joint press release issued on January 8, 2013;
- Letter to Retailers informing of "recall to inspect" (January 7, 2013);
- Recall notice http://service.mattel.com/us/recall/rock_sleepernew.asp posted on Firm's website and social media platforms such as Facebook, Twitter;
- Inspect/replacement/refund;

Page 2
#CA120159

- Renegotiate the CAP should the Commission staff determine its effectiveness to be less than adequate;
- Submit modified Monthly Progress Reports in the format agreed upon with Compliance staff (see specific instructions below).

Please continue the corrective actions implemented and initiate any others contained in the CAP. The Office of Compliance and Field Operations will be monitoring the CAP.

Monthly Progress Report Submission

An alternate Monthly Progress Report has been agreed upon with Don Fest, the Firm's Regulatory Project Manager, due to the nature of this recall since consumers are not returning all of the Subject Products. A copy of the first Monthly Progress Report submitted on April 4th, 2013, is included with this letter. The "incident" and "injury" categories have been replaced with "Reports of Mold." Incidents and injuries will continue be reported to CPSC on this product through the retail reporting system already in place.

Deb Crosby, the Firm's Sr. Safety Data Coordinator, will continue to submit the monthly reports for Case #CA121059 to Judy Smith, CPSC's Recall Coordinator at jsmith@cpsc.gov and cc'd to me at tnelson@cpsc.gov.

CPSC Staff Monitoring of Corrective Action Plan

In addition to reviewing the Firm's monthly progress reports, field investigators and/or state investigators may be contacting retailers and consumers who may have received the Subject Products to confirm their receipt of the approved notification material and the Firm's compliance with the associated instructions pursuant to the CAP.

When the Firm determines that the CAP has been implemented to the best of the Firm's ability and as many products as possible have been removed from the marketplace, it may submit a final progress report, referencing the file number, and request that the file be closed. At that time, the staff will review the CAP's progress and decide whether the file should be closed. The Office of Compliance and Field Operations will evaluate the effectiveness of the CAP. The staff could seek broader corrective action if the CAP does not prove effective. When the staff closes its file on a CAP, it asks that the Firm continue the CAP until as many of the Subject Products as possible have been removed from the marketplace. Please continue to maintain the Firm's toll-free recall number as a means for consumers to reach the Firm about the recall. Should the Firm decide to change or discontinue its toll-free recall number, the Firm must immediately notify the Office of Compliance and Field Operations and provide a new recall contact number for the Firm. If the Firm wishes to change the terms of the CAP, it must also discuss any proposal with us before it makes any change. This information will be maintained by the Commission and provided to consumers and others seeking information on the recall or CAP.

Compliance with Reporting Obligations

The staff will also investigate and assess whether it believes the Firm has complied with

Page 3
#CA120159

the reporting requirements of section 15(b) of the CPSA, 15 U.S.C. § 2064(b). That section requires every manufacturer, importer, distributor, and retailer of a consumer product, or of any other product or substance over which the CPSC has jurisdiction under any other statute enforced by the CPSC, who obtains information which reasonably supports the conclusion that the product (1) contains a defect which could create a substantial product hazard, (2) creates an unreasonable risk of serious injury or death, (3) fails to comply with an applicable consumer product safety rule or with a voluntary consumer product safety standard upon which the CPSC has relied under section 9 of the CPSA, 15 U.S.C. § 2058, or (4) fails to comply with any other rule, regulation, standard, or ban under the CPSA or any other statute enforced by the CPSC, to immediately inform the CPSC of the defect, risk, or failure to comply, unless the firm has actual knowledge that the CPSC has been adequately informed of the defect, risk, or failure to comply. See 16 C.F.R. Part 1115.

Failure to comply with the CPSC's reporting requirements is a prohibited act under Sections 19(a)(3) and (4) of the CPSA, 15 U.S.C. §§ 2068(a)(3) and (4). Pursuant to section 20 of the CPSA, 15 U.S.C. § 2069, such violations could subject you and the Firm to civil penalties of up to \$100,000 per violation up to a maximum of \$15.15 million for any related series of violations. In addition, pursuant to section 21 of the CPSA, 15 U.S.C. § 2070, such violations could subject you and the Firm to criminal penalties including a fine, imprisonment for not more than five (5) years and forfeiture of assets associated with the violation(s).

Continuing Obligations and Duty to Preserve

If the Firm receives or learns of any information concerning complaints, claims, incidents, or injuries that the Firm did not report, or other information affecting the scope, prevalence, or seriousness of the reported problem, issue, or potential defect or hazard, the Firm must immediately report that information to the Office of Compliance and Field Operations. Additionally, if the Firm receives information that might indicate that its corrective actions are not satisfactory in eliminating the problem, risk of injury, or potential defect or hazard, or that the effectiveness of the CAP is less than had been anticipated, it must immediately report that information to the Office of Compliance and Field Operations. In addition, under section 19(a)(2)(B) of the Consumer Product Safety Act ("CPSA"), 15 U.S.C. § 2068(a)(2)(B), it is unlawful to sell, offer for sale, manufacture for sale, distribute in commerce, or import into the United States a product that is covered by a manufacturer's corrective action plan created in consultation with, and publicized by, the Commission.

Until this matter and any related matters are resolved, there will remain the possibility of further enforcement action, including reasonably anticipated litigation. Therefore, the Firm must abide by the continuing legal obligation to preserve all information, documents, electronically-stored data, and samples, now in existence or created hereafter, related to the Subject Product.

Information Disclosure

Section 6(b)(1) of the CPSA, 15 U.S.C. § 2055(b)(1), requires the Commission to provide manufacturers and private labelers with advance notice and opportunity to comment on information the Commission intends to disclose, if the public can readily ascertain the identity of

Page 4
#CA120159

the Firm from the information the Commission intends to disclose. See 16 C.F.R. Part 1101. The staff is enclosing a summary of the CAP which the Commission intends to disclose to the public. **For full consideration, your written comments must be received within 10 calendar days of the date of this letter.** Please include with any comments specific information and documents, where available, to support any claim that the information is inaccurate. If you have no comments or objections, you are not obligated to respond. If the Commission decides to disclose the information, over any accuracy objections, it will give the Firm five (5) days' notice, as required by section 6(b)(2) of the CPSA, 15 U.S.C. § 2055(b)(2), unless the Commission publishes a finding that the public health and safety require less notice.

Contact Information

Thank you for your continued cooperation in this matter. If you have any questions, please contact me at 301-504-7509 or tnelson@cpsc.gov. Written correspondence may be addressed to: Office of Compliance and Field Operations, U.S. Consumer Product Safety Commission, Room 613-28, 4330 East West Highway, Bethesda, MD 20814-4408.

Sincerely,



Theresa Nelson
Compliance Officer
Defect Investigations Division

Enclosures/Links:

- Corrective Action Plan Summary – see below
- Monthly Progress Report Form – attached electronically

cc: Kitty Pilarz
Kelly Moore
Judy Smith

Voluntary Corrective Action Plans Under Section 15
of the Consumer Product Safety Act and
Section 15 of the Federal Hazardous Substances Act

The following is a list of voluntary corrective action plans recently accepted by the Commission (or the staff acting under authority delegated by the Commission). A firm's taking corrective action does not constitute an admission by the firm that a substantial product hazard exists.

Space does not permit the staff to give a complete list of the specific model numbers of the products involved in each of these corrective actions. Consumers who believe that they have a product affected by one of these actions should follow the instructions given in this list or contact either the manufacturer or the Commission to determine if their product is one of those affected.

Corrective Action Plan Summary

DATE	FIRM AND PRODUCT	ALLEGED HAZARD	CORRECTIVE NARRATIVE
4/17/2013	Fisher-Price, Inc. 636 Girard Ave. East Aurora, NY 14052 Rock 'N Play Sleeper	Infants in product containing mold may be more susceptible to respiratory illness or may experience the exacerbation of respiratory illnesses.	Recall to Inspect Rock 'N Play Infant Sleepers due to risk of exposure to mold. Firm agreed to Replace or Refund if mold could not be eradicated with cleaning.

Monthly Progress Report for Corrective Action Plan & Incident Update

CASE #: CA120159

Company Name: Fisher-Price, Inc.

Reporting Dates, From: 1/8/2013 To: 3/31/2013

Compliance Officer: Theresa Nelson

Product: Newborn Rock 'n Play Sleeper

Total# of Affected Products: 800,000

I) PRODUCTS CORRECTED/CAPTURED BY YOUR FIRM

Remedy Options

Accepted Cleaning Instructions
 Returned Product for Replacement Product
 Returned Product for Refund
 Returned Product for Voucher
 Replacement Pad Sent
 Resolution Pending*
 TOTALS:

Corrections this Period

_____	(b)(4); (b)(3) CPSCA Section 6(a);
_____	(b)(3) CPSCA Section 6(b)

* Indicates the Firm is working through a remedy with consumer, consumer may be calling back, returning product to retail, etc.

II) Reports of Mold

This Period

Reports

_____	(b)(4); (b)(3) CPSCA Section 6(a);
-------	--

III) NOTIFICATION MEASURES:

(Using the categories listed below, record the number of notifications attempted by your firm during this reporting period, and record the total number of notifications to date.)

	Number for this Reporting Period	Total
Direct Mail Letter to Known Owners	_____	_____
Direct email to Known Owners	_____	_____
Email to All Members of "Fisher-Price Family"	_____	_____
Social Media (Facebook) Posting (no. of followers)	_____	_____

Note: Retail posters were not necessary with this action as products at retail were unaffected

IV) Consumer Correspondence

From Customers This Reporting Period

Phone Contacts
 E-mail Contacts
 "Live Chats"
 Web Site "Hits"
 Written Inquiries

_____	(b)(4); (b)(3) CPSCA Section 6(a);
_____	(b)(3) CPSCA Section 6(b)

NOTE: Submit completed by the FIRST of EACH MONTH to Judy Smith, Recall Coordinator at:
 United States Consumer Product Safety Commission, Office of Compliance
 4330 East West Highway, Room 613 Bethesda, MD 20814
 OR, fax report to (301) 504-0359 or email to jsmith@cpsc.gov. Address any questions to Ms. Smith at 301-504-7525

U.S. CONSUMER PRODUCT SAFETY COMMISSION

Office of Compliance and Field Operations

Firm Name: Fisher-Price, Inc.
 Product Brand: Fisher-Price
 Product Model: All models
 Product Name: Rock N Play Sleeper

File Number: CA120159

Hazard Priority: c

CORRECTIVE ACTION PLAN:

A. Notice (to Consumers):

	Event:	Date:
<input checked="" type="checkbox"/>	Press release/recall alert	January 8, 2013
	Direct mail (%)	
	Point of purchase signs	
	Advertising (describe)	
<input checked="" type="checkbox"/>	Firm website	January 8, 2013
<input checked="" type="checkbox"/>	Social media (Facebook, Twitter, etc.)	January 8, 2013
	Video news release	
	Other (describe) :	

B. Repair, replacement, refund:

<input checked="" type="checkbox"/>	repair approved by technical support
	replacement with product approved by technical support
<input checked="" type="checkbox"/>	Refund
	other (describe) :

C. Procedures:

	Distribution chain recall
	manufacturer/importer level
	wholesaler/distributor level
	retailer level
	consumer level
<input checked="" type="checkbox"/>	Mail in to firm
<input checked="" type="checkbox"/>	Return to retailer
<input checked="" type="checkbox"/>	repair or replace
	Home visit
	At dealer
<input checked="" type="checkbox"/>	At Retailer
<input checked="" type="checkbox"/>	Home repair by consumer
<input checked="" type="checkbox"/>	Toll-free line
<input checked="" type="checkbox"/>	Website registration
	Other (describe) :

Firm Name: Fisher-Price, Inc.

File Number: CA120159

D. Effectiveness:

	Total Products Involved:	Total Products Corrected:
At Manufacturer:		
At Distributors:		
At Retailers:		
With Consumers:	800,000	
Totals:	800,000	

E. Decision on corrective action:

<input checked="" type="checkbox"/>	Accept CAP and Monitor
	Fast Track Product Recall Case
	Accept CAP and Close File (provide rationale)
	Pursue further remedial action (provide rationale)
	Refer to Legal Division
	Refer to Commission with recommendation to accept CAP [Class A case]

F. Data Quality (Performance Goal):

<input checked="" type="checkbox"/>	All appropriate firm and mail firm data entered and verified
<input checked="" type="checkbox"/>	Hazard code verified and country of origin verified
<input checked="" type="checkbox"/>	Products involved and corrected identical to database numbers
<input checked="" type="checkbox"/>	All associated IDI's linked in Case Management System
<input checked="" type="checkbox"/>	All associated samples linked in Case Management System
<input checked="" type="checkbox"/>	All sample collection reports reviewed for accuracy and MIS #
<input checked="" type="checkbox"/>	All samples have accurate SEND and RECEIVE location info in Sample Tracking
	All incident data submitted to EPI

CAP APPROVALS:

Compliance Officer	<i>Alicia Nelson</i> 4/8/2013
Attorney	<i>Will</i> 4/22/2013
Compliance Lead	<i>Rachel</i> 4/18/13
Director – CRE/CDI	<i>[Signature]</i> 4/22/13



NEWS from CPSC



U.S. Consumer Product Safety Commission

Office of Communications

Washington, D.C.

FOR IMMEDIATE RELEASE
January 8, 2013
Release #13-087

Firm's Recall Hotline: (800) 432-5437
CPSC Recall Hotline: (800) 638-2772
CPSC Media Contact: (301) 504-7908

Fisher-Price Recalls to Inspect Rock 'N Play Infant Sleepers Due to Risk of Exposure to Mold

WASHINGTON, D.C. - The U.S. Consumer Product Safety Commission, in cooperation with the firm named below, today announced a voluntary recall of the following consumer product. Consumers should immediately inspect this product and stop using it if mold is found. Units currently in retail stores are not included in this recall to inspect.

Name of Product: Newborn Rock 'n Play Sleeper™

Units: About 800,000 units

Importer: Fisher-Price Inc., of East Aurora, N.Y

Hazard: Mold can develop between the removable seat cushion and the hard plastic frame of the sleeper when it remains wet/moist or is infrequently cleaned, posing a risk of exposure to mold to infants sleeping in the product. The CPSC advises that mold has been associated with respiratory illnesses and other infections. Although mold is not present at the time of purchase, mold growth can occur after use of the product.

Incidents/Injuries: Fisher-Price has received 600 reports of mold on the product. Sixteen consumers have reported that their infants have been treated for respiratory issues, coughs and hives after sleeping in the product.

Description: This recall to inspect includes all Fisher-Price Rock N' Play infant recliner seats called sleepers. The sleeper is designed for babies up to 25 pounds and is composed of a soft plastic seat held by a metal rocking frame. The product has a removable, fabric cover that is sold in 14 patterns and color palettes.

Sold at: Mass merchandise stores nationwide and online since September 2009 for between \$50 and \$85. Units currently in retail stores are not affected by this recall to inspect. Only products that show signs of mold after use by consumers are included in this announcement.


Manufactured in: China

Remedy: Consumers should immediately check for mold under the removable seat cushion. Dark brown, gray or black spots can indicate the presence of mold. If mold is found, consumers should immediately stop using the product. Consumers can contact Fisher-Price for cleaning instructions or further assistance. Cleaning and care instructions can also be found at www.service.mattel.com or by contacting the firm.

Consumer Contact: Fisher-Price; at (800) 432-5437, from 9 a.m. to 6 p.m. ET Monday through Friday, or online at www.service.mattel.com for more information.



Fisher-Price Rock 'N Play Infant Sleeper



Fisher-Price Infant Sleeper Removable Seat Cushion

The U.S. Consumer Product Safety Commission (CPSC) is still interested in receiving incident or injury reports that are either directly related to this product recall or involve a different hazard with the same product. Please tell us about your experience with the product on SaferProducts.gov

CPSC is charged with protecting the public from unreasonable risks of injury or death associated with the use of the thousands of consumer products under the agency's jurisdiction. Deaths, injuries and property damage from consumer product incidents cost the nation more than \$900 billion annually. CPSC is committed to protecting consumers and families from products that pose a fire, electrical, chemical or mechanical hazard. CPSC's work to ensure the safety of consumer products - such as toys, cribs, power tools, cigarette lighters and household chemicals - contributed to a significant decline in the rate of deaths and injuries associated with consumer products over the past 30 years.

To report a dangerous product or a product-related injury go online to www.SaferProducts.gov or call CPSC's Hotline at (800) 638-2772 or teletypewriter at (800) 638-8270 for the hearing impaired. Consumers can obtain news release and recall information at www.cpsc.gov, on Twitter @OnSafety or by subscribing to CPSC's [free e-mail newsletters](#).

Connect with us!



YouTube



Twitter



Flickr



**Mattel & Fisher-Price
Customer Service**

[Parts Order Status](#) | [Where to Buy](#)



[Search all of service.mattel.com](#)

[Home](#) > [Recall](#)

Recall Information

Recall to Inspect

Fisher-Price®, in cooperation with the United States Consumer Product Safety Commission, is voluntarily announcing a recall to inspect Fisher-Price Newborn Rock 'n Play Sleepers™. Mold can develop between the removable seat cushion and the hard plastic frame of the sleeper when it remains wet/moist or is infrequently cleaned.



Mold is not present at the time of purchase, but mold can grow after use of the product. Newborn Rock 'n Play™ Sleepers currently in retail stores are not affected by this recall to inspect.

The Newborn Rock 'n Play Sleeper™ is designed for babies up to 25 pounds and is composed of a metal rocking frame and removable, washable fabric cover. The product is sold in various patterns and color palettes.

Please examine under the removable fabric seat cover and fabric liner for dark brown, gray or black spots indicating mold.



If mold growth is discovered, you can click [here](#) for cleaning instructions.

You can also contact Fisher-Price at 1-800-432-5437 Monday through Friday between the hours of 9 AM and 6 PM Eastern Time.

You can click [here](#) for the press release.

Fisher-Price

Mattel

[Product Recalls & Safety Alerts](#) | [Instruction Sheets](#) | [Technical Product Support](#) | [FAQ Search](#) | [Power Wheels Service](#) | [Contact Us](#) | [International](#)
[Mattel Shop](#) | [Fisher-Price Shop](#) | [Barbie Collector](#) | [Hot Wheels Collector](#) | [American Girl Shop](#) | [Corporate Information](#)
[Mattel](#) | [Fisher-Price](#) | [Barbie](#) | [Hot Wheels](#) | [Matchbox](#) | [Power Wheels](#) | [Tyco](#)

Use of this site signifies your acceptance of Mattel's Website Terms and Conditions and Privacy Policy.
©2013 Mattel, Inc. All Rights Reserved.



U.S. Consumer Product Safety Commission – Recall

Recall Date: January 8, 2013

Recall Number: 13-087

Fisher-Price Recalls to Inspect Rock ‘N Play Infant Sleepers Due to Risk of Exposure to Mold

WASHINGTON, D.C. – *Consumers should immediately inspect this product and stop using it if mold is found. Units currently in retail stores are not included in this recall to inspect.*

Recall Summary

Name of product: Newborn Rock ‘n Play Sleeper™

Hazard: Mold can develop between the removable seat cushion and the hard plastic frame of the sleeper when it remains wet/moist or is infrequently cleaned, posing a risk of exposure to mold to infants sleeping in the product. The CPSC advises that mold has been associated with respiratory illnesses and other infections. Although mold is not present at the time of purchase, mold growth can occur after use of the product.

Remedy: New Instructions, Repair

Consumer Contact: Fisher-Price; at (800) 432-5437, from 9 a.m. to 6 p.m. ET Monday through Friday, or online at www.service.mattel.com for more information.

Recall Details

Units: About 800,000 units

Description: This recall to inspect includes all Fisher-Price Rock N’ Play infant recliner seats called sleepers. The sleeper is designed for babies up to 25 pounds and is composed of a soft plastic seat held by a metal rocking frame. The product has a removable, fabric cover that is sold in 14 patterns and color palettes.

Incidents/Injuries: Fisher-Price has received 600 reports of mold on the product. Sixteen consumers have reported that their infants have been treated for respiratory issues, coughs and hives after sleeping in the product.

Remedy: Consumers should immediately check for mold under the removable seat cushion. Dark brown, gray or black spots can indicate the presence of mold. If mold is found, consumers should immediately stop using the product. Consumers can contact Fisher-Price for cleaning instructions or further assistance. Cleaning and care instructions can also be found at www.service.mattel.com or by contacting the firm.

Sold at: Mass merchandise stores nationwide and online since September 2009 for between \$50 and \$85. Units currently in retail stores are not affected by this recall to inspect. Only products that show signs of mold after use by consumers are included in this announcement.

Importer: Fisher-Price Inc., of East Aurora, N.Y.

Manufactured in: China

The U.S. Consumer Product Safety Commission (CPSC) is still interested in receiving incident or injury reports that are either directly related to this product recall or involve a different hazard with the same product. Please tell us about your experience with the product on SaferProducts.gov.

CPSC is charged with protecting the public from unreasonable risks of injury or death associated with the use of the thousands of consumer products under the agency's jurisdiction. Deaths, injuries, and property damage from consumer product incidents cost the nation more than \$900 billion annually. CPSC is committed to protecting consumers and families from products that pose a fire, electrical, chemical, or mechanical hazard. CPSC's work to ensure the safety of consumer products—such as toys, cribs, power tools, cigarette lighters, and household chemicals—contributed to a decline in the rate of deaths and injuries associated with consumer products over the past 30 years.

To report a dangerous product or a product-related injury, go online to: SaferProducts.gov, call CPSC's Hotline at (800) 638-2772 or teletypewriter at (301) 595-7054 for the hearing and speech impaired. Consumers can obtain this news release and product safety information at www.cpsc.gov. To join a free e-mail subscription list, please go to www.cpsc.gov/cpsclist.aspx.

Photos will display in a slideshow at the top right of the recall.



Photo 1 Caption: Fisher-Price Rock 'N Play Infant Sleeper




Photo2 Caption: Fisher-Price Infant Sleeper Removable Seat Cushion

Nelson, Theresa

From: Pilarz, Kitty <Kitty.Pilarz@Fisher-Price.com>
Sent: Wednesday, January 09, 2013 9:33 PM
To: Nelson, Theresa
Cc: Schoem, Marc
Subject: FW: Rock and Play Sleeper - letter to retailers
Attachments: LetterToRetailers.PDF

Hi Terri,

(b)(4); (b)(3);CPSA Section 6(a); (b)(3);CPSA Section 6(b)

Best regards, Kitty

Confidential treatment requested

Submitted under section 15b

Kitty Pilarz
Senior Director, Mattel Product Safety
Fisher-Price
636 Girard Avenue
East Aurora, New York 14052
716-687-3343

This message (including any attachments) is only for the use of the person(s) for whom it is intended. It may contain Mattel confidential and/or trade secret information. If you are not the intended recipient, you should not copy, distribute or use this information for any purpose, and you should delete this message and inform the sender immediately.

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Nelson, Theresa

From: Pilarz, Kitty <Kitty.Pilarz@Fisher-Price.com>
Sent: Friday, October 12, 2012 9:43 AM
To: Moore, Kelly; Nelson, Theresa
Cc: Schoem, Marc; Murphy, Mary
Subject: FW: Rock and Play Sleeper
Attachments: RNPSMessage_10.11.12.doc; Keep This Product Clean and DryFINALdocx.docx

Dear Kelly and Terri,

Here is our communication plan.

(b)(4); (b)(3);CPSA Section 6(a); (b)(3);CPSA Section 6(b)

(b)(4); (b)(3);CPSA Section 6(a); (b)(3);CPSA Section 6(b)

(b)(4); (b)(3); CPSA Section 6(a); (b)(3); CPSA Section 6(b)

Best regards, Kitty

Confidential treatment requested

Submitted under section 15b

Kitty Pilarz
Senior Director, Mattel Product Safety
Fisher-Price
636 Girard Avenue
East Aurora, New York 14052
716-687-3343

From: Moore, Kelly [<mailto:KMoore@cpsc.gov>]
Sent: Wednesday, October 10, 2012 4:15 PM
To: Pilarz, Kitty
Cc: Schoem, Marc; Nelson, Theresa; Murphy, Mary
Subject: RE: Rock and Play Sleeper

Kitty,

Thank you for your response. At the outset, we all agree that we need to cast a wide net to communicate the message to consumers and, to that end, we support your use of the forms of media you identified. As we have told you previously, we will work with you to ensure that the wording of the message does not cause, as you put it, "undue alarm." However, because mold exposure can be harmful to infants, the message bears repeating in a press release to the general public. (b)(3); CPSA Section 6(b)

(b)(4); (b)(3); CPSA Section 6(a); (b)(3); CPSA Section 6(b)

We look forward to reviewing your communications plan. When it will be available?

Thanks,
Kelly

From: Pilarz, Kitty [<mailto:Kitty.Pilarz@Fisher-Price.com>]
Sent: Tuesday, October 09, 2012 10:51 AM
To: Nelson, Theresa
Cc: Schoem, Marc; Moore, Kelly
Subject: Rock and Play Sleeper

Dear Terri,

(b)(4); (b)(3); CPSA Section 6(a); (b)(3); CPSA Section 6(b)

1.
2.
3.
4.

(b)(4); (b)(3):CPSA Section 6(a); (b)(3):CPSA Section 6(b)

Confidential treatment requested

Submitted under section 15b

Kitty Pilarz

Senior Director, Mattel Product Safety

Fisher-Price

636 Girard Avenue

East Aurora, New York 14052

716-687-3343

This message (including any attachments) is only for the use of the person(s) for whom it is intended. It may contain Mattel confidential and/or trade secret information. If you are not the intended recipient, you should not copy, distribute or use this information for any purpose, and you should delete this message and inform the sender immediately.

*****!!! Unless otherwise stated, any views or opinions expressed in this e-mail (and any attachments) are solely those of the author and do not necessarily represent those of the U.S. Consumer Product Safety Commission. Copies of product recall and product safety information can be sent to you automatically via Internet e-mail, as they are released by CPSC. To subscribe or unsubscribe to this service go to the following web page: <https://www.cpsc.gov/cpsclist.aspx> *****!!!

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)


of the Freedom of Information Act

Withheld pursuant to exemption


(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act


(b) (3) (A), (b) (4)




(b) (3) (A), (b) (4)




(b) (3) (A), (b) (4)




(b) (3) (A), (b) (4)



(b) (3) (A), (b) (4)




(b) (3) (A), (b) (4)




(b) (3) (A), (b) (4)



(b) (4), (b) (3) (A)



(b) (3) (A), (b) (4)



Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act

Withheld pursuant to exemption

(b)(4) ; (b)(3):CPSA Section 6(a) ; (b)(3):CPSA Section 6(b)

of the Freedom of Information Act