

U.S. CONSUMER PRODUCT SAFETY COMMISSION

WASHINGTON, D.C. 20207
MINUTES OF COMMISSION MEETINGS

September 21, 1983

Third Floor Hearing Room 1111 - 18th Street, N. W. Washington, D.C.

The September 21, 1983, meeting of the U.S. Consumer Product Safety Commission was convened in open session by Chairman Nancy Harvey Steorts. Commissioners Terrence Scanlon, Edith Barksdale Sloan, Stuart M. Statler and Sam Zagoria were present.

Before moving to the agenda, Commissioner Zagoria read a statement concerning the Commission vote to convene a Chronic Hazard Advisory Panel on formaldehyde that was taken at the September 15, 1983, Commission meeting at which he was not present. Commissioner Sloan, who also was not present at that meeting, stated that she would be issuing a written statement on the matter. Chairman Steorts requested the General Counsel to prepare a memorandum of advice on the procedural issues relating to the meeting.

Agenda Matters.

1. Metal Factory-Built Chimneys.

The staff briefed the Commission on activities relating to the investigation of fire-safety problems associated with certain metal factory-built chimneys. Included in the briefing were discussions of industry-submitted fire data, current industry activities, planned CPSC investigations, plans for updating CPSC's April 1983 consumer safety alert and options for regulatory action. Staff reported that its previous recommendation to issue an advance Notice of Proposed Rulemaking is still the staff's recommendation, except that the majority of staff believes a decision to take this action should be deferred until further investigations are completed. The Commission will consider the matter of regulatory options at a future Commission meeting.

Closed to the Public.

2. Enforcement Matter: Mesh-Sided Cribs and Playpens (OS #5083)

Meeting then in closed session, the Commission decided by a vote of 4-1 to authorize the staff to issue an administrative complaint for public notice and remedial action against nine manufacturers of mesh-sided cribs and playpens under Section 15 of the Consumer Product Safety Act. Commissioner Scanlon voted not to authorize the complaint and to direct staff to organize a joint CPSC/Juvenile Products Manufacturing Association press conference and to accept industry's additional corrective action plan. Commissioner Scanlon filed a brief statement of his views with the Office of the Secretary. (Attached)

Page 2 - Minutes of Commission Meeting, September 21, 1983

3. Enforcement Matter (OS #3391)

The Commission considered issues relating to enforcement matter OS #3391, and provided instructions to the staff.

4. Commission Policy on Separate Opinions

The Commission reviewed the procedures it will use to note separate or dissenting opinions in $\underline{\text{Federal}}$ Register notices and press releases. The Office of the General Counsel is to issue a statement of the procedures adopted by the Commission.

There being no further business on the agenda, Chairman Steorts adjourned the meeting.

For the Commission:

October 18,1983

Sadye E. Dunn Secretary

Attachment

* See attached, November 14, 1983, General Counsel Memorandum



U.S. CONSUMER PRODUCT SAFETY COMMISSION WASHINGTON, D.C. 20207

SEPARATE VIEWS OF COMMISSION SCANLON ON ENFORCEMENT MATTER (#05083) ON MESH SIDED CRIBS/PLAYPENS

Commissioner Scanlon voted not to authorize the complaint and wanted to direct the staff to organize a joint Consumer Product Safety Commission/Juvenile Products Manufacturing Association Press Conference, and to accept and work with industry's additional corrective action plan as outlined in the September 20, 1983, Juvenile Products Manufacturing Associations counsel letter. This would provide adequate notice to the consumers of the potential hazard, without the adversarial litigation if a complaint were issued, which complaint would make cooperative efforts impossible and in the long run deny adequate notice to the public. This vote was based upon information before the Commission at this time.

19. The sides of the cribs can be lowered and are known as "dropsides."

The cribs bear no labels warning of suffocation or asphyxiation hazards.

- 21. The cribs were produced or distributed for sale to consumers for use by infants and young children (children) in or around permanent or temporary households or residences, in recreation or otherwise, or for the personal use, consumption, or enjoyment of children in or around a permanent or temporary household or residence, in recreation, or otherwise.
- 22. The cribs are "consumer products" within the meaning of section 3(a)(1), CPSA, 15 U.S.C. 2052(a)(1).

Substantial Product Hazard

23. When a side of a crib is down, the mesh of that side forms a loose pocket which can extend beyond and below the floor of the crib.

24. When a side of a crib is down, there is no barrier to prevent a child from falling off the floor of the crib.

25. Children can and have fallen off the floor of a crib with a side down into the loose mesh pocket.

26. Children caught or trapped in the mesh pocket of a lowered side can and have been killed by lack of air due to compression of the chest or obstruction of the nose and/or mouth or by other causes.

27. Children entrapped in the mesh pocket of a lowered side can suffer brain damage or other injury caused by lack of air and/or compression.

28. Three children are known to have died in cribs manufactured by Respondent Pride-Trimble when they became entrapped in the mesh pocket formed by a lowered side.

29. One child is known to have died in a crib manufactured by Respondent Century Products, Inc. when she became entrapped in the mesh pocket formed by a lowered side.

30. One child is known to have suffocated to death in the mesh pocket formed by the lowered side of a crib similar to those manufactured by Respondents Pride-Trimble and Century.

31. Six children are known to have been killed in the same manner in dropside mesh-sided playpens.

32. In addition, one child is known to have stopped breathing and required emergency treatment when she became entrapped in the mesh pocket of a lowered side of a crib manufactured by Respondent Pride-Trimble.

33. The dropsides of the cribs are a defect in the cribs within the meaning of section 15(a)(2), CPSA, 15 U.S.C.

2064(a)(2).

34. The mesh pocket formed by a side when it is down is a defect in the cribs

within the meaning of section 15(a)(2), CPSA, 15 U.S.C. 2084(a)(2).

35. The lack of a barrier to prevent children from falling off the floor of the cribs when a side is lowered is a defect in the cribs within the meaning of section 15(a)(2), CPSA, 15 U.S.C. 2064(a)(2).

36. Parents and others such as baby sitters are unaware of the asphyxiation hazards presented by a crib with a side that is down.

37. The cribs contain no warnings that a side that is lowered presents asphyxiation hazards.

38. Warnings accompanying the cribs are inadequate to give notice of the asphyxiation hazards presented by a lowered side.

39. The failure to provide warnings and the lack of adequate warnings are defects in the cribs within the meaning of section 15(a)(2), CPSA, 15 U.S.C. 2064(a)(2).

40. The defects in the cribs either singly or in combination or both, create a substantial risk or risks of injury because of the thousands of cribs distributed by Respondents Pride-Trimble and Century; the dropsides which are present in all the cribs; the lowering of the dropsides that will take place in the reasonable and foreseeable use and misuse of the cribs; the five children who have already been killed by becoming entrapped in the lowered mesh sides of dropside mesh-sided cribs; and the deaths and injuries that can and will occur in the future.

41. The cribs present a substantial product hazard or hazards within the meaning of sections 15 (a), (c), and (d) of the CPSA, 15 U.S.C. 2064 (a), (c), and (d).

Count II—Playpens

42. The allegations of paragraphs 1–11, 13, and 14 are hereby realleged.

The Consumer Products

43. Respondent Pride-Trimble manufactured over three million dropside mesh-sided playpens prior to May 1983.

44. Each Respondent manufactured thousands of dropside mesh-sided playpens prior to 1983 and manufactured and/or distributed the playpens during some portion of 1983.

45. The dropside mesh-sided playpens manufactured by Respondents (hereafter playpens) have a base or floor made of pressed wood, masonite, or a similar material that measures approximately 40" x 40" or 36" x 36" and non-adjustable legs which raise them approximately six inches from the floor of a room. The playpens can be folded and are portable.

46. The sides of the playpens can be lowered and are known as "dropsides."

47. The playpens bear no labels warning of suffocation or asphyxiation hazards.

48. The playpens were produced or distributed for sale to consumers for use by infants and young children (children) in or around permanent or temporary households or residences, in recreation or otherwise, or for the personal use, consumption or enjoyment of children in or around a permanent or temporary household or residence, in recreation, or otherwise.

49. The playpens are "consumer products" within the meaning of section 3(a)(1), CPSA, 15 U.S.C. 2052(a)(1).

Substantial Product Hazard

50. When a side of a playpen is down, the mesh of that side forms a loose pocket which can extend beyond and below the floor of the playpen.

51. When a side of a playpen is down, there is no barrier to prevent a child from falling off the floor of the playpen.

52. Children can and have fallen off the floor of a playpen with a side down into the loose mesh pocket.

53. Children caught or trapped in the mesh pocket of a lowered side can and have been killed by lack of air due to compression of the chest or obstruction of the nose and/or mouth or by other causes.

54. Children entrapped in the mesh pocket of a lowered side can suffer brain damage or other injury caused by lack of air and/or compression.

55. Two children are known to have died in playpens manufactured by Respondent Pride-Trimble when they became entrapped in the mesh pockets formed by lowered sides.

56. Two children are known to have died in playpens manufactured by Respondent Questor when they became entrapped in the mesh pockets formed by lowered sides.

57. One child is known to have died in a playpen manufactured by Respondent Century Products, Inc. when he became entrapped in the mesh pocket formed by a lowered side.

58. One child is known to have suffocated to death in the mesh pocket formed by the lowered side of a playpen manufactured by one of Respondents or similar to those manufactured by Respondents.

59. Five children are known to have been killed in the same manner in dropside mesh-sided cribs.

60. In addition, one child is known to have lowered her head into the mesh pocket formed by the lowered side of a

Corporation, a corporation; Strolee of California, a.k.a. California Strolee, Inc., a corporation; and Welsh Company, Inc., a corporation.

Compliant

Nature of the Proceedings

1/ This is an adjudicative proceeding for public notice and remedial action for a substantial product hazard or hazards pursuant to section 15 of the Consumner Product Safety Act (CPSA), as amended, 15 U.S.C. 2064, and in accordance with 48 FR 34018. This proceeding is governed by the Rules of Practice for Adjudicative Proceedings before the Consumer Product Safety Commission, 16 CFR Print 1025 (1982).

Jurisdiction

2. This proceeding is instituted pursuant to section 15 of the CPSA, 15 U.S.C. 2064.

Respondents

3. Respondent Bilt-Rite Juvenile Products, Inc. (Bilt-Rite or Respondent) is a corporation organized and existing under the laws of the State of New York with corporate offices at 71 Blaisdel Rd., Orangeburg, New York 10962 and is a wholly owned subsidiary of Gerber Products Co., Inc., Fremont, Michigan.

4. Respondent Century Products, Inc. (Century or Respondent) is a corporation organized and existing under the laws of the State of Ohio with corporate offices at 1386 Commerce Drive, Stow, Ohio, 44224 and is a wholly owned subidiary of Gerber Products Co., Inc., Fremont, Michigan.

5. Respondent Collier-Keyworth Co., Inc. (Collier-Keyworth or Respondent) is a corporation organized and existing under the laws of the State of Massachusetts with corporate offices at 1 Tuttle Place, Gardner, Mass. 01440.

6. Respondent Cosco, Inc. (Cosco or Respondent) is a corporation organized and existing under the laws of the State of Indiana with corporate offices at 2525 State St., Columbus, Indiana 47201.

7. Respondent Graco Metal Products, Inc. (Graco or Respondent) is a corporation organized and existing under the laws of the State of Pennsylvania 19520.

8. Respondent Pride-Trimble
Corporation (Pride-Trimble or
Respondent) is a corporation organized
and existing under the laws of the State
of California with corporate offices at
539 W. Rosecrans, Gardena, California,
90248 and is a wholly owned subsidiary
of Virco Mfg. Corporation, Los Angeles,
California.

9. Respondent Questor Corporation (Questor or Respondent) is a corporation organized and existing

under the laws of the State of Delaware with corporate offices at 5750 North Hoover Blvd., Building A, Tampa, Florida, 33631.

10. Respondent Strolee of California (also known as California Strolee, Inc.) (Strolee of California or Respondent) is a corporation organized and existing under the laws of the State of California with corporate offices at 19067 S. Reyes Ave., Compton, California, 90221.

11. Respondent Welsh Company, Inc. (Welsh or Respondent) is a corporation organized and existing under the laws of the State of Missouri with corporate offices at 1535 S. 8th St., St. Louis, Missouri, 63104.

12. Respondents Century Products, Inc. and Pride-Trimble Corporation manufactured and distributed in commerce certain dropside mesh-sided cribs, identified more fully below, which are "consumer products" within the meaning of sec. 3(a)(1) of the CPSA, 15 U.S.C. 2052(a)(1) (1982).

13. Respondents Bilt-Rite Juvenile Products, Inc., Century Products, Inc., Collier-Keyworth Co., Inc., Cosco, Inc., Graco Metal Products, Inc., Pride-Trimble Corporation, Questor Corporation, Strolee of California (aka California Strolee, Inc.), and Welsh Company, Inc., manufactured and distributed in commerce certain dropside mesh-sided playpens (also known as play yards), identified more fully below, which are "consumer products" within the meaning of sec. 3(a)(1) of the CPSA, 15 U.S.C. 2052(a)(1).

14. Respondents are "manufacturers" of "consumer products" which have been "distributed in commerce," as those terms are defined in sections 3(a), (1), (4), (8), (11), and (12) of the CPSA, 15 U.S.C. 2052(a) (1), (4), (8), (11), and (12) (1982).

Count One-Cribs

15. The allegations of paragraphs 1, 2,4, 8, 12, and 14 are hereby realleged.

The Consumer Products

16. From about 1958 to and including some portion of 1980, Respondent Pride-Trimble manufactured over one million dropside mesh-sided cribs.

17. Prior to and during some portion of 1980, Respondent Century Products, Inc. manufactured approximately 34,500 to 44,500 dropside mesh-sided cribs.

18. The cribs manufactured by Respondents (hereafter, cribs) have a base or floor made of pressed wood, masonite, or a similar material that measures approximately 40" x 26", and extendable legs which can raise them about 20" from the floor of a room. The cribs can be folded and are portable.

CONSUMER PRODUCT SAFETY COMMISSION

[CPSC Docket No. 83-4]

Bilt-Rite Juvenile Products, Inc., et al.; Complaint

AGENCY: Consumer Product Safety Commission.

ACTION: Publication of a compliant under the Consumer Product Safety Act

SUMMARY: Under Provisions of its Rules of Practice for Adjudicative Proceedings [16 CFR Part 1025, 45 FR 29206], the Consumer Product Safety Commission must publish in the Federal Register Complaints which it issues. Printed below is a Complaint in the matter of Bilt-Rite Juvenile Products, Inc., et al., a corporation.

Dated: September 23, 1983. Sheldon D. Butts, Deputy Secretary.

Consumer Product Safety Commission

[CPSC No. 83-4]

In the matter of Bilt-Rite Juvenile Products, Inc., a corporation; Century Products, Inc., a corporation; Collier-Keyworth Co., Inc., a corporation; Cosco, Inc., a corporation; Graco Metal Products, Inc., a corporation; Pride-Trimble Corporation, a corporation; Questor

LaLeche League International, 9616 Minneapolis Street, Franklin Park, Illinois 80131 (312) 455-7730

National Association of Neighborhood Health Centers, Inc., 1625 "I" Street NW., Suite 401, Washington, D.C., (202) 833-9280 National Council of Jewish Women, 15 East 28th Street, New York, New York 10010 3000

National Council of Churches, 110 Massachusetts Avenue NE, Washington, D.C. 20002, (202) 544-2350

National Council of Catholic Women, 1312 Massachusetts Avenue NW., Washington, D.C. 20005, (202) 638-6050

National Safety Council, 444 North Michigan Avenue, Chicago, Illinois 60611 USDA Extension Service, Family Education, Washington, D.C. 20250, (202) 447-2920

Content To Be Included in All Notice

1. Mesh-sided dropside cribs and The first plant of the same playpens are hazardous when used with a side down.

- 2. Eleven young children have died in these products when left in them with a side down; six children in playpens and five children in cribs. Seven of the victims were six weeks old or younger.
- 3. The victims rolled off the floor of the crib or playpen into the loose mesh pocket formed by a lowered side and suffocated.
- 4. Children could also suffer other injury such as brain damage as the result of becoming caught in the mesh pocket of a lowered side.
- 5. Children are unable to cry out whencaught in the mesh pocket because they cannot breather

List and Summary of Documentary Evidence

- 6. Do not leave children in mesh-sided cribs and playpens with a side down.
- 7. Consumers who have a mesh-sided crib or playpen or both can obtain a repair, replacement, refund (whatever remedial measures are offered) by contacting the manufacturer at: [list names of manufacturers, brand names, and telephone numbers).
- 8. Further information can be obtained by calling the Consumer Product Safety Commission on its toll-free Hotline: 800-838-CPSC (in Maryland, 800-492-8104). The teletypewriter number for the hearing impaired is 800-638-8270

In the matter of Bilt-Rite Juvenile Products, Inc., et al.

sport but representing the country Activities of the left to decide Vilo terresoft in v inga royal se inconed believin as 1822 Here Skiden weed Hele Taylor.

	In death Impellanting as atten				Carrier (Section County Crist City County Co
	In-depth investigation or other source	DOA and victim	- Injury and accident	Manufacture	
		Mesh-Sid	ed Cribs		
	1. ND 74-74, Balti. Md	9/18/73, 8 wks. old	Death, infant lying face down wedged	Cross River.	
		•	between bottom of crib and mesh side.		
,	2. 770504BEP7014, Art., Va	4/19/77, 1 mo. old male, 12. bs.	Death, Baby found lying face down: Mattress on top of him. Side down.	Pride Trimble.	
	3. 780516PHI0718, Bart., Md	4/27/78, 6 wk, old female, 11	Death. Baby found tace up with head	Century Products:	10 (10 (10 (10 (10 (10 (10 (10 (10 (10 (
		ibs.	wedged between mattress and siding. Side down.		in the second second
	 Consumer Complaint, H- 886016, Leonard, ML. 	6/78, 6 mo. old female	Stopped breathing. Given mouth-to- mouth resuscitation and recovered.	Pride-Trimble.	To the second of
The state of the s	5. 781129CEP0771, Old	11/21/79, 2 wkold female; 8	Death, Head wedged in 2" wide de-	Pride-Trimble.	43 - Jan 198
en e	Bridge, N.J.	ibs.	pression between mattress and side netting. Pressure mark on right side		Commence of the Commence of the
			of tace. Baby found face down: Forehead laceration. Side down par-		
	0 000000HA1000 Friday	F (00 (00 OF 4) 4 1-	tietly.	Bardo Varanbio	· ·
		5/28/82, 25 day old male	Death, Infant lying on left side, head-	Pride-Trimble.	
	County, Va.		twisted to right. Abrasion on right	ľ	
	County, Va.		twisted to right. Abrasion on right side of face.		
	County, Va.	Mesh-Sideo			امرين در مورد
	1. 821128HIA1071, Virginia	6/21/79, 3 wk. old temale, 9	side of face. I Play Pens Death. Baby found face down; head	Pride-Trimble.	
	1. 821126HIA1071, Virginia Beach, Va.		side of face.		and the second of the second o
	821128HIA1071, Virginia Beach, Va. 820803HIA1296, Lewiston,	6/21/79, 3 wk. old female, 9 lbs. 4/26/62, 3½ mo. old, male	Death. Baby found face down; head wedged between mattress and side of pleypen. Death. Baby found face down in	Pride-Trimble.	
	821128HIA1071, Virginia Beach, Va. 820803HIA1298, Lewiston, Ma.	6/21/79, 3 w/c old temale, 9 lbs.	Death. Baby found face down; head wedged between mattress and side of playpen. Death. Baby found face down in pocket of loose mesh. Face wedged between bottom and mesh. Face	Pride-Trimble.	
	821128HIA1071, Virginia Beach, Va. 820803HIA1298, Lewiston, Ma.	6/21/79, 3 w/c. old temale, 9 lbs. 4/26/62, 31/4 mo. old, male	Death. Baby found face down; head wedged between mattress and side of pieypen. Death. Baby found face down in pocket of loose mesh: Face wedged between bottom and mesh. Face pressed against plastic draft shield. Side down.	Pride-Trimble. Pride-Trimble.	and the southway.
	821128HIA1071, Virginia Beach, Va. 820803HIA1298, Lewiston, Ma. 820819HIA3178, Missoula,	8/21/79, 3 wk. old temale, 9 lbs. 4/26/82, 3½ mo. old, male 8/15/82, 2½-mo. old, male	Death. Baby found face down; head wedged between mattress and side of pisypen. Death. Baby found face down in pocket of loose mesh. Face wedged between bottom and mesh. Face pressed against plastic draft shield. Side down. Death. Baby found facing center of	Pride-Trimble. Pride-Trimble. Cuestor.	er in de la
and the second of the second o	1. 821128HIA1071, Virginia Beach, Va. 2. 820803HIA1298, Lewiston, Ma. 3. 820819HIA3178, Missoula, Montz.	6/21/79, 3 wk. old temale, 9 lbs. 4/26/82, 3½ mo. old, male 8/15/82, 2½ mo. old, male; 13 lbs.	Death. Baby found face down; head wedged between mattress and side of pleypen. Death. Baby found face down in pocket of loose mesh: Face wedged between bottom and mesh. Face pressed against plastic draft shield. Side down. Death. Baby found facing center of play yard, lying on left side with right side of chest and abdomen pressed	Pride-Trimble. Pride-Trimble. Cuestor.	and the southway.
and the second seco	1. 821128HIA1071, Virginia Beach, Va. 2. 820803HIA1298, Lewiston, Ma. 3. 820819HIA3178, Missoula, Mont.	6/21/79, 3 wk. old temale, 9 lbs. 4/26/82, 3½ mo. old, male 8/15/82, 2½-mo. old, male	Death. Baby found face down; head wedged between mattress and side of playpen. Death. Baby found face down in pocket of loose mesh: Face wedged between bottom and mesh. Face pressed against plastic draft shield. Side down. Death. Baby found facing center of play yard, lying on left side with right side of chest and abdomen pressed against edge of floor board. Side down.	Pride-Trimble. Pride-Trimble. Cuestor.	er in de la
Table (1986) (Antique et al. 1986)	1. 821128HIA1071, Virginia Beach, Va. 2. 820803HIA1298, Lewiston, Ma. 3. 820819HIA3178, Missoula, Montz.	6/21/79, 3 wk. old temale, 9 lbs. 4/26/82, 3½ mo. old, male 8/15/82, 2½-mo. old, male	Side of face. Death. Baby found face down; head wedged between mattress and side of playpen. Death. Baby found face down in pocket of loose mesh: Face wedged between bottom and mesh. Face pressed against plastic draft shield. Side down. Death. Baby found facing center of play yerd, hing on left side with right side of chest and abdomen pressed against edge of floor board. Side down. Head became lowered into mesh.	Pride-Trimble. Pride-Trimble. Cuestor.	er in de la
Table (1986) (Antique et al. 1986) Table (1986) (Antique et al. 1986)	1. 821128HIA1071, Virginia Beach, Va. 2. 820803HIA1298, Lewiston, Ma. 3. 820819HIA3178, Missoula, Mont.	6/21/79, 3 wk. old temale, 9 lbs. 4/26/82, 3½ mo. old, male 8/15/82, 2½-mo. old, male	Death. Baby found face down; head wedged between mattress and side of playpen. Death. Baby found face down in pocket of loose mesh: Face wedged between bottom and mesh. Face pressed against plastic draft shield. Side down. Death. Baby found facing center of play yard, lying on left side with right side of chest and abdomen pressed against edge of floor board. Side down. Head became ilversed into mesh pocket when side was utom. Baby oried out and was picked up by cried out and was picked up by	Pride-Trimble. Pride-Trimble. Cuestor. Cosco, Inc.	er in de la
Table (1986) (Antique et al. 1986) Table (1986) (Antique et al. 1986)	1. 821128HIA1071; Virginia Beach, Va. 2. 820803HIA1298, Lewiston, Ma. 3. 820819HIA3178, Missoula, Montz. 4. 830223CEP1093, Front Royal, Va. 5. 830506CBB3082, Dallas,	8/21/79, 3 wk. old temale, 9 lbs. 4/26/62, 3½ mo. old, male 8/15/82, 2½-mo. old, male: 13 lbs. 11/7/62 3, mo. old temale	Side of face. If Play Pens Death. Baby found face down; head wedged between mattress and side of pisypen. Death. Baby found face down in pocket of loose mesh: Face wedged between bottom and mesh. Face pressed against plastic draft shield. Side down. Death. Baby found facing center of play yerd, lying on left side with right side of chest and abdomen pressed against edge of floor board. Side down. Head became lowered into mesh pocket when side was sown. Baby cried out and was picked up by prennts. No injury. Death. Infant rolled into mesh pocket.	Pride-Trimble. Pride-Trimble. Cussion. Cussion.	er in de la
Table Control (Antique of the Control (Control (1. 821128HIA1071, Virginia Beach, Va. 2. 820803HIA1298, Lewiston, Ma. 3. 820819HIA3178, Missoula, Mont. 4. 830223CEP1093, Front Royal, Va.	8/21/79, 3 wk. old temale, 9 lbs. 4/26/62, 3½ mo. old, male 8/15/82, 2½-mo. old, male: 13 lbs. 11/7/62 3, mo. old temale	Death. Baby found face down; head wedged between mattress and side of pleypen. Death. Baby found face down in pocket of loose mesh: Face wedged between bottom and mesh. Face pressed against plastic draft shield. Side down. Death. Baby found facing center of play yard, lying on left side with right side of chest and abdomen pressed against edge of floor board. Side down. Head became liversed into mesh pocket when side was utvern. Baby cried out and was picked up by perents. No injury.	Pride-Trimble. Pride-Trimble. Cussion. Cussion.	er in de la
indicated the second of the se	1. 821128HIA1071; Virginia Beach, Va. 2. 820803HIA1298, Lewiston, Ma. 3. 820819HIA3178, Missoula, Montz. 4. 830223CEP1093, Front Royal, Va. 5. 830506CBB3082, Dallas, Tex. 6. 830511DAL5085, Dallas,	8/21/79, 3 wk. old temale, 9 lbs. 4/26/82, 3½ mo. old, male 8/15/82, 2½ mo. old, male: 13 lbs. 11/7/82 3, mo. old temale 5/3/83, 6 mo. old male: 12.9	Side of face. If Play Pens Death. Baby found face down; head wedged between mattress and side of pisypen. Death. Baby found face down in pocket of loose mesh: Face wedged between bottom and mesh. Face pressed against plastic draft shield. Side down. Death. Baby found facing center of play yerd, hing on left side with right side of chest and abdomen pressed against edge of floor board. Side down. Head became lowered into mesh pocket when side was sown. Baby cried out and was picked up by prents. No injury. Death. Infant rolled into mesh pocket. Found face down. Mesh imprint on chest and head. Death. Child wedged in mesh. Pres-	Pride-Trimble. Pride-Trimble. Cuestor. Cosco, Inc. Century Froducts. Cuestor.	er in de la
STATES AND	1. 821128HIA1071, Virginia Beach, Va. 2. 820803HIA1298, Lewiston, Ma. 3. 820819HIA3178, Missoula, Mont. 4. 830223CEP1093, Front Royal, Va. 5. 830506CBB3082, Delias, Tex.	8/21/79, 3 wk. old temale, 9 lbs. 4/26/62, 3½ mo. old, male 8/15/82, 2½-mo. old, male: 13 lbs. 11/7/62 3, mo. old temale 5/3/83, 6 mo. old male: 12.9 lbs.	Death. Baby found face down; head wedged between mattress and side of playpen. Death. Baby found face down in pocket of loose mesh: Face wedged between bottom and mesh. Face pressed against plastic draft shield. Side down. Death. Baby found facing center of play yard, lying on left side with right side of chest and abdomen pressed against edge of floor board. Side down. Head became 'kvested into mesh pocket when side was utrem. Baby cried out and was picked up by perents. No injusy. Death, Infant rolled into mesh pocket. Found face down. Mesh imprint on chest and head. Death. Child wedged in mesh. Pressur marks on tace and body of mesh and floorboard.	Pride-Trimble. Pride-Trimble. Cusstor. Cosco, Inc. Comuy Products. Cuestor.	er in de la

[FR Doc. 83-28912 Filed 10-24-83; 8:45 am] BILLING CODE 6355-01-M

ar or the armount of the company of

CONSUMER PRODUCT SAFETY COMMISSION

[CPSC Docket No. 83-1]

Bilt-Rite Juvenile Products, Inc., et al; Correction

AGENCY: Consumer Product Safety
Commission.

ACTION: Publication of a Complaint when under the Consumer Product Safety Act, Correction

SUMMARY: This document corrects the complaint that appeared at page 44605 in the Federal Register of Thursday, September 29, 1983, (48 FR 44605). The action is necessary to add Attachments 1 and 2, and List and Summary of Documentary Evidence.

Dated: October 19, 1983.

Sadye E. Dunn,

Secretary.

Organizations To Contact

American College of Obstetricians and Gynecologists (ACOG), 600 Maryland Avenue SW., Washington, D.C. 20024, (202) 638–5577

International Childbirth Education Association (ICEA) P.O. Box 20048, Minneapolis, Minnesota 55420

National Association of Parents and Professionals For Safe Alternatives in Childbirth (NAPASC), P.O. Box 267, Marble Hill, Missouri 63764

The Bradly Method, P.O. Box 5224, Sherman Oaks, California 91413, (800) 423–2397 or (213) 788–6662

The Couple to Couple League International, Inc., P.O. Box 11084, Cincinnati, Ohio 45211

American Society for Psychoprophlaxis in Obstetrics (ASPO/Lamaze), 1411 K Street NW., Washington, D.C. 20005

NW., Washington, D.C. 20005
Parent and Child, Inc. (Washington
Metropolitan Area), 4905 Delray Avenue,
Suite 304, Bethesda, Maryland 20814, (301)
652-5383

American Academy of Pediatrics, 1801 Hinman Avenue, Evanston, Illinois 60204, [312] 869-4255

American Association for Maternal and Child Health, P.O. Box 965, Los Altos, California 94022, (415) 964–4575

American Home Economics Association, 2010 Massachusetts Avenue NW., Washington, D.C. 20063, (202) 862–8300

American Legion Auxiliary Children and Youth Committee, 777 N. Meridian Street, Indianapolis. Indiana 48204, (317) 635–8411

American National Red Cross, 17th and D Streets NW., Washington, D.C. 20006, (202) 737–8300

American Public Health Association, 1015 15th Street NW., Washington, D.C. 20005, (202) 789–5600

Coalition for Children and Youth, 815 15th Street NW., Washington, D.C. 20005, (202) 347-9380

Day Care and Child Development Council of America, 711 14th Street NW., Suite 507, Washington, D.C. 20005, [202] 638-2316 playpen manufactured by Respondent Cosco, Inc.

61. The dropsides of the playpens are a defect in the playpens within the meaning of section 15(a)(2), CPSA, 15 U.S.C. 2064(a)(2).

62. The mesh pocket formed by a side when it is down is a defect in the playpens within the meaning of section 15(a)(2), CPSA, 15 U.S.C. 2084(a)(2).

63. The lack of a barrier to prevent children from falling off the floor when a side is lowered is a defect in the playpens within the meaning of section 15(a)(2), CPSA, 15 U.S.C. 2064(a)(2).

64. Parents and others, such as baby sitters, are unaware of the asphyxiation hazards presented by a playpen with a

side that is down.

· 25 -

65. The playpens bear no warnings that a side that is lowered presents asphyxiation or suffocation hazards.

66. Warnings accompanying the playpens are inadequate to give notice of the asphyxiation hazards presented by a lowered side.

67. The failure to provide warnings and the lack of adequate warnings are defects in the playpens within the meaning of section 15(a)(2), CPSA, 15

U.S.C. 2064(a)(2).

68. The defects in the playpens, either singly or in combination or both, create a substantial risk or risks of injury because of the thousands of playpens distributed by each Respondent; the dropsides which are present in all the playpens; the lowering of the dropsides that will take place in the reasonable and foreseeable use and misuse of the playpens; the six children who have already been killed by becoming entrapped in the lowered mesh sides of dropside mesh-sided playpens; and the deaths and injuries that can and will occur in the future.

69. The playpens present a substantial product hazard or hazards within the meaning of sections 15 (a), (c), (d), CPSA, 15 U.S.C. 2064 (a), (c), and (d).

Relief Sought

Wherefore, Complaint Counsel requests the Commission to:

A. Determine that the cribs and playpens present a substantial product hazard or hazards within the meaning of sec. 15(a)(2), 15 U.S.C. 2064(a)(2), and that notification under sec. 15(c) of the CPSA, 15 U.S.C. 2064(c), is required to adequately protect the public and

1. Order Respondents to give public notice of the defect or defects in the

cribs and playpens by

(a) Mailing posters and notices to obstetricians, and the maternity wards of hospitals nationwider

(b) Mailing notice to parents of children 21 months or younger.

(c) Placing paid television and radio advertisements on national network and local stations during prime adult viewing and listening time;

(d) Holding a press conference;

(e) Mailing notice to TV stations, radio stations, newspapers, wire services, trade publications, and health organizations;

(f) Placing paid advertisements half a page in size for three consecutive issues in the following magazines: TV Guide, Parents Magazine, Woman's Day, Good Housekeeping, Essence, Consumer Reports, Mothers Manual, American Baby, Baby Talk Magazine, and Expecting Parents Magazine;

(g) Mailing notice to the organizations

specified in Attachment 1;

(h) Providing posters at least 11" by 22" to all retail customers with at least one poster for each retail outlet;

(i) Providing posters at least 11" by 22" to all wholesale customers for distribution to their retail customers with at least one poster for each retail outlet of each retail customer;

(j) Mailing notice to day care centers;

(k) Sending a representative to contact reporters and other appropriate media personnel in each of the largest 28 cities in the United States:

2. Order Respondents to mail notice to each distributor and retailer of any of

the cribs and playpens;

 Order Respondents to mail notice to every person to whom they know a crib or playpen was delivered or sold;

4. Order Respondents to give all notice with at least the content specified in Attachment 2.

B. Determine that the cribs and/or playpens present a substantial product hazard or hazards and that action under section 15(d) of the CPSA, 15 U.S.C. 2064(d), is in the public interest and order Respondents to

1. Repair the defects in the cribs and playpens, replace the cribs and playpens with like or equivalent products which do not contain the defects, or refund the purchase price of the cribs and playpens, or provide repair, replacement, or refunds as alternative remedies and

2. Submit a plan satisfactory to the Commission within 15 days of issuance of an order for taking the actions specified in paragraph B. 1 above.

C. Prohibit Respondents from manufacturing the cribs and playpens for sale, offering them for sale, distributing them in commerce, and importing them into the customs territory of the United States.

D. Order Respondents to reimburse each person for any reasonable and foreseeable expenses incurred in availing himself of any of the remedies in paragraph B.

E. Determine that reimbursement is in the public interest and order Respondents to reimburse all distributors and retailers for their expenses in connection with carrying out the order or orders of the Commission mandating the actions in paragraphs A and/or B including giving credit or refunds for returned inventory and paying transportation expenses.

F. Order Respondents to keep records of their actions taken to comply with paragraphs A through E and supply these records and extracts from these records to Commission staff for a period of three years after entry of each Commission order in this proceeding to establish compliance with the actions ordered.

G. Order Respondents to notify the Commission at least 60 days prior to any change in their business (such as incorporation, dissolution, assignment, sale, or declaration of bankruptcy) that results in the emergence of a successor corporation, the creation or dissolution of subsidiaries, the dissolution of the corporation, or any other change that might affect compliance obligations under any Commission order for a period of three years after issuance of each order in this proceeding.

H. Grant such other and further relief as the Commission deems necessary to protect the public health and safety and to implement the CPSA.

Issued by order of the Consumer Product Safety Commission.

Dated: September 21, 1983.

David Schmeltzer.

Associate Executive Director for Compliance and Administrative Litigation.

[FR Doc. 83–28508 Filed 9–28–83; 8:45 am] BILLING CODE 6355–01–M

