# Exhibit 86



# Hooey Recalls Children's Sweatshirts with Drawstrings Due to Strangulation Hazard



Examples of recalled youth sweatshirts with drawstrings









Hooey children's sweatshirts with drawstrings

#### Hazard:

A drawstring in the sweatshirt hood poses a strangulation hazard to children.

Drawstrings can become entangled or caught on playground slides, hand rails, school bus doors or other moving objects, posing a significant strangulation hazard to children.

#### Remedy:

Repair

#### **Recall Date:**

November 12, 2019

#### **Units:**

About 6,600 (In addition, 520 were sold in Canada)

### **Consumer Contact**

Hooey toll-free at 833-847-0829 from 8 a.m. to 5 p.m. CT Monday to Friday, email at <a href="mailto:info@getyourhooey.com">info@getyourhooey.com</a>, or online at <a href="https://getyourhooey.com/">https://getyourhooey.com/</a> and click on Product Safety for more information

# **Recall Details**

#### In Conjunction With:



#### **Description:**

This recall involves 15 styles of youth-sized sweatshirts with the "Hooey" brand or logo and drawstrings in the hood. The sweatshirts are polyester and cotton. The sweatshirts generally have a single front pocket. They were sold in boys' and girls' sizes XS, S, M, L, XL. A white size label has the word "Hooey" and "Made in China" and is located at the center back neck of the sweatshirts. A label in the side seam has the garment care instructions.

#### Remedy:

Consumers should immediately take the recalled sweatshirts away from children and remove the drawstring to eliminate the hazard.

## Incidents/Injuries:

None reported

#### Sold At:

Boot Barn, Orscheln's, Cavenders and other western wear apparel stores from September 2017 through October 2019 for about \$45.

#### Importer(s):

Hooey LLC, of Spring Branch, Texas

#### Manufactured In:

China

# Recall number:

20-018