

PURAFIL ENVIRONMENTAL CORROSION REPORT

22-Oct-2010

Company: 115390

Sales Order #: C002697

CCC Panel #: P67948

Date In: 20-Sep-2010

Date Out: 05-Oct-2010

Days In Service: 15

Room Area ID:

Reference #:



DO NOT TOUCH METAL COUPON

Corrosion Classification Coupon

Company		115390	
Address			
Room/Area I.D.		Living Room	
Date In	9/20/10	Time In:	16:58 a.m. p.m.
Date Out	10/5/10	Time Out:	12:52 a.m. p.m.
Coupon #	67948	Tracking #	02697
Serial #			
<input type="checkbox"/> Industrial <input type="checkbox"/> ERM <input type="checkbox"/> Preservation <input type="checkbox"/> CIF			

PURAFIL
First. In clean air

2654 Weaver Way • Doraville, Georgia 30340
Ph: (770) 662-8545 • (800) 222-6367
Fk: (770) 263-6922 • www.purafil.com

CCC Panel # P67948
ISA Class G2
Moderate

Copper Corrosion
472 Å/30 Days
Silver Corrosion
1375 Å/30 Days

(see next page for complete analysis)

Summary for PURAFIL CCC # P67948

The electrolytic reduction analysis on Corrosion Classification Coupon #P67948 shows the presence of moderate concentrations of contaminants in the environment tested. The hydrogen sulfide level is expected to range between 3 and 10 ppb and the sulfur dioxide level between 10 and 100 ppb. The effects of corrosion are measurable and may be a factor in determining equipment reliability.

Your local representative for additional information and assistance is:
 Environmental Health and Eng
 117 Fourth Avenue, Needham MA 02494, USA
 tminegishi@eheinc.com

Purafil, Inc. / 2654 Weaver Way, Doraville GA 30340 USA / (770) 662-8545 / (770) 263-6922
 Email: purafil@purafil.com / Internet: http://www.purafil.com

Displaying Page 1 [Display Page 2](#)

PURAFIL CCC # P67948 Analysis Results

Corrosion Film Composition				Gold Coupon - Magnified 20x
	Projections			
	<u>30 Days</u>	<u>1 Year</u>	<u>5 Year</u>	
Copper Films				
Cu ₂ S	215 Å	441 Å	753 Å	
Cu ₂ O	92 Å	189 Å	324 Å	
Unknowns	165 Å	338 Å	578 Å	
Totals	472 Å	968 Å	1655 Å	
Silver Films				
AgCl	0 Å	0 Å	0 Å	
Ag ₂ S	1375 Å	16740 Å	83700 Å	
Unknowns	0 Å	0 Å	0 Å	
Totals	1375 Å	16740 Å	83700 Å	

Gold Pore Corrosion:
 Note: 1000 Å = 0.1 micron

Equipment Reliability Correlation
 (ISA Standard S71.04-1985 for Copper)

