

# PURAFIL ENVIRONMENTAL CORROSIVITY REPORT

18-Jan-2011

Company: 120306

Room/Area ID:  
Reference #:

Sales Order #: C002726  
 CCC Panel #: P68810  
 Date In: 30-Nov-2010  
 Date Out: 14-Dec-2010  
 Days In Service: 14

**CCC Panel # P68810**

**ISA Class G1**  
 Mild

**Copper Corrosion**  
 267 Å/30 Days

**Silver Corrosion**  
 301 Å/30 Days

(see next page for complete  
 analysis)

## Summary for PURAFIL CCC # P68810

The electrolytic reduction analysis on Corrosion Classification Coupon #P68810 shows the presence of only very low concentrations of contaminants in the environment tested. The hydrogen sulfide level is not expected to exceed 3 ppb and the sulfur dioxide level should be less than 10 ppb. During the test period, corrosion, as shown by the copper coupon, is not a factor in determining equipment reliability.

Please note: Copper's reactivity is sensitive to temperature and relative humidity and can therefore exhibit seasonal variation. For example, below 30% relative humidity (typical for heated indoor air in winter), copper readings will be dramatically reduced. However, silver's reactivity is not affected by temperature and relative humidity. Due to the elevated level of film growth on the silver coupon, corrosion may be a factor in determining equipment reliability; continued monitoring is recommended.

Your local representative for additional information and assistance is:

Environmental Health and Eng  
 117 Fourth Avenue, Needham MA 02494, USA  
 tminegishi@eheinc.com

Purafil, Inc. / 2654 Weaver Way, Doraville GA 30340 USA / (770) 662-8545 / (770) 263-6922  
 Email: purafil@purafil.com / Internet: <http://www.purafil.com>

**PURAFIL CCC # P68810 Analysis Results**

Corrosion Film Composition				Gold Coupon - Magnified 20x
	Projections			
	<u>30 Days</u>	<u>1 Year</u>	<u>5 Year</u>	
<b>Copper Films</b>				
Cu <sub>2</sub> S	0 Å	0 Å	0 Å	
Cu <sub>2</sub> O	267 Å	357 Å	467 Å	
Unknowns	0 Å	0 Å	0 Å	
Totals	267 Å	357 Å	467 Å	
<b>Silver Films</b>				
AgCl	0 Å	0 Å	0 Å	
Ag <sub>2</sub> S	301 Å	3660 Å	18302 Å	
Unknowns	0 Å	0 Å	0 Å	
Totals	301 Å	3660 Å	18302 Å	
<b>Gold Pore Corrosion:</b>				
Note: 1000 Å = 0.1 micron				

**Equipment Reliability Correlation**  
(ISA Standard S71.04-1985 for Copper)

